



De-Hire Inspection Check

31/05/2025 / 383030 / Sydney / UE / Battery Electric / FN500192 /
Artemio Drio

Complete

Serial Number	FN500192
Hour Meter Read	8029 hr
Service Job No.	383030
Location	Sydney
Conducted on	31/05/2025 7:55 AM ACST
Conducted By	Artemio Drio

Truck Category

UE



Photo 1




Photo 2




Photo 3

Truck Make

Battery Electric

Equipment Exterior

General Appearance / Paintwork

WEAR & TEAR

Include Images of the Front, Rear & Sides of the Unit



Photo 4



Photo 5



Photo 6




Photo 7

Wheels/Tyres

Front Wheels / Tyres

WEAR & TEAR



Photo 8



Photo 9

Rear Wheels / Tyres

WEAR & TEAR



Photo 10

Wheel Bearings

N/A

Machine inoperational .

Chassis/Structure

Overhead Guard

OK



Photo 11



Photo 12

Chassis

Rust every where on the counter weight . Scratches around truck .



Photo 13



Photo 14



Photo 15

WEAR & TEAR

Battery Cover

N/A

Driver Seat & Fixing



Photo 16

OK

Panels and Covers (Left & Right)

OK

Accessories (Mirrors, Blue Lights)

OK



Photo 17

Windscreen

N/A

Rear Screen

N/A

Arm Rest

OK



Photo 18

Connection Elements	OK
Drive Unit	
Transmission Operation	OK
Transmission Noise & Leaks	OK
Drive Motor Condition	OK
Brake	
Brake Function & Adjustment	OK
Steering	
Steer Motor Operation/Noise	OK
Steering Cylinder	N/A
Steer Axle	OK
Steering Wheel/Controls	OK

Machine inoperational . Squeaking noise when wheel turned .



Photo 19

Hoist Frame/Load Lifting Device	
Mast To Full Height & Bearings	N/A
Machine inoperational .	

Forks & Fork Carriage

Slight bent on loadguard.

OK



Photo 20




Photo 21



Photo 22

Lift Chains Free & Secondary

Machine inoperational .

OK




Photo 23



Photo 24



Photo 25



Photo 26

Hydraulic Cylinder Free Lift

OK



Photo 27

Hydraulic Cylinders Secondary Light Right & Left

OK



Photo 28



Photo 29

Hydraulic Hoses Conditions

OK



Photo 30



Photo 31

Reach Carriage & Cylinder

N/A

Sideshift Carriage & Cylinder

OK



Photo 32



Photo 33

Tilt Function & Cylinders

OK



Photo 34



Photo 35

Hydraulic System	
Valve Block	OK
Pump Motor Operation	OK
Pump Operation	OK
Hydraulic Function Levers	OK
  Photo 36 Photo 37	
Electric System	
Multi-pilot & Solo-pilot	OK
Strobe & Working Lights / Alarms	OK
 Photo 38	
Drive Display, Console & Instruments	OK
 Photo 39	
Main Contactor & Connectors	OK
Charger Condition & Operation	OK

Battery

Battery Condition & Cables

WEAR & TEAR

Initially found unit and 40v charge and unit inoperational . Put it on charge for an hour, battery indication still flat but most functions already working .



Photo 40

Battery Carriage

OK

Battery Lock System

WEAR & TEAR

Additions or Attachments

Any other related attachments

No

Were any issues identified?

Wear & Tear

Battery extremely flat . Broken mast switch . Door lock not latching in. Found unit with 40v charge, put it on charge for an hour , bdi still shows flat battery.



Photo 41



Photo 42

(Internal) Parts required - BE

Chassis paint bad
Front tyres worn
Rear tyres worn
Load guard bent
Battery door lock defective
Mast switch broken

3 hr

Media summary



Photo 1

DATE: 17/7/24

MANITOU TCM

REMOVED FROM

Unit No.	Model	Van No.	Technician	Job No.	Date
120937	EFG				17/7/24

Service Manager: Jamie De Leon

Sales Manager:

Unit No.	Model	Van No.	Technician	Job No.	Date
120142	EFG220	VSYD18	Brandon Neundorff	350348	17/7/24

Replacement Action	Order Number	Parts Order Date	Parts ETA
Parts ordered		17/07/24	NA

Adelaide Head Office: 37 White Road, Gilles Plains SA 5094
Ph +61 8 8243 1222 Fax +61 8 8247 0583

Brisbane: 451 Boundary Road, Durrig QLD 4076
Ph +61 7 3216 7900 Fax +61 7 3216 7911

Melbourne: 412 South Gippsland Hwy, Dandenong South VIC 3175
Ph +61 3 8795 5999 Fax +61 3 8795 5990

Sydney: 4 Chester Place, Huntingwood NSW 2148
Ph +61 2 8750 2888 Fax +61 2 8750 2886

Perth: 21 Serpentine Avenue, Baysley WA 6206
Ph +61 8 9248 3077 Fax +61 8 9248 3077

Townsville: 201 Enterprise Drive, Baysley QLD 4858
Ph +61 7 4774 8000 Fax +61 7 4774 8000

FIG 1811222

Photo 2

Checklist for Basic Truck Condition Report # 344764

The following activities are undertaken to provide the recipient a brief overview of the truck condition. Complete the sections below and provide commentary in the allocated section. Photos of Forklifts & HGVs as well as any defects must be provided with this report.

Truck Data
Customer: RENTAL
Unit: 344
Serial No: FN 500192
Container: UNIT 120437
Model: EFG 218
Meter Reading: 7080

Checking functionality

	OK	Defect	% of total
■ Both travel switches, body protection switch (deadman switch)	☒	☐	
■ Ignition switch	☒	☐	
■ Raise, lower, reach, tilt (Hydraulic/Electronic functions)	☒	☐	
■ Horn	☒	☐	
■ Lamps	☒	☐	
■ Driving in a straight line, steering	☒	☐	
■ Clutch pedal, drive tyre, load rollers, on disc brakes for wear	☒	☐	
■ Side shift, hydraulic functions, attachments	☒	☐	
■ Truck due for service	☒	☐	

Checks of the drive-related functions

	OK	Defect	% of total
■ Check fluid levels	☒	☐	
■ Condition of battery (Note age in comments below)	☒	☐	
■ Connectors, plugs, hydraulic hoses etc.	☒	☐	

External checks

	OK	Defect	% of total
■ Condition of instrument cluster	☒	☐	
■ Condition of seat	☒	☐	
■ Condition of panels	☒	☐	
■ Condition of hydraulic hoses	☒	☐	
■ Condition of paint	☒	☐	

Additional comments
NO POWER IN BATTERY UNABLE TO START - BATTERY NOT RECHARGED

Truck Data
Inspected by: [Signature] Date: 23 5 24

JUNGHEINRICH

Photo 3



Photo 4



Photo 5



Photo 6




Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21




Photo 22




Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29



Photo 30



Photo 31



Photo 32



Photo 33



Photo 34



Photo 35



Photo 36



Photo 37



Photo 38



Photo 39



Photo 40



Photo 41



Photo 42