

VIN# YSR6X40005494104

Number	Description	Status	Operational Asset	Work Done	Completed
WO-SET-004-423	Prime Mover - B Service	Completed	PRM00568	Service as per work order	5 Aug 2022
WO-SET-004-316	FMC - MT Data - MDVR Hard Drive State Error - PRM00568 - NQD - QB Jondaryan - 16:35 Mon 06 Jun 22 (AWST)	Completed	PRM00568	Primed installation came and repaired MDVR box	20 Jun 2022
WO-SET-004-315	FMC - MT Data - MDVR Recording Error - PRM00568 - NQD - QB Jondaryan - 16:35 Mon 06 Jun 22 (AWST)	Completed	PRM00568	Primed installation came and repaired MDVR box	20 Jun 2022
WO-SET-004-314	FMC - MT Data - MDVR Channel State Error - PRM00568 - NQD - QB Jondaryan - 16:35 Mon 06 Jun 22 (AWST)	Completed	PRM00568	Primed installation came and repaired MDVR box	20 Jun 2022
WO-SET-004-308	FMC - MT Data - MDVR Recording Error - PRM00568 - NQD - QB Jondaryan - 06:14 Wed 01 Jun 22 (AWST)	Completed	PRM00568	External contractor	5 Jun 2022
WO-SET-004-307	FMC - MT Data - MDVR Channel State Error - PRM00568 - NQD - QB Jondaryan - 06:14 Wed 01 Jun 22 (AWST)	Completed	PRM00568	External contractor	5 Jun 2022
WO-SET-004-260	Prime Mover - B Service	Completed	PRM00568	496460km	20 Jun 2022
WO-SET-004-034	Scania Prime Mover (B Service)	Completed	PRM00568	Serviced at blacks Toowoomba 456142km	24 Mar 2022
WO-SET-003-856	Scania Prime Mover (B Service)	Completed	PRM00568	Service by black trucks toowoomba 417352km	21 Dec 2021
WO-SET-003-551	FMC - MT Data - MT Data GPS Error - PRM00568 - NSW & QLD - Bulk - Jondaryan - 11:51 Sat 28 Aug 21 (AWST)	Completed	PRM00568	Contacted mtdata and system was recalibrated to fix gps issue	6 Sep 2021
WO-SET-003-543	Brake Testing	Completed	PRM00568	completed by Truck sales Toowoomba 20.08.2021 See attached documents	20 Aug 2021
WO-SET-003-544	NHVR - NHVR, 52 WEEK ROADWORTHINESS COMPLIANCE INSPECTION (Prime Mover)	Completed	PRM00568	completed by Truck sales Toowoomba 20.08.2021 See attached documents	20 Aug 2021
WO-SET-003-460	Scania Prime Mover (B Service)	Completed	PRM00568	Serviced at Black Truck Sales Toowoomba @376085km	20 Aug 2021
WO-TIV-013-376	NHVR - NHVR, 52 WEEK ROADWORTHINESS COMPLIANCE INSPECTION (Prime Mover)	Completed	PRM00568	AVI Scania service agreement	25 Aug 2020
WO-TIV-013-311	Replace 4 X drive tyres Beaurepaire nth ipswich	Completed	PRM00568	Replace 4 X drive tyres 2 steer tyres replaced Beaurepaire nth ipswich	21 May 2021

WO-TIV-013-269	replace broken rear tail light mounting bar indicator light in bullbar not working	Completed	PRM00568	replace broken rear tail light mounting bar indicator light in bullbar not working.	20 Apr 2021
WO-TIV-013-266	Scania Prime Mover (B Service)	Completed	PRM00568	Scania Pinkenba Scania Flexi service Scania Pinkenba	19 Apr 2021
WO-TIV-013-120	Replace 4 X drive tyres Beaurepairs nth Ipswich	Completed	PRM00568	Replace 4 X drive tyres Beaurepairs nth Ipswich	12 Feb 2021
WO-TIV-013-032	Scania Prime Mover (B Service)	Completed	PRM00568	Service completed at Scania Richlands	31 Dec 2020
WO-TIV-013-026	Replace Steer tyres	Completed	PRM00568	Replace Steer tyres Beaurepairs Nth Ipswich	8 Jan 2021
WO-TIV-012-973	Scania Prime Mover (A Service)	Completed	PRM00568	service completed BDS	4 Dec 2020
WO-TIV-012-854	repair air leak	Completed	PRM00568	repair air leak	11 Sep 2020
WO-TIV-012-795	Replace 6 X drive tyres @ 245501.3kms POS 3,4,5,6,9,10	Completed	PRM00568	Replace 6 X drive tyres @ 245501.3kms POS 3,4,5,6,9,10	24 Aug 2020
WO-TIV-012-811	Scania Prime Mover (A Service)	Completed	PRM00568	Service completed with B service at Scania Richlands	25 Aug 2020
WO-TIV-012-780	beaurepairs gymple replace blown driver tyre with run out	Completed	PRM00568	beaurepairs gymple replace blown driver tyre with run out	18 Aug 2020
WO-TIV-012-740	Replace damaged Windscreen	Completed	PRM00568	Replace damaged Windscreen completed 14/08	14 Aug 2020
WO-TIV-012-738	Scania Prime Mover (B Service)	Completed	PRM00568	Service asset as per attached service sheet Scania Richlands	25 Aug 2020
WO-TIV-012-737	Brake Testing	Completed	PRM00568	Scania Richlands Brake Test	25 Aug 2020
WO-TIV-012-569	Scania Prime Mover (A Service)	Completed	PRM00568	Service asset as per attached service sheet adjust turntable/grease fix bull bar indicator light	29 Jun 2020
WO-TIV-012-538	Scania Prime Mover (B Service)	Completed	PRM00568	Service completed Scania Richlands 27/09/20	27 Jun 2020
WO-TIV-012-530	ecowind not working	Completed	PRM00568	Briskair repair ecowind	3 Apr 2020
WO-TIV-012-494	ecowind not working service eco wind	Completed	PRM00568	ecowind not working service eco wind	8 Jun 2020
WO-TIV-012-452	Replace 2 drive tyres & 2 steer tyres	Completed	PRM00568	Beaurepairs Rockhampton Replace 2 drive tyres L/H/R replace 2 steer tyres	2 Jun 2020
WO-TIV-012-380	Check Turntable operation	Completed	PRM00568	Check Turntable operation	18 May 2020
WO-TIV-012-355	NHVR	Completed	PRM00568	AVI completed Scania Richlands	1 May 2020
WO-TIV-012-290	Scania Prime Mover (B Service)	Completed	PRM00568	Service asset as per attached service sheet Scania Richlands	30 Apr 2020
WO-TIV-012-289	ecowind not working	Completed	PRM00568	Repaired again at Briskair Rocklea	1 May 2020
WO-TIV-012-221	rotate steer tyres on rims Beaurepairs SA	Completed	PRM00568	rotate steer tyres on rims Beaurepairs SA	7 Apr 2020
WO-TIV-012-103	repair to l/h/f mud guard	Completed	PRM00568	repair to l/h/f mud guard	19 Mar 2020

WO-TIV-011-811	wire in power wire to charge tarp electrical system.	Completed	PRM00568	wire in power wire to charge tarp electrical system.	23 Jan 2020
WO-TIV-011-801	Scania Prime Mover (B Service)	Completed	PRM00568	Service asset as per attached service sheet Scania Richlands	23 Jan 2020
WO-TIV-011-661	replace steer tyres and maybe 8 drive	Completed	PRM00568	replace steer tyres and maybe 8 drive	30 Dec 2019
WO-TIV-011-534	ecowind not working	Completed	PRM00568	ecowind not working taken to Briskair, internal control panel replaced, replaced external control board	3 Dec 2019
WO-TIV-011-424	eco wind not stop working yesterday	Completed	PRM00568	eco wind not stop working yesterday, started up and run fine for about 10 minutes shut down, run through cabling all looked good.	20 Nov 2019
WO-TIV-011-373	Scania Prime Mover (B Service)	Completed	PRM00568	Service completed at Scania Richlands 15/11/19	15 Nov 2019
WO-TIV-011-192	NHVR 52 week inspection	Completed	PRM00568	NHVR 52 week inspection done by scania	12 Mar 2019
WO-TIV-011-177	fit big Anderson plug	Completed	PRM00568	fit big Anderson plug	18 Oct 2019
WO-TIV-011-174	replace driver side weather shield	Completed	PRM00568	replace driver side weather shield	17 Oct 2019
WO-TIV-011-001	repairs to eco wind air con	Completed	PRM00568	repairs to eco wind air con	25 Sep 2019
WO-TIV-010-933	repair drivers side weather shield	Completed	PRM00568	repair drivers side weather shield	17 Sep 2019
WO-TIV-010-720	SENT TO BIG WHEELS FOR WHEEL ALIGNMENT	Completed	PRM00568	SENT TO BIG WHEELS FOR WHEEL ALIGNMENT	20 Aug 2019
WO-TIV-010-683	Scania Prime Mover (B Service)	Completed	PRM00568	Service asset as per attached service sheet, service completed by Scania Richlands	27 Apr 2018
WO-TIV-010-581	retarder fault looked at and repaired by Tibbs Rocky	Completed	PRM00568	retarder fault looked at and repaired by Tibbs Rocky	6 Aug 2019
WO-TIV-010-555	BRAKE TEST, E STOP WIRING & WHEEL NUT INDICATORS COMPLETED BY SCANIA RICHLANDS	Completed	PRM00568	BRAKE TEST, E STOP WIRING & WHEEL NUT INDICATORS COMPLETED BY SCANIA RICHLANDS	2 Aug 2019
WO-TIV-010-540	fir rear hock up	Completed	PRM00568	fir rear hock up	5 Aug 2019
WO-TIV-010-464	Scania hydraulics install	Completed	PRM00568	Scania hydraulics install	18 Sep 2019
WO-TIV-010-410	FMC - MT Data - MDVR Recording Error - Trk, PRM00568 - South Australia - Bulk - South Australia Transport - 00:05 Wed 17 Jul 19 (AWST) - Site to moderate as required	Completed	PRM00568	checked hawk-eye units test Ok	23 Aug 2019
WO-TIV-010-198	Australia - Bulk - South Australia Transport - 11:00 Mon 24 Jun 19 (AWST) - Site to moderate as required	Completed	PRM00568	ran update for dss unit. made test events rang guardian for service call and issue with camera fixed itself with update	23 Aug 2019
WO-TIV-010-051	Buzzer fault detected	Completed	PRM00568	DSS work done 19/6/19 WO-TIV-010-049	19 Jun 2019
WO-TIV-010-050	Speaker fault detected	Completed	PRM00568	DSS work done 19/6/19 WO-TIV-010-049	19 Jun 2019

WO-TIV-010-049	FMC - DSSI fault in truck PRM00568 the fault reported = Camera fault detected	Completed	PRM00568	FMC - DSSI fault in truck PRM00568 the fault reported = Camera fault detected	20 Jun 2019
WO-TIV-010-048	IR pods not active	Completed	PRM00568	IR pods not active	19 Jun 2019
WO-TIV-009-872	replace battery's	Completed	PRM00568	DSS work done 19/6/19 WO-TIV-010-049	16 May 2019
WO-TIV-009-844	jump start truck	Completed	PRM00568	replace battery's	14 May 2019
WO-TIV-009-315	Scania Prime Mover (B Service)	Completed	PRM00568	jump start truck	13 Mar 2019
WO-TIV-009-270	GPS not detected	Completed	PRM00568	Service asset as per attached service sheet, service completed by Scania Richlands	20 May 2019
WO-TIV-009-238	repair drive tyre	Completed	PRM00568	Checked system and GPS is detecting 20/05/19	5 Mar 2019
WO-TIV-009-209	drive tyre	Completed	PRM00568	repair drive tyre	4 Mar 2019
WO-TIV-009-042	air con fan	Completed	PRM00568	drive tyre	18 Feb 2019
WO-TIV-008-986	test battery's	Completed	PRM00568	air con fan	11 Feb 2019
WO-TIV-008-889	brake test	Completed	PRM00568	test battery's	1 Feb 2019
WO-TIV-008-402	Steer tyres	Completed	PRM00568	carry out brake test	12 Dec 2018
WO-TIV-008-064	reported and repaired tuntable to be checked and adjusted	Completed	PRM00568	replace steer tyres x 2	24 Oct 2018
WO-TIV-008-059	REPLACE MUDGUARDS	Completed	PRM00568	reported and repaired tuntable to be checked and adjusted	24 Oct 2018
WO-TIV-008-056	ad blue tank bolt	Completed	PRM00568	Replace left hand rear mudguard, fit bolt to adblue tank strap	23 Oct 2018
WO-TIV-008-037	Service asset as per attached service sheet, service completed by Scania Richlands	Completed	PRM00568	ad blue tank bolt	19 Oct 2018
WO-TIV-007-549	replace windscreen	Completed	PRM00568	Service asset as per attached service sheet, service completed by Scania Richlands	21 Aug 2018
WO-TIV-007-472	Scania Richlands replace damaged light protector and inspect air leak and dash warning light	Completed	PRM00568	replace windscreen by fixer windscreen	8 Jun 2018
WO-TIV-006-899	Scania Prime Mover (B Service)	Completed	PRM00568	Scania Richlands replace damaged light protector and inspect air leak and dash warning light	4 Jun 2018
				Service asset as per attached service sheet, service completed by Scania Richlands	