



Vehicle History Summary



| | |
|-----------------|-------------------|
| Fleet # | 60 |
| Registration | KST96 |
| Make | Kenworth |
| Model | K104 |
| VIN / Chassis # | 6F50000006A431144 |
| Build Date | 2006 |

| Number | Date | Kms | Hours | Type | Repairer Notes | Repairer |
|--------|------------|--------|-------|-----------------|--|-------------------------------|
| S-5159 | 19/11/2022 | 854470 | | C - Annual | | Kelvyn Fuller |
| S-5158 | 12/11/2022 | 853380 | 0 | A - 30 Days | | Colin Scott |
| T-1473 | 15/10/2022 | 0 | 0 | STRIP & FIT | TYRE WAS BLOWN 1 x S/F 1 x NWR | Tyreright |
| S-5070 | 14/10/2022 | 847518 | | A - 30 Days | | Kelvyn Fuller |
| S-5039 | 07/10/2022 | 844681 | | A - 30 Days | | Colin Scott |
| S-5036 | 01/10/2022 | 841665 | | A - 30 Days | | Colin Scott |
| S-4987 | 10/09/2022 | 833673 | | A - 30 Days | | Colin Scott |
| R-2119 | 24/08/2022 | 0 | 0 | Engine Oil Leak | REPAIR OIL LEAK, TIGHTEN SUMP PLUB | SH&M Fuller Transport Repairs |
| S-4959 | 20/08/2022 | 827110 | | A - 30 Days | | Colin Scott |
| R-2102 | 26/07/2022 | 0 | 0 | MISC | R & R BROKEN FUEL PUMP DRIVER AND GASKET. FRONT MUD FLAP, FADED REAR MARKER SIGNS, FUEL HOSES, GEARBOX, HOSES, RADIO AERIAL, PARTY HAT RUSTED BOLT AND WASHERS, MISSING AIRHORN COVER. | SH&M Fuller Transport Repairs |
| S-4986 | 04/07/2022 | 824049 | | B - 30k | | Colin Scott |
| R-2088 | 29/06/2022 | 0 | 0 | Misc | REPLACE FRONT SPRING BUSHES - PINS, FRONT CAB SHOCKS , FRONT SHOCK BUSHES, DRAG LINK, R & R DOOR LOCKS, INDICATOR STALK, BATTERIES, WINDOW REGULATOR., DASH LIGHT BULBS ADJUST CLUTCH, | SH&M Fuller Transport Repairs |
| S-4957 | 04/06/2022 | 823396 | | A - 30 Days | | Colin Scott |
| S-4716 | 07/05/2022 | 821681 | 0 | A - 30 Days | | Colin Scott |
| S-4680 | 09/04/2022 | 816952 | 0 | A - 30 Days | | Colin Scott |
| T-1382 | 05/04/2022 | 0 | 0 | Rotate | ROTATION OF 2 TYRES | Tyreright |
| T-1374 | 29/03/2022 | 0 | 0 | Rotate | | Tyreright |
| T-1370 | 29/03/2022 | 0 | 0 | STRIP & FIT | 5 STRIP AND FIT | Tyreright |

| Number | Date | Kms | Hours | Type | Repairer Notes | Repairer |
|--------|------------|--------|-------|--|---|------------------|
| S-4679 | 04/03/2022 | 812897 | 0 | A - 30 Days | | Colin Scott |
| S-4454 | 03/02/2022 | 806975 | 0 | A - 30 Days | R&R leaking air valve Fit spacer washers on sway-bar bolts Remove fan, turn it around and re-fit FURTHER REPAIRS Drag link Front spring bushes & pins Front shock & bushes Rear shocks & bushes Coolant hose & tap Through shaft seal Door locks & ignition barrel | Colin Scott |
| T-1328 | 17/01/2022 | 0 | 0 | NEW & RETREAD | 2 NEW 2 STRIP AND FIT 2 BALANCE | Tyreright |
| S-4249 | 06/01/2022 | 795887 | 0 | B - 30k | | Colin Scott |
| S-4229 | 22/12/2021 | 791225 | 0 | A - 30 Days | | Colin Scott |
| I-5 | 27/11/2021 | 778212 | 0 | HEAVY VEHICLE ANNUAL INSPECTION - TRUCKS | | |
| S-4216 | 25/11/2021 | 778212 | 0 | C - Annual | | Colin Scott |
| S-4187 | 28/10/2021 | 765074 | 0 | B - 30k | | Colin Scott |
| S-4180 | 02/10/2021 | 778212 | 0 | A - 30 Days | | Colin Scott |
| S-4227 | 04/09/2021 | 738775 | 0 | A - 30 Days | | Colin Scott |
| R-1526 | 23/08/2021 | 730757 | | MISC | R & R POSITION 5 HUG SEALS, ALL REAR SUSPENSION BUSHES, FRONT CAB SHOCKIES, REAR HOOK UP LAMPS, DASH BULB AND R/H DASH CLUSTER, DASH LIGHTS, HEAD LAMPS. REPLACE BRAKES AND BRAKE DRUM WHERE REQUIRED. REPLACE MISSING CLUTCH PEDAL RUBBER | SH&M Fuller |
| S-4228 | 21/08/2021 | 732196 | 0 | B - 30k | | Colin Scott |
| R-1524 | 19/08/2021 | | | MISC | REPAIR OIL LEAK AT FRONT COVER. OVERHAUL JAKE HEADS. R & R SUMP , EXHAUST MANIFOLD. ETC | TRANSMARINE |
| R-1522 | 17/08/2021 | | | WINDOW | S & F L/H AND R/H WINDOW | FIXER WINDSCREEN |
| S-3111 | 07/08/2021 | 730636 | 0 | A - 30 Days | | Colin Scott |
| S-4146 | 03/07/2021 | 715680 | 0 | A - 30 Days | | Colin Scott |
| S-4147 | 03/07/2021 | 715680 | 0 | B - 30k | | Colin Scott |
| S-4155 | 19/06/2021 | 708985 | 0 | A - 30 Days | | Kelvyn Fuller |
| S-3935 | 12/06/2021 | 705514 | 0 | A - 30 Days | | Kelvyn Fuller |

| Number | Date | Kms | Hours | Type | Repairer Notes | Repairer |
|--------|------------|--------|-------|-----------------|--|--------------------|
| R-1322 | 27/05/2021 | | | MISC | R & R POSTION HUB SEA. REMOVE DAMAGED GEARBOX, REMOVE CLUTCH AND CHECK THEN REFIT WITH NEW SPIGOT BEARINGS. FIT 2 ND HAND SUPPLIED GEARBOX, REASSEMBLE AS NEEDED, REFIT FUEL TANK AND ALL COMPONENTS. R & R FUEL TANK SUPPORT BUSHES. | SH&M Fuller |
| S-3589 | 09/05/2021 | 695170 | 0 | A - 30 Days | | Colin Scott |
| T-1163 | 15/04/2021 | | | Pressure Test | | TYRE EVOLUTION |
| R-1305 | 15/04/2021 | | | Wheels | UNBOLT OR BOT ON WHEEL ASSEMBLY (4 TYRES) | TYRE EVOLUTION |
| S-3622 | 10/04/2021 | 681277 | 0 | A - 30 Days | | Colin Scott |
| S-3623 | 10/04/2021 | 681277 | 0 | B - 30k | | Colin Scott |
| S-3112 | 19/03/2021 | 673072 | 0 | A - 30 Days | | Colin Scott |
| S-3113 | 26/02/2021 | 662883 | 0 | A - 30 Days | | Colin Scott |
| R-1257 | 06/02/2021 | | | AIR Conditioner | FIT UP NEW COMPRESSOR AND R/D EVACUATE AND REGAS. FIT NEW STATIC RECITIFIED REGULATOR TOW BEARINGS ETC | ROTHALE PTY LTD |
| T-1076 | 01/02/2021 | | | Rotate | | TYRE EVOLUTION |
| S-3679 | 29/01/2021 | 649874 | 0 | B - 30k | | Colin Scott |
| S-3680 | 29/01/2021 | 649874 | 0 | A - 30 Days | | Colin Scott |
| T-1070 | 21/01/2021 | | | Balance | | TYRE EVOLUTION |
| S-3210 | 28/11/2020 | 623766 | | C - Annual | | Kelvyn Fuller |
| S-3209 | 28/11/2020 | 623766 | | B - 30k | | Kelvyn Fuller |
| T-1023 | 26/11/2020 | | | Re - Treads | | TYRE EVOLUTION |

Signed: _____
Name: _____
Date: _____