



De-Hire Inspection Check

30/01/2026 / 406479 / Sydney / STR / Yes / Yes / 1x Seat cushion
Painting / 2.5 / Yes / 1xfloor spot bracket
1xcharger cable
1x320amp plug / 0.5 / FN500193 / Artemio Drio

Complete

Serial Number

FN500193




Photo 1



Photo 2

Hour Meter Read

9101 hr



Photo 3

Service Job No.

406479

Location

Sydney

Conducted on

30/01/2026 9:31 AM AEDT

Conducted By

Artemio Drio

Truck Category

STR

Function

Full function Test & Safety Check

Pass

Truck due for service?

No

Appearance

Condition of the Unit, Wheels, Paint

Fair

Charger with the truck belongs to another unit .



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10

Operation

Test & Tag valid?

No



Photo 11

Has damage or repair work been identified?

Yes

Bent floor spot bracket and charger cable cut open .



Photo 12



Photo 13



Photo 14




Photo 15



Photo 16

Was any wear & tear identified?

Yes

Seat cushion tear. Front tires near wear limit . Paint chips and scratches around truck . Battery dusty.



Photo 17



Photo 18



Photo 19



Photo 20

(Internal) Parts required

1x Seat cushion
Painting

(Internal) Est. Labour Requirements to repair (hrs)

2.5 hr

Was any damage identified?

Yes



Photo 21




Photo 22

(External) Parts Required

1xfloor spot bracket
1xcharger cable
1x320amp plug

(External) Labour Requirements (hrs)

0.5

Media summary




Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22