



TAX INVOICE

MULTIWORKS

Invoice Date
11 Jan 2023
Invoice Number
940
Reference
[1KWW-BMA] - [1KWW-BMB]
ABN
54 051 791 230
Advanced Windscreens -
ADP Gen 2 Pty Ltd.
Email:
advancedwindscreens@o
utlook.com
Phone: 0418634005
Post: P.O Box 83
DC ST ALBANS VIC 3021

Description	Quantity	Unit Price	GST	Amount AUD
SUPPLY AND FIT FRONT WINDSCREEN TO ISUZU CXT WIDE CAB 3 WIPER FLEET 200 [1KWW-BMA]	* 203	400.00	10%	400.00
SUPPLY AND FIT FRONT WINDSCREEN TO ISUZU TIPPER WITH NEW MOULD FLEET 202 [1KWW-BMB]	* 202	350.00	10%	350.00
SUPPLY AND FIT FRONT WINDSCREEN TO ISUZU D-MAX [ZYB-706]	* 1050	270.00	10%	270.00
Subtotal				1,020.00
TOTAL GST 10%				102.00
			TOTAL AUD	1,122.00

Due Date: 10 Feb 2023

Please note your account is due in 30 days.

Payments can be made by cash.

Direct transfer to:

Account name: ADP Gen 2 Pty Ltd

BSB: 030-134

Account number: 521347

Or by EFTPOS - 1.6% surcharge will be applied to the final total

Advanced windscreens -
ADP Gen 2 Pty Ltd
ABN 54 051 791 230
11 January 2023
10:49 am
Receipt No:
Authorization: 049650



Customer Account	\$1,122.00
Total	\$1,122.00
MasterCard 0346	\$1,122.00
(Contract)	

1104082

~~\$0.50~~

BOB JANE T-MARTS

BOB JANE T-MART : SPRINGVALE
(Bob Jane Corporation Ltd #1)
144 SPRINGVALE ROAD
SPRINGVALE 3171
tj@springvale.t-marts.com.au

ABN: 53 052 070 431 ACN: 005 070 431

Phone: 03 9548 7711
Fax: 03 9542 4383



Customer Code:
1

JAKE IAFETA
MULTIWORKS
BONBEACH VIC 3196

1204422
1044p
Page 1 of 2

Subscription Std

COPY TAX INVOICE 168423

Registration No. Z1E738
Odometer: 211380

Vehicle Make: ISUZU
Vehicle Model: D-MAX TF 2WD LS

Vehicle Year: 2012-2013
Wheel/Rad Ten, Set: 118 KM

Front PS: _____
Rear PS: _____

Tyre prices include fitting, standard balance, valves and tyre disposal (Retail customers only. Excludes Trade & Fleet)

Product	Description	Qty	Price	Amount
WORDER_050148				
TRADMAX	TRACMAX 245/70R16 111T X-P AT08 (BSW XL)	4	181.00	724.00
ZATS	ALIGNMENT - THRUST (SUV)	1	69.00	69.00
LLPNT	LLTP VIP MEMBERSHIP	1	0.00	0.00

WELCOME TO OUR BOB JANE T-MARTS LONG LIFE TYRE PLAN. THIS IS YOUR COMPLEMENTARY MEMBERSHIP.
THIS PLAN INCLUDES A FREE 3 MONTH TYRE SERVICE AND THEN DISCOUNTED SCHEDULED TYRE SERVICES
THEREAFTER. PLEASE REFER TO OUR WEBSITE [HTTP://WWW.BOBJANE.COM.AU/PROMOTIONS-LONG-LIFE-TIRE-PLAN](http://www.bobjane.com.au/promotions-long-life-tire-plan)



To opt out at any time, call 1800 032 038 and speak to our friendly customer service officer or email lltpout@bobjane.com.au with your registration number and we will remove you from our system.

Tyre prices include fitting, standard balance, valves and tyre disposal (Retail customers only. Excludes Trade & Fleet).

All Bob Jane T-Marts have strict commitment to absolutely serve the interests of customers to a level of service beyond their expectations, using the highest quality products and at the most competitive price. All products and services endorsed or approved by the Bob Jane Corporation, and sold through their independent Bob Jane T-Marts carry a full warranty to ensure you are happy with your purchase.

www.bobjane.com.au

PAID BY: EFTPOS : 793.00

Deposits totaling \$0.00 used for this invoice

Includes GST of \$73.00

TOTAL \$

793.00



Patterson Cheney Isuzu Ute

A Division of Patterson Cheney Pty. Ltd.
A.C.N. 005 800 247 A.B.N. 52 005 800 247
www.pattersoncheney.com.au
Refrigeration trading code no. 000163

200 Cheltenham Road, Keysborough, VIC 3173
Ph: (03) 9215 2300

ISUZU
UTE

BANK DETAILS
BSB: 033 000
ACC: 237 450

admin@pattersoncheney.com.au

Service TAX Invoice				Page 1 of 2				Doc #: JDCEDT11467	
Customer No.	Customer Name & Address				Owner:	JULIAN CASSIMATTY	1123	Other:	Name: Julian DM
1123	Toyota Financial Services Locked Bag 2000				Phone / Email / Web:	131515151515 CREW UTE AUTO 2WD		Reg. No.:	
Reg. No.	Mitsubishi Triton 1500 Owner - Multi Works				Model No.:	KD030006	D-MAX 4WD	Reg. Date:	
Unit No.:					Chassis No.:	4KDFE1152	Post Date:	Reg. Exp. Date:	
Customer Order No.	Other:		Customer Ref.:	Customer Name:		Customer Reg. No.:	Reg. Date:		
10000000000000000000									
Cash	Amount Paid:	13000000000000000000	Amount Paid:	13000000000000000000	Amount:	130	Delivery Order:	Delivery Date:	Next Reg. Date:
Change							Date & Time Received:	Time Received:	Amount Paid:
Credit Card	Card No.:	MPA1111111111111111	Expiry Date:				28/02/2013	01:00pm	07:30am
Refund									
Postal Address:	Mobile Number:				Mobile Check:	999 CHECK	Next Service Date:		
100-100000@toyota.com.au							20140202		
New Work Required:	Mobile Number Received:				Mobile Received:	410473	Reg. Exp. Date:		
Mobile Work ID:	Customer Name:				Customer Mobile:				

Labour	Operation	Description	Amount
Job: 1	000473467190401	100,000km/11 Month service (Model/yr: 2012-2013)	\$26.00

oil and oil filter change and check vehicle
CARRIED OUT 100,000KM SERVICE
REPLACED ENGINE OIL AND FILTER CUSTOMER REQUESTED
ROTATED TYRES REAR TO FRONT
ADJUSTED FRONT WHEEL BEARINGS
CARRIED OUT ROAD TEST AND FINAL INSPECTION OK

Customer Instructions:

Carried out 100,000km/11 month service as per handbook.
Checked lights, suspension, horn and electrical systems.
Checked all fluid levels and topped up as required.
Inspected engine compartment hoses, pipes and connections for damage or leaks.
Inspected engine oil for contamination and leaks.
Inspected cooling system hoses and connections.
Inspected engine coolant.
Inspected power steering fluid.
Inspected high pressure power steering hose.
Inspected air filter element.
Checked engine idle speed.
Checked drive belt and adjusted tension as required.
Inspected fuel filter water separator, drain when water separator warning light comes on.
Inspected diesel fuel filter, replace when fuel filter indicator light comes on.
Inspected under body for damage and fluid leaks.
Checked brake system operation.
Inspected brake pads and discs.
Inspected brake linings and drums.
Inspected brake lines and hoses.
Inspected park brake handle and cables.
Inspected park brake operation and adjusted as required.
Inspected suspension and steering components.
Inspected propeller shaft for wear and ball bearings.
Inspected steering wheel and linkages.
Inspected ball joints & dust covers.
Inspected front and rear wheel bearings.
Inspected exhaust system for security and leaks.
Inspected fuel system lines and connections.
Checked condition and pressures of all tyres including spare.
Tightened wheel nuts to correct torque.
Inspected tightness of chassis, body bolts and nuts.
Checked brake pedal travel.
Inspected seat belts, buckles, restraints, anchors and adjusters.
Inspected and lubricated hinges, locks and catches.