

B49 - 2019 DAF FTTXF105

2019 DAF FTTXF105

Unit #: B49

Tag #: XV27DV

Kilometers 912,273

Serial #: JG226924

ENGINE NO A347494

Date	Kilometers	Notes	Vendor	Employee	Total Cost
6/04/2021	306,491	CARRY OUT 100,000 KM SERVICE AS PER SERVICE SHEET ZS CHANGED ENGINE OIL AND FILTERS CHECKED COOLANT -40DEG CCH@389	,		\$0.00
Maintenance Performed					Cost
SERVICE					\$0.00
Total:					\$0.00
10/06/2021	329,536	CARRY OUT 20,000 KM SERVICE AS PER SERVICE SHEET AL, ZS DID NOT CHANGE ENGINE OIL AND FILTERS CHECKED COOLANT -40DEG CCH@ 410 REPLACED BELTS & TENSIONERS =WARRANTY= COOLANT LEAK FROM HEADER TANK POWER STEERING HOSE LEAK	,		\$0.00
Maintenance Performed					Cost
SERVICE					\$0.00
Total:					\$0.00
14/07/2021	348,971	CARRIED OUT 20,000KM SERVICE AS PER SERVICE SHEET AL CHANGED OIL AND FILTERS COOLANT -40DEG CCH@410	,		\$0.00
Maintenance Performed					Cost
SERVICE					\$0.00
Total:					\$0.00
30/08/2021	371,325	CARRIED OUT 20,000KM SERVICE AS PER SERVICE SHEET JI, ZS, RS DID NOT CHANGE ENGINE OIL OR FILTERS CHECKED COOLANT -40DEG CCH@410 REPLACED FRONT DRIVE AXLE BRAKE PADS AND CALIPERS REPLACED L/H BULL BAR HIGH BEAM GLOBE	,		\$0.00
Maintenance Performed					Cost
SERVICE					\$0.00
Total:					\$0.00
20/12/2021	396,796	CARRIED OUT 100,000KM SERVICE AS PER SERVICE SHEET ZS AL CHANGED OIL AND FILTER COOLANT -45DEG CCH@450	,		\$0.00

Maintenance Performed			Cost
SERVICE			\$0.00
Total:			\$0.00
27/01/2022	419,471	CARRY OUT 20,000 KM SERVICE AS PER SERVICE SHEET ZS, RS DID NOT CHANGE ENGINE OIL OR FILTERS CHECKED COOLANT -35DEG CCH@488 REPLACED L/H SPOTTER MIRROR COVER	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
Total:			\$0.00
28/02/2022	437,763	CARRIED OUT 20,000KM SERVICE AS PER SERVICE SHEET JI, ZS CHANGED ENGINE OIL AND FILTERS CHECKED COOLANT -35 SERVICED CAB COOLER 498HRS REPLACED ALL DRIVE BRAKE PADS REPLACED DNO SIGNS	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
Total:			\$0.00
21/03/2022	449,246	REPLACED STARTING BATTERIES AL	\$0.00
Maintenance Performed			Cost
REPAIRS			\$0.00
Total:			\$0.00
4/04/2022	457,610	CARRY OUT 20,000 KM SERVICE AS PER SERVICE SHEET ZS,AL DID NOT CHANGE ENGINE OIL OR FILTERS CHECKED COOLANT -45DEG CCH@501 REPLACED BOTH STEER MUDGUARDS REPLACED GRILL WITH GRILL FROM B20	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
Total:			\$0.00
11/04/2022	462,060	DRIVERS #26148 REPAIRED WIRE AT EBS EXTENTION LEAD AL REPAIRED DRIVER WINDOW REGULATOR	\$0.00
Maintenance Performed			Cost
REPAIRS			\$0.00
Total:			\$0.00
2/05/2022	474,985	DRIVERS FAULT #28451 MOVED BOTH FUEL TANKS AL REPLACED FAULTY EBS LEAD RS	\$0.00
Maintenance Performed			Cost
REPAIRS			\$0.00
Total:			\$0.00

4/05/2022	476,849	CARRY OUT 20,000KM SERVICE AS PER SERVICE SHEET RS, ZS, JS CHANGED ENGINE OIL AND FILTERS COOLANT -43 507CCH REPLACED BROKEN LH STEER HUB STUD REPLACED FRONT RH DRIVE BRAKE ROTOR	,	\$0.00
-----------	---------	--	---	--------

Maintenance Performed	Cost
SERVICE	\$0.00
Total:	\$0.00

24/06/2022	499,817	CARRY OUT 100,000 KM SERVICE AS PER SERVICE SHEET RS, ZS, JI DID NOT CHANGE ENGINE OIL OR FILTERS CHECKED COOLANT -40DEG CCH@508 REPAIRED R/H REVERSE LIGHT WIRING REPLACED ALL L/H STEER WHEEL STUDS	,	\$0.00
------------	---------	---	---	--------

Maintenance Performed	Cost
SERVICE	\$0.00
Total:	\$0.00

28/07/2022	518,130	CARRY OUT 20,000 KM SERVICE AS PER SERVICE SHEET ZS, JS CHANGED ENGINE OIL AND FILTERS CHECKED COOLANT -42DEG CCH@508 REPLACED SUMP GASKET REPLACED REAR R/H LOWER SHACKLE BUSH	,	\$0.00
------------	---------	--	---	--------

Maintenance Performed	Cost
SERVICE	\$0.00
Total:	\$0.00

12/09/2022	539,900	CARRY OUT 20,000 KM SERVICE AS PER SERVICE SHEET ZS DID NOT CHANGE ENGINE OIL OR FILTERS CHECKED COOLANT -42DEG CCH@508 REPAIRED R/H BRAKE LIGHT REPLACED BELTS	,	\$0.00
------------	---------	--	---	--------

Maintenance Performed	Cost
SERVICE	\$0.00
Total:	\$0.00

11/10/2022	560,261	CARRIED OUT 20,000KM SERVICE AS PER SERVICE SHEET AL CHANGED OIL AND FILTERS COOLANT -45 DEG CCH@511 REPLACED EXHAUST BRAKE SOLINOID REPLACED CABLE TO LH MIRROR CAMERA REPLACE SD CARD IN CAMERA UNIT REPLACED INDICATOR STALK RS TIGHTEND UHF AERIAL AND TESTED OK	,	\$0.00
------------	---------	--	---	--------

Maintenance Performed			Cost
SERVICE			\$0.00
Total:			\$0.00
22/11/2022	586,173	CARRIED OUT 20,000 KM SERVICE AS PER SERVICE SHEET AL DID NOT REPLACE OIL OR FILTERS COOLANT - 45 DEG CCH@526 REPLACED RH FRONT LOWER SHOCKER RUBBERS REPLACED COOLANT HOSES AND COOLANT REPLACED LH MIRROR CAMERA REPLACED UHF AERIAL	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
Total:			\$0.00
9/01/2023	609,706	CARRY OUT 100,000 KM SERVICE AS PER SERVICE SHEET ZS, DW CHANGED ENGINE OIL AND FILTERS CHECKED COOLANT -38DEG CCH@560 ADJUSTED VALVES ==JOBS TO BE DONE== ENGINE OIL LEAKS	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
Total:			\$0.00
15/02/2023	632,978	CARRIED OUT 20,000KM SERVICE AS PER SHEET DW ZS DID NOT CHANGE OIL OR FILTERS COOLANT @-32DEG CCH @591	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
Total:			\$0.00
16/03/2023	650,649	CARRIED OUT 20,000KM SERVICE AS PER SHEET JS ZS CHANGED ENGINE OIL AND FILTERS COOLANT-32DEG CCH@627 REPLACED BELTS AND TENSIONERS JS REPAIRED FRONT AIR VALVE LEAK ZS	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
Total:			\$0.00
27/04/2023	675,587	CARRIED OUT 20,000KM SERVICE AS PER SHEET BR DW DID NOT CHANGE OIL OR FILTERS COOLANT@-32 DEG CCH@667 REPLACED TRAILER LIGHT PLUG BR	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
Total:			\$0.00
28/06/2023	702,341		\$0.00

CARRIED OUT 100,000KM SERVICE AS
 PER SHEET JS DW
 CHANGED ENGINE OIL AND FILTERS
 COOLANT@-35 DEG
 CCH@671
 REPLACED SUMP GASKET
 RE SEALED POWER STEERING BOX
 REPLACED BIG POWER STEERING HOSE
 REPLACED RH INTERCOOLER TORSION
 ROD
 REPAIRED ENGINE BRAKE AIR VALVE
 LEAK
 REPLACED BOTH ENGINE MOUNTS
 REPLACED STEER BRAKE PADS
 REPLACED LH STEER CALIPER
 (REBUILT)
 REPLACED LH STEER WHEEL STUD AND
 NUT X1
 REPLACED REAR LH SHACKLE BUSH
 REPLACED LH STEER MUDGUARD
 REPLACED TURNTABLE JAWS

Maintenance Performed		Cost
ANNUAL CHECK		\$0.00
SERVICE		\$0.00
Total:		\$0.00

5/07/2023	702,341	OIL SAMPLE COME BACK AS HIGH IRON CONTENT CHECK OIL SAMPLE AND OPEN OIL FILTER NEXT SERVICE	,	\$0.00
-----------	---------	---	---	--------

Maintenance Performed		Cost
SERVICE		\$0.00
Total:		\$0.00

9/09/2023	722,617	CARRIED OUT 20,000KM SERVICE AS PER SHEET BC DIDN'T CHANGE ENGINE OIL AND FILTERS COOLANT @-35 DEG CCH 673.6 ===JOBS DONE=== REPLACED OIL FILL CAP (ROCKER COVER) REPLACED LH TENTIONER ===JOBS THAT NEED DOING=== AIR CON CLUTCH BROKEN OIL COOLER LEAKING BOTTOM REAR LH GAURD STRAP ROCKER COVER BREATHER PIPE LEAKING OIL (CLEANED CHECK)	,	\$0.00
-----------	---------	--	---	--------

Maintenance Performed		Cost
SERVICE		\$0.00
Total:		\$0.00

1/12/2023	746,639	CARRIED OUT 20,000KM SERVICE AS PER SHEET BR CHANGED ENGINE OIL AND FILTERS COOLANT@-31 DEG SERVICED CAB COOLER @697 HRS DW ===JOBS TO BE DONE=== AIRCON CLUTCH OIL COOLER LEAK ROCKER COVER BREATHER	,	\$0.00
-----------	---------	---	---	--------

Maintenance Performed			Cost
SERVICE			\$0.00
Total:			\$0.00
20/01/2024	764,136	REPLACED FAN HUB CLUTCH JS	\$0.00
Maintenance Performed			Cost
REPAIRS			\$0.00
Total:			\$0.00
5/02/2024	770,232	CARRY OUT 20,000 KM SERVICE AS PER SERVICE SHEET BC DID NOT CHANGE ENGINE OIL OR FILTERS CHECKED COOLANT -33DEG CCH @697 RESEALED EXHAUST BRAKE VALVE SUMP GASKET LEAK ROCKER COVER GASKET STARTING TO LEAK CLEANED RADIATOR	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
Total:			\$0.00
15/03/2024	789,614	CARRIED OUT 20,000KM SERVICE ASPER SHEET AR BC HA CHANED ENGINE OIL AND FILTERS COOLANT @-31 DEG CCH @698 REPLACED POWER STERING BOX	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
Total:			\$0.00
13/05/2024	811,414	CARRIED OUT 100,000KM SERVICE AS PER SHEET BC HA AR ZS DIDNT CHANGE ENGINE OIL AND FILTERS COOLANT @-31 DEG CCH @648 HRS REPLACED BELTS REPLACED SUMP GASKET	\$0.00
Maintenance Performed			Cost
ANNUAL CHECK			\$0.00
SERVICE			\$0.00
Total:			\$0.00
27/06/2024	832,170	CARRIED OUT 20,000KM SERVICE AS PER SHEET HA CHANGED ENGINE OIL AND FILTERS COOLANT @-33 DEG CCH @698 FRONT OF SUMP WEAPING OIL	\$0.00
Maintenance Performed			Cost
SERVICE			\$0.00
Total:			\$0.00
7/08/2024	851,534	CARRIED OUT 20,000KM SERVICE AS PER SHEET BC DW AR DIDNT CHANGE ENGINE OIL OR FILTERS COOLANT @-41 DEG CCH @698	\$0.00

CLEANED DIFF BREATHERS
CHECK BOTH DIFF FOR WHEEL SEAL
LEAKS NEXT SERVICE

Maintenance Performed		Cost
SERVICE		\$0.00
Total:		\$0.00

26/08/2024	858,919	RPLACED FRONT FAN HUB BEARING HA BC REPLACED FRONT MAIN SEAL RE-SEALED FRONT COVER RE-SEALED AIR LEAK ON RIGHT SIDE	\$0.00
------------	---------	--	--------

Maintenance Performed		Cost
REPAIRS		\$0.00
Total:		\$0.00

19/09/2024	870,964	CARRIED OUT 20,000KM SERVICE AS PER SHEET AR BC CHANGED ENGINE OIL AND FILTERS COOLANT @ -41 CCH @698 REAR DRIVE WHEEL SEALS STARTING TO WEEP	\$0.00
------------	---------	---	--------

Maintenance Performed		Cost
SERVICE		\$0.00
Total:		\$0.00

1/10/2024	875,686	REPLACED NOX SENSOR AFTER CATYLYST HA DW BC	\$0.00
-----------	---------	---	--------

Maintenance Performed		Cost
REPAIRS		\$0.00
Total:		\$0.00

9/11/2024	891,322	CARRIED OUT 20,000KM SERVICE AS PER SHEET DW DIDNT CHANGE ENGINE OIL OR FILTERS COOLANT @-30 CCH @698	\$0.00
-----------	---------	--	--------

Maintenance Performed		Cost
SERVICE		\$0.00
Total:		\$0.00

18/12/2024	906,123	(DRIVERS FAULT) 18/12/24 6:17:35 REPLACED TRAILER AIR PRESSURE SWITCH BC HA AR REPLACED RADIATOR DRAIN PLUG	\$0.00
------------	---------	---	--------

Maintenance Performed		Cost
REPAIRS		\$0.00
Total:		\$0.00

7/01/2025	912,273	CARRIED OUT 20,000KM SERVICE AS PER SHEET BC AR CHANGED ENGINE OIL AND FILTERS COOLANT @-40 DEG CCH @698 REPLACED RH BULL BAR HI BEAM GLOBE	\$0.00
-----------	---------	---	--------

Maintenance Performed		Cost
SERVICE		\$0.00
Total:		\$0.00

Total:	Cost Per Mi/Km/Hr:	\$0.00	\$0.00
---------------	---------------------------	---------------	---------------

Grand Total:			\$0.00
---------------------	--	--	---------------