## **All Maintenance**

Filters applied:

Asset Maintenance	Closed
Status	
Maintenance Type	A Service, B Service, Brake Test, C Service, D Service, Hydro/Hatch & Vent
Asset	HV288 Kenworth T608 783LAY
Asset Status	Active

Id	Crea	ated At	Туре	Asset Id	Description	Sub-type	Maintenance Type	Asset Maintenance Status	Description	Notes
	7797	30/01/2	023 Heavy Vehicles	HV288	Kenworth T608	Prime Mover	Repair	Closed	repair pyrometre, repair glove box & lights, repair listed defects	
	7793	30/01/2	023 Heavy Vehicles	HV288	Kenworth T608	Prime Mover	Repair	Closed	replace windscreen washers	
	6791	12/10/2	022 Heavy Vehicles	HV288	Kenworth T608	Prime Mover	Repair	Closed	Diagnose check engine light and oil temp gauge, oil temp sensor faulty, eng temp sensor faulty	
	5315	12/07/2	022 Heavy Vehicles	HV288	Kenworth T608	Prime Mover	Repair	Closed		g Repairs - finish torquing wheel nuts, change clutch brake, inspect system for operation
	5309	12/07/2	022 Heavy Vehicles	HV288	Kenworth T608	Prime Mover	Repair	Closed	Repairs	Finished brake shoes, drums and s-cams, torqued wheel nuts to 500, greased, checked system operation, adjusted brakes
	5308	12/07/2	022 Heavy Vehicles	HV288	Kenworth T608	Prime Mover	Repair	Closed	Inspect and check for defects	Replace rear diff brakes, replace rear s- cams and bushes, tighten gear box yoke and reassemble drive line, grease, fix air leaks
	5032	17/06/2	022 Heavy Vehicles	HV288	Kenworth T608	Prime Mover	Repair	Closed	foot brake pedal needs cleaning out - getting stuck	
	5031	17/06/2	022 Heavy Vehicles	HV288	Kenworth T608	Prime Mover	Repair	Closed	S-cam bushes need to be replaced	
	3817	21/03/2	022 Heavy Vehicles	HV288	Kenworth T608	Prime Mover	B Service	Closed	B Service	
	3204	25/02/2	022 Heavy Vehicles	HV288	Kenworth T608	Prime Mover	Brake Test	Closed		PASS

3197	25/02/2022 Heavy Vehicles	HV288	Kenworth T608	Prime Mover	Repair	Closed	Get PTO running and fix up stand hook air lines
							up
2229	30/11/2021 Heavy Vehicles	HV288	Kenworth T608	Prime Mover	D Service	Closed	D Service
2102	29/11/2021 Heavy Vehicles	HV288	Kenworth T608	Prime Mover	Repair	Closed	Air horn not working
							R&M 1728
892	01/10/2021 Heavy Vehicles	HV288	Kenworth T608	Prime Mover	Brake Test	Closed	