

Work Order History Report

26-May-2023

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
CB EME LDR 918#1		ClearyBros. Earthmoving Workshop Loader 918#1 (Getting SOLD)						
	303	Bad engine oil leak# Replaced O rings on fuel pump	31/05/2016	21176	Hours	0.0	0.0	\$0.00
	551	right hand rear tyre flat	18/06/2016		Hours	0.0	0.0	\$0.00
	685	Two new rear tyres fitted	20/06/2016	21228	Hours	0.0	0.0	\$0.00
	498	2 new tyres fitted to the rear of machine.	25/06/2016		Hours	0.0	0.0	\$0.00
	719	250 Hour Earthmoving service	04/07/2016	21260	Hours	0.0	0.0	\$0.00
	1677	Fit new bearings seals in center bearing	06/08/2016		Hours	0.0	0.0	\$0.00
	2931	500 Hour Earthmoving Service	18/11/2016	21530	Hours	0.0	0.0	\$0.00
	7812	Remove pedal assemblyClean and apply anti-seize refit and check operation	13/02/2017	21697	Hours	0.0	0.0	\$0.00
	4469	Rear yoke on diff very loose needs attentionComplete	20/02/2017		Hours	0.0	0.0	\$0.00
	4474	Water pump belt u/sComplete	20/02/2017		Hours	0.0	0.0	\$0.00
	7767	Pins not greasingFree up and grease all loader pins	08/03/2017		Hours	0.0	0.0	\$0.00
	4884	250 Hour Earthmoving service	21/03/2017	21770	Hours	0.0	0.0	\$0.00
	7756	Oil leakClean, remove guardsCheck for leaks, need parts to repair. left hand rear lights been hit, need to replace.	31/03/2017	21789	Hours	0.0	0.0	\$0.00
	7744	No 1st, 2nd and 3rd gear in forwardReplace #3 gear solenoid, remove and check suction screen, put gauges on trans pressure and it dropped off after a while. Put gauge in pump, pump pressure low at idle, when warm oil, replace oil filter, cleaned out orifice and check electrics. Drove OK but not sure if the problem is solved	13/05/2017		Hours	0.0	0.0	\$0.00
	8784	Not engaging gears all the timeRemoved cabremoved stripped and cleaned transmission valvesreplaced the 6 solenoids on	20/06/2017	21890	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading	Downtime (hours)	Repairtime (hours)	Cost
		transmission valvefitted transmission valvefront and front left window replacedremoved and replaced park brake shoes, cleaned all of the coal outcleaned transmission screendrained and replaced transmission oil					
	8816	Not always engaging in the gears	20/06/2017	Hours	0.0	0.0	\$0.00
	7295	oil leak LH lift ram	02/08/2017	Hours	0.0	0.0	\$0.00
	8347	Oil leakRear diff full of hydraulic oil	16/08/2017	Hours	0.0	0.0	\$0.00
	8348	Drain rear diff	17/08/2017	Hours	0.0	0.0	\$0.00
	8349	Rear brakesDisconnect rear brake supply, drain rear diff, fill hydraulic tank, fill diffBlown hydraulic pipe rusted out, replace with hose	30/08/2017	Hours	0.0	0.0	\$0.00
	9117	No air conditioningno rear brakesRemoved rear diffstripped rear brakesreplaced rear brake piston scals and friction disk and platefitted rear diffitted new A/C box in cabChanged A?C system from tx style to orifice tube systemadjusted hand brakegot the lights workingreplaced rear drive shaft and unitsreplaced rear pinion sealcleaned cabcharged all A/C filtersBled brakes	05/09/2017	Hours	0.0	0.0	\$0.00
	9044	Repair A/C	08/09/2017	Hours	0.0	0.0	\$0.00
	9194	500 Hour Earthmoving Service	04/10/2017	22040 Hours	0.0	0.0	\$0.00
	9565	A/C not workingChecked out and found to be low in gastopped up and all tested fineA/C refer 1672 A/C	10/10/2017	22043 Hours	0.0	0.0	\$0.00
	10077	Checked out had no gas so gave pressure test at 450psi but no leaks after 40 mins so vacced down and gassed up all tested fine	10/10/2017	22043 Hours	0.0	0.0	\$0.00
	9589	Front trans seal leakingReplace seal and park brake shoes, top up oil.	13/10/2017	22052 Hours	0.0	0.0	\$0.00
	10107	Couldn't get any gearsremoved cabremoved transmission valves, stripped and cleanedreplaced all solenoidsreplaced front transmission yoke sealfitted cabre adjust park brake cable	03/11/2017	Hours	0.0	0.0	\$0.00
	11793	Wont get gears, slow to pick up gears.Remove & clean plow control valve on inlet hose to transmission valves.Test pressures 350psi @ idle, remove & clean hyd trans valve bank.	22/12/2017	22512 Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	11915	Pre-release check sheet.Transmission not getting gears.Removed cab.Removed transmission/stripped cleaned/resealed.Replaced trans cooler lines.Replaced all uni bearings and centre bearing.Fitted centre bearing canister self greaser.New engine oil pressure light.Add extra trans filter and housing with oil bypass light, wired up to a light and buzzer.New front drive shaft yoke.Stripped and cleaned valves new seals.Fixed indicator.Fixed horn.	06/02/2018	22186	Hours	0.0	0.0	\$0.00
	12620	250HR Earthmoving service	04/04/2018	22304	Hours	0.0	0.0	\$0.00
	16134	Monthly inspectionReplaced rear stop/tail indicator light	31/05/2018	22397	Hours	0.0	0.0	\$0.00
	15565	2000 Hour earthmoving service	23/08/2018	22549	Hours	0.0	0.0	\$0.00
	14699	Blown hoseCalled pirtek	02/10/2018		Hours	0.0	0.0	\$0.00
	17061	coolant leakRemoved radiator pin hole in bottom tank Radiator sent to ecezleys radiator repairs for bottom tank repair Refit radiator and filled with afloc	09/10/2018	22595	Hours	0.0	0.0	\$0.00
	17846	electrical problemStarter U/SReplaced starter motor (CAT OR) Replaced fuel stop solenoid	14/11/2018		Hours	0.0	0.0	\$0.00
	18490	fitting leaking on lift ramCalled pirtek	17/12/2018		Hours	0.0	0.0	\$0.00
	18770	A/C not cold also oil leaks need to be fixed check wich window cracked	09/01/2019		Hours	0.0	0.0	\$0.00
	18575	Fitting broken on 4 in 1 bucket Called pirtek	11/01/2019		Hours	0.0	0.0	\$0.00
	19169	250HR Earthmoving service	31/01/2019	22789	Hours	0.0	0.0	\$0.00
	19268	brakes sticking on	06/02/2019		Hours	0.0	0.0	\$0.00
	19506	Broken Front windows and wiring hanging down needs new door seals and wipers.Replace front window Repair cab wiring New park brake shoes and cableNew engine oil pressure switch New rear tail lights New centre drive shaft(reco daniels) New seal front of transmission output sealRepair horn wiring New window and door seals Repair A/C wiring new thermostat	25/02/2019	22830	Hours	0.0	0.0	\$0.00
	19943	Install new roof lining tidy up wiring for music player replace o ring on LHS steering cylinder at rear	13/03/2019	22861	Hours	0.0	0.0	\$0.00
	22227	install gpsBen Patrick	08/06/2019	23008	Hours	0.0	0.0	\$0.00
	25080	Tyre repairPremium tyres see attach	19/06/2019	23029	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	Done	Reading	Downtime (hours)	Repairtime (hours)	Cost
	22412	front pinion seal leakingfront diff pinion bearings/seal u/s remove front pinion,rebuild new bearings/seals,pinion &nutmake new seal carrier ,replace center bearing,replace front uni joint,replace trans filters,replace trans oil(30w oil used),replace LH light on cabBen Patrick	25/06/2019	23040	Hours	0.0	0.0	\$0.00
	22375	500 Hour Earthmoving Service	18/07/2019	23102	Hours	0.0	0.0	\$0.00
	23329	Needs pinion seal, Front brakes U/S and diff fuel of coal.PKWS	29/07/2019		Hours	0.0	0.0	\$0.00
	26953	250 Hour Earthmoving Service	06/12/2019	23333	Hours	0.0	0.0	\$0.00
	25172	blown hose Pirtek called and repaired	10/12/2019		Hours	0.0	0.0	\$0.00
	28905	Won't drive dropping out of gearTop up trans oil check drives okCheck for leaks, front drive seal leaking, replaced seal topped up oil, check dive okCenter bearing play, park brake cable U/S	14/01/2020	23385	Hours	0.0	0.0	\$0.00
	28980	Flashing light dullReplace flashing light	20/02/2020	23455	Hours	0.0	0.0	\$0.00
	28977	Park brake cable stickyInstall new park brake cable and adjust Preform park brake test 2nd gear high idle no movement detected	21/02/2020	23459	Hours	0.0	0.0	\$0.00
	29027	R/F TYRE FLAT POS.1 24/2/2020Remove R.H frontGive to premium tyres to repairInstall R.H front tyre	24/02/2020		Hours	0.0	0.0	\$0.00
	30822	Oil leaks Monthly insoectionsRemove steel hydraulic line replace orings for 3 in 1 hose on bucket due to exposed wire/rustcentre bearing some playB Patrick	15/04/2020		Hours	0.0	0.0	\$0.00
	30555	500 Hour Earthmoving Service	17/04/2020	23566	Hours	0.0	0.0	\$0.00
	32611	Wont drive clunk noiseReplace trans filters,replace center bearing & seals,replace front trans seal,Clean and adjust park brake,remove z-link pins clean out grease holesB Patrick	25/05/2020	23647	Hours	0.0	0.0	\$0.00
	32840	Front glass crackedReplace LH & front glass(used cat glass),straighten window frameB Patrick	10/06/2020	23678	Hours	0.0	0.0	\$0.00
	34592	Indicators/stop tail not workingRepair wiring to lights,replace flasherB Patrick	22/07/2020	23756	Hours	0.0	0.0	\$0.00
	34949	250 Hour Earthmoving Service	10/08/2020	23798	Hours	0.0	0.0	\$0.00
	35738	Rear uni joints u/sReplace rear universal joints X 2,rear drive shaft,grease all jointsBen P	29/09/2020		Hours	0.0	0.0	\$0.00
	37339	Transmission leakReplace front output seal, clean out park	17/10/2020		Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
		brake, adjust park brakeBen P						
	38498	Slow to go into gearsTest pump pressures-ok, test FWD pack pressure-ok, slow to rise in pressure, replace valve assem. 3E-6269, reverse also slow to rise, remove gauze screen from end of valve, filled with what looks to be filter paper, test drive okBen P	25/11/2020	23999	Hours	0.0	0.0	\$0.00
	38764	Centre bearing u/sRemove centre bearing assembly, wrong bearing supplied, order correct bearingInstall new centre bearing, grease machine:note drive shafts & yokes wornBen P	03/12/2020		Hours	0.0	0.0	\$0.00
	38243	500 Hour Earthmoving Service	09/12/2020	24021	Hours	0.0	0.0	\$0.00
	39952	Trans oil leakR&R trans yoke shaft seals, clean out park-brake drum's & shoe'sR&R broken drum bolt, refill trans, diffs, check levelsBrad W	09/01/2021	24067	Hours	0.0	0.0	\$0.00
	41084	Park brake not holding during testReplace shoe's, clean coal slurry out of drum's and adjustBen P	23/02/2021	24153	Hours	0.0	0.0	\$0.00
	40639	Rear diff oil leakReplace rear diff pinion seal & yoke, installed new bolts/ strap for universal jointBen P	02/03/2021	24164	Hours	0.0	0.0	\$0.00
	42225	Front left tyre flatremoved tyre took to premium tyre's and got replaced and refittedC BuckPremium tyre'ssee attach)	06/04/2021	24224	Hours	0.0	0.0	\$0.00
	47501	External Tyre InspectionInspection done by Premium Tyres	07/04/2021		Hours	0.0	0.0	\$0.00
	42835	Low oil/water levels, pin wont greaseTop up fluids, check for leaks, remove all loader frame pins , clean out grease holes, grease uni-joints and all pinsBen P	14/04/2021	24238	Hours	0.0	0.0	\$0.00
	42161	250 Hour Earthmoving Service	14/04/2021	24239	Hours	0.0	0.0	\$0.00
	43568		17/05/2021		Hours	0.0	0.0	\$0.00
	45891	Centre bearing u/sReplace driveshaft centre bearing	25/06/2021		Hours	0.0	0.0	\$0.00
	46062	Cutting edges wornInstall new cutting edges. 2x 1u0607-centre edge 2x 4t8091 bit end. Repl. UHF & music whips	22/07/2021	24420	Hours	0.0	0.0	\$0.00
	44769	See work order 46062	27/07/2021		Hours	0.0	0.0	\$0.00
	46078	2000 Hour Earthmoving Service	27/08/2021	24500	Hours	0.0	0.0	\$0.00
	47040	Park brake needs adjustingAdjust Park Brake Ben P	18/09/2021	24532	Hours	0.0	0.0	\$0.00
	48464	Blown hoseHose repaired by Pirtek Campbelltown	14/10/2021		Hours	0.0	0.0	\$0.00
	48609	Replace turboreplace turbo CAT OR, new seals gaskets used, 2xnew hose turbo outletBen P	19/10/2021	24609	Hours	0.0	0.0	\$0.00

Asset	W/O No	Description	Finished	DoneReading		Downtime (hours)	Repairtime (hours)	Cost
	49961	Blown transmission filterReplace transmission filters(2x donaldson) drain and change oil trans oil, water presentCheck for leaks test-ok, wash down machineBen P	22/11/2021	24673	Hours	0.0	0.0	\$0.00
	50584	Replace centre bearing and seals, install new yoke grease machine(#Centre and front drive shaft slip joints very worn) Won't drive bearing failed in alternator Replaced alternator gears ok Ben P	08/12/2021	24701	Hours	0.0	0.0	\$0.00
	50312	250 Hour Earthmoving Service	14/12/2021	24720	Hours	0.0	0.0	\$0.00
	48199	Park brakedrums replacedShoes cleaned	28/01/2022		Hours	0.0	0.0	\$0.00
	51761	Back up alarm replaced and wiring repairedReplaced wiper blades	08/02/2022		Hours	0.0	0.0	\$0.00
	53133	oil leak # pirtek made blown hose	12/05/2022		Hours	0.0	0.0	\$0.00
	54508	500 Hour Earthmoving Service	20/05/2022	24942	Hours	0.0	0.0	\$0.00
	55375	Replaced front brake supply line	02/06/2022	24966	Hours	0.0	0.0	\$0.00
	56398	-Replaced centre bearing-Replaced seat cushion, -Replaced park brake shoes and adjusted	07/07/2022	25035	Hours	0.0	0.0	\$0.00
	56625	Front window re-installed	16/07/2022	25061	Hours	0.0	0.0	\$0.00
	57824	250 Hour Earthmoving Service	31/08/2022	25142	Hours	0.0	0.0	\$0.00
	56366	Park brake cable and switch adjusted	02/11/2022		Hours	0.0	0.0	\$0.00
	60477	Front diff pinion seals and front uni replaced	11/11/2022		Hours	0.0	0.0	\$0.00
	60640	LHR wheel puncture repaired	17/11/2022		Hours	0.0	0.0	\$0.00
	61227	Belts replaced	28/11/2022		Hours	0.0	0.0	\$0.00
No of W/O for 918#1		:	94	Asset Total:	918#1	0.0	0.0	\$0.00
No of W/O for CB		:	94	Parent Total:	CB	0.0	0.0	\$0.00
Grand Total			94			0.0	0.0	\$0.00