

## Service and Expense Summary

[25] 2006 D6R LGP Cat Dozer CATERPILLAR (YELLOW)

CAT00D6RELGP00362

Date	Odometer	Description	Notes	Cost
8/09/2016	14,300.0	Repairs and Full Service	PAINTED MACHINE SITECH FITTED GPS SYSTEM HAD BOTH LIFT CYLINDERS RESEALED HAD TRACK ADJUSTER RESEALED FITTED NEW CHAINS TO EXISTING GROUSER PLATES FITTED NEW CARRIER ROLLER FITTED NEW SPROCKET SEGMENTS BOTH SIDES NEW EXHAUST PIPE FULL ENGINE AND HYDRAULIC SERVICE, CHANGED OILS AND FILTERS	\$0.00
16/09/2016	14,342.0	REPAIRS	New Lift Ram Seals x2 New Track Chains x2 New Track Segments (Left and Right sides) Fire Extinguisher fitted New exhaust tip	\$0.00
2/11/2016	14,601.0	Service -250 hour	Serviced change engine, transmission and fuel filters. Grease	\$0.00
4/01/2017	14,942.0	MAINTENANCE	Tighten and replace bush bolts Repair hydraulic oil leak	\$0.00
11/01/2017	14,983.0	REPAIRS	Replace, repair hydraulic hose	\$0.00
10/02/2017	15,099.0	MAINTENANCE	Remove and replace heater fan	\$0.00
7/04/2017	15,196.0	REPAIRS	Repair oilk leak	\$0.00
19/04/2017	15,245.0	Repairs and Full Service	New Starter Motor HT Auto inv4278	\$0.00
26/07/2017	15,595.0	FULL SERVICE	Replace adjustable link Change air filters Serviced Repaired oil leak on filter mount	\$0.00
4/08/2017	15,652.0	MAINTENANCE	Replace idler, cut, weld and refit. 12HRS DEALS RD	\$0.00
25/09/2017	15,701.0	REPAIRS	Fitted new D-rings on line off main hyd pump.	\$0.00
18/10/2017	16,010.0	FULL SERVICE	Engine service. Replace rear idler and roller. 8HRS HENRY ST	\$0.00
21/10/2017	16,058.0	REPAIRS	Link Assembly remove and repair and clean.	\$0.00

## Service and Expense Summary

[25] 2006 D6R LGP Cat Dozer CATERPILLAR (YELLOW)

CAT00D6RELGP00362

Date	Odometer	Description	Notes	Cost
2/11/2017	16,075.0	REPAIRS	New Hydraulic Filters New Transmission filters New Air Filter New Seals in Fuel Cap Fix Air Con. 6HRS HENRY ST	\$0.00
23/11/2017	16,129.0	REPAIRS	Weld alternator bracket, weld adjusting arm. 1HR HENRY ST	\$0.00
16/01/2018	16,397.0	MAINTENANCE	Replace battery, needs a new battery box. 2HRS HENRY ST	\$0.00
30/01/2018	16,450.0	MAINTENANCE	Rewire UHF Fix battery mounts.	\$0.00
8/02/2018	16,499.0	MAINTENANCE	Replace battery and terminals, reset battery in housing.3HRS HENRY ST	\$0.00
23/02/2018	16,582.0	MAINTENANCE	Tighten segments and replace roller. 5HRS HENRY ST	\$0.00
28/02/2018	16,641.0	MAINTENANCE	Tighten Bolts on Idler cap. Clean radiator. 2HRS HENRY ST	\$0.00
2/03/2018	16,650.0	FULL SERVICE	Serviced, changed engine, transmission air inner and outer, fuel filters	\$0.00
13/04/2018	16,708.0	REPAIRS	Removed belly plates and cleaned engine bay and plates. 3.5HRS DROUIN	\$0.00
18/04/2018	16,729.0	REPAIRS	Removed engine bay, doors and bronnet. removed muffler. replaced grouzer plate. 4.5HRS DROUIN	\$0.00
24/04/2018	16,761.0	MAINTENANCE	Muffler, oil cooler gaskets.	\$0.00
24/04/2018	16,761.0	MAINTENANCE	Remove worn rollers and replace with new ones. 8HRS DROUIN	\$0.00
30/04/2018	16,769.0	REPAIRS	Repair final drive - replace o-ring seals. 4HRS	\$0.00
1/05/2018	16,769.0	REPAIRS	Remove seat and plates, steering box and valve body, replace drive seals. Test. 8HRS	\$0.00
7/05/2018	16,775.0	MAINTENANCE	Refit tracks to dozer. 5HRS	\$0.00
8/05/2018	16,775.0	MAINTENANCE	Fit shims to draft arm 4HRS	\$0.00
16/05/2018	16,775.0	MAINTENANCE	Replaced Center Pinb and Bushes. 2HRS DROUIN	\$0.00
17/05/2018	16,775.0	MAINTENANCE	Replaced lights with LED. 2HRS DROUIN	\$0.00
21/05/2018	16,781.0	MAINTENANCE	Replace shims on blade. 4HRS DROUIN	\$0.00

## Service and Expense Summary

[25] 2006 D6R LGP Cat Dozer CATERPILLAR (YELLOW)

CAT00D6RELGP00362

Date	Odometer	Description	Notes	Cost
5/06/2018	16,796.0	MAINTENANCE	Tighten segment bolts. 1HR	\$0.00
25/06/2018	16,845.0	REPAIRS	Replace Stabilizer bar. 4HRS	\$0.00
27/10/2018	17,180.0	MAINTENANCE	Replace pilot valve seals, reassemble unit. Changed hydraulic filters, changed hydraulic oil. 6HRS DROUIN	\$0.00
27/10/2018	17,180.0	Service.	Service. Replace pilot valve seals, reassemble unit. Changed hydraulic filters, changed hydraulic oil.	\$0.00
2/11/2018	17,189.0	REPAIRS	Replaced Tilt Ram how. Wekded new guard over hose. 3HRS HAMPTON PARK	\$0.00
13/11/2018	17,241.0	REPAIRS	Source problem with Air conditioner. needs a new thrmostate and a new compressor. Repaired oil leak. Replaced oring. 6HRS	\$0.00
29/11/2018	17,294.0	REPAIRS	Replace blown transmission hose. Main Line. 4HRS HALLAM TIP	\$0.00
30/01/2019	17,437.0	Service.	Service. Oil change. Replaced engine oil. Replaced oi, air, fuel, hydraulic cabin and transmission filters. Greased. Topped up transmission oil and Hydraulic oil. Checked final drive oil level. General inspection of machine. 2.5HRS SHAMROCK	\$0.00
12/02/2019	17,489.0	MAINTENANCE	Remove worn out idler and 2 rollers. Replaced. Reshimmied draft arms. 9HRS HAMPTON PARK	\$0.00
7/03/2019	17,602.0	REPAIRS	Removfe side wall of track casing remove broken bolts. Replace side wall, replace cap, bolts and pin. Tension. Tensioned up track bolts as well. 4HRS HALLAM RD	\$0.00
22/03/2019	17,776.0	REPAIRS	Fit new Link Assembly and clean tracks. Inv 7478 Track Repairs PL	\$0.00
26/03/2019	17,803.0	REPAIRS	Remove broken exhaust manifold studs and replace. 4HRS HAMPTON PARK	\$0.00
9/04/2019	17,866.0	SERVICE - 500 HR	250 Hour Service. lipped cutting edges, new corner tiups, adjust alternator belt. 6HRS HALLAM RD.	\$0.00
11/04/2019	17,878.0	REPAIRS	REMOVED AND REPLACED WATERPUM,P, HOSES AND BELTS. REMOVED MANIFILD AND EXTRACCTED BROKEN STUDS, REPLACED NEW STUDS, BOLTS, NUTS AND GASKETS. 9HRS HALLAM RD.	\$0.00
31/05/2019	18,014.0	Service -250 hour	Performed 250hr service. Changed all filters and greased	\$0.00

*Service and Expense Summary*

[25] 2006 D6R LGP Cat Dozer CATERPILLAR (YELLOW)

CAT00D6RELGP00362

Date	Odometer	Description	Notes	Cost
20/07/2019	18,231.0	REPAIRS	Replace damaged hydraulic hose. Invoice 1515 JEV Engineering	\$0.00
2/08/2019	18,252.0	MAINTENANCE AND SERVICE	Performed a 250 hour service, replaced leaking transmission o/rings.Repaired front light.Welded a new bracket on tilt ram. Repaired draft arm plates.	\$0.00
16/08/2019	18,300.0	Service, repairs	Performed a 250 hour service. Replaced injector orings.Repaired steering box oil leak. Repaired stabiliser bar leak. Replaced dust extraction hose.	\$0.00
9/09/2019	18,320.0	Repairs and Full Service	Stripped machine, sanded ,repaired rust patches,repared both bonnet doors,repared bonnet,repared battery enclosure, replaced both lift rams. Replaced bottom roller.Repaired all hydraulic leaks.Repaired both trunions. Repaired air intake group.Repaired door latches and replaced strikers. Painted machine and fitted with new identification stickers and safety labels. Also replaced front and rear windscreens. Repaired dash and surrounds.	\$0.00
11/09/2019	18,320.0	MAINTENANCE	Replaced injector loom.Replaced broken and bent push rods on number 5 cylinder. Completed a full valve set. Drained oil and chasnged filter as fuel was evident after the faild push rods. Completed at Patho.	\$0.00
30/01/2020	18,533.0	REPAIRS	Repaired stabiliser arm from push arm to center of blade....Replaced injectors 5 and 2. were leaking diesel into the engine oil.	\$0.00
30/01/2020	18,533.0	REPAIRS	Replaced both batterys.	\$0.00
11/02/2020	18,589.0	MAINTENANCE	Remove belly plate remove and replace blown transmission feed hose.	\$0.00
24/02/2020	18,643.0	Service, repairs	Performed a 250 hr service Repaired broken cannon mounting left side.	\$0.00
24/06/2020	18,848.0	REPAIRS	Replaced left side chain.	\$0.00
29/07/2020	18,951.0	250 hour service	Performed a 250 hour service. Machine needed jump starting	\$0.00
5/08/2020	18,978.0	REPAIRS	Replaced tensioner pulley bearing ..Adjusted belts	\$0.00
16/02/2021	19,735.0	250 hour service	Performed a 250 hour service	\$0.00
3/04/2021	19,852.0	REPAIRS	RHS draft arm remove old bearign and cap. clean up weld and adjust shims. Scoresby	\$0.00

*Service and Expense Summary*

[25] 2006 D6R LGP Cat Dozer CATERPILLAR (YELLOW)      CAT00D6RELGP00362

Date	Odometer	Description	Notes	Cost
27/10/2021	0.0	REPAIRS	Replace Hi-Ten bolts, nuts and washers.	\$0.00
			Sub Total:	\$0.00
			Grand Total:	\$0.00