

CS533E CATERPILLAR SMOOTH DRUM ROLLER

YEAR	2011
PIN.	CATCS533LTJL02050
SERIAL No.	TJL02050
ENGINE No.	CST02716
ENGINE MODEL	3054C
MODEL	CS533E
ID No.	504
CONDITIONAL REGO No.	94845D
CONDITIONAL REGO EXPIRY	20/01/2025
UPDATED	12/02/2024

DATE	HOURS	JOB / SERVICE TYPE	SERVICE / REPAIR DETAIL
1/08/2016	1043	Pre-start	
3/08/2016	1044	Urgent	New batteries fitted (onsite stolen) , new cables made up and fitted, rear lamp wiring repaired
12/08/2016	1057	Pre-start	
18/08/2016	1069	Pre-start	
26/08/2016	1073	Pre-start	
9/09/2016	1083	Pre-start	
16/09/2016	1095	Pre-start	
21/10/2016	1113	Pre-start	
28/10/2016	1117	Urgent	UHF radio power harness changed.
28/10/2016	1117	Pre-start	
5/11/2016	1127	Pre-start	
11/11/2016	1137	Pre-start	UHF cradle needs repair.
19/11/2016	1138	Pre-start	
26/11/2016	1158	Pre-start	
4/12/2016	1162	Pre-start	
7/12/2016	1164	Pre-start	
22/12/2016	1179	Pre-start	
23/12/2016	1180	Pre-start	
12/01/2017	1186	Pre-start	
19/01/2017	1192	Pre-start	
25/01/2017	1192	Pre-start	
13/02/2017		Fuel truck	Greased

7/04/2017	1232	Pre-start	
12/04/2017	1241	Pre-start	
21/04/2017	1248	Pre-start	
28/04/2017	1258	Pre-start	
5/05/2017	1271	Pre-start	
12/05/2017	1280	Pre-start	
19/05/2017	1294	Pre-start	
26/05/2017		Fuel truck	Greased
27/05/2017	1321	Pre-start	
3/06/2017	1332	Pre-start	Low engine oil Topped up Nick J 7/06/2017
6/06/2017	1339	Pre-start	
16/06/2017	1354	General	Losing coolant, unable to find leak point, topped up 2 ltrs. R & rR directio control handle that had been incorrectly fitted previously.
16/06/2017	1352	Pre-start	Eng oil low - topped up
24/06/2017	1368	Pre-start	
1/07/2017	1378	Pre-start	
21/07/2017	1408	Pre-start	
28/07/2017	1415	Pre-start	
4/08/2017	1428	Pre-start	
19/08/2017	1454	Pre-start	Low coolant - topped up, needs new reservoir, oil needs topping up, door latch faulty.
23/08/2017		Fuel truck	Greased
24/08/2017		Fuel truck	Greased
25/08/2017	1467	Pre-start	Door latch faulty, low eng oil.
8/09/2017	1512	Pre-start	
21/09/2017	1532	Service	Service machine, r & r all filters, replace broken water separator bowl, repaired faulty a/c fan. Tested machine - all ok
21/09/2017		SOS	
21/09/2017		SOS	
21/09/2017		SOS	
21/09/2017		SOS	
21/09/2017		SOS	
21/09/2017		Remac	1.0 KG ABE Fire Extinguisher
21/09/2017	1532	SOS Sample	T120-47268-0341
21/09/2017	1532	SOS Sample	T120-47268-0340
21/09/2017	1532	SOS Sample	T120-47268-0341
21/09/2017	1532	SOS Sample	T120-47268-0340

11/10/2017	1570	General	Re-set circuit breaker for a/c.
16/10/2017	1586	Pre-start	
17/10/2017		Fuel truck	Greased
31/10/2017	1617	General	Replaced alternator belts & a/c belt, tested - ok.
3/11/2017		Fuel truck	Greased
4/11/2017	1628	Pre-start	Hyd hosedrum replaced - Pirtek
10/11/2017	1648	Pre-start	
21/11/2017		Fuel truck	Greased
24/11/2017	1676	Fuel truck	Greased
29/11/2017	1682	Fuel truck	Greased
1/12/2017	1686	Pre-start	
7/12/2017	1688	Pre-start	
13/12/2017	1691	Fuel truck	Greased
16/12/2017	1693	Pre-start	
22/12/2017	1698	Pre-start	
5/01/2018	1703	Pre-start	
12/01/2018	1718	Pre-start	Fire extinguisher missing
20/01/2018	1734	Pre-start	Fire extinguisher missing
25/01/2018	1738	Pre-start	Fire extinguisher missing
2/02/2018	1744	Pre-start	
16/02/2018		Pre-start	A/C not working, front rubber flap missing.
19/02/2018	1754	Pre-start	A/C not working
20/02/2018		Remac	1 x 1.5 Kg extinguisher
22/02/2018	1756	General	A/C fault, found & reset fuse, all pk, checked belts & compressor - ok no leaks. Fitted new extinguisher in cab, blew out cab filter.
2/03/2018		Pirtek	Replace case drain hose from main drive motor to valve under roller.
3/03/2018	1767	Pre-start	
9/03/2018	1778	Pre-start	
19/03/2018	1779	Pre-start	
20/03/2018	1781	Pre-start	
27/03/2018	1789	Pre-start	
29/03/2018		Fuel truck	Greased
7/04/2018	1799	Pre-start	
13/04/2018	1803	Pre-start	A/C not working.
18/04/2018	1803	Pre-start	
4/05/2018	1805	Pre-start	

28/05/2018	1807	Pre-start	A/C not working
31/05/2018	1807	Fuel truck	
31/05/2018	1807	Service	Serviced machine, r & r lube, hyd & air filters.
31/05/2018		SOS	
31/05/2018		SOS	
31/05/2018		SOS	
31/05/2018		SOS	
31/05/2018	1807	SOS Sample	T120-48155-0434
31/05/2018	1807	SOS Sample	T120-48155-0323
31/05/2018	1532	SOS Sample	T120-48155-0647
31/05/2018	1807	SOS Sample	T120-48155-0434
31/05/2018	1807	SOS Sample	T120-48155-0323
31/05/2018	1532	SOS Sample	T120-48155-0647
4/06/2018	1807	SOS Sample	T120-48155-0354
4/06/2018	1807	SOS Sample	T120-48155-0354
8/06/2018	1807	4397	Check & grease machine, found a/c fan circuit breaker popped, reports of fan cutting out, ran machine a/c operating correctly, belt ok - no obvious fault.
21/06/2018		General	Checkover - ok.
26/06/2018	1807	Pre-start	
2/07/2018	1808	Pre-start	
4/07/2018	1809	General	remove, repair & refit door latch, install inspected fire extinguisher, fit grease nipples to articulation points, repair f/r lever, checkover - ok. Greased (fuel truck)
6/07/2018	1809	General	Replace broken park brake knob.
31/07/2018		Remac	Check 1 x 1.5 Kg extinguisher
2/08/2018	1811	Pre-start	
14/08/2018	1817	Pre-start	
20/08/2018		Premium	Repair tyre
21/08/2018	1817	General	Check over, wash & grease
19/10/2018	1819	Pre-start	Fan belt slipping.
26/10/2018	1825	Pre-Start	
20/11/2018	1834	General	Top up HYD oil check for HYD fault, Do not have program westrac to fix
29/11/2018		Westrac	Inspct machine No drive Find fault failed coupling
7/12/2018	1834	General	Check Hyd pump, Remove eng due to failed coupling,replace exhaust gasket,replace sump gasket repair boost fitting, replace engine coupling.
20/03/2019	1837	General	504
1/05/2019	1839	Pre-start	Low on coolant

6/05/2019	1852.6	Pre-start	
7/05/2019	1853.3	Pre-start	
9/05/2019	1856.5	Pre-start	
9/05/2019	1858	General	Top up coolant. Grease machine. Check oils. Blow out filters and coolers
20/05/2019	1880	General	Refit forward reverse leaver
22/05/2019	1883	Pre-start	
23/05/2019	1886	Pre-start	
29/05/2019	18909	Pre-start	
30/05/2019	1891.7	Pre-start	
31/05/2019	1894.8	Pre-start	
7/06/2019	1908	Pre-start	
11/06/2019	1911	Pre-start	
12/06/2019	1914	Pre-start	
12/06/2019	1914	Pre-start	
13/06/2019	1920.8	Pre-start	
14/06/2019	1924.4	Pre-start	
15/06/2019	1929	Pre-start	
19/06/2019	1934.4	Pre-start	
3/07/2019	1949	Pre-start	
8/07/2019	1956	Pre-start	
9/07/2019	1961	Pre-start	
10/07/2019	1965	Pre-start	
18/07/2019	1986.9	Pre-start	
23/07/2019	1993.3	Pre-start	
30/07/2019	2001.1	Pre-start	
31/07/2019	2003	Pre-start	
1/08/2019	2006	Pre-start	
2/08/2019	2010.8	Pre-start	
5/08/2019	2012.2	Pre-start	
6/08/2019	2014	Pre-start	Struts not working on bonnet
7/08/2019	2021	Pre-start	Struts not working on bonnet
9/08/2019	2028	Pre-start	
9/08/2019	0	General	Battery
9/08/2019	0	General	Battery
12/08/2019	2035.8	Pre-start	
13/08/2019	2044.2	Pre-start	

14/08/2019	2051.7	Pre-start	
15/08/2019	2060.3	Pre-start	
16/08/2019	2065.7	Pre-start	
2/09/2019	2086	Pre-start	
3/09/2019	2091	Pre-start	
4/09/2019	2093	Pre-start	Strut to hold up bonnet not working
9/09/2019	2101	Pre-start	
10/09/2019	2103	Pre-start	
12/09/2019	2114.5	Pre-start	
13/09/2019	2117	Pre-start	
26/09/2019	2137	Pre-start	
30/09/2019	2144	Pre-start	
30/09/2019	0	General	hyd hose
30/09/2019	0	General	hyd hose
3/10/2019	2148	Pre-start	
14/10/2019	2154	Pre-start	
15/10/2019	2157.5	Pre-start	
16/10/2019	2159	Pre-start	
17/10/2019	2165	Pre-start	
18/10/2019	0	General	Fuel transfer pump
18/10/2019	0	General	Fuel transfer pump
24/10/2019	2171	Pre-start	
1/11/2019	2174.9	Pre-start	
4/11/2019	2177.9	Pre-start	
11/11/2019	2185	Pre-start	Air con not working
21/11/2019	2197	Pre-start	Air con doesn't work, the back good does not stay up when trying to restart machine
22/11/2019	2198	Pre-start	Air con does not work, stereo does not work, window gets jammed when opened all the way (right hand side) engine hood does not remain opened making it hard to do a pre start
25/11/2019	2199	Pre-start	Right window gets stuck when down as air con does not work Air conditioner does not work The bonnet does not stay open hard to do more start Right side window gets stuck when down
26/11/2019	2200.2	Pre-start	
27/11/2019	2205.4	Pre-start	Window crackedHood shocks not working
3/12/2019	0	General	Bonnet struts
3/12/2019	2212	General	Replace 2 rear hood gas struts
3/12/2019	0	General	Bonnet struts

5/12/2019	2213	General	Checkover machine. Blowout coolers and filters. Check electrical system.
10/12/2019	2220.3	Pre-start	
20/12/2019	22240	Pre-start	
9/01/2020	2228	General	Replace and rewire flashing light
22/01/2020	2228	Urgent	Repair rear vision mirror and isolator lock out assembly
5/02/2020	2229	Pre-start	Broken window Broken two way Ariel
21/02/2020	2240	Pre-start	
5/03/2020	0	General	Front glass replaced
27/03/2020	2250	Pre-start	
8/04/2020	2256	Pre-start	
17/04/2020	2264	Pre-start	
28/04/2020	2268	Pre-start	
5/05/2020	2273	Urgent	Remove failed rubber mounts. Replace 4x but waiting on 2x. Repair Horn. Replace headlight globe and indicator globe. Top up hydraulic oil. Grease. Repair washer tube. Checkover driveline and electrical system.
7/05/2020	2273.7	Pre-start	
11/05/2020	2277	Pre-start	
12/05/2020	2281.8	Pre-start	
13/05/2020	2288	General	Fit new indicator lenses
14/05/2020	2288	Pre-start	
15/05/2020	0	General	Drum rubbers
15/05/2020	0	General	drum rubbers x2
15/05/2020	2292	Pre-start	
20/05/2020	23012	Pre-start	Good
24/05/2020	0	Pre-start	
28/05/2020	2308	General	Fit new reverse alarm, repair and rewrite 2way power supply
1/06/2020	0	General	back up alarm
3/06/2020	2313.1	Pre-start	
5/06/2020	2313	Pre-start	
26/06/2020	2317	Pre-start	
9/07/2020	2319	Pre-start	
10/07/2020	2320.4	Pre-start	
20/07/2020	2323	Pre-start	Permit to operate no swms
26/08/2020	2329	Pre-start	
23/09/2020	0	General	Oil & fuel Filter for service

23/09/2020	2333	Service	Replace engine oil and filter. Replace fuel filters and bleed system. Repair flashing light. Move reverse alarm to meet rms spec. Tag fire alarm. Checkover electrical and operating systems.
30/10/2020	2342	Urgent	Move 2way hand piece holder. Checkover roller
18/11/2020	2349.4	Pre-start	
19/11/2020	2351	Pre-start	
1/12/2020	2371	Pre-start	
10/12/2020	2372	Pre-start	
2/02/2021	0	Registration	20/01/2021-20/01/2022
8/02/2021	2377	Pre-start	
9/02/2021	2380	Pre-start	
11/02/2021	2384.3	Pre-start	
12/02/2021	2386.8	Pre-start	
15/02/2021	2387	Urgent	Remove failed drum roller mount rubbers. Fit new ones and torque bolts. Replace fire extinguisher.
15/02/2021	2387	Pre-start	
17/02/2021	0	Service	For the Exchange of: 1 x 1.5 KG ABE Fire Extinguisher
18/02/2021	2396	Pre-start	
19/02/2021	2400	Pre-start	
23/02/2021	2409	Pre-start	
25/02/2021	2418.9	Pre-start	
2/03/2021	2436	Pre-start	
3/03/2021	2326.2	Pre-start	
4/03/2021	24422	Pre-start	
5/03/2021	2447	Pre-start	
10/03/2021	24589	Pre-start	
15/03/2021	2470	Pre-start	
18/03/2021	2479.7	Pre-start	
25/03/2021	2488	Pre-start	
30/03/2021	2503.3	Pre-start	
15/04/2021	2517.1	Pre-start	
19/04/2021	2520.1	Pre-start	
20/04/2021	2521	Pre-start	
27/04/2021	2534.4	Pre-start	
28/04/2021	2540.1	Pre-start	
29/04/2021	25472	Pre-start	
30/04/2021	2550	Pre-start	
3/05/2021	2556.9	Pre-start	

3/05/2021	2556.9	Pre-start	
10/05/2021	2565.6	Pre-start	
11/05/2021	2570	Pre-start	
14/05/2021	2572	Pre-start	
26/05/2021	2583	Pre-start	
27/05/2021	2598	Pre-start	
28/05/2021	2589	Pre-start	
2/06/2021	2596	Pre-start	
9/06/2021	26039	Pre-start	
10/06/2021	2605	Pre-start	
16/06/2021	2606.9	Pre-start	
17/06/2021	2611	Pre-start	
18/06/2021	2612.8	Pre-start	
21/06/2021	2615.4	Pre-start	
22/06/2021	2619.3	Pre-start	
24/06/2021	2633.1	Pre-start	
25/06/2021	2636.6	Pre-start	
28/06/2021	2637.3	Pre-start	
29/06/2021	2643	Pre-start	
1/07/2021	2649.4	Pre-start	
2/07/2021	2650	Pre-start	
5/07/2021	2652	Urgent	Repair lighting. Replace 1Xlight
5/07/2021	2652	Pre-start	
9/07/2021	2653.5	Pre-start	
14/07/2021	2654	Pre-start	Front lights not working
23/07/2021	2662	Pre-start	
9/08/2021	2679	Pre-start	Mirror vandalised over the weekend
11/08/2021	2685	Urgent	Replace worklights
11/08/2021	2690	Pre-start	
17/08/2021	2715	Pre-start	
23/08/2021	2735	Urgent	Replace vibratory drum hoses and top up oil
26/08/2021	0	Service	Blown hose on CAT roller CS533E Assist with removal, make new hoses, assist with assembly
1/10/2021	2791	Pre-start	
2/10/2021	2800	Pre-start	
6/10/2021	2807	Pre-start	
14/10/2021	2827	Pre-start	

19/10/2021	2838	Service	Carried service, cleaned cab filter, cleaned coolers, carried out inspection
21/01/2022	0	Registration	20/01/2022-20/01/2023 Conditional Rego
14/02/2022	0	Tyres	2 x SCRAP TYRES EARTHMOVING SMALL POS;LOOSE FITTER;GREG DATE;14.2.2022
4/05/2022	2865	General	Checked over and repaired
11/05/2022	2866	Pre-start	Hood struts not holding up engine cover when checking oil
20/05/2022	2879.7	Pre-start	
20/06/2022	2897.2	Pre-start	
27/06/2022	2902.5	Pre-start	
28/06/2022	2905	Pre-start	
25/07/2022	2927.8	Pre-start	
9/08/2022	2950.5	Pre-start	
11/08/2022	2953.1	Pre-start	
18/08/2022	2966.1	Pre-start	
31/08/2022	2976.9	Pre-start	
2/09/2022	2980	Pre-start	
5/09/2022	2982.1	Pre-start	
7/09/2022	2988.5	Pre-start	
12/09/2022	2994.7	Pre-start	
14/09/2022	2996.3	Pre-start	
15/09/2022	3001.2	Pre-start	
20/09/2022	3001.9	Pre-start	
21/09/2022	3003.2	Pre-start	Bonnet struts have failed
11/10/2022	3019.3	Pre-start	
12/10/2022	3020.6	Pre-start	
13/10/2022	3025.8	Pre-start	Engine cover strut won't hold
19/10/2022	3028.1	Pre-start	
28/10/2022	3034	Pre-start	Windscreen cracked up top corner
3/11/2022	3037.5	Pre-start	
4/11/2022	3038	Pre-start	
8/11/2022	3041	Pre-start	
10/11/2022	3045.1	Pre-start	
11/11/2022	3049.8	Pre-start	
12/11/2022	3058.9	Pre-start	
21/11/2022	3066.1	Pre-start	
23/11/2022	3070.8	Pre-start	

25/11/2022	3073.4	Pre-start	Cracks in front windscreen top right cornerRear bonet gas struts don't hold bonet up .left side need bolting back on.
28/11/2022	3074	General	Removed snapped grease nipples and checked over machine
28/11/2022	3075.4	Pre-start	Front window/windscreen broken
30/11/2022	3078	Pre-start	
3/12/2022	3081	Pre-start	
7/12/2022	3087.7	Pre-start	Windscreen crackedBonnet won't stay up/bonnet struts failing
9/12/2022	3092.7	Pre-start	Bonnet strut R S
13/12/2022	3091.9	Pre-start	Cracked windscreen
15/12/2022	3015.6	Pre-start	Crack right side windscreen
20/12/2022	3108.9	Pre-start	
3/01/2023	3114.1	Pre-start	Cracked windscreen
16/01/2023	3125.2	Pre-start	
18/01/2023	3721.1	Pre-start	
24/01/2023	3133.1	Pre-start	
25/01/2023	3139.1	Pre-start	
31/01/2023	3148	Pre-start	
14/02/2023	3161.6	Pre-start	
27/02/2023	3163	Urgent	Gas struts on hood broken and not holding replaced gas struts
6/03/2023	3168	Pre-start	
4/05/2023	3208.5	Pre-start	
6/05/2023	3212.5	Pre-start	
15/05/2023	3225.2	Pre-start	
22/05/2023	3234	Pre-start	
6/06/2023	3251	Urgent	Damaged fuel line replacement fuel line supplied from cat
29/06/2023	3252	Pre-start	
30/06/2023	3256	Pre-start	
18/07/2023	3276.7	Pre-start	
20/07/2023	3277.8	Pre-start	
24/07/2023	3282.6	Pre-start	
31/07/2023	3284	Pre-start	Crack in front window Dirty floor and dash rubbish in cabOil leak
1/08/2023	3287	Pre-start	
10/08/2023	3297	Pre-start	
11/08/2023	3300	Pre-start	
28/08/2023	3310	Pre-start	
30/08/2023	3312	Pre-start	

31/08/2023	3313	Pre-start	
4/09/2023	3317	Pre-start	
5/09/2023	3319	Pre-start	
13/09/2023	3336	Pre-start	
19/09/2023	1234	Pre-start	
20/09/2023	3347	Service	Carried out oil and fuel service
21/09/2023	3350	Pre-start	
27/09/2023	3354	Pre-start	
28/09/2023	3354	General	new mirror assembly, grease
16/10/2023	3358	Pre-start	
16/10/2023	3358	Pre-start	
17/10/2023	3316	Pre-start	Very wet and muddy
17/10/2023	3360	Pre-start	
20/10/2023	3369	Pre-start	
23/10/2023	3380	Pre-start	
24/10/2023	3385	Pre-start	Needs top up of hydraulic oil
25/10/2023	3386	Pre-start	
26/10/2023	3382	General	hydraulic hose blew, pirteck came and replaced.
26/10/2023	3385	Urgent	Replace 4x damaged hydraulic hoses. Reseal hydraulic pump. Top up fluids. Adjust belts. Checkover machine
31/10/2023	3397.6	Pre-start	Left side of drum feels loose
7/11/2023	3401	Pre-start	
8/11/2023	34026	Pre-start	
9/11/2023	3408.8	Pre-start	No uhf radio
10/11/2023	3413.5	Pre-start	No radio
20/11/2023	3417	Pre-start	
21/11/2023	3417	Pre-start	
22/11/2023	3421	Pre-start	
23/11/2023	3423	Pre-start	
24/11/2023	3428.2	Pre-start	
27/11/2023	3429.2	Pre-start	
28/11/2023	3431.3	Pre-start	
30/11/2023	3432.3	Pre-start	
1/12/2023	3434.6	Pre-start	
4/12/2023	3440.2	Pre-start	Clean
5/12/2023	3447	Pre-start	

6/12/2023	3453	Pre-start	
8/12/2023	0	General	2.5KG ABE FIRE EXTINGUISHER
12/12/2023	3457	Pre-start	
21/12/2023	3463.2	Pre-start	
8/01/2024	3466.1	Pre-start	
11/01/2024	3467	Pre-start	
7/02/2024	3468.7	Pre-start	