

DATE	KLMS	SERVICE TYPE
22/10/2015	220,659	10,000km
2/03/2018	245,360	10,000km
7/05/2018	256,125	10,000km
7/12/2018	276,346	10,000km
9/04/2019	288,214	10,000km
1/07/2019	298,980	10,000km
16/09/2019	310,125	10,000km
9/01/2020	324,440	10,000km
29/03/2020	334,000	10,000km
30/07/2020	345,057	10000km
26/11/2020	356,280	10000km
10/03/2021	365,450	10000km
9/08/2021	375,916	10000km
6/04/2022	384,972	10000km

Repairs :

DATE	KLMS	DESCRIPTION OF REPAIRS CARRIED OUT	PARTS
20/02/2014	-	1 x Disc Pads DB1968CP, TOTAL: \$44.00inc TRUCKLINE	
23/06/2014	-	Compaint: will not run, checked engine, removed inlet manifold and removed glow plugs, carried out compression test found all compressionsl low, fitted supplied motor to vehicle transferred worn flywheel fitted turbo and manifold to supplied engine. Fitted new oil filter and fillerd with new oil, supplied and filled cooling system with new coolant. Gasket Exh Manifold, Gasket inlet, Gasket, 1 x Seal O Ring, 1 x Anti Freeze 5ltr, Oil Filter, Labour, TOTAL: \$3296.65inc MAUGHAN THIEM	
28/08/2015	219,500	R&R timing chain, R&R crank seal, R&R chain guides x 2 , R&R Harmonic balancer, Re-Assemble & fill with coolant	\$1,066.92
22/10/2015	220,659	R&R L/H Mirror assembly, replace radio antenna & Base, Replace fuel filler door, re-seal timing cover	\$479.79
6/10/2016	-	Install new bonnett grille and washer jets	\$207.75
7/07/2017	233,190	Straiten rear bar and fit new trailer plug	
20/07/2017	233,238	R & R 2 x Batteries, ENRIGI	269.5
31/07/2017	233,359	Install new/repai red drivers seat. Run wires for rear loom.	316.8
1/08/2017		Carry out 10,000kms service, fit new oil filter housing, fit UHF antenna and bracket, fit and wire up UHF	139
27/11/2017		R & R Drives central locking unit. R & R Drives door barrel to suit key. (Drives central locking kit - EBAY \$275, Lock Barrel unit - Stillwell Ford \$155, Calibrate drives lock - On the Spot Locksmith \$65)	

10/01/2018	235,709	Drove van to pin point fault & cause of nosie. Found crack in boost hose. R&R	
17/04/2018	252,713	Fitted elec trailer brake controller and wired up. Tested ok. Baxters: Brake controller \$129	
7/05/2018	256,125	Needs 4 x new discs. All new pads. Possible vac pump (oil leaking)	
6 & 7/6/18	263,951	Replace front brake rotors and pads. Replace rear brake rotors and pads. Replace turbo oil feed line. Replace fan belt tensioner. Replace fan belt. Recitfy brake roter warning light. Replace missing R/H windscreen moulding. Wash van. Cut and polish black marks out of paint R/H side. Parts: Stillwell Fords, moulding windshield \$194.77, wire assembly patch \$19.80, tensioner and belt \$241.78, 4 x brake pads and 2-sets pads \$820.96, 2 x hub seals and 2 x axel gaskets \$213.14, 1 x tube oil feed \$119.30	
29/06/2018	265,694	Carried out 10k service. Ordered washer bottle cap. Found oil leaking from crankshaft seal (check next service). Found thrust bearing knocking - needs attention. R & R RHF Parklight globe. STOCK: Park light globe x 1	
16/07/2018	266,472	Remove gearbox, remove clutch, flywheel, and rear main seal, replace rear main seal & spiggot bearing, fit new flywheel and clutch, re-fit gearbox, road test and bleed clutch, Truckline \$1280.07+, Stillwell fords \$158.48	
18/10/2018	271,218	R&R sliding door lock actuator with 1 from wreckers.	\$250.00+
16/06/2020	340,839	inspect engine light clear codes, replace fuel filter, replace air cleaner, clear intake of oil & maf sensor	
24/06/2020	341,602	replace front brake pads	Stillwell Fords: 1x brake pad set \$75
30/07/2020	345,057	Carried out 10k service. Found several oil leaks: rocker cover, vaccum pump, output shaft & possibly timing cover- Spoke to Brendan told to leave until decision on van is made. Found rear brake rotors have a lip - recommend replace when brake pads next changed. R&R engine oil & oil filter - R&R fuel filter - Cleaned air filter - Washed engine down due to oil leak.	Stock: AFL98 x 1 - Oil Filter, C11-9176bc x 1 Fuel filter
26/11/2020	356,280	Carried out 10k service as required - R&R engine oil & filter - R&R leaking heater tap & hose fitting. Checked A/C operation - found high pressure hose rubbed through - repaired and gassed	Ford Stillwell: 1 x hose & tube 1 x AFL98 oil filter
7/12/2020	357,384	Diagnose clutch issue - R&R Master cylinder	Ford Parts: 1 x master cylinder \$201.61
9/08/2021	375,916	Carried out 10000km service - Topped up power steering - R&R LHF parker globe - R&R engine oil & filter - Tyres will need doing	STOCK: 1 x AFL98
6/04/2022	384,972	Carried out 10000km service - Inspected engine light and power gear light on, found EGR valve to be faulty . Advised not to change	