



# Vehicle Service Records (VSR Explorer)

## Repair history D-137194

Registration nr: XQ61RR  
Market type: FH16 64T

Chassis nr: D-137194  
Country: AUS

VIN nr: YV5AP80D8DD137194  
Delivery date: 2014-04-07

PC	Type	Code	Description (Original)	#
<b>W 2023-05-17 - Mileage: 1478137 - Order nr: 8173841</b>				
	*	M	PLEASE FILL IN	
		VO-1774400	Basic service. Chassis lubrication and o	5.3
		LO-310	INVESTIGATE INJECTOR FAULT	3.5
		LO-310	INJECTION HARNESS LEAKING	0.76
	*	2331100	Filter, water separator, replace	
	*	2330600	Fuel filter, replace (one)	
	*	1751300	Engine, oil and filter, replace. Lube	
	*	1707300	Service alert system, configuration and	
		VO-24122024	SERVICE KIT - FK18B	1
		AU2-AMP23068346	VDS 4.5 ENGINE OIL BULK	42.3
			Gurdeep: 0450 150 095	
		VO-20429371	HOUSING	2
		VO-20734499	CABLE SEAL - BLUE	10
		VO-990147	CABLE TERMINAL	10
		VO-23509305	CONTROL VALVE	1
		VO-1677370	SEALING RING - PURPLE VEB	2
		VO-20526428	SEALING RING - PURPLE VEB	1
		AU2-9718-240002743	BBC4 BRAKE CLEANER	1
		VO-1161277	LINER SILASTIC	1
		VO-983472	TIE, INJECTOR CABLE - S (GREY)	4
		VO-8131393	CAGE	4
		VO-21634024	PRESSURE SENSOR	1
		VO-21582423	4 PIN PLUG KIT	1
		OTH-ACX1297-SMALL	HEATSHRINK - B/PRESSURE	1
			Found plugs for injectors 5 and 6 to have loose pins in them. replaced	
			injectors both 5 and 6 with new plugs and pins. cleared fault codes	
			ready for a run.	
			Completed	
		VO-2850800	Exhaust back pressure sensor, replace	0.2

PC	Type	Code	Description (Original)	#
	☒		pins have an open circuit,	
	☒		needs a new injector harness to fix fault.	
	☒		Removed rocker cover, checked harness wires, not brittle,	
	☒		pin tensions good, cleaned old oil out of plugs, put back	
	☒		together, runs ok, carried out injector cut off test - ok,	
	☒		carried out cylinder balancing test.	
Ⓜ	*	97	ENVIRONMENTAL CHARGE	
Ⓜ	*	91	WORKSHOP CONSUMABLES	
<b>2023-01-19 - Mileage: 1460507 - Order nr: 8167922</b>				
Ⓜ	*	M	PLEASE FILL IN	
Ⓜ	Ⓞ	VO-1774400	Basic service. Chassis lubrication and o	5.3
Ⓜ	*	1751300	Engine, oil and filter, replace. Lube	
Ⓜ	*	2330600	Fuel filter, replace (one)	
Ⓜ	*	2331100	Filter, water separator, replace	
Ⓜ	■	VO-24122024	SERVICE KIT - FK18B	1
Ⓜ	■	AU2-9718-240002743	BBC4 BRAKE CLEANER	1
Ⓜ	■	AU2-AMP23068346	VDS 4,5 ENGINE OIL BULK	42.2
	☒		Gurdeep - 0450 150 095	
	☒		Mileage:1460507	
	☒		Hrs:24252	
	☒		Next Service:1505507	
	☒		Parked:P1	
Ⓜ	*	BSDEFECTS	Outstanding Defects	
<b>2022-08-31 - Mileage: 1403257 - Order nr: 8162151</b>				
Ⓜ	*	M	Next Service:45,000Km or 29/03/2023	
Ⓜ	Ⓞ	VO-1774400	Basic service. Chassis lubrication and o	5.3
Ⓜ	*	2331100	Filter, water separator, replace	
Ⓜ	*	2330600	Fuel filter, replace (one)	
Ⓜ	*	1751300	Engine, oil and filter, replace. Lube	
Ⓜ	*	1707300	Service alert system, configuration and	
Ⓜ	*	1752700	Final drive oil, change. Lube area	
Ⓜ	Ⓞ	VO-2141300	Valves and unit injectors, adjust	3.5
Ⓜ	Ⓞ	LO-262	COOLANT STILL LEAKING	2
Ⓜ	■	VO-24122024	SERVICE KIT - FK18B	1
Ⓜ	■	VO-949329	DIFF COPPER WASHER - VOLVO	4
Ⓜ	■	VO-20736230	SEAL STRIP, R/COVER GASKET	1
Ⓜ	■	AU2-9718-240002743	BBC4 BRAKE CLEANER	1

PC	Type	Code	Description (Original)	#
	🔧		Air Drier at 111% Consumed - Needs to be replaced	
	🔧		Active fault codes, see attached	
	🔧		RH FLASHING LIGHT NOT WORKING	
	🔧		Rh rear marker light broken	
	🔧		Lh rear marker light not working	
	🔧		Lh brake/tail light - not all LEDS working	
	🔧		Lh mirror marker light not working	
	🔧		Rh mirror marker light not working	
	🔧		Stone chip in windscreen	
	🔧		A/C filter very dirty- needs replacing	
	🔧		Rh cab tilt ram leaking oil - needs new seals	
	🔧		Fan ring and shroud are damaged	
	🔧		Exhaust brake actuator seal blown out	
	🔧		Front calliper bushes worn - both sides	
	🔧		Crack in exhaust pipe, below muffler	
	🔧		Excessive wear in turntable bushings	
	🔧		Play in both ends of Tie rod	
	🔧		No air in 4x REAR Airbags	
	🔧		Rear lh bump stop split	
	🔧		Air filter dirty - needs replacing	
🔧	🔧	AU2-AMP23068346	VDS 4.5 ENGINE OIL BULK	42.2
🔧	🔧	VO-5611600	Air drier, replace	0.8
🔧	🔧	VO-21620181	AIR DRIER FILTER KIT	1
🔧	🔧	AU2-9718-240002743	BBC4 BRAKE CLEANER	1
	🔧		Valve set complete all clearances recorded And checked by Sean	
	🔧		Pressure tested cooling system to check for leak. Only	
	🔧		remove reset air drier filter - Done	
	🔧		Cap missing from top of tilt ram reservoir	
	🔧		Parked: 45	
	🔧		Parked up	
	🔧		.	
	🔧		found leaking from overflow tank. Thinking leaking from	
	🔧		there, did a Billy test on Compressor and found Compressor	
	🔧		to be pressuring cooling system.Needing new Compressor,	
	🔧		possible header tank and radiator.	
	🔧		Attempted to call customer but couldn't get in touch to	
	🔧		get approval to replace the compressor	
🔧	*	BSDEFECTS	Outstanding Defects	



PC	Type	Code	Description (Original)	#
Ⓡ	*	97	ENVIRONMENTAL CHARGE	
	☒		Gurdeep: 0450 150 095	
	☒		Mileage: 1,403,257	
	☒		Hrs: 22936	
Ⓡ	*	91	WORKSHOP CONSUMABLES	
🔍 <b>W 2022-08-15 - Mileage: 1394678 - Order nr: 8161248</b>				
Ⓡ	*	M	Contact: Gurdeep:0450 150 095	
	☒		Email: blackeagle0095@gmail.com	
Ⓡ	Ⓢ	VO-2611800	Expansion tank, replace	0.8
Ⓡ	*	430	Suspect rear main seal leaking	
Ⓡ	Ⓢ	LO-230	customer states injector harness leaking	1
Ⓡ	Ⓢ	LO-210	Rear timing cover leaking	16
Ⓢ	Ⓢ	VO-20483426	SEALING RING- INPUT SEAL	1
Ⓢ	Ⓢ	VO-4313100	Sealing ring input shaft, replace. Gearb	0.6
Ⓡ	Ⓢ	VO-984738	FLANGE BOLT M8 x 40mm Black	2
Ⓡ	Ⓢ	VO-21015266	SCREW	6
Ⓡ	Ⓢ	VO-994447	FLANGE BOLT M8 x 25mm Black	25
Ⓡ	Ⓢ	VO-20815558	SEALING STRIP	1
Ⓡ	Ⓢ	VO-21185132	SEALING	2
Ⓢ	Ⓢ	VO-994102	HEX BOLT M14 x 48mm	4
Ⓢ	Ⓢ	VO-25339078	HEX NUT - M14 FINE (11MM)	4
Ⓡ	Ⓢ	VO-983762	HEX. SOCKET SCREW	1
Ⓡ	Ⓢ	VO-20483919	HEX. SOCKET SCREW	6
Ⓡ	Ⓢ	VO-22081685	IDLER GEAR	1
Ⓡ	Ⓢ	VO-992065	O-RING - COMPRESSOR MOUNT	1
Ⓡ	Ⓢ	VO-984127	O-RING	1
Ⓡ	Ⓢ	VO-977030	O-RING P/STRG MOUNT	1
Ⓡ	Ⓢ	VO-943177	O-RING OIL COOLER - GREEN	1
Ⓡ	Ⓢ	VO-8192804	SCREW	8
Ⓡ	Ⓢ	VO-20734156	SEAL STRIP, OIL PAN	1
Ⓡ	Ⓢ	VO-20736230	SEAL STRIP, R/COVER GASKET	1
Ⓡ	Ⓢ	VO-471708	SEALING RING - BLACK	1
Ⓡ	Ⓢ	VO-21780376	SEALING RING - PURPLE	1
Ⓡ	Ⓢ	VO-22438707	TIMING GEAR PLATE	1
Ⓡ	Ⓢ	VO-85122800	ATF DEX3 1LTR	2
Ⓡ	Ⓢ	AU2-9718-240002743	BBC4 BRAKE CLEANER	2
Ⓡ	Ⓢ	OTH- WUR0674850240/MTR	EMERY CLOTH G240	1

PC	Type	Code	Description (Original)	#
Ⓟ	Ⓜ	VO-1161277	LINER SILASTIC	1
Ⓟ	Ⓜ	AU2-LOC44279	Loctite 263 Stud Locker	1
Ⓟ	Ⓜ	AU2-WUR0673205010	Nylon Power LOC 2I	4
Ⓟ	Ⓜ	VO-1161963	RUBBER GREASE	1
Ⓟ	Ⓜ	AU2-AMP85158444	MACK DEO VDS-4.5 5L*	1
Ⓟ	Ⓜ	AU2-LOC1162941	Loctite 5 MIN EPOXY	1
Ⓟ	Ⓜ	AU2-FOR64804554	RTV SILICONE GREY K164	1
Ⓟ	Ⓜ	VO-976068	O-RING - PTO	1
Ⓟ	Ⓜ	VO-21687075	PIPE	1
Ⓟ	Ⓜ	VO-21523327	PIPE	1
Ⓟ	Ⓜ	VO-22191895	CRANKSHAFT SEAL	1
Ⓟ	Ⓜ	VO-22191895	CRANKSHAFT SEAL	1
Ⓟ	Ⓜ	VO-85108352	CRANKSHAFT SEAL	1
Ⓟ	Ⓜ	VO-1677370	SEALING RING - PURPLE VEB	2
Ⓟ	Ⓜ	VO-20526428	SEALING RING - PURPLE VEB	1
Ⓟ	Ⓜ	VO-977639	NIPPLE M12x1.5 x 6mm	2
Ⓟ	Ⓜ	VO-977237	HOSE	1
Ⓟ	Ⓜ	VO-471708	SEALING RING - BLACK	1
Ⓟ	Ⓜ	VO-21532261	SEALING RING - BLACK	1
Ⓟ	Ⓜ	VO-20852765	DOWTY WASHER O.D. 24mm	6
Ⓟ	Ⓜ	VO-21019175	RELAY	1
Ⓟ	Ⓜ	VO-994560	HOSE CLAMP 26-38mm	1
	Ⓜ		oil leaking from front of transmission	
	Ⓜ		fitted on RO 7278094 dated 31/05/2021 travelled 300739 ks'	
Ⓟ	Ⓜ	VO-4317000	Gearbox, remove	0.8
Ⓟ	Ⓜ	VO-4317200	Gearbox, install	1.5
Ⓟ	Ⓜ	VO-990950	FLANGE NUT M8 CRIMP	1
Ⓟ	Ⓜ	VO-994441	FLANGE BOLT M8 x 50mm Black	1
Ⓟ	Ⓜ	VO-994195	FLANGE SCREW M10 x 50MM	1
Ⓟ	Ⓜ	VO-990941	FLANGE NUT M10	1
Ⓟ	Ⓜ	VO-1676400	HEADER TANK FH12	1
Ⓟ	Ⓜ	VO-21103569	SEALING RING	1
Ⓟ	Ⓜ	AU2-AMP22567335	VOLVO VCS COOLANT 20L*	40
	Ⓜ		2nd one given - tool broken and damaged seal on install, refer Luke B	
Ⓟ	Ⓜ	OTH-RMHC6	CLAMP-HOSE 8-22MM	2
	Ⓜ		Mileage:1394678	
	Ⓜ		Hrs:22817	
	Ⓜ		-----	



PC	Type	Code	Description (Original)	#
		VO-2620200	Coolant pump, replace	1.3
		VO-2166300	Crankshaft seal, replace (rear). Flywheel	0.3
		VO-2600600	Coolant system, pressure test	0.5
		VO-1820200	Localised wash for fault tracing	0.3
			remove harness with rocker cover removed clean out harness	
			and fill with epoxy refit harness.	
			drain fluids remove engine sump remove engine pipe work	
			and rocker cover remove flywheel and timing cover remove	
			timing gear set remove timing plate found timing plate	
			fretted to engine block surface clean surfaces and replace	
			engine timing plate refit to block reassemble gear set	
			checking backlash and timing. Refit timing cover and upper	
			cover refit rocker cover and engine pipe work refill with	
			oil.	
			Please check over reported coolant pump gasket leaking	
	*	97	ENVIRONMENTAL CHARGE	
	*	91	WORKSHOP CONSUMABLES	
<b>2022-07-13 - Mileage: 0 - Order nr: 8160174</b>				
	*	M	PLEASE FILL IN	
			Gurdeep:0450 150 095	
		LO-642	POWER STEERING STILL LEAKING	8.58
			PLEASE MAKE THIS A PRIORITY - THIS WILL BE THE FOURTH TIME.	
		VO-1592945	POWER STG RES.	1
		VO-22282711	HOSE	1
		VO-21373204	SERVO PIPE	1
		VO-23296894	FITTING	3
		VO-20852765	DOWTY WASHER O.D. 24mm	2
		VO-85122800	ATF DEX3 1LTR	2
		VO-3979639	GASKET - PREHEATER	2
		VO-990950	FLANGE NUT M8 CRIMP	4
			blackeagle0095@gmail.com	
			PLEASE GIVE THIS JOB CARD TO AARON - THIS WILL E THE	
			FOURTH ATTEMP IT HAD THE LAST REPAIRED ON 7/7/2022.	
			remove and replaced steel pipes for steering under	
			radiator cut on 8160037	
<b>W 2022-07-07 - Mileage: 1373384 - Order nr: 8160037</b>				
		VO-6452600	Hydraulic hose power steering, replace	2
		VO-20736230	SEAL STRIP, R/COVER GASKET	1

PC	Type	Code	Description (Original)	#
W	R	VO-1161277	LINER SILASTIC	1
B	R	UNK-STH632907AK	Hose - 21373204	1
W	M	VO-2116500	Valve cover gasket, replace (first)	0.6
W	M	VO-1820200	Localised wash for fault tracing	0.3
	E		Removed and replaced leaking suction hose at reservoir.	
B	*	97	ENVIRONMENTAL CHARGE	
B	*	91	WORKSHOP CONSUMABLES	

**2022-07-01 - Mileage: 1369098 - Order nr: 8159834**

B	*	M	PLEASE FILL IN	
	E		Contact: Gurdeep:0450 150 095	
B	M	LO-640	PLEASE CHECK OVER REPORTED POWER	3,3
	E		STEERING LEAK (VISIBLE) - DRIVER TOPPED UP 1 LITRE FULLY	
B	R	VO-22213665	SERVO PIPE - FH16	1
B	R	VO-23296894	FITTING	1
B	R	VO-22260493	HOSE	1
B	R	VO-85122800	ATF DEX3 1LTR	3
B	R	VO-977976	CLAMP	3
B	R	VO-984733	FLANGE BOLT M8 x 16mm Black	3
	E		Authoriser:	
	E		Email: blackeagle0095@gmail.com	
B	*	97	ENVIRONMENTAL CHARGE	
	E		AND IS LEAKING.	
	E		Tilted cab. Found leak from power steer pressure line as	
	E		was rubbing together. Removed hose and fuel filters. Fit	
	E		new steel pipe and power steer hose. Refitted fuel	
	E		filters. Refitted power steer oil. Bled the system. Tested	
	E		for operation.Ok.	
B	*	91	WORKSHOP CONSUMABLES	

**2022-06-29 - Mileage: 0 - Order nr: 8159573**

I	*	M	PLEASE FILL IN	
	E		Contact: Gurdeep:0450 150 095	
I	M	LO-640	PLEASE CHECK OVER REPORTED POWER STEERIN	2.25
	E		LEAK - COMPLAINT THAT THERE IS A POWER STEERING LEAK NEAR	
	E		Email: blackeagle0095@gmail.com	
	E		-	
	E		THE RESERVOIR HOSES AND RESERVOIR. REFER PREVIOUS RO	
	E		8159002	

**2022-06-22 - Mileage: 1364588 - Order nr: 8159002**



PC	Type	Code	Description (Original)	#
Ⓡ	*	M	PLEASE FILL IN	
	☒		Contact: Gurdeep: 0450 150 095	
Ⓡ	Ⓢ	VO-1774400	Basic service. Chassis lubrication and o	5.3
	☒		oil changes included only in some models	
Ⓡ	*	1751300	Engine, oil and filter, replace. Lube	
Ⓡ	*	2330600	Fuel filter, replace (one)	
Ⓡ	*	2331100	Filter, water separator, replace	
Ⓡ	*	1751100	Lubrication of fifth wheel	
Ⓢ	Ⓢ	VO-2373600	Unit injector, replace (all)	4.1
Ⓡ	Ⓡ	VO-24122024	SERVICE KIT - FK18B	1
Ⓡ	Ⓢ	LO-645	POWER STEERING HOSE LEAKING	2,3
Ⓢ	Ⓢ	VO-2117600	Sleeve, injector replace (all). Coolant	1.8
Ⓢ	Ⓢ	VO-2620200	Coolant pump, replace	1.3
Ⓢ	Ⓢ	VO-2510400	Gaskets, exhaust manifold, replace	2
Ⓢ	Ⓡ	VO-21351717	INJECTOR SLEEVE	6
Ⓢ	Ⓡ	AU2-WUR0673205010	Nylon Power LOC 2I	3
Ⓢ	Ⓡ	AU2-9718-240002743	BBC4 BRAKE CLEANER	1
Ⓢ	Ⓡ	VO-20736230	SEAL STRIP, R/COVER GASKET	1
Ⓢ	Ⓡ	OTH-LOC51850	LOCTITE 518 50ML	1
Ⓢ	Ⓡ	VO-21344774	FLANGE BOLT M10 x 50mm ENG	6
Ⓢ	Ⓡ	VO-1677370	SEALING RING - PURPLE VEB	2
Ⓢ	Ⓡ	VO-20526428	SEALING RING - PURPLE VEB	1
Ⓢ	Ⓡ	VO-1161963	RUBBER GREASE	1
Ⓢ	Ⓡ	VO-276948	O-RING KIT	6
Ⓢ	Ⓡ	VO-85023583	PUMP UNIT, EXCH	1
Ⓢ	Ⓡ	VO-990950	FLANGE NUT M8 CRIMP	4
Ⓡ	Ⓡ	VO-21133804	V-RIBBED BELT 10PK1400	1
Ⓡ	Ⓡ	VO-21613426	THERMOSTAT	1
Ⓡ	Ⓡ	VO-21753149	IDLER PULLEY	1
Ⓢ	Ⓡ	AU2-AMP22567335	VOLVO VCS COOLANT 20L*	40
Ⓢ	Ⓡ	VO-21103569	SEALING RING	1
Ⓢ	Ⓡ	VO-983472	TIE, INJECTOR CABLE - S (GREY)	6
Ⓢ	Ⓡ	VO-20852765	DOWTY WASHER O.D. 24mm	2
Ⓡ	Ⓡ	AU2-9718-240002743	BBC4 BRAKE CLEANER	1
Ⓢ	Ⓡ	AU2-9718-240002743	BBC4 BRAKE CLEANER	1
Ⓡ	Ⓡ	VO-21620181	AIR DRIER FILTER KIT	1
Ⓢ	Ⓡ	VO-21695684	SEALING RING - EXHAUST	2
Ⓢ	Ⓡ	VO-20938964	SEAL	1



PC	Type	Code	Description (Original)	#
W	R	VO-20784537	GASKET TURBO BASE	1
W	R	VO-993811	FLANGE BOLT M10 x 50mm TURBO	4
W	R	VO-22206133	TURBO FEED GASKET	1
W	R	VO-470993	TURBO RTN GKT	1
W	R	VO-21940615	SEALING RING - PURPLE	1
W	R	VO-469601	O-RING TURBO - GREEN	1
W	R	VO-21940610	SEALING RING - PURPLE	1
W	R	VO-21352841	GASKET EXHAUST	6
I	R	AU2-WUR0673205010	Nylon Power LOC 2I	3
W	R	VO-85103205	GREEN PAINT	1
W	R	VO-994441	FLANGE BOLT M8 x 50mm Black	1
W	R	VO-990950	FLANGE NUT M8 CRIMP	1
I	R	AU2-WUR0672010318	FANTYPE-NC-K80-30X	1
I	R	AU2-WUR0672010428	FANTYPE-NC-K80-40X	1
B	U	LO-561	Replace air drier filter	0.5
B	R	VO-20909063	HOSE PERFORMED - SUCTION	1
	E		Replaced drier filter & reset.	
B	R	VO-21849890	HOSE	1
B	R	VO-20915849	HOSE CLAMP 16-27mm	2
B	R	VO-85122800	ATF DEX3 1LTR	2
B	R	AU2-AMP23068346	VDS 4.5 15W/40 ENG OIL - BULK	38.7
	E		Manifold leaking	
	E		Water pump leak	
	E		Customer Advised Vehicle Hard to Start	
W	U	VO-2601200	Cooling system, drain and refill	0.9
W	U	LO-230	Fuel in the cooling system, check	1.1
B	U	VO-2621400	Piston thermostat, replace	1.1
B	U	LO-263	Fan belt idler pulley & Belt, replace	1
	E		found belt frayed and idler bearing noisy, replaced both	
W	U	VO-2600600	Coolant system, pressure test	0.5
W	U	VO-1820200	Localised wash for fault tracing	0.3
	E		REPLACED BOTH RESERVOIR HOSES & BLEED UP SYSTEM.	
	E		Thermostat housing leaking, belt frayed. Replaced both	
	E		items, filled with water and leak tested. Road-tested,	
	E		brought back into workshop and underwent system flush	
	E		including water core and radiator. Flushed again then	
	E		filled with fresh coolant. Checked, all OK.	
B	*	97	ENVIRONMENTAL CHARGE	

PC	Type	Code	Description (Original)	#
Ⓟ	*	91	WORKSHOP CONSUMABLES	
<b>2022-04-28 - Mileage: 1318750 - Order nr: 8156907</b>				
Ⓟ	*	M	PLEASE FILL IN	
	☒		Gurdeep: 0450 150 095	
Ⓟ	Ⓞ	VO-1771800	Basic service. city	3
Ⓟ	*	91	WORKSHOP CONSUMABLES	
Ⓟ	☒	VO-24122024	SERVICE KIT - FK18B	1
Ⓟ	☒	AU2-AMP23068346	VDS 4.5 15W/40 ENG OIL - BULK	42.3
	☒		WIL PICK UP TRUCK THUSDAY NIGHT 11PM?	
Ⓟ	*	97	ENVIRONMENTAL CHARGE	
<b>2022-03-18 - Mileage: 1279918 - Order nr: 7495047</b>				
Ⓟ	*	101	Engine Hours - 18361	
	☒		CONTACT - Gurdeep 0450 150 095	
Ⓟ	Ⓞ	VO-2843500	Fault codes, test mode	2.86
Ⓟ	Ⓞ	LO-1772244	Basic service checks	4
Ⓟ	*	2330600	Fuel filter, replace (one)	
Ⓟ	*	2331100	Filter, water separator, replace	
Ⓟ	*	1751300	Engine, oil and filter, replace. Lube	
Ⓟ	*	91	WORKSHOP CONSUMABLES	
Ⓟ	*	1707300	Service alert system, configuration and	
	☒		reports	
Ⓟ	☒	VO-24122024	FILTER KIT	1
Ⓟ	☒	AU2-AMP23068346	VOLVO ENGINE OIL VDS4 BULK	42
Ⓟ	☒	AU2-WUR0890117	BRAKE CLEANER SPRAY 500ML	1
Ⓟ	☒	AU2-WUR0892333	RAPID WINDSCREEN CLEANER 32ML	1
	☒		CONNECT LAPTOP AND CHECK FAULTS, NO LIGHT ON DASH. CHECK	
	☒		WIRING AT TRAILER PLUG, ALL WIRING OKAY. LIGHT ONLY COMING	
	☒		ON WHEN TRAILER IS CONNECTED, NEED TO CHECK TRAILER.	
	☒		CITY HORN NOT WORKING	
	☒		X2 TOP CLEARANCE LIGHTS NOT WORKING	
	☒		N/S FOG LIGHT IS NOT WORKING	
	☒		O/S FOG LIGHT GLASS BROKEN	
	☒		N/S MIRROR LIGHT NOT WORKING	
	☒		BULL BAR BOLT MISSING BOLT, LIGHT WORKING O/S	
	☒		N/S 1ST DRIVE AXLE MUDGUARD REFLECTOR IS MISSING	
	☒		N/S LOOP KIT	
	☒		O/S REAR CLEARANCE LIGHT DAMAGED	
	☒		O/S LOOP KIT RIPPED, NOT SECURE	



PC	Type	Code	Description (Original)	#
	☒		BONNET DAMAGED	
	☒		A/C FILTER BLOCKED	
	☒		FRONT GRILL DAMAGED	
	☒		OIL LEAKING FROM N/S FRONT CAB SHOCK	
	☒		EXHAUST FLEX LEAKING	
	☒		N/S 1ST DRIVE MUDFLAP MISSING, O/S 1ST DRIVE MUDFLAP RIPPED	
	☒		CAB PUMP MOTOR NOT SECURE	
	☒		AIR LEAKING AT BOTH O/S AND N/S AIR BAGS	
	☒		MINOR AIR LEAK FROM AIR TANK HOSE	
	☒		BOTH 1ST AND 2ND DRIVE V-STAY MINOR MOVEMENT, CHECK NEXT	
	☒		SERVICE	
	☒		N/S 2ND DRIVE LINK ROD WORN	
	☒		N/S 2ND DRIVE MUDGUARD SPRAY SUPPRESSION MISSING	
	☒		TURNTABLE JAW WORN	
	☒		OIL LEAKING FROM INJECTOR HARNESS	
	☒		OIL LEAKING FROM SANDWICH PLATE	
	☒		COOLANT LEAKING AT WATER PUMP HOLE	
	☒		OIL WEEPING FROM SIDE STEERING BOX	
	☒		O/S STEERING AXLE MUDGUARD INSIDE BRACKET BROKEN	
	☒		FRONT ENGINE MOUNT RUBBER CRACKED	
	☒		OIL LEAKING N/S CAB TILT HOSE	
	☒		INACTIVE LINING WEAR SENSOR WEAR AXLE 2 O/S	
	☒		EXHAUST GAS TEMP SENSOR ACTIVE	
Ⓜ	*	91	WORKSHOP CONSUMABLES	
🔍 <b>2022-03-07 - Mileage: 0 - Order nr: 8155270</b>				
	☒		Repair without detail info	
🔍 <b>W 2022-03-04 - Mileage: 1249723 - Order nr: 8155245</b>				
📍	*	M	PLEASE FILL IN	
	☒		Contact: Gurdeep: 0450 150 095 blackeagle0095@gmail.com	
Ⓜ	🔧	VO-2117600	Sleeve, injector replace (all). Coolant	1.8
Ⓜ	🔧	VO-20736230	SEAL STRIP, R/COVER GASKET	1
Ⓜ	🔧	VO-1161963	RUBBER GREASE	1
Ⓜ	🔧	VO-983472	TIE, INJECTOR CABLE - S (GREY)	8
Ⓜ	🔧	VO-21344774	FLANGE BOLT M10 x 50mm ENG	6
Ⓜ	🔧	VO-21351717	INJECTOR SLEEVE	6
Ⓜ	🔧	LO-373	Pass-through seal, injector harness,	1.3
Ⓜ	🔧	VO-944126	O-RING INJ HARNESSD9B/D12D/D13	1
Ⓜ	🔧	VO-20536487	O-RING	2

PC	Type	Code	Description (Original)	#
		VO-1677370	SEALING RING - PURPLE VEB	2
		VO-20526428	SEALING RING - PURPLE VEB	1
			drained and injectors removed	
		VO-2373600	Unit injector, replace (all)	4.1
		VO-2601200	Cooling system, drain and refill	0.9
		LO-230	Air in the fuel system, check	1.1
			replace	

**2022-03-04 - Mileage: 1249723 - Order nr: 4087767**

		M	PLEASE FILL IN	
			Contact: Gurdeep: 0450 150 095 blackeagle0095@gmail.com	
		LO-2000	Low power, hard to start	9.02
		VO-20736230	SEAL STRIP, R/COVER GASKET	1
		VO-1161963	RUBBER GREASE	1
		VO-983472	TIE, INJECTOR CABLE - S (GREY)	8
		VO-21344774	FLANGE BOLT M10 x 50mm ENG	6
		VO-21351717	INJECTOR SLEEVE	6
		VO-2302000	Injector, replace (one). Excl. programmi	0.78
		VO-944126	O-RING INJ HARNESSD9B/D12D/D13	1
		VO-20536487	O-RING	2
		VO-1677370	SEALING RING - PURPLE VEB	2
		VO-20526428	SEALING RING - PURPLE VEB	1
			Checked the fuel system and found compression in the fuel	
			system. Checked codes. Had low boost fault and back	
			pressure fault. Took the truck for a drive and found truck	
			running out of fuel. Carried out inspection and found	
			lines blocked. Cleaned the lines. Had to pull the fuel	
			tank to inspect. Checked ECU cooler. Test drove.	
			Removed and replaced the injector tubes. Had to replace	
			the 2, 3 and 4 injectors. Carried out full tappet sets.	
			Reassembled with the parts listed. tested for operation.Ok.	
		91	WORKSHOP CONSUMABLES	

**2022-02-24 - Mileage: 1263713 - Order nr: 3900350**

		LO-4000	truck wont select gears	4.1
			at shell service station in west dubbo	
		VO-25339078	HEXAGON NUT	8
		VO-994102	HEXAGON SCREW	8
		VO-20489408	PROPELLER SHAFT	1
		VO-FREIGHT	FREIGHT CHARGE	46



PC	Type	Code	Description (Original)	#
	📄		complaint: truck stuck at traffic lights no drive	
	📄		cause: failed jack shaft slip joint	
	📄		correction: attend breakdown at traffic lights in west	
	📄		Dubbo.	
	📄		Police in attendance as truck stuck on the road.	
	📄		Checked and found truck to be selecting gears but making a	
	📄		bad noise.	
	📄		Climbed under vehicle and went to undo tail shaft for tow	
	📄		truck when we found the tail shaft to be turning freely.	
	📄		Upon closer inspection found the jack shaft to have failed	
	📄		the slip joint.	
	📄		Engaged the difflock, guided the vehicle off the hwy and	
	📄		to a safe location to disconnect the trailers.	
	📄		Followed the truck to our workshop .	
	📄		Parts were ordered for the next day.	
	📄		Lift truck up into the air and remove and replace the	
	📄		jackshaft with new bolts.	
	📄		Lower vehicle and carry out test drive all ok.	
	📄		Return old part to customer	
Ⓜ	*	91	Workshop Consumables	
<b>🔍 2022-02-17 - Mileage: 1259234 - Order nr: 7493722</b>				
Ⓜ	*	SHIFT	SHIFT: DAY	
	📄		CONTACT:Gurdeep:0450 150 095	
Ⓜ	🕒	LO-520	INVESTIGATE LOW BRAKE PADS AND REPORT	0.2
Ⓜ	🕒	LO-560	SECURE LOOSE AIR TANK STRAPS	0.2
Ⓜ	🕒	LO-DEFECT	CLEAR DEFECT	0.23
Ⓜ	*	370	RECTIFY EBS WIRING TO PLUG	
Ⓜ	🕒	LO-770	RECTIFY HUB SEAL LEAK @ O/S/F/D	8
Ⓜ	🔧	VO-21036050	BEARING KIT	1
Ⓜ	🔧	VO-1076656	SEALING RING	1
Ⓜ	🔧	VO-3199066	SEAL	1
Ⓜ	🔧	VO-1076335	NUT M82x2	1
Ⓜ	🔧	VO-23149532	BRAKE PAD KIT	1
Ⓜ	🔧	VO-22537018	SENSOR WHEEL	1
	📄		ENG HOURS: 18041	
	📄		CHECK BRAKE MEASUREMENT	
	📄		FRONT: O/S 90% N/S 87.6%	
	📄		1ST DRIVE: O/S 54.8% N/S 50.8%	

PC	Type	Code	Description (Original)	#
	☒		2ND DRIVE: O/S 66.8% N/S 70%	
	☒		CLEAN 1ST DRIVE TO SEE LEAK	
	☒		REMOVE O/S 1ST DRIVE AXLE WHEELS, BRAKE BOOSTER, BRAKE	
	☒		PADS AND CALIPER. REMOVE AXLE AND HUB, CLEAN AND REMOVE	
	☒		HUB BEARINGS. PRESS IN NEW BEARINGS AND PULSE RING. REFIT	
	☒		COMPONENTS, REPLACE 1ST DRIVE BRAKE PADS, TENSION WHEEL	
	☒		NUTS. CHECK OPERATION, ALL OKAY	
Ⓜ	*	91	WORKSHOP CONSUMABLES	
<b>2022-02-01 - Mileage: 1249723 - Order nr: 8154001</b>				
Ⓜ	*	M	PLEASE FILL IN	
	☒		Contact: Gurdeep: 0450 150 095 blackeagle0095@gmail.com	
Ⓜ	Ⓜ	LO-2000	Low power, hard to start	12.2
Ⓜ	Ⓜ	LO-360	Active faults on dash	2
Ⓜ	Ⓜ	VO-2156300	Battery cable terminal, replace (UD mark)	2.5
Ⓜ	☒	VO-85123544	HOSE KIT - PUSH LH TO RH RAM	1
Ⓜ	☒	VO-85123545	HOSE KIT - PULL LH TO RH RAM	1
Ⓜ	☒	VO-20736230	SEAL STRIP, R/COVER GASKET	1
Ⓜ	☒	VO-1161963	RUBBER GREASE	1
Ⓜ	☒	VO-983472	TIE, INJECTOR CABLE - S (GREY)	8
Ⓜ	☒	VO-21344774	FLANGE BOLT M10 x 50mm ENG	6
Ⓜ	☒	AU2-9718-240002743	BBC4 BRAKE CLEANER	2
Ⓜ	☒	VO-21351717	INJECTOR SLEEVE	6
Ⓜ	Ⓜ	VO-2332100	Water drainage fuel system, test	2.3
Ⓜ	Ⓜ	LO-218	Check engine mounts	6
Ⓜ	Ⓜ	VO-2302000	Injector, replace (one). Excl. programmi	0.78
Ⓜ	Ⓜ	VO-5116100	Brake pads, replace, one front wheel (UD	3.5
Ⓜ	☒	VO-85021450	WATER PUMP UNIT, EXCH	1
Ⓜ	☒	VO-21103569	SEALING RING	1
Ⓜ	☒	VO-944126	O-RING INJ HARNESSD9B/D12D/D13	1
Ⓜ	☒	VO-85013343	UNIT INJECTOR - D16G	1
Ⓜ	☒	VO-85013343	UNIT INJECTOR - D16G	1
Ⓜ	☒	VO-85013343	UNIT INJECTOR - D16G	1
Ⓜ	☒	VO-20536487	O-RING	2
Ⓜ	☒	MK-NARV56306	CABLE TIE 1=25PK (4.8x300mm)	1
Ⓜ	☒	VO-1677370	SEALING RING - PURPLE VEB	2
Ⓜ	☒	VO-20526428	SEALING RING - PURPLE VEB	1
Ⓜ	☒	AU2-AMP22567335	VOLVO VCS COOLANT 20L*	40
Ⓜ	☒	VO-20499469	RUBBER CUSHION	2



PC	Type	Code	Description (Original)	#
Ⓟ	Ⓟ	LO-870	A/C INTERMITTANTLY COLD	1.84
	Ⓟ		drops in and out	
Ⓟ	Ⓟ	MK-NARV56310	CABLE TIE 1=10PK (7.6x370mm)	2
Ⓟ	Ⓟ	VO-85139619	PRESSURE SENSOR - EXHAUST	1
Ⓟ	Ⓟ	VO-21582423	4 PIN PLUG KIT	1
Ⓟ	Ⓟ	OTH-ACX1297-SMALL	HEATSHRINK - B/PRESSURE	1
Ⓟ	Ⓟ	VO-21390374	SENSOR WEAR PAD	1
Ⓟ	Ⓟ	VO-21396128	SENSOR - FE	1
Ⓟ	Ⓟ	VO-20429834	HOUSING 2 PIN, indicator	1
Ⓟ	Ⓟ	VO-20734499	CABLE SEAL - BLUE	2
Ⓟ	Ⓟ	VO-983013	CABLE TERMINAL	2
Ⓟ	*	97	ENVIRONMENTAL CHARGE	
	Ⓟ		Removed and replaced the engine mounts	
	Ⓟ		Checked the fuel system and found compression in the fuel	
	Ⓟ		Removed nbd replaced the pressure sensor and reassembled	
	Ⓟ		Removed and replaced cab tilt hose.	
	Ⓟ		Removed and replaced the water pump.	
	Ⓟ		system. Checked codes. Had low boost fault and back	
	Ⓟ		pressure fault. Took the truck for a drive and found truck	
	Ⓟ		running out of fuel. Carried out inspection and found	
	Ⓟ		lines blocked. Cleaned the lines. Had to pull the fuel	
	Ⓟ		tank to inspect. Checked ECU cooler. Test drove.	
	Ⓟ		Removed and replaced the injector tubes. Had to replace	
	Ⓟ		the 2, 3 and 4 injectors. Carried out full tappet sets.	
	Ⓟ		Reassembled with the parts listed. tested for operation.Ok.	
	Ⓟ		with the parts listed.	
	Ⓟ		Removed and replaced the brake pads as required.	
	Ⓟ		Carried out inspection and found the blower temp sensor at	
	Ⓟ		fault. Removed and replaced the blower sensor. Replaced	
	Ⓟ		the plug to the sensor and reassembled with the parts	
	Ⓟ		listed. tested for operation.Ok.	
Ⓟ	*	91	WORKSHOP CONSUMABLES	
🔍	<b>2021-12-06 - Mileage: 1217276 - Order nr: 7490919</b>			
	Ⓟ		HOURS 19970	
Ⓟ	Ⓟ	LO-1772244	Basic service checks	4
Ⓟ	*	2330600	Fuel filter, replace (one)	
Ⓟ	*	2331100	Filter, water separator, replace	
Ⓟ	*	1751300	Engine, oil and filter, replace. Lube	

PC	Type	Code	Description (Original)	#
Ⓟ	*	91	WORKSHOP CONSUMABLES	
Ⓟ	*	1707300	Service alert system, configuration and	
	☒		reports	
Ⓟ	Ⓞ	VO-1752300	Gearbox oil and filter, replace. Lube ar	0.4
	☒		MINERAL	
Ⓟ	Ⓞ	VO-1752700	Final drive oil, change. Lube area	0.6
	☒		MINERAL	
Ⓟ	☒	AU2-CAL85121714	VOLVO SAE50 TRANS	17
Ⓟ	☒	AU2-CAL85121715	VOLVO 85W140 GEAR - DIFF OIL	34
Ⓟ	☒	AU2-AMP23068346	VOLVO ENGINE OIL VDS4	43
Ⓟ	☒	VO-20779040	FILTER TRANS ISHIFT	1
Ⓟ	☒	VO-24122024	FILTER KIT	1
Ⓟ	*	91	WORKSHOP CONSUMABLES	

**2021-10-06 - Mileage: 1164025 - Order nr: 8150121**

Ⓟ	*	M	PLEASE FILL IN	
	☒		Gurdeep: 0450 150 095	
Ⓟ	Ⓞ	VO-1771800	Basic service, city	3.1
Ⓟ	*	91	WORKSHOP CONSUMABLES	
Ⓟ	☒	VO-24122024	SERVICE KIT	1
Ⓟ	Ⓞ	VO-2141300	Valves and unit injectors, adjust	3.5
Ⓟ	Ⓞ	VO-1752700	Final drive oil, change. Lube area	0.8
	☒		mineral oil	
Ⓟ	☒	VO-1161277	LINER SILASTIC	1
Ⓟ	☒	AU2-9718-240002743	BBC4 BRAKE CLEANER	1
Ⓟ	☒	VO-949329	WASHER, COPPER DIFF	4
Ⓟ	☒	VO-20736230	SEAL STRIP, R/COVER GASKET	1
Ⓟ	☒	AU2-AMP23068346	VDS 4.5 ENG OIL - BULK*	42.5
Ⓟ	☒	AU2-CAL85121715	OIL GEAR 85W140 BULK*	36.1
	☒		Mileage:1164025	
	☒		Hrs:19242	
	☒		Next Service:1,209,000KM or 5/04/2022	
Ⓟ	*	97	ENVIRONMENTAL CHARGE	
Ⓟ	*	91	WORKSHOP CONSUMABLES	

**2021-05-07 - Mileage: 1093939 - Order nr: 7278094**

	☒		Gurdeep:0450 150 095/blackeagle0095@gmail.com	
Ⓟ	Ⓞ	LO-465	D&R ON TAIL SHAIFT CAME ADRIFT AND HAS	20
	☒		DAMAGED AIRLINES- ASSESS DAMAGE AND ADVISE	
	☒		**TRUCK TOWED IN- CUSTOMER ORGANISED TOW**	



PC	Type	Code	Description (Original)	#
Ⓟ	■	VO-20877939	FILTER CAP	1
Ⓟ	■	MK-NARV56306	CABLE TIE 300MMX4.8 25PK	2
Ⓟ	■	VO-980832	8MM AIRLINE PLASTIC	2
Ⓟ	■	VO-980833	12MM AIRLINE PLASTIC	1
Ⓟ	■	AU2-9701-GP1162M12	12MM JOINER	4
Ⓟ	■	MK-FTM62X16	JOINER HOSE 16MM	2
Ⓟ	■	MK-FTM62X8	JOINER, 8MM TUBE	2
Ⓟ	■	VO-991092	NIPPLE	1
Ⓟ	■	VO-991080	NIPPLE	1
Ⓟ	■	VO-994000	ELBOW NIPPLE MEDx12mm	1
Ⓟ	■	VO-991980	T NIPPLE	1
Ⓟ	■	VO-991075	NIPPLE Regular-12x1.5	1
Ⓟ	■	VO-991075	NIPPLE Regular-12x1.5	2
Ⓟ	■	VO-992013	F NIPPLE	2
Ⓟ	■	MK-FTM62X8	JOINER, 8MM TUBE	7
Ⓟ	■	VO-980832	8MM AIRLINE PLASTIC	3
Ⓟ	■	MK-FT62X5	5/16 JOINER	1
Ⓟ	■	VO-21429181	HOSE	5
Ⓟ	■	VO-975269	HOSE CLAMP	4
Ⓟ	■	MK-NARV56713	TUBING SPLIT 13MMX10M	1
Ⓟ	■	VO-20748166	CONNECTOR,SAE 3/8	2
Ⓟ	■	VO-20744599	CONNECTOR,5/16	1
Ⓟ	■	VO-20748166	CONNECTOR,SAE 3/8	1
Ⓟ	■	VO-20744597	CONNECTOR,SAE 5/16	1
Ⓟ	■	OTH-NARV587330TC/1MT	CABLE 7 CORE 3MM	1
Ⓟ	■	VO-20791305	SEALING RING	1
Ⓟ	■	VO-20785448	BALL BEARING	1
Ⓟ	■	VO-1652802	RETAIN.RING,3.7THK	1
Ⓟ	■	VO-1652803	RETAIN.RING,3.8THK	1
Ⓟ	■	VO-1652804	RETAIN.RING,3.9THK	1
Ⓟ	■	VO-914556	RETAIN.RING,4.0THK	1
Ⓟ	■	MK-NARV56820BK	NITTO INSULATION TAPE 19MM	1
Ⓟ	■	VO-25106045	CLAMP HOSE -5/8:	4
Ⓟ	■	MK-FT3400X6	BRASS PIPE	1
Ⓟ	■	VO-944364	O-RING	2
Ⓟ	■	VO-949656	O-RING	2
Ⓟ	■	MK-342SX33	SILICONE DOW	1

PC	Type	Code	Description (Original)	#
Ⓟ	Ⓜ	VO-20785252	LID GASKET KIT	1
Ⓟ	Ⓜ	VO-995906	HEX BOLT M14X46 FINE	4
Ⓟ	Ⓜ	VO-984050	HEX NUT M14 FINE	4
Ⓟ	Ⓜ	VO-993252	NIPPLE	1
Ⓟ	Ⓜ	MK-FTM62X8	JOINER, 8MM TUBE	1
Ⓟ	Ⓜ	AU2-CAL85121714	VOLVO SAE50 TRANS	15
Ⓟ	Ⓜ	MK-FT62X5	5/16 JOINER	1
Ⓟ	Ⓜ	MK-FTM62X8	JOINER, 8MM TUBE	1
Ⓟ	Ⓜ	VO-85001704	EXCH GEARBOX	1
Ⓟ	Ⓜ	LO-471	GEARBOX SPECIAL PACKAGE	6
Ⓟ	Ⓜ	LO-470	SPEC UP GEARBOX	4
Ⓟ	Ⓜ	VO-23701845	OIL HOSE ISHIFT SMALL	1
Ⓟ	Ⓜ	VO-23701846	OIL HOSE ISHIFT LARGE	1
Ⓟ	Ⓜ	VO-995906	HEX BOLT M14X46 FINE	2
Ⓟ	Ⓜ	VO-984050	HEX NUT M14 FINE	2
Ⓟ	Ⓜ	VO-1701000	Connect-disconnect of diagnostic tool	0.35
	Ⓜ		CUSTOMER	
	Ⓜ		Removed gearbox and tailshaft and assessed damage from	
	Ⓜ		tailshaft that had come out. Had to replace and run all new	
	Ⓜ		airlines for brakes and suspension. Replaced 4 way valve	
	Ⓜ		fittings. Replaced damaged adblue pump tubing and replaced	
	Ⓜ		wiring for trailer modulator valve. Removed damaged	
	Ⓜ		gearbox rear housing as it was cracked. Customer supplied	
	Ⓜ		second hand housing and second hand tailshaft. Fitted	
	Ⓜ		housing to gearbox and refitted gearbox and tailshaft.	
	Ⓜ		Road tested vehicle and found it had bad vibration. Traced	
	Ⓜ		to bent mainshaft in gearbox from impact damage from	
	Ⓜ		tailshaft failure. Replaced with new gearbox – Refer below	
	Ⓜ		special -	
Ⓟ	Ⓜ	LO-430	GEARBOX	9.94
	Ⓜ		Swapped over gearbox oil cooler and replaced leaking hoses.	
	Ⓜ		Programmed gearbox and filled with new oil.	
Ⓟ	*	91	WORKSHOP CONSUMABLES	
🔍	<b>2020-11-20 - Mileage: 0 - Order nr: 8139360</b>			
	Ⓜ		Repair without detail info	
🔍	<b>2020-09-22 - Mileage: 950833 - Order nr: 7270621</b>			
	Ⓜ		GURDEEP 0450 150 095	
	Ⓜ		fitted with a D16 Euro 5 Motor as per	



PC	Type	Code	Description (Original)	#
	☑		Carry out Basic Volvo Service on truck	
	☑		Volvo Truck Guidelines.	
Ⓟ	Ⓞ	LO-177P414	Basic Service :	4
Ⓟ	*	91	WORKSHOP CONSUMABLES	
Ⓟ	*	93	OILS & GREASE	
Ⓟ	*	97	ENVIRONMENTAL CHARGE	
Ⓟ	☑	AU2-CAL85121795	BULK VDS4 ENGINE OIL	45
Ⓟ	☑	VO-85136742	FILTER KIT (FK18B)	1
Ⓟ	☑	AU2-CAL85121715	GEAR OIL 85/140	5
Ⓟ	☑	VO-992519	GLOBE BA15S 24V 5W	2
Ⓟ	Ⓞ	LO-353	RECTIFY LIGHTS INOP	0.5
Ⓟ	*	100	TOP UP DIFF OIL OART CHARGE ONLY	
	☑		BRAKE REPORT	
	☑		Replace 2 blown roof light globes & check operation ok.	
	☑		1st Axle 90%	
	☑		2nd Axle 90%	
	☑		3rd Axle 90%	
	☑		WORK LIST	
	☑		1/ Passenger's side outer fog light inop	
	☑		2/ Windscreen washer bottle leaking Next 2 weeks	
	☑		3/ Front Cab shocks worn Next 2 weeks	
	☑		4/ Multiple turntable mount bolts loose, Urgent repair	
	☑		needed	
	☑		5/ Engine oil filler hose leaking at sump monitor	
	☑		6/ Rear steering spring shackle pin bushes worn, Urgent	
	☑		repair needed	
	☑		7/ Rear engine mounts worn Next 2 weeks	
	☑		8/ 2nd Axle air bags leaking air Next 2 weeks	
	☑		9/ Front diff thru shaft seal leaking oil Next 2 weeks	
	☑		10/ Gearbox oil cooler hoses leaking Next 2 weeks	
	☑		11/ 2nd & 3rd Axles seals leaking both sides Monitor	
	☑		12/ Coolant level was low not external leaks Monitor	
	☑		13/ Both Cab rams leaking oil Monitor	
	☑		14/ Windscreen wiper blades worn	
	☑		15/ Power steering reservoir leaking oil Monitor	
	☑		16/ Steering box leaking oil Monitor	
Ⓟ	*	91	WORKSHOP CONSUMABLES	
🔍	<b>2020-07-15 - Mileage: 914936 - Order nr: 7268429</b>			

PC	Type	Code	Description (Original)	#
	📄		Gurdeep:0450 150 095	
🔧	🕒	LO-432	D&R WON'T GO MORE THAN 40KM/HR IN AUTO	2.75
	📄		GEAR BUT OK IN MANUAL - WHILE DRIVING IT MISSES & DROPS	
🔧	📄	VO-22387296	VEHICLE SPEED SENS	1
🔧	🕒	VO-1701000	Connect-disconnect of diagnostic tool	0.4
🔧	🕒	LO-P22SHTR	Short Road Test	0.5
	📄		Went on run with driver & replicate fault. Checked codes &	
	📄		checked speedo sensor, found connector full or corrosion,	
	📄		cleaned pins, checked wiring found wiring modified &	
	📄		corrosion in loom, cut out modifications & wired back to	
	📄		OEM standard, replace speedo sensor, calibrated clutch &	
	📄		gearbox, road tested with driver & now working correctly.	
	📄		GEAR THEN PICKS UP AGAIN	
🔧	✳	91	WORKSHOP CONSUMABLES	
<b>🔍 2020-06-24 - Mileage: 902074 - Order nr: 7267733</b>				
	📄		GURDDEEP - 0450 150 095	
	📄		fitted with a D16 Euro 5 Motor as per	
	📄		Carry out Basic Volvo Service on truck	
	📄		Volvo Truck Guidelines.	
🔧	🕒	LO-177P414	Basic Service :	4
🔧	✳	91	WORKSHOP CONSUMABLES	
🔧	✳	93	OILS & GREASE	
🔧	✳	97	ENVIRONMENTAL CHARGE	
🔧	📄	AU2-CAL85121795	BULK VDS4 ENGINE OIL	45
🔧	📄	VO-85136742	FILTER KIT (FK18B)	1
	📄		Remove wheels, replace pads, refit	
	📄		wheels, tension wheel nuts.	
🔧	🕒	LO-510	WHEEL BRAKES-GENERAL	5
🔧	📄	VO-23149532	BRAKE PAD KIT	2
	📄		Carried out 2nd & 3rd axle brake relines.	
	📄		BRAKE REPORT	
	📄		1ST AXLE 50%	
	📄		2ND AXLE 100% (NEW)	
	📄		3RD AXLE 100% (NEW)	
	📄		1-CABIN PANELS HELD ON BY CABLE TIES	
	📄		2-TWO ROOF LIGHTS INOP	
	📄		3-MINOR OIL LEAK UPPER TIMING COVER	
	📄		4-GEARBOX HARNESS EXPOSED	



PC	Type	Code	Description (Original)	#
<b>2020-01-23 - Mileage: 816865 - Order nr: 8126790</b>				
	*	M	PLEASE FILL IN	
	E		Contact:Gurdeep 0450 150 095	
	U	LO-430	CHANGE TRANSMISSION SETTING FROM	1
	E		PERFORMANCE TO LINEHAUL.	
	U	VO-1752300	Gearbox oil and filter, replace. Lube ar	0.6
	E		area	
	R	AU2-CAL85121714	OIL TRANSMISSION SAE50 BULK	16
	R	VO-20779040	SERVICE KIT, OIL FILTER	1
	R	VO-85121291	CONVERSION KIT	1
	R	VO-85121286	CONVERSION KIT	1
	E		Mileage:816865	
	E		Hrs:14076	
	E		Hooked up the laptop. Ordered accessory kit and	
	E		reprogrammed mid130.recalibrate the gearbox. Deleted the	
	E		fault codes.	
	*	97	ENVIRONMENTAL CHARGE	
	*	91	WORKSHOP CONSUMABLES	
<b>2019-12-13 - Mileage: 811326 - Order nr: 7261921</b>				
	E		GURDEEP 0450 150 095	
	U	LO-261	D&R COOLANT LEAK AT RADIATOR AREA	7
	E		S0478 TECU, SW UPDATE. FH/FM	
	U	VO-1701000	Connect-disconnect of diagnostic tool	0.2
	U	VO-4329400	MID 130 Control unit. Only campaign	0.3
	U	VO-4007000	Gearbox, clutch, engagement point, calib	0.2
	E		calibration	
	R	VO-85003229	RADIATOR, EXCH	1
	R	AU2-CAL85108913	5L VOLVO VCS COOLANT	1
	R	VO-984749	FLANGE SCREW	1
	R	VO-990950	FLANGE LOCK NUT	1
	R	VO-20968736	RADIATOR HOSE	1
	R	VO-20740344	HOSE	1
	R	VO-993975	HOSE CLAMP	1
	R	VO-995680	HOSE CLAMP	1
	*	91	WORKSHOP CONSUMABLES	
<b>2019-12-12 - Mileage: 810397 - Order nr: R01066654</b>				
	E		Carried out campaign	
	U	VO-4329400	MID 130 Control unit. Only campaign	0.3

PC	Type	Code	Description (Original)	#
		VO-4007000	Gearbox, clutch, engagement point, calibration	0.2
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
<b>2019-04-12 - Mileage: 781483 - Order nr: 8623385</b>				
		VO-2141300	Valves and unit injectors, adjust	3
			TUNE UP.	
		VO-20736230	SEALING STRIP	1
		VO-21190817	V-RIBBED BELT	1
		VO-21454379	BELT TENSIONER	1
		VO-21133804	V-RIBBED BELT	1
		VO-21753149	IDLER PULLEY	1
		VO-2630000	Fan, fan shroud and clutch. Secondary op	2
			REMOVED TAPPET COVER AND CARRIED OUT VALVE AND UNIT	
			INJECTOR ADJUSTMENTS. RECORDED MEASUREMENTS.	
			REFIT TAPPET COVER WITH NEW SEAL AND TENSION.	
			WASHED DOWN ENGINE AREA.	
			DURING REPAIR FOUND FAN AND ALTERNATOR BELTS CRACKED AND	
			FAILED. REPLACED ALTERNATOR BELT TENSIONER AND FAN BELT	
			IDLER PULLEYS. FITTED NEW FAN AND ALTERNATOR BELTS.	
			RUN ENGINE AND CHECK ALIGNMENT.	
	*	97	ENVIRONMENTAL CHARGE	
	*	91	WORKSHOP CONSUMABLES	
<b>2018-06-15 - Mileage: 727729 - Order nr: 4880943</b>				
	*	4110000	LOST DRIVE ON NATHAN STREET.	
	*	4310000	CLUTCH HOUSING.	
			PARTS WARRANTY CLAIM FITTED 22/11/2017 ON 8618566 AT	
			GOODWILL ASSISTAN.	
			526536KCOMPLAINT: LOST ALL DRIVE.	
			CAUSE: COMMUNICATION FAULT AND AIR LEAKING IN CONTROL	
			HOUSING.	
			CORRECTION: REMOVED TRANSMISSION CONTROL HOUSING AND	
			REPLACED COMMUNICATION HARNESS AND SEALING RINGS.	
			PARTS WARRANTY CLAIM FITTED 22/11/2017 ON 8618566 AT 526536K	
			EXCESS LABOUR CLAIMED CLAIMED 8 HOURS PD 1.4 HOURS	
			COMPLAINT: LOST ALL DRIVE.	
			CAUSE: CLUTCH CYLINDER AND CONTROL VALVE FAILURE.	
			CORRECTION: REMOVED TRANSMISSION AND REPLACED CLUTCH	
			CYLINDER AND CONTROL VALVE.	
			COMMERCIAL GOODWILL MICHAEL GOMERSALL.	



PC	Type	Code	Description (Original)	#
	☒		EXCESS LABOUR CLAIMED 12 HOURS PAID 7 HOURS	
<b>2018-05-02 - Mileage: 742243 - Order nr: 8620240</b>				
Ⓡ	Ⓢ	VO-5610000	Compressor, regulator, anti-freeze unit.	3
Ⓡ	Ⓢ	VO-992247	SWIVEL	1
	☒		CONNECTED VCADS COMPUTER AND READ VEHICLE INFORMATION.	
Ⓡ	*	97	ENVIRONMENTAL CHARGE	
	☒		FOUND FAULT CODE MID 144, PSID 23, FMI 4. AIR DRYER	
	☒		REGENERATION. ABNORMALLY LOW VOLTAGE OR SHORT CIRCUIT.	
	☒		CARRIED OUT INSPECTION OF AIR SYSTEM.	
	☒		LOAD TESTED AND CHECKED WIRING TO AIR DRYER.	
	☒		REPLACED BLOWN FUSE IN NUMBER 6 POSITION.	
	☒		REPAIRED AIR LEAKING AT AIR DRYER.	
	☒		CLEARED FAULT CODES AND ROAD TESTED.	
	☒		RECHECKED AFTER ROAD TEST.	
Ⓡ	*	91	WORKSHOP CONSUMABLES	
<b>2018-04-03 - Mileage: 727729 - Order nr: 8619913</b>				
Ⓢ	Ⓢ	VO-4110000	Mechanical clutch. Secondary operation n	8
Ⓢ	Ⓢ	VO-22117441	KIT	1
Ⓢ	Ⓢ	VO-20562642	KIT	1
Ⓢ	Ⓢ	VO-20785252	KIT	1
Ⓢ	Ⓢ	VO-21244695	GASKET	1
Ⓢ	Ⓢ	VO-21339891	RUBBER HOSE	1
Ⓢ	Ⓢ	VO-21052612	CONNECTOR	1
Ⓢ	Ⓢ	VO-21380391	CONNECTOR	1
Ⓢ	Ⓢ	VO-85013166	CYLINDER	1
Ⓢ	Ⓢ	VO-983472	CABLE TIE	3
Ⓢ	Ⓢ	VO-22429386	OIL HOSE	1
Ⓢ	Ⓢ	VO-22429384	OIL HOSE	1
Ⓢ	Ⓢ	VO-20992763	AIR HOSE	1
Ⓢ	Ⓢ	VO-20860677	SEALING RING	1
Ⓢ	Ⓢ	VO-20722721	AIR INLET	1
Ⓢ	Ⓢ	VO-1521975	LOCK BRACE	1
Ⓢ	Ⓢ	VO-994102	HEXAGON SCREW	8
Ⓢ	Ⓢ	VO-25339078	HEXAGON NUT	8
Ⓢ	Ⓢ	VO-20544196	ELBOW NIPPLE	1
Ⓢ	Ⓢ	VO-22327063	SOLENOID VALVE	1
Ⓢ	Ⓢ	VO-948211	STRIP CLAMP	5
Ⓢ	Ⓢ	VO-4310000	Gearbox, manual. Secondary operation num	12

PC	Type	Code	Description (Original)	#
		VO-4310000	Gearbox, manual. Secondary operation num	1
		VO-4310000	Gearbox, manual. Secondary operation num	1
			PARTS WARRANTY CLAIM FITTED 22/11/2017 526536 K 8618566.	
		VO-85000882	DRIVEN PLATE, EXCH	1
			PARTS WARRANTY CLAIM FITTED 22/11/2017 ON 8618566 AT	
			526536K COMPLAINT: LOST ALL DRIVE.	
			CAUSE: COMMUNICATION FAULT AND AIR LEAKING IN CONTROL	
			HOUSING.	
			CORRECTION: REMOVED TRANSMISSION CONTROL HOUSING AND	
			REPLACED COMMUNICATION HARNESS AND SEALING RINGS.	
			PARTS WARRANTY CLAIM FITTED 22/11/2017 ON 8618566 AT 526536K	
			GOODWILL ASSISTAN.	
			COMPLAINT: LOST ALL DRIVE.	
			CAUSE: CLUTCH CYLINDER AND CONTROL VALVE FAILURE.	
			CORRECTION: REMOVED TRANSMISSION AND REPLACED CLUTCH	
			CYLINDER AND CONTROL VALVE.	
			COMMERCIAL GOODWILL MICHAEL GOMERSALL.	
			COMPLAINT: OIL FILTER HOSES LEAKING OIL.	
			CAUSE: POOR CRIMPING OF HOSES.	
			CORRECTION: FITTED NEW WHSES AND CLEANED AREA.	
			PARTS WARRANTY CLAIM FITTED 22/11/2017 526536 K 8618566.	
			COMMERCIAL GOODWILL ASSISTANCE.	
			COMPLAAINT: TRANSMISSION COOLER HOSE LEAKING.	
			CAUSE: POOR SEALING.	
			CORRECTION: FITTED NEW COOLER HOSE AND FITTINGS.	
			COMMERCIAL GOODWILL MICHAEL GOMERSALL.	
<b> 2017-12-05 - Mileage: 683333 - Order nr: 8618801</b>				
		VO-1701000	Connect-disconnect of diagnostic tool	6
		VO-21620181	KIT	1
		VO-948211	STRIP CLAMP	5
		VO-85139619	PRESSURE SENSOR	1
		VO-21582423	KIT	1
			VO/21582423 WAS FITTED BY BRANCH 4800	
			.- ON REPAIR ORDER 8615989 - DATE 2016-12-23 MILEAGE - 496162	
			VO/85139619 WAS FITTED BY BRANCH 4800	
			.- ON REPAIR ORDER 8615989 - DATE 2016-12-23 MILEAGE - 496162	
		VO-2850800	Exhaust back pressure sensor, replace	0.2
		VO-2530000	Exhaust brake, exhaust pressure governor	2



PC	Type	Code	Description (Original)	#
W	U	VO-3711700	Connector, replace (1-8 cables)	0.3
W	U	VO-3710200	Electric wires and connections, check	0.4
W	U	VO-1701000	Connect-disconnect of diagnostic tool	0.2
W	U	VO-1701200	Fault codes, reading	0.2
	E		PARTS WARRANTY CLAIM FITTED 8615989 23/12/2016 AT 496162 K.	
	E		COMPLAINT: ENGINE FAULT ON DISPLAY.	
	E		CAUSE: MID 128, PSID 131 FMI 5 EXHAUST BACK PRESSURE.	
	E		CORRECTION: CONNECTED VCADS COMPUTER AND READ VEHICLE	
	E		INFORMATION. CHECKED WIRING AND CONNECTIONS TO BACK	
	E		PRESSURE SENSOR. REPLACED SENSOR AND ADAPTION HARNESS.	
	E		CLEARED FAULT CODES AND RECHECK.	
	E		ATTEND TO SYSTEM FAUT CODES ON DISPLAY.	
	E		CONNECT VCADS COMPUTER AND READ VEHICLE INFORMATION.	
	E		FOUND FAULTS STORED FOR AD-BLUE SYSTEM, EXHAUST BACK	
	E		PRESSURE AND BOOST PRESSURE.	
	E		CHECKED AB-BLUE PUMP AND WIRING, NO FAULTS.	
	E		CARRIED OUT SCR SYSTEM PRESSURE TEST AND ALL GOOD.	
	E		PRESSURE TESTED INTERCOOLER AND CHECK FOR LEAKS. NO LEAKS.	
	E		REPLACED AIR DRYER FILTER CANISTER AND CLEANED AND CHECKED	
	E		DRYER, CARRIED OUT RESET CALIBRATION.	
	E		CARRIED OUT ENGINE COMPRESSION TEST AND FOUND CYLINFER 3	
	E		DOWN ON COMPRESSION AND BELOW SPECIFICATION.	
	E		ADVISED RAY OF FINDINGS.	
U	*	97	ENVIRONMENTAL CHARGE	
<b>2017-09-23 - Mileage: 637743 - Order nr: 8618173</b>				
U	U	VO-1701000	Connect-disconnect of diagnostic tool	1.2
U	R	VO-22889891	ACTUATOR SERVICE K	1
	E		CONNECT VCADS COMPUTER AND READ VEHICLE INFORMATION.	
	E		FOUND ERROR CODE MID 128, PID 131, FMI 2.	
	E		CARRIED OUT ENGINE BRAKE CHECKD.	
	E		CHECKED AND FOUND EXHAUST ACTUATOR LEAKING.	
	E		FITTED A NEW ACTUATOR AND RECHECKED OPERATION.	
	E		CLEARED FAULT CODES. ROAD TEST AND RECHECK.	
	E		*** NOTE ***	
	E		EXHAUST MANIFOLD AND TURBO MOUNT LEAKING GAS.	
	E		REBOOKED THURSDAY 28/09/2017.	
U	*	97	ENVIRONMENTAL CHARGE	
<b>2017-08-31 - Mileage: 624004 - Order nr: 8618001</b>				

PC	Type	Code	Description (Original)	#
Ⓡ	Ⓢ	VO-4110000	Mechanical clutch. Secondary operation n	14
Ⓡ	Ⓢ	VO-5610000	Compressor, regulator, anti-freeze unit.	4
Ⓡ	Ⓢ	VO-22327063	SOLENOID VALVE	1
Ⓢ	Ⓢ	VO-22989089	FLYWHEEL	1
Ⓡ	Ⓢ	VO-20992763	AIR HOSE	1
Ⓡ	Ⓢ	VO-20860677	SEALING RING	1
Ⓡ	Ⓢ	VO-994102	HEXAGON SCREW	8
Ⓡ	Ⓢ	VO-25339078	HEXAGON NUT	8
Ⓡ	Ⓢ	AU2-9770-5089	BRAKLEEN 500g Aer	1
Ⓡ	Ⓢ	VO-6781769	SPLICE-RED(22-18)	1
Ⓡ	Ⓢ	VO-948211	STRIP CLAMP	20
Ⓡ	Ⓢ	VO-980464	STRIP CLAMP	20
Ⓢ	*	2160000	P3212 FLYWHEEL REPLACE FH16.	
	Ⓢ		ATTEND TO AIR SYSTEM FAULT MID 144, PSID 23, FMI 4.	
	Ⓢ		CHECKED CONNECTION TO AIR DRYER AND FOUND OXIDATION IN	
	Ⓢ		PLUG AND TERMINALS. CLEANED TERMINALS AND CHECKED POWER	
	Ⓢ		SUPPLY.	
	Ⓢ		REMOVED EB PLUG ON FIREWALL AND CHECKED CONTINUITY.	
	Ⓢ		FOUND BROKEN WIREIN HARNESS.	
	Ⓢ		STRIPPED HARNESS AND REPAIRED WIRE AND REINSULATED AND	
	Ⓢ		SECURED.	
	Ⓢ		CLEARED FAULT CODE AND RECHECKED AIR SYSTEM.	
	Ⓢ		CONNECTED VCADS COMPUTER AND READ VEHICLE INFORMATION.	
	Ⓢ		FOUND CLUTCH RELEASE CYLINDER FAILED.	
	Ⓢ		DRAINED COOLANT AND REMOVED TAILSHAFT.	
	Ⓢ		DISCONNECTED AIR, PTO AND ELECTRICS FROM GEARBOX.	
	Ⓢ		REMOVED GEARBOX, CLUTCH AND FLYWHEEL.	
	Ⓢ		FITTED NEW FLYWHEEL CLUTCH KIT. NEW CLUTCH CYLINDER.	
	Ⓢ		FIT NEW PWM VALVE AND HOSE.	
	Ⓢ		REFIT GEARBOX AND CONNECT AIR, PTO AND ELECTRICS.	
	Ⓢ		REFIT TAILSHAFT.	
	Ⓢ		CARRIED OUT GEARBOX AND CLUTCH CALIBRATIONS,	
	Ⓢ		REFILL BLEED AND TOP UP COOLANT.	
	Ⓢ		WASHED AND CLEANED AREA.	
	Ⓢ		ROAD TEST AND RECHECK.	
Ⓡ	*	97	ENVIRONMENTAL CHARGE	
	Ⓢ		COMPLAINT: VIBRAION AT IDLE AND ABOVE.	
	Ⓢ		CAUSE:TWIN MASS FLYWHEEL FAILURE.	



PC	Type	Code	Description (Original)	#
	☒		CORRECTION: FITTED SINGLE MASS FLYWHEEL KIT.	
Ⓡ	*	91	WORKSHOP CONSUMABLES	
<b>2016-12-23 - Mileage: 503425 - Order nr: 8616125</b>				
Ⓡ	Ⓢ	VO-8610000	Bumper with mounting and damping	0.6
Ⓡ	*	2370000	CHECK FOR HARD STARTING FUEL DRAIN BACK.	
Ⓡ	Ⓡ	VO-85013343	UNIT INJECTOR, EXC	1
Ⓡ	Ⓡ	VO-21351717	INJECTOR SLEEVE	6
Ⓡ	Ⓡ	VO-1677370	SEALING RING	2
Ⓡ	Ⓡ	VO-20526428	SEALING RING	1
Ⓡ	Ⓡ	VO-21344774	FLANGE SCREW	6
Ⓡ	Ⓡ	VO-983472	CABLE TIE	8
Ⓡ	Ⓡ	AU2-9770-2019	ELECTRICAL PARTS C	1
Ⓡ	Ⓡ	VO-FREIGHT	FREIGHT	30
Ⓡ	Ⓡ	VO-21261987	GASKET	2
Ⓡ	Ⓡ	VO-21458307	OVERFLOW VALVE	1
Ⓡ	Ⓡ	VO-20852765	GASKET	2
Ⓡ	Ⓡ	VO-85013343	UNIT INJECTOR, EXC	1
Ⓡ	Ⓡ	VO-20723207	SEALING RING	1
	☒		INSPECT AND SECURE/TIGHTEN BULLBAR AS REQUIRED	
	☒		ATTEND TO HARD STARTING	
Ⓡ	Ⓢ	VO-1701000	Connect-disconnect of diagnostic tool	0.2
Ⓡ	Ⓢ	VO-1701200	Fault codes, reading	0.2
Ⓡ	Ⓢ	VO-2100600	Cylinder Compression, test	0.2
Ⓡ	Ⓢ	VO-2840700	Sensor values, check	0.2
Ⓡ	Ⓢ	VO-2301600	Cylinder balancing, check	0.2
Ⓡ	Ⓢ	VO-1703400	Vehicle information, test	0.2
Ⓡ	Ⓢ	VO-2302100	Fuel consumption, check	0.3
Ⓡ	Ⓢ	VO-2371200	Injector shut off, manual	0.4
Ⓡ	Ⓢ	VO-1703000	Parameter, programming	0.2
Ⓡ	Ⓢ	VO-2373400	Unit injector, replace (one)	1.8
Ⓡ	Ⓢ	VO-2141300	Valves and unit injectors, adjust	1.8
	☒		PC CONNECT AND DISCONNECT READ FAULT CODES, CARRIED OUT	
	☒		FAULT CODE TEST, VEHICLE INFORMATION TEST.	
	☒		2 X UNITS INJECTORS NO:1 AND NO:6 FAILURE	
	☒		DRAIN FUEL FROM CYLINDER HEAD REMOVE ROCKER SHAFT	
	☒		REMOVE AND REPLACE UNIT INJECTOR NO:6 AND NO:1	
	☒		REMOVE AND REPLACE COPPER SLEEVES INSTALL ROCKER	
	☒		SHAFT-CARRIED OUT A VALVE AND UNIT INJECTOR	

PC	Type	Code	Description (Original)	#
	☒		ADJUSTMENTS. BLEED FUEL SYSTEM START UP AND CHECK OPERATION	
	☒		TEST DRIVE FOUND TO BE ALL OK	
	☒		REMOVED SERIAL NUMBER 1 Å43498319	
	☒		NEW SERIAL NUMBER NUMBER 1 Å23420629	
	☒		REMOVED SERIAL NUMBER 6 Å43504319	
	☒		NEW SERIAL NUMBER NUMBER 6 Å23405629	
Ⓢ	*	91	WORKSHOP CONSUMABLES	
<b>2016-12-09 - Mileage: 497306 - Order nr: 8616012</b>				
Ⓢ	Ⓢ	VO-1774400	Basic service. Chassis lubrication and o	4
Ⓢ	Ⓢ	VO-1707300	Service alert system, configuration and	0.4
Ⓢ	Ⓢ	VO-1750400	Lubrication according to actual lubricat	0.2
Ⓢ	Ⓢ	VO-2331100	Filter, water separator, replace	0.5
Ⓢ	Ⓢ	VO-2330600	Fuel filter, replace (one)	0.4
Ⓢ	Ⓢ	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
Ⓢ	Ⓢ	VO-2582200	Filter, AdBlue, replace	0.3
Ⓢ	*	3860000	CHECK FOR ROAD SPEED SENSOR FAULT.	
	☒		OCCURED ONCE.	
Ⓢ	Ⓢ	VO-FK18B	FILTER KIT	1
Ⓢ	Ⓢ	AU2-CAL85121795	VDS4 BULK ENGINE O	42
Ⓢ	Ⓢ	VO-21333097	FILTER KIT ADBLUE	1
Ⓢ	Ⓢ	VO-2562400	Filter insert, air cleaner, replace. Onl	0.5
Ⓢ	Ⓢ	VO-21716424	AIR FILTER	1
Ⓢ	Ⓢ	VO-2562500	Secondary air filter, replace. Air filte	0.2
Ⓢ	Ⓢ	VO-20411816	AIR FILTER	1
Ⓢ	Ⓢ	VO-8720800	Air conditioning air filter, replace	0.5
Ⓢ	Ⓢ	VO-21758906	FILTER	1
Ⓢ	Ⓢ	VO-21620181	KIT	1
Ⓢ	Ⓢ	VO-20545485	DIAPHRAGM	1
Ⓢ	Ⓢ	VO-992519	BULB	2
Ⓢ	Ⓢ	VO-3520000	Lighting, front. Secondary operation num	1
Ⓢ	*	3500000	FIT NEW SPOT LIGHTS.	
Ⓢ	*	30	ATTEND TO FIT NEW SPOT LIGHTS.	
Ⓢ	Ⓢ	OTH-PVQ1700P	POWER VISION QUATTRO	2
Ⓢ	Ⓢ	VO-5612600	Air drier, drier insert, replace	0.5
Ⓢ	Ⓢ	VO-3511800	Bulb position light, replace (roof mount	0.1
Ⓢ	Ⓢ	VO-4650000	Final drive (front and rear). Secondary	0.5
	☒		INVOICE 17105	
	☒		Fit new spot lights ( supplied by customer).	



PC	Type	Code	Description (Original)	#
	☒		CARRIED OUT HEADLIGHT CHECK AND ADJUSTMENT.	
	☒		FOUND LEFT HAND HEADLIGHT LOW BEAM LENS LOOSE.	
	☒		NEEDS A NEW LEFTR HAND HEADLIGHT ASSEMBLY.	
	☒		FOUND AIR LEAKING AT DIFFERENTIAL.	
	☒		REPLACED LEAKING DIAPHRAM. RECHECKED FOR AIR LEAKS.	
	☒		CHECKED FOR ROAD SPEED FAULTS. NO FAULTS RECORDED AND ALL	
	☒		CONNECTIONS AND SENSOR IN GOOD ORDER,	
	☒		CARRIED OUT BASIC SERVICE AS PER SCHEDULE.	
	☒		CHANGED ENGINE OIL AND FILTERS.	
	☒		CHANGED ALL AIR FILTERS, AD-BLUE FILTER AND AIR DRYER FILTER	
	☒		REPLACED BLOWN GLOBES AS REQUIRED.	
	☒		CARRIED OUT ALL SYSTEM CHECKS.	
	☒		WASHED DOWN ENGINE BAY.	
Ⓜ	*	97	ENVIRONMENTAL CHARGE	
Ⓜ	*	91	WORKSHOP CONSUMABLES	

🔍 **2016-12-06 - Mileage: 496162 - Order nr: 8615989**

Ⓜ	*	8700000	CHECK ICEPACK NOT STARTING.	
Ⓜ	🔧	VO-1701000	Connect-disconnect of diagnostic tool	2
Ⓜ	*	80	ATTEND TO ICEPACK NOT STARTING.	
Ⓜ	🔧	VO-85139619	PRESSURE SENSOR	1
Ⓜ	🔧	VO-21582423	KIT	1
	☒		INVOICE 17064	
	☒		Inspect Icepack not starting. Found battery no good.	
	☒		Battery mounted in poor place. Remove battery.	
	☒		Relocate battery and rerun cables.	
	☒		Customise bracket to suit. Mount and fit new battery.	
	☒		Test starting and charging- fine.	
	☒		12V 230CCA 20AMP/HR Hardcore Fullriver Battery	
	☒		CONNECT VCADS COMPUTER AND CHECKED FAULT CODES.	
	☒		FOUND ADCIVE FAULTS FOR BACK PRESSURE SENSOR, SILENCER,	
	☒		AD-BLUE SYSTEM.	
	☒		ATTENDED TO BACK PRESSURE SENSOR FAULT.	
	☒		FITTED A NEW SENSOR AND WIRING ADAPTION HARNESS.	
	☒		CLEARED FAULT CODES. ROAD TEST AND RECHECK.	
Ⓜ	*	97	ENVIRONMENTAL CHARGE	

🔍 **2016-11-28 - Mileage: 491743 - Order nr: 8615902**

Ⓜ	🔧	VO-2373300	Sleeve, unit injector, replace. Unit inj	0.4
Ⓜ	🔧	VO-3520000	Lighting, front. Secondary operation num	0.5

PC	Type	Code	Description (Original)	#
Ⓟ	Ⓢ	VO-2630600	Thermostat fan, replace	2.1
Ⓟ	Ⓢ	VO-21351717	INJECTOR SLEEVE	6
Ⓟ	Ⓢ	VO-20736230	SEALING STRIP	1
Ⓟ	Ⓢ	VO-85000818	THERMOSTAT FAN, EX	1
Ⓟ	Ⓢ	VO-3979639	GASKET	2
Ⓟ	Ⓢ	VO-1677370	SEALING RING	2
Ⓟ	Ⓢ	VO-20526428	SEALING RING	1
Ⓟ	Ⓢ	VO-983472	CABLE TIE	8
Ⓟ	Ⓢ	AU2-9770-2018	LECTRA CLEAN - TCE	1
Ⓟ	Ⓢ	VO-20723207	SEALING RING	1
Ⓟ	Ⓢ	VO-20852765	GASKET	4
Ⓟ	Ⓢ	VO-990037	BULB	1
Ⓟ	Ⓢ	VO-2373100	Sleeve, unit injector, replace (Others e	0.4
Ⓟ	Ⓢ	VO-2378000	Unit injector, remove. All	2.5
Ⓟ	Ⓢ	VO-2378100	Unit injector, install. All	6
	Ⓢ		COMPLAINT: HARD STARTING AND ENGINE MISSFIRE.	
	Ⓢ		CHECKED ALL LIGHTS. REPLACED BLOWN HEADLIGHT GLOBE.	
	Ⓢ		RECHECKED.	
	Ⓢ		COMPLAINT: ENGINE FAN NOT LOCKING IN.	
	Ⓢ		CAUSE: WIRING OPEN CIRCUIT IN FAN.	
	Ⓢ		CORRECTION: FITTED A NEW ENGINE FAN. CHECKED OPERATION.	
	Ⓢ		CAUSE: INJECTOR TUBES PASSING COMPRESSION.	
	Ⓢ		CORRECTION: REPLACED ALL INJECTOR TUBES.	
Ⓟ	*	97	ENVIRONMENTAL CHARGE	
Ⓟ	*	91	WORKSHOP CONSUMABLES	
<b>2016-11-21 - Mileage: 488832 - Order nr: 8615858</b>				
Ⓟ	Ⓢ	VO-5610000	Compressor, regulator, anti-freeze unit.	2.75
Ⓟ	*	2140000	ENGINE HARD TO START SUSPECT INJECTOR TU	
Ⓟ	Ⓢ	MK-FTM62X8	JOINER, 8MM TUBE	1
Ⓟ	Ⓢ	VO-991971	NIPPLE	1
Ⓟ	Ⓢ	VO-980832	PLASTIC PIPE,8MM	0.5
Ⓟ	Ⓢ	VO-22144200	AIR SPRING	2
Ⓟ	Ⓢ	VO-20734773	ADAPTER	1
Ⓟ	Ⓢ	VO-948211	STRIP CLAMP	2
Ⓟ	Ⓢ	VO-980464	STRIP CLAMP	1
Ⓟ	Ⓢ	LO-1940000	ATTEND TO BREAKDOWN MINGELA.	5.5
	Ⓢ		DIAGNOSE STARTING ISSUE TO INJECTOR TUBES CAUSING FUEL	
	Ⓢ		RUNBACK. TO BE REPAIRED AT NEXT VISIT.	



PC	Type	Code	Description (Original)	#
	☒		ATTEND TO BREAKDOWN ON MINGELA RANGE.	
	☒		LOAD TOOLS AND PARTS AND TRAVEL TO BREAKDOWN SITE.	
	☒		INSPECTED FOR REPORTED FAILURE CAUSING BRAKES TO COME ON.	
	☒		TRACED FAULT TO NUMBER 3 TRAILER LEAKING BRAKE BOOSTER.	
	☒		CARRIED OUT TEMPORARY REPAIRS BY BLOCKING OFF AIR SUPPLY	
	☒		FROM PARK BRAKE CIRCUIT. WOUND OFF BRAKE BOOSTER ADJUSTER.	
	☒		DRIVER IS AWARE AND IS GETTING REPAIRED IN CHARTERS TOWERS.	
	☒		RETURNED TO VCV TOWNSVILLE WORKSHOP.	
Ⓡ	*	92	UTE MILEAGE 105 km's @ 1.20/km.	
	☒		ATTEND TO AIR SYSTEM FAULTS.	
	☒		AIR LEAKING FROM PIPE RUBBING ON GEARBOX OIL COOLER.	
	☒		REMOVED LEAKING PIPE AND USED JOINERS AND NEW PIPE AND	
	☒		FITTING TO TANK.	
	☒		FOUND ANOTHER LEAK FROM REAR LEFT CABIN AIR BAG. REPLACED.	
	☒		CARRIED OUT REGENERATION RESET VOLUME AND CHECKED BUILD UP,	
	☒		AROUND AIR DRYER CONSUMPTION AT 90%.	
	☒		ALSO FOUND ENGINE FAN FAULTS LOGED. BROKEN WIRING HARNESS.	
Ⓡ	*	97	ENVIRONMENTAL CHARGE	
Ⓡ	*	91	WORKSHOP CONSUMABLES	
<b>2016-10-25 - Mileage: 473635 - Order nr: 8615590</b>				
Ⓡ	*	8700000	AIR CONDITIONER NOT COOLING.	
Ⓡ	*	80	ATTEND TO AIR CONDITIONER NOT COOLING.	
Ⓡ	☒	VO-21086300	CONDENSER	1
Ⓡ	☒	VO-20490947	RECEIVER DRIER	1
Ⓡ	☒	VO-20443754	O-RING	2
Ⓡ	☒	VO-20443759	O-RING	2
	☒		INSPECT TRUCK FOR A/C FOR NOT COOLING.	
	☒		FOUND CONDENSOR LEAKING AND DRIER UNSERVICEABLE.	
	☒		REMOVE AND REPLACE CONDENSOR AND DRIER, VAC AND GAS AS	
	☒		REQUIRED. INSPECT FOR LEAKS FOUND TO BE ALL OK	
<b>2016-10-11 - Mileage: 468667 - Order nr: 8615531</b>				
Ⓡ	Ⓡ	VO-4810800	Power take off (pto), replace	3.3
Ⓡ	☒	VO-85123253	CONVERSION KIT	1
	☒		REMOVED AND REFIT DASH PANELS TO CHECK INSTALLATION	
	☒		OF PTO SWITCHES AND WIRING.	
	☒		REMOVED AND REFITTED WALKPLATE TO CHECK CORRECT	
	☒		INSTALLATION OF PTO.	
	☒		CARRIED OUT PROGRAMMING.	

PC	Type	Code	Description (Original)	#
	☒		CARRIED OUT GEARBOX CALIBRATION.	
	☒		CARRIED OUT PARAMETER PROGRAMMING.	
	☒		CHECKED PTO OPERATION.	
ⓑ	*	1700000	FAULT CODES FOUND DURING COMPUTER CONNEC	
	☒		MID 128, PPID 386, FMI 0. ( 255 COUNTS )	
	☒		EXHAUST PRESSURE ABOVE NORMAL LIMITS.	
	☒		MID 128, SID 33, FMI 5 ( ACTIVE 1 )	
	☒		FAN CLUTCH OUTPUT OPEN CIRCUIT.	
	☒		MID 128, PSID 98, FMI 1 ( 71 COUNTS )	
	☒		BOOST PRESSURE TOO LOW.	
	☒		MID 223, PSID 36, FMI 12 ( 1 ) ( OUTPUT ACTUATOR )	
	☒		GEAR SELECTOR ECU FAULTY DEVICE.	
	☒		MID 223, PSID 212, FMI 2 ( 17 COUNTS )	
	☒		GEAR SELECTOR ECU IGNITION SIGNAL DATA ERATIC.	
	☒		MID 144, PID 84, FMI 2 ( 8 COUNTS )	
	☒		ROAD SPEED SENSOR.	
	☒		MID 128, PID 131, FMI 2 ( 4 COUNTS )	
	☒		EXHAUST BACK PRESSURE SENSR DATA ERATIC.	
ⓑ	*	91	WORKSHOP CONSUMABLES	

**2016-09-05 - Mileage: 449034 - Order nr: 8615240**

ⓑ	ⓐ	VO-3317000	Starter motor, remove	5
ⓑ	ⓐ	VO-85020793	STARTER MOTOR, EXC	1
	☒		ATTEND TO VEHICLE NOT STARTING AT TOWNSVILLE PORT	
	☒		STARTER SYSTEM FAULT / 7079	
ⓑ	*	91	WORKSHOP CONSUMABLES	
	☒		SHELL DEPOT.	
	☒		INSPECT VEHICLE CONNECT COMPUTER AND CHECKED FOR ERROR CODES	
	☒		CARRIED OUT VEHILCE INFORMATION TEST.	
	☒		FILLED AIR TANKS.	
	☒		CHECKED RELAYS, BATTERIES VOLTAGE, CARRIED OUT GEARS TEST,	
	☒		CLUTCH CYLINDER TEST, PWM VALVE TEST AND GEAR SELECTOR	
	☒		SIGNAL TEST, FOUND ALL TO BE OK.	
	☒		TRIED TO START VEHICLE FOUND VERY SLUGGISH BUT STARTED.	
	☒		NEUTRAL.	
	☒		TILTED CAB AND CHECKED POWER SUPPLY TO STARTER MOTOR	
	☒		FOUND THE STARTER MOTOR TO BE UNSERVICEABLE.	
	☒		SHUT DOWN, SOURCE REPLACEMENT STARTER MOTOR.	



PC	Type	Code	Description (Original)	#
	🔧		DISCONNECT BATTERIES AND REMOVE EXHAUST FLEXI PIPE,	
	🔧		DISCONNECT WIRES TO STARTER REMOVED AND REFITTED WITH	
	🔧		REPLACEMENT, RECONNECT ALL WIRES AND FLEXI, STARTED TRUCK	
	🔧		ON OFF A NUMBER OF TIMES STARTING ALL OK.	
	🔧		CLEARED ALL INACTIVE CODES TEST OK.	
	🔧		RETURN TO WORKSHOP.	
<b>2016-07-19 - Mileage: 416533 - Order nr: 8614909</b>				
🔧	🔧	VO-2580000	Emissions after-treatment. Secondary ope	5.5
	🔧		CURRENT ENGINE HOURS 6546.5 HOURS.	
🔧	🔧	VO-85020841	PUMP UNIT, EXCH	1
🔧	🔧	VO-20998072	GASKET	1
🔧	🔧	VO-85113349	ADBLUE 1000 LTR IBC	22
🔧	🔧	AU2-CUMCC36059	AD BLUE 20ltr Drum	1
🔧	🔧	VO-21492717	SENSOR	1
	🔧		COMPLAINT: NOT USING AD BLUE - ENGINE FAULT DE-RATING	
🔧	🔧	VO-2584600	SCR system, test	0.5
🔧	🔧	VO-1710500	Road test	0.3
🔧	🔧	VO-1701000	Connect-disconnect of diagnostic tool	0.2
🔧	🔧	VO-2583100	AdBlue system, draining	0.5
🔧	🔧	VO-2585500	AdBlue dosing module, calibration	0.4
🔧	🔧	VO-2586300	AdBlue tank, clean	0.2
	🔧		252610.7 LITRES FUEL BURN.	
	🔧		CAUSE:AD BLUE PUMP FAILURE BLOCKAGE AND CONTAMINATION.	
	🔧		CORRECTION: CONNECT PC AND READ CODES AD BLUE MECHANICAL	
	🔧		FAULT MID 128 PPID 273 FMI7	
	🔧		CARRIED OUT SCR SYSTEM TEST	
	🔧		NO PRESSURE IN PUMP, CHECKED ALL HOSES AND TANK FOR LEAKS	
	🔧		CHECKED PICKUP REMOVED PICK UP FROM TANK TO MAKE SURE NO	
	🔧		BLOCKAGES. RESEALED PICKUP MOUNTING PLATE AS IT HAD BEEN	
	🔧		LEAKING. CLEANED AD BLUE LINES AND CHECKED FOR BLOCKAGES	
	🔧		CHECKED CORRECT FITTING OF HOSES ALL OK. REPLACED AD BLUE	
	🔧		PUMP.	
	🔧		ADBLUE IN TANK FAILED REFLECTOMETER TEST. CONTAMINATED.	
	🔧		APPEARS TO BE VERY WEAK MIXTURE.	
	🔧		DRAINED TANK AND REFILLED WITH NEW ADBLUE. FITTED A NEW	
	🔧		AD-BLUE TANK LEVEL SENSOR DUE TO BEING BLOCKED.	
	🔧		PROGRAMMED NEW ADBLUE CONTROL MODULE CLEARED ALL FAULTS	
	🔧		CARRIED OUT SCR SYSTEM TEST ROAD TESTED ALL OK	

PC	Type	Code	Description (Original)	#
	☒		OLD PUMP SERIAL NUMBER 00465	
	☒		NEW PUMP SERIAL NUMBER 00059	
Ⓡ	*	91	WORKSHOP CONSUMABLES	
<b>2016-07-11 - Mileage: 410131 - Order nr: 8614832</b>				
Ⓡ	Ⓢ	VO-1774600	Annual service. Chassis lubrication and	6
Ⓡ	Ⓢ	VO-1706600	24 Months ECU download and oil sample. O	0.9
Ⓡ	Ⓢ	VO-8100500	24 Months cab inspection	0.5
Ⓡ	Ⓢ	VO-1707300	Service alert system, configuration and	0.4
Ⓡ	Ⓢ	VO-2331100	Filter, water separator, replace	0.5
Ⓡ	Ⓢ	VO-2330600	Fuel filter, replace (one)	0.4
Ⓡ	Ⓢ	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
Ⓡ	Ⓢ	VO-2562500	Secondary air filter, replace. Air filte	0.2
Ⓡ	Ⓢ	VO-2562400	Filter insert, air cleaner, replace. Onl	0.5
Ⓡ	Ⓢ	VO-2582200	Filter, AdBlue, replace	0.3
Ⓡ	Ⓢ	VO-2141300	Valves and unit injectors, adjust	1.8
Ⓡ	Ⓢ	VO-2373200	Yoke, injector, check. Valve cover remov	0.4
Ⓡ	Ⓢ	VO-5616600	Air drier cassette, replace	0.3
Ⓡ	Ⓢ	VO-5618500	Air drier setting reset, calibration	0.2
Ⓡ	Ⓢ	VO-2341400	Filter for fuel tank ventilation, replac	0.1
Ⓡ	Ⓢ	VO-1752300	Gearbox oil and filter, replace. Lube ar	0.5
Ⓡ	Ⓢ	VO-1752700	Final drive oil, change. Lube area	0.5
Ⓡ	Ⓢ	VO-1770000	Maintenance service trucks basic service	1.5
Ⓡ	Ⓢ	VO-1701000	Connect-disconnect of diagnostic tool	0.2
Ⓡ	Ⓢ	VO-2520000	Silencer and exhaust pipe. Secondary ope	2.5
Ⓡ	Ⓢ	VO-3110000	Battery, energy storage system. Secondar	1.2
	☒		CURRENT HOURS OF UNIT 6440.1 HOURS.	
Ⓡ	Ⓡ	VO-8394887	OIL TEST KIT	4
Ⓡ	Ⓡ	VO-FK18B	FILTER KIT	1
Ⓡ	Ⓡ	AU2-CAL85121795	VDS4 BULK ENGINE O	42
Ⓡ	Ⓡ	VO-20411816	AIR FILTER	1
Ⓡ	Ⓡ	VO-21716424	AIR FILTER	1
Ⓡ	Ⓡ	VO-21620181	KIT	1
Ⓡ	Ⓡ	VO-3944785	AIR FILTER - COMP.	1
Ⓡ	Ⓡ	VO-20779040	SERVICE KIT, OIL F	1
Ⓡ	Ⓡ	AU2-CAL85121714	VOLVO BULK SAE50 TRANS	17
Ⓡ	Ⓡ	AU2-CAL85121715	VOLVO 85W140 GEAR	34
Ⓡ	Ⓡ	AU2-CUMFS1251	F/W/SEP (REPS FS12	1
Ⓡ	Ⓡ	OTH-YAN-114210-1	YANMAR AIR FILTER ELEMENT	1



PC	Type	Code	Description (Original)	#
Ⓡ	Ⓜ	VO-21927064	EXHAUST PIPE	1
Ⓡ	Ⓜ	VO-20736230	SEALING STRIP	1
Ⓡ	Ⓜ	MK-9727-3380340	RX MONO 20L	0.1
Ⓡ	Ⓜ	VO-990413	HEX. SOCKET SCREW	1
	Ⓜ		CARRIED OUT MAJOR ANNUAL SERVICE AS PER SCHEDULE.	
	Ⓜ		ELECTRONIC CONTROL UNIT DOWNLOAD, OIL SAMPLES AND CABIN	
	Ⓜ		INSPECTION. RESET SERVICE ALERT REMINDER 20,000 KILOMETRES.	
	Ⓜ		CHANGED ENGINE OIL AND FILTERS, FUEL AND WATER SEPERATOR	
	Ⓜ		FILTERS,	
	Ⓜ		CHANGED GEARBOX OIL AND FILTER, DIFFERENTIAL OILS.	
	Ⓜ		CARRIED OUT VALVE AND UNIT INJECTOR ADJUSTMENTS, CHECKED AND	
	Ⓜ		TENSIONED YOKE BOLTS.	
	Ⓜ		CHANGED AIR DRYER FILTER, CLEANED AND CHECKED DRYER.	
	Ⓜ		RESET CALIBRATION.	
	Ⓜ		CHANGED OUTER AND INNER AIR FILTERS, CLEANED AND CHECKED	
	Ⓜ		FILTER HOUSING.	
Ⓡ	*	97	ENVIRONMENTAL CHARGE	
	Ⓜ		CARRIED OUT INCPACK SERVICE.	
	Ⓜ		CHECKED EXHAUST PIPE AND FOUND CRACKED. HAS BEEN REPAIRED	
	Ⓜ		SEVERAL TIMES BEFORE. FITTED AND SECURED A NEW PIPE.	
	Ⓜ		FAULT CAUSED BY AD-BLUE LEAKING FROM CRACKED EXHAUST PIPE.	
	Ⓜ		FOUND SLUGGISH STARTING. CHECKED AND TESTED BATTERIES AND	
	Ⓜ		FOUND LOW VOLTAGE. PUT ON CHARGE OVERNIGHT. RETESTED IN	
	Ⓜ		THE MORNING AND FOUND FAILED TEST. FITTED TWO NEW BATTERIES	
	Ⓜ		SUPPLIED BY CENTUARY BATTERIES UNDER THEIR WARRANTY.	
	Ⓜ		CHECKED STARTING AND ALTERNATOR OUTPUTS.	
Ⓡ	*	91	WORKSHOP CONSUMABLES	
<b>W 2016-04-12 - Mileage: 355790 - Order nr: 8614240</b>				
Ⓡ	Ⓜ	VO-8180000	Cab mounting	0.7
Ⓡ	Ⓜ	VO-22144200	AIR SPRING	2
	Ⓜ		COMPLAINT: AIR LEAK AT REAR OF CAB.	
	Ⓜ		VO/22144200 WAS FITTED BY BRANCH 4800	
	Ⓜ		.- ON REPAIR ORDER 8612965 - DATE 2015-10-07 MILEAGE - 0	
	Ⓜ		CURRENT ENGINE HOURS 5564,	
	Ⓜ		CAUSE: LHS SIDE REAR CAB AIR BAG LEAKING(MATERIAL FAILURE).	
	Ⓜ		CORRECTION: REMOVED BOTH REAR CAB AIR BAGS AND REPLACED BOTH	
	Ⓜ		RHS & LHS AIR BAGS. BOTH REAR CAB AIR BAGS WERE CHANGED ON R	

PC	Type	Code	Description (Original)	#
	📄		EPAIR ORDER 8612965 ON THE 28/9/2015.	
🔍	📄	<b>2015-11-16 - Mileage: 286221 - Order nr: 8613267</b>		
🔍	🔧	VO-3831000	Sensor, speedometer, replace	0.6
🔍	🔧	VO-1706500	18 Months ECU download and oil sample. O	0.9
🔍	🔧	VO-1774400	Basic service. Chassis lubrication and o	1
🔍	🔧	VO-1707300	Service alert system, configuration and	0.4
	📄		CURRENT HOURS OF UNIT 4467.8 HOURS.	
🔍	🔧	VO-2331100	Filter, water separator, replace	0.4
🔍	🔧	VO-2330600	Fuel filter, replace (one)	0.4
🔍	🔧	VO-1750400	Lubrication according to actual lubricat	0.2
🔍	🔧	VO-1751500	Oil and filter, engine, change	0.5
🔍	🔧	VO-8394887	OIL TEST KIT	4
🔍	🔧	VO-FK18B	FILTER KIT	1
🔍	🔧	AU2-CAL85121795	VDS4 BULK ENGINE O	42
🔍	🔧	AU2-CAL85121792	B/DOG HP GREASE NL	1
🔍	🔧	VO-22387296	VEHICLE SPEED SENS	1
🔍	🔧	VO-21758906	FILTER	1
🔍	🔧	VO-21620181	KIT	1
🔍	🔧	VO-944126	O-RING	1
🔍	🔧	VO-983472	CABLE TIE	7
🔍	🔧	VO-2800000	Ignition and control system, general. Se	2
🔍	🔧	VO-5612600	Air drier, drier insert, replace	0.5
🔍	🔧	VO-21168663	SHOCK ABSORBER	1
	📄		VO/21168663 WAS FITTED BY BRANCH 4800	
	📄		.- ON REPAIR ORDER 8611203 - DATE 2015-03-06 MILEAGE - 166990	
🔍	🔧	VO-8500000	Interior furnishings, general	0.3
🔍	🔧	VO-3600000	Other electrical equipment, general. Sec	0.8
🔍	🔧	VO-8700000	Air conditioning unit, general	0.2
🔍	🔧	VO-8100000	Body and cab framework, general	0.3
🔍	🔧	3500000	CHECK ALL LIGHTS	
	📄		TOP ROOF AMBER LIGHTS	
🔍	🔧	30	CHECK AND REPAIR SPOT LIGHTS.	
🔍	🔧	VO-992520	BULB	2
	📄		CHECK FOR SPEEDO SENSOR FAULT.	
	📄		COMPLAINT: CARRY OUT 18 MONTH ECU DOWNLOAD AND SAMPLES	
	📄		CARRY OUT BASIC SERVICE AS PER CHECKLIST.	
	📄		REMOVED AND REPLACE ENGINE OIL AND FILTERS, OIL SAMPLES	
	📄		COMPLAINT: OIL LEAKING FROM CYLINDER HEAD.	



PC	Type	Code	Description (Original)	#
	🔧		ATTEND TO DRIVER SEAT BASE LOOSE, INSPECT SEAT FOUND SMALL	
	🔧		ATTEND TO NOISE FROM WINDSCREEN WIPERS.	
	🔧		REMOVE AND REPLACE LHS REAR CAB SHOCKY	
	🔧		FOUND 2 ORANGE CLEARANCE LIGHT BULBS OUT REMOVE AND REPLACE	
	🔧		AS REQUIRED TEST OK	
W	*	3830000	SPEEDO DROPS OUT.	
	🔧		COMPLAINT: SPEEDO DROPPING OUT.	
	🔧		CURRENT HOURS OF UNIT 4467.8 HOURS.	
	🔧		CHECKED FAULT CODES, MID 128 , PSID 84 , FMI 9	
	🔧		TESTED WIRING FOR SPEED SENSOR, NO FAULTS FOUND	
	🔧		REMOVE AND REPLACE SPEEDO SENSOR, TEST OK	
	🔧		RESET SERVICE ALERT REMINDER 20,000 KILOMETRES.	
	🔧		CHANGED FUEL WATER SEPERATOR FILTER.	
	🔧		CHANGED FUEL FILTER.	
	🔧		LUBRICATION.	
	🔧		CHANGED ENGINE OIL AND FILTERS.	
Ⓜ	*	97	ENVIRONMENTAL CHARGE	
	🔧		CHANGED AIR DRYER FILTER AND CLEANED AND CHECKED DRYER.	
	🔧		CRACK IN LOCK IN BEND, TEMPORARY FIX AND RE-INSTALL SEAT	
	🔧		BASE, REQUIRES NEW SEAT BASE AND CLIPS	
	🔧		INSPECT NOISE FROM WINDSCREEN WIPERS - WINDSCREEN PANEL	
	🔧		CRACKED - CUT AWAY BROKEN PART THAT IS RUBBING AGAINST	
	🔧		THE WIPER ARM - WINDSCREEN WIPER COVER NEEDS TO BE REPLACED.	
	🔧		REPLACED CABIN AIR INTAKE FILTER AND CLEANED HOUSING.	
	🔧		CAUSE: OPERATION DUE	
	🔧		CORRECTION: CARRIED OUT 18 MONTH ECU DOWNLOAD AND SAMPLES AS	
	🔧		REQUIRED	
	🔧		CAUSE: INTERNAL CONTACT FAULT IN SPEED SENSOR.	
	🔧		CORRECTION:CHECK FOR SPEEDO SENSOR FAULT.	
	🔧		CHECKED FAULT CODES, MID 128 , PSID 84 , FMI 9	
	🔧		TESTED WIRING FOR SPEED SENSOR, NO FAULTS FOUND	
	🔧		REMOVE AND REPLACE SPEEDO SENSOR, TEST OK	
	🔧		CUSTOMER CONCERN AUTHORISATION 200401026 PART ONLY.	
	🔧		CAUSE: INJECTOR HARNESS O RING PERISHED AND PASSING OIL.	
	🔧		CORRECTION:REMOVE AND REPLACE INJECTOR HARNESS O'RING	
	🔧		LEAKING	
	🔧		SUSTOMER CONCERN AUTHORISATION 200401027.	

PC	Type	Code	Description (Original)	#
	📄		INVOICE 13698	
🔧	*	91	WORKSHOP CONSUMABLES	
🔍 <b>W 2015-10-06 - Mileage: 268736 - Order nr: 8612996</b>				
🔧	🔧	VO-3213000	Belt tensioner, alternator, replace	0.6
🔧	🔧	VO-85003229	RADIATOR, EXCH	1
🔧	🔧	VO-85000818	THERMOSTAT FAN, EX	1
🔧	🔧	VO-21454379	BELT TENSIONER	1
🔧	🔧	VO-21631484	BELT TENSIONER	1
🔧	🔧	VO-21753149	IDLER PULLEY	1
🔧	🔧	VO-20466767	FAN SHROUD	1
🔧	🔧	VO-21133804	V-RIBBED BELT	1
🔧	🔧	VO-21190817	V-RIBBED BELT	1
🔧	🔧	VO-20585893	VIBRATION DAMPER	1
🔧	🔧	VO-984815	FLANGE SCREW	6
🔧	🔧	AU2-CAL8394800	VOLVO VCS COOLANT	2
🔧	🔧	LO-1940000	RECOVER FROM MINGELA RANGE	2.5
🔧	*	20	RECOVER TRUCK FROM MINGELA	
🔧	🔧	VO-990862	FLANGE SCREW	2
🔧	🔧	VO-CALLOUT	CALLOUT VO	100
	📄		INVOICE 00106241	
🔧	🔧	VO-2630600	Thermostat fan, replace	2.1
🔧	🔧	VO-2631300	Fan belt tensioner, replace	0.6
🔧	🔧	VO-2630000	Fan, fan shroud and clutch. Secondary op	0.6
🔧	🔧	VO-2169100	Vibration dampener, replace	2.9
🔧	🔧	VO-2610800	Radiator, replace	2.3
🔧	🔧	VO-1701000	Connect-disconnect of diagnostic tool	0.2
🔧	🔧	VO-1701200	Fault codes, reading	0.2
	📄		CURRENT HOURS OF UNIT 4192.1 HOURS.	
	📄		CURRENT HOURS OF INIT 4192.1 HOURS.	
	📄		VOLVO ACTION SERVICE CASE 2015201400.	
	📄		VOLVO ACTION SERVICE CASE 2015201400.	
🔧	*	92	VAN MILEAGE 194 km's Ö Å0.98/km.	
	📄		COMPLAINT: LOUD BANG AND LOST COOLANT AND CHARGE LIGHT ON.	
	📄		CAUSE: ALTERNATOR BELT TENSIONER FAILED AND TOOK OUT FAN,	
	📄		RADIATOR, SHROUD AND CRANK PULLEY.	
	📄		CORRECTION:LOADED TOOLS AND PARTS AND TRAVELLED TO	
	📄		BREAKDOWN SITE. FOUND DAMAGE EXTENSIVE AND NOT ABLE	
	📄		TO CARRY OUT REPAIRS ROAD SIDE. TRAVELLED 194 KILOMETRES	



PC	Type	Code	Description (Original)	#
	📄		ROUND TRIP.STARTED MONDAY 5/10/2015 11.00 RETURNED 14.00.	
	📄		ARRANGE RECOVERY OF VEHICLE FROM MINGELA RANGE	
	📄		TO VCV TOWNSVILLE WORKSHOP.	
	📄		TOWNSVILLE TOWING INVOICE 00106241 Å1000.00 EXCLUDING GST.	
	📄		COMPLAINT: LOUD BANG AND LOST COOLANT AND CHARGE LIGHT ON.	
	📄		CAUSE: ALTERNATOR BELT TENSIONER FAILED AND TOOK OUT FAN,	
	📄		RADIATOR, SHROUD AND CRANK PULLEY.	
	📄		CORRECTION: TILTED CABIN AND INSPECTED FAILURE AND DAMAGE.	
	📄		ALTERNATOR BELT TENSIONER FAILED AND CAUSED EXTENSIVE	
	📄		DAMAGE AND FAILURE. FITTED A NEW RADIATOR, FAN AND SHROUD,	
	📄		ALTERNATOR AND FAN BELT TENSIONERS AND IDLER. FITTED NEW	
	📄		CRANKSHAFT DAMPER. FITTED NEW BELTS. REFILLED BLEED AND	
	📄		TOPPED UP COOLANT. CONNECTED VCADS COMPUTOR AND READ	
	📄		AND CLEARED FAULT CODE MID 128, SID33, FMI 5.	
	📄		CLEANED DOEN ENGINE BAY. ROAD TEST AND RECHECK.	

🔍 **2015-09-28 - Mileage: 0 - Order nr: 8612965**

🔍	📄	VO-8182700	Cab shock absorber air rear, replace (tw	1.5
🔍	📄	VO-22144200	AIR SPRING	2
	📄		CHECKED FOR AIR LEAKING AT CABIN AIR SPRINGS.	
	📄		FITTED NEW LEFT AND RIGHT REAR CABIN AIR SPRINGS.	
	📄		RECHECKED FOR LEAKS.	
🔍	*	97	ENVIRONMENTAL CHARGE	
🔍	*	91	WORKSHOP CONSUMABLES	

🔍 **2015-09-03 - Mileage: 250551 - Order nr: 8612799**

🔍	*	7210000	CHECK STEER AXLE SPRINGS AND SHOCKS.	
	📄		BOTTOMING AND BOUNCING.	
🔍	📄	VO-1774400	Basic service. Chassis lubrication and o	2.7
🔍	📄	VO-1707300	Service alert system, configuration and	0.4
🔍	📄	VO-2331100	Filter, water separator, replace	0.4
🔍	📄	VO-2330600	Fuel filter, replace (one)	0.4
🔍	📄	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
🔍	📄	VO-1750400	Lubrication according to actual lubricat	0.2
🔍	📄	VO-2562400	Filter insert, air cleaner, replace. Onl	0.5
🔍	📄	VO-2562500	Secondary air filter, replace. Air filte	0.2
🔍	📄	VO-20411816	AIR FILTER	1
🔍	📄	VO-21716424	AIR FILTER	1
🔍	📄	VO-2341400	Filter for fuel tank ventilation, replac	0.2
🔍	📄	VO-3944785	AIR FILTER - COMP.	2

PC	Type	Code	Description (Original)	#
Ⓡ	Ⓢ	VO-2582200	Filter, AdBlue, replace	0.5
Ⓡ	Ⓡ	VO-21333097	FILTER KIT ADBLUE	1
Ⓡ	Ⓡ	VO-FK18B	FILTER KIT	1
Ⓡ	Ⓡ	AU2-CAL85121795	VDS4 BULK ENGINE O	42
Ⓡ	Ⓢ	VO-8720800	Air conditioning air filter, replace	0.4
Ⓡ	Ⓡ	VO-21758906	FILTER	1
	Ⓢ		CURRENT VOURS OF UNIT 3906.1 HOURS.	
Ⓡ	Ⓡ	VO-85135344	HOSE CLAMP	1
	Ⓢ		CARRIED OUT BASIC SERVICE AS PER SCHEDULE.	
	Ⓢ		RESET SERVICE ALERT REMINDER 20,000 KILOMETRES.	
	Ⓢ		CHANGED FUEL WATER SEPERATOR FILTER.	
	Ⓢ		CHANGED FUEL FILTER.	
	Ⓢ		CHANGED ENGINE OIL AND FILTERS.	
Ⓡ	*	97	ENVIRONMENTAL CHARGE	
	Ⓢ		LUBRICATION AS PER SCHEDULE.	
	Ⓢ		REMOVED OUTER AND INNER AIR FILTERS. CLEANED HOUSING AND	
	Ⓢ		FIT NEW INNER AND OUTER AIR FILTERS.	
	Ⓢ		CHANGED TANK VENTILATION FILTERS.	
	Ⓢ		CHANGED AD-BLUE PUMP FILTER.	
	Ⓢ		CHANGED CABIN AIR INTAKE FILTER AND CLEANED HOUSING.	
	Ⓢ		CHECKED STEER AXLE AND SPRINGS. COULD NOT FAULT OPERATION.	
	Ⓢ		DID FIND CABIN SHOCK ABSORBER SPRINGS NEEDED ADJUSTING.	
	Ⓢ		ADJUSTED AND CHECKED.	
Ⓡ	*	91	WORKSHOP CONSUMABLES	
<b>2015-07-28 - Mileage: 228902 - Order nr: 8612559</b>				
Ⓡ	Ⓢ	VO-1774400	Basic service, Chassis lubrication and o	2.7
Ⓡ	Ⓢ	VO-1707300	Service alert system, configuration and	0.4
Ⓡ	Ⓢ	VO-2331100	Filter, water separator, replace	0.4
Ⓡ	Ⓢ	VO-2330600	Fuel filter, replace (one)	0.4
Ⓡ	Ⓢ	VO-1750400	Lubrication according to actual lubricat	0.2
Ⓡ	Ⓢ	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
Ⓡ	Ⓢ	VO-3520000	Lighting, front. Secondary operation num	0.3
	Ⓢ		CURRENT HOURS OF UNIT 3562.2 HOURS.	
Ⓡ	Ⓡ	VO-FK18B	FILTER KIT	1
Ⓡ	Ⓡ	AU2-CAL85121795	VDS4 BULK ENGINE O	42
Ⓡ	Ⓡ	VO-982558	BULB	1
Ⓡ	Ⓡ	VO-990950	FLANGE LOCK NUT	1
Ⓡ	Ⓡ	VO-984738	FLANGE SCREW	2



PC	Type	Code	Description (Original)	#
Ⓡ	Ⓢ	VO-8260000	Rear mudguard	0.5
	Ⓢ		CARRIED OUT BASIC SERVICE AS PER SCHEDULE.	
	Ⓢ		RESET SERVICE ALERT REMINDER 20,000 KILOMETRES.	
	Ⓢ		CHANGED FUEL WATER SEPERATOR FILTER.	
	Ⓢ		CHANGED FUEL FILTER.	
	Ⓢ		CARRIED OUT LUBRICATION.	
	Ⓢ		CHANGED ENGINE OIL AND FILTERS.	
Ⓡ	*	97	ENVIRONMENTAL CHARGE	
	Ⓢ		CHECKED ALL LIGHTS, REPLACED BLOWN INDICATOR GLOBE.	
	Ⓢ		FITTED NUT AND BOLT AND SECURED MUDGUARD LOOP.	
Ⓡ	*	8700000	ICEPACK FAULT ON 743VBI	
Ⓡ	*	80	ATTEND TO ICEPACK FAULT.	
	Ⓢ		INVOICE 12438	
	Ⓢ		JOB CARRIED OUT ON 743VBI	
	Ⓢ		ICEPACK KEEPS SHUTTING DOWN. ALTERNATOR NOT CHARGING.	
	Ⓢ		FITTED A NEW ALTERNATOR AND TESTED.	
Ⓡ	*	91	WORKSHOP CONSUMABLES	
🔍 <b>W 2015-07-08 - Mileage: 216028 - Order nr: 8612373</b>				
Ⓡ	Ⓢ	VO-2520000	Silencer and exhaust pipe. Secondary ope	3
Ⓡ	*	3520000	REPAIR SPOT LIGHT.	
Ⓢ	Ⓢ	VO-1701000	Connect-disconnect of diagnostic tool	0.2
	Ⓢ		CURRENT HOURS OF UNIT 3348.8 HOURS.	
Ⓢ	Ⓢ	VO-21582423	KIT	1
Ⓢ	Ⓢ	VO-85139619	PRESSURE SENSOR	1
Ⓡ	Ⓢ	VO-955892	WASHER	2
Ⓡ	Ⓢ	OTH-76581	BOLT,1/4UNFX2	1
Ⓢ	Ⓢ	VO-2850800	Exhaust back pressure sensor, replace	0.2
Ⓢ	Ⓢ	VO-2840700	Sensor values, check	0.2
Ⓢ	Ⓢ	VO-1701200	Fault codes, reading	0.2
Ⓢ	Ⓢ	VO-3710200	Electric wires and connections, check	0.4
Ⓢ	Ⓢ	VO-3711700	Connector, replace (1-8 cables)	0.3
	Ⓢ		CHECKED FOR AD-BLUE LEAKING FROM EXHAUST PIPE. FOUND PIPE	
	Ⓢ		CRACKED. REMOVED SHIELDING AND REMOVED PIPE. REMOVED	
	Ⓢ		DOSAGE VALVE AND TEMPERATURE SENSOR. WELD PIPE AND	
	Ⓢ		CLEANED AREA. REFIT VALVE AND SENSOR. REFIT PIPE AND SHIELD.	
	Ⓢ		RUN ENGINE AND CHECKED PIPE. CLEANED DOWN AREA.	
Ⓡ	*	97	ENVIRONMENTAL CHARGE	
	Ⓢ		LIGHT HAS A BLOWN GLOBE. NONE IN STOCK. ORDERED REPLACEMENT	

PC	Type	Code	Description (Original)	#
	📄		GLOBES.	
	📄		COMPLAINT: ENGIE FAULT ON DISPLAY.	
	📄		CAUSE: MID 128, PID 131, FMI 5 PRESSURE SENSOR FAULT.	
	📄		CORRECTION: CONNECTED VCADS COMPUTOR AND READ FAULT CODES.	
	📄		FOUND FAULT CODE MID 128, PID 131, FMI 5 BACK PRESSURE	
	📄		SENSOR CONTACT FAULT. CHECKED WIRING AND CONNECTIONS.	
	📄		FITTED A NEW SENSOR AND WIRING ADAPTION HARNESS. CLEARED	
	📄		FAULT CODES. ROAD TEST AND RECHECK.	
🔧	*	91	WORKSHOP CONSUMABLES	
🔍 <b>W 2015-06-16 - Mileage: 202376 - Order nr: 8612218</b>				
🔧	🔧	VO-1774400	Basic service. Chassis lubrication and o	2.7
🔧	🔧	VO-1707300	Service alert system, configuration and	0.4
🔧	🔧	VO-2331100	Filter, water separator, replace	0.4
🔧	🔧	VO-2330600	Fuel filter, replace (one)	0.4
🔧	🔧	VO-1750400	Lubrication according to actual lubricat	0.4
🔧	🔧	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
🔧	🔧	VO-7714500	Wheel nuts, check tightening (all)	0.3
🔧	🔧	AU2-CAL85121792	B/DOG HP GREASE NL	1
🔧	🔧	VO-FK18B	FILTER KIT	1
🔧	🔧	AU2-CAL85121795	VDS4 BULK ENGINE O	42
🔧	🔧	VO-3510400	Headlight bulb, replace (one). 1 unit, e	0.4
🔧	🔧	VO-8460100	Rear view mirror glass, replace	0.2
🔧	🔧	VO-21333097	FILTER KIT ADBLUE	1
🔧	🔧	VO-21716424	AIR FILTER	1
🔧	🔧	VO-20411816	AIR FILTER	1
🔧	🔧	VO-990037	BULB	1
🔧	🔧	VO-20545485	DIAPHRAGM	1
🔧	🔧	VO-1752700	Final drive oil, change. Lube area	0.4
🔧	🔧	VO-949329	GASKET	2
🔧	🔧	AU2-CAL85121715	VOLVO 85W140 GEAR	35
🔧	🔧	VO-2562400	Filter insert, air cleaner, replace. Onl	0.5
🔧	🔧	VO-4680100	Diaphragm, differential lock, replace	0.4
🔧	🔧	VO-2582200	Filter, AdBlue, replace	0.5
🔧	🔧	VO-2562500	Secondary air filter, replace. Air filte	0.2
	📄		current hours of unit 3129.0 hours.	
	📄		CURRENT HOURS OF UNIT 3129.0 HOURS.	
	📄		CARRIED OUT BASIC SERVICE AS PER SCHEDULE.	
	📄		RESET SERVICE ALERT REMINDER 20,000 KILOMETRES.	



PC	Type	Code	Description (Original)	#
	🔧		CHANGED FUEL WATER SEPERATOR FILTER.	
	🔧		CHANGED FUEL FILTER.	
	🔧		CARRIED OUT LUBRICATION.	
	🔧		CHANGED ENGINE OIL AND FILTERS.	
🔧	*	97	ENVIRONMENTAL CHARGE	
	🔧		CHECKED AND TENSIONED ALL WHEEL NUTS.	
	🔧		CHECKED LIGHTS AND REPLACED BLOWN HEADLIGHT GLOBE.	
	🔧		CHECKED MIRROR OPERATION AND SECURITY AND COULD NOT FAULT.	
	🔧		CHANGED BOTH DIFFERENTIAL OILS AND PLUG GASKET.	
	🔧		REMOVED OUTER AND INNER AIR FILTERS. CLEANED AND CHECKED	
	🔧		HOUSING AND FIT NEW INNER AND OUTER AIR FILTERS.	
	🔧		REMOVED AD-BLUE PUMP FILTER. CHECKED AND CLEANED PUMP AND	
	🔧		FIT NEW FILTER.	
	🔧		COMPLAINT: AIR LEAKING FROM DIFFERENTIAL.	
	🔧		CAUSE: DIAPHRAM PERISHED AND LEAKING.	
	🔧		CORRECTION: REMOVED COVER CLEANED AND INSPECTED. FITTED A	
	🔧		NEW DIAPHRAM AND REFIT COVER. RECHECK.	
🔧	*	91	WORKSHOP CONSUMABLES	

🔍 **W 2015-03-16 - Mileage: 166990 - Order nr: 8611485**

🔧	*	3921600	Radio, replace	
	🔧		PARTS ONLY WARRANTY CLAIM	
🔧	🔧	VO-85010049	RADIO, EXCH	1
	🔧		COMPLAINT: RADIO WILL NOT PROGRAM	
	🔧		CAUSE: INTERNAL PROGRAMMING FAULT	
	🔧		CORRECTION: OREDER REPLACEMENT RADIO FOR CUSTOMERS VEHICLE	
	🔧		KMS WHEN FITTED : 166990	
	🔧		KMS WHEN FAILED : 166990	
	🔧		NIL KMS TRAVLLED - FAILED FROM NEW	
	🔧		POP INVOICE MINTO 7130035 09.02.2015	

🔍 **W 2015-02-06 - Mileage: 166990 - Order nr: 8611203**

🔧	🔧	VO-2630400	Drive belt, replace	0.7
🔧	🔧	VO-8182700	Cab shock absorber air rear, replace (tw	0.7
🔧	🔧	VO-3500000	Lighting, general. Secondary operation n	1.5
🔧	🔧	VO-7211100	Front spring, replace (right hand side)	3.6
🔧	🔧	VO-3640400	Light switch, replace	0.3
🔧	🔧	VO-3500000	Lighting, general. Secondary operation n	4
🔧	*	8510000	DASH LOOSE IN CENTRE.	
🔧	🔧	VO-8911000	Sun visor complete, replace	0.7

PC	Type	Code	Description (Original)	#
	*	3520000	OUTSIDE SPOT LIGHTS CUT OUT.	
		VO-3921600	Radio, replace	0.2
		VO-21133804	V-RIBBED BELT	1
		VO-257888	FRONT SPRING	1
		VO-82921563	SUN VISOR	1
		VO-965212	FLANGE SCREW	1
		VO-21168663	SHOCK ABSORBER	2
		VO-990949	FLANGE LOCK NUT	1
		VO-955892	WASHER	6
		OTH-14X1.12ZPBRTW	1/4 PANEL WASHER	1
	*	30	SUPPLY AND FIT ONE SPOT LIGHT,	
			INVOICE 10983	
			SUBCONTRACT REPAIR:	
			FIT AND REPLACED MISSING SPOT LIGHT.	
		VO-20374548	SHOCK ABSORBER	1
		VO-82072452	MOULDING	1
		VO-21753354	RADIO	1
		OTH-21033999	switch panel	1
			CURRENT HOURS OF UNIT 2544.2 HOURS.	
		VO-7610200	Front shock absorber, replace (one)	0.5
			(two sides)	
			VO/82921563 WAS FITTED BY BRANCH 4800	
			.- ON REPAIR ORDER 8609183 - DATE 2014-05-30 MILEAGE - 33166	
			COMPLAINT: EXTERIOR SUNVISOR VIBRATING AND RATTELING.	
			COMPLAINT: STEERING SHAKES WHEN HITTING BUMPS.	
			COMPLAINT: KNOCK RIGHT FRONT.	
			COMPLAINT: CAN NOT EJECT CD'S.	
		VO-1705400	Accessory kit, programming	0.3
		VO-3920200	MID 206 Control unit, programming	0.6
		VO-1703000	Parameter, programming	0.2
		VO-1701200	Fault codes, reading	0.2
			COMPLAINT: EXCESSIVE CAB MOVEMENT AND BANGING.	
			COMPLAINT: INTERIOR LIGHTS WORK INTERMITTENTLY.	
			CHECKED ALL ENGINE DRIVE BELTS. REPLACED FAN BELT.	
			MIRROR LOAD LIGHTS MOVEMENT. REPOSITIONED AND MODIFIED	
			LOAD LIGHTS ON EXTERIOR MIRRORS.	
			CHECKED CABIN WIRING AND TV CONNECTIONS. REWIRED TV INTO	
			BODY BUILDERS FUSE PANEL.	



PC	Type	Code	Description (Original)	#
	☒		CHECKED DASH AND COULD NOT FAULT.	
⊕	*	91	WORKSHOP CONSUMABLES	
	☒		CAUSE: RIGHT HAND STEER AXLE SPRING CRACKED AT CENTRE BOLT.	
	☒		CORRECTION: JACKED AND SUPPORTED CHASSIS. REMOVED WHEELS	
	☒		AND UNBOLTED U BOLTS. REMOVED SHACKLES AND REMOVED SPRING.	
	☒		FIT NEW SPRING AND REFIT SHACKLES AND U BOLTS AND TENSION.	
	☒		REFIT ND TENSION WHEEL.	
	☒		CAUSE: RIGHT HAND STEER SHOCK ABSORBER SOFT.	
	☒		CORRECTION: FITTED A NEW RIGHT HAND STEER SHOCK ABSORBER.	
	☒		CAUSE: INTERNAL FAULT IN STEREO.	
	☒		CORRECTION: CHECKED CD OPERATION. FIT NEW UNIT.	
	☒		NEW RADIO CODE 4448.	
	☒		CAUSE: REAR CAB SHOCK ABSORBERS SOFT.	
	☒		CORRECTION: REPLACED THO REAR CABIN SHOCK ABSORBERS.	
	☒		CAUSE:LEFT HAND CORNER MOUNTING LUG BROKEN DIE TO	
	☒		MATERIAL FATIGUE AND VIBRATION.	
	☒		CORRECTION:FITTED A NEW EXTERIOR SUNVISOR.	
⊕	*	WTY-NONGEN	SWITCH PANEL	
	☒		CAUSE: CONTACT FAULT IN CONTROL SWITCH.	
	☒		CORRECTION: CHECKED INTERIOR LIGHT OPERATION. FITTED NEW	
	☒		CONTROL SWITCH. RECHECKED,	
	☒		OTHER COST FOR SWITCH PANEL FROM SOUTHERN TRUCK CENTRE	
	☒		Å315.99.	

🔍 **W 2015-01-15 - Mileage: 159378 - Order nr: 8611043**

⊕	🔍	VO-8810000	Instrument and radio panel	2.5
⊕	🔍	VO-3640000	Electrical item. Secondary operation num	0.4
⊕	*	2750000	CRUISE CONTROL DROPS OUT BY ITSELF	
⊕	🔍	VO-6420000	Steering gear	0.6
⊕	🔍	VO-7200000	Springs, general	0.6
	☒		SUSPENSION VERY ROUGH.	
⊕	*	8310000	CHECK FOR WATER LEAK DRIVERS DOOR.	
	☒		INSIDE TRIM POOLS WITH WATER.	
⊕	🔍	VO-1774400	Basic service. Chassis lubrication and o	2.7
⊕	🔍	VO-1707300	Service alert system, configuration and	0.4
⊕	🔍	VO-2331100	Filter, water separator, replace	0.4
⊕	🔍	VO-2330600	Fuel filter, replace (one)	0.4
⊕	🔍	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
⊕	🔍	VO-1770000	Maintenance service trucks basic service	1.5

PC	Type	Code	Description (Original)	#
Ⓡ	*	1701000	CHECK FOR NUMEROUS FAULT CODES LOGED.	
	☒		CURRENT HOURS OF UNIT 2433.0 HOURS.	
Ⓡ	☒	VO-FK18B	FILTER KIT	1
Ⓡ	☒	AU2-CAL85121795	VDS4 BULK ENGINE O	42
Ⓜ	Ⓜ	VO-8240000	Front section	0.3
Ⓜ	☒	VO-20379348	GAS SPRING	1
Ⓜ	☒	VO-21033999	SWITCH PANEL	1
Ⓜ	☒	VO-20562030	COVER	2
Ⓜ	☒	VO-8143122	SIX POINT SOCKET S	2
Ⓡ	☒	MK-9424-FS1251	SEPARATOR FUEL/WAT	1
Ⓡ	☒	OTH-YAN-114210-1	YANMAR AIR FILTER ELEMENT	1
Ⓜ	☒	VO-FREIGHT	FREIGHT	25
Ⓡ	*	97	ENVIRONMENTAL CHARGE	
	☒		CURRENT HOURS OF UNIT 2433.0 HOURS.	
	☒		COMPLAINT:GRILL GAS STRUT BROKEN.	
	☒		CARRIED OUT ICEPACK SERVICE AS REQUESTED.	
	☒		CHANGED ENGINE OIL AND FILTERS.	
	☒		CHANGED FUEL FILTER.	
	☒		CHANGED FUEL WATER SEPERATOR FILTER.	
	☒		RESET SERVICE ALERT REMINDER.	
	☒		CARRIED OUT BASIC SERVICE AS PER SCHEDULE.	
	☒		CURRENT HOURS OF UNIT 2433.0 HOURS.	
	☒		COMPLAINT: CRASH PAD LOOSE ON LEFT HAND SIDE.	
	☒		COMPLAINT: INTERIOR LIGHTS NOT OPERATING WITH DOORS.	
	☒		CHECKED CABIN DOORS FOR WATER LEAKS. FOUND ADDITIONAL LIGHTS	
	☒		FITTED TO TOPS OF DOORS AND WIRES CAUSING POOE SEALING OF	
	☒		DOORS.	
	☒		ROAD TEST AND CHECK STEERING OPERATION. REMOVED COLUMN	
	☒		COVERS AND CHECKED UNIVERSAL JOINTS. ALL IN GOOD ORDER.	
	☒		CHECKED SUSPENSION AND CABIN. FOUND ALL IN GOOD ORDER.	
	☒		CHECKED DRIVE SUSPENSION HEIGHT SETTINGS.	
Ⓡ	*	91	WORKSHOP CONSUMABLES	
	☒		CAUSE: MOUNTING BOLT 946173 AND BRACKET 20531175 BROKEN.	
	☒		CORRECTION: INSPECTED LOOSE CRASH PAD. FOUND BOLT BROKE IN	
	☒		FIREWALL. REMOVED PANELS TO ACCESS AND DRILL OUT BROKEN	
	☒		BOLT SECTION. FIT NEW BOLT AND BRACKET AND SECURE. REFIT	
	☒		REMOVED PANELS.	
	☒		CAUSE: CONTACT FAULT IN SWITCH PANEL.	



PC	Type	Code	Description (Original)	#
	☒		CORRECTION: CHECKED INTERIOR LIGHT OPERATION. FITTED NEW	
	☒		SWITCH AND RECHECKED.	
	☒		CAUSE: SHAFT CRACKED AT BALL JOINT END.	
	☒		CORRECTION: REMOVED BROKEN STRUT AND FIT NEW UNIT.	
<b>2014-12-03 - Mileage: 111707 - Order nr: 8610740</b>				
Ⓡ	*	1774400	SUBCONTRACT BASIC SERVICE.	
Ⓡ	*	3530000	REPAIR REVERSE LIGHTS.	
Ⓡ	*	10	CARRY OUT BASIC SERVICE AND REPAIRS.	
	☒		INVOICE ZTCST47016	
	☒		BASIC SERVICE CARRIED OUT IN TOOWOOMBA.	
<b>2014-10-21 - Mileage: 106641 - Order nr: 8610363</b>				
Ⓡ	*	1774400	CARRY OUT BASIC SERVICE AS PER SCHEDULE.	
	☒		CURRENT HOURS OF UNIT 1756 HOURS.	
Ⓡ	*	1751300	Engine, oil and filter, replace. Lube	
Ⓡ	*	1707300	RESET SERVICE ALERT REMINDER.	
Ⓡ	*	2331100	Filter, water separator, replace	
Ⓡ	*	2330600	Fuel filter, replace (one)	
Ⓡ	*	1752300	Gearbox oil and filter, replace.	
Ⓡ	*	1752700	Final drive oil, change.	
	☒		SERVICE AND REPAIRS CARRIED OUT IN TOOWOOMBA.	
	☒		REPAIRED SPOT LIGHT WIRING AT BULL BAR.	
	☒		CARRIED OUT BASIC SERVICE AS PER SCHEDULE.	
	☒		CHANGED GEARBOX OI AND FILTER.CHANGED POWER STEER FILTER.	
	☒		CHANGED BOTH DIFFERENTIAL OILS.	
	☒		FITTED UHF MIC CLIP.	
	☒		MADE UP AND FITTED ALLOY PLATES TO LOCKER BOX FLOOR.	
	☒		REPLACED BLOWN HEADLIGHT GLOBE AND ADJUST.	
	☒		FOTTED TUBES TO MIRROR LOAD LIGHTS.	
Ⓡ	*	10	SERVICE AND REPAIRS.	
	☒		INVOICE 46224,46384.	
<b>2014-10-17 - Mileage: 111707 - Order nr: T46408</b>				
Ⓡ	Ⓡ	VO-22144200	AIR SPRING	2
Ⓡ	Ⓡ	VO-8182700	Cab shock absorber air rear, replace (two sides)	0.7
Ⓡ	Ⓡ	VO-8184500	Air bellows, shock absorber for cab, check (two). two	0.3
Ⓡ	☒		REAR OF CAB DOWN	
<b>2014-09-05 - Mileage: 86124 - Order nr: 8610025</b>				
Ⓡ	Ⓡ	VO-1706300	6 Months ECU download and oil sample. On	0.9
Ⓡ	Ⓡ	VO-1774400	Basic service. Chassis lubrication and o	2.7

PC	Type	Code	Description (Original)	#
Ⓡ	Ⓢ	VO-1707300	Service alert system, configuration and	0.4
Ⓡ	Ⓢ	VO-2331100	Filter, water separator, replace	0.4
Ⓡ	Ⓢ	VO-2330600	Fuel filter, replace (one)	0.4
Ⓡ	Ⓢ	VO-1751300	Engine, oil and filter, replace. Lube ar	0.7
Ⓡ	*	3631700	WINDSCREEN WASHERS LEAKING.	
Ⓡ	*	8510000	TELEVISION MOUNT LOOSE.	
Ⓡ	Ⓢ	VO-FK18B	FILTER KIT	1
	Ⓢ		VO/FK18B WAS FITTED BY BRANCH 4800	
	Ⓢ		,- ON REPAIR ORDER 8609298 - DATE 2014-06-13 MILEAGE - 38443	
Ⓢ	Ⓢ	VO-8394887	OIL TEST KIT	4
	Ⓢ		VO/8394887 WAS FITTED BY BRANCH 4800	
	Ⓢ		,- ON REPAIR ORDER 8609298 - DATE 2014-06-13 MILEAGE - 38443	
Ⓢ	Ⓢ	AU2-CAL85121795	VDS4 BULK ENGINE O	42
	Ⓢ		CURRENT HOURS OF UNIT 1392.1 HOURS.	
Ⓡ	Ⓢ	VO-21716424	AIR FILTER	1
Ⓡ	Ⓢ	VO-2562700	Filter insert, air cleaner, replace. Onl	0.4
	Ⓢ		CARRIED OUT BASIC SERVICE AS PER SCHEDULE.	
	Ⓢ		RESET SERVICE ALERT REMINDER.	
	Ⓢ		CHANGED FUEL WATER SEPERATOR FILTER.	
	Ⓢ		CHANGED FUEL FILTERS.	
	Ⓢ		CHANED ENGINE OIL AND FILTERS.	
Ⓡ	*	97	ENVIRONMENTAL CHARGE	
	Ⓢ		CHECKED WINDSCREEN WASHER OPERATION AND FOR LEAKS.	
	Ⓢ		CHECKED AND TIGHTENED ALL TV MOUNTS AND SWIVELS.	
	Ⓢ		FITTED A NEW AIR FILTER.	
	Ⓢ		COMPLAINT:CARRY OUT 6 MONTH ELECTRONIC CONTROL UNIT	
	Ⓢ		DOWNLOAD AND TAKE OIL SAMPLES.	
	Ⓢ		CAUSE:DUE OPERATION.	
	Ⓢ		CORRECTION:CARRIED OUT 6 MONTH ELECTRONIC CONTROL UNIT	
	Ⓢ		DOWNLOAD AND TOOK OIL SAMPLES.	
Ⓡ	*	91	WORKSHOP CONSUMABLES	
<b>2014-06-11 - Mileage: 38443 - Order nr: 8609298</b>				
Ⓢ	*	5600000	PARK BRAKE ALRM FOR DOOR.	
	Ⓢ		CURRENT HOURS OF UNIT 602.6 HOURS.	
Ⓢ	Ⓢ	VO-979002	TERMINAL	2
Ⓢ	Ⓢ	VO-969161	BLADE FUSE,10A	1
Ⓡ	Ⓢ	VO-1774400	Basic service. Chassis lubrication and o	5
Ⓡ	Ⓢ	VO-FK18B	FILTER KIT	1



PC	Type	Code	Description (Original)	#
Ⓡ	✱	VO-8394887	OIL TEST KIT	1
Ⓡ	✱	AU2-CAL85121795	VDS4 BULK ENGINE O	42
Ⓡ	✱	97	ENVIRONMENTAL CHARGE	
	☒		CARRIED OUT BASIC SERVICE AS PER SERVICE SCHEDULE	
	☒		CHANGED OIL & FUEL FILTERS.	
	☒		CHANGED ENGINE OIL.	
	☒		OIL SAMPLE TAKEN.	
	☒		CHECKED AND TOQRUED WHEELS NUTS & U BOLTS.	
	☒		CHECKED FAULT CODES & SET UP SERVICE INTERVAL.	
Ⓡ	✱	91	WORKSHOP CONSUMABLES	
<b>W 2014-05-27 - Mileage: 33166 - Order nr: 8609183</b>				
Ⓡ	✱	3520000	DRIVING LIGHTS - INTERMITTENT FAULT	
Ⓡ	✱	8730000	ICE PACK - NOT WORKING	
Ⓡ	✱	2340000	POLISH L/H/S FUEL TANK	
Ⓡ	✱	20	POLISH FUEL TANK	
Ⓡ	Ⓢ	VO-8820000	Interior equipment	0.75
Ⓡ	Ⓢ	VO-8911000	Sun visor complete, replace	0.7
Ⓡ	✱	8750000	BOLT LOOSE BOTTOM OF ICE PACK	
Ⓡ	✱	VO-20425858	CLIP	2
Ⓡ	Ⓢ	VO-3600000	Other electrical equipment, general. Sec	4
Ⓡ	✱	VO-82921563	SUN VISOR	1
Ⓡ	✱	OTH-253MXB	ZIP TIE 11"	15
Ⓡ	✱	VO-6781769	SPLICE-RED(22-18)	4
Ⓡ	✱	OTH-WIRE	WIRE	1
Ⓡ	✱	MK-NARV56820BK	TAPE NITTO BLACK	1
Ⓡ	✱	VO-979002	TERMINAL	9
Ⓡ	✱	VO-946770	CABLE SHOE	1
Ⓡ	✱	VO-20382270	DIODE	1
Ⓡ	✱	VO-959046	INSULATOR	1
Ⓡ	✱	VO-949597	SLEEVE	2
Ⓡ	✱	VO-21244697	RELAY	2
Ⓡ	✱	VO-8141996	RECEPTACLE HOUSING	2
Ⓡ	✱	VO-9130476	SPLICE-BLUE(14-16)	3
	☒		CURRENT HOURS OF UNIT 468.2 HOURS.	
	☒		SUBCONTRACT TO HAVE LEFT HAND FUEL TANK POLISHED.	
	☒		NEW BALLESTS FITTED UNDER KENNY'S AUTO WARRANTY.	
	☒		CURRENT HOURS OF UNIT 468.2 HOURS.	
	☒		COMPLAINT:INTERIOR CURTIN TRACK KEEPS FALLING DOWN.	

PC	Type	Code	Description (Original)	#
	📄		CURRENT HOURS OF UNIT 468.2 HOURS.	
	📄		TIGHTENED BOTTS ON ICEPACK.	
	📄		REPAIRED BY KENNY'S AUTO ELECTRICAL.	
	📄		SUPPLIED AND FITTED PARK BRAKE ALARM.	
	📄		COMPLAINT:EXTERIOR SUNVISOR VIBRATING AND RATTILING.	
	📄		CAUSE:RETAINING CLIP NOT HOLDING SECURLEY.	
	📄		CORRECTION:FIT NEW RETAINING CLIP AND SECURE RAIL.	
	📄		CAUSE:LEFT HAND CORNER MOUNTING LUG BROKEN DIE TO	
	📄		MATERIAL FATIGUE AND VIBRATION.	
	📄		CORRECTION:FITTED A NEW EXTERIOR SUNVISOR.	
<b>🔍 2014-05-22 - Mileage: 29926 - Order nr: T44207</b>				
🔍	📄		cracking noise in lf side fuel tank	
🔍	🔧	VO-2340000	PUMP OUT FUEL & FILTER & ADD TO NEW TANK	0.6
🔍	🔧	VO-2341200	Fuel tank, replace	1.3
🔍	🔧	VO-20582669	FUEL TANK,690L,LH	1
🔍	🔧	VO-8720000	LOCATE CAUSE OF RATTLE IN LH SIDE OF DASH,R/R LH KICK PANEL ,INSPECT, INSTALL & SECURE VENTS	0.8
🔍	📄		RATTLE LH SIDE OF DASH	
<b>🔍 2014-05-01 - Mileage: 0 - Order nr: 8047019</b>				
	📄		Repair without detail info	
<b>🔍 2014-04-23 - Mileage: 9687 - Order nr: 8900415</b>				
🔍	🔧	VO-1721000	Warranty service. After 4 weeks or maxim	2.9
	📄		CURRENT HOURS OF UNIT 192 HOURS.	
🔍	🔧	10	GEARBOX OIL	
🔍	🔧	1720000	PARTS AND OILS USED IN SERVICE.	
	📄		COMPLAINT:CARRY OUT FIRST SERVICE AS PER SCHEDULE.	
	📄		INVOICE 0155365	
	📄		CAUSE:DUE OPERATION.	
	📄		CORRECTION:CARRIED OUT FIRST SERVICE AS PER SCHEDULE.	
<b>🔍 2014-04-03 - Mileage: 2957 - Order nr: 8608790</b>				
🔍	🔧	LO-360	FIT 7 PIN UDELEX ON THE SUZI COIL	0.5
	📄		TRAILER END	
🔍	🔧	80	FIT 7 PIN ADAPTER TO SUZI COIL	
	📄		INVOICE 8135	
<b>🔍 2014-03-12 - Mileage: 2957 - Order nr: 8608631</b>				
	📄		Pre delivery	
	📄		Extra Load Light to rear of cab LHS	
	📄		Check Campaigns	



PC	Type	Code	Description (Original)	#
	☒		Fit Chrome Inserts without nuts	
	☒		Fit Loop Kits to rear drives	
	☒		Change Drive Guards to Yellow	
	☒		Fit GCM Plate & Number Plates	
	☒		Fit alloy Bullbar (supplied)	
🔧	🔧	VO-1710200	Delivery service	5
🔧	*	3560000	EXTRA LOAD LIGHT LEFT REAR CAB.	
🔧	🔧	VO-7710000	Wheel and wheel trim	1.5
🔧	🔧	VO-8260000	Rear mudguard	4
🔧	🔧	VO-8260200	Rear mudguard, new install	2
🔧	🔧	VO-8610000	Bumper with mounting and damping	6
🔧	🔧	VO-8970000	Instruction and information plates	0.5
🔧	🔧	VO-6895965	HUB-CAP	6
🔧	🔧	VO-8394442	CLIPS, HUBCAP FIT	18
🔧	🔧	MK-9728-MG22Y	MUDGUARD YELLOW	4
🔧	🔧	MK-9728-LK24	LOOP KIT MUDGUARD	2
🔧	🔧	OTH-SSR316	RIVET,3/16 S/S	8
🔧	🔧	MK-9711-0005SP	NUT COVER	3
🔧	🔧	VO-20548038	EMBLEM	2
🔧	🔧	VO-21192961	EMBLEM	1
🔧	🔧	VO-85113349	ADBLUE 1000 LTR IBC	33
🔧	🔧	UNK-FREIGHT1	FREIGHT	1
🔧	🔧	UNK-FREIGHT1	FREIGHT	1
🔧	🔧	OTH-VOLVO1824ASC3	MUDFLAP	4
🔧	🔧	OTH-M4X20	M4 x 20 S/S SCREW	12
🔧	🔧	OTH-M4-S/S-WASHER	M4 S/S WASHER	12
🔧	🔧	OTH-M4NYLOC	M4 NYLOCK NUT	12
🔧	🔧	VO-984735	FLANGE SCREW	2
🔧	🔧	VO-990950	FLANGE LOCK NUT	2
🔧	🔧	OTH-05WRO056	5/16 x 1-1/4 FLAT WASHER	10
🔧	🔧	OTH-SSR18	RIVET,1/8 S/S	8
🔧	🔧	VO-975209	FLANGE SCREW	4
🔧	🔧	OTH-VWC10210ALU	disc cutting 4" alloy	1
🔧	🔧	OTH-CP33Y	CHECKPOINT NUT INDI	1
🔧	🔧	OTH-SSR316	RIVET,3/16 S/S	8
🔧	🔧	OTH-204020	hand ratchet 25mm x 4m	1
	☒		Once bullbar fitted found bullbar won't go all the way down,	
	☒		had to remove it and cut more of the hinges so bullbar	

PC	Type	Code	Description (Original)	#
	☒		would go all the way.	
📌	📌	LO-390	FIT DECALS TO CAB	0.5
📌	*	3900000	SUPPLY ONLY YELLOW NUT INDICATORS	
	☒		Fitment Not Possible.	
📌	📌	VO-7130300	Winch spare wheel, replace	0.5
📌	📌	VO-8550000	Other upholstery	1
	☒		FITTED SEAT COVER FOUND PASSENGER SEAT INCORRECT RUTH	
	☒		ORGANISED CORRECT ONE - FITTED.	
	☒		CONFIRMED WITH REX	
🔍	<b>2014-01-30 - Mileage: 100 - Order nr: 8709424</b>			
	☒		DG Harness to Alternator	
	☒		Mirror Lights	
	☒		Supply & Fit TV-DVD	
	☒		S & F UHF Radio (same as Blenners)	
📌	📌	LO-355P43M	MIRROR LIGHTS	4.75
📌	📌	LO-395P43U	S&F UHF RADIO (SAME AS BLENNERS)	4.12
📌	📌	OTH-LLX21101	SMALL LED WORKLIGHT	2
📌	📌	MK-NARV56306	CABLE TIE 1=25PK	1
📌	📌	OTH-T110PMTR	CABLE 3MM TWIN CORE	7
📌	📌	VO-20375162	CABLE TERMINAL	2
📌	📌	VO-6781769	SPLICE RED	6
📌	📌	OTH-MCVO-UHF-LOWCAB-F	UHF ONLY - FM/FH (NO REMOTE)	1
📌	📌	MK-9771-LEM6P	MICROPHONE EXT LEA	1
📌	*	10	SUPPLY & INSTALL TV/DVD	
📌	📌	VO-20569981	SWITCH FH ROCKER	1
📌	📌	VO-1594558	SYMBOL STRIP WORK LAMP	1
🔍	<b>2013-10-21 - Mileage: 600 - Order nr: 8513578</b>			
📌	📌	LO-210	PREDELIVERY	6.5





UD TRUCKS



# Volvo Commercial Vehicles - Sydney West

Division of Volvo Group Australia Pty Ltd  
ABN 27 000 761 259

## WORKSHOP TAX INVOICE

Invoice To :

Page no.....: 1

Invoice number...: 7278094 - 002000

Invoice Date.....: 31/05/21

Customer Ref.....:

Due Date.....:

Terms.....: NET 30 DAYS (3)

Our reference....: 7278094 - 002000

Advisor was.....:

Remarks.....:

### Vehicle Details

Reg Number: XQ61RR VOLVO (0) FH 6\*4  
Chassis No: 137194  
Odometer...: 1,093,939 Engine Hrs: 0  
Contract...:  
VIN .....: YV5AP80D8DD137194  
Fleet .....

Operation /Part Number	Description	List Price	Nett Price	--Quantity-- Invced B/Ord	Amount
465	D&R ON TAIL SHAIFT CAME ADRIPT AND HAS DAMAGED AIRLINES- ASSESS DAMAGE AND ADVISE CUSTOMER Removed gearbox and tailshaft and assessed damage from tailshaft that had come out. Had to replace and run all new airlines for brakes and suspension. Replaced 4 way valve fittings. Replaced damaged adblue pump tubing and replaced wiring for trailer modulator valve. Removed damaged gearbox rear housing as it was cracked. Customer supplied second hand housing and second hand tailshaft. Fitted housing to gearbox and refitted gearbox and tailshaft. Road tested vehicle and found it had bad vibration. Traced to bent mainshaft in gearbox from impact damage from tailshaft failure. Replaced with new gearbox - Refer below special -				3160.00
VO 20877939	FILTER CAP	68.40	64.98	1.0	64.98
MK NARV56306	CABLE TIE 300MM	3.81	3.52	2.0	7.05
VO 980832	8MM AIRLINE PLA	6.61	5.95	2.0	11.90
VO 980833	12MM AIRLINE PL	12.59	11.33	1.0	11.33
AU2 9701-GP1162M12	12MM JOINER	20.60	19.05	4.0	76.22
MK FTM62X16	JOINER HOSE 16M	19.63	17.86	2.0	35.73
MK FTM62X8	JOINER, 8MM TUB	7.32	6.66	2.0	13.32
VO 991092	NIPPLE	31.97	28.77	1.0	28.77
VO 991080	NIPPLE	20.95	18.85	1.0	18.86
VO 994000	ELBOW NIPPLE ME	23.29	20.96	1.0	20.96
VO 991980	T NIPPLE	23.51	21.16	1.0	21.16
VO 991075	NIPPLE Regular	33.37	30.03	1.0	30.03
VO 991075	NIPPLE Regular	33.37	30.03	2.0	60.07
VO 992013	F NIPPLE	16.38	14.74	2.0	29.48
MK FTM62X8	JOINER, 8MM TUB	7.32	6.66	7.0	46.63

**Volvo Commercial Vehicles - Sydney West**  
9 Oatley Close, Blacktown NSW 2148  
Main Switch : (02) 9678 2000  
Fax : (02) 9678 2088  
www.vcvssydneywest.com.au

Volvo Commercial Vehicles - Sydney  
6/34 Yarrunga Street, Prestons NSW 2170  
Main Switch : (02) 9731 8600  
Fax : (02) 9731 8699  
www.vcvssydney.com.au

Volvo Commercial Vehicles - Newcastle  
8 Birraba Avenue, Beresfield NSW 2322  
Main Switch : (02) 4922 2600  
Fax : (02) 4966 1755  
www.vcvnewcastle.com.au



UD TRUCKS



# Volvo Commercial Vehicles - Sydney West

Division of Volvo Group Australia Pty Ltd  
ABN 27 000 761 259

## WORKSHOP TAX INVOICE

Invoice To :

Page no.....: 2

Invoice number...: 7278094 - 002000

Invoice Date.....: 31/05/21

Customer Ref.....:

Operation /Part Number	Description	List Price	Nett Price	--Quantity-- Invced B/Ord	Amount
VO 980832	8MM AIRLINE PLA	6.61	5.95	3.0	17.85
MK FT62X5	5/16 JOINER	5.00	4.55	1.0	4.55
VO 21429181	HOSE	11.32	10.19	5.0	50.94
VO 20748166	CONNECTOR,SAE 3	13.00	11.70	2.0	23.40
VO 20744599	CONNECTOR,5/16	12.13	10.92	1.0	10.92
VO 20748166	CONNECTOR,SAE 3	13.00	11.70	1.0	11.70
VO 20744597	CONNECTOR,SAE 5	33.32	29.99	1.0	29.99
OTH NARV587330TC/1MT	CABLE 7 CORE 3M	4.35	4.35	1.0	4.35
VO 20791305	SEALING RING	115.13	106.50	1.0	106.50
VO 20785448	BALL BEARING	329.35	296.41	1.0	296.42
VO 1652802	RETAIN.RING,3.7	21.22	19.63	1.0	19.63
VO 1652803	RETAIN.RING,3.8	21.22	19.63	1.0	19.63
VO 1652804	RETAIN.RING,3.9	35.53	32.87	1.0	32.87
VO 914556	RETAIN.RING,4.0	13.81	12.77	1.0	12.77
MK NARV56820BK	NITTO INSULATIO	2.10	1.94	1.0	1.94
VO 25106045	CLAMP HOSE -5/8	4.20	3.78	4.0	15.12
MK FT3400X6	BRASS PIPE	4.74	4.31	1.0	4.31
VO 944364	O'RING	5.66	5.09	2.0	10.19
VO 949656	O-RING	7.71	6.94	2.0	13.88
MK 342SX33	SILICONE DOW	15.01	13.81	1.0	13.81
VO 995906	HEX BOLT M14X46	12.80	11.84	4.0	47.36
VO 984050	HEX NUT M14 FIN	5.77	5.19	4.0	20.77
VO 993252	NIPPLE	32.09	28.88	1.0	28.88
MK FTM62X8	JOINER, 8MM TUB	7.32	6.66	1.0	6.66
MK FT62X5	5/16 JOINER	5.00	4.55	1.0	4.55
MK FTM62X8	JOINER, 8MM TUB	7.32	6.66	1.0	6.66
VO 975269	HOSE CLAMP	2.90	2.61	4.0	10.44
MK NARV56713	TUBING SPLIT 13	11.27	10.42	1.0	10.42
VO 20785252	LID GASKET KIT	248.71	248.71	1.0	248.71

Subtotal: 001 Order Job 001: 4721.71

471	GEARBOX SPECIAL PACKAGE				948.00
VO 85001704	EXCH GEARBOX	14052.00	14052.00	1.0	14052.00

Subtotal: 002 Order Job 002: 15000.00

470 SPEC UP GEARBOX 632.00

Swapped over gearbox oil cooler and replaced leaking hoses.  
Programmed gearbox and filled with new oil.

**Volvo Commercial Vehicles - Sydney West**  
**9 Oatley Close, Blacktown NSW 2148**  
**Main Switch : (02) 9678 2000**  
**Fax : (02) 9678 2088**  
**www.vcvssydneywest.com.au**

Volvo Commercial Vehicles - Sydney  
6/34 Yarrunga Street, Prestons NSW 2170  
Main Switch : (02) 9731 8600  
Fax : (02) 9731 8699  
www.vcvssydney.com.au

Volvo Commercial Vehicles - Newcastle  
8 Birraba Avenue, Beresfield NSW 2322  
Main Switch : (02) 4922 2600  
Fax : (02) 4966 1755  
www.vcvnewcastle.com.au





UD TRUCKS



# Volvo Commercial Vehicles - Sydney West

Division of Volvo Group Australia Pty Ltd  
ABN 27 000 761 259

## WORKSHOP TAX INVOICE

Invoice To :

Page no.....: 3

Invoice number...: 7278094 - 002000

Invoice Date.....: 31/05/21

Customer Ref.....:

Operation /Part Number	Description	List Price	Nett Price	--Quantity-- Invced B/Ord	Amount
VO 23701845	OIL HOSE ISHIFT	134.51	124.42	1.0	124.42
VO 23701846	OIL HOSE ISHIFT	139.16	128.72	1.0	128.72
VO 995906	HEX BOLT M14X46	12.80	11.84	2.0	23.68
VO 984050	HEX NUT M14 FIN	5.77	5.19	2.0	10.39
AU2 CAL85121714	VOLVO SAE50 TRA	6.11	5.80	15.0	87.07
1701000	Connect-disconnect PC				52.00
	Subtotal: 003 Order Job 003:				1058.28
430	GEARBOX (32)				
	Subtotal: 004 Order Job 004:				0.00
91	WORKSHOP CONSUMABLES				150.00
For Payment via EFT:					Sub Total Parts..: 15987.99
Citibank					Sub Total Labour.: 4792.00
BSB - 242 000					Sub Total Other..: 150.00
ACC - 100599147					GST.....: 2093.03
We thank you for your business.					=====
					T O T A L 23023.02
					=====

HEADING\_20\_QPR1JOB/A013256/731708

**Volvo Commercial Vehicles - Sydney West**  
9 Oatley Close, Blacktown NSW 2148  
Main Switch : (02) 9678 2000  
Fax : (02) 9678 2088  
www.vcvssydneywest.com.au

Volvo Commercial Vehicles - Sydney  
6/34 Yarrunga Street, Prestons NSW 2170  
Main Switch : (02) 9731 8600  
Fax : (02) 9731 8699  
www.vcvssydney.com.au

Volvo Commercial Vehicles - Newcastle  
8 Birraba Avenue, Beresfield NSW 2322  
Main Switch : (02) 4922 2600  
Fax : (02) 4966 1755  
www.vcvnewcastle.com.au



**SWAN HILL**  
 4 Jennings Rd Swan Hill  
 Vic 3585  
 Ph: 03) 5024 4666

**MILDURA**  
 579 Benetook Ave Mildura  
 Vic 3501  
 Ph: 03) 5024 4666  
 Fax: 03) 5021 3113

Website: www.johnsonstrucks.com.au email: accounts@johnsonstrucks.com.au  
 Head Office: PO Box 1700cp Mildura Vic 3501 ABN: 59 007 391 264 LMCT 10347

<b>Invoice # H120897</b>		<b>TAX INVOICE</b>		<b>R/O # R119319</b>		Page 1 of 2
Doc. Date <b>01/04/2021</b>	Customer Name and Address			Rego <b>XQ61RR</b>	Stock No. <b>XQ61RR</b>	Adviser <b>aj</b>
Order No.				Manufacturer <b>Volvo Trucks</b>	Kms <b>1,075,989</b>	Build Period <b>00/0000</b>
Customer Code				Vin <b>YV5AP80D8DD137194</b>		
User Code	Charge To <b>SERVICE CASH SALE</b>			Engine No	Chasis No <b>D137194</b>	Warranty Date <b>00/00/0000</b>
				Model <b>VOLVO</b>	Version	Body Type
Terms <b>C.O.D.</b>	Contact Ph. (Home) Ph. (Work) Ph. (Other)			Next Service Date <b>00/00/0000</b>	Date & Time In <b>26/03/2021 08:00</b>	Body Color
				Next Service Kms <b>0</b>	Date & Time Promised <b>26/03/2021 08:00</b>	Engine Hours <b>0</b>

Job	Description	Quantity	Price Excl.
<b>1</b>	<b>IN CHASSIS ENGINE REBUILD</b>		
L	IN CHASSIS ENGINE REBUILD		7,800.00
WS	WORKSHOP SUPPLIES	1	30.00
EV	ENVIRONMENTAL LEVY	1	7.00
VT85121797L	VDS4 OIL PER LITRE	50	357.50
VT85108914L	COOLANT, YELLOW PER LITRE P/MIX	50	325.50
VT85022268	EXCH CLY HEAD	1	7,650.00
VT85028268	CORE CLY HEAD	1	1,000.00
VT20734156	SEALING STRIP	1	79.06
MPERM81950	PX ASSEMBLY LUBE 4	1	18.91
VT8192804	SCREW	8	22.96
VT20586602	BIG-END BEARING KI	6	340.68
VT21503575	SEALING RING	1	26.77
VT21254035	CYLINDER LINER KIT	6	5,666.16
VT20578851	MAIN BEARING SHELL	6	340.68
VT20578853	MAIN BEARING SHELL	1	56.78
VT22879257	CAMSHAFT BEARING K	1	66.18
VT22879256	CAMSHAFT BEARING K	6	595.44
OT0673207518	NYLON POWER LOC 31	3	13.92
OT0674850240	EMERY G240	3	8.82
OT5005	CRC 5.56 SPRAY CAN	3	33.60
VT20728609	INLET HOSE	1	439.57
VT955982	O-RING	6	24.66
VT983472	CABLE TIE	10	3.30
FR	FREIGHT	1	300.00
VT21948268	THRUST WASHER KIT	1	102.17
VT85000622	EXCH TURBOCHARGER	1	2,377.05
VT85006622	CORE TURBOCHARGER	1	350.00
VT21345127	STUD	4	57.20
VT20573472	SPACER SLEEVE	4	39.56
VT1543499	FLANGE NUT	4	13.68
VT21539900	GASKET KIT	1	990.00
VT85136742	FILTER KIT	1	262.88
VT21716424	AIR FILTER	1	229.55

**Continued**



Invoice # <b>H120897</b>		<b>TAX INVOICE</b>		R/O # <b>R119319</b>		Page 2 of 2	
Doc. Date <b>01/04/2021</b>	Customer Name and Address			Rego <b>XQ61RR</b>	Stock No. <b>XQ61RR</b>	Adviser <b>aj</b>	
Order No.				Manufacturer <b>Volvo Trucks</b>	Kms <b>1,075,989</b>	Build Period <b>00/0000</b>	
Customer Code				Vin <b>YV5AP80D8DD137194</b>			Delivery Date <b>00/00/0000</b>
User Code	Charge To <b>SERVICE CASH SALE</b>	Engine No	Chasis No <b>D137194</b>	Warranty Date <b>00/00/0000</b>		Body Type	
		Model <b>VOLVO</b>	Version	Body Color			
Terms <b>C.O.D.</b>	Contact Ph. (Home) Ph. (Work) Ph. (Other)	Next Service Date <b>00/00/0000</b>	Date & Time In <b>26/03/2021 08:00</b>	Engine Hours <b>0</b>			
		Next Service Kms <b>0</b>	Date & Time Promised <b>26/03/2021 08:00</b>				
Job	Description	Quantity	Price Excl.				
VT20411816	AIR FILTER	1	241.03				
	INSPECT COOLANT IN OIL STRIP DOWN ENGINE FOUND 2X CRACKED PISTON LINERS REMOVE AND REPLACE ALL PISTONS AND LINERS CLEAN OUT OIL SYSTEM FREE OF COOLANT REPLACE CYLINDER HEAD REPLACE ALL CRANKSHAFT BEARINGS REMOVED AND REPLACED NUMBER 1-5-6 INJECTORS REPLACE CAM BEARINGS REPLACE ENGINE OIL AND FILTERS REPLACE COOLANT REPLACE AIR FILTERS REPLACE TURBO CARRY OUT ALL ADJUSTMENTS AND REFIT ALL COMPONENTS *****C.O.D.***** **PLEASE NOTE THIS DOES NOT INCLUDE TOWING OF VEHICLE FROM WAIKERIE**						
VT21371399	PIPE SET	1	186.79				
OT28MXBS	T&B CABLE TIE 360MM X 4.8MM	20	5.20				
OT00571055	BOLT METRIC 10 X 55MM	1	1.68				
OT040710	WASHER FLAT 10MM	2	0.16				
MPERM80019	PX 3H AVIATION FAG	1	11.02				
OT036810	NUT NYLOC 10MM	1	0.28				
VT23285701	OIL LEVEL SENSOR	1	224.93				
OT05392812	HOSE CLAMP 8-12MM	1	1.78				
OTMT200	BRAKE CLEANER	1	4.22				
VT85013343	EXCH UNIT INJECTO	3	3,327.24				
VT85019343	CORE UNIT INJECTO	3	1,237.50				
			Job Total (EX GST):		<b>34,871.41</b>		
-Please note if paying via EFTPOS Surcharges will apply. -							
- Thank you for supporting our small Australian owned and operated business!							

**Bank Account Details**  
 BSB: 633 000 Account No: 113258578



**Parts: 26,734.41**  
**Labour: 7,800.00**  
**Others: 337.00**  
**Sub Total: 34,871.41**  
**Total GST: 3,487.14**  
**Rounding: 0.00**  
**Total: 38,358.55**