



# MAZDA RECALLS

View your vehicles details below

**Model:** MAZDA3 E SEDAN 5 SPEED AUTO MAXX SPORT

**VIN:** JM0BL10F100102061

**Year:** 2009



**YOUR VEHICLE IS AFFECTED BY 1 RECALL**

**1** Active Recall | **0** Pending Recalls

**Result returned on:** 06/03/2023 09:45 AM AEST

## SEAT LIFTER LINK RECALL

STATUS	RECALL CODE	PRA NUMBER
Active	R201810	2017/15935 REC-000879

### Risk

On the drivers seat of the affected vehicles, it is possible that the Seat Height Adjustment Lifter Link may crack, or the Lifter Link Retaining Nuts may separate. In the worst case, the Lifter Link may break or separate from the seat frame, causing the seat to move out of position.

### Remedy

Mazda Australia will contact all affected owners. Owners will be advised to present their vehicle to their preferred Mazda Dealer for inspection and repair at no charge.

---