

Stock No: APH01025

Caterpillar 740B Articulated Dump Truck

Serial No: CAT0740BVT4R00385

Reg No:

Cat: DTRK40

Year: 2011

Provisional?:

Supplier:

Model: Caterpillar 740

Under Repair?

Log

<i>Date</i>	<i>Type</i>	<i>Description</i>	<i>Meter</i>	<i>Labour</i>	<i>Parts</i>
18/07/2024	OTHER	Westrac: Supply 2 x Mirrors			\$259.14
17/07/2024	REPAIR	Harris Heavy Mechanical - repair auto greaser		\$760.00	
17/07/2024	OTHER	Pirtek: Supply grease line fittings: lubrication hose, standpip hose, ferrule, elbows			\$283.86
4/07/2024	OTHER	westrac: Suply switch as			\$168.72
21/06/2024	OTHER	Westrac: Bin Body Control handle			\$139.56
19/06/2024	OTHER	Tilly's: Supply Tailgate Arr			\$8,500.00
6/06/2024	REPAIR	DC: Engine oil leaks. Found brake pump loose. Mount bolts, new pump sourced and fitted with new gasket and o-rings. Test pressure OK, sump gasket seal leak. Tension 1/4 turn monitor. Replace engine components and guards (@ 13295 Hours)	13295	\$400.00	
5/06/2024	OTHER	Westrac: Supply hyd gp pump, integra seal			\$2,220.22
5/06/2024	OTHER	SCH: high temp wire hose, female hose, hose end, ferrule to suite hose, hose assembly			\$660.00
4/06/2024	REPAIR	Tyrepower: Earthmover tyre service labour		\$150.00	
29/05/2024	REPAIR	Westrac: Troubleshoot diesel particulate filter Inspect exhaust/emissions system for defects, take PSR, clear logged events. Perform ard air system test, perform manual DPF regeneration, test drive truck to ensure fault does not return, return truck to service (@ 13241 Hours)	13241	\$987.74	

Stock No: APH01025

Caterpillar 740B Articulated Dump Truck

Serial No: CAT0740BVT4R00385

Reg No:

29/05/2024	REPAIR	Harris Heavy Mechanical: Complete turning with laptop remotely. Remove muffler box and remove centre. Reassemble and unplug sensors. Check auto greaser fault		\$690.00
29/05/2024	OTHER	ECU Tech: Cat DPF Delete		\$3,500.00
26/04/2024	OTHER	Next Service - meter reading postponed from 13405		
26/03/2024	OTHER	Western Battery: Supply 2 x Gold N150 Truck batteries		\$500.73
19/03/2024	OTHER	RDW: Supply Joint GP slip front 745		\$3,376.41
15/03/2024	REPAIR	DC: Remove replace RH bottom bush. Gas and level suspension struts (@ 13159 Hours)	13159	\$200.00
15/03/2024	OTHER	Tilly's: Pin-mount, suspension bearing, tapered bushing		\$890.50
14/03/2024	REPAIR	DC: Fit bushes to torque rods, fit rods, replace and refit rear steer cylinder bushes. Unbolt RH tub cylinder (@ 13159 Hours)	13159	\$350.00
13/03/2024	REPAIR	DC: Fit panels, exhaust, hoses. Repair LH mirror, remove middle torque bars and cut out of bushes (@ 13159 Hours)	13159	\$400.00
13/03/2024	OTHER	Westrac: Supply filter element and ring		\$99.97
12/03/2024	REPAIR	DC: Re-install drop box/cooler assembly, fill with coolant, charge batteries as they were flat. Install handrail, fit pump, fill with 20L 430 (@ 13159 Hours)	13159	\$400.00
12/03/2024	OTHER	Westrac: Supply seal-bellows		\$190.60
4/03/2024	REPAIR	DC: Fit cooler packs, transmission drive shaft, hose drop box and connect cooler hoses. Wash out coolers (@ 13159 Hours)	13159	\$320.00
26/02/2024	REPAIR	DC: Start fitting drop box lube pump		\$115.00
12/02/2024	OTHER	Westrac: Pump GP		\$1,492.57

Stock No: APH01025

Caterpillar 740B Articulated Dump Truck

Serial No: CAT0740BVT4R00385

Reg No:

1/12/2023	REPAIR	DC: Remove cooler packs and drop box	\$225.00	
28/11/2023	OTHER	SCH: Supply plugs and caps ORFS 1/4 to 3/4 "		\$346.43
27/11/2023	REPAIR	DC: Start removing drop box	\$225.00	
7/11/2023	OTHER	.		
31/10/2023	OTHER	Road Runner: Supply UHF Transceiver 80 channel and antenna		\$328.81
			<hr/>	
			\$5,222.74	\$22,957.52