

Work Order ID	Equipment ID	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R155-0021511	1531	998.40	2053753		VEHICLE SHUTTING DOWN	31/07/2023	1/08/2023
R155-0021343	1531	60.00	2050948		Air con temp adjuster broken	10/07/2023	12/07/2023
R155-0021182	1531	153.19	2049997		KEY BROKEN	26/06/2023	28/06/2023
R155-0021158	1531	588.11	2049815		SUZI COIL LEAKING AIR	22/06/2023	26/06/2023
R155-0021090	1531	1458.72	2048460		REPORTED NOT CHANGING GEARS - FAULT LIGHT DISPLAYED	15/06/2023	20/06/2023
R155-0021090	1531				STOP ENGINE LIGHT DISPLAYED	15/06/2023	20/06/2023
R155-0020632	1531	37.18	2042521		SERVICE ON 17244794 ADEL DEPOT 08-05-2023 HUBO 2191533 Pos. Article Description Stock From No. of Caps RTD Case condition Reason for removal Details 05 Runout Tyre 11R22.5 - RTD - 10.0mm RN 10.0 Not Worth Retreading (NWR Sidewall Cut or Staked Qty SERVICES/ACCESSORIES REMARKS / SIZE: 1 EA Tyre Replacement 33000084 - FIT TBR TYRE (Pos: 5) 1 EA Tyre Removed 33000241 - SCRAP TYRES TBR (Pos: 5)	8/05/2023	9/05/2023
R155-0020620	1531	194.40	2042448		REPLACE BENT TURN TABLE HANDLE. USE HANDLE OUT OF 2131D OLD TURN TABLE	6/05/2023	10/05/2023
R155-0020607	1531	1197.57	2042220		SERVICE ON 17227475 ADEL DEPOT 03-05-2023 HUBO 2191100 Pos. Article Description Stock From No. of Caps RTD Case condition Reason for removal Details 11 11003134 - 11R22.5 148/145L BS M749II EC CC 2.0 Retread (recap) Customer Pull Point 12 11003134 - 11R22.5 148/145L BS M749II EC CC 2.0 Retread (recap) Customer Pull Point Qty SERVICES/ACCESSORIES REMARKS / SIZE: 2 EA Tyre Replacement 33000084 - FIT TBR TYRE (Pos: 11, 12) 2 EA Tyre Removed - (Pos: 11, 12) 2 EA	3/05/2023	8/05/2023

R155-0020336	1531	273.60	2037888	REPORTED DE-RATING	11/04/2023	13/04/2023
R155-0020115	1531	452.56	2036079	AIR BAG LEAKING	20/03/2023	21/03/2023
R155-0020029	1531	183.60	2031527	Water on the floor, can't log in	14/03/2023	15/03/2023
R155-0020029	1531			REPORTED UNABLE TO LOG IN	14/03/2023	15/03/2023
R155-0020011	1531	1228.15	2028939	SERVICE ON 17026243 ADEL DEPOT 09-03-2023 HUBO 1 Pos. Article Description Stock From No. of Caps RTD Case condition Reason for removal Details 09 11003134 - 11R22.5 148/145L BS M749II EC CC 1.0 Retread (recap) Customer Pull Point 10 11003134 - 11R22.5 148/145L BS M749II EC CC 0.0 Not Worth Retreading (NWR) Worn Too Far Qty SERVICES/ACCESSORIES REMARKS / SIZE: 2 EA Tyre Replacement 33000084 - FIT TBR TYRE (Pos: 9, 10) 1 EA Tyre Removed 33000241 - SCRAP TYRES TBR (Pos: 10) 1 EA	9/03/2023	10/03/2023
R155-0019995	1531	1518.41	2028073	REPORTED BRAKES NOT STOPPING	8/03/2023	14/03/2023
R155-0019995	1531			REPLACE WORN L/H/R TYRES	8/03/2023	14/03/2023
R155-0019995	1531			HEATER CORE LEAKING	8/03/2023	14/03/2023
R155-0019871	1531	2273.93	2027107	Brakes not pulling up well	25/02/2023	6/03/2023
R155-0019825	1531	1735.46	2026197	Brake pedal is really hard and truck doesn't pull up good	21/02/2023	1/03/2023
R155-0019825	1531			HIT KANGAROO	21/02/2023	1/03/2023
R155-0019810	1531	116.40	2025335	Brakes don't pull up well	20/02/2023	21/02/2023
R155-0019663	1531	21.35	2020479	SUZI COIL LEAKING AIR	3/02/2023	6/02/2023
R155-0019626	1531	(2000.00)	2019536	CORE RETURN	31/01/2023	2/05/2023

R155-0019612	1531	1297.14	2014492	<p>SERVICE ON 16860575 ADEL DEPOT 30-01-2023 HUBO 2168257</p> <p>Pos. Article Description Stock From No. of Caps RTD Case condition Reason for removal Details 01 11006520 - 295/80R22.5 152/148M BS R154 CC 6.0 Retread (recap) Irregular Wear or Alignment 02 11006520 - 295/80R22.5 152/148M BS R154 CC 6.0 Retread (recap) Irregular Wear or Alignment Qty SERVICES/ACCESSORIES REMARKS / SIZE: 2 EA Wheel Balance 33000051 - BALANCE TBR (Pos: 1, 2) 2 EA Tyre Replacement 33000084 - FIT TBR TYRE (Pos: 1, 2) 2 EA</p>	30/01/2023	31/01/2023
R155-0019536	1531	1875.53	2014492	B SERVICE	23/01/2023	30/01/2023
R155-0019473	1531	916.40	2012090	VEHICLE WILL NOT START	18/01/2023	19/01/2023
R155-0019433	1531	354.00	2012090	ENGINE WARNING LIGHT DISPLAYED. PYRO TEMP REPORTED HIGH	16/01/2023	17/01/2023
R155-0019433	1531			REFER SECTION 1	16/01/2023	17/01/2023
R155-0019456	1531	30.80	2012090	<p>SERVICE ON 16779497 ADEL DEPOT 16-01-2023 HUBO 2160817</p> <p>1 EA Flip On Rim 33000540 - FLIP TRUCK TYRE OR RETREAD (Pos: 9) 2 EA Tyre Rotation 33000085 - ROTATE TBR TYRE (Pos: 2-1, 1-2) 4 EA Labour - STANDARD</p>	16/01/2023	20/01/2023
R155-0019342	1531	1062.84	2010736	WARNING LIGHT DISPLAYED ON DASH	6/01/2023	18/01/2023
R155-0019333	1531	468.00	2010696	NO THROTTLE - WILL NOT SELECT GEARS	5/01/2023	6/01/2023
R155-0019264	1531	10.27	2005071	REPORTED CODES 3569 & 3164 CODES DISPLAYED ON DASH	28/12/2022	29/12/2022
R155-0019233	1531	0.00	1999935	Engine light on comes on a little bit after driving	22/12/2022	29/12/2022

R155-0019219	1531	203.31	1999935	REPORTED CHECK ENGINE LIGHT DISPLAYED.	21/12/2022	21/12/2022
R122-0057302	1531	259.39	1999098	THROTTLE VALVE SENT TO ADELAIDE W/SHOP REFER J.R	15/12/2022	15/12/2022
R155-0019142	1531	171.60	1998315	REPORTED STOP ENGINE LIGHT DISPLAYED	14/12/2022	19/12/2022
R155-0019125	1531	39.60	1997506	SERVICE ON 16727653 ADEL DEPOT 12.12.2022 HUBO 1146041 1 EA Tyre Repair 33000096 - PUNCTURE REPAIR TBR (Pos: 11) 3 EA Labour - STANDARD 23000110 - SCHEDULED DEPOT SERVICE 15MIN	12/12/2022	20/12/2022
R155-0019104	1531	7888.32	1997506	VEHICLE OVERHEATING. - BREAKDOWN S.E FREEWAY	10/12/2022	14/12/2022
R155-0019104	1531			REPLACE TURBO	10/12/2022	14/12/2022
R155-0019038	1531	1805.54	1994181	WATER PUMP LEAKING	5/12/2022	13/12/2022
R155-0018968	1531	406.36	1989227	Check engine light is on	26/11/2022	29/11/2022
R155-0018891	1531	339.60	1984119	WARNING LIGHTS DISPLAYED ON DASH	18/11/2022	21/11/2022
R155-0018879	1531	52.76	1983328	Bar under the truck on drivers side is loose ?	17/11/2022	17/11/2022
R155-0018881	1531	80.40	1983328	Vibration through truck at 40-60km/h	17/11/2022	17/11/2022
R155-0018850	1531	0.00	1982495	Mass management sticker needs to be replaced	15/11/2022	30/11/2022
R155-0018850	1531			REFER SECTION 1	15/11/2022	30/11/2022
R155-0018752	1531	99.71	1975907	ELECTRICAL SUZI COIL INOPERATIVE	4/11/2022	7/11/2022
R155-0018702	1531	36.00	1972718	ELECTRICAL SUZI COIL INOPERATIVE	29/10/2022	31/10/2022
R155-0018668	1531	3823.05	1969294	REPLACE KING PINS & BALL JOINTS AS PER QUOTE	26/10/2022	4/11/2022
R155-0018608	1531	804.86	1966818	WILL NOT SELECT GEARS	20/10/2022	31/10/2022
R155-0018608	1531			OIL LEAK AT STEER HUB	20/10/2022	31/10/2022
R155-0018575	1531	579.96	1965135	SEAT BELT INOPERATIVE	17/10/2022	31/10/2022
R155-0018576	1531	464.86	1965135	WHEEL ALIGNMENT	17/10/2022	2/11/2022
R155-0018577	1531	0.00	1965135	Turntable release cable broken, steering vibration between 40km/hr & 50km/hr	17/10/2022	19/10/2022
R155-0018535	1531	0.00	1961647	Vibration through cab at 40-60km/h	12/10/2022	13/10/2022
R155-0018536	1531	1464.82	1961647	Air con is not working correctly and windscreen demister is not working	12/10/2022	13/12/2022
R122-0055493	1531	1546.19	1960647	REPAIR A/C INOPERATIVE	11/10/2022	11/10/2022
R122-0055493	1531			replace 2 torque rod bushes	11/10/2022	11/10/2022
R155-0018446	1531	1376.58	1955069	DRIVER REPORTING VIBRATION WHILE DRIVING AT40-50KPH	30/09/2022	18/10/2022
R155-0018446	1531			Checker plate bolts loose	30/09/2022	18/10/2022
R155-0018446	1531			Fit Coles approved reverse alarm	30/09/2022	18/10/2022
R155-0018446	1531			CLUNKING NOISE COMING FROM FRONT END	30/09/2022	18/10/2022
R155-0018446	1531			LOCKING CABLE BROKEN	30/09/2022	18/10/2022
R155-0018373	1531	1780.06	1950978	B SERVICE	23/09/2022	7/10/2022
R155-0018338	1531	319.17	1947995	MUDGUARD DAMAGED	19/09/2022	20/09/2022

R155-0018204	1531	1272.88	1937901	<p>SERVICE ON 16358106 ADEL DEPOT 02-09-2022 HUBO 1086770</p> <p>01 11006520 - 295/80R22.5 152/148M BS R154 CC 8.0 Runout Held by Customer Match Tread Depth or Pattern</p> <p>02 11006520 - 295/80R22.5 152/148M BS R154 CC 8.0 Not Worth Retreading (NWR Sidewall Cut or Staked Qty SERVICES/ACCESSORIES REMARKS / SIZE: 2 EA Wheel Balance 33000051 - BALANCE TBR (Pos: 1, 2) 2 EA Tyre Replacement 33000084 - FIT TBR TYRE (Pos: 1, 2) 1 EA Tyre Removed 33000370 - TYRE HELD FOR RUNOUT (Pos: 1) 1 EA Tyre Removed 33000241 - SCRAP TYRES TBR (Pos: 2) 4 EA</p>	2/09/2022	8/09/2022
R155-0018133	1531	532.33	1933092	Drivers side seat belt buckle doesn't work	25/08/2022	31/08/2022
R155-0018116	1531	442.97	1932319	Volt meter is not working, plug in is broken ?	24/08/2022	25/08/2022
R155-0018035	1531	160.84	1925780	OIL LEAK FROM VEHICLE	13/08/2022	23/08/2022
R155-0017986	1531	111.00	1922567	Volt meter has stopped working	8/08/2022	9/08/2022
R155-0017934	1531	426.46	1918575	Truck has an oil leak out of pipe	2/08/2022	3/08/2022
R155-0017934	1531			DRIER LEAKING	2/08/2022	3/08/2022
R155-0017887	1531	142.25	1914485	TRAILER NOT LOCKED IN PROPERLY. - CALLBACK. CHECK & REPAIR DAMAGE	27/07/2022	28/07/2022
R155-0017754	1531	102.75	1904826	Volt gauge is not working	12/07/2022	15/07/2022
R155-0017754	1531			VOLT METER INOP.	12/07/2022	15/07/2022
R155-0017754	1531			VOLT METER NOT WORKING	12/07/2022	15/07/2022
R155-0017715	1531	1576.85	1901455	GUARDIAN NOT WORKING	7/07/2022	12/07/2022
R155-0017715	1531			GREASE THRUST BEARING	7/07/2022	12/07/2022
R155-0017705	1531	(407.00)	1899858	CMV CREDIT CAD649 REFER INVOICE 898821 CORE CHARGE (P155-0008846) R155-0017538 DEPOSIT RETURNED	4/07/2022	20/07/2022
R155-0017617	1531	127.00	1892768	Engine warning light was on, abs light was on, volt meter gauge dropped	24/06/2022	27/06/2022
R155-0017582	1531	228.00	1891233	Volt meter is not working, check engine light on, esc light on on, tacho jumping around	21/06/2022	22/06/2022
R155-0017563	1531	1559.11	1890106	B SERVICE	20/06/2022	23/06/2022
R155-0017538	1531	1352.12	1887957	AFTER TREATMENT LIGHT ON	15/06/2022	21/06/2022
R155-0017538	1531			WARNING LIGHT ON DASH	15/06/2022	21/06/2022
R155-0017498	1531	31.20	1884696	ELECTRICAL SUZI COIL INOPERATIVE	9/06/2022	20/06/2022

R155-0017455	1531	1012.80	1881554	ELECTRICAL SUZI COIL INOPERATIVE	3/06/2022	16/06/2022
R155-0017455	1531			L/H FUEL TANK BRACKETS BENT	3/06/2022	16/06/2022
R155-0017170	1531	1130.89	1862572	AIR LEAK FROM VEHICLE	30/04/2022	12/05/2022
R122-0050899	1531	2156.00	1856637	SERVICE ON 1531 SYDN DEPOT 01.04.2022 HUBO 1001695 11002831 - 11R22.5 146/143L BS M766 POS 05-08 33000084 - FIT TBR TYRE (Pos: 5, 6, 7, 8) 77000180 SIZE: CASE STOCK 11-22 5 (Pos: 5, 6, 7, 8)	4/04/2022	7/04/2022
R155-0017003	1531	752.76	1856637	VEHICLE WILL NOT START	4/04/2022	7/04/2022
R140-0096074	1531	1162.75	1854093	VIESA FAULT	30/03/2022	30/03/2022
R140-0095807	1531	2200.00	1848167	SERVICE ON 15783500 BRIS DEPOT 22.03.2022 HUBO 996593 11002831 - 11R22.5 146/143L BS M766 POS 09-12 33000084 - FIT TBR TYRE (Pos: 9, 10, 11, 12) 33000085 - ROTATE TBR TYRE (Pos: 9-5, 10-6, 11-7, 12-8) 77000180 SIZE: CASE STOCK 11-22 5 (Pos: 9, 10, 11, 12)	22/03/2022	25/03/2022
R140-0095704	1531	380.07	1847835	HEADLIGHT PROTECTORS	21/03/2022	21/03/2022
R140-0095733	1531	402.32	1847835	HEADLIGHT INSERTS FITTED	21/03/2022	21/03/2022
R130-0038133	1531	147.48	1839096	REPLACE ONE WAY CHECK VALVE TO STOP WATER LEAKING INTO CABIN FROM VIESSA	8/03/2022	11/03/2022
R130-0038115	1531	0.00	1838318	Left hand spotter mirror is missing Refer to R140-0094938	7/03/2022	7/03/2022
R140-0094938	1531	27.51	1837402	RENEW SPOT MIRROR	5/03/2022	5/03/2022
R140-0094839	1531	62.62	1835539	Left hand step has been damaged can we please fix it	3/03/2022	3/03/2022
R140-0094576	1531	2566.23	1831168	B SERVICE E5 CUMMINS 60,000 KM	24/02/2022	1/03/2022
R140-0094576	1531			RENEW R/H/R & L/H/F SLACK ADJUSTERS	24/02/2022	1/03/2022
R130-0037795	1531	150.00	1829575	CHECKED LIGHTS FOR FAULT + REPAIRED WIRING FOR PARK LIGHTS CNF INDICATORS	22/02/2022	22/02/2022
R140-0094395	1531	26.00	1828905		21/02/2022	21/02/2022
R140-0094331	1531	42.39	1826508	Viesa has come loose and can't turn it on or off, Right hand blinker comes on and goes off by its self	18/02/2022	18/02/2022
R140-0094352	1531	278.34	1826508	FAULT	18/02/2022	19/02/2022
R155-0016516	1531	1.50	1824294	DASH LIGHTS NOT WORKING	15/02/2022	28/02/2022
R140-0093856	1531	17.32	1818907	AFTERTREAT LIGHT ON - NOT USING ADBLUE - AIR LEAK IN THE CAB - WITH THE PARKERS ON AND TRYING TO REVERSE THE DASH LIGHTS GO OUT	8/02/2022	8/02/2022
R156-0015531	1531	20.91	1814214	Re-filled coolant top up bottle.	1/02/2022	1/02/2022
R122-0048277	1531	0.00	1808497	AIR CON NOT WORKING	25/01/2022	25/01/2022
R122-0048091	1531	0.00	1803361	CHECK STEERING WHEEL CONTROLS	18/01/2022	22/01/2022
R122-0048049	1531	323.23	1802998	REPLACE CLOCK SPRING	17/01/2022	21/01/2022
R140-0092593	1531	5725.14	1798636	REPLACE CLUTCH	7/01/2022	12/01/2022
R140-0092612	1531	5.50	1798636	SERVICE ORDER 15543618 BRIS DEPOT 07.01.2022 ODO 946795 Runout Tyre 11R22.5 - RTD - 10.0mm 06 33000084 - FIT TBR TYRE (Pos: 6) 77000180 SIZE: CASE STOCK 11-22 5 (Pos: 6)	7/01/2022	12/01/2022
R140-0092843	1531	(119.88)	1798636	CLAIM 01688 WARRANTY CLAIM TMN70ZZ x 1	6/01/2022	7/04/2022

R155-0016159	1531	1163.25	1797767	SERVICE ORDER 15539225 ADEL DEPOT 06.01.2021 HUBO 944743 11004496 - 295/80R22.5 152/148M BS R154 01-02 33000051 - BALANCE TBR (Pos: 1, 2) 33000084 - FIT TBR TYRE (Pos: 1, 2) 33000370 - TYRE HELD FOR RUNOUT (Pos: 1) 33000118 - SCHEDULED DEPOT SERVICE 15MIN 33000104 - TYRE CASE STOCK 295/80R22.5 (Pos: 2) NO DRIVE WHEN GEAR SELECTED	6/01/2022	11/01/2022
R155-0016152	1531	1474.95	1797007	REPLACE STEER TYRES	5/01/2022	31/01/2022
R155-0016152	1531			REPLACE STEER TYRES	5/01/2022	31/01/2022
R130-0036584	1531	1974.66	1796633	CHECK GEARBOX FOR FAULT CHECK WIRING REPLACE ECA ROAD TEST AFTER NEW ECA FITTED	4/01/2022	5/01/2022
R140-0092718	1531	(359.64)	1788759	CLAIM 01683 WARRANTY CLAIMS TMN70ZZ x 4 TM 680CCA 170RC	23/12/2021	7/04/2022
R140-0092174	1531	407.53	1787143	Air con is blowing hot air	22/12/2021	23/12/2021
R140-0092174	1531			RENEW CRACKED WINDSCREEN	22/12/2021	23/12/2021
R140-0091991	1531	930.95	1782593	REPLACE R/H WINDOW REG	16/12/2021	17/12/2021
R140-0091745	1531	722.74	1778432	NEEDS SHOCK RUBBERS ?	10/12/2021	10/12/2021
R140-0091745	1531			RENEW FAILED BATTS	10/12/2021	10/12/2021
R140-0091738	1531	13.78	1777653	Hit pot hole and lost steer hub cap	9/12/2021	9/12/2021
R155-0015957	1531	548.24	1775871	REAR BRAKE SHOES WORN, NEED REPLACEMENT	7/12/2021	7/12/2021
R155-0015957	1531			REPLACE REAR STABILIZER BUSHES	7/12/2021	7/12/2021
R155-0015928	1531	1622.72	1772219	B SERVICE	2/12/2021	30/12/2021
R155-0015928	1531			REPLACE SD CARD	2/12/2021	30/12/2021
R155-0015892	1531	567.22	1772219	L/H CAB AIR BAG LEAKING	27/11/2021	30/11/2021
R155-0015892	1531			Rear cab shockies leaking - replace	27/11/2021	30/11/2021
R140-0091152	1531	33.00	1772219	SERVICE ORDER 15404214 BRIS DEPOT 25.11.2021 ODO 913915 Runout Tyre 295/80R22.5 - RTD - 11.0mm 01 33000051 - BALANCE TBR (Pos: 1) 33000084 - FIT TBR TYRE (Pos: 1) 33000370 - TYRE HELD FOR RUNOUT (Pos: 1) LIGHT REPAIRS	25/11/2021	26/11/2021
R140-0091048	1531	5.24	1772219	LIGHT REPAIRS	23/11/2021	23/11/2021
R122-0046108	1531	0.00	1772219	dash lights out	18/11/2021	19/11/2021
R122-0046046	1531	145.98	1772219	adblue cap missing	17/11/2021	18/11/2021

R142-0004826	1531	1317.35	1772219	16.11.21 PROFORMA : 73765-## \$1317.35 INC. GST REPAIR JACKSHAFT AND BROKEN SUSPENION REMOVE BROKEN JACK SHAFT, CUT OFF CONNECTING BOLTS AS ALL WERE DAMAGED. REMOVE SHAFT YOKE ON FRONT DRIVE, REMOVE SEAL, CLEAN AND REPLACE SEAL. REFIT YOKE WITH NEW WASHER AND LOCK NUT. REMOVE TOP BROKEN SUSPENSION ARM. REPLACE WITH NEW, FIT NEW BOLTS ALSO. BACK OFF L/H REAR BRAKE, REMOVE WHEEL AND HUB ASSEMBLY. REMOVE ALL BRAKE PARTS, CLEAN AND INSPECT WHEEL BEARINGS. REPLACE WHEEL BEARING, REPACK HUB BEARING GREASE, REPLACE BRAKE SHOES AND BOLT ON RETAINERS. REASSEMBLE, ADJUST BEARING PRE LOAD, ADJUST BRAKES. REFIT WHEEL. CHECK DIFF OIL LEVEL, CLEAN OUT DIFF BREATHER. BOLT ON ROLLER RETAINER [WT3417] 1.00 3.97 SET CUP-CONE 594A/592A [SET403] 1.00 61.25 SET CUP-CONE 580/572 [SET401] 1.00 55.85 QPLUS SHOE SET DRIVE [KSMA2124707QP] 1.00 100.52 DRIVE SEAL HI-TEMP - ALT 476 [47697] 1.00 29.13 DRIVE AXLE LOCK WASKER KIT B [1229F4634S] 1.00 18.41 NUTS BOLTS WASHERS [53230] 18.45 WORKSHOP SUPPLIES 30.00 Labour 880.00 Parts 269.13 Products 30.00 Sublet 18.45 Other GST 110.77	16/11/2021	18/11/2021
R140-0090720	1531	410.63	1772219	NO FAN FOR THE AIR CON	15/11/2021	18/11/2021
R140-0090666	1531	258.47	1772219	Cruise control on/off switch works only sometimes	11/11/2021	12/11/2021
R130-0035498	1531	114.00	1772219	ROAD TEST FOR CRUISE CONTROL (CNF)	9/11/2021	10/11/2021
R130-0035393	1531	135.31	1772219	replace suzi coils	3/11/2021	3/11/2021
R130-0035376	1531	107.47	1772219	REPLACE FITTING REPAIR SPARE SUZI LIGHTING SYSTEM	1/11/2021	3/11/2021
R130-0035376	1531				1/11/2021	3/11/2021
R120-0035808	1531	2304.15	1772219	SEND PARTS TO INNISFAIL FOR TRUCK REPAIR - JACKSFAT AND SEAL PARTS	22/10/2021	29/10/2021
R142-0004789	1531	880.00	1772219	TRAVEL TO LINDSAY BROTHERS TRANSPORT - ZILKE AVE, BUNDABERG. TRANSPORT KENWORTH PRIME MOVER (XN51BF / UNIT 1813) TO BRUCE HIGHWAY, DAMASCUS , VIA BUNDY STAR TO PUT AIR IN TYRES THEN TO SWAP OUT WITH BROKEN	22/10/2021	26/10/2021
R142-0004790	1531	880.00	1772219	DOWN UNIT. 4 HOURS @ \$200 +GST 22.10.21 TW0368169A \$800.00 PLUS GST TRAVEL TO BRUCE HIGHWAY, DAMASCUS WITH REPLACEMENT PRIME MOVER. TRANSPORT KENWORTH PRIME MOVER (574VOT / UNIT 1531) TO BUNDY STAR TRUCK & MACHINERY - PRINCESS ST, BUNDABERG EAST. 4 HOURS @ \$200 +GST	22/10/2021	26/10/2021
R156-0014472	1531	21.80	1770966	Topped up oil bottle.	19/10/2021	19/10/2021
R122-0044656	1531	29.95	1764688	FIT SD CARD	11/10/2021	13/10/2021
R140-0088736	1531	231.33	1764686	VIESA REPAIRS	23/09/2021	23/09/2021
R130-0034287	1531	14.77	1764686	POWER STEERING FLUID LOW TOP UPPOWER STEERING	6/09/2021	6/09/2021
R140-0087740	1531	2574.92	1764686		31/08/2021	24/09/2021
R140-0087740	1531			CARRY OUT C SERVICE AS PER SERVICE SHEET.	31/08/2021	24/09/2021
R140-0087740	1531			AFTERTREATMENT LIGHT ON	31/08/2021	24/09/2021

R140-0087767	1531	1163.25	1764686	SERVICE ORDER 14917344 BRIS DEPOT 31.08.20221 ODO 854066 11004496 - 295/80R22.5 152/148M BS R154 01-02 33000051 - BALANCE TBR (Pos: 1, 2) 33000084 - FIT TBR TYRE (Pos: 1, 2) 77000194 SIZE: CASE STOCK 295/80-22.5 (Pos: 1, 2)	31/08/2021	2/09/2021
R140-0087216	1531	16.18	1764686	Supply purple metal polish	17/08/2021	17/08/2021
R122-0042804	1531	0.00	1764686	GI light is on the gearbox	11/08/2021	12/08/2021
R155-0014925	1531	116.25	1764686	DRIVER REPORTS NO LIGHTS - CALL BACK	22/07/2021	23/07/2021
R130-0034062	1531	(825.00)	1764676	REFER INVOICE 1011416 (P130-0019975) R130-0032315 RETURN CORE CHARGE 10CS0025CORE x 1	14/07/2021	26/08/2021
R140-0085632	1531	0.00	1764676	3 Trailer abs light is on with every set of trailers	10/07/2021	10/07/2021
R155-0014828	1531	0.00	1764676	Grinding noise coming from the gearbox area	8/07/2021	9/07/2021
R155-0014829	1531	4730.22	1764676	Bad noise in front of engine / gear housing Cause: Vibration dampener out of spec Correction: CSS-00175744 1,823,763 km JSA, LOTO, removed gear train, inspected, found no problems, removed vibration damper, found vibration damper to have excessive bowing and has signs of hitting front gear cover bolts. Measured gear train, all in specification, performed base engine timing, fitted front cover, torqued down rocker levers. Performed tune up, fitted fan, intake trunking, coolant hoses, rocker cover, air filter, primed truck. Started truck and confirm repair. Steam clean engine and road test Clear inactive fault codes, pack up job and complete paperwork. Release vehicle back into service	8/07/2021	9/08/2021
				Description Operation Unit price Qty Extension		
				Labour		
				3285 159.00 10.00 1590.00		
				LABOUR TOTAL 1590.00		
				Material		
				4374074 SCREW, TWELVE POINT CAP 6.01 6 36.06		
				3687007 SEAL,RECTANGULAR STRIP 65.50 1 65.50		
				3685915 BEARING THRUST 158.79 1 158.79		
				3690868 DAMPER, VIBRTN VSCS ~485- 2414.85 1 2414.85		
				Miscellaneous		
				Environmental Levy 25.00 1 25.00		
				Consumables 10.00 10.00		
				MISC TOTAL 35.00		
				SUB-TOTAL 4300.20		
				G.S.T 430.02		
R140-0085364	1531	127.00	1764676	RENEW FAILED EBS LEAD	5/07/2021	5/07/2021
R155-0014765	1531	0.00	1764676	R/H INDICATOR NOT WORKING	1/07/2021	1/07/2021
R140-0085026	1531	258.95	1764676	HIGH BEAM TELL TAIL LIGHT ON THE DASH ISNT WORKING	28/06/2021	29/06/2021
R140-0085026	1531			Rear air tank strap broken	28/06/2021	29/06/2021
R130-0032840	1531	0.00	1761533	MODULATION VALVE WASN'T BOOKED REF R130-0032315	16/06/2021	16/06/2021
R130-0032752	1531	84.00	1757170	GLASS RE SECURE WEATHER SHIELD	10/06/2021	12/06/2021

R130-0032757	1531	75.00	1757170	L/H WINDOW HITTING THE SIDE OF THE CAB RESECURED LH WIPER ARM + REPAIRED VOLT GAUGE FUSE	10/06/2021	12/06/2021
R140-0084046	1531	4.74	1755328	VOLT GAUGE NOT WORKING - L/H HIGH BEAM NOT WORKING	7/06/2021	7/06/2021
R140-0083896	1531	0.00	1751290	GUARDIAN NOT COMMUNICATING	2/06/2021	3/06/2021
R130-0032486	1531	883.75	1744895	B SERVICE E5 CUMMINS COMPLETED SERVICE REPLACED SUNVISOR CLIP REPLACED FUSE FOR VOLTMETRE REPAIR ALTERNATOR WIRING REPLACED 2 BOOST HOSES REPLACED BOOST CLAMP	26/05/2021	31/05/2021
R130-0032514	1531	0.00	1744634	Sun visor hinge is broken, volt meter gauge is not working REPLACED VISOR CLIP REPLACED VOLT GAUGE FUSE	26/05/2021	27/05/2021
R130-0032315	1531	10078.32	1739185	REAR BRAKES & DRUMS REPLACE LF BOOSTER AND REPLACED BUSH FOR SLACK ADJUSTER REPLACED LR BRAKE SHOES	17/05/2021	25/05/2021
R130-0032315	1531			DIFFERENTIAL CARRIER CLEAN FRONT DIFF RE SEAL FRONT DIFF RE SEAL FRONT DIFF BEARING COVER REPLACED AXLE GASKETS ON FRONT DIFF	17/05/2021	25/05/2021
R130-0032315	1531			LIGHTING SYSTEM REPLACED REVERSE BUZZER REPLACED LOAD LIGHT	17/05/2021	25/05/2021
R130-0032315	1531			AIR RIDE SUSPENSION REPLACED HEIGHT CONTROL VALVES ADJUSTED RIDE RIDE REPLACED BRITTLE AIR HOSE	17/05/2021	25/05/2021
R130-0032315	1531			HEATING & VENTILATING REPLACED EXHAUST GASKET	17/05/2021	25/05/2021
R130-0032315	1531			BRAKE LINES & FITTINGS - HYDRAULIC & AIR REPLACED FITTINGS ON FRONT BRAKE MODULATOR VALE REPLACED SPRING BREAK VALVE REPLACED RF DRIVE SLACK ADJUSTER	17/05/2021	25/05/2021
R130-0032315	1531			POWER STEERING PUMP REPLACE POWER STEERING GASKET	17/05/2021	25/05/2021
R130-0032315	1531			FENDERS & MUD FLAPS - FRONT WHEEL REPLACED RR MUD GUARD	17/05/2021	25/05/2021
R130-0032315	1531			DROP OFF & PICKUP TRUCK FOR ROADWORTHY @ WERRIBEE SOUTH	17/05/2021	25/05/2021
R130-0032315	1531			BULBS, FUSES & WIRING - CLEARANCE / MARKER / INTERIOR LAMPS ADD REFLECTORS REAPLCE MIRROR LIGHT	17/05/2021	25/05/2021
R130-0032315	1531			GLASS	17/05/2021	25/05/2021
R130-0032315	1531			STEERING REPLACE STEER UNIS REMOVE STEER COLUMN REPALCED LHS TYE ROD END AND REPLACED DRIVERS SEAT	17/05/2021	25/05/2021
R130-0032315	1531			GUARDIAN SYSTEMS SECURE FFC TO WINDSCREEN REPLACE COMPLETE SEAT	17/05/2021	25/05/2021
R130-0032361	1531	2101.00	1739185	SERVICE ORDER 14606941 MELB DEPOT 17.05.2021 ODO 984788 11001472 - 11R22.5 148/145L BS M749 09-12 33000084 - FIT TBR TYRE (Pos: 9, 10, 11, 12) 33000370 - TYRE HELD FOR RUNOUT (Pos: 9, 10) 77000222 SIZE: CASE STOCK 11R22.5 SCORIA (Pos: 11, 12)	17/05/2021	18/05/2021

R130-0032475	1531	825.00	1744316	APPROVED BH 25.5.21 KLMS: 785,012 Truck was presented for a full roadworthy inspection, failed first test due to right hand side mirror light, left hand side tie rod end, all steering unis, amber reflector rear clearance lights, window tint, seat to be rebushed, steering wheel and column loose, right side tank side of bumper front, passed second test, all OK. SECOND INSPECTION: \$150.00 MECHANIC: Tom VIN NO: 6F5000000FA454736 ENGINE NO: 79826733 ROADWORTHY NO: 178434	17/05/2021	25/05/2021
R130-0032336	1531	0.00	1739185	left hand driving light in bumper is faulty, heated mirror on the right hand side isn't working	14/05/2021	14/05/2021
R130-0032407	1531	550.00	1739185	APPROVED BH 20.5.21 KW1647 - SUPPLY & INSTALL FR WINDSCREEN - KENWORTH 1/2 SCREEN LH T604/T904 (06/14 - ONWARDS) 1.00 250.00 10% 250.00 KW1648 - SUPPLY & INSTALL FR WINDSCREEN - KENWORTH 1/2 SCREEN RH T604/T904 (06/14 - ONWARDS) 1.00 250.00 10% 250.00 Subtotal 500.00 Total GST 10% 50.00 Invoice Total 550.00 Total Payments 0.00	14/05/2021	20/05/2021
R140-0082428	1531			Tails haft uni's are still originals replace next service	28/04/2021	
R140-0082428	1531			R.H.R drive auto slack adjuster not latching	28/04/2021	
R140-0082238	1531	33.46	1724539	R.H dash vent broken	22/04/2021	22/04/2021
R155-0014109	1531	0.00	1717762	REFIL COOLANT CONTAINER FOR TRUCK	14/04/2021	21/04/2021
R122-0038122	1531	55.00	1706729	SERVICE ORDER 14418936 SYDN DEPOT 29.03.2021 ODO 752288	29/03/2021	1/04/2021
R122-0038064	1531	0.00	1704690	33000051 - BALANCE TBR (Pos: 1, 2) RIDE HEIGHT ARM BROKEN - ROTATE STEER TYRES	26/03/2021	30/03/2021
R122-0037998	1531	195.80	1702681	SERVICE ORDER 14398975 SYDN DEPOT 24.03.2021 HUBO 748414 33000085 - ROTATE TBR TYRE (Pos: 2-1, 1-2, 12-5, 11-6, 10-7, 9-8, 8-9, 7-10, 6-11, 5-12) 33000051 - BALANCE TBR (Pos: 1, 2) 33000540 - FIT TRUCK TYRE OR RETREAD (Pos: 1, 2)	24/03/2021	25/03/2021
R140-0080531	1531	53.36	1697188	NEEDS NEW WIPER ARM - WIPERS BANGING ON WINDSCREEN AND NOT WIPING CORRECTLY	18/03/2021	18/03/2021
R130-0031468	1531	0.00	1694617	Auto greaser is leaking	15/03/2021	15/03/2021
R140-0080108	1531	135.01	1690074	REPLACE WIPER ASSY	10/03/2021	13/03/2021
R140-0079763	1531	2090.00	1684083	SERVICE ORDER 14303969 BRIS DEPOT 02.03.2021 ODO 729459 11001472 - 11R22.5 148/145L BS M749V 09-12 33000084 - FIT TBR TYRE (Pos: 9, 10, 11, 12) 33000085 - ROTATE TBR TYRE (Pos: 9-5, 10-6, 11-7, 12-8) 77000222 FITS CASE STOCK 11R22.5 ESCORIA (Pos: 9, 10, 11, 12) B-SERVICE E5 CUMMINS	2/03/2021	4/03/2021
R122-0037334	1531	1007.03	1683160	RELINER FRONT DRIVE AXLE BRAKES	27/02/2021	1/03/2021
R122-0037334	1531			RELINER FRONT DRIVE AXLE BRAKES	27/02/2021	1/03/2021
R140-0078494	1531	0.00	1670210	HIGH TRAILER AIR HOBBS SWITCH REPLACED	10/02/2021	10/02/2021
R140-0078385	1531	2218.34	1669778	REPLACE LEAKING AIRBAG	9/02/2021	10/02/2021

R140-0078385	1531				REPLACE GOV VALVE LINES & HOTLINE	9/02/2021	10/02/2021
R140-0078385	1531				Driver reported no lights on trailer	9/02/2021	10/02/2021
R140-0078296	1531	57.75	1668043		VOLTMETER NOT WORKING	6/02/2021	6/02/2021
R155-0013497	1531	106.13	1665525		EXHAUST FLEX FALLEN OFF	4/02/2021	10/02/2021
R130-0030373	1531	91.48	1650183		TRUCK SUZIE COILS BROKEN REPLACED SUZIE COILS WITH NEW	11/01/2021	14/01/2021
R155-0013263	1531	(253.59)	1645198			5/01/2021	7/01/2021
R155-0013228	1531	255.29	1644032		DRIVER REPORTS SLUGGISH TO START	4/01/2021	5/01/2021
R140-0076343	1531	56.48	1631231		TURNTABLE PAD PEELED OFF	17/12/2020	17/12/2020
R130-0029884	1531	1320.52	1623745		Exhaust is leaking, High beam drivers side out, Grill is loose	8/12/2020	11/12/2020
R130-0029884	1531				GENERATOR/ALTERNATOR	8/12/2020	11/12/2020
R122-0035055	1531	1201.75	1623745		B-SERVICE E5 CUMMINS	7/12/2020	8/12/2020
R122-0035055	1531				exhaust gasket replaced	7/12/2020	8/12/2020
R122-0035055	1531				gearbox reverse light switch replaced	7/12/2020	8/12/2020
R122-0035055	1531				torque rod bushes replaced	7/12/2020	8/12/2020
R122-0035071	1531	1056.00	1623293		SERVICE ORDER 13991569 SYDN DEPOT 07.12.2020 ODO 667923 11001553 - 295/80R22.5 152/148M BS R150 POS 1-2 33000051 - BALANCE TBR - POS 1-2 33000084 - FIT TBR TYRE POS 1-2 33000370 - TYRE HELD FOR RUNOUT POS 1-2 77000194 SIZE: CASE STOCK 295/80-22.5 pYRO FLICKERING	7/12/2020	9/12/2020
R140-0075574	1531	131.25	1618471			30/11/2020	1/12/2020
R130-0029594	1531	15.28	1610753		FRONT STEER AXLE WHEEL END COMPONENTS	20/11/2020	23/11/2020
R122-0034617	1531	77.00	1609143		SERVICE ORDER 13907647 SYDN DEPOT 17.11.2020 ODO 653742 33000051 - BALANCE TBR 1-2 33000085 - ROTATE TBR TYRE - POS 1-2	17/11/2020	18/11/2020
R140-0074782	1531	72.99	1600054		Check engine light stuck on	6/11/2020	7/11/2020
R130-0029259	1531	195.00	1598783		GAUGES & WARNING DEVICES	2/11/2020	5/11/2020
R130-0028712	1531	310.06	1572425		FUEL GUAGE NOT READING RIGHT	28/09/2020	29/09/2020
R140-0073396	1531	0.00	1569810		Remove and replace UHF hand piece (hand piece was supplied by driver)	24/09/2020	25/09/2020
R140-0073300	1531	85.80	1567985		SERVICE ORDER 13664112 BRIS DEPOT 21.09.2020 ODO 611565 33000051 - BALANCE TBR 1-2 33000540 - FLIP TRUCK TYRE OR RETREAD	22/09/2020	23/09/2020
R140-0073227	1531	1070.32	1567985	12579.00	Due for service, coolant in the cab, passenger high beam is out	21/09/2020	22/09/2020
R140-0073227	1531					21/09/2020	22/09/2020
R130-0028376	1531	588.83	1557485		approved ML 07.09.20 repair order: 5168111 SERVICE CALLOUT TRAVEL TO SITE OF BREAKDOWN AND THEN TO COLLECT REQUIRED PARTS. \b \$127.50 \b0 TRANSMISSION TRUCK IS STUCK IN GEAR AT DOCK WOOLWORTHS WODONGA. TRAVEL TO TRUCK AND CONNECT LAPTOP, FOLLOW TROUBLESHOOT AND REPAIR \b \$382.50 \b0 Connected laptop and found code for ECA fault. Disconnected batteries and allowed truck to power down. Reconnected batteries and found still not selecting a gear, removed clutch inspection plate to inspect for broken springs or dry components, found all ok. Advised customer of failed ECA and customer to source. Fitted new ECA and secured, checked and all ok. \b \$10.00 \$15.30 \b0 Miscellaneous Charges Diagnostic fee Workshop Consumables Advisor: Dave Hansen \b Direct Deposit: \fs18 Sub Total for All: Rounding: GST: Total: \b0 \$0.00 \$53.53 \$588.83 \fs16 Bank: Bendigo Bank Branch: BSB: 633000 Account No.: 135823573 Account Name: Twin City Truck Centre Pty Ltd \fs18 \$ \cf1\fs16	8/09/2020	8/09/2020
R130-0028400	1531	396.00	1557485		APPROVED BH 8.9.20 \b\fs18 Towed From: \b0 WESTERN RING ROAD LAVERTON TO \fs24 \fs18 LINDSAY TRANSPORT VELLA DRIVE SUNSHINE WEST\fs24 \f2\fs16	8/09/2020	9/09/2020
R130-0028361	1531	1515.48	1557286		COLLECTED FROM DAIMLER A;BURY BREAKDOWN WOOLIES	7/09/2020	25/09/2020
R140-0072651	1531	136.50	1555437		ADJUST DRIVE MUD GUARDS	4/09/2020	4/09/2020
R140-0072664	1531	2200.00	1555437		SERVICE ORDERR 13589596 BRIS DEPOT 04.09.2020 ODO 599911 11001472 - 11R22.5 148/145L 16 BS M749 - POS 33000084 - FIT TBR TYRE - POS 33000370 - TYRE HELD FOR RUNOUT POS 33000085 - ROTATE TBR TYRE - POS	4/09/2020	7/09/2020

R130-0028233	1531	555.50	1548791		SERVICE ORDER 13552624 MELB DEPOT 27.08.2020 ODO N/A 11001472 - 11R22.5 148/145L 16 BS M749 - POS 10 33000084 - FIT TBR TYRE - POS 10 33000241 - SCRAP TYRES TBR - POS 10 CHECK AC	27/08/2020	28/08/2020
R130-0028188	1531	3827.69	1548771		REPAIR ACCIDENT DAMAGE	26/08/2020	31/08/2020
R130-0028188	1531				ABS LIGHT ON	26/08/2020	31/08/2020
R140-0072174	1531	11.25	1547042		ESC - ABS - GEARBOX LIGHTS COMIG ON	24/08/2020	24/08/2020
R130-0028064	1531	(44.00)	1542217		SERVICE ORDER 13511274 MELB DEPOT 18.08.2020 ODO 583744 RUNOUT TYRE 0.0MM - 5-6 33000084 - FIT TBR TYRE - POS 77000180 SIZE: CASE STOCK 11-22.5 - POS	18/08/2020	19/08/2020
R130-0027993	1531	1073.01	1539440		ESC LIGHT COMING ON - GEARBOX WARNING LIGHT FLASHING	14/08/2020	15/08/2020
R130-0027993	1531				DIFFERENTIAL CARRIER	14/08/2020	15/08/2020
R155-0012092	1531	144.00	1538790		DRIVER REPORTS WARNING LIGHT DISPLAYED ON DASH	13/08/2020	19/08/2020
R130-0027776	1531	549.92	1531006		REPLACE DAMAGED GUARD - CHECK TURNTABLE	3/08/2020	3/08/2020
R130-0027776	1531				REPLACE JAWS	3/08/2020	3/08/2020
R140-0071392	1531	16.10	1527600			29/07/2020	29/07/2020
R130-0027332	1531	60.00	1512879		CHECK PYRO	7/07/2020	7/07/2020
R122-0031778	1531	112.50	1507409		CHECK PRYO - NOT WORKING	1/07/2020	1/07/2020
R130-0027199	1531	2202.35	1506785	11796.00	RESECURE WIRING	26/06/2020	1/07/2020
R130-0027199	1531				DUE FOR A SERVICE	26/06/2020	1/07/2020
R130-0027199	1531				DIFF OIL AND FILTER CHANGE	26/06/2020	1/07/2020
R130-0027199	1531				GEARBOX OIL AND FILTER CHANGE	26/06/2020	1/07/2020
R130-0027068	1531	94.72	1498498		gearbox is showing GI light gearbox is showing GI light	19/06/2020	20/06/2020
R122-0030623	1531	269.64	1470704		CHECK ENGINE LIGHT ON\lang1033 REPLACE OIL PRESSURE SENDER UNIT \f0	11/05/2020	12/05/2020
R122-0030644	1531	1001.00	1470704		SERVICE ON 13101157 SYDN DEPOT 11.05.2020 ODO 514366 POS 1-2	11/05/2020	13/05/2020
R130-0026142	1531	651.37	1465793		WONT START	5/05/2020	7/05/2020
R130-0026009	1531	134.41	1461335		REPLACE WIPER BLADES	29/04/2020	29/04/2020
R122-0030326	1531	203.13	1460371		A/C is not working, passenger wiper needs replacing	27/04/2020	30/04/2020
R122-0030084	1531	1601.54	1451215		REPLACE CLUTCH ECA UNIT + WIRING HARNESS	15/04/2020	17/04/2020
R130-0025638	1531	1319.81	1447412	11047.00	B-Service	7/04/2020	9/04/2020
R130-0025559	1531	38.65	1443016		TOP UP AND COOLANT OIL BOTTLES	2/04/2020	2/04/2020
R155-0011051	1531	23.28	1443016		REPLACE MISSING HUBCAP	2/04/2020	6/04/2020
R130-0025434	1531	350.17	1437349		change oil drain gasket	25/03/2020	31/03/2020
R130-0025434	1531				REPLACE WIPER BLADES	25/03/2020	31/03/2020
R140-0066325	1531	2046.00	1434451		SERVICE ORDER 12766446 BRISBANE DEPOT 20.03.2020 ODO 477671 POS 9-12	20/03/2020	23/03/2020
R140-0065398	1531	(301.08)	1415902		RO RAISED TO REMOVE PART FROM TRUCK AS RETURNED NOT REQUIRED REFER P140-0038275 & R140-0064903	26/02/2020	26/02/2020
R140-0065273	1531	6.00	1414353		INSPECT LIGHTS AND OPERATION	24/02/2020	24/02/2020
R140-0065311	1531	5.43	1414353		DOME LIGHT INOP	24/02/2020	26/02/2020
R140-0064903	1531	2250.13	1406717		stuck in 18th gear	14/02/2020	17/02/2020
R130-0024653	1531	37.50	1401676		CHECK TURNTABLE	7/02/2020	7/02/2020
R130-0024492	1531	213.75	1394439		Shudder in the truck, pulls to the right badly under breaking	30/01/2020	5/02/2020
R130-0024492	1531				TURNTABLE DAMAGED - HAVE TO HIT THE TURNTABLE TO LOCK IN	30/01/2020	5/02/2020
R130-0024337	1531	1735.89	1387193	10273.00	complete b service	20/01/2020	21/01/2020
R130-0024089	1531	308.46	1378345		replace driver seat belt	6/01/2020	8/01/2020
R130-0023983	1531	430.06	1375394		inspect steer	28/12/2019	4/01/2020
R155-0009913	1531	1078.00	1352513		2 X 11R22.5 M749 POSITION 7,8 2 X FIT 3 X CALLOUT FTSD-12578534	26/11/2019	28/11/2019
R155-0009898	1531	318.62	1352163		RE-WIRE TRAILER PLUG - LEAK IN FRONT AIR BAG	25/11/2019	26/11/2019
R155-0009898	1531				FRONT AIR BAG LEAKING	25/11/2019	26/11/2019

R140-0061791	1531	11775.64	1350452		APPROVED BH 21.11.19 CODE: 045 GEAR HOUSING LEAKING OIOL, FUEL GEAR PUMP ;LEAKING FROM INTERNAL SEAL, OIL PUMP DUE FOR RENEWAL, INTAKE ROCKER GALLED-STRIP ENGINE AND INSPECT, REMOVE FULE PUMP HEAD AND INSPECT-OVERHAUL ENGINE REGO: 574VOT, KLMS: 1386996, HRS: 18467	21/11/2019	22/11/2019
R130-0023194	1531	968.00	1342947		2 X 11R22.5 M749 POSITION 5,6 2 X FIT 2 X TRADES FTSD-12516912	7/11/2019	7/11/2019
R122-0027102	1531	78.75	1342024		CANT ADJUST THE BACK OF THE SEAT	5/11/2019	6/11/2019
R155-0009744	1531	114.00	1340436		CHANGE OVER FLAT TYRES	3/11/2019	5/11/2019
R140-0061040	1531	1280.38	1338335		LIGHT IN BALLBAR LHS BROKEN FORM KNAGAROO	31/10/2019	31/10/2019
R140-0061040	1531				RENEW R/H/R HUB SEAL	31/10/2019	31/10/2019
R130-0022964	1531	54.00	1331989		AIR TANK VALVE RELEASE - CANT REALEASE	22/10/2019	23/10/2019
R130-0022804	1531	1617.85	1326671	9459.00	PM for 000-002 Last Done: 20/07/2019 Interval: 60000 Utilization: 58910 PYRO FAULT	14/10/2019	21/10/2019
R140-0060288	1531	199.10	1324655			11/10/2019	11/10/2019
R140-0060342	1531	38.60	1324655			11/10/2019	12/10/2019
R140-0060342	1531					11/10/2019	12/10/2019
R130-0022677	1531	904.50	1319287		LEAKY AIR BAG	4/10/2019	7/10/2019
R120-0026890	1531	497.20	1305782		APPROVED BH 17.9.19 CODE: 045 \cf0\fs18 Vehicle Details Order No: Rego No: 574-VOT Make: Model: T409 Unit No: 1531 Truck VIN No: 454736 Odometer: 345179 DOM: 07/15 Engine No: Work Carried Out: 11/09/2019 \$ \$ Repairs / Services Required - Travel to Spire View. Replace boost hose and clamp. Tension all clamps. Start up and follow truck up hill. All ok. Return to workshop. \$ \$ Labour 1.50 \$120.00 \$180.00 Parts - CTR 4 x 4 x 6" Long hump Hose 1.00 \$69.00 \$69.00 Parts - CTR 4" Intercooler Clamp 1.00 \$23.00 \$23.00 Travelling (per km) 120.00 \$1.50 \$180.00 Subtotal \$452.00 Total GST 10% \$45.20 Invoice Total AUD \$497.20 \b\ f2	17/09/2019	17/09/2019
R140-0059273	1531	179.73	1303262		TRAILER ABS BULB	12/09/2019	12/09/2019
R122-0026012	1531	626.26	1301375		DRIVE SEAL LEAKING	9/09/2019	10/09/2019
R130-0022188	1531	0.00	1299265		UHF ISSUES - NO RANGE	5/09/2019	6/09/2019
R122-0025741	1531	755.03	1291402		REPLACE WORN OUT INDICATOR STALK	24/08/2019	26/08/2019
R122-0025741	1531				WATER IN FUEL LIGHT ON	24/08/2019	26/08/2019
R130-0021749	1531	438.51	1277983		AFTERTREATMENT LIGHT ON	5/08/2019	7/08/2019
R130-0021749	1531				PARK BRAKE LIGHT N/W	5/08/2019	7/08/2019
R122-0025311	1531	129.95	1274944		FUEL GUAGE NOT READING CORRECTLY REPLACE SENDER UNIT	1/08/2019	1/08/2019
R130-0021617	1531	471.54	1269692		CHECK CB/UHF	25/07/2019	26/07/2019
R130-0021617	1531				REPLACE STEREO	25/07/2019	26/07/2019
R130-0021539	1531	45.43	1267518		CHECK STEREO	22/07/2019	23/07/2019
R130-0021539	1531				CHECK VISOR	22/07/2019	23/07/2019
R130-0021525	1531	637.04	1267517	8681.00	PM for 000-002 Last Done: 8/04/2019 Interval: 60000 Utilization: 60892	20/07/2019	22/07/2019
R120-0026031	1531	88.00	1266091		SIGNWRITING NOT CHARGED OUT ON ORIGINAL JOB. REFER - R120-0025219	19/07/2019	20/07/2019
R130-0021482	1531	37.02	1264366		check dash for light out	17/07/2019	18/07/2019
R130-0021427	1531	57.75	1263317		CHECK DASH LIGHTS	15/07/2019	16/07/2019
R130-0021397	1531	550.00	1261618		11.7.19 1531 INSTALLATION OF GUARDIAN SERIAL NO \cf0\fs22 P1001229-S00014113 \cf1\lang1033\fs16 SIM \cf0\fs22 8200 0451 5586 6N \cf1\fs16	12/07/2019	17/07/2019
R130-0021181	1531	293.75	1258184		TABLET WONT POWER UP / OVERSPEED BUZZER N/W \f0	1/07/2019	2/07/2019
R130-0021027	1531	68.39	1252938		check coolant level	24/06/2019	27/06/2019
R130-0021027	1531				HOSE - COOLANT, AUXILIARY HEATER	24/06/2019	27/06/2019
R130-0020623	1531	1100.06	1235329		ENIGNE NOISE - HOWLING OR LOOSE SOUND - RATTLING	27/05/2019	29/05/2019

R130-0020623	1531				HEATER HOSE LEAKING - FILLED WITH WATER	27/05/2019	29/05/2019
R120-0025219	1531	26235.56	1235013	8236.00	C SERVICE POLISH RIMS	20/05/2019	1/06/2019
R120-0025219	1531				REPLACE DOSER PUMP AND FILTERS	20/05/2019	1/06/2019
R120-0025219	1531				SERVICE VIESA/PAINT KOOLKAT COVER RED	20/05/2019	1/06/2019
R120-0025219	1531				REPLACE POWER STEERING OIL & FILTER. REPLACE STEER HUB OILS. REPLACE PITMAN ARM PINCH BOLT AND TENSION	20/05/2019	1/06/2019
R120-0025219	1531				CARRY OUT ENGINE TUNE. REPLACE ENGINE BRAKE KIT. INSPECT ROCKER SHAFTS AND CAMSHAFT FOR WEAR	20/05/2019	1/06/2019
R120-0025219	1531				REKIT HORTON FAN REPLACE ALL BELTS & TENSIONERS	20/05/2019	1/06/2019
R120-0025219	1531				REPLACE A/C COMPRESSOR	20/05/2019	1/06/2019
R120-0025219	1531				REKIT AIR DRYER	20/05/2019	1/06/2019
R120-0025219	1531				R/R RADIATOR STRIP AND CLEAN IN HOUSE. REPLACE COOLANT AND FILTER. PRESSURE TEST INTERCOOLER	20/05/2019	1/06/2019
R120-0025219	1531				REPLACE AIR COMPRESSOR & D2 GOVERNOR VALVE	20/05/2019	1/06/2019
R120-0025219	1531				REPLACE WATER PUMP	20/05/2019	1/06/2019
R120-0025219	1531				REPLACE TURBO	20/05/2019	1/06/2019
R120-0025219	1531				REPLACE OIL & COOLANT THERMOSTATS	20/05/2019	1/06/2019
R120-0025219	1531				INSPECT BONNET AND GRILLE FOR DAMAGE REPLACE WORN BONNET MOUNTS	20/05/2019	1/06/2019
R120-0025219	1531				REPLACE FRONT CRANKSHAFT SEAL	20/05/2019	1/06/2019
R120-0025219	1531				REPLACE REAR ENGINE MOUNTS, INSPECT FRONT	20/05/2019	1/06/2019
R120-0025219	1531				REPLACE DIFF OIL AND FILTER, RESEAL FRONT DIFF	20/05/2019	1/06/2019
R120-0025219	1531				REPLACE GEARBOX OIL AND FILTER	20/05/2019	1/06/2019
R120-0025219	1531				REPLACE TANK STRAP RUBBERS REPAIR LHF AND RHF CRACKED J BRACKETS	20/05/2019	1/06/2019
R120-0025219	1531				REPAIR FUEL PUMP MOUNT LEAKS	20/05/2019	1/06/2019
R120-0025219	1531				REPLACE DRIVE MUDGUARDS AND FLAPS	20/05/2019	1/06/2019
R120-0025219	1531				EPLACE ALTERNATOR BEARING	20/05/2019	1/06/2019
R130-0020456	1531	158.56	1229312		WORK LIGHTS ARE NOT WORKING, AFTERTREATMENT LIGHT IS ON	16/05/2019	16/05/2019
R130-0020456	1531				EXHAUST LEAKS - POSSIBLE BOOST LEAK - BRAKE LIGHTS NOT WORKING	16/05/2019	16/05/2019
R130-0020456	1531				DOWNLOAD	16/05/2019	16/05/2019
R130-0020408	1531	37.50	1227513		Speedo and fuel gaige back light is out	14/05/2019	15/05/2019
R130-0020150	1531	2769.16	1217351		17.4.19 1531 REGO 574VOT KLMS 1252098 ROCKER SHAFT ELONGATED DETENT POCKETS REAR ENGING BRAKE SOLENOID LEAKING OIL REMOVE AND REPLACE FRONT ROCKER SHAFT	30/04/2019	1/05/2019
R130-0019936	1531	1779.85	1210777		ENGINE BRAKE NOT WORKING	15/04/2019	26/04/2019
R130-0019866	1531	1936.00	1206426		4 X 11R22.5 M749 POSITION 5,6,7,8 4 X FIT 4 X TRADES FTSD-11803650	9/04/2019	10/04/2019
R130-0019838	1531	1629.68	1206426	7794.00	Blown globes in the cab, driver's door handle is broken, bonnet cables need to b connected	6/04/2019	9/04/2019
R130-0019838	1531				DRIVERS DOOR HANDLE	6/04/2019	9/04/2019
R130-0019838	1531				B SERVICE	6/04/2019	9/04/2019
R130-0019705	1531	282.54	1197792		AFTERTREAT LIGHT COMING ON - DE-RATED	29/03/2019	29/03/2019
R130-0019612	1531	550.97	1194920		Air con has stopped working	25/03/2019	26/03/2019
R155-0008148	1531	1056.00	1191950		2 X 295/80R22.5 R150 POSITION 1,2 2 X BALANCE 2 X FIT 1 X TRADES FTSD-11742718	20/03/2019	22/03/2019
R130-0019526	1531	493.24	1190970		23.1.19 CALLOUT TO GREAT WESTERN-NO CLEARANCE LIGHTS-FOUND RESETTABLE FUSE FOR TRAILER CLEARANCE BLOWN-RESET FUSE ALL OK REGO: 574VOT KLMS: 194.374	19/03/2019	19/03/2019
R155-0008126	1531	444.82	1190970		AFTER TREATMENT LIGHT DISPLAYED	19/03/2019	26/03/2019
R130-0019457	1531	155.25	1188024		CHECK TRUCK PHONE	15/03/2019	15/03/2019
R130-0019426	1531	609.84	1185889		R&R COOLANT THERMOSTAT-FIT NEW THERMOSTAT AND REFIT HOUSING TOWED IN OIL PRESSURE LIGHT CAM ON-LOW OIL PRESSURE. ENGIN DOES NOT SOUND GOOD REGO: 574VOT KLMS: 1,221,426	13/03/2019	18/03/2019
R130-0019261	1531	48.75	1180439		PICK UP FROM CUMMINS LAVERTON	4/03/2019	5/03/2019

R155-0007995	1531	203.40	1177943		AXLE GASKET LEAKING	27/02/2019	28/02/2019
R130-0019132	1531	295.01	1175622		COOLANT LEAK	23/02/2019	23/02/2019
R122-0022215	1531	307.44	1163222		APPROVED BY BH 6.2.19 CODE: 042 EXTRA LABOUR CHARGES NOT INCLUDED IN ORIGINAL ORDER P122-009638 REFER TO INVOICE 861936 (21.11.2018)	6/02/2019	6/02/2019
R155-0007779	1531	138.75	1158709		Steer hub gasket is leaking	31/01/2019	31/01/2019
R130-0018719	1531	69.75	1155447		CHECK ENGINE LIGHT ON	26/01/2019	29/01/2019
R155-0007732	1531	157.50	1153601		CHECK ENG LIGHT ON AND SHUTTING DOWN	24/01/2019	29/01/2019
R155-0007714	1531	258.63	1151968		MICROPHONE N/W	22/01/2019	23/01/2019
R155-0007714	1531				FIT AIR BLOWER IN CAB	22/01/2019	23/01/2019
R155-0007647	1531	42.75	1146879		AIR CON IS NOT WORKING AIR CON IS NOT WORKING, SEAT NEEDS FIXING	15/01/2019	16/01/2019
R130-0018490	1531	1690.85	1146879	6977.00	B SERVICE	14/01/2019	15/01/2019
R130-0018463	1531	300.00	1142852		CHECK ENGINE BRAKE	10/01/2019	14/01/2019
R130-0018438	1531	0.00	1141389		OIL LEAK ON THE DRIVER'S SIDE	9/01/2019	9/01/2019
R155-0007591	1531	255.79	1141389		DRIVER REPORTS VEHICLE LOSING POWER / DE-RATING	9/01/2019	11/01/2019
R140-0049277	1531	1969.00	1136484		SERVICE ON 11531078 BRIS DEP 3.1.19 HUBO 177244 POS 7-12	3/01/2019	7/01/2019
R130-0018133	1531	225.58	1127534		CODES AND OIL LEAKS	19/12/2018	19/12/2018
R130-0018009	1531	476.95	1121973		Air con is not working it's not cold	12/12/2018	17/12/2018
R130-0018009	1531				AIR CON NOT WORKING, ENGINE BRAKE NOT WORKING PROPERLY	12/12/2018	17/12/2018
R130-0018009	1531				A/C NOT WORKING	12/12/2018	17/12/2018
R130-0018029	1531	1051.60	1121973		AB AUTO TO REPAIR AC	12/12/2018	17/12/2018
R155-0007257	1531	968.00	1112283		2 X 11R22.5 M749 POSITION 5,6 2 X FIT 2 X TRADES FTSD-11435504	30/11/2018	3/12/2018
R155-0007244	1531	822.39	1111081		CHECK ENGINE LIGHT DISPLAYED.	29/11/2018	30/11/2018
R155-0007244	1531				FUEL GAUGE INOPERATIVE	29/11/2018	30/11/2018
R155-0007247	1531	440.00	1111081		BOTH WINDSCREENS HEAVILY CRACKED	29/11/2018	10/12/2018
R130-0017735	1531	415.00	1109324			27/11/2018	27/11/2018
R130-0017690	1531	305.89	1109299		CALLOUT TO YARD + BRING INTO WORKSHOP	26/11/2018	26/11/2018
R130-0017690	1531				REPLACED TRAILER SOCKET	26/11/2018	26/11/2018
R130-0017557	1531	81.00	1102299		REPAIR MIRROR LIGHT.	14/11/2018	15/11/2018
R130-0017485	1531	101.25	1099594		GEARBOX ISSUES	9/11/2018	10/11/2018
R130-0017322	1531	1866.00	1094523		CHECK TRANSMISSION	31/10/2018	3/11/2018
R130-0017304	1531	418.00	1093321		REPAIR TRANSMISSION FAULT FIT NEW TCM & PROGRAM TO SUIT TRUCK REGO: 574VOT	30/10/2018	7/11/2018
R130-0017276	1531	2380.98	1093292		REPLACE TRANSMISSION ECU	29/10/2018	29/10/2018
R130-0017172	1531	1773.35	1089225		CHECK TRANSMISSION	22/10/2018	25/10/2018
R130-0017099	1531	1034.55	1087796		CHECK OIL PRESSURE	17/10/2018	25/10/2018
R130-0017099	1531				TRANSMISSION - AUTOMATIC	17/10/2018	25/10/2018
R130-0017053	1531	934.83	1085788	6141.00	DUE FOR A SERVICE SIF 21744806 SIF 21745407 \f0	12/10/2018	13/10/2018
R140-0045768	1531	(330.00)	1083067		REFER TO INVOICE 1450621 (P140-0026883) R140-0044413 REFUND OF CORE CHARGE 2894943CORE x 1	10/10/2018	11/10/2018
R130-0016969	1531	133.50	1081550		TRUCK IS NOT BOOSTING PROPERLY	6/10/2018	8/10/2018
R155-0006844	1531	39.43	1079968		TOP UP OIL & COOLANT CONTAINERS	4/10/2018	4/10/2018
R155-0006828	1531	249.75	1079208		TRANSMISSION FAULTS PLEASE CHECK OUT	3/10/2018	4/10/2018
R140-0044413	1531	1468.47	1055876		MANIFOLD HAS COME APART , AFTERTREATMENT LIGHT ON \f0	6/09/2018	10/09/2018
R140-0044413	1531				RHS BONNET INDICATOR MISSING, DOOR HANDLE LOOSE	6/09/2018	10/09/2018
R140-0044458	1531	1001.00	1055876		SERVICE ON 11171071 BRIS DEP 6.9.18 HUBO 946452 POS 1-2	6/09/2018	11/09/2018
R140-0044157	1531	167.25	1048806		INDICATOR FAULT ON BONNET	30/08/2018	31/08/2018
R140-0043819	1531	692.75	1041373		EXHAUST FLEX BROKENUNDER TRUCK	23/08/2018	25/08/2018
R140-0043427	1531	2068.00	1026219		FTSD 11091920 BRIS 09.08.18 POS 9-12 ODO 68,818	10/08/2018	13/08/2018

R140-0043376	1531	2443.60	1028420	5441.00	B SERVICE E5 CUMMINS 60,000 KM	9/08/2018	11/08/2018
R140-0043376	1531				RENEW L/H STEER HUB SEAL	9/08/2018	11/08/2018
R140-0041697	1531	665.97	980182		TYRES NEED BALANCED, AIR LEAKS	28/06/2018	28/06/2018
R140-0041697	1531				REPAIR AIR LEAKS	28/06/2018	28/06/2018
R120-0020152	1531	277.23	967270		PO APPROVED BY BH 14.6.18 \cf0\fs18 LABOUR NATIONAL FLEET \fs16 CHECK AND REPAIR COOLANT LEAKING. LOWERED BONNET INSPECTED, PRESSURE TESTED COOLING SYSTEM AND FOUND THERMOSTAT HOSE SPLIT. REMOVED AND RPELACED HOSE TOPPED UP FLUID 20LITRES OF COOLANT PRESSURE TESTED FOUND NO LEAKS ALL OK. REGO: 574VOT KLMS: 999,903 PRICE AS PER RPOFORMA R107663 \cf1\fs2	14/06/2018	22/06/2018
R140-0040983	1531	1808.41	968084	4720.00	B SERVICE E5 CUMMINS 60,000 KM	14/06/2018	15/06/2018
R140-0040983	1531				BRAKE RELINE R/H/R DRIVE.	14/06/2018	15/06/2018
R140-0040671	1531	199.50	962618		BONNET REPAIRS	7/06/2018	8/06/2018
R140-0040436	1531	0.00	955983		REPAIR INDICATORS	31/05/2018	31/05/2018
R120-0019917	1531	1300.93	954062		PO REQUESTED BY BH 29.5.18 \cf0 ATTEND CALLOUT AT WORKSHOP CHECK AND REPAIR CAUSE OF jump start truck flat batteries ATTENDED CALL OUT IN BPARKING BAY INFORM OF WORKSHOP. CONNECTED WORK UTE AND JUMP STARTED AND FOUND TRUCK STARTED. FOUND BATTERY ACID LEAKING OUT OF BATTERY. REMOVED AND REPLACED ALL BATTERY. CLEANED TERMINALS STARTED TRUCK ALL OK. REGO: 574VOT KLMS: 975,717 PRICE AS PER PROFORMA R107490 \cf1\fs2	29/05/2018	29/05/2018
R140-0039708	1531	88.50	940589		LOSS OF CAB POWER	14/05/2018	15/05/2018
R140-0039612	1531	170.53	937625		IFACE NOT WORKING	10/05/2018	10/05/2018
R122-0017712	1531	354.45	935727		PO REQUESTED BY BILLY 8.5.18 \cf0 ATTEND CALLOUT OFFSITE CHECK AND REPAIR CAUSE OF JUMP START TRUCK ATTENDED BREAKDOWN AT BP SERVICE STATION IN DUBBO. FOUND NO IGNITION WARNING LIGHTS, TRUCK NBOT STARTING. TILT BONNET TESTED BATTERY VOLTAGES AND FUSES TRUCK CAME GOOD AND STARTED DRIVER REQUESTED TO KEEP GOING WITH NO FURTHER INSPECTED OR FAULT FINDING TILL BONNET AND BULLBAR RETURN TO WORKSHOP. REGO: 574VOT KLMS: 958,459 PRICE AS PER PROFORMA INVOICE R107352 \cf1\fs2	8/05/2018	10/05/2018
R120-0019459	1531	1410.79	927797		1531 - 14.3.18 REGO 574VOT KLMS 918433 AFTERTREATMENT LIGHT AND DERATED PLUGGED FUEL FILTERS CALL OUT PRESSURE DROP ACROSSFUEL FILTERS TO BE OUT OF SPEC	1/05/2018	2/05/2018
R140-0039141	1531	20.25	920962		DRIVER CANT LOG ON	24/04/2018	24/04/2018
R130-0014345	1531	828.08	917580		INSPECT I FACE	19/04/2018	20/04/2018
R140-0038987	1531	2156.00	917580		FTSD 14897983 BRIS DEP 17.4.18 HUBO 941173 POS 5-8	19/04/2018	23/04/2018
R140-0038820	1531	2559.07	915941	4056.00	B SERVICE E5 CUMMINS 60,000 KM	17/04/2018	18/04/2018
R156-0004808	1531	622.79	911516		1531 - 11.4.18 REGO 574VOT \cf0 AFTERHOURS BREAKDOWN - Brake lights inoperable Met vehicle at workshop. \b \$340.00 \b0 Carried out testing and found no power for brake lights. Checked fuses - all ok. Tested from truck side and found all working. Removed and replaced failed trailer light suzi. Tested operation. No further fault found. Part Number Part Description Quantity Total Cost 82536 SUZI COIL-7 CORE, 4.6M 4MM 1.00 82.88 OF OPENING FEE, PARTS 1.00 100.00 CF CALLOUT FEE 1.00 30.00 \b Parts Totals: 3.00 \$212.88\b0\fs24 \cf1\fs3\fs16	13/04/2018	13/04/2018
R140-0037911	1531	0.00	898821		CHECK STEER TYRES OUT PLEASE	23/03/2018	23/03/2018
R140-0037447	1531	860.00	893746		FTSD 1489360 BRIS DEP 8.3.18 HUBO 911721 POS 1-2	12/03/2018	13/03/2018
R122-0016768	1531	1956.58	888587		STARTER MOTOR 4.3.18 REGO 574VOT AS PER EMAIL JUSTIN EMAIL COMPONENT CODE 7.3.18 JUSTIN APPROVED 8.3.18	7/03/2018	9/03/2018
R122-0016741	1531	1137.90	887592		REGO 574VOT 1.3.18 BREAKDOWN 1531 KLMS 897960 BOOST PRESSURE/TEMP SENSOR FAILED	6/03/2018	7/03/2018
R130-0013556	1531	0.00	883607		CHECK STARTER	5/03/2018	5/03/2018
R130-0013385	1531	78.75	881741		INSPECT BONNET.	26/02/2018	26/02/2018
R120-0018224	1531	247.50	881741		PO REQUESTED BY BILLY 16.2.18 TECHNICIAN CALLOUT SD CARD	16/02/2018	28/02/2018
R140-0036596	1531	77.00	881741		FTSD NO 1454970 BRIS DEPOT 15.2.18 KLMS 887446 POS 1,2	16/02/2018	27/02/2018
R140-0036560	1531	113.14	881741		PO REQUESTED BY JUSTIN B 15.2.18 MACHINE FLYWHEEL REGO: 574VOT KLMS: 879538	15/02/2018	16/02/2018

R140-0036104	1531	6190.22	876285		FITTED AT CUMMINS BRISBANE	5/02/2018	9/02/2018
R140-0036104	1531				RESEAL BOTH DIFFS.	5/02/2018	9/02/2018
R140-0036104	1531				AC BLOWING HOT AIR	5/02/2018	9/02/2018
R140-0036104	1531				REPLACE LEAKING AIR BAG.	5/02/2018	9/02/2018
R140-0036051	1531	66.00	876285		FTSD: 1456828 BRISBANE 1.2.18 REGO: 547VOT ODO: 879522 POS: 1,2 FLIP ON RIMS, 2 x STRIP & FIT, 2 BALANCE B SERVICE E5 CUMMINS	2/02/2018	16/02/2018
R140-0035949	1531				REPLACE DIFF OILS AND FILTERS	1/02/2018	2/02/2018
R140-0035949	1531				REPLACE GEARBOX OILS AND FILTERS	1/02/2018	2/02/2018
R140-0035949	1531				INSTALL DRIVER FATIGUE MANAGEMENT KIT	1/02/2018	2/02/2018
R140-0035949	1531				FIFTH WHEEL ASSEMBLY	1/02/2018	2/02/2018
R130-0012550	1531	280.16	858160		BAD AIR LEAK	15/01/2018	16/01/2018
R130-0012566	1531	1936.00	858160		4 X 11/22.5 M749 POSITION,10,11,12 4 X TRADES 4 X FIT FTSD-1509838	15/01/2018	16/01/2018
R130-0012429	1531	19.80	851562		10 X PRESSURE CHECK POSITION 1 TO 12 FTSD-10597950	9/01/2018	11/01/2018
R140-0034984	1531	0.00	850730		NEEDS STEER TYRES BALANCED, NEEDS A WHEEL	8/01/2018	8/01/2018
R140-0034507	1531	1072.50	829654		B/STONE 2X 295/80/22.5 POS 1,2 2X FIT 1X TRADE 1X SCRAP 2X BAL FTSD 1521891	21/12/2017	27/12/2017
R130-0012022	1531	760.30	819680	2843.00	B SERVICE SAMPLE SIF 21749250	11/12/2017	12/12/2017
R140-0033512	1531	2128.50	806187		B/STONE 4X 11R22.5 M749 POS 5-8 4X FIT 1X ROTATE 1X CASE 1X SCRAP FTSD 1555992	30/11/2017	7/12/2017
R122-0015060	1531	561.00	804133		PO REQUESTED BY BILLY 29.11.17 REPAIR FLAT DRIVE TYRE HAY TYRE AND BATTERY	29/11/2017	1/12/2017
R140-0032891	1531	637.62	789900		REPLACE HOOD ASSIST	16/11/2017	27/11/2017
R130-0011484	1531	102.75	786517		INSPECT BONNET STRUT.	13/11/2017	13/11/2017
R156-0003870	1531	19.80	778370		31/10/17 PRESSURE CHECK @MAREEBA ON 1531	7/11/2017	9/11/2017
R140-0031515	1531	145.46	760383		RENEW CONTAMINATED FUEL FILTER	18/10/2017	18/10/2017
R140-0031426	1531	189.90	760382		SUPPLY CUMMINS WACOL WITH COOLANT & FILTER	17/10/2017	17/10/2017
R140-0031361	1531	352.39	760366		R/H DRL SMASHED	16/10/2017	16/10/2017
R140-0031344	1531	1073.50	760366		B SERVICE E5 CUMMINS	14/10/2017	16/10/2017
R140-0031344	1531				RELIN FRONT DIVE HUBS	14/10/2017	16/10/2017
R140-0031344	1531				RENEW ENGINE MOUNTS	14/10/2017	16/10/2017
R130-0010861	1531	57.75	745775		CODES	2/10/2017	4/10/2017
R155-0004281	1531	979.81	741355		DRIVER REPORTS TAIL LIGHTS INOPERATIVE	27/09/2017	29/09/2017
R155-0004281	1531				DRIVER REPORTS CLUTCH GRABS	27/09/2017	29/09/2017
R155-0004281	1531				DRIVER REPORTS SEAT LOSING AIR & DROPPING DOWN	27/09/2017	29/09/2017
R155-0004281	1531				CHECK BATTERY CONDITION - DRIVER REPORTED SLOW TO TURN OVER	27/09/2017	29/09/2017
R130-0010748	1531	561.30	741252		ADJST HEADLOINGTS	25/09/2017	28/09/2017
R130-0010748	1531				REPLACE HUB SEAL	25/09/2017	28/09/2017
R140-0030136	1531	19.80	733721		B/STONE PRESSURE CHECK X10	19/09/2017	21/09/2017
R140-0029815	1531	16.18	728796		LOW COOLANT WARNING COMING ON	13/09/2017	13/09/2017
R140-0029492	1531	137.25	724330		CIG LIGHTER NOT WORKING	8/09/2017	9/09/2017
R140-0029492	1531				TURBO TIMER NOT WORKING TO SWITCH OFF	8/09/2017	9/09/2017
R120-0015091	1531	2662.39	713546		SUBLET TO BROWN AND HURLEY CABOULTURE WHERE THE ADBLUE PUMP WAS BLOCKED - REPLACED FILTER AND CLEANED OUT PICK UPI	28/08/2017	29/08/2017
R140-0028618	1531	440.00	707235		IAP INSPECTION	21/08/2017	23/08/2017
R122-0012978	1531	855.93	700566		PM for 000-002 Last Done: 14/06/2017 Interval: 60000 Utilization: 54872	11/08/2017	14/08/2017
R122-0012587	1531	296.91	677091		REPLACE EXHAUST FLEX & CLAMP	21/07/2017	21/07/2017

R140-0026213	1531	38.50	655922		1 X PUNCTURE REPAIR FTSD-32405-STANTHORPE	29/06/2017	29/06/2017
R120-0013878	1531	193.20	649187		60 LITRES OF COOLANT WHICH SHOULD OF BEEN BOOKED TO C - SERVICE -R120-0008269	22/06/2017	26/06/2017
R140-0025878	1531	347.79	649187		AFTER TREATMENT LIGHT ON.CHECK FAULTS.CARRY OUT TROUBLESHOOTING.INPECT ADBLUE INJECTOR TIP MISSING.REMOVE & REPLACE.FLUSH OUR ADBLUE AIR SYSTEM & ADBLUE SIDE OF PUMP.REMOVE & REPLACE ADBLUE AIR FILTER & CODE BECAME IBACTIVE.CHECK AIR FLOW RATE & OVERRIDE TEST.CARRY ECM CALIBRATION.CLEAR FAI II TS	22/06/2017	22/06/2017
R122-0011826	1531	622.77	642476		B SERVICE	14/06/2017	15/06/2017
R122-0011771	1531	252.54	637507		REPLACE MAIN COMPRESSOR AIR LINE	9/06/2017	10/06/2017
R120-0013475	1531	971.30	630822		1 X 295/80R22.5 R150 POSITION 1 1 X SCRAP 1 X BALANCE BEADS 1 X ETA FEE NO 54452 FTSD-	2/06/2017	2/06/2017
R122-0011647	1531	4268.00	630822		11R 'M749' POS# 5-6-7-8-9-10-11-12 TRADE-IN x 6 FTSD- 1434919	2/06/2017	9/06/2017
R122-0011531	1531	218.56	627167		THE GEARSTICK CONTROLLER IS LOOSE IN THE DASH	29/05/2017	30/05/2017
R122-0010759	1531	1093.90	579672	1900.00	B SERVICE + DIFF OILS	19/04/2017	20/04/2017
R122-0010349	1531	1060.84	557488		REPLACE STEER TYRES WITH 295 'R150, CASES x 2 8 x P-CHECK, FTSD- 1362229	24/03/2017	24/03/2017
R122-0010031	1531	147.30	543210		REPLACE R/H /R INDICATOR	8/03/2017	11/03/2017
R122-0009973	1531	63.75	541325		DROP AT CUMMINS COOLANT PIPE REPLACEMENT	6/03/2017	8/03/2017
R122-0009741	1531	45.00	530412		STEER TYRES CHOPPING OUT BADLY	22/02/2017	23/02/2017
R122-0009422	1531	22.00	519150		STEER ROTATION, FTSD-1294712	9/02/2017	17/02/2017
R122-0009392	1531	705.80	519150		B SERVICE	8/02/2017	9/02/2017
R122-0009143	1531	173.51	507378		CHANGE FILTER UN BLOCK A/C DRAIN	27/01/2017	31/01/2017
R120-0010480	1531	275.00	490853		CALLOUT TO TRUCK NOT STARTING.BROKEN EXCITER WIRE FOR STARTER	6/01/2017	9/01/2017
R122-0008737	1531	2288.00	490853		REPLACE POS#5-6-7-8 WITH 11R M749, 2 x KEPT FOR RUN OUTS, 2 x CASES, FTSD-1297642	6/01/2017	9/01/2017
R122-0008580	1531	2288.00	483901		REPLACE POS#9-10-11-12 WITH 11R M749, 4 x CASES, FTSD-1296135	28/12/2016	3/01/2017
R122-0008588	1531	606.50	483901		BIG WHEELS, WHEEL ALIGNMENT, 21-12-16 483959 KM	28/12/2016	3/01/2017
R122-0008120	1531	1045.00	467191		REPLACE STEER TYRES WITH 295 R150, 8 x P-CHECK, FTSD-No.1297291	6/12/2016	15/12/2016
R122-0008102	1531	1061.42	467191		B SERVICE	5/12/2016	6/12/2016
R122-0008102	1531				RELINER REAR AXLE BRAKES	5/12/2016	6/12/2016
R122-0007950	1531	101.00	460131		REPLACE CB MIC	28/11/2016	29/11/2016
R140-0016482	1531	410.62	454300		REPAIR A/C SYSTEM- SUBLET TO PTE.	22/11/2016	28/11/2016
R122-0007065	1531	54.75	420570		REPLACE AIR FITTING AT STEER ABS VALVE	21/10/2016	22/10/2016
R122-0007050	1531	41.80	419298		STEER ROTATION, TURN ON RIMS, P-CHECK, FTSD-1072917	20/10/2016	21/10/2016
R122-0006793	1531	61.78	412793		REPAIR AIR LINE TO AIR BAG DUMP CIRCUIT	12/10/2016	12/10/2016
R120-0008269	1531	22226.91	410044		CARRY OUT C SERVICE	4/10/2016	2/11/2016
R120-0008269	1531				REMOVE RADAITOR AND SEND TO NATRAD TO BE CLEANED AND TESTED	4/10/2016	2/11/2016
R120-0008269	1531				WARRANTY- REPLACE ROCKER SHAFTS AND TUNE ENGINE	4/10/2016	2/11/2016
R120-0008269	1531				REPLACE STARTER	4/10/2016	2/11/2016
R120-0008269	1531				REPLACE TURBO	4/10/2016	2/11/2016
R120-0008269	1531				REPLACE AIR COMPRESSOR	4/10/2016	2/11/2016
R120-0008269	1531				REPLACE WATER PUMP	4/10/2016	2/11/2016
R120-0008269	1531				REPLACE DOSER AND FILTERS	4/10/2016	2/11/2016
R120-0008269	1531				REPLACE OIL THERMOSTAT	4/10/2016	2/11/2016
R120-0008269	1531				PRESSURE TEST INTERCOOLER AND CLEAN	4/10/2016	2/11/2016
R120-0008269	1531				UPGRADE SUZI COILS	4/10/2016	2/11/2016
R120-0008269	1531				REPLACE THERMOSTATS	4/10/2016	2/11/2016
R120-0008269	1531				REPLACE STEER OILS REPLACE POWER STEER OILS AND FILTER	4/10/2016	2/11/2016
R120-0008269	1531				REKIT HORTON REPLACE BELTS TENSIONERS AND IDLERS	4/10/2016	2/11/2016
R120-0008269	1531				REPLACE ALTERNATOR	4/10/2016	2/11/2016

R120-0008269	1531				REPLACE A/C COMPRESSOR AND HOSES	4/10/2016	2/11/2016
R120-0008269	1531				KIT AIR DRIER	4/10/2016	2/11/2016
R120-0008269	1531				SERVICE VIESA	4/10/2016	2/11/2016
R120-0008269	1531				GAUGES LOOSE	4/10/2016	2/11/2016
R120-0008269	1531				REPLACE BROKEN VENTS	4/10/2016	2/11/2016
R120-0008269	1531				TANK STRAP RUBBERS WORN OUT	4/10/2016	2/11/2016
R120-0008269	1531				REPLACE WIPER BLADES	4/10/2016	2/11/2016
R120-0008269	1531				RETENSION U BOLTS	4/10/2016	2/11/2016
R120-0008269	1531				EXHAUST PIPE INSECURE AT ENGINE BLOCK	4/10/2016	2/11/2016
R120-0008269	1531				FUEL LINES LEAKING FUEL PUMP LEAKING	4/10/2016	2/11/2016
R120-0008269	1531				TIDY BRAKE LINES	4/10/2016	2/11/2016
R120-0008269	1531				EXHAUST LEAKS WARRANTY- MANIFOLD GASKETS	4/10/2016	2/11/2016
R120-0008269	1531				FRONT CAB MOUNTS WORN	4/10/2016	2/11/2016
R120-0008269	1531				EXTEND ESOC	4/10/2016	2/11/2016
R120-0008269	1531				WARRANTY- RAIL SENSOR LEAKING	4/10/2016	2/11/2016
R120-0008269	1531				REPLACE REAR GAURDS	4/10/2016	2/11/2016
R120-0008269	1531				TIDY ENGINE AND CHASSIS HARNESS	4/10/2016	2/11/2016
R120-0008269	1531				LOWER BUSHES WORN	4/10/2016	2/11/2016
R120-0008269	1531				WORN SWAY BAR BUSHES WORN TORQUE ROD BUSHES	4/10/2016	2/11/2016
R120-0008269	1531				ADJUST AND REPLACE WEAR PADS	4/10/2016	2/11/2016
R120-0008269	1531				BROKEN SUNVISOR CLIPS	4/10/2016	2/11/2016
R120-0008269	1531				UHF INSECURE	4/10/2016	2/11/2016
R120-0008269	1531				POLISH RIMS	4/10/2016	2/11/2016
R120-0008295	1531	330.00		409955	Radiator service	4/10/2016	5/10/2016
R122-0006514	1531	792.89		406506	PM for 000-002 Last Done: 29/07/2016 Interval: 60000 Utilization: 56506	28/09/2016	28/09/2016
R122-0005926	1531	41.80		361017	STEER ROTATION, P-CHECK FTSD-1186273	5/09/2016	22/09/2016
R140-0011638	1531	0.00		330730	STARTER MOTOR ISSUES	3/08/2016	3/08/2016
R122-0005032	1531	34.50		330730	REPLACE BOTH DRIVING LIGHT GLOBES	1/08/2016	2/08/2016
R122-0004975	1531	1295.51		350000	B SERVICE	29/07/2016	30/07/2016
R122-0004975	1531				REPLACE EXHAUST FLEX AT TRANS	29/07/2016	30/07/2016
R122-0004975	1531				REPLACE MAIN AIR LINE	29/07/2016	30/07/2016
R122-0004975	1531				REPLACE DASH VENTS	29/07/2016	30/07/2016
R122-0004927	1531	99.75		326036	REPLACE L/H DAYTIME RUNNING LIGHT	27/07/2016	28/07/2016
R122-0004864	1531	78.75		324682	ELECTRONIC LOG BOOK WONT TURN ON	25/07/2016	26/07/2016
R122-0004723	1531	37.50		318740	WARRANTY CHECK & REPAIRS REPLACE CLUTCH + TANK STRAP RUBBERS	19/07/2016	19/07/2016
R122-0004599	1531	72.75		314586	BAD SHUTTER IN THE GEARBOX WHEN TAKING OFF TAKEN TO KENWORTH FOR WARRANTY + END OFF WARRANTY INSPECTION REPLACED CLUTCH UNDER WARRANTY Vfo	13/07/2016	15/07/2016
R122-0004528	1531	35.25		314586	WARRANTY REPAIR G&R TRANS NOT SHIFTING CORRECTLY	8/07/2016	11/07/2016
R122-0004473	1531	129.00		314586	G&R WARRANTY ENGINE/TRANS HAS HESITATION	6/07/2016	6/07/2016
R122-0004433	1531	37.50		314586	WARRANTY AT G&R REPLACE STARTER MOTOR	5/07/2016	5/07/2016
R122-0004399	1531	1045.00		314586	B/STONE... REPLACE STEER TYRES WITH 295 'R150, 2 x KEPT FOR RUN OUTS, FTSD-1145312	2/07/2016	8/07/2016
R122-0003961	1531	4246.00		304280	B/STONE... REPLACE DRIVE TYRES WITH 11R 'M749, 2 x KEPT FOR RUN OUTS, 6 x 11R TRADE-IN, FTSD-1185550	14/06/2016	20/06/2016
R122-0003658	1531	127.50		290195	REVERSE BUZZER STUCK ON (BEEN DISCONNECTED)	27/05/2016	30/05/2016
R122-0003639	1531	93.60		288687	REPLACE L/H HEAD LIGHT SHIELD.	26/05/2016	30/05/2016

R122-0003551	1531	1165.60	286760	128.00	b service	23/05/2016	24/05/2016
R122-0002743	1531	695.49	276652		DUE FOR B\fo SERVICE	13/04/2016	13/05/2016
R120-0003472	1531	1177.00	246439		ETA CALLOUT -DONE BY M GROUP -PAGET-FTSD69891 REPLACE POS. 23/24 WITH 11R22.5-R168	11/04/2016	9/05/2016
R122-0002531	1531	1045.00	236346		B/STONE... REPLACE STEER TYRES WITH 295 'R150, 2 x KEPT FOR RUN OUTS, FTSD-1022554	1/04/2016	11/04/2016
R122-0002489	1531	75.00	234660		CHECK ENGINE LIGHT COMING ON	30/03/2016	31/03/2016
R120-0002863	1531	60.84	225788		AIR FILTER	18/03/2016	18/03/2016
R122-0001922	1531	22.00	210422		B/STONE... STEER ROTATION, TURN ON RIMS, LEFT TO RIGHT, FTSD-1013382	1/03/2016	4/03/2016
R122-0001831	1531	1040.97	220560		B SERVICE	24/02/2016	31/03/2016
R122-0001831	1531				REPLACE R/H DAYTIME LIGHT	24/02/2016	31/03/2016
R140-0002393	1531	43.96	183964		SUPPLIED DRIVER WITH ANTI BACTERIAL CALFA BAG.	30/01/2016	19/02/2016
R122-0000928	1531	22.00	175380		2 X STEER ROTATION POS 1-2 FTSD 859973	21/01/2016	2/02/2016
R122-0000771	1531	635.64	169713		B SERVICE	14/01/2016	15/01/2016
R122-0000590	1531	80.25	161013		ROOF LEAKS	6/01/2016	6/01/2016
R122-0000355	1531	(110.00)	128070		2 X FIT 11R M749 POS 7-8 2 X TRADE FTSD 859762	22/12/2015	8/01/2016
R122-0000361	1531	4246.00	128070		8 X FIT 11R M749 POS 3-10 6 X TRADE 2 X LEFT FOR SPARE FTSD 859768	22/12/2015	7/01/2016
R122-0000223	1531	95.25	141846		SENT TO CUMMINS... ENGINE OIL LEAK-WARRANTY	16/12/2015	17/12/2015
R122-0000081	1531	935.00	1		2 X FIT R150 POS 1-2 2 X TRADE FTSD 020491	10/12/2015	18/01/2016