

Work Order ID	Equipment ID	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R120-0043209	1508	\$2,628.00	2346254		STRIP AND FIT CAB. PREP CAB FOR PAINTING REFITCAB	13/09/2023	5/10/2023
R120-0043069	1508	\$3,916.97	2346254		PREP CAB FOR PAINTING. PAINT CAB FOR TRADE	4/09/2023	19/10/2023
R120-0043009	1508	\$686.40	2346254		STRIP FOR TRADE	30/08/2023	30/08/2023
R120-0042974	1508	\$123.60	2346254		REPLACE STEER WHEELS replace steer wheels [new for old]	28/08/2023	30/08/2023
R122-0063561	1508	\$33.02	2341021		replace spotter mirror	18/08/2023	19/08/2023
R130-0047535	1508	\$2,765.44	2336305		B SERVICE CARRY OUT B SERVICE ON TRUCK  REPAIR ALL BLOWN LIGHTS  FIX GREASELINES TO KING PINS  REPAIR WON HEATR HOSE  FIX VIESA AND SECURE CONDUCT B SERVICE  DIAGNOSE AUTO GREASER FAULTS  REPLACE HEATER HOSE  REP;LACE NUMBER PLATE LIGHT  REPLACE LOAD LIGHT  REPLACE CAB MARKER LIGHT	3/08/2023	11/08/2023
R130-0047061	1508	\$5,297.37	2329057		REPLACE ALL MUDGUARDS REPLACE RHR LIGHT ASSEMBLY MAKE SUZIS AND REPAIR SPARE SET REPLACE HEQDLIGHT GLOBE	11/07/2023	17/07/2023
R130-0047061	1508				DIFF RESEAL. REPLACED AIR HOSE. REPLACED R/H/M AIR BAG AND R/H/F AIR BAG. RE-SEAL DIFF AND REPAIR LIGHT BAR REPLACE 2 AIRBAGS	11/07/2023	17/07/2023
R130-0047065	1508	\$3.60	2329057		RAN FLUSH ON SYSTEM  AN CLICK TEST AND DOSER OVER RIDE TEST  AFTFRTRFAT I LGHT CI FARFD ALIGN GUARDIAN	11/07/2023	13/07/2023
R130-0046746	1508	\$111.60	2320217		REPALCED GOVENOR ADJUSATED GOVENOR	22/06/2023	22/06/2023
R130-0046643	1508	\$177.91	2318132		fit new fuel tags	19/06/2023	22/06/2023
R130-0045979	1508	\$90.00	2303675		REPLACED GEAR BOX OIL AND FILTER	17/05/2023	17/05/2023
R130-0045654	1508	\$1,638.41	2294147		REPLACED 2X LHS TANK STRAPS  RFPI ACFD 3X RHS TANK STRAPS REPLACED 5X TANK STRAPS	4/05/2023	13/05/2023
R130-0045548	1508	\$90.00	2280851		check heater for fault	4/05/2023	13/05/2023
						1/05/2023	1/05/2023

R130-0045234	1508	\$7,285.49	2280851	REPLACE KINPINS CARRY OUT B SERVICE ON TRUCK  COMPLETE REPAIR LIST  STRIP LING PINS DOWN AND INSPECT WEAR  FOUND NOT TO BE GETTING GREASE	14/04/2023	29/04/2023
R130-0045234	1508			DIAGNOSE FAULTS IN AUTO GREASER AND REPAIR RHS HEAD LAMP REPALCED	14/04/2023	29/04/2023
R130-0044777	1508	\$702.34	2262402	AIRDRIER REKIT	20/03/2023	27/03/2023
R130-0044713	1508	\$79.06	2258115	replace coolant filter top up coolant	14/03/2023	14/03/2023
R130-0044578	1508	\$241.33	2252523	REPLACE AXLE SEAL FIT ,ISSING HUBCAPS	7/03/2023	7/03/2023
R130-0044556	1508	\$647.95	2252523	REPLACE AC COMPRSSOR	6/03/2023	7/03/2023
R130-0044479	1508	\$1,077.30	2248568	DATE: 09.2.2023   DOCUMENT NO. 524809   294,108 klms   BREAK DOWN FOR OIL LEAK RHS STEER DROVE TO MOKOAN PARKING BAY JACKED UP FRONT AXLE AND CHECKED BEARINGS AND REPIACFD RH HUB CAR AND FILLED HUB WITH OIL   NOT BOOKED OUT R130-0044045	2/03/2023	10/03/2023
R130-0044317	1508	\$0.00	2238394		21/02/2023	21/02/2023
R130-0044148	1508	\$60.00	2229827	secure yellow and red release button	10/02/2023	10/02/2023
R130-0044045	1508	\$842.76	2227787		7/02/2023	9/02/2023
R130-0044045	1508			TIGHTENED RHF WHEEL BEARING  CLEARED CODES  REPAIRED DRIVERS DOOR CARD	7/02/2023	9/02/2023
R130-0043986	1508	\$200.40	2223222	INSPECTED FRONT END SUSPENSION AND STEERING inspect and tighten pitman arm	3/02/2023	7/02/2023
R130-0043879	1508	\$2,457.22	2220093	B SERVICE CONDUCTED	30/01/2023	31/01/2023

R130-0043901	1508	\$1,297.14	2220093	<p>SERVICE ON 16882050 MELB DEPOT 30-01-2023 HUBO 677893</p> <p>Pos. Article Description Stock From No. of Caps RTD Case condition Reason for removal Details 01 11006520 - 295/80R22.5 152/148M BS R154 CC 0.0 Runout Held by Customer Customer Request 02 11006520 - 295/80R22.5 152/148M BS R154 CC 0.0 Retread (recap) Customer Pull Point Qty SERVICES/ACCESSORIES REMARKS / SIZE: 2 EA Wheel Balance 33000051 - BALANCE TBR (Pos: 1, 2) 2 EA Tyre Replacement 33000084 - FIT TBR TYRE (Pos: 1, 2) 1 EA</p>	30/01/2023	31/01/2023
R130-0043526	1508	\$1,563.21	2207051	REPLACE BROKEN WIPER BLADE	11/01/2023	12/01/2023
R130-0043526	1508			FOUND 2 LEAKING AIR BAGS AND A PPV REPLACE AND TEST FOR AIR LEAKS	11/01/2023	12/01/2023
R130-0043526	1508			REPLACE AND REPAIR DASH LIGHTS	11/01/2023	12/01/2023
R130-0043330	1508	\$380.48	2199843	MAKE AND RUN A NEW AIR COMP CHARGE LINE AND SECURE	29/12/2022	30/12/2022
R130-0043006	1508	\$21.60	2187821	REPLACE BONNET LATCH ON TRUCK	9/12/2022	12/12/2022
R130-0042878	1508	\$770.15	2185487	<p>DATE: 23.12.2022   CO # 6631420   WORK ORDER # 2790526   SUPPLY AND FIT REAR MAIN   CSS # 474544   COLLECT PARTS AND DRIVE TO SITE - ACCESS TRUCK - GEAR BOX AND FLYWHEEL ALREADY REMOVED - REMOVE REAR MAIN SEAL - CLEAN ALL SURFACES AND INSPECT CRANK - ALL OKAY - FIT NEW SEAL - CLEAN UP - DRIVE TO BRANCH</p> <p>05.12.2022  Hi</p> <p>Can I get a P/O for Cummins to do a rear main seal on truck 1508</p> <p>Regards,</p>	6/12/2022	11/01/2023

R130-0042859	1508	\$9,808.38	2185487	Not changing gears smoothly and holding in gears	5/12/2022	7/12/2022
R130-0042859	1508			REMOVED GEARBOX CLEANED REPALCED CLUTCH REFIT BOX ROADTESTED R & R GBOX OIL	5/12/2022	7/12/2022
R130-0042859	1508				5/12/2022	7/12/2022
R130-0042809	1508	\$519.60	2183483	REPLACE LOW PRESSURE FUEL PUMP O RING	1/12/2022	2/12/2022
R130-0042756	1508	\$48.93	2181497	REPLACE RHF AXLE SEAL	28/11/2022	29/11/2022
R130-0042588	1508	\$90.00	2175419	check overspeed for fault	21/11/2022	22/11/2022
R130-0042540	1508	\$209.37	2170478	REPLACE WINDSCREEN WIPERS	16/11/2022	16/11/2022
R130-0042540	1508			replace plate light	16/11/2022	16/11/2022
R130-0042255	1508	\$6,785.10	2160087	B SERVICE	27/10/2022	3/11/2022
R130-0042255	1508			KING PIN RHS REPALCED KING PINS ROAD TESTED RECHECK BEARINGS TOP IIP HIR FLUIDS	27/10/2022	3/11/2022
R150-0000523	1508	\$1,667.60	2158835	DATE: 25.10.2022   INVOICE/RO NUMBER # 169569   1 LABOUR CHECK AND REPAIR WONT S Labor \$819.46 \$819.46 \$.00 \$819.46 1 D61-1004-003 STARTER - PACCAR DP60, K PACCAR Part \$469.22 \$469.22 \$.00 \$469.22 30 382-7.5/W-1 CABLE TIE - INDIVIDUAL 7.5M Other Part \$.22 \$.22 \$.00 \$6.60 114 TRV VEHICLE KILOMETERAGE Miscellaneous \$1.73 \$1.73 \$.00 \$197.22 1 SUPP WORKSHOP SUPPLIES Miscellaneous \$23.50 \$23.50 \$.00 \$23.50 1 Goods and Services Tax Goods and S \$151.60 \$151.60 \$.00 \$151.60 Parts \$469.22 Other Parts \$6.60 Labor/Other \$1,040.18 Freight \$.00 Tax \$151.60 Total Adjustment \$.00 Final Amount \$1,667.60	25/10/2022	17/11/2022
R130-0042039	1508	\$288.74	2150926		12/10/2022	14/10/2022
R130-0042039	1508			REAPLCED CRANK ANGLE SENSOR	12/10/2022	14/10/2022
R130-0041934	1508	\$1,349.68	2145167	CHECK CODES REPLACE NOX SENSOR AND TEST DRIVE	5/10/2022	6/10/2022
R130-0041766	1508	\$78.00	2138268	DOWNLOAD GUARDIAN FOOTAGE	23/09/2022	23/09/2022
R130-0041738	1508	\$248.34	2135905	REPLACE RHS HEADLIGHT PLUG AND TEST	20/09/2022	21/09/2022
R130-0041524	1508	\$648.00	2127183	REPLACE IFACE	7/09/2022	7/09/2022
R130-0041447	1508	\$60.00	2125652	connect cd play antenna	1/09/2022	1/09/2022
R130-0041266	1508	\$99.95	2118448	replace headlight globes	23/08/2022	23/08/2022
R130-0041221	1508	\$156.00	2116147	REWIRE CIGAR LIGHTER	18/08/2022	18/08/2022
R130-0041136	1508	\$92.40	2114216	FAULT FIND AND RE[PAIR CIGAR LIGHTER	15/08/2022	18/08/2022

R130-0041005	1508	\$5,837.57	2110579	REPAIR DATE: 25.7.22 WORKSHOP PROPOSAL: 6606211 \$5,837.57 Complaint: Oil in coolant - Diagnose & Report Cause: - Oil cooler core leaking. Correction: Guidanz SO Number: 00394308  Speedo : 561057 kms ( Vehicle has done over 2 million kms ). Ecm Hrs/Klms: 2125222 kms / 28185 hrs Fuel Burn: 1095094 ltrs - Write Jsa - Connect insite and carry out ecm download. - Removed radiator cap- signs of oil in coolant, removed turbo and coolant transfer tubes, removed oil cooler housing and pressure tested- found to be leaking, removed cooler core and fitted new core, pressure tested- no leaks, refitted housing and tensioned, refitted transfer tubes and turbo. - Change oil, fill up with water, wash and road test vehicle, running cold and blowing block smoke when changing gears. - Drain coolant and remove thermostat, found thermostat stuck open. Fit new thermostat and seal, fill up water and pressure test cooling system. Holds pressure. - Boost test, found pin hole on boost hose and boost hose clamp not tightening causing the boost leaks. Fit new boost hose and new clamp. Boost test again. Boost leaks fixed. - Road test again. All good. Fill up restorer and Flush cooling system x 5 times. - R & R water filter, quick release valve, R & R vent hose due to blocked. - Fill up with new coolant. Reset FC, final check- all ok. - Released vehicle back in service.  =====	9/08/2022	12/08/2022
R130-0040841	1508	\$170.39	2106380	REPLACE TURNTABLE FOOT BUSHES	1/08/2022	2/08/2022
R130-0040728	1508	\$2,081.08	2102857	RESECURE WIRING CARRY OUT SERVICE ON TRUCK  REPAIR BLOWN LIGHTS	25/07/2022	27/07/2022
R130-0040612	1508	\$281.92	2099501	FIT ESOC FITTING TO ENGINE DIAGNOSE AIR LEAK IN DASH	18/07/2022	18/07/2022
R130-0040561	1508	\$835.51	2097232	REPLACE AIR MANIFOLD ON FIREWALL REPAIR AND STRAIGHTEN LHR LIGHT BAR AND REPLACE AND REWIRE NEW LIGHT	14/07/2022	14/07/2022
R130-0040561	1508			REPLACE FAN AND A/C DUE TOSLIPPING AND CRACKS IN BELTS	14/07/2022	14/07/2022
R130-0040080	1508	\$86.25	2079627	INSPECT FOR COLANT LEAKS FOUND SIGHT-GLASS LEAKING RESEAL FITTING AND WASH INSPECT PHONE MIC	20/06/2022	24/06/2022
R130-0039869	1508	\$183.75	2070210	RFMOV E SIGHT GKI ASS AND REPI ACE WITH BUING DRIVE TO TRUCK ON HUME HWY  FOUND BOOSTER HOSESHAD BROKEN FREE FROM BOSSTER AND SMASHED HOLE IN CENTRAL CHAMBER  CAGE BOOSTER AND CRIMP HOSES	7/06/2022	7/06/2022
R130-0039846	1508	\$75.00	2069372	TEST OPERATION AND DRIVE BACK TO WORKSHOP REPLACE IFACE MOUNTING BACK	4/06/2022	4/06/2022

R130-0039708	1508	\$4,312.00	2065463	<p>SERVICE ON 15996438 MELB DEPOT 27-05-2022 HUBO: 523955</p> <p>05 11002831 - 11R22.5 146/143L BS M766 CC 0.0 Retread (recap) Customer Pull Point</p> <p>06 11002831 - 11R22.5 146/143L BS M766 CC 0.0 Retread (recap) Customer Pull Point</p> <p>07 11002831 - 11R22.5 146/143L BS M766 CC 0.0 Retread (recap) Customer Pull Point</p> <p>08 11002831 - 11R22.5 146/143L BS M766 CC 0.0 Retread (recap) Customer Pull Point</p> <p>09 11002831 - 11R22.5 146/143L BS M766 CC 0.0 Retread (recap) Customer Pull Point</p> <p>10 11002831 - 11R22.5 146/143L BS M766 CC</p>	27/05/2022	31/05/2022
R130-0039422	1508	\$1,025.89	2057866	INSTALL FRIDGE IN BUNK WIRE IN FRIDGE	12/05/2022	16/05/2022
R130-0039365	1508	\$71.22	2056986	CHECK OIL AND TAKE SAMPLE	10/05/2022	10/05/2022
R130-0039134	1508	\$315.75	2050018	REPAIR PHONESPEAKER BRACKET FIX SOME AIRLEAKS INSPECT TRUCK FORAIR LEAKS REAPIR SUSPENSION AIR LEAKS DIAGNOSE I FAKS IN BEHIND DASH AND REASSEMRI F	27/04/2022	27/04/2022
R130-0039154	1508	\$69.75	2050018	REPAIR BROKEN RIDE HIGHT VAVLE HOSE AND RESECURE	27/04/2022	28/04/2022
R130-0038945	1508	\$4,434.49	2043034	B SERVICE REPLACED AD BLUECAP REPLACEABS SENSOR AND AIR BAG ON LHR DRIVE FIX REVERSE LIGHTS REPLACE REVERSE BUZZER WITH SQUWAKER REPLACE FRONT ENGINE MOUNTS FIX ABS LIGHT STEAM CLEAN ENGINE THOROUGHLY	12/04/2022	13/04/2022
R130-0038945	1508			replace turbo feed and drain gasket	12/04/2022	13/04/2022
R130-0038945	1508			change diff oil and filter RESEAL REAR DIFF	12/04/2022	13/04/2022

R130-0038749	1508	\$771.26	2037128	CAB BLOWER NOT WORKING POWER AT PLUG WHEN IGNITION ON AND FAN SPEED OFF OR ON ANY SPEED SAME VOLTAGE. FOUND BLOWER MOTOR FAILED, HVAC POWER SUPPLY WIRE TO RELAY HOT AND MELTED. DISCONNECTED RESISTOR AND CONTROL UNIT POWER ONLY GOES AWAY WHEN UNIT PLUG DISCONNECTED. NO CONTINUITY TO EARTH ON POWER RETURN WIRE. REPLACED MOTOR AND REPLACED TERMINAL 30 TO HVAC POWER RELAY. TESTED FAN WORKING ON ALL SPEEDS OK PARTS PICKED UP FROM NAPPA.	4/04/2022	6/04/2022
R130-0038231	1508	\$177.75	2020486	FAULT FINDING FIX VOLTAGE DROP TO GBOX FUSE AND ABS FUSE	10/03/2022	11/03/2022
R130-0038070	1508	\$3,414.42	2014182	BREAKDOWN COMPRESSOR NOT BUILDING AIR CHANGE GOVERNOR ANDRECHECK, BLANK OFF GOVERNOR TO AIR DRYER AND STILL NOT BUILDING AIR TOWED BACK TO DEPOT INSPECT AND DIAGNOSE TRUCK NOT BUILDING UP AIR INSPECT ALL AIR SYSTEM FOR FAILURES REMOVE AND KIT AIR DRYER REMOVE AIR COMP CYLINDER CLEAN PARTS AND FIT AND TENSION NEW HEAD FIT TAILSHAFT AND TEST DRIVE TRUCK	3/03/2022	7/03/2022
R130-0038750	1508	\$440.00	2015481	Towed From: WESTERN RING ROAD BROADMEADOWS Towed To: VELLA DRIVE SUNSHINE TOWING 400.00 GST 40.00 TOTAL \$440.00	3/03/2022	11/04/2022
R130-0037900	1508	\$1,063.68	2010034	TIGHTEN LOOSE DASH AND SHIFTER REPLACE CIG LIGHT REPLACE RHF AIRBAG	26/02/2022	1/03/2022
R130-0037900	1508			REPLACE RHF AIRBAG	26/02/2022	1/03/2022
R130-0037900	1508			PRESSURE TEST AIR COMP CHARGE LINE FOR LEAKS FOUND TO BE LEAKING AROUND THE COUPLING AND NEARLY RUBBED THROUGH MID WAY ALONG THE HOSE REMOVE MEASURE UP NEW HOSE AND SWAP FITTINGS ACROSS AND RE-RUN TEST FOR I FAKS	26/02/2022	1/03/2022
R130-0037447	1508	\$251.49	1992958	HARD TO START CHECK BATTERIES CHECK CHARGING SYSTEM	10/02/2022	17/02/2022
R130-0037447	1508			AIR COMPRESSOR REPLACE GOVERNOR CHECK A/D FOR FAULT	10/02/2022	17/02/2022
R130-0037213	1508	\$707.59	1986206	Air con is not working CHECK A/C FOR FAULT CHECK BLOWER MOTOR VOLTAGE 12V REPLACE BLOWER CHECK A/C ON	3/02/2022	3/02/2022
R130-0037213	1508			SUZI COILS KINKED REPLACED SUZI COILS	3/02/2022	3/02/2022
R130-0037213	1508			TANK STRAP U/S	3/02/2022	3/02/2022
R130-0037035	1508	\$2,345.41	1981064	B SERVICE E5 CUMMINS COMPLETE B SERVICE REPAIR AIR LEAKS REPLACE INTAKE FILTER	25/01/2022	27/01/2022
R130-0037035	1508			GEARBOX OIL AND FILTER CHANGE	25/01/2022	27/01/2022
R130-0037035	1508			DRIVE AXLE WHEEL END COMPONENTS REPLACE LH FRONT DRIVE BRAKES AND HUB SEAL DUE TO LEAKING REPLACE RHS FRONT REAR BEARINGS AND SEALS REPLACE SHOES	25/01/2022	27/01/2022

R130-0037073	1508	\$1,163.25	1981064	SERVICE ON 15602391 MELB DEPOT 25.01.2022 HUBO 441385  11004496 - 295/80R22.5 152/148M BS R154 POS 1-2 33000051 - BALANCE TBR (Pos: 1, 2) 33000084 - FIT TBR TYRE (Pos: 1, 2) 77000104 FITZ CASE STOCK 205/80 22.5 (Pos: 1, 2)	25/01/2022	28/01/2022
R130-0036949	1508	\$2,494.58	1979036	CHECK TURNTABLE REPALCED TURN TABLE LOCK BAR AND JAW REPAIRED TURNTABLEHANDLE HOOK UP AND TEST TURNTABLE	20/01/2022	21/01/2022
R130-0036949	1508			DIFF LEAKING CHECK DIFF FOR LEAKS AND OIL LEVEL RESEAL AND REPLACED OIL AND FILTER	20/01/2022	21/01/2022
R130-0036949	1508			CABIN AIR BAG LEAK LIFT CAB AND SUPPORT REMOVE AND REPLACE DRIVERS SIDE CAB AIR BAG TEST FOR LEAKS	20/01/2022	21/01/2022
R150-0000235	1508	\$396.00	1979036	PO REQUEST #: 000041 19-1-21: Travel to Aeroplane rest area - Found latch for turn table missing clamp nut, fashioned up temporary measure as required. Will need further attention @ Lindsay's yard as advised Labour - Normal Rate \$132.00 GST \$12.00 \$132.00 160 TRV1 Travel - Per KM - Weekday \$1.65 GST \$24.00 \$264.00	19/01/2022	2/02/2022
R130-0036668	1508	\$105.00	1970169	CHECK ENGINE CODES FOUND AFTERTREATMENT CODES IN THE LAST 10 HOURS CLEAR CODES AND FLUSH ADBLUE SYSTEM VERIFY CHECK ENGINE LIGHT IS GONE	10/01/2022	11/01/2022
R130-0036580	1508	\$33.45	1966480	REPALCED LHS HEADLIGHT	4/01/2022	5/01/2022
R130-0036471	1508	\$19.14	1962630	REPLACED ANDERSON LEAD	24/12/2021	24/12/2021
R130-0035982	1508	\$620.63	1940017	BONNET STRUT U/S REPLACE R/S BONNET STRUT	2/12/2021	3/12/2021
R130-0035982	1508			INSTRUMENT PANEL CHECK RELAY FOR FAULT REPAIRED CONNECTION	2/12/2021	3/12/2021
R130-0035832	1508	\$242.47	1935152	GUARDIAN SYSTEMS ADJUST CAMERA CHECK X Y	26/11/2021	26/11/2021
R130-0035832	1508			WINDSHIELD WIPER & WASHER REPLACE WIPER BLADE FILL UP WASHER WATER	26/11/2021	26/11/2021
R130-0035832	1508			GUARDIAN SYSTEMS CHECK CAMERA FOR FAULT NO FAULT FOUND	26/11/2021	26/11/2021
R130-0035642	1508	\$18.75	1926607	BULBS, FUSES & WIRING - CLEARANCE / MARKER / INTERIOR LAMPS DASH LIGHTS NOT WOKRING REPALCED RELAY	16/11/2021	17/11/2021
R130-0035560	1508	\$1,501.60	1923206	B SERVICE REPLACE HEATER TAP& TOP UP COOLANT + SPARE BOTTLE REPLACE ELEC PLUG ON SPARE SUZIES ADJUST TURNTABLE JAWS ADJUST L/M WHEEL BEARING REPAIR DASH LIGHT REPAIR PARKER REPLACE LEACE BRACKET	12/11/2021	13/11/2021
R130-0035560	1508				12/11/2021	13/11/2021
R130-0035474	1508	\$111.98	1919415	REPLACED GOVERNOR AS FAULTY	6/11/2021	6/11/2021
R130-0035318	1508	\$484.23	1911439	FIXEDWIPER BLADE REPLACE JET	28/10/2021	30/10/2021
R130-0035318	1508			CHECK FAULT CODES FIX BROKEN WIRING FOR FUEL WATER READER REAPLCED FUEL SENSOR AND CABLE	28/10/2021	30/10/2021
R130-0034572	1508	\$1,897.18	1880424	PM CODES CHECK CODES PRESSURE TEST RADIATOR FOUND WATER PUMP LEAKING	22/09/2021	23/09/2021



R130-0034572	1508				WATER PUMP DRAIN COOLANT REMOVE ALTERNATOR AND TENSIONER, REMOVE COOLANT PUMP CORE AND REPLACE. ROAD TEST	22/09/2021	23/09/2021
R130-0034572	1508				LF STEER RIM CRACKED REPLACED BY BRIDGESTONE	22/09/2021	23/09/2021
R130-0034589	1508	\$33.00		1880424	SERVICE ORDER 15152209 MELB DEPOT 22.09.20212 HUBO 342881  Runout Tyre 295/80R22.5 - RTD - 6.0mm 01 33000051 - BALANCE TBR (Pos: 1) 33000084 - FIT TBR TYRE (Pos: 1) 33000370 - TYRE HILD FOR PUMOUT (Pos: 1)	22/09/2021	23/09/2021
R130-0034081	1508	\$235.14		1863957	GAUGES & WARNING DEVICES FIT OIL FILL CAP TOP UP OIL	26/08/2021	28/08/2021
R130-0034045	1508	\$1,651.89		1863108	CLEAN ENGINE AND CHASSIS B SERVICE E5 CUMMINS B SERVICE	25/08/2021	25/08/2021
R130-0034045	1508				REPLACED COOLANT FILTER FUEL TANK STRAPS	25/08/2021	25/08/2021
R130-0034045	1508				REPLACED FUEL TANK RUBBER LHS GUARDIAN SYSTEMS	25/08/2021	25/08/2021
R130-0033591	1508	\$3.75		1844265	ADJUSTED GUARDIAN CAMERA IFACE WONT TURN ON	28/07/2021	29/07/2021
R130-0033479	1508	\$102.08		1841568	CHECK IFACE + RESET + TEST ALL OK Left hand headlight is not working	22/07/2021	23/07/2021
R130-0033479	1508				REPLACED LEFT HEADLIGHT GLOBE AND ROOF LIGHTS SUN VISOR - EXTERIOR & INTERIOR	22/07/2021	23/07/2021
R130-0032970	1508	\$391.12		1822785	REPLACE CLIP RR HUB SEAL LEAKING	23/06/2021	23/06/2021
R130-0032829	1508	\$334.65		1817959	replaced wheel seal, hub qasket and brake shoes NO POWER CHECK CODES	16/06/2021	16/06/2021
R130-0032829	1508				REPLACED INJECTOR NOZZLE WITH GOOD SPARE FLUSG HOT WATER THROUGHT SYSTEM DRIVE TO CONFIRM FULL BOOST RFPL ACFD TIMING GEAR PLUG	16/06/2021	16/06/2021
R130-0032654	1508	\$127.00		1811162	INTAKE MANIFOLD REPLACED BOOST HOSE AND CLAMP	3/06/2021	7/06/2021
R130-0032440	1508	\$2,546.95		1805672	ABS, ANTI-LOCK SYSTEM CHANGED ABS LEAD REPLACE STEERING UNIS	24/05/2021	25/05/2021
R130-0032438	1508	\$1,267.03		1804473	SECURE UHF ANTENNA REPLACED KINGPINS L/S, ASSIST DAN WITH R/S, SMOOTH OFF STEEL IMPERFECTION AS UNABLE TO SHIM STUB PROPERLY. REALIGN STEERING WHEEL AND ROAD TEST. CI FAR ABS/ ESC FAULT B SERVICE B SERVICE	22/05/2021	24/05/2021
R130-0032259	1508	\$45.69		1791478	REPLACED GOVERNOR HOSES MADE UP SPARE SLIZI COILS	10/05/2021	10/05/2021
R130-0032245	1508	\$407.92		1789171	replace sender REPAIR BAD EARTH	7/05/2021	10/05/2021
R130-0032245	1508				CHECK ALL LIGHTS get footage of guardian	7/05/2021	10/05/2021
R130-0032245	1508				TOP UP FLUIDS	7/05/2021	10/05/2021
R130-0032245	1508				replaced oil sender pick up fitting from kenworth	7/05/2021	10/05/2021
R130-0031959	1508	\$69.75		1770408	SPEEDO NEEDS INSPECTING ROADTESTED OK	15/04/2021	19/04/2021
R130-0031869	1508	\$71.25		1765443	GUARDIAN SYSTEMS ADJUST CAMERA ALLIGNMENT	9/04/2021	9/04/2021
R130-0031445	1508	\$1,852.90		1741602	B SERVICE	12/03/2021	15/03/2021
R130-0031227	1508	\$331.84		1725456	INSPECT RH HEADLIGHT	25/02/2021	6/03/2021

R130-0031164	1508	\$5,258.00	1722319		SERVICE ORDER 14270490 MELB DEPOT 22.02.2021 ODO 186014  11001553 - 295/80R22.5 152/148M BS R150 01-02 11001472 - 11R22.5 148/145L BS M749 33000084 - FIT TBR TYRE (Pos: 1, 2, 5, 6, 7, 8, 9, 10, 11, 12) 33000370 - TYRE HELD FOR RUNOUT (Pos: 2, 5, 6, 7) 33000051 - BALANCE TBR (Pos: 1, 2) 77000194 SIZE: CASE STOCK 295/80-22.5 (Pos: 1) 77000222 SIZE: CASE STOCK 11R22.5 148/145L BS M749 (Pos: 2, 5, 6, 7, 8, 9, 10, 11, 12)	22/02/2021	25/02/2021
R130-0030950	1508	\$959.44	1711510		DRIVERS SEAT LUMBER SUPPORT - DRIVE FEELS LOOSE REMOVED DRIVE SHAFT AND TIGHTEN YOKE NUT TIGHTENED LOOSE STABILIZER BAR/BRACKETS	11/02/2021	11/02/2021
R130-0030950	1508				ENGINE MOUNTINGS REPLACED REAR ENGINE MOUNTS	11/02/2021	11/02/2021
R130-0030950	1508				FUEL TANK SUPPORT REPLACED TANK STRAP	11/02/2021	11/02/2021
R130-0030936	1508	\$2,092.42	1710529		DRIVERS SEAT LUMBER SUPPORT - DRIVE FEELS LOOSE REPLACED SEAT REMOUNT VIBRATION MOTOR RE SECURE INDICATOR STALK	10/02/2021	19/02/2021
R130-0030936	1508				GUARDIAN SYSTEMS	10/02/2021	19/02/2021
R130-0030698	1508	\$246.41	1696698		AFTERTREAT LIGHT ON CHECKED FOR CODES. CHECKED BREATHER, BLEW THROUGH LINES. HOT FLUSHED AND CHECKED INJECTOR - SOME HOLES BLOCKED BUT FOUND SPLIT ON BEND OF INJECTOR. REFITTED UNTIL PARTS AVAIL. CLEARED CODES AND SENT	29/01/2021	30/01/2021
R130-0030483	1508	\$1,751.86	1683681		B SERVICE B SERVICE REPLACED 4 REAR SLACK ADJUSTERS AS WINDING OFF REPLACED DASH GLOBE RESET GI LIGHT FIXED AND TESTED FLECC SUITZIE	18/01/2021	19/01/2021
R130-0030073	1508	\$1,437.24	1657079		LOOSING AIR PRESSURE CHECK FOR AIR LEAKS REPLACED PPV ON SECONDARY TANK REPLACED FILTER FOR HORTON REFITTED SUITZIE COILS AND FLECCIFAD	18/12/2020	19/12/2020
R130-0030073	1508				REPLACE TREADLE VALVE	18/12/2020	19/12/2020
R130-0030073	1508				REPLACE HORTON FILTER	18/12/2020	19/12/2020
R130-0029949	1508	\$756.85	1649092		DIFF HOUSING LEAKING RE SEAL REAR DIFF CLEAN FRONT DIFF STRAINER REPLACED DIFF OIL AND FILTER	11/12/2020	16/12/2020
R130-0029851	1508	\$18.75	1640800		LIGHTING SYSTEM	4/12/2020	5/12/2020
R130-0029616	1508	\$172.80	1628234		HEADLIGHT COVER U/S	23/11/2020	23/11/2020
R130-0029550	1508	\$2,860.00	1624944		21.10.20 TOWED FROM HUME HIGHWAY HOLBROOKE SOUTH TOWED TO CIMMINS LAVERTION A' TRAILER - 320 QRT / 'B' TRAILER - 321 QRT, TAKE KENWORTH PRIME MOVER (16 LBT) FROM, SUNSHINE AND CHANGE OVER AT BARNAWARTHA AND BRING BROKEN ONE RACK	18/11/2020	19/11/2020
R130-0029494	1508	\$2,043.52	1624944	13844.00	AIR CON NOT WORKING - R/H DOOR SKIN COMING OFF	16/11/2020	23/11/2020
R130-0029494	1508				B SERVICE	16/11/2020	23/11/2020
R130-0029494	1508				WIRING HANGING OFF	16/11/2020	23/11/2020
R130-0029494	1508				ASSET TRACKING	16/11/2020	23/11/2020
R130-0029409	1508	\$767.91	1620168		AIR CONDITIONING ASSEMBLY - COMPLETE	11/11/2020	13/11/2020

R130-0029302	1508	\$16,763.87	1613427		<p>APPROVED JB/BH 5.11.20 26.10.20 \cf0\fs20 Ticking / Knocking Noise in Engine-Cause: - Front Rocker Shaft / Broken @ No.3 Cylinder. - Cylinder Head / Fretted Due To The Above. - Heater Control Valve / Leaking. - Oil Pressure Sensor Malfunctioning. Connect inside and carry out ecm download. - Start and run engine to listen and verify customer's report of knocking sound. - Removed oil filter and cut open- found no traces of metal. - Removed valve cover to find one mounting bolt on front rocker shaft loose and no. 3 cylinder section of rocker shaft had cracked through and shaft was bent. Remove valve shaft and injector on no. 3 cyl, used bore scope to inspect cylinder for possible damage. No cylinder damage found. Attempted to insert a 7mm feeler gauge under remaining engine brake levers, could not insert gauge- indicating possible valve recession and may be the cause of rocker shaft failure. - Coolant stains were noticed around the header tankindicating possible pressurizing of the cooling system. - Drained coolant and removed cylinder head, cleaned block surfaces and measured liner heights- all within spec. - Measured turbo wastegate, is set at 0.060", in spec, camshaft idler shaft is out of spec, idler gear is ok. - Cleaned and inspected all other parts. - Found fretting in cylinder head from the broken rocker shaft which had created groove in the casting. - Develop repair plan and notified customer. - Tap out block threads for cylinder head mounting bolts,prepare new cylinder head for fitting to engine. - Remounted new stifner plate due to old plate being damaged on bolt removal, mounted oil pickup and sump, mounted and cable tied looming underneath. - Assembled rocker shaft, replaced front shaft due to being cracked/ bent, mounted intake manifold, fitted fuel rail fuel supply lines, cyl head exhaust manifold, turbo coolant housing on head, thermostat assy pipes, wiring radiator. - Fit rocker shafts, running clearance is 0.055 and 0.060", engine base timing done and fit front cover, completed tune up, assembled front of engine and radiator assy, mounted all piping and cable tied all looming, replaced heater control valve as it was damaged. - Complete up fitting OEM components to engine, fit fan hub, fan, radiator brackets, coolant pipes, CAC hoses, A/C comp, condenser, wiring, air box, zip tie looms, fill engine with oil and coolant, fitted new engine oil presensorexisting sensor was leaking oil and also causing an active fault code for oil pres sensor circuit. - De-isolate batteries, start and run engine, after engine start up, noticed an oil leak coming from an OEM oil feed hose used for engine oil filling. Removed hose and fitted a bung in place of the fitting. - Steam cleaned engine, road tested vehicle and checked over - all ok, paint engine. - Released vehicle back in service \cf1\fs16</p>	5/11/2020	5/11/2020
R191-0000158	1508	\$862.96	1607529		<p>APPROVED BH 29.10.20 22.10.20 \cf0 TRAVEL TO BREAKDOWN SOUTH OF HOLBROOK ON HWY-CHECK AND REPAIR KNOCKING NOISE COMING FROM ENGINE SOURCED PARTS, LOADED THE VAN AND TRAVELLED TO THE TRUCK. CONNECTED THE LAPTOP AND CHECKED FOR CODES. THE ONLY ACTIVE OIL PRESSURE SENSOR SHORTED TO HIGH. CHECKED OIL AND COOLANT LEVELS - ALL OK. REMOVED THE INTAKE PIPING GOING TO THE INTAKE ON THE HEAD. STARTED THE TRUCK AND FOUND IT WAS POPPING OUT OF THE INTAKE - POSSIBLE DROPPED VALVE. IT ALSO APPEARED TO HAVE COOLANT DRIBBLING OUT THE BOOST HOSE NEAR WHERE IT HAD BEEN REMOVED. ADVISED THE OWNER - OWNER ORGANISED A TOW TRUCK. TRAVELLED BACK TO THE WORKSHOP, UNLOADED THE VAN, CLEANED UP AND CARRIED OUT PAPERWORK. \cf1\fs2</p>	29/10/2020	10/11/2020
R130-0028880	1508	\$223.85	1591362		HEATING & VENTILATING	8/10/2020	9/10/2020
R130-0028479	1508	\$279.75	1573025		INSPECT PHONE	15/09/2020	21/09/2020
R130-0028290	1508	\$3,970.72	1565237	13098.00	PM for 000-002 Last Done: 12/06/2020 Interval: 60000 Utilization: 59814 AXLES - FRONT STEERING	2/09/2020	4/09/2020
R130-0028290	1508				CHECK TURNTABLE	2/09/2020	4/09/2020
R130-0028288	1508	\$130.60	1562673		BRAKES	1/09/2020	3/09/2020
R130-0027634	1508	\$398.04	1534669		SPEEDO GETTING STUCK	23/07/2020	27/07/2020
R130-0027555	1508	\$208.50	1530252		CHECK SPEEDO	18/07/2020	20/07/2020
R130-0027555	1508				CHECK ENGINE LIGHT	18/07/2020	20/07/2020
R130-0027420	1508	\$222.88	1521754		replace handle	9/07/2020	15/07/2020

R130-0027380	1508	\$18.75	1519899		check guardian for fault	7/07/2020	8/07/2020
R130-0026842	1508	\$1,001.00	1503574		SERVICE ORDER 13213488 MELB DEPOT 09.06.2020 ODO 535620 11001553 - 295/80R22.5 152/148M BS R150 POS 1-2 33000084 - FIT TBR TYRE POS 1-2 77000194 SIZE: CASE STOCK 295/80-22.5 - POS 1-2	9/06/2020	10/06/2020
R130-0026824	1508	\$4,030.88	1503601	12206.00	PM for 000-002 Last Done: 17/03/2020 Interval: 60000 Utilization: 57506	6/06/2020	16/06/2020
R130-0026313	1508	\$824.49	1484619		replace i face	13/05/2020	14/05/2020
R130-0026313	1508				PM CODES	13/05/2020	14/05/2020
R130-0026313	1508				UPHOLSTERY TRIM - CAB	13/05/2020	14/05/2020
R130-0025851	1508	\$127.50	1469134		CHECK IFACE	21/04/2020	22/04/2020
R130-0025825	1508	\$281.77	1469134		WONT START	20/04/2020	20/04/2020
R130-0025640	1508	\$421.11	1462647		inspect dash	7/04/2020	9/04/2020
R130-0025552	1508	\$202.50	1459705		check dash light for fault	2/04/2020	2/04/2020
R130-0025505	1508	\$164.68	1457751		POWER SUPPLY ISSUES	31/03/2020	31/03/2020
R130-0025516	1508	\$69.00	1457751		CHECK GAUGES	31/03/2020	31/03/2020
R130-0025369	1508	\$171.63	1451636		check codes	23/03/2020	23/03/2020
R130-0025264	1508	\$1,732.92	1444711		PM for 000-002 Last Done: 8/01/2020 Interval: 60000 Utilization: 59023	17/03/2020	18/03/2020
R130-0025232	1508	\$0.00	1444593		STEERING NEEDS TO BE LOOKED AT - WANDERING ALL OVER THE ROAD	16/03/2020	16/03/2020
R130-0025089	1508	\$112.50	1436322		WANDERING ALL OVER THE ROAD	5/03/2020	5/03/2020
R130-0024797	1508	\$3,982.00	1421966		8 X 11R22.5 M749 POSITION 5,6,7,8,9,10,11,12 8 X FIT 2 X RUNOUT 6 X TRADES FTSD-12813875	17/02/2020	18/02/2020
R130-0024552	1508	\$98.57	1408827		replace missing dash globes	3/02/2020	5/02/2020
R130-0024289	1508	\$231.75	1392294		check dash light for fault	16/01/2020	16/01/2020
R130-0024262	1508	\$363.00	1391440		CHECK CAB AC	15/01/2020	15/01/2020
R130-0024262	1508				GEAR SHIFTER IS LOOSE	15/01/2020	15/01/2020
R130-0024262	1508				CIGAR LIGHTER	15/01/2020	15/01/2020
R130-0024173	1508	\$30.00	1385688		check turntable	9/01/2020	10/01/2020
R130-0024126	1508	\$2,039.22	1385688		PM for 000-002 Last Done: 19/10/2019 Interval: 60000 Utilization: 59417	8/01/2020	8/01/2020
R130-0024126	1508				ADJUST CAMERA	8/01/2020	8/01/2020
R130-0024126	1508				DIFF OIL CHANGE	8/01/2020	8/01/2020
R130-0024126	1508				GEARBOX OIL CHANGE	8/01/2020	8/01/2020
R130-0023755	1508	\$38.50	1364149		1 X PUNCTURE REPAIR POSITION 10 FTSD-12616263	11/12/2019	13/12/2019
R130-0023462	1508	\$396.00	1349526		APPROVED BH 22.11.19 CODE:026-015 TOW FROM MELBOURNE MARKET GATE3 EPPING TO LINDSAY DEPOT AT SUNSHINE	22/11/2019	25/11/2019
R130-0023443	1508	\$1,001.00	1349526		2 X 295/80R22.5 R150 POSITION 1,2 2 X BALANCE 2 X FIT 2 X TRADES FTSD-12569203	21/11/2019	22/11/2019
R130-0023371	1508	\$487.50	1349526		BREAKDOWN AT MARKET FOR TRUCK NOT STARTING	18/11/2019	18/11/2019
R130-0023373	1508	\$4,106.68	1349526		WONT START	18/11/2019	22/11/2019
R130-0023373	1508				CHECK TRACKING	18/11/2019	22/11/2019
R130-0022959	1508	\$472.00	1326556		SPEEDO READING 110KM - NO CRUISE CONTROL, BUZZER WONT STOP GOING OFF	22/10/2019	23/10/2019
R130-0022930	1508	\$964.14	1326271	9609.00	CRUISE CONTROL STAYS ON	19/10/2019	21/10/2019
R130-0022930	1508				B SERVICE	19/10/2019	21/10/2019
R130-0022455	1508	\$87.75	1301754		DOWNLOAD GUARDIAN FOOTAGE	19/09/2019	21/09/2019
R130-0022375	1508	\$103.75	1299239		REPLACE SD CARD	16/09/2019	16/09/2019
R130-0022142	1508	\$32.25	1297666		CHECK PHONE	2/09/2019	2/09/2019

R120-0026657	1508	\$240.00	1295398		SIGNWRITING TO BE FIXED UP	30/08/2019	31/08/2019
R130-0021897	1508	\$466.50	1283893		STUCK ON CHANNEL	14/08/2019	14/08/2019
R131-0000991	1508	\$1,337.17	1279931		8.8.19 1508 REGO XN38HD KLMS 294108 \cf0\fs24 R1 BREAKDOWN \f2\fs14 Complaint: Customer reports vehicle broken down between Avenel and Euroa with coolant leak. After hours service call out to vehicle between Avenel and Euroa. Checked over vehicle and found hole in top radiator hose. Disconnected hose from header tank and thermostat housing, removed hose ends, cut new hose ends to fit new radiator pipe and refit pipe to vehicle. Tightened all hose clamps and filled vehicle with coolant. Labour \f2 Operation Amount BREAKDOWN 540.00 Parts \f2 Qty Num/Ref Unit Price Amount (F1) P/Cm-Hose 2.5"X4ply 30 X5581-250-1CM 1.71 51.30 (F1) Clamp-Hose 2.5" 4 KB9228: 0275B 8.31 33.24 (F1) Coolant-Kw-20ltsr - Pre 1 KALLC00L-20M 63.57 63.57 (F1) Call Out Fee 1 COUT 100.00 100.00 Sundry \f2 Qty Code Amount Call Out Fee 1.00 CO 120.00 Van Hire Per Klm 190.00 VA 285.00 Gtm - Workshop Supplies 1.50 WS 22.50 Total Item 1 1215.61 \fs24 Total Costs \f2\fs14 Total Invoice (excluding GST) 1215.61 Total Goods & Services Tax 121.56 \fs24 Total Invoice \fs14 (including GST) \fs24 1337.17	8/08/2019	15/08/2019
R130-0021619	1508	\$1,935.69	1268885		CHECK HEATER FAN	25/07/2019	30/07/2019
R130-0021619	1508				REPLACE TANK STRAPS + REPAIR DAMAGE	25/07/2019	30/07/2019
R120-0025979	1508	\$20,796.70	1265904	8705.00	CARRY OUT C SERVICE - CHECK PHONE OPERATION - REPLACE TANK STRAP RUBBER WHERE REQUIRED - FLIP ABS PLUG - REPLACE FEMALE TRAILER PLUG - REPLACE R/H GRILLE - TIDY ALL CHASSIS HARNESSSES - RE - LOCATE INLET ESCO HOSE - TIDY FUEL LINES RUBBING ON THE SUMP - TIGHEN BELLY BAR - TIGHEN FUL LINE AT JUNCTION AT GEARBOX - CHECK AUTO GREASER TIMING LITTLE GREASE AT MAJOR POINTS - TIDY SUZI COILS - HILL START ASSIST NOT WORKING	15/07/2019	24/07/2019
R120-0025979	1508				REPLACE DOSER PUMP AND FILTERS - SECURE ADBLUE INJECTOR LINE	15/07/2019	24/07/2019
R120-0025979	1508				SERVICE VIESA	15/07/2019	24/07/2019
R120-0025979	1508				REPLACE POWER STEERING OIL & FILTER. REPLACE STEER HUB OILS. TIDY STEER GREASE LINES - REPLACE STEER WHEEL BEARINGS	15/07/2019	24/07/2019
R120-0025979	1508				REKIT HORTON FAN REPLACE ALL BELTS & TENSIONERS	15/07/2019	24/07/2019
R120-0025979	1508				A/C COMPRESSOR BEARING	15/07/2019	24/07/2019
R120-0025979	1508				REKIT AIR DRYER	15/07/2019	24/07/2019
R120-0025979	1508				REPLACE OIL & COOLANT THERMOSTATS	15/07/2019	24/07/2019
R120-0025979	1508				R/R RADIATOR STRIP AND CLEAN IN HOUSE. REPLACE COOLANT AND FILTER. PRESSURE TEST INTERCOOLER - REPLACE SIGHT GLASS - REPLACE COOLANT TEMP SENDER FOR THE GAUGE - ADJUST RADAITOR OFF	15/07/2019	24/07/2019
R120-0025979	1508				REPLACE WATER PUMP	15/07/2019	24/07/2019
R120-0025979	1508				REPLACE ALTERNATOR - CHECK STARTER CABLES	15/07/2019	24/07/2019
R120-0025979	1508				REPLACE WIPER ARM ASSEMBLIES	15/07/2019	24/07/2019
R120-0025979	1508				INSPECT ALL TELL TAILS LIGHTS - RE LOCATE TRANSTECH DEVICE - REPLACE R/H SUNVISOR CLIP - REPLACE DAMAGED PHONE MIC - TIGHTEN SHIFTER CONSOLE - FIT UHF HAND PEICE CLIP - REPLACE FLOOR MATS - SPEAKER LOOSE - FULL DETAIL - REPLACE CAB STICKERS - REPLACE FIRST AID KIT - REPLACE STEERING WHEEL - MOVE GIRDIAN PROFESSOR	15/07/2019	24/07/2019
R120-0025979	1508				CHANGE DIFF FILTER	15/07/2019	24/07/2019
R120-0025979	1508				B SERVICE - CUMMINS E5	15/07/2019	24/07/2019
R120-0025979	1508				REPLACE REAR MUD GUARDS AND MUDFLAPS - STARIGHTEN REAR BAR - REPLACE REAR TAIL LIGHTS L/H	15/07/2019	24/07/2019
R120-0025979	1508				REPLACE TURNTABLE JAW AND LOCK KIT	15/07/2019	24/07/2019
R120-0025979	1508				REPLACE STOP, REVERSE AND BLINKER LIGHTS	15/07/2019	24/07/2019
R120-0025979	1508				REPLACE FRONT COVER BUNG - REMOVE HARMONIC BALANCER AND INSPECT FRONT MAIN SEAL - REPLACE FUEL PUMO IDLER COVER GASKET	15/07/2019	24/07/2019
R120-0025979	1508				RE-SEAL FRONT DIFF -	15/07/2019	24/07/2019
R120-0025979	1508				REMOVE STACKS - REPLACE FRONT J BRACKETS USE SECOND ONES FROM WHERE THE FUEL TANK WAS REMOVED - REPLACE SCR INLET GASKET - REPLACE EXHAUST DUMP RUBBERS	15/07/2019	24/07/2019

R120-0025979	1508				POLISH ALL DRIVE AND STEER RIMS	15/07/2019	24/07/2019
R120-0025979	1508				INSPECT BONNET AND GRILLE FOR DAMAGE REPLACE RH FRILLE AND HEADLIGHT PROTECTORS	15/07/2019	24/07/2019
R130-0020871	1508	\$550.00	1240345		13.6.19 1508 INSTALLATION OF GUARDIAN SERIAL NO. G2-SY-CON2-1001272 13.6.19 MELBOURNE P1001229-S00013985 SIM NUMBER 820004516214 4N	13/06/2019	9/07/2019
R130-0020780	1508	\$930.96	1235446		BREAKDOWN BREAKDOWN AFTER HOURS CALLOUT \$560.00 . The following breakdown repair for Lindsay Transport, to T409SAR Kenworth Truck, Chassis# 6F500000FA454110, Rego#XN38HD included: . * Customer contacted dealership to report breakdown * Customer advised that exhaust flex clamp failure * Technician met customer at TCTC workshop, McKoy St, Wodonga * Inspect exhaust components & confirmed failed exhaust flex gasket & clamp * Removed exhaust clamps, gasket, flex & components * Cleaned all components & gasket surface areas * Installed replacement gaskets, clamps, flex & components * Tensioned all components to specification * Start, test, confirm & quality check repair * Return vehicle to service . TRAVEL: NO TRAVEL REQUIRED 000kms @ \$1.40p/km (excluding gst) . AH CALLOUT TECHNICIAN (JWL) \$50.00 . Part Number Part Description Quantity Nett Value Total Cost M42-1002 GASKET-EXHAUST 4 INCH 1.00 22.89 22.89 CALL-OUT PARTS CALL-OUT FEE(AFTER HOURS) 1.00 150.00 150.00 90-0012 CLAMP-4" V-BAND 1.00 35.14 35.14 3.00 \$208.03 REGO: 2XN38HD KLMS: 1,249,196	5/06/2019	16/07/2019
R130-0020510	1508	\$4,037.00	1222629		8 X 11R22.5 M749 POSITION 5.6.7.8.9.10.11.12 8 X FIT 5 X TRADES FTSD-11917465	20/05/2019	22/05/2019
R130-0020226	1508	\$835.86	1211650	7900.00	B SERVICE	4/05/2019	6/05/2019
R130-0019969	1508	\$1,733.75	1196818		APPROVED BH 15.4.19 CODE: 045 ADDITIONAL PARTS USED DURING ENGINE REBUILD-REFER QUOTE # 6353631 WORKSHOP PROPOSAL 5.4.19 REGO: NV97HS KLMS: 1.146.639	15/04/2019	16/04/2019
R130-0019630	1508	\$2,035.50	1178029		APPROVED BH 25.3.19 CODE: 032 13.3.19 CALLOUT TO AEROPLANE HILL TRUCK STOP FAULT CODES GEAR SELECTION COMING UP 14.3.19 CALLOUT TO GLENROWAN PARKING BAY -VEHICLE NOT STARTING STARTER LOCKOUT RELAY -BYPASSED RELAY TESTED OK REGO: XN.38HD ODO: 178.000	25/03/2019	15/04/2019
R130-0019573	1508	\$1,875.01	1173854		APPROVED BH 21.3.19 8.3.19 CALLOUT FOUND TRUCK NOT STARTING-AUTO SHIFT FAULT CODE 17 STARTER LOCK OUT RELAY TEST & FOUND FINEBUT NOT GETTING SWITCH FROM ECU BYPASS RELAY TEST & FOUND START ALL OK & SENT DRIVE ON HIS WAY REGO: XN38HD KLMS: 176,191 RO: 5156768	21/03/2019	17/04/2019
R130-0019454	1508	\$933.00	1168181		CHECK STARTING SYSTEM	15/03/2019	16/03/2019
R130-0019435	1508	\$199.50	1167514		INTERMITTENT STARTING ISSUES	14/03/2019	14/03/2019
R130-0019414	1508	\$3,258.06	1165712		APPROVED BY BH 12.3.19 MATHEW ADVISED CODE: 023-002	13/03/2019	13/03/2019
R130-0019366	1508	\$301.10	1162871		CHECK TRANSMISSION	9/03/2019	12/03/2019
R130-0019231	1508	\$20,113.79	1153869		APPROVED BH 28.2.19 CODE: 045 ENGINE REBUILD FOR MAINTENANCE-STRIP DOWN ENGINE TO REMOVE PISTONS AND LINERS- REFIT ALL REMOVED PARTS NEW CYLINDER HEAD AND TURBO-VEHICLE RETURNED TO SERVICE REGO: NV97HC KLMS: 1146639	28/02/2019	7/03/2019
R122-0022444	1508	\$1,012.00	1145969		2 X 295/80R22.5 R150 POSITION 1,2 2 X FIT 2 X TRADES 2 X RTT EQUAL FTSD-11656679	20/02/2019	21/02/2019
R122-0022421	1508	\$742.34	1145154		B-SERVICE E5 CUMMINS	19/02/2019	19/02/2019
R122-0022421	1508				SEND TO BIG WHEELS FOR ALIGNMENT	19/02/2019	19/02/2019
R122-0022439	1508	\$679.25	1145154		19.2.19 REGO XN38HD 17 Vehicle Rego # : XN38HD - Fleet # : 1508 1 S&R Shake & Report 75.00 \$82.50 1 WA Wheel Alignment 195.00 \$214.50 1 CA Caster Adjustment 75.00 \$82.50 2 DA Drive Alignment 125.00 \$275.00 1 WS Workshop Consumables 22.50 \$24.75	19/02/2019	21/02/2019
R130-0019045	1508	\$123.03	1144564		REPLACE ABS LEAD	18/02/2019	18/02/2019
R130-0018964	1508	\$220.14	1142872		REPLACE VISOR CLIPS	14/02/2019	14/02/2019
R130-0018964	1508				REPLACE IFACE	14/02/2019	14/02/2019

R122-0022322	1508	\$825.42	1142872		9.2.19 1508 REGO NV97HC KLMS 152240 LABOUR ROADSIDE REPAIRS TRAVEL TO BREAKDOWN CHECK AND REPAIR TRUCK WON'T BUILD UP AIR. ***** SOURCED PARTS, LOADED THE VAN AND TRAVELLED TO THE TRUCK AT AEROPLANE HILL. INSPECTED AND FOUND THE COMPRESSOR HOT LINE TO BE LOOSE. REFITTED SECURELY AND STARTED THE TRUCK. BUILT UP AIR AND CHECKED FOR LEAKS - NONE FOUND. RETURN THE TRUCK TO SERVICE. TRAVELLED BACK TO THE WORKSHOP, UNLOADED THE VAN, CLEANED UP AND CARRIED OUT PAPERWORK . ***** Labour ROADSIDE REPAIRS 524.64 Others VEHICLE KILOMETERAGE 128 202.24 WORKSHOP SUPPLIES 1 23.50 Sub Total ExGST: 750.38 CHECK OUT	12/02/2019	20/03/2019
R130-0018639	1508	\$369.82	1137390		REPLACE RF MODULATION VALVE	22/01/2019	29/01/2019
R130-0018624	1508	\$841.25	1136828		RESEAL REAR DIFF	21/01/2019	22/01/2019
R130-0018606	1508	\$672.37	1135816		REPLACE MATTRESS	18/01/2019	19/01/2019
R130-0018393	1508	\$1,141.83	1126286		CHECK BRAKES	8/01/2019	11/01/2019
R130-0018393	1508				REPLACE FRONT DIFF SEAL	8/01/2019	11/01/2019
R130-0018365	1508	\$1,001.00	1123586		2 X 295/80R150 POSITION 1,2 2 X BALANCE 2 X FIT 2 X TRADES FTSD-11534639	4/01/2019	7/01/2019
R130-0018284	1508	\$43.16	1120734		INSPECT EXHAUST STACK	31/12/2018	3/01/2019
R130-0018257	1508	\$42.80	1117783		REPLACED TRAILER PLUG	28/12/2018	28/12/2018
R130-0018063	1508	\$60.00	1105053		INSPECT STEER TYRES.	13/12/2018	17/12/2018
R130-0017822	1508	\$1,452.73	1095559	6231.00	B SERVICE	1/12/2018	3/12/2018
R130-0017393	1508	\$8,945.83	1080276	6004.00	B SERVICE	5/11/2018	17/11/2018
R130-0017393	1508				REPLACE ENGINE MOUNTS AND CAB MOUNTS	5/11/2018	17/11/2018
R130-0017393	1508				REPLACE KING PINS	5/11/2018	17/11/2018
R130-0017393	1508				REPLACE BUSHES	5/11/2018	17/11/2018
R130-0017393	1508				REPLACE DRAG LINK + TIE ROD ENDS + KING PINS	5/11/2018	17/11/2018
R130-0017393	1508				REPLACE SHOCKY BUSHES	5/11/2018	17/11/2018
R130-0017412	1508	\$1,936.00	1076454		4 X 11R22.5 M749 POSITION 5,6,7,8 4 X FIT 4 X TRADES FTSD-11351534	5/11/2018	7/11/2018
R130-0017034	1508	\$1,008.68	1053001		LOW BOOST	11/10/2018	11/10/2018
R130-0016421	1508	\$5.30	1015168		REPLACE TRAILER PLUG	27/08/2018	30/08/2018
R120-0021221	1508	\$1,383.99	1012932		1 X 295/80R22.5 R150 1 X ETA 66749 4 X CALLOUT 1 X FIT 1 X SCRAP ETA-67749	23/08/2018	31/08/2018
R130-0016360	1508	\$777.47	1013445	5035.00	B SERVICE SIF 21745529	23/08/2018	24/08/2018
R130-0016365	1508	\$1,991.00	1012932		4 X 11R22.5 M749 POSITION 9,10,11,12 4 X FIT 1 X RUNOUT 3 X TRADES FTSD-11128729	23/08/2018	24/08/2018
R130-0016240	1508	\$528.00	1006096		1 X 295/80R22.5 R150 POSITION 1 1 X FIT 1 X RUNOUT FTSD-11103011	15/08/2018	16/08/2018
R130-0016098	1508	\$109.85	1001006		SPOTTER MIRROR NEEDS TO BE REPAIRED	8/08/2018	14/08/2018
R130-0016098	1508				AXLES - DRIVEN, REAR	8/08/2018	14/08/2018
R130-0016098	1508				REPLACE SPOTTER MIRROR	8/08/2018	14/08/2018
R130-0016008	1508	\$166.42	995536		REPLACE AXLE GASKET	2/08/2018	3/08/2018
R130-0015645	1508	\$440.00	976846		REPLACE BOTH SCREENS	11/07/2018	12/07/2018
R130-0015468	1508	\$46.81	968154		INSPECT EXHAUST FLEX	2/07/2018	2/07/2018
R130-0015360	1508	\$1,486.64	962600		REPLACE STARTER.	25/06/2018	26/06/2018
R130-0015360	1508				LOW ON POWER	25/06/2018	26/06/2018
R130-0015058	1508	\$855.84	947886	4074.00	B SERVICE SAMPLE SIF 21745532	5/06/2018	7/06/2018
R130-0015058	1508				AXLES - DRIVEN, REAR	5/06/2018	7/06/2018
R130-0015011	1508	\$594.00	942709		BREAKDOWN TRUCK TOWED TO WORKSHOP FOR CUMMI NS REPLACE COMPRESSOR UNDER WARRANTY	31/05/2018	4/06/2018
R130-0014923	1508	\$90.00	938537		COMPRESSOR FASILED CUMMINS WARRANTY TO REPLACE WE FIT DRIVE SHAFT	25/05/2018	25/05/2018
R130-0014663	1508	\$279.86	924541		REPLACE EX FLEX	8/05/2018	8/05/2018

R130-0014636	1508	\$29.06	923861		REPLACE R/F DRIVE AXLE GASKET	7/05/2018	7/05/2018
R130-0013938	1508	\$240.64	889763		REPLACE WEAR PADS	26/03/2018	27/03/2018
R122-0016960	1508	\$730.50	886062	3162.00	B-SERVICE E5 CUMMINS	19/03/2018	20/03/2018
R130-0013751	1508	\$3.75	878227		REPLACE ELECT SOCKET	14/03/2018	15/03/2018
R122-0016423	1508	\$1,715.40	859253		PO REQUESTED BY BILLY 20.2.18 REGO: NV97HC KLMS: 862455 CALL OUT TO TARCUTTA ALTERNATOR WON'T CHARGE REMOVED & REPLACED ALTERNATOR PRICE AS PER PROFORMA R502033 10 X PRESSURE CHECK FTSD-10646857	20/02/2018	20/02/2018
R130-0013125	1508	\$19.80	855539		TEMP GAUGE NOT WORKING.	14/02/2018	15/02/2018
R130-0012761	1508	\$613.11	840491		REPLACE AXLE GASKETS	29/01/2018	31/01/2018
R130-0012651	1508	\$7.10	832846		FIT BUMPER FROM COFFS	19/01/2018	22/01/2018
R130-0012557	1508	\$156.00	829633		TRANSMISSION - AUTOMATIC	15/01/2018	16/01/2018
R130-0012511	1508	\$543.87	826757		CHECK/REPLACE DRIVE BRAKES	12/01/2018	15/01/2018
R130-0012511	1508					12/01/2018	15/01/2018
R122-0015721	1508	\$1,907.27	825441	2346.00	B-SERVICE E5 CUMMINS	10/01/2018	18/01/2018
R122-0015721	1508				REPLACE FRONT DIFF TORQUE ROD BUSHES	10/01/2018	18/01/2018
R122-0015721	1508				REPLACE MAIN AIR LINE FROM COMPRESSOR TO DRIER	10/01/2018	18/01/2018
R130-0012374	1508	\$377.99	818412		INSPECT REPLACE BUMPER	4/01/2018	5/01/2018
R122-0015499	1508	\$1,056.00	814606		B/STONE FIT 2X 295/80/22.5 R150 POOS 1/2 AND BALANCE FTSD 1496155	27/12/2017	11/01/2018
R122-0015311	1508	\$4,092.00	804859		8 X 11R22.5 M749 POSITION 5,6,7,8,9,10,11,12 4 X TRADES 4 X RUNOUT 4 X TRADES FTSD-1502707	12/12/2017	18/12/2017
R130-0011961	1508	\$19.80	799318		10 X PRESSURE CHECK POSITION 1 TO 12 FTSD-10288825	5/12/2017	6/12/2017
R122-0015076	1508	\$1,366.54	792820		REPLACE R/H CAB AIR BAG	29/11/2017	30/11/2017
R122-0015076	1508				REPLACE NOX SENSOR	29/11/2017	30/11/2017
R122-0015076	1508				REPLACE UHF + MIC	29/11/2017	30/11/2017
R122-0014831	1508	\$11.00	778141		2 X FLIP ON RIM POSITION 1,2 2 X FIT FTSD-1505473	15/11/2017	16/11/2017
R130-0011351	1508	\$420.31	763929		REPLACE CAB AIR BAG.	31/10/2017	1/11/2017
R122-0014433	1508	\$19.80	761448		P-CHECK x 10 FTSD-	27/10/2017	30/10/2017
R130-0011254	1508	\$883.91	761448		B SERVICE.	26/10/2017	27/10/2017
R130-0011254	1508				INSPECT RADIO.	26/10/2017	27/10/2017
R120-0015616	1508	\$1,401.25	736100		REPAIR CRANK NO START..STARTER MOTOR TO BE FAULTY.REMOVE & REPLACED STARTER MOTOR. CHECK OPERATION	28/09/2017	4/10/2017
R155-0004238	1508	\$22.00	729415		1 X 11R22.5 RUNOUT POSITION 10 1 X SCRAP 1 X FIT FTSD-1610966	21/09/2017	25/09/2017
R122-0013644	1508	\$37.84	725515		STEER ROTATION, STRAIGHT LEFT TO RIGHT, P-CHECK DRIVE, FTSD-1535493	18/09/2017	21/09/2017
R122-0013411	1508	\$447.27	715790		COOLANT LEAK	4/09/2017	4/09/2017
R140-0029220	1508	\$401.14	713145		TEMP GAUGE IS NOT WORKING	1/09/2017	23/10/2017
R130-0010040	1508	\$1,041.80	701237		B SERVICE SAMPLE SIF 21750673	14/08/2017	18/08/2017
R130-0010040	1508				Default PlanWOULD LIKE A NEW RADIO	14/08/2017	18/08/2017
R130-0009904	1508	\$61.46	689961		REPLACE PLUG ON ELEC LEAD.	4/08/2017	7/08/2017
R130-0009273	1508	\$240.32	672343		WEATHER SHIELD BROKEN	6/07/2017	10/07/2017
R130-0009273	1508				MISSING SOME NUT COVERS	6/07/2017	10/07/2017
R130-0009247	1508	\$583.19	671435		REPAIR AND REFIT SEAT BASE	5/07/2017	5/07/2017
R130-0009169	1508	\$58.50	667931		SEND BASE FOR REBUILD AND REFIT	30/06/2017	30/06/2017
R122-0011888	1508	\$935.00	657766		REPLACE STEER TYRES WITH 295 'R150, TRADE-IN x 2 FTSD- 1406328	16/06/2017	22/06/2017
R122-0011806	1508	\$40.22	655132		REPLACE R/H/F AXLE GASKET	13/06/2017	14/06/2017
R130-0008607	1508	\$863.57	641511	1946.00	B SERVICE SAMPLE K1557507	29/05/2017	31/05/2017
R130-0008306	1508	\$45.02			FIT NEW LATCH	12/05/2017	12/05/2017
R155-0003201	1508	\$20.92	619333		REPLACE BLOWN HEADLIGHT	3/05/2017	5/05/2017
R155-0003201	1508				WATER LEAKING THROUGH CAB	3/05/2017	5/05/2017



R122-0010770	1508	\$626.47	610452		replace batteries	20/04/2017	21/04/2017
R122-0010746	1508	\$37.84	609119		STEER ROTATION, P-CHECK x 10, FTSD-1362731	18/04/2017	1/06/2017
R130-0007772	1508	\$76.50	602353		BROKEN EXHAUST FLEX	5/04/2017	6/04/2017
R120-0012194	1508	\$1,040.02	597926		CALLOUT TO GUNDAGAI GEARBOX WON'T SELECT.CHECK FOR FAULTS.FOUND CODES FOR THE INPUT SHAFT WORN.GREASE THE INPUT SHAFT. TEST ALL OK.(CLUTCH NEEDS REPLACING)	31/03/2017	3/04/2017
R120-0012124	1508	\$3,863.92	594846		CLUTCH NOT ENGAGING.REMOVE TAILSHAFT,AIR TANKS,EXHAUST PIPING,AIRLINES & ELECTRICAL PLUGS.REMOVE SPRING PLATE,SUPPORT BOX ON GEARBOX JACK.REMOVE BELLHOUSING BOLTS,REMOVE GEARBOX.FIT SHIPPING BOLTS,REMOVE CLUTCH/FLYWHEEL.FOUND REAR MAIN LEAKING.FIT FLYWHEEL & TENSION.FIT CLUTCH & TENSION.RE-FIT COMPONENTS THAT HAD BEEN REMOVED.CARRY OUT CLUTCH DATA RESET & ADJUST.GREASE INPUT SHAFT.TEST DROVE & RECHECK	27/03/2017	27/03/2017
R130-0007621	1508	\$432.18	591150		REPAIR AIR LEAKS	23/03/2017	27/03/2017
R130-0007621	1508				REPALCE EX FLEX	23/03/2017	27/03/2017
R130-0007621	1508				REWPLACE L/F FUEL TANK STRAP	23/03/2017	27/03/2017
R122-0010306	1508	\$641.81	590286		BIG WHEELS... WHEEL ALIGNMENT, 20-3-17 589774 KM	22/03/2017	23/03/2017
R120-0011940	1508	\$375.00	588837		SUBLET CLUTCH REPLACEMENT TO BROWN AND HURLEY - CLUTCH WAS DONE AS A GOOD WILL. WE SUPPLY LABOUR TO ASSIST	20/03/2017	20/03/2017
R122-0010240	1508	\$37.50	588837		NEEDS A WHEELO	20/03/2017	21/03/2017
R122-0010161	1508	\$185.25	586952		TRANS WILL NOT SHIFT TAKE TO G&R FOR REPAIR 588 383 KM	15/03/2017	16/03/2017
R130-0007501	1508	\$141.00	586418		INSPECT CLUTCH AND GEARBOX FAULTS	14/03/2017	14/03/2017
R122-0010096	1508	\$22.00	584757		STEER ROTATION, TURNED ON RIMS, P-CHECK x 8 FTSD- 1361589	11/03/2017	30/05/2017
R130-0007483	1508	\$230.25	584757		ULTRASHIFT FAULT CODES	11/03/2017	15/03/2017
R130-0007434	1508	\$910.07	583175	1198.00	B SERVICE E5 CUMMINS	8/03/2017	9/03/2017
R130-0007346	1508	\$438.00	578726		REPLACE GUARDS	2/03/2017	3/03/2017
R122-0009840	1508	\$4,576.00	576133		REPLACE ALL DRIVE TYRES WITH 11R M749, 8 x CASES, FTSD-1361078	27/02/2017	3/03/2017
R122-0009765	1508	\$126.00	572211		TEMP SENDER IS READING THE WRONG TEMP	23/02/2017	24/02/2017
R122-0009766	1508	\$47.25	572211		AIR LEAK ON THE STEER AXLE	23/02/2017	24/02/2017
R130-0006977	1508	\$300.00	557658		CALLOUT TO FIX AIR LEAK AT FAN HUB	8/02/2017	8/02/2017
R130-0006975	1508	\$151.50	557331		REPAIR AIR LEAKS	7/02/2017	10/02/2017
R130-0006550	1508	\$19.80	537916		10 X PRESSURE CHECK POSITION 3-12 FTSD-1331709	13/01/2017	16/01/2017
R130-0006503	1508	\$309.75	536289		CHECK AUTO GREASER OPERATION	11/01/2017	12/01/2017
R122-0008610	1508	\$389.13	527279		AXLE GASKET LEAKING	29/12/2016	29/12/2016
R122-0008610	1508				REPLACE TRANS OIL	29/12/2016	29/12/2016
R130-0006277	1508	\$328.38	527279		AUTO GREASER LEAKING OUT OF KING PINS	28/12/2016	30/12/2016
R130-0006277	1508				B SERVICE	28/12/2016	30/12/2016
R130-0006252	1508	\$63.50	525129		REPLACE L/F DRIVE AXLE GASKET	22/12/2016	22/12/2016
R130-0006071	1508	\$195.25	516511		REPLACE DAYTIME RUNNING LIGHTS DUE TO BROKEN	12/12/2016	15/12/2016
R130-0005947	1508	\$123.34	509420		REPLACE F/R DRIVE AXLE GASKET	2/12/2016	5/12/2016
R130-0005947	1508				AIR TYPE POWER BRAKES	2/12/2016	5/12/2016
R130-0005928	1508	\$990.00	508493		2 X 295/80 22.5 R150 POSITION 1.2 1 X TRADES 1 X RUNOUT FTSD-1304453	1/12/2016	5/12/2016
R130-0005353	1508	\$34.32	484971		1 X RUNOUT 11R22.5 POSITION 4 1 X SCRAP 9 X PRESSURE CHECK POSITION 1-10 FTSD-982990	28/10/2016	31/10/2016
R122-0006979	1508	\$41.80	475588		STEER ROTATION, P-CHECK FTSD-1071895	18/10/2016	20/10/2016
R130-0005064	1508	\$26.25	470359		REPAIR WIPERS	12/10/2016	13/10/2016
R140-0014582	1508	\$99.00	466831		REPLACE LEAKING AIR COMPRESSOR HOT LINE	7/10/2016	14/10/2016
R130-0004926	1508	\$655.29	465850		B SERVICE SAMPLE K1549415	5/10/2016	6/10/2016
R130-0004926	1508				HOSE - COMPRESSOR TO CONDENSER, HVAC SYSTEM	5/10/2016	6/10/2016
R120-0006013	1508	\$330.00	385358		service radiator	5/07/2016	7/07/2016

R120-0005988	1508	\$22,333.87	391262	C SERVICE	4/07/2016	14/07/2016
R120-0005988	1508			CHECK ABS	4/07/2016	14/07/2016
R120-0005988	1508			REPLACE ADBLU FILTERS	4/07/2016	14/07/2016
R120-0005988	1508			SERVICE VIESA	4/07/2016	14/07/2016
R120-0005988	1508			REPLACE STEER OILS	4/07/2016	14/07/2016
R120-0005988	1508			ENGINE TUNE REPLACE SPOOL VALVES	4/07/2016	14/07/2016
R120-0005988	1508			KIT HORTON IDLERS AND TENSIONERS	4/07/2016	14/07/2016
R120-0005988	1508			REPLACE WATER PUMP	4/07/2016	14/07/2016
R120-0005988	1508			REMOVE RADIATOR AND SEND TO NATRAD	4/07/2016	14/07/2016
R120-0005988	1508			REPLACE THERMOSTATS	4/07/2016	14/07/2016
R120-0005988	1508			A/C BEARING	4/07/2016	14/07/2016
R120-0005988	1508			REPLACE ALTERNATOR	4/07/2016	14/07/2016
R120-0005988	1508			KIT AIR DRIER	4/07/2016	14/07/2016
R120-0005988	1508			REPLACE POWER STEER OIL AND FILTER	4/07/2016	14/07/2016
R120-0005988	1508			TEST AND CLEAN	4/07/2016	14/07/2016
R120-0005988	1508			REPLACE DOSER PUMP	4/07/2016	14/07/2016
R120-0005988	1508			REPLACE AIR COMPRESSOR	4/07/2016	14/07/2016
R120-0005988	1508			REPLACE TURBO	4/07/2016	14/07/2016
R120-0005988	1508			REPLACE OIL THERMOSTAT	4/07/2016	14/07/2016
R120-0005988	1508			REPLACE STARTER	4/07/2016	14/07/2016
R120-0005988	1508			B SERVICE - CUMMINS E5	4/07/2016	14/07/2016
R120-0005988	1508			FIT TRANSTECH SPEED ALARM	4/07/2016	14/07/2016
R120-0005988	1508			REPLACE SUZI COILS REMOUNT ANDERSON PLUG	4/07/2016	14/07/2016
R120-0005988	1508			WARRANTY- EXHAUST MANIFOLD LEAKING	4/07/2016	14/07/2016
R120-0005988	1508			REPLACE EXHAUST FLEX AT GBOX EXHAUST MOUNTS AT BLOCK	4/07/2016	14/07/2016
R120-0005988	1508			WARRANTY- FUEL PUMP LEAKING	4/07/2016	14/07/2016
R120-0005988	1508			REPLACE STEER UNIS	4/07/2016	14/07/2016
R120-0005988	1508			CHECK OPERATON OF GREASER GREASE ALL POINTS FIT GREASE LINE TO TURNTABLE	4/07/2016	14/07/2016
R120-0005988	1508			TENSION U BOLTS	4/07/2016	14/07/2016
R120-0005988	1508			FRONT ENGNE MOUNTS	4/07/2016	14/07/2016
R120-0005988	1508			WARRANTY-INSPECTION PLATE LEAKING -SPLITTER LEAKING	4/07/2016	14/07/2016
R120-0005988	1508			FIT INLET ESOC	4/07/2016	14/07/2016
R120-0005988	1508			REPLACE HEATER TAPS HEATER PIPE BRACKET BROKEN	4/07/2016	14/07/2016
R120-0005988	1508			RELINE REAR DRIVE AXLE	4/07/2016	14/07/2016
R120-0005988	1508			WARRANTY- RESEAL FRONT AND REAR DIFFS	4/07/2016	14/07/2016
R120-0005988	1508			REPLACE VARIOUS TANK STRAP RUBBERS	4/07/2016	14/07/2016
R120-0005988	1508			ADJUST TURNTABLE	4/07/2016	14/07/2016
R120-0005988	1508			LH DOOR SEAL INSECURE	4/07/2016	14/07/2016
R120-0005988	1508			LH GRAB HANDLE LOOSE	4/07/2016	14/07/2016
R120-0005988	1508			DETAIL FIT ALL STICKERS SUNVISOR CLIP	4/07/2016	14/07/2016
R120-0005988	1508			CHECK GAUGES AND LIGHTS	4/07/2016	14/07/2016
R120-0005988	1508			POLISH RIMS	4/07/2016	14/07/2016
R122-0004418	1508	\$71.25	385358	REPLACE OIL PRESSURE RELIEF VALVE	4/07/2016	5/07/2016
R122-0003098	1508	\$30.00	342405	STEERING WANDERING SEND TO BIG WHEELS TO HAVE STEERING CHECKED NO CHARGE AS HAD ALIGNMENT MONTH EARLIER\y0	3/05/2016	3/05/2016
R122-0003098	1508			CHECK SPEED ALERT	3/05/2016	3/05/2016
R130-0002062	1508	\$37.50	332407	SEND TO K/W FOR WARRANTY CHECK OVER	20/04/2016	20/04/2016

R130-0002026	1508	\$620.95	332049	B SERVICE CHECK OVER FOR K/W WARRANTY REPAIRS SAMPLE K1540698	19/04/2016	20/04/2016
R120-0003499	1508	\$775.50	326261	CARRY OUT WHEEL ALIGNMENT	11/04/2016	15/04/2016
R130-0001718	1508	\$4,139.96	320899	8 X 11R M749 2 X P/CHECKS FTSD 906526	4/04/2016	5/04/2016
R122-0002414	1508	\$935.00	313668	B/STONE... REPLACE STEER TYRES WITH 295 'R150, 2 x 295 TRADE-IN, FTSD-1012774	24/03/2016	29/03/2016
R130-0001260	1508	\$44.62	297033	INSPECT REPAIR AIR LEAK ON FRONT RIGHT	1/03/2016	1/03/2016
R155-0000509	1508	\$828.90	293074	B SERVICE DUE	25/02/2016	16/03/2016
R140-0003371	1508	\$78.65	286714	FIT TURNTABLE WORKLIGHT- SUBLET TO PTE.	16/02/2016	1/03/2016
R130-0000636	1508	\$129.80	269541	2 X ROTATE POS 1-2 8 X PRESSURE CHECK POS 3-10 FTSD 895371	20/01/2016	2/02/2016
R122-0000889	1508	\$22.00	268492	2 X ROTATE POS 1-2 FTSD 859965	19/01/2016	1/02/2016
R130-0000609	1508	\$0.00	268492	ROTATE DRIVE TYRES . DONE BY BRIDGESTONE \f0	19/01/2016	19/01/2016
R130-0000255	1508	\$509.97	252040	B SERVICE. SAMPLE K1532616	22/12/2015	23/12/2015
R130-0000038	1508	\$27.83	241878	REPLACE R/F DRIVE AXLE GASKET	11/12/2015	14/12/2015