

Finished Date/Tim Description

230k service - Aztech

230,000km log book service:

- Engine oil and oil filter

- Air filter

- Cabin filter

26/07/2023

26/06/2023 Repairs - Aztech - Remove and replace both front rack ends

30/03/2023 220000 km service - Aztech

18/04/2023 Rego & CTP Renewal

13/09/2022 Replace windscreen - O'Briens Insurance

2/08/2022 DPF Replacement - Toyota recall

Repairs - Horn - Aztech

Checked for cause of horn inop. Checked fuses and relays, seemed ok. Removed upper cover to gain access to horn. Checked for power and earth, earth intermittent,

14/07/2022 -Removed horn and and repaired contact, re fit and re test

Blowing smoke. - GB Auto

01/06/22 - Carried out DPF regeneration (burn). Diagnose DPF requires replacing.

Following component of job charged to MCC

Install light bar /Horn not working

02/06/22 - Installed LED lightbar & wired in.

07/06/22 - Removed steering wheel, replaced clock spring & re-assembled. Horn now working intermittently, tested

7/07/2022 wiring to horn, all OK. Replaced horn & tested OK.

2 new tyres

8/07/2022 Toyo 265/65R17 120R OPEN COUNTRY AT2 TLWSW

200000km Service - GB Auto

200,00km service.

02/06/22 - Carried out 200,000 km major service. Wash down excessive mud. Replaced engine oil, air, cabin & fuel filters. Replace front & rear diff oils. Adjusted handbrake. Topped up fluids & inspected vehicle. Road test ok.

Following repairs undertaken by MCC

Blowing smoke/Horn not working

01/06/22 - Carried out DPF regeneration (burn). Diagnose DPF requires replacing. Diagnosed horn not working, requires new clock spring.

02/06/22 - Installed LED lightbar & wired in.

07/06/22 - Removed steering wheel, replaced clock spring & re-assembled. Horn still not working, tested wiring to horn,

7/06/2022 all OK. Replaced horn & tested OK.

13/04/2022 UF59 Renew rego & CTP EXP 26.4.2022

UF59 Repairs - Aztech Inv21073 - Done

- Air filter

- Cabin filter

- Fuel filter

- Adjust hand brake (at wheels)

5/04/2022 - Replaced wiper blades

190000km Service - Aztech - Inv 21048

28/03/2022

Carried out 190,000km service.

31/03/2022 - Engine oil and oil filter

Repairs Required During 180,000km Service Completes by Aztech INV 20296

Replace Fuel filter as U/S, replaced wiper blades.

3/02/2022

Carried out 180,000km Service, removed and replaced oil and filter, air filter and cabin air filter,

3/02/2022 Adjusted handbrake. Completes by Aztech INV 20290

15/12/2021

- Replaced air, cabin & fuel filter
- Replaced wiper blades
- Replaced left hand mud guard bracket

N.B:

- Left hand mirror broken
- Left hand side of bullbar damaged

6/01/2022

15/12/2021

- Carried out 170,000km service
- Adjusted handbrake

- First aid kit FA098

- Fire extinguisher

Bottle: 01/2021

Tag: 08/21

Sticker: FE254

6/01/2022 inv-19789

1 x Bonnet decal sticker

2/11/2021 INV#14218

08/09/2021

- Carried out 160,000km service
- Adjust hand brake

N:B. - Need left hand side mirror and rear tyres

1.5

Oil Filter

0W-30

SAE 90 5.2

Fuel Filter

PINK COOLANT P-OAT TYPE A CONC

21/09/2021 INV#18638

- Replaced air & pollen filter
- Replaced brake pads

1

Air Filter 1

Cabin Air Filter

Brake Pad set

Consumables

21/09/2021 INV#18639

Carried out 150 000k service. (Oil, air and pollen filters.) - Adjust park brake. Replaced fuel filter.
Replaced wiper blades. Unblocked LH washer jet.

30/07/2021 Sent to browns for tyres INV#17764 & INV#17825

2/11/2021 Replace 2 x tyres MAXXIS LT265/65R17 AT811 Razr10PR INV#109605

carried out 140,000km service
adjusted handbrake

11/05/2021 road test

130,000km service

Adjust hand brake.

Replace wiper blades.

Check battery and charging.

Replace battery.

Fire Extinguisher - FE232

Bottle: 09/25

11/02/2021 Tag: Jan 2021

17/12/2020 120,000km service

110,000km Service

09/10/20 - Carry out 110,000 km service. Replace oil, air, fuel & pollen filters. Adjust rear brakes.

Road test. Fabricate

9/10/2020 bracket & mount to mine bar.

Carried out 90,000km service. (oil, air, pollen)

- Adjust park brake.

1/07/2020 - Fit towbar.