

Work Order ID	Equipment ID	RO Total Cost	Current ODO	Current HR	Instructions	Start Date	End Date
R155-0021896	1542	\$108.77	938243		ELECTRICAL SUZI COIL INOPERATIVE	7/09/2023	8/09/2023
R155-0021858	1542	\$128.48	936031		WEAR PAD DAMAGED	2/09/2023	4/09/2023
R155-0021439	1542	\$743.54	932361		STEERING WHEEL HAS EXCESSIVE FREEPLAY	21/07/2023	24/07/2023
R155-0020822	1542	\$994.42	923338		CHECK / GREASE CLUTCH	24/05/2023	25/05/2023
R155-0020822	1542				REPLACE TABLET	24/05/2023	25/05/2023
R155-0020822	1542				SUZI COIL LEAKING AIR	24/05/2023	25/05/2023
R155-0020795	1542	\$1,004.00	922939		VEHICLE WILL NOT START - CALLBACK	21/05/2023	29/05/2023
R155-0020435	1542	\$338.40	918081		DRIVER REPORTED SLOW TO TURN OVER	18/04/2023	20/04/2023
R155-0020441	1542	\$1,297.14	918081		SERVICE ON 17147489 ADEL DEPOT 17.04.2023 HUBO 917505 01 11006520 - 295/80R22.5 152/148M BS R154 CC 4.0 Retread (recap) Irregular Wear or Alignment 02 11006520 - 295/80R22.5 152/148M BS R154 CC 4.0 Retread (recap) Irregular Wear or Alignment Qty SERVICES/ACCESSORIES REMARKS / SIZE: 2 EA Wheel Balance 33000051 - BALANCE TBR (Pos: 1, 2) 2 EA Tyre Replacement 33000084 - FIT TBR TYRE (Pos: 1, 2) 2 EA Tyre Removed - (Pos: 1, 2) -2 EA	17/04/2023	25/04/2023

R150-000630	1542	\$769.56	911921	DATE: 02.12.2022 INVOICE # 1744 894,508 klms JOB DESCRIPTION Trailer lights not working REPORT Customer rang for assistance, lost lights on both A and B trailers Travelled to breakdown to asses Found A trailer plug had a loose earth wire due to lost pin in plug Replaced plug, checked lights, all except park lights were working Check all wiring connections, earths and sockets - All ok park lights were working Customer rang depot mechanic for assistance Mechanic alerted that trailer lights had separate fuses Located fuse panel in cabin Checked all fuses and relays, found trailer park light fuse had reset button and was out due to earth wire in trailer plug shorting out Reset fuse Park lights working on both trailers Check all lights again	10/03/2023	10/03/2023
R155-0019872	1542	\$427.57	910678	Blinker stalk is loose, noise near brake boosters, alarms staying on	27/02/2023	28/02/2023
R155-0019872	1542			SUZI COIL LEAKING AIR	27/02/2023	28/02/2023
R155-0019872	1542			ELECTRICAL SUZI COIL INOPERATIVE	27/02/2023	28/02/2023
R155-0019835	1542	\$1,874.38	910025	WATER PUMP LEAKING	21/02/2023	28/02/2023
R155-0019835	1542			STEERING SHROUD MISSING	21/02/2023	28/02/2023
R155-0019723	1542	\$165.60	908358	REPORTED SLOW TO TURN OVER	10/02/2023	10/02/2023
R155-0019373	1542	\$2,136.20	902076	VEHICLE WILL NOT START	10/01/2023	11/01/2023
R155-0019373	1542			B SERVICE	10/01/2023	11/01/2023
R155-0019297	1542	\$114.00	901245	REPORTED TABLET NOT ALLOWING DRIVER TO START WORK	30/12/2022	30/12/2022
R155-0019061	1542	\$5,414.00	898843	RADIATOR LEAKING	7/12/2022	13/12/2022
R155-0018917	1542	\$39.60	894020	SERVICE ON 16648387 ADEL DEPOT 21-11-2022 HUBO 893876 1 EA Tyre Repair 33000096 - PUNCTURE REPAIR TBR (Pos: 1) 4 EA Labour - STANDARD 33000096 - SCHEDULED DEPOT SERVICE 15MIN	21/11/2022	23/11/2022
R155-0018803	1542	\$16.84	892755	VEHICLE WILL NOT START	8/11/2022	9/11/2022

R155-0018717	1542	\$2,288.44	892601	SERVICE ON 16499266 ADEL DEPOT 01-11-2022 HUBO 892469 09 11003134 - 11R22.5 148/145L BS M749II CC 2.0 Retread (recap) Customer Pull Point 10 11003134 - 11R22.5 148/145L BS M749II CC 2.0 Retread (recap) Customer Pull Point 11 11003134 - 11R22.5 148/145L BS M749II CC 2.0 Retread (recap) Customer Pull Point 12 11003134 - 11R22.5 148/145L BS M749II CC 2.0 Retread (recap) Customer Pull Point Qty SERVICES/ACCESSORIES REMARKS / SIZE: 4 EA Tyre Replacement 33000084 - FIT TBR TYRE (Pos: 9, 10, 11, 12) 4 EA	1/11/2022	3/11/2022
R155-0018671	1542	\$600.91	892162	DOWNLOAD GUARDIAN - RE ACCIDENT	26/10/2022	28/10/2022
R155-0018671	1542			REPLACE HEADLIGHT PROTECTOR	26/10/2022	28/10/2022
R155-0018549	1542	\$756.60	890577	AIR LEAK	13/10/2022	14/10/2022
R155-0018443	1542	\$64.57	889740	ELECTRICAL SUZI COIL LEAD	30/09/2022	11/10/2022
R155-0018246	1542	\$1,086.62	888434	HORTON FAN CUTTING IN AND OUT	8/09/2022	16/09/2022
R155-0018246	1542			SYSTEM HARD TO START.	8/09/2022	16/09/2022
R155-0018018	1542	\$1,688.35	1899914	TRACKING INOPERATIVE REPLACE IVU UNIT WITH VT102	12/08/2022	18/08/2022
R155-0017906	1542	\$339.08	1899914	OIL COOLER LEAKING - PARTS ONLY	28/07/2022	29/07/2022
R155-0017870	1542	\$668.86	1899874	HEATER CORE LEAKING	23/07/2022	27/07/2022
R155-0017832	1542	\$107.77	1899484	PARTS OMITTED FROM PREVIOUS REPAIR - PARTS ONLY	20/07/2022	20/07/2022
R155-0017793	1542	\$122.95	1899320	REPLACE REVERSE BUZZER	15/07/2022	18/07/2022
R155-0017654	1542	\$4,906.86	1896457	OIL IN COOLANT	28/06/2022	30/06/2022
R155-0017379	1542	\$143.83	1893075	SUZI COIL LEAKING AIR	26/05/2022	30/05/2022
R155-0017379	1542			REPLACE HAZARD SWITCH	26/05/2022	30/05/2022
R122-0051908	1542	\$0.00	1892728	REMOVED FROM TRUCK TO PROCESS CREDIT - ORIGINAL R122-0050658 SECT 5 456231A1 STEERING SHROUD COVER	18/05/2022	18/05/2022
R155-0017292	1542	\$284.68	1892654	SUZI COIL LEAKING AIR	17/05/2022	18/05/2022

R155-0017241	1542	\$72.43	1892228	SUZI COIL LEAKING AIR	11/05/2022	12/05/2022
R155-0017028	1542	\$33.75	1885640	SERCURE L/H MIRROR	7/04/2022	7/04/2022
R155-0017028	1542			TOP UP OIL & COOLANT	7/04/2022	7/04/2022
R155-0017029	1542	\$280.00	1885640	REPLACE R/H WINDSCREEN	7/04/2022	16/05/2022
R122-0050688	1542	\$270.00	1879525	REPLACE OS/WINDSCREEN 1542	28/03/2022	30/03/2022
R122-0050658	1542	\$1,134.68	1878636	Gearbox is playing up, very rough gear changes, missing top cover on steering column, has a shake in the steer. Driver is on way to Melbourne but wouldn't drive truck as it is	26/03/2022	28/03/2022
R122-0050658	1542			CHECK FRONT END & TYRES	26/03/2022	28/03/2022
R122-0050658	1542			REPLACE REAR ENGINE MOUNTS	26/03/2022	28/03/2022
R122-0050658	1542			REPLACE EXHAUST FLEX LINK	26/03/2022	28/03/2022
R122-0050658	1542			REPLACE STEERING COLUMN SHROUD	26/03/2022	28/03/2022
R140-0095062	1542	\$0.00	1866223	EMF SHIELDING NEEDED TO BE APPLIED TO FFC	9/03/2022	10/03/2022
R130-0037579	1542	\$1,224.41	1852329	SERVICE ON 15664875 MELB DEPOT 14.02.2022 HUBO 839271 11004496 - 295/80R22.5 152/148M BS R154 POS 01-02 33000051 - BALANCE TBR (Pos: 1, 2) 33000084 - FIT TBR TYRE (Pos: 1, 2) 33000241 - SCRAP TYRES TBR (Pos: 1, 2) B SERVICE	14/02/2022	16/02/2022
R122-0049048	1542	\$1,101.32	1848372	REPLACE FUEL TANK STRAP	11/02/2022	12/02/2022
R122-0049048	1542			REPLACE MUDFLAPS	11/02/2022	12/02/2022
R122-0049048	1542			REPLACE MUDFLAPS	11/02/2022	12/02/2022
R156-0015634	1542	\$0.00	1848372	Due for service will be in tonight. B service carried out 22/03/2021, R140-0080690.	10/02/2022	10/02/2022
R156-0015635	1542	\$0.00	1848372	Driver cant log onto the sentinel device, phone says it has no sim card. Sentinel & phone faults repaired 13/08/2020, R140-0071881.	10/02/2022	10/02/2022
R122-0048494	1542	\$19.61	1840055	REPLACE WIPER BLADE	31/01/2022	1/02/2022
R122-0048278	1542	\$0.00	1834556	Bunk cooler not working, windscreen washers not working	25/01/2022	25/01/2022
R155-0016319	1542	\$52.50	1834028	DRIVER REPORTS ABS LIGHT DISPLAYED	24/01/2022	24/01/2022
R140-0092939	1542	\$737.18	1828382	VIESA REPAIRS	18/01/2022	19/01/2022
R122-0047963	1542	\$147.88	1824426	replace r/h height control valve	12/01/2022	12/01/2022
R130-0036738	1542	\$2,156.00	1824426	SERVICE ORDER 15553798 MELB DEPOT 11.01.2022 ODO 811877 11001472 - 11R22.5 148/145L BS M749 05-08 33000084 - FIT TBR TYRE (Pos: 5, 6, 7, 8) 77000232 STE- CASE STOCK 11R22.5 ECOPIA (Pos: 5, 6, 7, 8)	12/01/2022	13/01/2022
R140-0092850	1542	-\$119.88	1820308	CLAIM 01688 WARRANTY CLAIM TMN70ZZ x 1	6/01/2022	7/04/2022
R140-0092430	1542	\$479.52	1816273	FLAT BATTERIES	31/12/2021	31/12/2021
R140-0092365	1542	\$72.99	1816272	REPLACE LEAKING GOV VALVE	30/12/2021	30/12/2021
R140-0092721	1542	-\$119.88	1814187	CLAIM 01683 WARRANTY CLAIM TMN70ZZ x 1 TM 680CCA 170RC	23/12/2021	7/04/2022
R140-0091910	1542	\$0.00	1804314	RENEW FAILED BATTERIES	14/12/2021	14/12/2021
R140-0091589	1542	\$37.50	1798619	Aftertreatment light stuck on	6/12/2021	7/12/2021
R140-0091075	1542	\$4,561.97	1790311	B SERVICE E5 CUMMINS 60,000 KM	24/11/2021	25/11/2021
R140-0091075	1542			REPLACE GEARBOX OILS AND FILTERS	24/11/2021	25/11/2021
R140-0091075	1542			REPLACE DIFF OILS AND FILTERS	24/11/2021	25/11/2021
R140-0091075	1542			C SERVICE	24/11/2021	25/11/2021
R140-0091075	1542				24/11/2021	25/11/2021
R140-0091075	1542			RENEW FAILED NOX SENSOR	24/11/2021	25/11/2021

R140-0091081	1542	\$416.32	1790311	AUTOGREASER SPRING ASSEMBLY	24/11/2021	24/11/2021
R122-0046288	1542	\$63.81	1789211	Had an incident yesterday and backed into a trailer bending the light bar on rear of truck	23/11/2021	23/11/2021
R140-0090801	1542	\$11.00	1782730	SERVICE ORDER 15360801 BRIS DEPOT 15.11.2021 ODO 1769895 Runout Tyre 11R22.5 - RTD - 6.0mm 07-08 33000084 - FIT TBR TYRE (Pos: 7, 8) 77000180 SIZE- CASE STOCK 11-22.5 (Pos: 7, 8)	16/11/2021	17/11/2021
R122-0044794	1542	\$0.00	1756511	GUARDIAN ISSUE - HARSH GEAR CHANGES	14/10/2021	15/10/2021
R140-0089339	1542	\$830.85	1754624	FLUSH COOLING SYSTEM	11/10/2021	14/10/2021
R140-0089346	1542	\$2,156.00	1754624	SERVICE ORDER 15223343 BRIS DEPOT 11.10.2021 HUBO 1743025 11001472 - 11R22.5 148/145L BS M749 09-12 33000084 - FIT TBR TYRE (Pos: 9, 10, 11, 12) 33000370 - TYRE HELD FOR RUNOUT (Pos: 11, 12) 77000222 SIZE- CASE STOCK 11R22.5 SCORIA (Pos: 9, 10)	11/10/2021	13/10/2021
R140-0088208	1542	\$0.00	1738299	GAUGES DONT WORK	10/09/2021	11/09/2021
R140-0087793	1542	\$4,305.05	1732723		1/09/2021	8/09/2021
R140-0087793	1542			REPLACE GEARBOX OILS AND FILTERS	1/09/2021	8/09/2021
R140-0087793	1542				1/09/2021	8/09/2021
R140-0087793	1542			C SERVICE	1/09/2021	8/09/2021
R140-0087793	1542			Tensioner worn	1/09/2021	8/09/2021
R140-0087793	1542			Mudguard brackets cracked	1/09/2021	8/09/2021
R140-0087793	1542			Turntable wear ring	1/09/2021	8/09/2021
R140-0087633	1542	\$78.41	1729033	RENEW FIRE EXTINGUISHER	27/08/2021	27/08/2021
R140-0087419	1542	\$34.89	1727020	EXHUAST REPAIRS	23/08/2021	24/08/2021
R140-0086564	1542	\$13.78	1711925	Steer hub cap missing	2/08/2021	2/08/2021
R140-0085903	1542	\$20.35	1695546		16/07/2021	16/07/2021
R140-0085543	1542	\$215.25	1689529	CHECK TRANSMISSION FAULT CODES	8/07/2021	9/07/2021
R140-0085009	1542	\$213.74	1680303	RENEW LEAKING THROUGH SHAFT SEAL	26/06/2021	28/06/2021
R122-0040746	1542	\$0.00	1672401	STEER TYRES FEEL LIKE THEY NEED TO BE BALANCED replaced tyres by tyre fitter	16/06/2021	17/06/2021
R140-0084541	1542	\$950.73	1672401	B SERVICE E5 CUMMINS 60,000 KM	16/06/2021	17/06/2021
R122-0040702	1542	\$77.00	1671960	REPLACE MUDFLAPS AND CANDY STRIPE SIGNS	15/06/2021	15/06/2021
R122-0040716	1542	\$1,223.75	1671960	SERVICE ORDER 14678931 SYDN DEPOT 15.06.2021 ODO 1661693 11004496 - 295/80R22.5 152/148M BS R154 01-02 33000085 - ROTATE TBR TYRE (Pos: 12-5, 11-6, 10-7, 9-8, 8-9, 7-10, 6-11, 5-12) 33000051 - BALANCE TBR (Pos: 1, 2) 33000084 - FIT TBR TYRE (Pos: 1, 2)	15/06/2021	17/06/2021
R140-0083457	1542	\$0.00	1656258	HARD TO START - SEEMS TO BE STARTER MOTOR RELATED - BROKEN DOWN 3 TIMES LAST WEEK FOR NOT STARTING	24/05/2021	24/05/2021
R140-0083423	1542	\$0.00	1655231	Truck has air leaks	22/05/2021	26/05/2021
R140-0083006	1542	\$200.27	1646356	Air leaks in vehicle	12/05/2021	12/05/2021
R140-0083006	1542			Replace 7 pin plug	12/05/2021	12/05/2021
R140-0083006	1542			Replace wiper blades	12/05/2021	12/05/2021
R140-0083006	1542			Supply top up oil	12/05/2021	12/05/2021
R140-0082890	1542	\$70.08	1645071	Attend breakdown,Driver reported that he has damaged suzie hoses	10/05/2021	10/05/2021
R155-0014263	1542	\$0.00	1641232	TABLET WONT TURN ON	4/05/2021	5/05/2021

R155-0014265	1542	\$466.24	1641232	COMPRESSOR HOSE TO DRIER POROUS	4/05/2021	7/05/2021
R155-0014253	1542	\$574.43	1641108	DRIVER REPORTS AIR LEAK FROM REAR SUSPENSION	3/05/2021	6/05/2021
R140-0082606	1542	\$0.00	1638639	PULLING TO THE LEFT - DRIVER SAID IT THAT'S BAD ITS DANGEROUS	1/05/2021	1/05/2021
R140-0082423	1542	\$107.80	1637086	SERVICE ORDER 14536156 BRIS DEPOT 28.04.2021 ODO 1627397 33000051 - BALANCE TBR (Pos: 1, 2) 33000085 - ROTATE TBR TYRE (Pos: 2-1, 1-2) 33000540 - FIT TRUCK TYRE ON REAR (Pos: 1, 2)	28/04/2021	30/04/2021
R140-0082372	1542	\$2,702.29	1636997	Driver reported that the vehicle is pulling to the left and is dangerous to drive	27/04/2021	29/04/2021
R140-0082372	1542			Harmonic balance failed - engine knocking coming in at about 1650rpm	27/04/2021	29/04/2021
R140-0082372	1542			Camera needs to be adjusted	27/04/2021	29/04/2021
R140-0082372	1542			Flip tyres on rims and balance after wheel alignment	27/04/2021	29/04/2021
R140-0080829	1542	\$238.16	1612404	NEEDS A RADAITOR	24/03/2021	25/03/2021
R140-0080829	1542			RENEW 1 X DOWNSHAFT UNI	24/03/2021	25/03/2021
R140-0080690	1542	\$679.63	1611071	B SERVICE E5 CUMMINS 60,000 KM	22/03/2021	22/03/2021
R122-0037681	1542	\$0.00	1603351	REPLACE WIPER BLADES - WASHERS NEED TO BE ADJUSTED	11/03/2021	12/03/2021
R120-0033299	1542	\$0.00	1595340	ADJUST ICS AND RESET ANGLES	2/03/2021	3/03/2021
R120-0033258	1542	\$1,253.74	1595339	REPLACE WORN TYRES	1/03/2021	2/03/2021
R140-0077964	1542	\$0.00	1577819	FIT BUNK FRIDGE	1/02/2021	1/02/2021
R122-0036375	1542	\$0.00	1576702	replaced oil lubricating line	29/01/2021	5/02/2021
R140-0077469	1542	\$544.50	1567573	APPROVED BH 19.1.21	19/01/2021	19/01/2021
R140-0077325	1542	\$1,127.50	1567567	SERVICE ORDER 14131502 BRIS DEPOT 15.01.2021 ODO N/A	15/01/2021	18/01/2021
R140-0077294	1542	\$249.90	1567567		14/01/2021	15/01/2021
R120-0032702	1542	\$320.00	1567567	SIGNWRITING NOT CHARGED TO ORIGINAL JOB. REFER - R120-0032876.	13/01/2021	13/01/2021
R140-0077196	1542	\$45,991.34	1567567	REMOVE AND REPLACE CAB SUSPENSION	13/01/2021	27/04/2021
R140-0077196	1542			REMOVE AND REPLACE CAB ASSY	13/01/2021	27/04/2021
R140-0077196	1542			REMOVE AND REPLACE BATTX X 4 REPAIR AND SECURE CABLING	13/01/2021	27/04/2021
R140-0077196	1542				13/01/2021	27/04/2021
R140-0077196	1542				13/01/2021	27/04/2021
R140-0077196	1542				13/01/2021	27/04/2021
R140-0077196	1542				13/01/2021	27/04/2021
R140-0077196	1542				13/01/2021	27/04/2021
R140-0077196	1542				13/01/2021	27/04/2021
R140-0076566	1542	\$98.19	1563933	AFTERTREATMENT LIGHT ON	23/12/2020	13/01/2021
R140-0076535	1542	\$42.90	1562302	SERVICE ORDER 14054240 BRIS DEPOT 22.12.2020 ODO 1554115	22/12/2020	24/12/2020
R140-0076462	1542	\$3,114.40	1562302	AFTERTREATMENT LIGHT ON	21/12/2020	23/12/2020
R140-0076206	1542	\$64.10	1557544	Trailer lights N/W	15/12/2020	16/12/2020
R140-0075905	1542	\$702.33	1551470		8/12/2020	9/12/2020
R140-0075712	1542	\$363.75	1546407	AIR CON LEAKING ONTO THE PASSANGER FLOOR	3/12/2020	4/12/2020
R155-0012582	1542	\$38.50	1514096	SERVICE ORDER 13800824 ADEL DEPOT 22.10.2020 ODO 507574 33000096 - PUNCTURE REPAIR TBR - POS 11 33000118- SCHEDULED DEPOT SERVICE 15MIN	22/10/2020	23/10/2020
R140-0073863	1542	\$99.75	1507069	Starting faults - getting hard to start	12/10/2020	13/10/2020
R122-0033471	1542	\$1,050.50	1491077	SERVICE ORDER 13682051 SYDN DEPOT 24.09.2020 ODO 484444 11001472 - 11R22.5 148/145L 16 BS M749 - POS 33000084 - FIT TBR TYRE - POS 33000370 - TYRE HELD FOR RUNOUT POS	24/09/2020	28/09/2020

R140-0073367	1542	\$137.50	1491077	APPROVED BILL 24.09 BURPENGARY TYRE & MECHANICAL CENTRE JOB: 16678 DATE 03.09.20 STRIP & FIT RUNOUT 11R X 1 POS 7 SCRAP X 1 SERVICE CALL X 1	24/09/2020	29/09/2020
R140-0073317	1542	\$1,918.67	1491077		23/09/2020	24/09/2020
R122-0033297	1542	\$693.51	1483465	APPROVED BH 16.9.20 \cf0\fs17 Vehicle Rego # : 715WWL - Fleet # : 1542 - 1 S&R Shake & Report, 1 WA Wheel Alignment, 1 CCA Camber/Caster Check, 2 DA Drive Alignment, 4 HW 5/8" 5/8" Hard Washer X Thick, 2 APHW-581, Alignment Shim 5/8" 1.0mm (.50). 1 WS Workshop Consumables \cf1\fs16	16/09/2020	16/09/2020
R122-0033250	1542	\$123.10	1482875	Vibration in the steering	15/09/2020	16/09/2020
R122-0033250	1542			SEND TO BIG WHEELS FOR ALIGNMENT	15/09/2020	16/09/2020
R122-0033269	1542	\$566.50	1482875	SERVICE ORDER 13636087 SYDN DEPOT 15.09.2020 ODO 476382 11001553 - 295/80R22.5 152/148M BS R150 POS 1-2 33000051 - BALANCE TBR - POS 1-2 33000084 - FIT TBR TYRE POS 1-2 33000370 - TYRE HELD FOR RUNOUT POS 1-2 77000194 SIZE: CASE STOCK 295/80-22.5	15/09/2020	16/09/2020
R140-0072817	1542	\$193.50	1476576	GUARDIAN NOT COMMUNICATING	9/09/2020	9/09/2020
R140-0072689	1542	\$114.00	1471657	GUARDIAN NOT COMMUNICATING	5/09/2020	7/09/2020
R140-0072625	1542	\$499.13	1469811	RH SCREEN SCRATCH AND HARD TO SEE OUT	3/09/2020	4/09/2020
R140-0072276	1542	\$442.01	1463214	Driver cant hear the uhf it needs to be louder please	26/08/2020	31/08/2020
R140-0072276	1542			GUARDIAN NOT COMMUNICATING	26/08/2020	31/08/2020
R140-0072276	1542			Sentinel is loose, drivers wiper blade needs to be replaced	26/08/2020	31/08/2020
R140-0072131	1542	\$238.50	1459448	GUARDIAN NOT COMMUNICATING	21/08/2020	21/08/2020
R140-0072049	1542	\$246.32	1457417	Windscreen washers on drivers side are not working, needs new wiper blades please, uhf speaker isn't very loud	19/08/2020	19/08/2020
R140-0071881	1542	\$132.75	1451788	TABLET CANT LOG ON - PHONE READING NO SIM CARD	13/08/2020	13/08/2020
R140-0071540	1542	\$355.45	1443186	BUNK COOLER NOT WORKING	3/08/2020	4/08/2020
R140-0071500	1542	\$5.25	1440248	GUARDIAN REPAIRS	31/07/2020	31/07/2020
R120-0030876	1542	\$31,295.07	1439445	C SERVICE, SERVICE VIESA, CHANGED STEER OILS,CARRY OUT ENGINE TUNE, REPLACE A/C BEARING, KIT AIR DRYER,REPLACE POWER STEER FILTER AND OIL,REMOVE RADIATOR AND CLEAN, REPLACE COOLANT, REPLACE COOLANT FILTER,REPLACE DOSER PUMP,REPLACE WATER PUMP, REPLACE OIL THERMOSTAT,REPLACE SPOOL VALVES,REPLACE STARTER MOTOR,REPLACE ALTERNATOR,REPLACE GOVERNOR VALVE,REPLACE IDLERS AND TENSIONERS,REPLACE CLUTCH AND ECA,REPLACE TAILSHAFT UNIS,UPGRADE MUFFLER, SECURE DRIVERS DOOR TRIM, REPLACE FLOOR MATS,REPLACE WIPER ARMS,REPLACE BOTH INNER DOOR SEALS,REPLACE USB PLUG AND LEAD,REPLACE UHF MIC MOUNT,REPLACE FAILED TELLTALE BULBS AND DAHS BULBS, DETAIL CAB, CLEAN FRIDGE,REPLACE SUNVISOR CLIPS,REPLACE DRIVERS SEAT,TIDY DOG BOXES,RELOCATE TRANSTECH,SECURE RH WEATHER SHIELD,REPLACE EMERGENCY STICKER,INSTALL CAB FIR EXTINGUISHER,SECURE LH DOOR TRIM,REPAIR GUARDIAN FAULT,REPAIR TOWN HORN,REPLACE FIRST AID KIT,REPLACE ENGINE TEMP GAUGE SENDER,REPLACE PITMAN ARM BOLT, TIDY ENGINE HARNESS,TIDY OEM HARNESS,REPLACE HEADLIGHT COVERS,REPLACE FRONT CAB MOUNTS,POLISH TANKS,POLISH BUMPER,REPLACE TANK RUBBERS,REPLACE GRILLE COMPONENTS,REPLACE LH HIGH BEAM BULB,REPLACE MISSING BUMPER BOLTS,RESEAL FLYWHEEL HOUSING,REPLACE LHF "J" BRACKET,REMOVE RH REAR FUEL TANK,REPLACE STEER MUDFLAPS,ADJUST BRAKES, LOAD TEST BATTERIES,WELD RH CAB STEP,REPLACE LOWER DRIVE SHOCK RUBBERS,REPLACE REAR LIGHTS,REPLACE WALK PLATE RUBBER,TIDY SUZI COILS, TOP UP AUTO GREASER,REPLACE 9KG FIRE EXTINGUISHER,STRAIGHTEN REAR LIGHT BAR, TIDY LIGHT BAR WIRING,REPLACE TURNTABLE FOOT BUSHES,REPLACE TURNTABLE PULLCORD,RESEAL RH AIRTANK FITTINGS,CLEAN DIFF BREATHERS	21/07/2020	3/08/2020
R120-0030876	1542			POLISH WHEELS	21/07/2020	3/08/2020
R120-0030876	1542			REPLACE CLUTCH AND ECA	21/07/2020	3/08/2020
R120-0030876	1542			REPLACE DOSER PUMP AND FILTERS	21/07/2020	3/08/2020
R120-0030876	1542			SERVICE VIESA/PAINT KOOLKAT COVER RED	21/07/2020	3/08/2020

R120-0030876	1542				REPLACE POWER STEERING OIL & FILTER. REPLACE STEER HUB OILS. REPLACE PITMAN ARM PINCH BOLT AND TENSION	21/07/2020	3/08/2020
R120-0030876	1542				CARRY OUT ENGINE TUNE. REPLACE ENGINE BRAKE KIT. INSPECT ROCKER SHAFTS AND CAMSHAFT FOR WEAR	21/07/2020	3/08/2020
R120-0030876	1542				REPLACE A/C COMPRESSOR	21/07/2020	3/08/2020
R120-0030876	1542				REKIT AIR DRYER	21/07/2020	3/08/2020
R120-0030876	1542				REPLACE OIL & COOLANT THERMOSTATS	21/07/2020	3/08/2020
R120-0030876	1542				R/R RADIATOR STRIP AND CLEAN IN HOUSE. REPLACE COOLANT AND FILTER. PRESSURE TEST INTERCOOLER	21/07/2020	3/08/2020
R120-0030876	1542				REPLACE WATER PUMP	21/07/2020	3/08/2020
R120-0030876	1542				REPLACE STARTER MOTOR	21/07/2020	3/08/2020
R120-0030876	1542				REPLACE ALTERNATOR	21/07/2020	3/08/2020
R120-0030876	1542				STRAIGHTEN AND POLISH BUMPER	21/07/2020	3/08/2020
R120-0030876	1542				POLISH RIMS INSPECT AND ROTATE TYRES	21/07/2020	3/08/2020
R120-0030876	1542				INSPECT BONNET AND GRILLE FOR DAMAGE REPLACE WORN BONNET MOUNTS	21/07/2020	3/08/2020
R122-0032183	1542	\$202.85	1439093			21/07/2020	24/07/2020
R122-0032033	1542	\$215.25	1433604		GUARDIAN NOT COMMUNICATING	14/07/2020	14/07/2020
R140-0070690	1542	\$63.75	1429648		CHECK ENGINE FAULT CODES	9/07/2020	9/07/2020
R130-0027340	1542	\$0.00	1429588		Camera not workingCamera not working	7/07/2020	7/07/2020
R140-0070539	1542	\$897.60	1429588		STEERING WHEEL REPLACED	6/07/2020	8/07/2020
R140-0070539	1542				NOT COMMUNICATING	6/07/2020	8/07/2020
R140-0070539	1542				JUMP START NEEDED IN YARD	6/07/2020	8/07/2020
R140-0070480	1542	\$4,492.32	1429588			3/07/2020	4/07/2020
R140-0070480	1542				GUARDIAN REPAIRS	3/07/2020	4/07/2020
R140-0070480	1542				RENEW 2 X DRIVE HUB SEALS	3/07/2020	4/07/2020
R140-0070480	1542				REPLACE GEARBOX OILS AND FILTERS	3/07/2020	4/07/2020
R140-0070480	1542				REPLACE DIFF OILS AND FILTERS	3/07/2020	4/07/2020
R140-0070498	1542	\$555.50	1429580		SERVICE ORDER 13318393 BRIS DEPOT 03.07.2020 HUBO 423947 11001472 - 11R22.5 148/145L 16 BS M749 - POS 6 33000084 - FIT TBR TYRE - POS 6 33000241 - SCRAP TYRES TBR - 6	3/07/2020	6/07/2020
R140-0070340	1542	\$132.75	1426369		GUARDIAN NOT COMMUNICATING	30/06/2020	30/06/2020
R140-0070203	1542	\$58.50	1422977		FORWARD FACE CAMERA NOT WORKING	26/06/2020	26/06/2020
R140-0070042	1542	\$72.75	1419368		GUARDIAN NOT COMMUNICATING	23/06/2020	23/06/2020
R140-0070010	1542	\$2,002.00	1419368		SERVICE ORDER 13088833 BRIS DEPOT 20.06.2020 HUBO 413932 11001472 - 11R22.5 148/145L 16 BS M749 - POS 9-12 33000085 - ROTATE TBR TYRE - POS 1-2, 9-12 33000084 - FIT TBR TYRE - POS 9-12 77000180 SIZE: CASE STOCK 11-22.5 - POS 9-12	22/06/2020	23/06/2020
R140-0069842	1542	\$1.50	1416735		NO COMM	17/06/2020	17/06/2020
R155-0011613	1542	\$238.50	1413128		GUARDIAN SYSTEM NOT LOGGING	12/06/2020	15/06/2020
R122-0031220	1542	\$838.13	1411379		Auto greaser has been damaged	9/06/2020	13/06/2020
R140-0069400	1542	\$21.00	1409830		GUARDIAN NO COMMUNICATION	5/06/2020	5/06/2020
R122-0031170	1542	\$84.00	1408863		repair camera	4/06/2020	5/06/2020
R122-0031053	1542	\$58.50	1402824		GUARDIAN UNINSTALLED ITSELF AGAIN!	29/05/2020	29/05/2020
R122-0030976	1542	\$37.50	1401186		Guardian - Cameras Misaligned	27/05/2020	28/05/2020
R140-0068878	1542	\$135.00	1400354		GUARDIAN NOT COMMUNICATING	26/05/2020	26/05/2020
R155-0011381	1542	\$422.25	1390501		GUARDIAN REPORTED INOPERATIVE	14/05/2020	20/05/2020
R122-0030499	1542	\$66.25	1385438		repair system	5/05/2020	6/05/2020
R140-0067755	1542	\$289.79	1379273		RENEW GOV VALVE	27/04/2020	27/04/2020
R140-0067355	1542	\$1,001.00	1375199		SERVICE ON 13019493 BRIS DEPOT 18.04.2020 ODO 369993 POS 1-2	20/04/2020	22/04/2020
R120-0029733	1542	\$46.50	1369903		INSPECT LOSS OF POWER COMPLAINT	9/04/2020	14/04/2020
R140-0066931	1542	\$3,465.69	1368908			6/04/2020	9/04/2020

R140-0066931	1542					6/04/2020	9/04/2020
R140-0066959	1542	\$85.80	1367753		SERVICE ORDER 12979501 BRISBANE DEPOT 06.04.2020 ODO 364480 POS 1-2	6/04/2020	7/04/2020
R140-0066318	1542	\$135.42	1356185		RENEW WIPER BLADES	20/03/2020	20/03/2020
R140-0066111	1542	\$801.58	1353459		JUMP START	16/03/2020	16/03/2020
R140-0064690	1542	\$1,629.64	1334264		Cruise control not working, electrics not working property, water leak above drivers visor Cruise control not working, electrics not working property, water leak above drivers visor	10/02/2020	11/02/2020
R122-0028883	1542	\$138.75	1333092		GUARDIAN NOT COMMUNICATING	7/02/2020	10/02/2020
R140-0064461	1542	\$1,988.80	1330724		SERVICE ORDER 12770760 BRISBANE DEPOT 04.02.2020 ODO 326720 POS 9-12	4/02/2020	5/02/2020
R140-0063997	1542	\$0.00	1326977		HEAD UNIT HAS INTERMITTENT ISSUES	30/01/2020	30/01/2020
R140-0063777	1542	\$299.94	1324372		Sentinel has stopped working, needs new wiper blades, 12 volt plug isnt working to charge phone, drivers weather shield needs replacinq	24/01/2020	28/01/2020
R140-0063302	1542	\$19,015.85	1315322		11.1.20 1542 (APPROVED JB 13.1.20) REGO 715WWL KLMS 1309753 PITTED HEAD BOLTS FRONT ROCKER SHAFT WORN TURBOCHARGER WASTEGATE LEAKING (CUSTOMER OPTED TO REPLACED DUE TO AGE /WEAR. OVER HAUL ENGINE USING NEW PISTON KITS LINERS BEARINGS RECON TURBO HE 6	13/01/2020	13/01/2020
R140-0063252	1542	\$252.54	1315099		Air con isn't blowing cold air, engine running hot, light cover missing, radio doesn't work, stinks like an ash tray, take a while to select gears	11/01/2020	14/01/2020
R140-0063160	1542	\$235.37	1313457		A/C REPAIRS	9/01/2020	10/01/2020
R140-0063160	1542				GUARDIAN NOT COMMUNICATING	9/01/2020	10/01/2020
R122-0028148	1542	\$573.58	1310543		replace batteries	30/12/2019	31/12/2019
R122-0028077	1542	\$646.45	1306465		B-SERVICE E5 CUMMINS	23/12/2019	27/12/2019
R140-0062639	1542	\$2,188.61	1300259		RENEW LEAKING AIR BAG RENEW DRIVE SHOCK BUSHES	18/12/2019	20/12/2019
R140-0062639	1542				RENEW LEAKING HEATER TAP	18/12/2019	20/12/2019
R154-0000285	1542	\$3,622.60	1295138		12.12.19 1542 REGO XN36HD KLMS 1290817 \cf0 BREAK Break down - no air pressure - South of Marlborough Loaded parts and tools in to breakdown ute and travelled to vehicle South of Marlborough. \b \$635.58 \b0 Connected Insite and carried out download as per Cummins requirments for Warranty Plus claims. Lowered bullbar and followed troubleshooting for "air compressor will not pump air". Step 1 - ok. Step 2 - ok. Step 3 - check the unloader system and head assy system. Found damage to the head and bore on air compressor. Removed power steering pump and removed and replaced compressor. Replaced all o'rings and gaskets. Refit power steering pump and all other removed components. Topped up coolant after refilling. Ran up and checked for leaks. Raised bullbar and sent truck back in to service. Part Number Part Description Quantity Total Cost 3690864RX RECON AIR COMPRESSOR ISX 1.00 2,373.76 3685614 GASKET ACC DRIVE SUPPORT 1.00 48.72 ALLCOOL-5M TRP ALLCOOL 5L PREMIX 1.00 16.46 T TRAVEL PER KLM 155.00 193.75 \b Parts Totals: 158.00 \$2,632.69 \cf1\b0\cf2	12/12/2019	13/12/2019
R156-0007999	1542	\$38.50	1276029		1 X PUNCTURE REPAIR POSITION 8 FTSD-1800915	18/11/2019	25/11/2019
R140-0061400	1542	\$1,001.00	1270288		SERVICE ON 12532852 BRIS DEP 11.11.19 HUBO 266624 POS 1-2	11/11/2019	13/11/2019
R140-0061401	1542	\$1,936.00	1270288		SERVICE ON 12532854 BRIS DEP 11.11.19 HUBO 999800 POS 9-12	11/11/2019	12/11/2019
R140-0061242	1542	\$849.81	1265316		r/h bonnet strut	5/11/2019	6/11/2019
R140-0060616	1542	\$5,332.35	1248177		APPROVED JB 18.10.19 NO CODE GIVEN 4993120RX RECON ECM ISX, CORE DEPOSIT, CALIBRATION CHARGE	18/10/2019	21/10/2019
R122-0026715	1542	\$323.25	1247331		PHONE INOPERATIVE	17/10/2019	18/10/2019
R122-0026715	1542				LEAKING WATER IN CABIN	17/10/2019	18/10/2019
R122-0026715	1542				TRANSMISSION SKIPPING SHIFTS	17/10/2019	18/10/2019
R140-0060400	1542	\$3,298.58	1245774			15/10/2019	17/10/2019
R140-0060400	1542				no throttle	15/10/2019	17/10/2019
R140-0060389	1542	\$38.50	1244966		SERVICE ON 12434092 BRIS DEP 14.10.19 HUBO 242660 POS 10	14/10/2019	18/10/2019
R140-0060109	1542	\$128.04	1237781		suzi lines need replacing	4/10/2019	8/10/2019
R140-0059797	1542	\$126.79	1231215		RENEW EBS LEAD	26/09/2019	26/09/2019
R140-0059703	1542	\$555.50	1229210		SERVICE ON 12374135 BRIS DEP 24.9.19 HUBO NA POS 11	24/09/2019	25/09/2019

R140-0059709	1542	\$77.00	1229210	SERVICE ON 23.9.19 BRIS DEP 23.9.19 HUBO NA POS 1-2	24/09/2019	25/09/2019
R140-0059625	1542	\$106.04	1228641	CHECK OVER FRONT END	23/09/2019	23/09/2019
R140-0059534	1542	\$326.25	1226193	GEARSHIFT LOCK DOESN'T WORK SO IT SLIDES INTO DIFFERENT GEARS	19/09/2019	20/09/2019
R140-0059435	1542	\$2.11	1224211	REPAIR DIFF OIL LEAK	17/09/2019	18/09/2019
R140-0059333	1542	\$22.00	1220714	SERVICE ON 12339063 BRIS DEP 13.9.19 HUBO 218717 POS 11	13/09/2019	16/09/2019
R122-0026054	1542	\$300.00	1218548	CALL OUT TO YARD REPAIR 7 PIN PLUG	11/09/2019	11/09/2019
R140-0059117	1542	\$22.50	1217276		9/09/2019	10/09/2019
R122-0025598	1542	\$143.26	1200861	GEARCHANGES ARE STICKING INTERMITTENTLY	16/08/2019	19/08/2019
R140-0057885	1542	\$119.25	1194687	shift fault	8/08/2019	13/08/2019
R140-0057891	1542	\$42.90	1194687	SERVICE ON 12215637 BRIS DEP 8.8.19 HUBO 193115 POS 1	8/08/2019	8/08/2019
R140-0057697	1542	\$16.67	1192341	RENEW DRIVE HUB CAP	5/08/2019	5/08/2019
R130-0021618	1542	\$995.69	1185996	PM for 000-002 Last Done: 15/04/2019 Interval: 60000 Utilization: 59423	25/07/2019	26/07/2019
R130-0021451	1542	\$233.25	1182384	DROP TO CUMMINS FOR OIL LEAK	16/07/2019	18/07/2019
R130-0021349	1542	\$691.65	1182320	TRANMISSION ISSUES AT MARKET	10/07/2019	12/07/2019
R130-0021123	1542	\$300.00	1173892	CALLOUT TO YARD TO REPAIR LIGHTS	28/06/2019	28/06/2019
R140-0055992	1542	\$24.62	1171019		24/06/2019	25/06/2019
R140-0055448	1542	\$198.58	1161353	FRONT ENGINE MOUNTS REPLACED BY CUMMINS WACOL	10/06/2019	12/06/2019
R140-0054965	1542	\$55.00	1150902	SERVICE ORDER: 11942821 BRIS DEPOT 24.05.19 UNIT 1542 ODO: 149,102 WHEEL BALANCE X 2 POS 1&2	27/05/2019	29/05/2019
R140-0054800	1542	\$67.50	1147954	STEERING HEAVY - WONT RETURN TO CENTRE	22/05/2019	22/05/2019
R140-0054818	1542	\$5.86	1147954	RENEW 7 PIN SOCKET	22/05/2019	22/05/2019
R140-0054190	1542	\$0.00	1140135	WINDSCREEN WASHER STALK IS LOOSE	8/05/2019	8/05/2019
R130-0020192	1542	\$2,204.67	1136935	AFTERTREAT LIGHT ON - STEERING WOBBLING (ALL OVER THE ROAD)	2/05/2019	3/05/2019
R130-0020192	1542			STEERING WOBBLE	2/05/2019	3/05/2019
R130-0020192	1542			CHECK WIPERS	2/05/2019	3/05/2019
R130-0020192	1542			STEERING HAS A WOBBLE - WINDSCREEN WIPER CONTROL HAS COME LOOSE	2/05/2019	3/05/2019
R130-0020192	1542			SWITCH - MULTI-FUNCTION STALK LEVER	2/05/2019	3/05/2019
R130-0020208	1542	\$5,148.00	1136935	2 X 295/80R22.5 R150 POSITION 1,2 8 X 11R22.5POSITION 5.6.7.8.9.10.11.12 10 X FIT 2 X BALANCE 5X TRADES FTSD-11868676	2/05/2019	3/05/2019
R140-0053427	1542	\$4,521.51	1125893		15/04/2019	16/04/2019
R140-0053427	1542			REPLACE GEARBOX OILS AND FILTERS	15/04/2019	16/04/2019
R140-0053427	1542			REPLACE DIFF OILS AND FILTERS	15/04/2019	16/04/2019
R140-0053427	1542			RENEW WIPER BLADES	15/04/2019	16/04/2019
R140-0053447	1542	-\$49.50	1125397	SERVICE ON 11825455 BRIS DEP 15.4.19 HUBO 124967 POS 2	15/04/2019	17/04/2019
R140-0052686	1542	\$80.27	1109779	NO TRAILER INDICATORS	26/03/2019	26/03/2019
R140-0052224	1542	\$131.25	1107063	communiacion issue	15/03/2019	15/03/2019
R140-0051944	1542	\$5.50	1101214	SERVICE ON 11712658 BRIS DEP 8.3.19 HUBO 1095487 POS 1-2	8/03/2019	12/03/2019
R156-0006271	1542	\$55.91	1101214	SUZI COILS TANGLED BLOWN HOSE- REMOVE AND REPLACE SUZI COILS	8/03/2019	8/03/2019
R140-0051897	1542	\$104.78	1099941	RENEW BLEED HOSE	7/03/2019	8/03/2019
R140-0051743	1542	\$0.00	1098013	no lights on trailer	4/03/2019	5/03/2019
R122-0022599	1542	\$679.25	1093602		28/02/2019	28/02/2019
R140-0051533	1542	\$91.50	1092773	driver facing camera requires adjusting due to tampering	27/02/2019	27/02/2019
R122-0022549	1542	\$52.50	1091981	LEFT STEER TYRE IS CHOPPING OUT BADLY SEND FOR WHEEL ALIGNMENT	26/02/2019	27/02/2019
R140-0051272	1542	\$281.06	1087614	BLUE SERVICE LINE FITTING TO TRAILER NEEDS REPLACING	21/02/2019	21/02/2019
R156-0006143	1542	\$1,694.00	1084803	2 X 11R22.5 M766 POSITION 3.4 1 X SCRAP 1 X RUNOUT 1 X ETA CALLOUT 8 X CALLOUT FTSD-1170286	15/02/2019	18/02/2019

R140-0050266	1542	\$746.30	1074072		29.1.19 1542 REGO 715WWL KLMS68591 \cf0\fs18 LBD LABOUR BREAKDOWN 3 420.00 \fs16 Travelled to afterhours truck breakdown callout to Bestbrook, Maryvale Via Warwick. Truck was shutting down due to high coolant temperature and horton not engaging. Found horton air supply very weak (possible blocked filter on solenoid). Fitted bolts to horton to manually engage fan so driver can complete trip. Truck still overheating - 110 deg on road relay but radiator core was cold. Removed thermostat, 100% stuck shut. Removed centre of thermostat - and refitted. running cool again. Travelled back to Warwick. \fs18 CF CALLOUT FEE 1 100.00 TRAV TRAVELLING / KM \$1.25 per KM 111 138.75 WS WORKSHOP SUPPLIES 1 18.50 OTN051C HT. Bolt 1 x 5/16' UNC 2 1.20 Sub Total: 678.45 \cf1\fs16	30/01/2019	30/01/2019
R140-0050216	1542	\$2,312.04	1074072		RENEW THERMOSTAT, AND ENGINE FAN	29/01/2019	16/02/2019
R140-0050216	1542				INSTALL GUARDIAN SYSTEM	29/01/2019	16/02/2019
R140-0049720	1542	\$107.80	1065178		SERVICE ON 11565270 BRIS DEP 16.1.19 HUBO 1059411 POS 1-2	16/01/2019	17/01/2019
R140-0049670	1542	\$2,518.42	1065178	5915.00		15/01/2019	16/01/2019
R122-0021592	1542	\$160.04	1052883		REPLACE TURNATBLE PAD	2/01/2019	2/01/2019
R140-0048951	1542	\$1,148.18	1044358		LOSES AIR QUICKLY WHEN PARKED, SENTINEL DEVICE WONT TURN ON	20/12/2018	21/12/2018
R122-0021379	1542	\$223.50	1040124		REPLACE MAIN AIR LINE FROM COMPRESSOR	15/12/2018	17/12/2018
R140-0048254	1542	\$208.54	1032684		CHECK ABS AND LIGHT IS ON DASH	7/12/2018	8/12/2018
R140-0047844	1542	\$51.00	1024854		INDICATORS NOT WORKING ON TRAILER	28/11/2018	28/11/2018
R140-0047617	1542	\$40.32	1018999		LEFT HAND SUN VISOR KEEPS POPPING OUT OF THE CLIP	22/11/2018	22/11/2018
R140-0047479	1542	\$1,980.00	1016958		SERVICE ON 11398582 BRIS DEP 19.11.18 HUBO 1012720 POS 9-12	19/11/2018	20/11/2018
R140-0047056	1542	\$10.22	1010445		WALK PLATE BRACKET	9/11/2018	9/11/2018
R140-0046762	1542	\$88.00	1003793		REPLACE SEAT BELT	2/11/2018	3/11/2018
R140-0046687	1542				B SERVICE E5 CUMMINS 60,000 KM	1/11/2018	7/11/2018
R140-0046451	1542	\$826.39	998239		WONT SELECT GEARS	26/10/2018	26/10/2018
R140-0046242	1542	\$7.70	995112		REPLACE MISSING HUB CAP	22/10/2018	22/10/2018
R140-0045816	1542	\$64.75	985471		OVERSPEED ALARM NOT ALWAYS WORKING	11/10/2018	11/10/2018
R140-0045385	1542	\$372.00	977573		AIR CON IS NOT WORKING	2/10/2018	2/10/2018
R140-0045288	1542	\$0.00	974041		ROO DAMAGE	27/09/2018	27/09/2018
R140-0045289	1542	\$0.00	974041		CHECK BATTERIES	27/09/2018	27/09/2018
R140-0044973	1542	\$221.58	967630		INSPECT FAULT CODES	20/09/2018	20/09/2018
R140-0045013	1542	\$946.00	967630		SERVICE ON 11211907 BRIS DEP 20.9.18 HUBO 964811 POS 1-2	20/09/2018	26/09/2018
R140-0044615	1542	\$225.00	959617		TRANSMISSION IS PLAYING UP NOT CHANGING GEARS	11/09/2018	12/09/2018
R122-0019614	1542	\$95.25	953510		CANT LOG IN	4/09/2018	4/09/2018
R140-0044290	1542	\$2,046.00	952765		SERVICE ON 11160709 BRIS DEP 3.9.18 HUBO 949794 POS 9-12	3/09/2018	5/09/2018
R140-0043859	1542	\$1,299.83	944431	4312.00	B SERVICE	24/08/2018	29/08/2018
R140-0043859	1542				REPLACE SUCTION HOSE	24/08/2018	29/08/2018
R140-0043910	1542	\$107.80	943357		SERVICE ON 10660806 BRIS DEP 24.8.18 HUBO 941049 POS 6	24/08/2018	27/08/2018
R140-0043777	1542	\$147.04	941102		UHF HAND PIECE NOT WORKING	22/08/2018	23/08/2018
R140-0043626	1542	\$516.59	933879		RHS HEADLIGHT COVER AND DRL BROKEN	17/08/2018	18/08/2018
R154-0000092	1542	\$1,729.65	933879		APPROVED BY BH 15.8.18 2.8.18 REPAIR HOLE IN RADIATOR REMOVED RADIATOR FROM UNIT AND SENT AWAY FOR REPAIRS REFITTED RADIATOR TO UNIT AND RAN VEHICLE FOR 5 MINUTES TESTED OK REGO: 715WWL KLMS: 920,538	15/08/2018	16/08/2018
R140-0042670	1542	\$117.52	912734		suzi lines need replacing	19/07/2018	20/07/2018
R140-0042670	1542				7 pin lead needs replacing	19/07/2018	20/07/2018
R122-0018857	1542	\$663.75	912129		SENTINEL DEVICE WILL NOT TURN ON	18/07/2018	19/07/2018
R122-0018837	1542	\$108.75	911319		SENTINEL ISN'T WORKING, OVER SPEED ALARM ISN'T WORKING ALL THE TIME	17/07/2018	18/07/2018
R140-0041248	1542	\$0.00	888756		MONDAY. VIESA KEEPS TURNING ITSELF OFF	20/06/2018	20/06/2018

R140-0041341	1542	\$539.29	888756		APPROVED BY BILLY 20.6.18 \cf0 Break down call out - air leak Attend breakdown at workshop. Found air leaking from treadle valve. Removed side panel. Rempved and replaced an airline. Tested operation. Refitted side panel. \b REGO: QV11QW KLMS: 884,737 PRICE AS PER PROFORMA RO 552700 \cf1\b0\cf2	20/06/2018	21/06/2018
R140-0041028	1542	\$38.50	883729		WORK ORDER 4420197237 FTSD 1623822 BRISBANE 13.06.18 ODO: 879174	14/06/2018	18/06/2018
R140-0040697	1542	\$66.00	877144		FTSD 1631194 BRIS DEP 6.6.18 HUBO 872926 POS 1-2	7/06/2018	12/06/2018
R140-0040623	1542	\$2,127.40	877144	3397.00	B SERVICE E5 CUMMINS 60,000 KM	6/06/2018	7/06/2018
R140-0040091	1542	\$645.09	863688		A/C REPAIRS	23/05/2018	26/05/2018
R140-0039898	1542	\$854.12	859214		INSPECT TRANS CODES	18/05/2018	21/05/2018
R140-0039898	1542				INSPECT A/C OPERATION	18/05/2018	21/05/2018
R140-0039811	1542	\$702.61	857427		DRIVELINE HAS PLAY INIT. KEY IS AT THE GATE HOUSE	16/05/2018	17/05/2018
R140-0039811	1542				RENEW FIREWALL AIR LINE MANIFOLD	16/05/2018	17/05/2018
R122-0017725	1542	\$249.00	850723		NEEDS A NEW BRACKET TO HOLD THE UHF BRACKET	9/05/2018	10/05/2018
R122-0017573	1542	\$131.25	843155		CHECK COOLANT	30/04/2018	30/04/2018
R140-0039172	1542	\$209.75	839416		CHECK ENGINE LIGHT ON	26/04/2018	30/04/2018
R140-0039172	1542				REPLACE O RONG AND SEAL.	26/04/2018	30/04/2018
R122-0017466	1542	\$389.31	834419		REPLACE R/H HOOD STRUT	20/04/2018	23/04/2018
R122-0017393	1542	\$106.50	831624		TOMORROW. BUNK COOLER NOT WORKING	17/04/2018	20/04/2018
R140-0038797	1542	\$77.25	831227		INSPECT BUNK COOLER	16/04/2018	16/04/2018
R140-0038553	1542	\$2,156.00	825758		FTSD 16310014 BRIS DEP 6.4.18 HUBO 819605 POS 5-8	9/04/2018	12/04/2018
R140-0037897	1542	\$3,951.66	811176	2517.00	B SERVICE E5 CUMMINS 60,000 KM	23/03/2018	27/03/2018
R140-0037897	1542				REPLACE GEARBOX OILS AND FILTERS	23/03/2018	27/03/2018
R140-0037897	1542				REPLACE DIFF OILS AND FILTERS	23/03/2018	27/03/2018
R140-0037897	1542				REPLACE LOWER SHOCK ABSORBER BUSHES.	23/03/2018	27/03/2018
R140-0037897	1542				BRAKE RELINE L/H/R DRIVE AND REPLACE DRU,M	23/03/2018	27/03/2018
R140-0037897	1542				GLASS - VIEW WINDOW	23/03/2018	27/03/2018
R130-0013735	1542	\$1,187.00	802278		CHECK SPEED ALARM OPERATION	14/03/2018	15/03/2018
R130-0013735	1542				REPLACE TRAKA WITH UPDATED ONE	14/03/2018	15/03/2018
R140-0037293	1542	\$102.75	796641		GEARBOX SERVICE LIGHT FLASHES	7/03/2018	8/03/2018
R122-0016596	1542	\$91.50	789870		VIESA IS TURNING ITSELF ON WHEN YOU HIT A BUMP	27/02/2018	27/02/2018
R140-0036937	1542	\$11.27	789869		MISSING HUB CAP STEER	26/02/2018	26/02/2018
R140-0036716	1542	\$33.75	785299		DAYTIME RUNNING LIGHTS	21/02/2018	22/02/2018
R140-0036355	1542	\$4,483.16	777266		TRUCK JERKS WHEN TAKING OFF	9/02/2018	14/02/2018
R140-0036296	1542	\$15.84	776066		SERVICE ORDER NO 106468 BRIS DEPOT 05.02.18 HUBO 771324 POS 5-12	8/02/2018	16/02/2018
R140-0036220	1542	\$1,056.00	775466		FTSD 1454146 BRIS DEPOT 05.02.18 ODO 771324 POS 1-2	7/02/2018	14/02/2018
R140-0036029	1542	\$490.58	770960			2/02/2018	2/02/2018
R140-0036010	1542	\$1,958.00	769941		FTSD 1454120 BRIS DEPOT 31.01.18 ODO: 766,862 POS 9-12	1/02/2018	12/02/2018
R140-0035884	1542	\$0.00	768972		BUNK COOLER NOT WORKING	31/01/2018	31/01/2018
R122-0016030	1542	\$76.50	768075		GEARBOX ISSUES	30/01/2018	30/01/2018
R122-0015855	1542	\$253.38	757905		replace exhaust flex	18/01/2018	20/01/2018
R130-0012622	1542	\$22.54	757849		FIT MISSING STEER HUBCAPS	17/01/2018	17/01/2018
R140-0034987	1542	\$0.00	750400		STARTING TO HAVE STARTER MOTOR ISSUES	8/01/2018	8/01/2018
R122-0015652	1542	\$612.07	750400		PM for 000-002 Last Done: 28/10/2017 Interval: 60000 Utilization: 60225	6/01/2018	8/01/2018
R155-0004913	1542	\$108.89	733197		AIR BAGS WILL NOT GO DOWN	19/12/2017	19/12/2017
R155-0004913	1542				DRIVER REPORTS A/C INOPERATIVE	19/12/2017	19/12/2017

R155-0004913	1542			CHECK OIL & COOLANT	19/12/2017	19/12/2017
R155-0004916	1542	\$220.00	733197	L/H WINDSCREEN CRACKED.	19/12/2017	4/01/2018
R122-0015317	1542	\$153.03	726842	REPLACE MISSING FUEL CAP	12/12/2017	14/12/2017
R130-0011960	1542	\$19.80	721722	10 X PRESSURE CHECK POSITION 1 TO 12 FTSD-10497606	5/12/2017	6/12/2017
R140-0032922	1542	\$695.50	706327	SMOKE COMING OUT FROM UNDER BONNET	17/11/2017	18/11/2017
R122-0014550	1542	\$39.00	692131	COOLANT PIPE BEHIND TURBO LEAKING TAKE TO CUMMINS WARRANTY	2/11/2017	2/11/2017
R140-0032239	1542	\$925.59	690987	RENEW 4 LEAKING AIR BAGS	1/11/2017	6/11/2017
R140-0032239	1542			RENEW POWER STEERING FILTER	1/11/2017	6/11/2017
R140-0032239	1542			REPLACE DASH LIGHT	1/11/2017	6/11/2017
R140-0032252	1542	-\$330.00	690987	REFER ORIGINAL RO R140-0030168 (P140-0018853) RETURN OF EXHAUST SENSOR CORE ORIGINAL INVOICE 1207711	1/11/2017	1/11/2017
R140-0032062	1542	\$528.45	689051	CHECK OVER FOR AIR LEAKS	30/10/2017	31/10/2017
R130-0011303	1542	\$1,347.54	688177	CARRY AOUT B SERVICE.	28/10/2017	30/10/2017
R122-0013984	1542	\$123.75	671773	REPLACE L/H BRAKE AIR LINE TO STEER ABS VALVE	9/10/2017	10/10/2017
R140-0031023	1542	\$120.30	669691	INSPECT LIGHTS & OPERATION	7/10/2017	9/10/2017
R140-0030168	1542	\$1,071.71	655690	AFTERTREATMENT LIGHT ON	20/09/2017	21/09/2017
R140-0029689	1542	\$15.84	646614	B/STONE PRESSURE CHECK X8	12/09/2017	14/09/2017
R140-0029614	1542	\$311.25	646501	TRANSMISSION SERVICE LIGHT IS ON	11/09/2017	12/09/2017
R122-0013419	1542	\$37.84	641256	STEER ROTATION, LEFT TO RIGHT, 8 x P-CHECK FTSD-1535455	4/09/2017	6/09/2017
R140-0029296	1542	\$1,111.00	641256	B/STONE FIT 2X 295/80/22.5 R150 POS 1/2 AND BALANCE 2X HELD FOR R/O FTSD 1435831	4/09/2017	8/09/2017
R130-0010055	1542	\$256.51	626994	REPLACE L/R DRIVE SEAL	14/08/2017	16/08/2017
R130-0009913	1542	\$586.72	621783	B SERVICE SAMPLE SIP 21751882	7/08/2017	9/08/2017
R120-0014287	1542	\$938.70	603223	REPLACE BROKEN FLEX UNDERNEATH THE CAB	17/07/2017	18/07/2017
R140-0026357	1542	\$4,304.96	592318	FTSD: 1335949 8 x 11R22.5 148/145L POSITIONS 5-12 2 x PRESSURE CHECKS 5 x TRADES	3/07/2017	3/07/2017
R122-0011832	1542	\$48.50	577389	REPLACE SUZY COILS	14/06/2017	14/06/2017
R140-0024927	1542	\$97.50	567701	CIG LIGHTER SOCKET NOT WORKING	31/05/2017	31/05/2017
R140-0024529	1542	\$166.25	563715	REPLACE ABS LEAD	24/05/2017	20/06/2017
R140-0024296	1542	\$3,084.65	561977	B SERVICE E5 CUMMINS	19/05/2017	23/05/2017
R140-0024296	1542			REPLACE DIFF OILS AND FILTERS	19/05/2017	23/05/2017
R140-0024296	1542			RELINE FRONT DRIVE HUB	19/05/2017	23/05/2017
R140-0024296	1542			REPLACE LEAKING EXHAUST FLEX.	19/05/2017	23/05/2017
R140-0024296	1542			REPLACE FAILED BATTERIES	19/05/2017	23/05/2017
R156-0002814	1542	\$470.00	557431	HIT A BIG BIRD AND DAMAGED BOTH SIDES.	15/05/2017	15/05/2017
R140-0022359	1542	\$0.00	447233	NEEDS A WHEELO	4/04/2017	4/04/2017
R140-0022360	1542	\$0.00	447233	FUEL TANK DAMAGED	4/04/2017	4/04/2017
R122-0010212	1542	\$118.50	432553	FUEL GAUGE NOT WORKING	17/03/2017	18/03/2017
R122-0010212	1542			CHECK FOR NOISE IN L/H/R DRIVE BRAKE	17/03/2017	18/03/2017
R122-0010196	1542	\$1,060.84	431634	REPLACE STEER TYRES WITH 295 'R150, CASES x 2 P-CHECK x 8 FTSD- 1361595	16/03/2017	17/03/2017
R140-0021605	1542	\$56.25	431634	INSPECT FUEL GUAGE OPERATION	16/03/2017	16/03/2017
R130-0007503	1542	\$198.75	430211	DO BATTERY AND SD CARD UPGRADE	14/03/2017	14/03/2017
R122-0010104	1542			REPLACE FUEL FILTERS	13/03/2017	13/03/2017
R140-0021353	1542	\$27.50	430211	B/STONE FIT 1X OWN STOCK R.O POS 1 AND BALANCE 1X SENT TO COFFS FTSD 1352103	10/03/2017	23/03/2017
R140-0021360	1542	\$514.80	430211	CARRY OUT WHEEL ALIGNMENT- SUBLET TO STRAIGHT WHEELS.	10/03/2017	10/03/2017
R140-0021295	1542	\$7.90	430211	CHECK STEERING COMPONENTS	9/03/2017	13/03/2017
R140-0021295	1542			CHECK FUEL TANK SUPPORT FOR DAMAGE	9/03/2017	13/03/2017
R140-0021295	1542			REPAIR AIR LEAKS	9/03/2017	13/03/2017

R140-0021156	1542	\$805.26	430211		AIR LEAKS	8/03/2017	13/03/2017
R156-0002311	1542	\$22.00	430211		ROTATE SIDE TO SIDE POSITION 1,2 FTSD-1322089	24/02/2017	24/02/2017
R140-0020338	1542	\$169.14	430211		REPLACE FUEL TANKL STEP PARTS ONLY	20/02/2017	22/02/2017
R120-0011329	1542	\$603.05	430211		STEERING STIFF.REPLACE THE TOP UNI ON THE STEERING SHAFT CLOSEST TO THE FIREWALL,ALTHOUGH IT WAS STILL TIGHT.ENDING UP FINDING A RAG RAPPED AROUND THE STEERING SHAFT INSIDE THE CAB. B SERVICE E5 CUMMINS	16/02/2017	24/03/2017
R140-0020205	1542	\$1,027.98	430211		NEEDS DOOR RUBBER GLUED BACK ON	16/02/2017	17/02/2017
R140-0018256	1542	\$0.00	430211		DRIVER WOULD LIKE SPARE BELTS ETC FOR DOG BOX	4/01/2017	4/01/2017
R140-0018257	1542	\$0.00	430211		GUBBER ON DRIVERS DOOR NEEDS GLUING BACK ON	4/01/2017	4/01/2017
R140-0017966	1542	\$242.25	430211		CARRY OUT ROAD WORTHY AND MEASURE UP- SUBLET TO BPD MECHANICAL.	24/12/2016	24/12/2016
R140-0017309	1542	\$287.00	430211		SUPPLIED WITH SPARE FAN BELTS	9/12/2016	14/12/2016
R140-0017141	1542	\$77.19	430211		REPLACE STEER TYRES WITH 295 R150, 2 x CASES, FTSD No.1297275	7/12/2016	7/12/2016
R122-0007984	1542	\$1,045.00	430211		BIG WHEELS, WHEEL ALIGNMENT 17-11-16 431718 KM	29/11/2016	6/12/2016
R122-0007993	1542	\$548.66	430211		BIG WHEELS FOR WHEEL ALIGNMENT	29/11/2016	1/12/2016
R122-0007747	1542	\$35.25	430211		CLUNK UNDER CAB	17/11/2016	18/11/2016
R120-0009341	1542	\$191.25	430211		WHEELO	16/11/2016	16/11/2016
R120-0009317	1542	\$135.00	424163		ROTATE DRIVE TYRES	15/11/2016	16/11/2016
R120-0009317	1542				GREASE LEAK AT RESERVOIR	15/11/2016	16/11/2016
R120-0009275	1542	\$60.00	424163		supply cleaning products	12/11/2016	12/11/2016
R120-0009197	1542	\$27.72	423706		BROKEN GREASE LINES	9/11/2016	9/11/2016
R120-0009050	1542	\$91.50	416694		REPLACE POS#3-4-5-6 WITH 11R M749, 4 x CASE FTSD-1071867	2/11/2016	3/11/2016
R122-0006797	1542	\$2,288.00	402611		SERVICE RADIATOR	12/10/2016	14/10/2016
R120-0008458	1542	\$330.00	402028		C-SERVICE	11/10/2016	13/10/2016
R120-0008433	1542	\$19,656.08	408742	1952.00	REPLACE DOSER PUMP REPLACE FILTERS	10/10/2016	25/10/2016
R120-0008433	1542				REPLACE TURBO	10/10/2016	25/10/2016
R120-0008433	1542				REMOVE RADIATOR AND SEND TO NATRAD	10/10/2016	25/10/2016
R120-0008433	1542				KIT HORTON REPLACE TENSIONERS AND BELTS	10/10/2016	25/10/2016
R120-0008433	1542				REPLACE WATER PUMP	10/10/2016	25/10/2016
R120-0008433	1542				REPLACE THERMOSTAT	10/10/2016	25/10/2016
R120-0008433	1542				A/C BEARING	10/10/2016	25/10/2016
R120-0008433	1542				SERVICE VIESA	10/10/2016	25/10/2016
R120-0008433	1542				REPLACE STEER OILS	10/10/2016	25/10/2016
R120-0008433	1542				ENGINE TUNE	10/10/2016	25/10/2016
R120-0008433	1542				REPLACE ALTERNATOR	10/10/2016	25/10/2016
R120-0008433	1542				KIT AIR DRIER	10/10/2016	25/10/2016
R120-0008433	1542				POWER STEER OIL AND FILTER	10/10/2016	25/10/2016
R120-0008433	1542				REPLACE AIR COMPRESSOR	10/10/2016	25/10/2016
R120-0008433	1542				REPLACE OIL THERMOSTAT	10/10/2016	25/10/2016
R120-0008433	1542				REPLACE STARTER	10/10/2016	25/10/2016
R120-0008433	1542				CHECK ABS SYSTEM	10/10/2016	25/10/2016
R120-0008433	1542				VIESA WATER PUMP ISSUE	10/10/2016	25/10/2016
R120-0008433	1542				B SERVICE - CUMMINS E5	10/10/2016	25/10/2016
R120-0008433	1542				REPLACE STEER UNIS	10/10/2016	25/10/2016
R120-0008433	1542				WARRANTY- EXHAUST MANIFOLD LEAKING	10/10/2016	25/10/2016
R120-0008433	1542				FULL BONNET INSPECTION REAR FEET LOOSE	10/10/2016	25/10/2016
R120-0008433	1542				REPLACE TURNTABLE PADS ADJUST TURNTABLE	10/10/2016	25/10/2016
R120-0008433	1542				REPLACE FLEX UNDER GBOX REPLACE MOUNTS AT BLOCK	10/10/2016	25/10/2016

R120-0008433	1542				WARRANTY- FRONT DIFF INPUT SEAL LEAK	10/10/2016	25/10/2016
R120-0008433	1542				DETAIL CAB , FIT STICKERS	10/10/2016	25/10/2016
R120-0008433	1542				UPGRADE SUZI COILS	10/10/2016	25/10/2016
R120-0008433	1542				FREONT CAB MOUNTS	10/10/2016	25/10/2016
R120-0008433	1542				POLISH RIMS	10/10/2016	25/10/2016
R122-0006724	1542	\$76.34	401803		STEER ROTATION P-REPAIR POS#1, P-CHECK, FTSD-1071694	10/10/2016	11/10/2016
R140-0014129	1542	\$11.62	385576		REPAIR AIR LEAK @ STEER QR VALVE	23/09/2016	23/09/2016
R120-0006937	1542	\$88.50	344048		LOOK OVER TRUCK,MAKE REPAIRS LIST AND TAKE TO B&H WARRANTY- STEER UNIS HEATER TAP BRACKET CRACKED -LEAK AT P/STEER GASKET -XY SHIFTER LEAK -TORQUE ROD BUSHES -EXHAUST MOUNTS AT BLOCK -LH LOWER ENGINE MOUNT BROKEN -FRONT DIFF POWER DIVIDER LEAK - CHECK STEER COLUMN MOVEMENT	12/08/2016	12/08/2016
R122-0005244	1542	\$2,299.88	342257		B/STONE... REPLACE POS#7,8,9,10 WITH 11R 'M749, 1 x KEPT FOR RUN OUT, 3 x CASE TO COFFS, P-CHECK x 6, FTSD-1185648	10/08/2016	12/09/2016
R122-0005235	1542	\$544.57	342257	1161.00	B SERVICE	9/08/2016	10/08/2016
R120-0006585	1542	\$21.51	330727		WARRANTY- LH MIRROR MOTOR	28/07/2016	29/07/2016
R120-0006585	1542				REPLACE SUNVISOR CLIP	28/07/2016	29/07/2016
R120-0006120	1542	\$0.32	309604		WARRANTY : TANK STRAP RUBBERS refer to job r120-0006081 \f0	9/07/2016	9/07/2016
R120-0006120	1542				DRIVE BRAKES refer to job r120-0006081 \f0	9/07/2016	9/07/2016
R120-0006120	1542				MIRROR MOTOR NOT WORKING warranty refer to job r120-0006081 \f0	9/07/2016	9/07/2016
R120-0006120	1542				AIR LEAKS refer to job r120-0006081 \f0	9/07/2016	9/07/2016
R120-0006081	1542	\$84.99	309604		CHECK OVER TRUCK FOR WARRANTY	8/07/2016	8/07/2016
R120-0006081	1542				WARRANTY- REPACE FRONT DRIVE BRAKES	8/07/2016	8/07/2016
R120-0006081	1542				WARRANTY- AXLE GASKETS LEAKING	8/07/2016	8/07/2016
R120-0006081	1542				WARRANTY- MIRROR MOTOR INOP	8/07/2016	8/07/2016
R122-0004115	1542	\$1,042.15	291832	500.00	B SERVICE + DIFF OILS	20/06/2016	21/06/2016
R122-0004122	1542	\$935.00	291407		B/STONE... REPLACE STEER TYRES WITH 295 'R150, 2 x 295 TRADE-IN, FTSD-1144192	20/06/2016	23/06/2016
R140-0008344	1542	\$43.50	270003		ADJUST BONNET MOUNTS	30/05/2016	30/05/2016
R122-0003552	1542	\$71.25	263470		AIR LEAK COMIG FROM THE HOT PIPE	23/05/2016	26/05/2016
R122-0003427	1542	\$98.84	257383		REPLACE AXLE GASKET	17/05/2016	17/05/2016
R122-0003232	1542	\$696.90	259067	62.00	B SERVICE	9/05/2016	19/05/2016
R122-0002480	1542	\$744.38	212716		DUE FOR B\f0 SERVICE	30/03/2016	31/03/2016
R122-0002155	1542	\$2,068.00	193023		B/STONE... REPLACE POS#3,4,5,6 WITH 11R 'M749, 4 x 11R TRADE-IN, FTSD-1013966	10/03/2016	17/03/2016
R122-0001906	1542	\$15.00	176249		TRACKING NOT WORKING	29/02/2016	29/02/2016
R122-0001906	1542				ELECTRONIC LOG BOOK KEEPS TURNING IT SELF OFF AND NOT SHOWING UP THE SPEED	29/02/2016	29/02/2016
R120-0002025	1542	\$51.00	176249		HUD NEEDS CALIBRATING TO SPEEDO	22/02/2016	23/02/2016
R122-0001664	1542	\$2,068.00	174439		B/STONE... REPLACE POS#7,8,9,10 WITH 11R 'M749, 4 x 11R TRADE-IN, FTSD-867443	18/02/2016	24/02/2016
R122-0001577	1542	\$696.76	173519		B SERVICE	15/02/2016	16/02/2016
R120-0001155	1542	\$407.27	153720		ROCKER COVER LEAKING OIL.CARRT OUT FAULT TREE T102.CHECK OIL USAGE RATE OK.CHECK FOR EXTERNAL OIL LEAK & FOUND TO HAVE A BAD OIL LEAK AT THE REAR OF THE ROCKER COVER.REMOVE THE ROCKER COVER.REPLACED & REFITTED GASKET.PROCEDURE 007-024-DEGREASED..JOB DONE BROWN & HURLEY	25/01/2016	5/02/2016
R120-0000976	1542	\$7.50	147523		WARRANTY- REPLACE EXHAUST FLEX UNDER GEARBOX	19/01/2016	19/01/2016
R120-0000790	1542	\$157.50	142853		A/C DRAIN BLOCKED SENT TO B&H FOR WARRANTY	14/01/2016	14/01/2016
R122-0000738	1542	\$935.00	141608		2 X FIT 295 R150 POS 1-2 2 X TRADE FTSD 872532	13/01/2016	29/01/2016
R120-0000656	1542	\$201.00	137077		A/C DRAIN BLOCKED	8/01/2016	8/01/2016
R120-0000656	1542				GI LIGHT ON THE GEARBOX	8/01/2016	8/01/2016
R120-0000656	1542				ROOF LEAK	8/01/2016	8/01/2016

R120-0000656	1542				TAPPET COVER GASKET LEAKING- WARRANTY B&H	8/01/2016	8/01/2016
R122-0000537	1542	\$537.26	132954		B SERICE	4/01/2016	4/01/2016
R122-0000539	1542	\$33.75	132954		GEARBOX GI LIGHT ON	4/01/2016	5/01/2016
R120-0000424	1542	\$37.50	126162		REPLACE SUZI COIL FITTINGS	24/12/2015	5/01/2016