

SERVICE HISTOR

Plant Details	274	Dumper	2006 Moxy MT31 Dumper (Jeffery)	
Date	Odometer	Comments	Jobsite	
18/09/2023	4368	14,000hr service completed	Eric Dunnacliff	
2/06/2022	4035	4000hr service completed	Eric Dunnacliff	
18/08/2021	3475	3500hr service completed	Eric Dunnacliff	
24/09/2020	3088	3000hr service completed	Eric Dunnacliff	
15/03/2020	2600	2500hr service completed	Eric Dunnacliff	
10/10/2019	1912	2000hrs service completed	Eric Dunnacliff	
25/10/2018	955	1,000hr service completed	Eric Dunnacliff	
13/08/2018	685	500hr service completed	Eric Dunnacliff	
9/04/2018	9500	500hr service	Completed by Eric Dunnacliff	
12/05/2017	8500	8500hr service completed by Eric Dunnacliff		
1/08/2016	7500	7500hr service & checkover.	E Dunnacliff	
5/04/2016	7000	Service & checkover		
14/11/2015	6500	Matt Irving		
20/07/2015	6000			
2/10/2014	5500	Eric Dunnacliff		
5/04/2014	5000			
14/12/2013	4500			
9/09/2013	4000			
17/12/2012	3500	Eric Dunnacliff	Eric Dunnacliff	
21/09/2012	3000	Eric Dunnacliff	Eric Dunnacliff	
7/05/2012	2500	Eric Dunnacliff	Eric Dunnacliff	

Unit 274 -Dump Truck - Moxy MT31

Name	Date	Fault	Repair
Matt Irving	13/02/2017	Derating and staying in 2nd gear.	Investigated, auto greaser empty, went over to Bayswater and picked up grease. Filled auto greaser.
Matt Irving	15/03/2017	Hole in exhaust	Test fitted a couple of exhaust bands to find correct size
Matt Irving	20/04/2017	Flashing light not working window wiper not working	Broken wires replaced light bulb wiper had spun on spline removed and repositioned and tightened
Matt Irving	20/04/2017	Window wiper and washer not working	Replaced blade holder blew washing line out. Line had come apart at a join removed belly plate to locate and rejoin
Matt Irving	21/04/2017	Blown bulb and broken wire going to light	Replaced bulb ditched plugged wires
Matt Irving	10/05/2017	Fuel tank leaking. Exhaust has a hole in it.	Remove exhaust and took back to work shop for repair /Patch hole
Matt Irving	11/05/2017	Tank leaking	Refitted tank attempted to fit exhaust but needed more repairs
Matt Irving	12/05/2017	Exhaust leak	Fitted exhaust stack
Michael Thomas	16/05/2017	A/C not working	Check A/C found filters blocked heaters turn on and duct switch on demist
Matt Irving	1/06/2017	Seat not staying pumped up	Air bag had hole in it took seat out of 222 and put in took seat 274 back to work shop for repairs
Matt Irving	6/06/2017	Busted air bag under seat	Picked up seat and bag from workshop
Matt Irving	21/06/2017	Flat batteries	Jump started ute
Matt Irving	21/06/2017	CV shaft RHS replacement	Started to fit new shaft, got wheel side in and then needed a jack to do diff end
Matt Irving	21/06/2017	CV shaft RHS replacement	Eric turned up with jack & finished bolting into position
Matt Irving	28/06/2017	A/C not working	Checked, labelled climate controls in cab for operator
Matt Irving	3/07/2017	Reverse light & beeper staying on	Faulty relay, removed and replaced
Matt Irving	5/07/2017	Seat belt all twisted up	Removed seat belt and pulled apart to get twist out of belt
Matt Irving	11/08/2017	Broken Grease Line	Repair Grease Line
Scott it all	22/08/2017	Check A/C find low on gas and little compressor cutting, cut to long find thermo wrongly adjusted	Check A/C find low on gas and little compressor cutting, cut to long find thermo wrongly adjusted
Matt Irving	12/09/2017	Seat belt not retracting	Inspected and attempted to fix
Matt Irving	13/09/2017	Seat belt not retracting	Removed a seat belt from old seat
Matt Irving	15/09/2017	Seat belt not retracting	Removed and replaced broken seat belt
Michael Thomas	25/09/2017	No A/C	Check A/C, clean out filters, found no gas in system. Looked for leak, found pin hole in condenser
Michael Thomas	9/10/2017	a/c switch	replace a/c switch
Eric Dunnadiff	1/12/2017		remove speedo and replace with another from a truck not being used
Brad Page	1/12/2017	Assisted Lance & Stumpy	Fixing lights & defects
Lance Hall	4/12/2017	Lights	check lights and test low beam
Michael Thomas	4/01/2018	Oil leak	Check leak found ground pump low pressure sensor leaking. Removed & plugged hole, ordered new switch through Peter
Michael Thomas	5/01/2018	Bonnet won't close	Found bonnet hitting cab & latch edge rounded off spaced bonnet catch up & grinded latch edge flat
Michael Thomas	9/01/2018	Emergency steering, low pressure switch, broken wire to switch	Fit new switch, repair wiring, fit guard
Michael Thomas	24/01/2018	Radio not working	replace fuse
Matt Irving	24/01/2018	Hydraulic leak. Faulty valve. Dip stick sleeve broken	Located leak. Removed and replaced hose. Removed and replaced epr valve. Removed broken dip stick sleeve.
Brad Page	24/01/2018	Flat tyre POS & old worn tyre	
Michael Thomas	6/02/2018	No dash	Check no dash
Michael Thomas	12/02/2018	Transmission overheating	Found oil overfull, suck oil out 15lts. Told operator to wash out radiator blocked with mud
GCFM	14/03/2018	Battery light was on	Restarted, light went out
Matt Irving	4/04/2018	Door latch broken	Inspected, back to w/s for repairs
Lance Hall	9/04/2018	Door latch/check over	Remove dash for door latch to be welded and replace. Repair lights and remove RH front guard
Lance Hall	10/04/2018	Lights, step	Repair step and fit to truck
Lance Hall	10/04/2018	Hoist ram leaking LH side	Remove ram
Lance Hall	11/04/2018	Ram 274 hoist	Remove ram and load onto trailer
Lance Hall	11/04/2018	Ram leak 274 LH body lift cylinder	Remove ram 222, remove cylinder from 222 and start to fit to 274
Adam Hardy	11/04/2018	Ram leaking. LH Hoist cylinder	Remove ram and put onto Triton for transport
Adam Hardy	11/04/2018	Ram leaking. LH Hoist cylinder	Remove ram from 222 and fit to 274
Michael Thomas	12/04/2018	Hoist ram leaking, check over	Fit LH hoist ram and test. Check over, repair lights
Matt Irving	16/04/2018	Flat battery	Jump started
Jordan Lebrocq	24/04/2018	Truck is running terrible	Change fuel filters
Jordan Lebrocq	7/05/2018	Mazy is flat	Jump start truck
Matt Irving	8/05/2018	Flat batteries	Jump started
Matt Irving	9/05/2018	Flat batteries	Jump started
Matt Irving	9/05/2018	Flat batteries	Picked up new batteries. Removed and replaced batteries
Matt Irving	10/05/2018	Lost drive	Lifted cab and inspected drive coupling and jack shaft. Inspected all drive shafts. Front RHS cv shaft snapped off uni joint. Removed snapped off bolts. Retaped holes. Refitted shaft.

Michael Thomas	25/06/2018	A/C fans not working, park brake light not working	Check pb light, replaced globe - ok. Check A/C fans, found motors u/s. Travel to w/shop & get new motors. Travel to Liddell, remove fans
Michael Thomas	25/06/2018	A/C fans	Travel to Liddell Ash, Replace motors in A/C fans. Fit fans & test - ok
Michael Thomas	16/07/2018	Bubble in tyre, LH low beam	Drill small hole in bubble, replace LH low beam globe
Tom Wilkinson	2/08/2018	Fuel gauge not working	Fuel gauge not required - P. Ross
Eric Dunnaciff	13/08/2018		carry out service
Jordan Lebrocq	21/08/2018	Door latch has snapped off Moxy cabin	Remove dash panels so the boiler can weld in door Stricker ASSY
Jordan Lebrocq	21/08/2018	Dash has been removed to repair door Stricker	Fit dash back into truck after Marty has repaired door Stricker
Michael Thomas	23/08/2018	Bubble in tyre	Drill hole in tyre bubble
Michael Thomas	19/09/2018	Hoist pin coming out	Check hoist pin, found collets broken, parked truck up until parts available
Michael Thomas	20/09/2018	Hoist ram pin u/s	Fit new hoist ram pin LH bottom
Michael Thomas	28/09/2018	A/C belt loose & oil leaks	Tighten A/C belt, check oil leaks
Michelle Saunders	10/10/2018	Fuel gauge does nto work	Fuel gauge not required - P. Ross
Michael Thomas	23/10/2018	Broken A/C belt	Get broken A/C belt
Denis Costello	4/12/2018	Back windscreen cracked	23/07/2019 - MRS Windscreen
Jordan Lebrocq	11/12/2018	Truck needs windscreen wipers	Change wipers
Jordan Lebrocq	8/01/2019	Both lower lift bearings on rams are dry	Grease bearings
Jordan Lebrocq	22/02/2019	Dip stick has snapped off the engine & fuel gauge is faulty	Zip tie dip stick onto engine & order new parts
Kalium Frey	28/02/2019	Fuel gauge not working, badly cracked rear window	Truck filled daily - not required to be repaired. 23/07/19 MRS Windcreens
Michelle Saunders	22/03/2019	Hydraulic hose about to blow	26/03/19 - Matty Irving
Matt Irving	25/03/2019	Blown hydraulic hose	Removed hose & took to Pirtok for replacement
Scott it all	3/04/2019	A/C Not Working	A/C Compressor u/s
Scott it all	8/04/2019	A/C Not Working	Fit Compressor, fit drier, fit pressure switch, Vac and regas, adjust thermostat, compressor, drier, switch. Supply gas and oil.
Matt Irving	9/04/2019	Lost all drive	Backed off park brake, inspected truck, front drive shaft RHS had a uni-joint fail, removed shaft & changed out uni-joints
Matt Irving	10/04/2019	Lost all drive	Front cv shaft RHS uni-joint unserviceable. Attempted to fit shaft, had trouble fitting one bolt hole on York coming out of front diff had been Heli coiled previously & I didn't know. Removed broken bolts from yoke coming from front diff first.
Matt Irving	11/04/2019	Front cv shaft, uni joints unserviceable	Finished off installing shaft
Matt Irving	26/04/2019	Blown hydraulic hose	Fitted new hose & new spiro wrap to hoses across artic
GOFM	14/05/2019		Remove front RHS/F Wheel. Started to take brakes off. Leaking inner axle steel.
Michael Thomas	20/05/2019	Hub ASSY for 281	Remove hub ASSY, remove input axle assemble in hub, replace seal & bearing & refit to hub
Michael Thomas	7/06/2019	Front hub, LH side POS 2	Remove hub plantaris from T8 pos 4. Count teeth on sun gear, ring gear & plantation, count teeth on 274 hub sun, ring & plantar gears, hubs are the same. Disassemble T8 pos 4 hub, disassemble 274 stub axle ASSY for repair
Michael Thomas	18/06/2019	Hub ASSY for 281	Disassemble hub
Michael Thomas	21/06/2019	POS 2 hub ASSY	Clean & replace bearing & seal on hub inner axle & fit to stub axle
Will Hobden	24/06/2019	Front axle	Assisting Mike put the axle back on Moxy
Michael Thomas	24/06/2019	POS 2 hub ASSY	Fit hub stub axle pos 2
Jordan Lebrocq	25/06/2019	POS 2 hub ASSY	Fit new bearings into hub
Jordan Lebrocq	26/06/2019	POS 2 hub ASSY	Finish rebuilding the Moxy hub
Michael Thomas	27/06/2019	POS 2 hub ASSY	Assemble pos 2 hub, set bearing pre-load
Jordan Lebrocq	28/06/2019	POS 2 hub ASSY	Help rebuild hub then bolt onto stub axle, assemble brakes, fit new brake shoes (pos 2)
Brad Page	28/06/2019		Assisted Jordan on Moxy pos 2 hub, fit brakes & linings
Matt Irving	4/07/2019	Front diff output seals leaking RHS had broken bolt in uni-attachment hole.	Started to remove bolt
Brad Page	4/07/2019		Assisted Matt lower front suspension using jacks, removed shocks & chains
Matt Irving	5/07/2019	Front diff output seals leaking RHS had broken bolt in uni-attachment hole.	Continued on with removing & replacing seals
Brad Page	5/07/2019		Assisted Matt remove drive shaft, yokes from Moxy front diff, put stands under truck to lower suspension to get to yokes, stripped yokes down, fixed broken bolt in brakes & fitted new linings
Will Hobden	9/07/2019	Tail gate missing/bent	Bent the tail gate back to normal - assisted Stumpy, fitted on back, hit into bush, making up caps for shaft
GOFM	9/07/2019		Got old tail gate straightened and then fix. Made locking pins and brackets.
GOFM	10/07/2019		Fit diff drives back together - Moxy
Will Hobden	12/07/2019	Refit front diff axles	Fitted axles with Matty & torqued bolts, cleaned up bolts
Jordan Lebrocq	17/07/2019	Both front axle seals leaking in front diff	Suspension has been pulled out of Moxy for repairs, bolt suspension back into truck.
Brad Page	17/07/2019	Assisted Jordan on Moxy	Fit front drive shaft/brakes & new brake linings. Bleed brakes/fit shocks & chains.
Jordan Lebrocq	18/07/2019	Both front axle seals leaking in front diff	Suspension has been removed from the Moxy, bolt brakes back onto front diff, fit new brake pads, bleed brakes, fit tyres onto truck.

Matt Irving	22/07/2019	Tail gate fitted back onto truck	Tapped out holes for dust caps of tail gate pins, de burred off sides of holes, bolted caps on
Jordan Lebrocq	22/07/2019	Moxy needs to be refitted with a tailgate	Bolt tailgate onto bin (build parts to finish the job). Build parts to fit tailgate to truck
GOFM	22/07/2019		Repair leaking fuel tank. Fabricate STEP for Terex
Brad Page	22/07/2019	Remove rear L/H side	Pos 3, pos 5 to check brakes, all good plenty of meat left
Brad Page	22/07/2019		Put 2 drums of fuel in truck after Marty fixed tank.
Scott it all	24/07/2019		Find air leak, top up AC, check for leaks
Will Hobden	31/07/2019	Air brake leak	R&R brake foot valve with Scotty
Scott it all	31/07/2019		Jack up cab, remove and fit brake treadle valve, test drive, check ok
Michael Thomas	6/08/2019	Front end locking up	Check R&LH hubs - ok. Test drive, can hear a noise while turning, clunking. Drain front diff, check front diff, found chunks in diff, front diff u/s
Michael Thomas	6/08/2019	Diff oil drained	Fill up front diff for transport to workshop
Peter Ross	9/08/2019	Front diff failed	Jack up vehicle, Remove front wheel to start removing diff
Jordan Lebrocq	12/08/2019	Blown front diff	Drop suspension, drain transmission, drain diff, jack cab, remove muffler, unbolt diff, ready for removal
GOFM	14/08/2019		Help remove diff stand log cutter up then moved it to side of shed.
Jordan Lebrocq	15/08/2019	Front diff has blown - front diff failed	Remove front diff from truck
Will Hobden	19/08/2019	Taking off diff & setting up tranny on stand	Assisted Peter
Peter Ross	19/08/2019	Front diff failed	Remove spare diff off spare transmission
Jordan Lebrocq	20/08/2019	Front diff has blown on Moxy	Seals have arrived, start fitting diff to transmission
Matt Irving	21/08/2019		Assisted Jordan, fitted front diff back to truck
Jordan Lebrocq	21/08/2019	Front diff has blown	Keep bolting diff into place
GOFM	21/08/2019		Help put front diff back in
Jordan Lebrocq	22/08/2019	Front diff has blown	Fit diff back into truck, lift suspension into place, fit drive shafts, top up diff, top up transmission, test dump truck, found leak beneath truck
GOFM	22/08/2019		Finish off cross arm on axle up, wheels on hose and guards on
Jordan Lebrocq	23/08/2019	Pump is leaking on the rear of the transmission	Wash truck
Matt Irving	30/08/2019	Seat leaking air	Fitting in top of airbag had snapped off. Removed & replaced fitting
Jordan Lebrocq	16/09/2019	The engine tensioner pully has locked up and snapped the belt	Replace tensioner & belt
Scott it all	18/09/2019		Check AC Comp clutch u/s
Michael Thomas	19/09/2019	No A/C	Found blown fuse & compressor unplugged. Found rub through on compressor wiring. Temporarily fixed wire & test - A/C ok
Michael Thomas	30/09/2019	Coolant leak	Check leak, found hole in oil cooler
Michael Thomas	1/10/2019	Pos 1 wheel	Assist Brad to change wheel
Michael Thomas	2/10/2019	Hole in oil cooler for trans retarder oil	Clean up hole & devcon up hole
Michael Thomas	3/10/2019	Coolant leak	Check repair to oil cooler - ok. Fill coolant up, found leak in top hose from engine, cut down hose & top up coolant, check for leaks - ok.
GOFM	18/10/2019		Remove bonnet radiator. Replace transmission oil cooler and started putting back together
Brad Page	18/10/2019	Oil cooler for transmission leaking coolant	Removed bonnet, hoses & wires. Removed radiator with fork lift, cleaned up radiator, swapped oil cooler for new one - assisted Graham
Will Hobden	21/10/2019	Transmission oil cooler failed	Put radiator in, re fitted all new hoses, filled up with coolant, pumped grease into rear grease points. Assisted Stumpy
Jordan Lebrocq	21/10/2019	Auto greaser is not working	Manually pump grease into machine & cycle grease through truck
GOFM	21/10/2019		Put radiator back in with all other parts, bonnet filled with coolant
Will Hobden	22/10/2019		Topped up coolant, hydraulic oil, transmission oil & washed
GOFM	22/10/2019		Checked and filled with oils, hydraulic, transmission. Checked tyres. Coolant
Michael Thomas	13/11/2019	Oil leak	Jack cab & remove LH inner guard, found test line rubbed through, disconnect line & cap fitting, fit guards & put down cab
Michael Thomas	14/11/2019	Turbo to manifold gasket	Remove intake line & oil lines. Remove turbo, replace gasket, refit turbo lines
Matt Irving	15/11/2019	Door not closing properly	Tightened door striker
Lance Hall	20/11/2019	Door latch, worn, wipers	R&R dash, Repair wipers & horn fuse
Matt Irving	22/11/2019	Blown hydraulic & brake hoses	Lifted cab & started to remove
Lincoln Smith	25/11/2019	Horn, wipers & fuel gauge not working	10/06/2020 M.Thomas
Lincoln Smith	25/11/2019	Door latch plate broken away from frame	28/11/19 Workshop fixed
Scott it all	28/11/2019		Check AC, change filters, clean condensers
MRG Maintenance	28/11/2019		Repair door latch
Michael Thomas	30/12/2019	No start	Check no start, found TCU has no power, check fuses, found fuse for engine cooler blown, replace fuse & it blew ignition fuse, replace in fuse & replace engine cooler relay, start truck & drive back to go line.
Michael Thomas	2/01/2020	No start	Found ignition fuse blown, replace fuse & start truck. Check wiring to engine fan solenoid, found wires rubbed through on steel line, taped up wires.
Brad Page	6/01/2020	Assisted Matt	Leaking oil behind pos 2, removed wheel, found brake linings falling out, leaking from brake
Brad Page	7/01/2020	Assisted Matt pos 2	Fit pistons back in calliper. Go to Ash Dam, fit calliper back on truck, bleed brake, fit wheel back, remove pos 4, pos 6, found more damage

MRG Maintenance	23/01/2020		Straighten out panels
MRG Maintenance	28/01/2020		Straighten out panels
Matt Irving	29/01/2020	Seat padding no good	Removed & replaced seat. Had to redrill holes to mount seat
Jordan Lebrocq	29/01/2020	Seat in Moxey is faulty	Help Matt lift seat into truck & connect air
MRG Maintenance	31/01/2020		Straighten out panels
Keith Rumble	1/02/2020	Seat is losing air around air fitting	03/02/20 M.Irving
MRG Maintenance	3/02/2020		Straighten out panels
Matt Irving	3/02/2020	Leaking air, seat	Removed air fitting & replaced
Michael Thomas	10/02/2020	Oil leak found in cab	Found transmission oil coming out of air valve, trace back to retarder valve, suspect leak in retarder valve into air circuit. Parts to be ordered.
Jordan Lebrocq	10/02/2020	Moxey has an oil leak on the front of the cabin	Diagnose fault and order parts
Matt Irving	20/02/2020	Lose dip stick holder	Replaced dip stick holder
Michael Thomas	9/03/2020	Retarder valve O-rings leaking transmission oil	Jack cab, remove actuator piston, replace O-rings, fit piston & plate with new gaskets
Scott it all	11/03/2020		Check AC, pressurise system, find blown hose under cab, fit hose, vac and regas
Matt Irving	25/03/2020	Rubbed through hose	Fitted replacement hose, filled hydraulic tank
Matt Irving	25/03/2020	Transmission input yoke keeper lose	Removed transmission input uni
Matt Irving	31/03/2020	Leaking transmission input seal	Removed & replaced seal
Matt Irving	1/04/2020	Blown hydraulic hose - very dirty	Dropped all belly guards & cleaned off. Dug dirt out from around transmission, degreased & washed truck. Removed & replaced front B15 cab mount
Matt Irving	2/04/2020	Hydraulic leak	Lowered cab & bottled belly guards back up
Matt Irving	6/04/2020	Air valve leaking - 4way protection valve	Located leak, lifted cab, removed valve from truck
Matt Irving	7/04/2020	4 way air valve leaking	Fitted new valve onto truck
Matt Irving	8/04/2020	Service due - 500hr	Service truck
Matt Irving	27/04/2020	Lose fitting going to transmission codes	Tightened
Glen Devine	5/05/2020	No A/C fan	10/06/20 M Thomas
Glen Devine	5/05/2020	Exhaust stack loose in muffler - rattling around and hitting trans dipstick tube	10/06/20 M Thomas
Glen Devine	5/05/2020	Front shock absorbers (NS) truck bounces around like crazy	10/06/20 M Thomas
Glen Devine	5/05/2020	Noise vibration at times left front wheel - axle uni joint	10/06/20 M Thomas
Matt Irving	6/05/2020	Lose exhaust clamp	Clamp needs to be cut off & replaced
Georgia Sadler	11/05/2020	Auto greaser playing up - won't change gears with it plugged in (tried re-plugging it in etc, still no movement of gears)	25/05/20 M Thomas
Michael Thomas	12/05/2020	Bonnet won't close	Pull cable through & close bonnet
Michael Thomas	13/05/2020	Auto greaser is not working	Checked found hose to rear valve block leaking. Remove & take to Scotty. Get new hose, refit to truck & bleed line
Michael Thomas	13/05/2020	Auto greaser	Checked. Found hose to rear valve block leaking, remove. Take to Scotty, get new hose. Refit to truck & bleed line.
Michael Thomas	19/05/2020	Grease pot	Remove grease pot from truck, take to workshop & disassemble
Michael Thomas	20/05/2020	Auto greaser	Clean parts & reassemble auto greaser. Take to site & fit to truck. Test - still faulting, pull out & pull apart again. Check circuit board, found it to be u/s. Swap with another spare circuit board & reinstall, test - still faulting. Check pressure sensor & wiring - ok. Found main plug to auto greaser unit has broken pins. Fit new connector, test - still faulting. Asked operator about it on 25/05/20, he said it is operating properly. Must of had air in the system.
Michael Thomas	10/06/2020	Exhaust, horn, wipers not working, A/C fan not working	Fit new clamp to exhaust on muffler, fit new mount. Bolt to muffler, check operation of horn & wipers - found them to be working perfectly. Check AC fan operation - found fan to be working normally. Check front axle shafts - found small amount of movement in inner uni will replace soon.
Keith Rumble	12/06/2020	E-stop broken on left side	17/06/20 M Thomas
Keith Rumble	12/06/2020	Air con not working just stops	15/06/20 M Thomas
Michael Thomas	15/06/2020	No AC	Fit fuse to AC system
Michael Thomas	17/06/2020	E-stop on back of cab broken	Fit new e-stop
Rawdon Hunter	30/06/2020	Brake test failed	30/06/20 M.Irving
Matt Irving	30/06/2020	Operator claimed it failed brake test	Removed & replaced park brake pads
Matt Irving	30/06/2020	Hole in exhaust, rubber mount on fire	Extinguished fire. Tagged truck out, adjusted park brake
Matt Irving	7/07/2020	Hole in exhaust	Removed exhaust
Matt Irving	14/07/2020	Hole in exhaust	Removed burnt rubber mount & fitted new mount. Fitted repaired exhaust
Matt Irving	15/07/2020	Park brake not holding	Adjusted
Matt Irving	16/07/2020	Wear lip on park brake disc	Buffed lip off disc & readjusted park brake
Matt Irving	17/07/2020	Low hydraulic oil level	Topped up oil
Matt Irving	11/08/2020	28R not starting. Swapped ECUS over with 274	Still not starting, zipped tied electrical cable back onto ECUS
Matt Irving	14/08/2020	Leaking fuel lines	Fitted new lines
Michael Thomas	21/08/2020	Hydraulic leak	Jack cab, found fan hose leaking
Michael Thomas	24/08/2020	Hydraulic hose, knocking noise	Remove fan hose, get new one made & fit to truck - start & check for leaks - ok. Check knocking noise, cannot hear in engine bay, sounds like it is coming from transmission input bearing & retarder valve.

Matt Irving	25/08/2020	Still leaking fuel from bango fitting on injector pump	Change hose back to plastic pipe
Brandan Saunders	27/08/2020	AC not working	Scotty has looked at it a couple of times
Brandan Saunders	27/08/2020	Cab mounts stuffed	Mike inspected 31/08/20
Matt Irving	2/09/2020	Ran out of fuel, no dash gauges working	Changed fuel filter, primmed fuel system
Matt Irving	2/09/2020	Park brake locked on	Hole in air hose going to park brake actuator repaired hose
Matt Irving	10/09/2020	Bearing U/S on intermediate shaft	Started to disassemble
Matt Irving	11/09/2020	Worn bearing on intermediate shaft	Finished removing shaft & took back to workshop. Removed bearing housing.
Matt Irving	23/09/2020	Intermediate shaft bearings worn out	Fitted new shaft to trucks
Jordan Lebrocq	23/09/2020	Shaft has blown bearing out	Replace disc at the workshop, assist Matt to fit drive shaft
Brad Page	23/09/2020	Assisted Matt - drive shaft	Helped Matt fit drive shaft in. Line all bolt holes up, lift hand brake back on, found disc was bent
Jordan Lebrocq	24/09/2020	Drive shaft needs rebuilding	Replace bearings on driveshaft
Brad Page	24/09/2020	Assisted Matt - leak behind pos 2	Unloaded fork lift, jacked up pos 2, found brake piston leaking
Jordan Lebrocq	25/09/2020	Drive shaft discs has been machined	Try to fit driveshaft but machine shop has pressed park brake disc to flat
Jordan Lebrocq	28/09/2020	Drive shaft needs holes drilled bigger	Drill holes bigger to fit new brake disc to truck, adjust handbrake
MRG Maintenance	29/09/2020		Repair fuel tank
Jordan Lebrocq	1/10/2020	Shaft needs bearings fitted	Fit bearings & bolt shaft onto Moxy, adjust parkbrake
Brad Page	1/10/2020	Tail shaft - assisted Jordan	Assisted Jordan to fit new drive shaft & hand brake, bleed/adjust hand brake & test.
Michael Thomas	2/10/2020	No A/C	Found evaporator iced up due to thermostat failure. Get new thermostat & fit to machine. Set to correct temperature
T&C Services - Programmed	13/10/2020		Press and skim brake rotor
Brad Page	22/10/2020	Checking brakes	Jacked up pos 1 and pos 3. Removed wheels, checked linings & disc
Matt Irving	23/10/2020	Brake inspections	Removed all tyres and checked brakes
Brad Page	23/10/2020	Checking brakes	Loaded fork lift, jack & brakes. Went to Ash Dam to unload. Removed all wheels & checked brakes
Jordan Lebrocq	12/11/2020	Check over for rail job	Top up brake fluid, replace reverse alarm
Will Hobden	19/11/2020	Tailshaft failed from transmission to park brake	Cleaned truck artic area for repairs
Brad Page	19/11/2020	Assisted Will - drive shaft	Got first drive out of cement Moxy put in part's washer, cleaned it up.
GOFM	3/12/2020		Remove park brake assembly, removed drive line and damaged grease lines.
Brad Page	3/12/2020	Assisted Graham	Remove drive shaft & hand brake. Strip shaft down, bearings & discs. Got ready for sending for repair to threads.
GOFM	8/12/2020		Started setting up tail shaft to go back in between transmission and park brake.
Brad Page	8/12/2020	Assisted Graham	Put new bearings in tailshaft, drill and tap threads for grease nipples
Will Hobden	9/12/2020		Re-tapped threads on park brake rotor for Stumpy.
GOFM	9/12/2020		Finish putting tail shafts back together and put back on between trans and park brake
Brad Page	9/12/2020	Assisted Graham	Fit yokes together on truck, had to line up holes
GOFM	10/12/2020		Finish bolting shafts on and purge grease lines made fitting to do job. Checked over, found leaking hydraulic hose, put AC cover back on, start to lift cab to get to hose.
GOFM	11/12/2020		Jack cab up, removed coolant tank to get to blown hose, got hose out, then put new one back in. (hose from pump to fan)
Brad Page	11/12/2020	Assisted Graham	Fit cab pins in, needed one person with bar. Put some bolts in fan oil line. Clap held the back of bolt
Michael Thomas	4/01/2021	Transmission light on dash.	Check code, found 27 - retarded temp sensor OC. Jack cab, found plug off sensor. Cable tie plug onto sensor, Put down cab.
MRG Maintenance	6/01/2021		Repair radiator bracket
Jordan Lebrocq	6/01/2021	Truck needs cab mounts (operator defitted machine)	Take 274 for a drive & confirm cab mounts
Michael Thomas	11/01/2021	Fuel leak	Found rub through plastic hose. Remove hose & get new slave & hose from Pirek
Michael Thomas	15/01/2021	Cab mounts stuffed	Jack rear of cab, remove pins. Die grind out RH rear mount, clean up drill & tap hole for lock bolt. Fit new cab mount.
Michael Thomas	18/01/2021	Cab mounts rear	Die grind & hit LH rear cab mount out. Drill & tap bolt hole to lock new bush, fit new bush, fit cab pins.
Matt Irving	3/03/2021	Park brake not holding	Adjusted park brake
Peter Mepham	25/03/2021	No fuel gauge	Not required - 28/07/21 M.Thomas
Jordan Lebrocq	7/04/2021	Leak in transmission	Top up trans with 20l of oil, run moxy to find leak
Brad Page	7/04/2021	Oil leak	Assisted Jordan find oil leak. Lift cab, found gearbox dipstick empty. We topped up oil, found oil leak around drive shaft so we tagged machine out
Scott it all	15/04/2021		Fit second hand trans yoke, have trouble fitting as spline damaged, remove drive shaft. Fit drive shaft, fit lock, remove broken fitting, fit grease line, remove exhaust, refit elbow, repair horn, find issue with wipers, remove wiper motor and dismantle. Find issue with door latch.
Brad Page	15/04/2021	Assisted Scotty, trans rear output oil leak	Helped Scotty put yoke in gearbox, had to try & hit it in
GOFM	16/04/2021		Remove exhaust pipe for repairs.
MRG Maintenance	19/04/2021		Repair exhaust, muffler and door
Jordan Lebrocq	29/04/2021	AC motor has stopped working	Finish fitting wiper motor & wire up motor

Matt Irving	21/05/2021	Park brake not holding	Adjusted park brake
Jordan Lebrocq	1/06/2021	AC fans have stopping working & seat is faulty	Replace AC fans & fix seat, air hose
Matt Irving	30/06/2021	Fuel leak	Hose joiner had come apart, rejoined, degreased & washed down. Coolant leak, added another hose clamp to hose. Adjusted park brake. Missing bolt, bottom of injector pump - replaced bolt.
Matt Irving	1/07/2021	Low hydraulic oil level	Topped up hydraulic oil
Matt Irving	5/07/2021	Fuel leak	Removed hose and fitting & took to Pirtek
Matt Irving	6/07/2021	Fuel leak	Fitted new hose. Coolant leak, dropped coolant out & cleaned up steel pipe with emery cloth. Reclamped hose back on & filled with coolant.
Matt Irving	16/07/2021	Low on power	Auto greaser empty. Filled auto greaser, no 5 injector line appears to be cracked. Wiper washer hose split, new hose required. Wipers not working, blown fuses. Removed & replaced fuses. Parkbrake not holding - adjusted, still not holding. Air leak, split hose - repaired.
Matt Irving	19/07/2021	Missing u bolt supporting intercooler to turbo pipe	Fitted replacement U bolt.
Matt Irving	19/07/2021	Park brake not holding	Started looking at brake booster stroke
Matt Irving	20/07/2021	Leaking injector line pos 5. Park brake booster not working	Removed injector line & booster. Picked up replacement booster.
Matt Irving	22/07/2021		Fitted replacement park brake booster, cut push rod to length
Matt Irving	28/07/2021	New park brake booster fitted	Removed air fitting & took to pirtek. Replaced fittings & hose.
Matt Irving	28/07/2021	New park brake booster fitted	Fitted new hose & fittings to park brake booster. Fitted new injector line No. 5
Matt Irving	29/07/2021	Coolant leak	Drained coolant, applied liquid steel to steel pipe. Located injector clamps.
Matt Irving	30/07/2021	Creaked injector line	Finished clamping up injector lines. Filled with coolant, segregated some hoses, test drove.
Matt Irving	6/08/2021	Broken E-stop	Removed & replaced e-stop
Matt Irving	13/08/2021	Exhaust brake not working	Inspected - accumulator U/S
Matt Irving	18/08/2021	Exhaust brake accumulator broken	Removed accumulator & butterfly to repair
Matt Irving	19/08/2021	Exhaust brake accumulator broken	Assemble new accumulator. Removed & replaced broken accumulator
Matt Irving	2/09/2021	Door hard to open. Gear stick button not working	Sprayed latch with lube. Removed & replaced button on top of gear stick.
Brad Page	21/09/2021	Slow leak pos 2	Went LAD to pump up tyre has slow leak, will swap out when can get to it.
Matt Irving	28/09/2021	Pos 2 leaking brake fluid	Removed caliper & removed/replaced piston seals
Brad Page	28/09/2021	Brake caliper leaking pos 2	Wheel was stuck on, had to get portapower on it. Jacked up truck, removed wheel, found to have pistons leaking on back caliper. Removed it, cleaned it up
Matt Irving	29/09/2021	Bleed brakes, Pos 2 leakign brake fluid	Tightened exhaust clamp
Brad Page	29/09/2021	Brake caliper leaking pos 2	Put new seals in & boots. Rubber greased seals, put piston in, put linings in & pins, fitted back on truck & lock tightened bolts. Bled brakes, fitted wheel back on & tensioned nuts.
Matt Irving	14/10/2021	Loose exhaust bracket	Tightened bracket
Matt Irving	18/10/2021	Low on power - engine	Clamp holding pipe to intake had come undone
Matt Irving	3/11/2021	Ran trucks & located leaks. Cab ram not lifting	Lifted cab with chain & comealong. Cleaned off belly guards
Matt Irving	4/11/2021	Leaking hydraulic hose	Drained hydraulic tank to change hose. Removed & replaced hose.
Matt Irving	9/11/2021	Hydraulic leak	Bolted belly guards back on. Finished tightening replacement hose. Filled hydraulic tank. Tightened hose fitting inside artic bottom.
Matt Irving	11/11/2021	Some lights not working	Removed & replaced blown bulbs.
Matt Irving	1/12/2021	Wiper motor keeps blowing fuses	Removed & replaced wiper motor. Had to redo plug ends as the new one was a 5 pin plug & the old was a 4
Matt Irving	8/12/2021	No flashing light, pole for light loose & holding on by one bolt	Replaced missing bolt in pole. Tightened other bolt, replaced flashing light.
Matt Irving	15/12/2022	Low hydraulic oil	Topped up oil
Matt Irving	12/01/2022	Lifted cab (hyd oil leaks)	Inspected for oil leaks - many found. Cab lift ram not going up.
Matt Irving	14/01/2022	Leaking hydraulic hose	Fitted replacement hoses. Filled hydraulic tank back up. Topped up coolant - test drove. Cab lift ram leaking & not lifting - removed ram.
Matt Irving	24/01/2022	Hydraulic hose leaking	Located leak. Hose that was replaced last week is leaking from ferral
Will Hobden	24/01/2022	Hydraulic leak	Checked over before starting. Topped up hydraulic oil, started & operated hoist. Oil leaking out of hose in artic area.
Scott H all	25/01/2022		Make Up and Supply hoses to replace low pressure
Matt Irving	25/01/2022	Hydraulic hose leak	Removed hose
Matt Irving	27/01/2022	Hydraulic hose leaking, warn cab mount FLHS	Fitted replacement hose. Removed & replaced cab mount, drilled & tapped hole for mount keeper.
Matt Irving	31/01/2022	Hose blew clean out of ferral	Attempted to fit replacement hose. Wheel needs to be removed, picked up taller.
Will Hobden	25/01/2022	Hydraulic oil leak	Jacked cab after finding leak. Drained hydraulic oil.
Matt Irving	2/02/2022	Hydraulic leak	Fitted replacement hose. Fitted cab lift ram. Filled hyd oil tank. Fitted guards back on.
Matt Irving	10/02/2022	Coolant leak	Picked up coolant from Liddell Ash Dam. Topped up coolant leak to excessive to keep truck running.
Matt Irving	14/02/2022	Coolant leak	Removed leaking pipe going to water pump. Lifted cab to check wiring harness. Damaged plug going to speed sensor. LHS inner uni joint has play in it.
MRG Maintenance	22/02/2022		Find and repair crack
Matt Irving	16/02/2022	Coolant leak	Removed steel pipe to get repaired, lifted cab to inspect speed sensor.

Will Hobden	15/02/2022	Uni joint on LHS front diff	Removed & replaced uni
Will Hobden	18/02/2022	Coolant line	Fitted coolant line.
Matt Irving	2/03/2022	Steel pipe still leaking coolant	Removed for repair. Attempted to crack test
Michelle Saunders	21/01/2022	Hydraulic leak on RHS	02/02/2022 M Irving
Michelle Saunders	2/09/2021	Lights don't work LH RH	11/11/21 M Irving
Michelle Saunders	2/09/2021	Gear stick switch is faulty	02/09/21 M Irving
Michelle Saunders	2/09/2021	Wipers don't work	01/12/21 M Irving
Gavin Mortimer	20/10/2021	Horn not working	01/12/21 M Irving
Michael Thomas	24/03/2022	Coolant pipes, cab pins	Fit repaired pipe to water pump. Fit hoses and fill with coolant fit cab pins
Matt Irving	21/04/2022		Checked over and started up.
Matt Irving	16/05/2022	Park brake locked on	Pulled park brake accumulator back and then backed park brake off, found pressure reg on front RHS of truck had blown the plastic cap off
Brad Page	17/05/2022	V5	Adjusted park brake
Matt Irving	17/05/2022	Park brake locked on	Park brake reducer valve 11/5. By passed and adjusted park brake.
Scott it all	30/05/2022		Find elect fault cab blower, and repair. Secure console above head
Scott it all	31/05/2022		Drive to Void 5 check over 274 top up grease container, adjust exhaust, check oil level, hose weeping, top up hyd oil.
Scott it all	1/06/2022		Drive to void 5, Replace blown section of fuel return line.
Luke Sales	7/06/2022	Hyd oil leaks	Inspected leaks and damage to clamp truck
Brad Page	8/06/2022	Hyd oil leak	Took truck over to wash pad, tilted cab, lifted bin degreased engine gearbox, cleaned under engine everywhere to help find oil leaks, cleaned up washpad after that.
Brad Page	8/06/2022	Hose's	Drained Hyd oil tank helped Scotty remove hose's to make new one's
Brad Page	9/06/2022	Hyd oil leaks	Assisted Scotty, drained hyd tank, removed some hose's that Scotty made new one
Scott it all	9/06/2022		Remove hose's back off pump, start to remove pump, remove exhaust stack
Will Hobden	28/06/2022	Fuel	Fueled up
Brad Page	29/06/2022	Hyd pump oil leak	Assisted Scotty tilted cab up to look for easier way to get top bolts out from pump.
Reedbuild	30/06/2022		Reseal hyd pump, pick up new hose from Pirek and fit
Luke Sales	30/06/2022	Hose from tank to pump requires replacing	Got hose made up at Pirek
Will Hobden	1/07/2022	Hyd pump mount leaking oil	Helped Tristan (contractor) fit and tighten up hoses and bolts on pump
MRG Maintenance	4/07/2022		Repair Moxy exhaust
Scott it all	4/07/2022		Fit panels, fit exhaust, fit cab pins
Scott it all	5/07/2022		Fit panels fill up hyd oil, fit estop, fit cab mounts
Matt Irving	27/07/2022	Checked over	Filled auto greaser, park brake bulb blown
Matt Irving	10/08/2022	Low hyd oil	Topped up
Matt Irving	12/08/2022	Park brake not holding	Adjusted park brake disc badly warped, needs to be replaced.
Matt Irving	7/09/2022	Checked over	Tightened A/C belt, tightened exhaust clamp
Mickanical Services	6/10/2022	Blown hyd hose	Remove park brake hose from aggr truck in yard, travel to Denman and inspect leak, found RH rear brake hose blown, remove hose and cap line so truck can be moved out of rail corridor, travel to town and get new hose made by Scotty, travel to Denman and install new hose, top up hyd oil 20 litres.
Matt Irving	6/10/2022	Cracked mirror	Removed and replaced mirror
Scott it all	14/10/2022		Check A/C
Will Hobden	18/10/2022	Defects	Washed, inspected defect list and confirmed cracked manifold and oil leak on rear pump, removing and labelling hoses for access to pump for removal
Will Hobden	19/10/2022	Hyd pump leaking	Removed hoses, removed pump, capped and cleaned pump and drove down to Singleton for repair to pump to Valley Hyd
Will Hobden	20/10/2022	Defects	Removed turbo to get to cracked exhaust manifold, removed manifold, sealed everything up, removed POS 3, 3 and 5 tyres and inspected brakes, refitted tyres and torqued wheel nuts.
Will Hobden	21/10/2022	Fuel tank RH side	Helped Gus remove fuel tank, cleaned out fuel tank, helped Gus cut out bash plate to find crack in the tank, removed old fridge in camper
Scott it all	19/10/2022		Make up and supply 2 x-6 metric, ST/90
Scott it all	20/10/2022		Remove all LHS wheels, check brakes, modify sip stick, check final drives, grease up tandems
Reedbuild	19/10/2022		Remove and inspect hoist pump, hoist pump sent to Valley Hyd for repairs, reseal dipstick tube.
Will Hobden	21/11/2022	Park brake disc, hyd pump	Fitted new park brake disc, fitted park brake assembly, fitted drive shaft, fitted hyd pump
Luke Sales	25/11/2022	Artic bearings to be machined	Disassembled artic bearings, cleaned bearings, took to Programmed
Will Hobden	24/11/2022	Defects - hyd pump leaking oil, exhaust manifold cracked	Fitted hoses on pump, finished plumbing up, fitted exhaust manifold, fitted turbo.
Will Hobden	25/11/2022	Defects	Fitted turbo, plumbed up drain line, filled turbo with oil and fitted fill line, topped up tandem oil levels
Scott it all	24/11/2022		Replace fuse, top up a/c gas, wash out condenser, a/c gas
MRG Maintenance	24/11/2022		Weld blocks on bucket
Will Hobden	1/12/2022	Defects - cracked exhaust, leaking hyd pump	Fitted exhaust, fitted intake, bolted cab down, fixed up some e stop wiring issues, topped up hyd oil
MRG Maintenance	29/11/2022		Repair Moxy exhaust

MRG Maintenance	14/12/2022		Repair Moxy exhaust
Will Hobden	2/02/2023	Park brake out of adjustment	Operators have been driving through park brake, adjusted park brake.
Will Hobden	10/02/2023	Dumpy wouldn't go out of 2nd gear	Removed auto greaser plug to get going
Scott it all	24/02/2023		Check out a/c fan issue, clean filter, check pressures, find everything ok
Scott it all	13/03/2023		A/c repairs slight top up, replace pilot line
Scott it all	14/03/2023		Find elec issue with fans, bypass bad plugs, find fans u/s, modify and fit new fan assembly, rewire to suit, used Temex style fan
Will Hobden	3/05/2023	Check over for work	Dumped grease into tandem bearing seals, adjusted park brake, fueled up, checked levels.
Luke Sales	30/06/2023	Going to site - check over for hire	Checked over, filled engine oil
Luke Sales	3/07/2023	Check over for hire	Changed wiper on wind screen, reconnected auto grease lines, got auto grease fittings from Hydraulink.
Matt Irving	3/07/2023	Auto greaser empty	Auto greaser refiller missing hose, found a hose and fitted connector to make hose fit, filled auto greaser, checked auto greaser was pumping ok.
Brad Page	3/10/2023	Check over	Did tyre's for pressure's, checked lights, oils, fueled it up.
Luke Sales	18/10/2023	Shaft uni joint	Removed shaft and uni joints
Luke Sales	19/10/2023	Uni joint	Cleaned surfaces, replaced both uni joints, fit shaft and tightened
Matt Irving	20/10/2023	CV shaft uni joint u/s	Assisted Luke in changing
Brad Page	26/10/2023	check over for hire	Checked over truck tyres for pressure and oils had to re-wire cab light, fuel up
Matt Irving	1/11/2023	Flat batteries	Jump started, checked alternator for charge, no voltage regulator u/s, removed reg from 282 and fitted to 274.
Matt Irving	8/11/2023	Ran out of fuel	Bleed up fuel system
Brad Page	24/07/2024	Jump started	Ran around yard to charge it up
Luke Sales	2/08/2024	Inspection	Got ready for job with Pete
Peter Ross	2/08/2024	Going out on hire - check over	Check over machine, topped up engine oil, brake light not working - found fault with fuse loose in holder
Brad Page	2/10/2024	Oscillation bearing change	Got truck onto pad got train track out of yard, got in under the truck, got all stands under front of cab, got rear held up with bottle jack, undid hoses in hitch area, removed drive shafts from gearbox and park brake.
Brad Page	3/10/2024	Oscillation bearing change	Removed all bolts on cab side of bearing, got fork lift and separated cab from tipper body, removed all allen key bolts from isolation bearing, got fork lift and lifted it off chassis, got new bearing loosened off bolts to line up holes, got fork lift and lifted on, cleaned and buffed bolts, cleaned up bearing surfaces where sits on truck, started tensioning allen head bolts 800nm didnt get all done yet.
Peter Marheine	2/10/2024	Oscillation bearing to be changed	Start repairs/change out
Peter Marheine	3/10/2024	Oscillation to be replaced	Start fitting oscillation bearing
Brad Page	8/10/2024	Oscillation bearing	Put truck close together to line bolt holes had to turn bearing abit, jack up cab little line up, got bolts started put drive shaft bolt in, not finished
Brad Page	9/10/2024	Finished off	Finished off tightening all bolts on oscillation bearing, put drive shafts back in, cleaned air filter, checked tyre pressures, changed engine oil and filter, packed up oil trailer, shut shed up
Peter Marheine	8/10/2024	Oscillation bearing	Carry one with oscillation installation
Peter Marheine	9/10/2024	Oscillation bearing change out	Finished off bearing change