



## Vehicle History Detail



Fleet #	XN06AM
Registration	XN06AM
Make	KENWORTH
Model	K200
VIN / Chassis #	6F5000000DA450534

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-1820	13/12/2022	1750000	0	Mud Guard		REPLACED REAR BAR REPLACE L/H MUDFLAP AND MUDGUARDS REPLACE REAR COMBO LIGHTS REAR BAR WAS OLD STOCK MUDGUARDS AND MUDFLAP ALSO OLD 2ND HAND PARTS		\$3,398.63
O-201	23/11/2022	0	0	Registration			1- 0399432923	\$4,800.00
R-1786	02/11/2022	2003623	0	Power Steering		Remove Power Steering Hoses take to harden bearings to make new ones fit new P/S Hoses		\$770.11
S-2652	02/11/2022	2003623	0	A - Fortnightly				\$165.00
S-2637	10/10/2022	1750000	0	B - 50k	Jack			\$1,063.25
T-570	12/09/2022	1972708	25590	Second hand tyre		2x second hand tyres 2x truck tyre disposal	108209	\$340.00
R-1716	24/08/2022	1750000		HUB SEAL				\$167.48
R-1710	22/08/2022	1750000	0	Indicators				\$0.00
S-2578	22/06/2022	1951908	0	A - Fortnightly	Dylan			\$350.24
R-1660	22/06/2022	1750000	0	Battery	Jack	replace batteries		\$930.20

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-1650	21/06/2022	1951906	0	Wiper Washes	Dylan, Jack	adjust washers replace damaged tank rubber replace L/H spotter mirror		\$388.62
R-1613	02/06/2022	1948327	0	Dash - Gauges	Jack	replace all blown lights in dash		\$157.63
R-1565	14/05/2022	1750000	0	Electrical	Jack	replaced nox sensor IN EXHAUST Replaced heater hose ( found split in 16)		\$2,181.63
S-2565	11/05/2022	1750000	0	D - 300k				\$2,362.78
R-1566	10/05/2022	1750000		Electronic Diary		NAVMAN REMOVED		\$35.75
T-517	27/04/2022	1750000	0	Second hand tyre, Strip & Fit		1x strip and fit 2x second hand tyres 3x truck tyre disposal	106842	\$590.00
R-1393	27/04/2022	1750000	0	Defect				\$0.00
R-1516	21/04/2022	1750000		Air Compressor		Repair 01/ PERFECT AIR TO TEST A/C,SYSTEM, FOUND AFTER RUNNING FOR SOME TIMENCOMPRESSOR WOULD CUT OUT AND NOT WORK REPLACED COMPRESSOR AND REGASED SYSTEM, ALL GOOD.		\$1,140.73
S-2541	08/04/2022	1920702	0	D - 300k	Dylan			\$1,647.78
T-500	24/03/2022	1750000	0	New			106479	\$1,290.00
T-498	15/03/2022	1750000	0	New		4 x multi d caps stk 4 x truck tyre disposal 1 x strip & fit on truck	106384	\$1,823.00
R-1410	10/01/2022	1750000	0	Hub Leak	Jack	tighten hub bolts and clean oil from rim		\$286.00
O-181	26/11/2021	0	0	Registration			SN-372245954	\$4,703.60

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
O-182	26/11/2021	0	0	CTP				\$1,924.50
R-1373	06/11/2021	1750000	0	Defect		1x recon air compression 6x seal O ring 1x gasket acc drive support 1x gasket	1182249	\$2,993.14
S-2337	20/09/2021	1062717		B - 50k	Dylan, Jack, Kobi			
R-1381	15/09/2021	1750000	0	ad blue			0307144	\$2,147.38
T-372	15/07/2021	0	0	Cap		4x multi d caps 4c truck tyre disposal	103878	\$1,606.00
T-371	13/07/2021	1000000	0	New		2x bridgestone 2x truck tyre disposal	103864	\$1,675.00
T-345	01/07/2021			New - Steers		1x recamic cap and case 1x fitting 2.5x road service 1x truck tyre disposal	103733	\$801.50
R-1238	25/06/2021			Electronic Diary	Jack	Requesting a new cradle from Navman as won't stay charged new cradle and logbook returned on 23/6/21 just awaiting truck to be in the yard to fit it		\$0.00
R-1214	22/06/2021	0	0	Coolant Leak, Oil Leak		Pressure sensor leaking parts ordered 15/6/21 order coming from Brisbane to inland remove block return pipe replaced o rings and gasket refill system ( call out top up coolant added 11l of coolant )		\$739.55
R-1253	17/06/2021	1758906	0	Electrical	Jack	replace all blown globes in dash and replace speedometer		\$696.49
S-2256	15/06/2021	1757588	25590	C - 150k	Dylan, Jack			\$977.44
R-1158	04/06/2021	752360	0	Dash - Gauges	Jack	replace blown globes		\$86.13

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-1220	26/05/2021	1746577	0	Air Conditioner		AC WAS FIXED ON THIS TRUCK BY CANBERRA TRUCKS AND WAS ENTERED AS A NEW JOB INSTEAD OF BEING ADDED TO THIS		\$0.00
R-1188	15/05/2021	1739381	0	Ad Blue Tank, Gearbox	Kobi	add blue low red light on drove to service station filled with ad blue 147 litres - FUEL entry topped up gearbox oil		\$364.11
R-1192	15/05/2021	1000000	0	Trailer Plug	Kobi	replace trailer plug		\$79.70
S-2182	11/05/2021	1735819	0	A - Fortnightly				\$308.00
R-1177	11/05/2021	1735819	0	Driveline	Kobi	removed tail shaft then removed diff yoke and fixed dust seal cover then refit everything		\$286.00
R-1161	05/05/2021	1000000		Electrical	Jack	replace ebs and air suzi coils and fit new pogo pole to hold lines up		\$546.05
R-1156	05/05/2021			Fuel		Fuel card is back in vehicle		
R-1159	03/05/2021	1732339	0	Add Oil	Driver			\$36.08
R-1157	03/05/2021	1732339	0	Wheels		pry backing plate away from diff and back on to the yoke to stop rubbing noises		\$35.75
R-1133	24/04/2021	727842		Indicators	Jack	Replaced missing bolt		\$79.75
R-1139	24/04/2021	1727847	0	Electrical	Jack	Removed old tracking buzzer		\$35.75
R-1138	23/04/2021	1727284	0	Brakes	Dylan	brakes adjusted		\$71.50
R-1137	23/04/2021	1727284	0	Gearbox	Dylan	top up gearbox oil replace grease line in gearbox		\$259.49
S-2129	19/04/2021	1724705	0	A - Fortnightly -	Dylan	needed 13 liters engine oil replaced cracked fan belt part no. 12PK2370		\$458.71
R-1121	15/04/2021	724047	0	Lights	Jack	replace blown globes		\$86.13

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-970	26/03/2021	1000000	0	Body Repairs	Yard	inspected leak coming from windscreen needs to be resealed and visor mounts silicone visors mounts refitted dash components test for leak		\$165.00
R-1078	18/03/2021	1000000	0	Engine Light	Kobi	plugged insite cummins software read codes active codes for coolant low level checked coolant low topped up 12l of coolant codes inactive wash off and clear codes no more engine light		\$99.70
T-296	12/03/2021	1000000	0	Strip & Fit		1x strip and fit 1x truck tyre disposal	102538	\$88.50
S-2021	08/03/2021	1707966	0	B - 50k	Kobi			\$763.60
R-971	01/03/2021	1700234	0	Air Conditioner		jack inspected relay found faulty relay replaced and working fine		\$83.22
R-1047	27/02/2021	1000000		Add Oil				\$62.98
S-1924	08/02/2021	1692710	0	A - Fortnightly	Zane			\$165.00
R-933	13/01/2021	1683507	0	Air Conditioner	Jack	New blower and resister fitted		\$341.55
S-1822	11/01/2021	1682686	0	A - Fortnightly	Dylan			\$361.59
R-918	07/01/2021	1659638	0	Electrical	Jack			\$182.54
R-901	05/01/2021	1000000	0	Ad Blue Tank	Zane	new ad blue elbow fitted		\$102.12
R-828	23/12/2020	1000000		Trailer Plug	Jack			\$26.07
S-1218	22/12/2020	1670597	0	B - 50k	Dylan, Zane			\$572.88
T-228	21/12/2020	1000000	0	New		2x goodyear 1x truck tyre disposal	101559	\$1,296.50
R-751	05/12/2020	1662801	0	Air Conditioner		Truck a/c re gassed Waiting on invoice		\$0.00

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-586	02/12/2020	0	0	Electrical	Jack	Right weight scales have been burnt out. Circuit board is unrepairable. Will look into replacing with another device.		\$0.00
R-594	30/11/2020	1660000	0	Defect, Differential Oil Leak, Engine Oil leaks, Oil Leak		DEFECT CLEARED Re-registered 30/11 same rego		\$31,555.78
S-897	26/11/2020	1660000	0	B - 50k	Zane	B service carried out on completion of R-594		\$433.81
S-730	01/10/2020	1656733	0	A - Fortnightly				\$308.00
S-620	11/09/2020	1647174	0	B - 50k	Yard	Adjust RH steer wheel bearing		\$466.79
O-88	05/09/2020	0	0	Registration			22670891	\$4,599.15
R-586	26/08/2020	0	0	Electrical				\$0.00
T-123	31/07/2020	1000000	0	New, Strip & Fit		4x drive tyre 4x strip and fit 2x ruck tyre disposal	100027	\$2,497.00
T-120	27/07/2020	1000000	0	Puncture		Puncture repair	141564	\$77.00
S-533	20/07/2020	1000000	0	A - Fortnightly				\$192.06
R-373	14/07/2020	1000000		Lights		FITTED STEP LIGHTS		\$112.20
R-368	08/07/2020	1000000		Cab - Step	Yard			\$617.61
S-669	03/07/2020	1000000	0	A - Fortnightly	Yard	Test drive speedo 100 - Navman 97 Cruise control working over run jake truck 109-110 Navman 106-107		\$344.10
S-305	02/07/2020	1596020	0	B - 50k		Carried out B service checked wheel bearings		\$655.14
T-88	30/06/2020	1592256	0	Wear Inspection				
R-351	30/06/2020	1000000		Electrical	Jack			\$442.59

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-344	25/06/2020	1000000		Power Performance	Kobi			\$482.46
S-290	22/06/2020	1590341	0	B - 50k		completed B service		\$655.14
R-322	19/06/2020	1000000		Top Up Oil - Driver	Driver	Driver topped up engine oil		\$9.02
R-247	31/05/2020	1000000	0	Lights		Fit new Led lights and fix wiring to suit new lights Part no: 72711 (two of these used) Labour: 2.5hrs Done by Jack Odo: 573475		\$222.75
R-248	31/05/2020	1000000	0	Lights		Add new led strip lights Labour 1.5hrs Done by Jack Part no lv009		\$234.52
R-561	25/05/2020	1000000		Add Oil	Yard			\$37.72
R-228	22/05/2020	1000000	0	Lights		Add light bar to truck (bar supplied by Corey Robinson) Labour:2HRS Done by Jack & kobi		\$143.00
S-231	21/05/2020	1566437	0	A - Fortnightly				\$183.04
R-202	20/05/2020	1550537		Brakes, Defect	Mick	Adjust all brakes to meet manufactures specifications DEFECT HVN0551208 CLEARED		\$136.40
S-204	18/05/2020	1556863	0	B - 50k		duplicated job card		
T-66	07/05/2020	1000000	0	Puncture			140803	\$77.00
S-519	06/05/2020	1000000	0	A - Fortnightly				\$317.02
S-169	27/04/2020	1549115	0	A - Fortnightly		Reverse light on trailer not working - fault found in Suzy coil & repaired		\$335.06
R-189	27/04/2020	1000000	0	Suzi Coils	Yard	Reverse light on trailer (YN71FY) not working - fault found in Suzy coil & repaired		

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
T-62	15/04/2020	1000000	0	Rotate, Tyre Pressures		Drive rotation and pressure check	140578	\$968.00
S-156	14/04/2020	1539060	0	A - Fortnightly		6 litres engine oil in truck		\$186.56
T-33	10/04/2020	1000000	0	New		Good year x2 Tyre disposal	140387	\$1,296.50
S-74	26/03/2020	1528846	0	D - 300k	Dylan, Gus, Mick	G/box oil and filter changed Diff & g/box oils changed L/H cab lock hydraulic fitting snapped off - Repaired Done by Gus, Michael, Dylan		\$1,615.61
R-90	19/03/2020	1525126	0	Top Up Oil - Driver	Yard	Driver tyopped up oil with 13 litres		
R-48	11/03/2020	0	0	Towing			5293	\$660.00
S-469	03/03/2020	1000000	0	A - Fortnightly	Yard	6lt oil		\$348.59
R-78	26/02/2020	509874	0	Turntable	Yard	No grease required - ballrace		
R-79	26/02/2020	509874	0	Oil Leak, Water Leak				
R-76	26/02/2020	0	0	Cruise Control	Yard	De-activated - No Repair Required		
R-77	26/02/2020	0	0	Clutch	Yard	Driver error. No action required		
S-7	18/02/2020	1504110	0	B - 50k	Dylan, Mick			\$666.14
R-41	15/02/2020	801884	0	Brakes	Yard			
R-91	04/02/2020	1494111		Shock Absorbers	Gus	replaced shocks - rear drive		
R-21	03/02/2020	0	0	Engine				\$53.95
R-5	01/02/2020			Air Conditioner		replaced A/C compressor (already added to previous repair)		\$1,036.09
R-443	30/01/2020	1000000		Clutch		See attached for repairer notes		\$6,319.44



Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-2	30/01/2020	0	0	Windscreen Washers		replaced RHS and Middle wiper blades, replace RHS wiper washer jet,replace Middle wiper arm assy,		\$606.33
S-413	28/01/2020	1000000	0	A - Fortnightly		Tightened hub nuts on drive axle 2 X 120510739C0		\$209.04
S-349	16/01/2020	1482770	0	A - Fortnightly	Yard			\$317.02
R-4	10/01/2020	0	0	Cab	Tony Madden			
S-335	09/01/2020	1480180	0	A - Fortnightly	Yard			\$211.09
S-526	27/12/2019	1477034	0	B - 50k				\$581.90
S-971	18/12/2019	1471128	0	A - Fortnightly		8ltr engine oil		\$201.08
R-407	13/12/2019	1476621		Tailshaft		Tailshaft yoke eyes worn out both ends made new tailshaft, supplied with uni joints		\$453.19
S-1000	02/12/2019	1462769	0	C - 150k		5ltr oil. LHS tail light repaired Radiator cap		\$361.09
R-791	26/11/2019	1000000		Add Oil		4ltrs oil		\$28.77
R-790	22/11/2019	1000000		Add Oil		5 ltrs oil		\$33.27
S-999	19/11/2019	1453416	0	B - 50k		Filters only 6 ltr oil Drive tyres lazy rotation		\$460.87
R-6	19/11/2019	0	0	Cruise Control		no repairs, management issue		
R-789	18/11/2019	1000000		Add Oil		5ltrs oil		\$33.27
R-788	11/11/2019	1000000		Add Oil		5ltr oil		\$33.27
S-998	07/11/2019	1446164	0	A - Fortnightly		5ltr oil 12ltr oil Tighten drop arm & pipe c/member		\$384.67
S-51	15/10/2019	1431690	0	C - 150k	Yard			\$714.14
R-792	14/10/2019	1000000		Mud Guard		Replace LH drive guard		\$736.46
S-1001	30/09/2019	1000000	0	A - Fortnightly		Added 9ltr oil		\$205.59

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
R-480	27/09/2019	1000000		Defect, Self Clearing		fitted new windscreen DEFECT CLEARED		\$398.20
S-1002	10/09/2019	1406651	0	A - Fortnightly		4ltr engine oil Replace alternator. Replace 4x drive brake + drum seals. Replace 1st Drive wheel bearing pack 2nd drive (not sure of part numbers/ not added to job)		\$326.04
S-1003	29/08/2019	1397948	0	A - Fortnightly		Tighten RH steer booster bung		\$165.00
S-1240	19/08/2019	1391321	0	B - 50k				\$654.80
S-1239	22/07/2019	1372604	0	A - Fortnightly		Repair wiring at blower fan relay		\$236.50
R-879	15/07/2019	1000000		Add Oil		3ltr oil		\$35.80
R-878	11/07/2019	1000000		Add Oil		4ltrs engine oil		\$40.31
S-1592	09/07/2019	1366419	0	B - 50k		Filter only; changed geabox oil. No metal Fit recon air cleaner		\$382.67
R-877	08/07/2019	1000000		Add Oil		10ltrs oil		\$67.38
R-876	27/06/2019	1000000		Add Oil		6ltrs engine oil		\$49.34
S-1591	24/06/2019	1355668	0	A - Fortnightly		2ltr engine oil		\$174.02
S-1645	14/06/2019	1348203	0	B - 50k				\$542.05
S-1593	03/04/2019	1300174	0	B - 50k		7ltr oil filter change only		\$393.88
S-1644	23/03/2019	1292341	0	A - Fortnightly		5ltr oil		\$187.55
R-891	17/03/2019	1000000		Add Oil		6ltrs		\$44.94
R-890	10/03/2019	1000000		Add Oil		6ltr		\$44.94
R-1741			26303	Turntable				\$0.00
R-1742			26303	Headlights				\$0.00
R-1682			0	Windscreen Cracked				\$0.00

Number	Date	Kms	Hours	Type	Repairer	Repairer Notes	Invoice	Cost
150 Records							TOTAL:	\$116,797.54