

W/O No	Asset No	Registration Number	Asset Description	Job Type	Safety Note	Description	Contractor Name	Done Reading	Work Order Closed By	Cor Finished Date/Time	Labour Costs	Department	Parent Asset	Material Costs	Other Costs	Account Code	
13608	PM986		PRIME MOVER - PENDING DISPOS Break			COMPLETED BREAKDOWN - MURGON - OIL LEAK FROM ENGINE BAY	V02804 BDS MECHANICAL REPAIRS PTY LTD	212032	Casey Pickvance	4/07/2023	0 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC64	
18576	PM986		PRIME MOVER - PENDING DISPOS Correct			DEFECT #37405 - CEPACK		222173	Tuyet Tran	19/07/2023	156.25 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC64	
18578	PM986		PRIME MOVER - PENDING DISPOS Correct			COMPLETED REPLACE MISSING ABS PLUG			Tuyet Tran	19/07/2023	62.5 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC64	
18162	PM986		PRIME MOVER - PENDING DISPOS Break			COMPLETED BREAKDOWN - WACOL - AIR LEAK		19381	Casey Pickvance	24/07/2023	250 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC64	
21950	PM986		PRIME MOVER - PENDING DISPOS PM			COMPLETED ICEPACK SERVICE		0	Casey Pickvance	10/08/2023	250 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC64	
22435	PM986		PRIME MOVER - PENDING DISPOS Defect			COMPLETED DEFECT # 37406 & 37409SWAP DRIVERS SIDE SEATS WITH PM969. TRUCK LOCATED AT WACOLSEND DE ...			Casey Pickvance	11/08/2023	781.25 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC64	
27395	PM986		PRIME MOVER - PENDING DISPOS Movement	6x4		COMPLETED DROP DRIVER TO WACOL			Casey Pickvance	31/08/2023	62.5 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC64	
27597	PM986		PRIME MOVER - PENDING DISPOS Defect	6x4		COMPLETED DEFECT #37407 - SPEEDO REQUIRES FIXING		238474	Casey Pickvance	7/09/2023	500 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC64	
28853	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED EBS PLUG AND SUZI LINES LOOSE		1238474	Casey Pickvance	7/09/2023	156.25 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC64	
29122	PM986		PRIME MOVER - PENDING DISPOS Onboard	6x4		COMPLETED REPLACING ROCKYS OWN STICKERING			Casey Pickvance	8/09/2023	0 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC64	
29123	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED WASH TRUCK FOR SERVICE			Casey Pickvance	8/09/2023	750 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC64	
29409	PM986		PRIME MOVER - PENDING DISPOS PM	6x4		COMPLETED POLICE SERVICE		459361	Casey Pickvance	11/09/2023	312.5 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC64	
29410	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED FLATBED SERVICE			Casey Pickvance	11/09/2023	312.5 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC64	
32114	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED 24V BATTERIES CRACKED			Casey Pickvance	12/09/2023	0 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC64	
29458	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED HUB SEAL LEAKING			Casey Pickvance	12/09/2023	62.5 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC64	
29459	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED REAR BRAKES RELIGN		459361	Casey Pickvance	13/09/2023	312.5 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC64	
29460	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED INPUT SEAL LEAKING			Casey Pickvance	13/09/2023	375 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC64	
29462	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED FIT NEW AUTO GREASER			Casey Pickvance	13/09/2023	281.25 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC64	
32434	PM986		PRIME MOVER - PENDING DISPOS Capital	6x4	COMPLETE CRA	COMPLETED XROTC TURNTABLE & KING PIN CHANGEOUT PROJECT		0	Casey Pickvance	27/09/2023	312.5 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117	
32445	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED REPAIR SUZI LINES ELECTRICAL AND AIR		0	Casey Pickvance	27/09/2023	125 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117	
32471	PM986		PRIME MOVER - PENDING DISPOS Onboard	6x4		COMPLETED ONBOARDING			Sandy Griffiths	27/09/2023	31.25 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117	
32613	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED - CHANGE OUT FIRE EXTINGUISHER			Faleiniu Clarke	27/09/2023	0 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117	
34463	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		A/C REPAIRS - COMPLETED			Deanne Carige	5/10/2023	0 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC117	
34592	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		REMOVE TURNTABLE PIN - COMPLETED			Deanne Carige	5/10/2023	218.75 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC117	
34864	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED FIT GREASE LINES TO TURNTABLE	V02804 BDS MECHANICAL REPAIRS PTY LTD	0	Casey Pickvance	9/10/2023	1750 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC117	
37460	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED REMOVE/REPLACE INPUT SHAFT			Casey Pickvance	17/10/2023	125 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117	
34547	PM986		PRIME MOVER - PENDING DISPOS Defect	6x4		COMPLETED DEFECT # 37406 & 37409 - NEEDS NEW CLUTCH OR ADJUSTMENT		0	Casey Pickvance	21/10/2023	0 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117	
37165	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED REPLACE CLUTCH		0	Casey Pickvance	21/10/2023	4656.25 WKBR	PERTH ADMINISTRATIVE	464.22	0	0	CC117	
41720	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		REPAIR GREASE LINE TO TURN TABLE - COMPLETED		576099	Deanne Carige	7/11/2023	312.5 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC117	
43592	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		REPLACE FROM ENGINE MOUNTS - REPLACE BATTERIES - REPLACE TANK STRAPS - COMPLETED			Deanne Carige	15/11/2023	562.5 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC117	
45650	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED BREAKDOWN - PINKENBA - GEAR LINKAGE			Deanne Carige	20/11/2023	312.5 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC117	
51841	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		REPLACE ABS PLUG		0	Jodie Howlett	19/12/2023	312.5 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC117	
52500	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED CHECK ICEPACK OVER			Sandy Griffiths	21/12/2023	812.5 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC117	
53319	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		JUMPSTART TRUCK			0	Jodie Howlett	2/01/2024	125 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC117
53319	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		R&R CAB SHOCK			0	Jodie Howlett	4/01/2024	437.5 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC117
60119	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED STEP REPAIRS			0	Sandy Griffiths	30/01/2024	562.5 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC117
69889	PM986		PRIME MOVER - PENDING DISPOS Defect	6x4		COMPLETED FRIDGE NOT WORKING			Brittany Scott	21/02/2024	62.5 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC117	
54675	PM986		PRIME MOVER - PENDING DISPOS Defect	6x4		COMPLETED FRIDGE NOT WORKING - PHONE SIM SHOWING NO SIM CARD		576099	Sandy Griffiths	21/02/2024	62.5 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC117	
65945	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED R&R TORQUE ROD BUSHES			Sandy Griffiths	21/02/2024	62.5 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC117	
65944	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED R&D DRIVE AIRBAG			Sandy Griffiths	21/02/2024	718.75 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC117	
70181	PM986		PRIME MOVER - PENDING DISPOS Damage	6x4JACK		COMPLETED REPLACE DAMAGED ABS PLUG			Brittany Scott	7/03/2024	250 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117	
80596	PM986		PRIME MOVER - PENDING DISPOS PM	6x4		COMPLETED - OVERDUE B SERVICE KENWORTH MEDIUM CENTURION (NF)			Faleiniu Clarke	19/04/2024	1062.5 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117	
80804	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED - REPLACE LEAKING FRONT DIFF INPUT SHAFT SEAL		299361	Charmaine Kennedy	19/04/2024	500 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117	
80805	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED - REPLACE LEAKING DRIVE AIRBAG RH FRONT			Charmaine Kennedy	19/04/2024	375 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117	
80806	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED - REPLACE U/S SHOCK ABSORBERS AS REQUIRED		299361	Charmaine Kennedy	22/04/2024	625 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117	
37738	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED - REAR MAIN ENGINE SEAL REPLACE	V00647 BROWN AND HURLEY GROUP PTY I	304295	Charmaine Kennedy	13/05/2024	125 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117	
41381	PM986		PRIME MOVER - PENDING DISPOS Defect	6x4		COMPLETED - DEFECT#37409 - GEARBOX			0	Charmaine Kennedy	13/05/2024	250 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117
86145	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED CHECK BRAKE LEAKING		304295	Charmaine Kennedy	13/05/2024	118.75 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117	
86560	PM986		PRIME MOVER - PENDING DISPOS Break	6x4		COMPLETED JUMP START TRUCK			304300	Charmaine Kennedy	22/05/2024	125 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117
90763	PM986		PRIME MOVER - PENDING DISPOS PM	6x4		COMPLETED - NIWA'S ANNUAL INSPECTION POWERED EQUIPMENT (NF)			304369	Stacey Thompson	30/05/2024	375 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117
90764	PM986		PRIME MOVER - PENDING DISPOS PM	6x4		COMPLETED - A SERVICE KENWORTH MEDIUM CENTURION (NF)			304369	Stacey Thompson	30/05/2024	687.5 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117
90900	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED - SERVICE ICE PACK			304369	Stacey Thompson	30/05/2024	312.5 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117
91021	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED STEP REPAIRS			304369	Stacey Thompson	30/05/2024	968.75 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117
91704	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED SWAP OUT SEAT			304369	Casey Pickvance	21/06/2024	500 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117
10376	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED REPLACE WIPER BLADES			307695	Pean Outunuku	16/07/2024	37.5 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117
10378	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED CHECK HEATER TAPS			307695	Pean Outunuku	16/07/2024	18.75 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117
64029	PM986		PRIME MOVER - PENDING DISPOS Break	6x4		COMPLETED BREAKDOWN @ MILES - LOSS OIL PRESSURE			311994	Samantha Shaw	10/09/2024	312.5 WK ROCK	PERTH ADMINISTRATIVE	0	0	0	CC117
90724	PM986		PRIME MOVER - PENDING DISPOS Defect	6x4		COMPLETED DEFECT #57110 - SEAT REPLACEMENT			311994	Samantha Shaw	10/09/2024	62.5 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117
119144	PM986		PRIME MOVER - PENDING DISPOS Capital	6x4		COMPLETED - CAMPAIGN - ROT 50MM TURNTABLES, INSPECT FOR RE-USE			311994	Samantha Shaw	10/09/2024	156.25 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117
121333	PM986		PRIME MOVER - PENDING DISPOS Defect	6x4		REMOTE FOR DOORS NOT WORKING			311994	Samantha Shaw	10/09/2024	37.5 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117
121335	PM986		PRIME MOVER - PENDING DISPOS Defect	6x4		COMPLETED HOM NOT WORKING OR REVERSE BEEP			311994	Samantha Shaw	10/09/2024	37.5 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117
122309	PM986		PRIME MOVER - PENDING DISPOS PM	6x4		COMPLETED - B SERVICE KENWORTH MEDIUM CENTURION (NF)			311994	Samantha Shaw	10/09/2024	150 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117
122486	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED WINDSCREEN WASHERS NOT WORKING			311994	Samantha Shaw	10/09/2024	18.75 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117
122488	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED TIGHTEN LOOP BAR			311994	Samantha Shaw	10/09/2024	18.75 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117
122489	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		COMPLETED REPAIR SHOCK MOUNTS			311994	Samantha Shaw	10/09/2024	18.75 WKBR	PERTH ADMINISTRATIVE	0	0	0	CC117
122491	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		REPLACE HORN			0	Keri Edmondson	10/09/2024	18.75 WKBR	PERTH ADMINISTRATIVE	105.33	0	0	CC117
122491	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		TIGHTEN PITMAN ARM			311994	Samantha Shaw	10/09/2024	18.75 WKBR	PERTH ADMINISTRATIVE	50.96	0	0	CC117
122492	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		REPLACE WHEEL NUT INDICATORS			0	Keri Edmondson	10/09/2024	225 WKBR	PERTH ADMINISTRATIVE	679.68	0	0	CC117
122493	PM986		PRIME MOVER - PENDING DISPOS Correct	6x4		TIGHTEN CHATE PLATE BOLTS			0	Keri Edmondson	10/09/2024	18.75 WKBR</td					



KENWORTH TRUCKS
A DIVISION OF **PACCAR** AUSTRALIA PTY. LTD.

A.B.N. 43 004 669 667

64 Canterbury Road, Bayswater
P.O. Box 60, Bayswater, Victoria 3153, Australia
Telephone: (03) 9721 1500
Fax: (03) 9720 4144



30 January 2024

TO WHOM IT MAY CONCERN

Reference: Kenworth VIN 6F5000000HA459361

The current applicable ratings for this vehicle as manufactured by Kenworth Trucks for general on-highway operations are:

Gross Train Combination Mass up to and including 97.0 tonnes and/or
Gross Vehicle Mass up to and including 26.50 tonnes
(Lesser of Component Gross Vehicle Mass up to 27.60 tonnes, or,
ADR braking certification Gross Vehicle Mass of 26.5 tonnes)

The vehicle specifications as manufactured by Kenworth Trucks were as follows, shown with current applicable component ratings:

Model	:	K200	Date of Manufacture:	August 2017
Engine	:	Cummins X15 Euro V 525 - 550	Governed rpm:	2000
S/N	:	79982574		
Max Power	:	410 kW @ 1600 rpm		
Max Torque	:	2508 Nm @ 1200 rpm		
Transmission	:	Fuller RTLO20918B		
Ratios	:	14.40 12.29 8.51 7.26 6.05 5.16 4.38 3.74 3.20 2.73 2.28 1.94 1.62 1.38 1.17 1.00 0.86 0.73		
Tailshaft	:	Meritor RPL25		
Steer Axle	:	Meritor MFS73LA	Rating:	7300 kilograms
Front Suspension	:	Kenworth Leaf Spring 7.2t	Rating:	7200 kilograms
Steer Tyres	:	295/80R22.5	Rating:	6900 kilograms
Steer Wheels/Rims	:	8.25 x 22.5 285PCD Alloy Wheels	Rating:	6700 kilograms
		Front Axle Assembly (including Steering) Rated Capacity:		6700 kilograms
Drive Axles	:	Meritor RT46-160GP	Rating:	20900 kilograms
Drive Axle Ratio	:	4.30		
Rear Suspension	:	Kenworth Airglide 460 Tandem, Steel	Rating:	20900 kilograms
This airbag suspension system has been certified as Road-Friendly by the Federal Office of Road Safety (FORS). Certificate No. RF2012				
Drive Tyres	:	11R22.5	Rating:	21800 kilograms
Drive Wheels/Rims	:	8.25 x 22.5 285PCD Alloy Wheels	Rating:	26400 kilograms
		Rear Axle Assembly Rated Capacity:		20900 kilograms
Wheelbase	:	4280 mm	Chassis Section:	270 x 89 x 8mm High Tensile Steel (with rear suspension insert only)
Rear Overhang	:	1370 mm		

The maximum recommended operating speed is 100 km/h, for which suitable tyres must be fitted. The maximum geared road speed of this vehicle was 123 km/h, Road Speed Limited to 100 km/h.

HOLLAND FW351 X2 fifth wheel (D-Rating 190 kN) and fifth wheel mounting angles were fitted by Kenworth Trucks as original equipment, attached in accordance with Kenworth Engineering Specifications.



Please note that the above statements :

- do not affect the terms of any existing warranty in respect of this Kenworth truck
- are not a separate warranty by Kenworth Trucks
- are not separate application approval for any specific use of this Kenworth truck.

This vehicle was fitted with an Approved ADR Compliance Plate, in accordance with ADR61.

Compliance of the identified Category NC vehicle is confirmed by the Approval Number stamped in the upper left corner of the plate.

Individual ADR numbers are no longer required to be identified where an Approval Number is provided, excepting ADR64 (Roadtrains and B-Doubles). This compliance, if applicable, is shown on the Vehicle Identification Plate.

This vehicle is certified to ADR64 for Road Train and/or B-Double prime mover use (State permit requirements may be greater than ADR64 standards).

No authorisation exists for other Engineering Signatories to rate or approve this original specification Kenworth truck above the ratings stated in this letter (Vehicle Standards Bulletin No.6, Section S).

Any modification to certified components made after manufacture must be approved by an authorised Engineering Signatory and may vary the above ratings.

VSB6 (Part A, Section A, 4.4) stipulates that "requirements of the ADR's and original manufacturer's modification guidelines shall take precedence". As Kenworth Trucks offers a wide range of alternative manufacturer's original specifications, Kenworth Trucks can provide manufacturers ratings for most modifications (VSB6, Section S, Code S1).

Yours faithfully,
KENWORTH TRUCKS

Chevinda Chevy Karunanayake
Applications Engineer
Reference: Kenworth VIN 6F5000000HA459361