Asset No	Job Type	Description	Done Reading	Finished Date/Time
PM957	Correct	COMPLETED CLEAN CRANK ANGLE SENSOR		16/08/2023
PM957	Correct	REPLACE BRAKE BOOSTER DS REAR, ADJUST BRAKES, REPLACE REVERSE LIGHT INSERT - COMPLETED	327660	9/09/2023
PM957	Correct	REPLACE TRAILER PLUG - COMPLETED	327784	11/09/2023
PM957	Correct	CHECK ENGINE LIGHT ON - FOUND WIRING & PLUG TO CRANKCASE PRESSURE SENSOR FAULTY & REPAIREE		13/09/2023
PM957	Correct	COMPLETED - REPLACE ABS PLUG	0	17/09/2023
PM957	Correct	REPAIR COOLANT LEAK - SIDE STEPS - ADJUST CLUTCH - COMPLETED	329977	7/10/2023
PM957	Correct	REPAIR LIGHTS & FIT WHEEL NUT INDICATORS - COMPLETED	331708	14/10/2023
PM957	Correct	REPLACE SUZI COIL - AIR FITTINGS - DASH GLOBE - COMPLETED	432707	18/10/2023
PM957	Correct	REPLACE ELECTRICAL PLUG - RESET CIRCUIT BREAKER & CHECK LIGHT OPERATIONS - COMPLETED	0	
PM957	Capital	XROTC TURNTABLE & KING PIN CHANGEOUT PROJECT	889550	22/11/2023
PM957	Correct	REPLACE AIRCON FILTER	0	29/11/2023
PM957	Correct	COMPLETED REPLACE SPOTTER MIRROR	0	
PM957	Correct	REPAIR-CLEAR DEFECT, BROWN & HURLEY ROCKHAMPTON	994274	21/02/2024
PM957	Correct	COMPLETED CHECK-ADJUST CLUTCH		27/02/2024
PM957	Defect	NOT COMPLETED PRIOR TO AUCTION - DEFECT#04552 - ENGINE LIGHT ON		5/03/2024
PM957	Defect	NOT COMPLETED PRIOR TO AUCTION - DEFECT#04552 - TURBO TIMER NOT CUTTING OF		5/03/2024
PM957	Defect	NOT COMPLETED PRIOR TO AUCTION - DEFECT#04552 - BLOWING SMOKE		5/03/2024
PM957	PM	COMPLETED TOP UP ENGINE OIL	0	
PM957	Correct	COMPLETED - REPLACE ABS PLUG	0	
PM957	Defect	NOT COMPLETED PRIOR TO AUCTION - DEFECT#43420 - DOES DPF BURN ALL DAY		14/04/2024
PM957	Defect	NOT COMPLETED PRIOR TO AUCTION - DEFECT#43420 - 12VOLT CHARGING PLUG NOT WORKING		15/04/2024
PM957	Defect	COMPLETED - DEFECT#43420 - LEAKING OIL DRIVERS SIDE	0	17/04/2024
PM957	Correct	COMPLETED - REPAIR RH HEADLIGHT	0	17/04/2024
PM957	Defect	COMPLETED - DEFECT#43420 - AIR LEAK UNDER CAB	0	
PM957	Correct	COMPLETED - WASH ENGINE	0	17/04/2024
PM957	Correct	COMPLETED - REMOVE AND REFIT NEW STICKERS		17/05/2024
PM957	PM	COMPLETED - NHVAS ANNUAL INSPECTION POWERED EQUIPMENT (NF	0	17/05/2024
PM957	Correct	COMPLETED - CARRY OUT OFF POLICY B SERVICE	0	17/05/2024
PM957	Correct	COMPLETED - REPLACE MUD GUARDS AS REQUIRED	0	17/05/2024
PM957	Correct	CMPLETED - REPLACE ALL TORQUE ROD BUSHES	0	20/05/2024
PM957	Correct	COMPLETED - REPLACE INPUT SEAL ON FRONT DIFF	0	20/05/2024
PM957	Correct	COMPLETED - REPLACE THRU SHAFT SEAL	0	20/05/2024
PM957	Correct	COMPLETED - REPLACE SUMP GASKET	0	20/05/2024
PM957	Correct	COMPLETED - POWER STEERING PUMP	0	20/05/2024
PM957	Correct	COMPLETED - REPLACE AL STEERING UNI'S		20/05/2024
PM957	Correct	COMPLETED - REPLACE RIGHT REAR AND RIGHT FRONT SHOCKIES	0	20/05/2024
PM957	Correct	COMPLETED REPLACE TRAILER LIGHT PLUG		17/06/2024
PM957	Correct	COMPLETED REPLACE BATTERIES	348495	21/06/2024
PM957	Defect	NOT COMPLETED PRIOR TO AUCTION - DEFECT #44370 - INTERMITTENT START ISSUES		24/07/2024
PM957	Correct	COMPLETED - REPLACE DRIVER SEAT		30/07/2024
PM957	Correct	COMPLETED - REPLACE TRANSMISSION FILTER	349274	8/08/2024
PM957	Offboard	PREP FOR AUCTION	349274	26/09/2024
PM957	Cleaning	INT AND EXT DETAIL		1/10/2024
PM957	Movement	TAKE TRUCK TO KINGS DETAILERS	350065	
PM957	Capital	COMPLETED - CAMPAIGN - ROT 50MM TURNTABLES, INSPECT FOR RE-USE	350065	11/10/2024
PM957	Correct	COMPLETED - CAMPAIGN ROT 50MM TURNTABLES - REKIT TURNTABLE	350065	11/10/2024