

Repairs and Maintenance – 154WDE

26/5/2020	Remove and replace starter motor – warranty – Bundy star
1/6/2020	Found intercooler to have leak, ordered new one John Bundy Star, Removed and replaced intercooler.
1/6/2020	Replace fuel pump solenoid valve – under warranty ken Landt diesel – Kurt
17/6/2020	Remove and Replace L/H Axle air bag
28/7/2020	Replace front cab mounts, Replace steering wheel, replace cab stabiliser bar
12/8/2020	Replace all Drive brakes and drums, replace R/H front Drive axle Bearings Set 401-900 SA, Set 403-900 SA
12/9/2020	Replace 4 x Batteries
15/09/2021	New Engine Rebuild Cummins #9095529 (Kms 1,264,539)
23/9/2020	Remove and Replace R/H rear Air bag
23/10/2020	Replace 2 x Air Filters (139239Km), replace L/H Front Drive air bag, Replace L/h Front Drive Air Bag, Replace Fuel Pro Filter
13/11/2020	Repair Broken Plug for Monitor – Al Moree
20/12/2020	Tarp Winder Repaired, Radiator blown out and Intercooler pressure test, All Wheel bearings and brakes replaced, Front Pelmenton to B Trailer repaired, Front R/H slack Adjuster replaced, Oil leaks Repaired front and rear diff, Light on Mirror repaired, all air leaks repaired, Hoist grease nipple replaced, Driver side mirror replaced.
29/1/2021	Hub seal clean, Brake shoes and backing plate clean, adjust top up diff oil etc, refer to invoice 72158-00 – Bundy Star
19/2/2021	Repairs to Eco wind cab, a/s system, refer to invoice 15690 – Briskair
22/2/2021	New Air Dryer
4/6/2021	Replace 4 fuel Lines
30/6/2021	Fit New Batteries, Front Diff input seal, Coolant leak repair -Bundy star 73053-00 Done with B service
8/9/2021	Pressurizing cooling system – Cummins 9082047
8/10/2021	Repairs of Ecowind – Warranty – Briskair -154129
13/11/2021	Replace front shackle pins & bushes Lewis

MAL16 - SERVICE RECORD LOG

Vehicle Rego Number: 154 WDE

From: 30/6/21

To:

Page: 3

Date	Odometer	Type of Service A,B,C,D	Brake Re-line List Wheels	Issues/Monitoring Fault Report No.	Service/Repairs Carried Out	Service/Repairs Carried Out By
30/6	238742	B			Bundy Star	# 73053-00
18/7	249228	A				H. Attard
28/8	261218	B			Bundy Star	H73433-00
15/9	264539	B			New Engine Cummins	4 9095529
12/11	287263	B			LSD	#
4/12/21	296248	A				Mark (with)
17/12/21	303506	B			LSDR	Lewis #

MAL16 - SERVICE RECORD LOG

Vehicle Rego Number: 154 WDE From: 12/7/20 To: 8-6-21 Page: 2

Date	Odometer	Type of Service A,B,C,D	Brake Refine List Wheels	Issues/Monitoring Fault Report No.	Service/Repairs Carried Out	Service/Repairs Carried Out By
12/7/20	95746	A	-			BRETT TEMPLE
13/8/20	106500	B	-			BRETT TEMPLE
12/9/20	123058	B	-			BRETT TEMPLE
23/10/20	139239	B	-			BRETT TEMPLE
7/11/20	147037	A	-			BRETT TEMPLE
30/11/20	158497	B	-			BRETT TEMPLE
11/12/21	169585	C				JOHN STOKES (BUDY STAC)
13/12/21	179911	A				(BUDY STAC)
19/12/21	189498	B				(BUDY STAC)
8-4-21	199537	B	-			Scott Taylor
1-5-21	211857	A	-			Scott Taylor
17-5-21	220449	B	-			Scott Taylor
8-6-21	230785	A				Scott Taylor

MAL16 - SERVICE RECORD LOG

Vehicle Rego Number: 154 WDE From: 28/8/19 To: 12/6/20 Page: 1

Date	Odometer	Type of Service A,B,C,D	Brake Retire List Wheels	Issues/ Monitoring Fault Report No.	Service/Repairs Carried Out	Service/Repairs Carried Out By
28/8/19	954 973	A	—			BRETT TEMPLE
17/9/19	962 941	A	—			BRETT TEMPLE
15/10/19	969 213	A	—			BRETT TEMPLE
26/10/19	979 927	B	—			BRETT TEMPLE
21/11/19	987 503	A	—			BRETT TEMPLE
17/12/19	994 108	A	—			BRETT TEMPLE
24/12/19	999 641	B	—			BRETT TEMPLE
3/1/20	5041	A,C	—			BRETT TEMPLE
22/2/20	27 043	B	—			BRETT TEMPLE
17/3/20	35 641	A	—			BRETT TEMPLE
30/4/20	61 163	A	—			BRETT TEMPLE
9/5/20	64 857	B	—			BRETT TEMPLE
12/6/20	85 136	B	—			BRETT TEMPLE

