



Vehicle Service Records (VSR Explorer)





















































Repair history D-201850


























































Registration nr: 75NOL
Market type: FH13A64T

Chassis nr: D-201850
Country: AUS

VIN nr: YV5RG40DXFD201850
Delivery date: 2015-07-15

PC	Type	Code	Description (Original)	#
2024-07-05 - Mileage: 0 - Order nr: 8191178				
	*	M	PLEASE FILL IN	
			Contact: Brenden 0419 922 737	
			Mileage:	
			Hrs:	
			Next Service:	
			Parked:	
		LO-350	TEAM VIEWER	1
			Body builder issues, connected to nolans vehicle via, team	
		LO-170P40V	Charge for laptop connection	0.5
			Connect laptop to vehicle and conduct	
			diagnostic test.	
			viewr, carried out repair to bbm with nolans mecanic, also	
			programmed air drier as well as it had softeware fault,	
			tested all ok.	
	*	91	WORKSHOP CONSUMABLES	
2022-09-26 - Mileage: 1290294 - Order nr: 7294612				
			AARON 0417 631 673	
		LO-170	A+B +C NOLANS SERVICE	8
		VO-24122024	SERVICE KIT(FK18B)	1
		MK-9727-111943A	COOLANT TEST STRIPS SINGLE	1
		VO-23690622	AIR DRIER FILTER SERVICE KIT	1
		VO-20580233	FILTER OIL POWER STEERING	1
		VO-85122800	1L ATF OIL	4
		VO-23515346	FILTER AC OUTER FH V4	1
		VO-23515329	FILTER AC INNER FH V4	1
		VO-23381562	FILTER ADBLUE	1
		LO-210	COOLANT LEAK	2.25
		LO-360	RECTIFY LIGHTS OUT	0.5
		VO-23354972	TAIL LAMP ASM LH	1
		VO-20555313	CONNECTING PIPE	1

PC	Type	Code	Description (Original)	#
		VO-20479636	GASKET PIPE TO ENGINE	1
		VO-1547252	SEALING RING	1
		AU2-AMP23068346	BULK ENGINE OIL VDS4.5	38
		97	ENVIRONMENTAL CHARGE	
		93	GREASE	
			CARRY out Molans A, B & C service as per service sheets	
			Replace passenger side tail lamps as damaged & reverse	
			light imop, check operation ok.	
			Pressure tested & found a crack in the thermostat bypass	
			pipe, drain coolant to R&R the pipe with new gaskets,	
			refilled coolant & rechecked ok, wash down & check after	
			road test ok.	
			Service & repairs completed on the 26-9-2022	
		91	WORKSHOP CONSUMABLES	
 2022-04-12 - Mileage: 1275309 - Order nr: 7289280				
			Aaron 0417 631 673	
		LO-170	NOLANS 'A' SERVICE	1.5
		LO-384	D&R CRANKE CASE PRESURE LOW	1.25
			WARNING ON DASH	
		LO-560	D&R RS AIRBAG IS LEAKING	1.25
		VO-21634017	CRANKCASE PRESSURE SENSOR	1
		VO-23577661	AIR SPRING	2
		VO-992302	6MM PIPE RETAINER	1
			Carried out NOLANS 'A' service. Defect list as Follows:	
			- 1st drive output shaft minor leak	
			- 1st drive diff carrier weeping	
			- P/S front cab airbag leaking (RECTIFIED)	
			- Air compressor head has oil leak around head (minor)	
			- Oil weep at power steering pump (Minor)	
			- cab ram wet, tilts ok, topped up.	
			Crankcase pressure sensor fault relative to ambient air	
			pressure. Plugged in checked codes, found crancase	
			pressure sensor faulting, Remove and replace sensor. Check	
			on road test.	
			Front RHS cab air bag leaking, TPI to replace both if one	
			leaks, remove and replace both front cab air bags	
		VO-1701000	Connect-disconnect of diagnostic tool	0.5
		93	Grease	




























































PC	Type	Code	Description (Original)	#
	*	91	WORKSHOP CONSUMABLES	
 2022-02-17 - Mileage: 1263857 - Order nr: 7287403				
			DAVID 0448 010 841	
	*	170	NOLAS 'A' SERVICE	
		VO-24122024	SERVICE KIT(FK18B)	1
		MK-9727-111943A	COOLANT TEST STRIPS SINGLE	1
		AU2-AMP23068346	BULK ENGINE OIL VDS4.5	38
			Carry out Nolans A service as per service sheets	
			A Service does not include changing oil & filters, labour	
			charge to customer was for A service only.	
 2022-02-17 - Mileage: 1263857 - Order nr: 2882162				
			DAVID 0448 010 841	
	*	170	NOLAS 'A' SERVICE	
		VO-24122024	SERVICE KIT(FK18B)	1
		MK-9727-111943A	COOLANT TEST STRIPS SINGLE	1
		AU2-AMP23068346	BULK ENGINE OIL VDS4.5	38
			Parts credit only as not requested to be carried out.	
 2022-01-19 - Mileage: 1263857 - Order nr: 7286358				
			DAVID 0448 010 841	
		LO-170	NOLAS 'A' SERVICE	1.5
		LO-210	CARRY OUT VALVE ADJUSTMENT	3
		VO-24122024	SERVICE KIT(FK18B)	1
		MK-9727-111943A	COOLANT TEST STRIPS SINGLE	1
		AU2-AMP23068346	BULK ENGINE OIL VDS4.5	38
			Carry out valve adjustment to spec.	
			Carry out Nolans A service as per service sheets	
	*	93	OILS & GREASE	
	*	91	WORKSHOP CONSUMABLES	
 2021-11-16 - Mileage: 1241439 - Order nr: 7284481				
			AARON 0417 631 673	
		LO-170	NOLANS 'A' SERVICE	1.5
		LO-322	D&R ALTERNATOR LIGHT	1.25
		MK-9727-111943A	COOLANT TEST STRIPS SINGLE	1
		VO-21579977	CHARGE REGULATOR	1
		LO-255	TURBO MOUNTMOUNT GASKET LEAKING	3
		VO-20784537	GASKET TURBO MOUNT	1
		VO-993811	FLANGE BOLT M10X50	4
		VO-994441	FLANGE BOLT M8X50	1

PC	Type	Code	Description (Original)	#
		VO-990950	FLANGE LOCK NUT M8	1
		93	Grease	
			Carried out Nolans A service as per service sheet.	
			INTERMITTENTLY ON	
			NORMAL TRUCK OPERATION WHEN LIGHT IS ON	
			Checked wiring to alternator & batteries ok.	
			Remove & replace charge regulator & tested ok.	
			Remove intake & dump pipe, remove turbo, cleaned remaining	
			turbo mount gasket off surfaces, refit turbo with new	
			gasket & mount bolts, refit intake & dump, washed area &	
			checked over after road test.	
		91	WORKSHOP CONSUMABLES	
2021-08-10 - Mileage: 1214666 - Order nr: 7281205				
			DAVID 0448 010 841	
		LO-253	D&R FAULT ON DASH	2.5
		VO-22889891	ACTUATOR SERVICE KIT	1
		VO-1701000	Connect-disconnect of diagnostic tool	0.4
			Checked faults had epg inefficient, Carroed out related	
			tests, found actuator for epw weak, replace epw & actuator	
			& cleared faults & road test.	
		91	WORKSHOP CONSUMABLES	
2021-07-15 - Mileage: 0 - Order nr: 7280449				
			Aaron 0417 631 673 / DAVID 0448 010 841	
		385	D&R FAULT ON DASH	
			Truck did not turn up	
2021-03-12 - Mileage: 1190886 - Order nr: 7276257				
			DAVID 0448 010 841	
		LO-170	NOLANS A & B SERVICE	4
		LO-213	HOTSET - TAPPET ADJUSTMENT	3
		VO-85136742	FILTER KIT (FK18B)	1
		MK-9727-111943A	COOLANT TEST STRIPS SINGLE	1
		VO-20538793	GASKET ROCKER COVER	1
		VO-20571854	MAGNETIC PLUG & WASHER	1
		AU2-CAL85121795	BULK VDS4 ENGINE OIL	38
		97	ENVIRONMENTAL CHARGE	
		93	Grease	
			Carried out Nolans A/B service as per service sheet.	
			Carried out valve adjustments as per Volvo specifications.	

PC	Type	Code	Description (Original)	#
	*	91	WORKSHOP CONSUMABLES	
2021-01-04 - Mileage: 1181024 - Order nr: 7273939				
			SYDNEY - DAVID 9748 1711 / 0448 010 841	
		LO-361	D&R FIRE IN CAB, BASIC CLEAN UP	7.5
		VO-972081	ST 4.8X19	6
		AU2-9771-TX4500S	5 Watt 80 Channel	1
		VO-21371086	MICROPHONE	1
		OTH-INT003	400G GLASS CLEANER SPRAY	1
			Remove upper roof compartments to remove CB, found the	
			wiring had been arcing & caught fire damaged the CB & part	
			of the roof panel, clean out cab of the fire extinguisher	
			powder fitted new CB & microphone, repaired CB panel	
			section as unable to buy separately, clean all glass &	
			tested CB operation ok.	
	*	91	WORKSHOP CONSUMABLES	
2020-11-27 - Mileage: 1175997 - Order nr: 7272854				
			PAUL 0407-746 579	
		LO-170	NOLANS 'A' SERVICE	1.5
			AS PER THEIR SHEET	
		LO-874	RECTIFY A/C NOT BLOWING ANY AIR	1.25
		LO-250	RECTIFY EXHAUST FLEX LEAKING AT CLAMP	0.25
	*	560	RECTIFY FRONT CAB AIRBAG LEAKING	
		VO-84223451	FAN MOTOR	1
		VO-1629499	CLAMP	1
		VO-990951	FLANGE LOCK NUT M10	1
		VO-994195	FLANGE BOLT M10X50	1
	*	93	GREASE	
			Carried out A service as per service sheet.	
	*	100	REPORT FROM SERVICE	
			1. DAMAGE TO BULLBAR AND WELDS CRACKING	
			2. RHS FUEL TANK CAP SPLIT	
			3. MONITOR MINOR ADBLUE LEAK AT FILLER PIPE	
			4. 3RD AXLE MUDGUARDS DAMAGED	
			5. WASHER BOTTLE CRACKED AND LEAKS WATER	
			6. EXTERNAL SUNVISOR DAMAGED	
			7. MONITOR MINOR OIL LEAK AT AIR COMPRESSOR	
			Parts on order from QLD. Will contact customer when part	
			arrives.	

PC	Type	Code	Description (Original)	#
	🔧		Replaced a/c blower motor as internal fault in motor.	
	🔧		Replaced leaking exhaust flex clamp near muffler.	
🔧	*	91	WORKSHOP CONSUMABLES	
🔍 2020-10-08 - Mileage: 1170731 - Order nr: 7271123				
	🔧		DAVE - 0448 010 841	
🔧	*	361	D & R ENGINE LIGHT ON DASH	
🔧	🔧	LO-362	D & R DERATE TRUCK ONLY DOES 40KMS	3.25
🔧	🔧	VO-22406383	FILTER ADBLUE PICK UP MESH	1
🔧	🔧	VO-22851845	ADBLUE PUMP UNIT	1
🔧	🔧	VO-990037	BULB H7 24V 70W	1
🔧	🔧	LO-353	RECTIFY DRIVER'S SIDE LOW BEAM INOP	0.25
	🔧		Check & replace driver's side blown low beam globe, check	
	🔧		operation ok.	
	🔧		Refer Job 362 for Repairs	
🔧	🔧	VO-1701000	Connect-disconnect of diagnostic tool	0.4
	🔧		Check faults, found NOx & aftertreatment pressure below	
	🔧		spec faults, carry out adblue pressure tests failed,	
	🔧		remove adblue pick up & replace stariner as partially	
	🔧		blocked, R&R Adblue pump, retested & passed ok, cleared	
	🔧		faults & road tested ok.	
🔧	*	91	WORKSHOP CONSUMABLES	
🔍 2020-10-07 - Mileage: 1170721 - Order nr: 7271701				
	🔧		DAVE - 0448 010 841	
🔧	🔧	LO-284	BREAKDOWN 32 OTTELIA PLACE KEMP CREEK	3
	🔧		ENGINE LIGHT ON DASH 7-10-2020	
	🔧		While attending breakdown at the above site for Rego	
🔧	🔧	VO-85139619	EXHAUST BACK PRESSURE SENSOR	1
🔧	🔧	VO-21582423	WIRING KIT CANNON 4 PIN	1
🔧	🔧	VO-1608002	HEAT-SHRINKABLE TUBE	0.1
	🔧		126WZF, check for engine light, found exhaust back	
	🔧		pressure faults, check wiring & plug found corroded,	
	🔧		return to workshop for parts, return to site, R&R sensor &	
	🔧		plug, cleared faults ok.	
🔧	*	92	UTE MILEAGE 26 km's Ö Å1.50/km.	
🔧	*	91	WORKSHOP CONSUMABLES	
🔍 2020-06-24 - Mileage: 1163392 - Order nr: 8133292				
🔧	*	870	A/C not working	
	🔧		suspect evap core.	

PC	Type	Code	Description (Original)	#
		VO-82348991	EVAPORATOR	1
		VO-85013654	COMPRESSOR, EXCH - AIR CON	1
		VO-20443759	O-RING	1
		VO-20708247	O-RING 3/4 A/C	1
		VO-82693739	ACCUMULATOR	1
		VO-84437717	HOSE	1
		VO-21843360	SEALING ORING - AIR CON	2
		VO-82356752	O-RING	1
		VO-82356754	O-RING	3
		VO-82356756	O-RING	2
		VO-82356760	O-RING	1
		VO-82356762	O-RING - A/CON	2
		VO-82385480	O-RING	2
		VO-82386482	O-RING	1
		VO-23515346	VENTILATION FILTER	1
		VO-23515329	VENTILATION FILTER	1
			Drove truck in and visually inspected. Found traces of dy	
			in drain hose and on evaporator core. Found metal in	
			orifice pipe. Ordered parts. Removed a/c filter	
			accumulator, orifice pipe and cooling assembly from dash.	
			Removed the cooling unit. Removed and replaced the	
			evaporator core. Cleaned traces of dye. Refitted unit.	
			Reassembled dash. Fitted new orifice and reassembled with	
			the parts listed. Tested for operation.Ok.	
2020-06-24 - Mileage: 1163392 - Order nr: 4086972				
		870	A/C not working	
			suspect evap core.	
		VO-82348991	EVAPORATOR	1
		VO-85013654	COMPRESSOR, EXCH - AIR CON	1
		VO-20443759	O-RING	1
		VO-20708247	O-RING 3/4 A/C	1
		VO-82693739	ACCUMULATOR	1
		VO-84437717	HOSE	1
		VO-21843360	SEALING ORING - AIR CON	2
		VO-82356752	O-RING	1
		VO-82356754	O-RING	3
		VO-82356756	O-RING	2
		VO-82356760	O-RING	1

PC	Type	Code	Description (Original)	#
		VO-82356762	O-RING - A/CON	2
		VO-82385480	O-RING	2
		VO-82386482	O-RING	1
		VO-23515346	VENTILATION FILTER	1
		VO-23515329	VENTILATION FILTER	1
			Drove truck in and visually inspected. Found traces of dy	
			in drain hose and on evaporator core. Found metal in	
			orifice pipe. Ordered parts. Removed a/c filter	
			accumulator, orifice pipe and cooling assembly from dash.	
			Removed the cooling unit. Removed and replaced the	
			evaporator core. Cleaned traces of dye. Refitted unit.	
			Reassembled dash. Fitted new orifice and reassembled with	
			the parts listed. Tested for operation.Ok.	
2020-06-12 - Mileage: 1163392 - Order nr: 8132816				
		LO-870	A/C not working	5.5
			suspect evap core.	
		VO-82348991	EVAPORATOR	1
		VO-85013654	COMPRESSOR, EXCH - AIR CON	1
		VO-20443759	O-RING	1
		VO-20708247	O-RING 3/4 A/C	1
		VO-82693739	ACCUMULATOR	1
		VO-84437717	HOSE	1
		VO-21843360	SEALING ORING - AIR CON	2
		VO-82356752	O-RING	1
		VO-82356754	O-RING	3
		VO-82356756	O-RING	2
		VO-82356760	O-RING	1
		VO-82356762	O-RING - A/CON	2
		VO-82385480	O-RING	2
		VO-82386482	O-RING	1
		VO-23515346	VENTILATION FILTER	1
		VO-23515329	VENTILATION FILTER	1
		87	Charge for A/C Gas 0.65 kg of R134A	
			VCV RTA Lic - AU23546	
		97	ENVIRONMENTAL CHARGE	
			Drove truck in and visually inspected. Found traces of dy	
			in drain hose and on evaporator core. Found metal in	
			orifice pipe. Ordered parts. Removed a/c filter	

PC	Type	Code	Description (Original)	#
	🔧		accumulator, orifice pipe and cooling assembly from dash.	
	🔧		Removed the cooling unit. Removed and replaced the	
	🔧		evaporator core. Cleaned traces of dye. Refitted unit.	
	🔧		Reassembled dash. Fitted new orifice and reassembled with	
	🔧		the parts listed. Tested for operation.Ok.	
🔧	*	91	WORKSHOP CONSUMABLES	
🔍 2020-01-24 - Mileage: 403531 - Order nr: 8127012				
🔧	*	20	Vehicle Towed In With High Crank	
	🔧		Pressure.	
🔧	*	20	Kit	
	🔧		P: high crankcase pressure warning on dash, oil around	
	🔧		the starter	
	🔧		(coming from exhaust flex)	
	🔧		C: suspecting dropped the valve cracked the liner	
	🔧		*got a call, and called driver to confirm some details	
	🔧		*driver told that he got loss of power and message high	
	🔧		crankcase	
	🔧		pressure. And once he stopped. He found some oil? coming	
	🔧		from exhaust	
	🔧		flex and dripping on a starter. Oil level was ok on a	
	🔧		dipstick.	
	🔧		*Drove to breakdown in High Camp	
	🔧		*Located truck and assessed the area and set up safety zone	
	🔧		*Inspected the truck for the issue ? tilted cab and	
	🔧		checked for turbo	
	🔧		? was fine.	
	🔧		*Tried to start and found won't turn over. Checked the	
	🔧		level of	
	🔧		coolant ? was nothing in a tank. Checked the level of oil	
	🔧		? was too	
	🔧		much. Suspected that one of the cylinders has a hydraulic	
	🔧		lock due to	
	🔧		valve chipped and cracked the liner.	
	🔧		*Reported back to dealership and wait for an answer. They	
	🔧		organised	
	🔧		the tow truck	
	🔧		*Spare truck was already dropped off for a driver, so	
	🔧		build up air in	

































































PC	Type	Code	Description (Original)	#
	📄		a faulty truck and helped to pull out the faulty one from	
	📄		under the	
	📄		trailers and connect new truck.	
	📄		*left the keys under the floor mat as instructed. Packed	
	📄		up , drove	
	📄		back home.	
	📄		16/01/2020	
	📄		C: Oil Leak and High Crankcase Pressure	
	📄		C: Valve drop and Cracked Liner	
	📄		C: Log in to tech tool - read DTC, printed - carried out	
	📄		compression	
	📄		test, test fail	
	📄		Ä check dip stick, found oil sign was over the marking on	
	📄		the dip	
	📄		stick	
	📄		Ä sign of oil leak around the turbo and exhaust flex	
	📄		Ä sign of radiator leak	
	📄		Ä drain coolant, engine oil, fuel line on cylinder head	
	📄		Ä remove air cleaner housing, booster pipe, upper	
	📄		radiator pipe/	
	📄		thermostat housing, thermostat bypass, fuel pipe, all	
	📄		connector and	
	📄		sensor of the head, rocker cover, injector loom, ebg	
	📄		valve, rocker	
	📄		shaft, cam gear, cylinder head	
	📄		Ä on cylinder 3, the valve dropped	
	📄		Ä remove sump, oil pressure pipe, oil pickup pipe,	
	📄		stiffing plate,	
	📄		piston jet, piston, liner, oil pump	
	📄		Ä on liner 3, crack on 4 of the liners	
	📄		Ä clean the surface of the engine block, inside of the	
	📄		liner, crank	
	📄		shaft	
	📄		Ä remove and replace the main bearing, torque to spec,	
	📄		photo	
	📄		Ä install new liner O-ring and liner	
	📄		Ä disassemble the old piston, reuse the conrod and refit	
	📄		into the	

PC	Type	Code	Description (Original)	#
	🔧		new piston	
	🔧		Ä install new piston, new big end bearing, new bolts for	
	🔧		conrod,	
	🔧		torque to spec	
	🔧		Ä refit piston jest with new bolts	
	🔧		Ä disassemble the oil pump and cleaned, assemble the oil	
	🔧		pump, refit	
	🔧		the oil pump and torque to spec	
	🔧		Ä refit the stiffing plate, torque to spec with new bolts	
	🔧		Ä refit pressure pipe and oil pick up	
	🔧		Ä wash the oil sump, refit the sump with new gasket	
	🔧		Ä remove and replace oil filter	
	🔧		Ä remove camshaft, install onto the new head with new	
	🔧		bearing, torque	
	🔧		to spec	
	🔧		Ä remove injector, injector No3 is replace, clean the	
	🔧		injector,	
	🔧		remove and replace O-ring and washer, install injector on	
	🔧		to new	
	🔧		head, torque to spec	
	🔧		Ä remove and refit inlet manifold to new head	
	🔧		Ä remove turbo, exhaust manifold	
	🔧		Ä disassemble ex manifold, remove and replace sealing	
	🔧		ring and	
	🔧		assemble manifold	
	🔧		Ä install ex manifold	
	🔧		Ä install new turbo	
	🔧		Ä install head to block, torque to spec	
	🔧		Ä set timing to TDC and 0	
	🔧		Ä refit idler gear, cam gear	
	🔧		Ä check and adjust backlash, all in spec	
	🔧		Ä disassemble rocker arm, clean all of the rocker,	
	🔧		assemble rocker	
	🔧		shaft, refit the head, torque to spec	
	🔧		Ä check valve lift, in spec	
	🔧		Ä top end reset	
	🔧		Ä upper timing cover	
	🔧		Ä remove and replace O-ring for injector loom, refit	

PC	Type	Code	Description (Original)	#
	🔧		injector loom	
	🔧		Ä refit veb valve	
	🔧		Ä refit rocker cover	
	🔧		Ä remove and replace inner and outer air filter, install	
	🔧		air cleaner	
	🔧		housing	
	🔧		Ä refit feed pipe and return pip to turbo	
	🔧		Ä remove and replace radiator	
	🔧		Ä refit thermostat, housing, bypass	
	🔧		Ä header tank	
	🔧		Ä fill coolant, engine oil	
	🔧		Ä injector trim code	
	🔧		Ä wash truck	
	🔧		Ä road test	
	🔧		Ä recheck truck for and sign of oil and coolant leak, no	
	🔧		sign of	
	🔧		leak.	
🔍 2019-10-14 - Mileage: 1009424 - Order nr: 8122822				
📌	*	265	intercooler leaking	
📌	🔧	VO-85013014	CHARGE AIR COOLER - FH(4)	1
	🔧		Nolans special coverage item	
🔍 2019-07-02 - Mileage: 917323 - Order nr: 8118907				
📌	*	818	CAB SUSPENSION	
📌	🔧	MK-9739-16488479	CAB AIR BAG INSULATION	2
	🔧		CC 200442299	
🔍 📌 2019-05-01 - Mileage: 902210 - Order nr: 8116343				
📌	🔧	VO-4132000	Clutch cylinder, replace. Gearbox remove	0.2
📌	🔧	VO-85013166	CYLINDER	1
	🔧		removed	
📌	🔧	VO-4317000	Gearbox, remove	1
📌	🔧	VO-4317200	Gearbox, install	1.5
🔍 2019-05-01 - Mileage: 902210 - Order nr: 4086281				
📌	🔧	LO-410	CLUTCH SLIPPING - CHECK AND REPORT.	2.7
📌	🔧	VO-85013166	CYLINDER	1
	🔧		Set up hoist on vehicle. Removed chassis walk plate.	
	🔧		Raised vehicle and drained cooling system. Removed air	
	🔧		tank and cross member. Disconnected electrical plugs	
	🔧		coolant lines and air lines from gear box. Removed	

PC	Type	Code	Description (Original)	#
	🔧		driveshaft from gear box. Set gear box up on cradle and	
	🔧		removed from engine. Removed the clutch. Replaced the PWM	
	🔧		valve o ring and plate. Check clutch and refitted it.	
	🔧		Reassembled with the parts listed. Reprogrammed TECU.	
	🔧		Tested for operation.Ok.	
🔧	*	91	WORKSHOP CONSUMABLES	
📅 2019-04-12 - Mileage: 902210 - Order nr: 8115658				
🔧	*	M	PLEASE FILL IN	
	🔧		Contact:Daryl 07 5466 2851	
🔧	🔧	LO-410	CLUTCH SLIPPING - CHECK AND REPORT.	12
🔧	🔧	VO-85013166	CYLINDER	1
🔧	🔧	VO-990073	CABLE TIE	2
🔧	🔧	VO-22485772	SEALING KIT	1
🔧	🔧	VO-20739643	KIT	1
🔧	🔧	VO-995906	HEXAGON SCREW	4
🔧	🔧	VO-25339078	HEX NUT - M14 FINE (11MM)	4
🔧	🔧	VO-991092	NIPPLE BRASS - 12X1.5 x 16mm	1
🔧	🔧	LO-560	AIR DRYER CONSTANTLY PURGING	4.7
🔧	🔧	AU2-FOR67000048	BLACK MAGIC S411 400ML	1
🔧	🔧	AU2-9718-240002743	BBC4 BRAKE CLEANER	1
🔧	🔧	VO-991184	ELBOW NIPPLE 90 REG-REG	1
🔧	🔧	VO-20733172	SILENCER	1
	🔧		Mileage:902219	
	🔧		Hrs:11684	
	🔧		Next Service:	
	🔧		check and report.	
🔧	🔧	VO-85021442	AIR DRIER, MODULATOR	1
🔧	*	97	ENVIRONMENTAL CHARGE	
	🔧		Set up hoist on vehicle. Removed chassis walk plate.	
	🔧		Raised vehicle and drained cooling system. Removed air	
	🔧		tank and cross member. Disconnected electrical plugs	
	🔧		coolant lines and air lines from gear box. Removed	
	🔧		driveshaft from gear box. Set gear box up on cradle and	
	🔧		removed from engine. Removed the clutch. Replaced the PWM	
	🔧		valve o ring and plate. Check clutch and refitted it.	
	🔧		Reassembled with the parts listed. Reprogrammed TECU.	
	🔧		Tested for operation.Ok.	
	🔧		APM leaking out exhaust. Replaced APM. Had trouble with	

PC	Type	Code	Description (Original)	#
	🔧		seized air fittings. Replaced the broken fittings.	
	🔧		Reprogrammed APM. Checked for operation.Ok.	
🔧	*	91	WORKSHOP CONSUMABLES	
🔍 2019-03-19 - Mileage: 1234 - Order nr: 8114452				
🔧	🔧	LO-820	PREP AND PAINT HEADLIGHT PANELS X2	5
	🔧		REINFORCE INNER WITH ALLOY STRIPS/ SAND SIKA FLEX TO SUIT.	
🔧	*	810	CUSOTMER INFORMATION	
	🔧		REFER BRUCE VIGURS	
	🔧		ORDER NO;4028611	
🔧	*	MTPAINT	PANELSHOP PAINT	
🔧	*	91	PANELSHOP CONSUMABLES	
🔧	*	810	CUSTOMER INFORMATION	
	🔧		REFER BRUCE VIGURS	
	🔧		ORDER NO;4028611	
🔍 2019-03-19 - Mileage: 1234 - Order nr: 8114431				
🔧	🔧	LO-820	PREP AND PAINT HEADLIGHT PANEL	1.5
	🔧		INSIDE AND OUT	
🔧	*	810	CUSOTMER INFORMATION	
	🔧		REFER BRUCE VIGURS	
	🔧		ORDER NO;4028611	
🔍 2019-03-19 - Mileage: 1234 - Order nr: 4086195				
🔧	🔧	LO-820	PREP AND PAINT HEADLIGHT PANEL	1.5
	🔧		INSIDE AND OUT	
🔧	*	810	CUSOTMER INFORMATION	
	🔧		REFER BRUCE VIGURS	
	🔧		ORDER NO;4028611	
🔍 🌐 2019-03-08 - Mileage: 876893 - Order nr: 8114068				
🌐	*	352	RH headlamp Panel	
🌐	*	352	LH Headlamp panel	
🌐	🔧	VO-21874457	PANEL H/LAMP RH	1
🌐	🔧	VO-82884084	AIR DUCT	1
🌐	🔧	VO-21874450	PANEL H/LAMP LH	1
🌐	🔧	VO-82884080	AIR DUCT	1
🌐	*	30	Paint RH Headlamp Panel	
🌐	*	30	Paint LH Headlamp Panel	
🔍 2019-03-02 - Mileage: 873634 - Order nr: 8422925				
🔧	🔧	LO-310	No start	3
	🔧		Loaded tools and parts and travelled to vehicle at	

PC	Type	Code	Description (Original)	#
		92	UTE MILEAGE 74 km's Ö Å1.48/km.	
			Chinderah BP, and inspected for a no start. Found low	
			water and excess corrosion on battery terminals. Checked	
			starter and tightened terminal.	
		91	WORKSHOP CONSUMABLES	
 2018-12-19 - Mileage: 827576 - Order nr: 7250398				
		VO-4132000	Clutch cylinder, replace. Gearbox remove	0.2
		VO-85013166	CYLINDER	1
		VO-984050	HEXAGON NUT	4
		VO-995906	HEXAGON SCREW	4
		VO-20992763	AIR HOSE	1
		VO-20860677	SEALING RING	1
			removed	
		VO-4317000	Gearbox, remove	0.9
		VO-4317200	Gearbox, install	1.5
		VO-4007000	Clutch, gearbox, pulling position, calib	0.2
			calibration	
		VO-4001000	Clutch cylinder, test	0.2
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
			s/n: 66648200262	
 2018-11-21 - Mileage: 0 - Order nr: 8109630				
		258	NoX sensor, supply	
		VO-22827993	SENSOR NOX - FE(3)/ FM/FH(4)	1
 2018-10-12 - Mileage: 718286 - Order nr: 8107988				
		214	Valve adjustment fault	
		VO-1677396	NUT	12
		VO-21344803	HEX. SOCKET SCREW	12
		VO-946911	NUT	12
 2018-10-12 - Mileage: 718286 - Order nr: 4085901				
		214	Valve adjustment fault	
		VO-1677396	NUT	12
		VO-21344803	HEX. SOCKET SCREW	12
		VO-946911	NUT	12
 2018-08-31 - Mileage: 760142 - Order nr: 8106227				
		VO-8842000	Airbag module, replace	0.3
		M	PLEASE FILL IN	
			Contact:Workshop/Daryl -0754 662 832	


PC	Type	Code	Description (Original)	#
		LO-260	Fan faults	2.35
		VO-4317000	Gearbox, remove	0.35
		VO-990073	CABLE TIE	2
		VO-20483426	SEALING RING- INPUT SEAL	1
		VO-22485772	SEALING KIT	1
		VO-85013166	CYLINDER	0.6
		VO-21666546	DISC - AXLE BRAKE	1
		VO-3192614	PISTON SEAL	2
		VO-20497205	GASKET	1
		VO-85003294	FAN	1
		VO-84433698	AIRBAG MODULE	1
		VO-85013766	CLUTCH KIT, EXCH	0.2
		VO-1652986	BALL BEARING	1
		VO-22327063	SOLENOID PWM VALVE - I-SHIFT	1
		MK-9718-BBC4	Brake Cleaner 400G	1
		VO-20860677	SEALING RING	1
		VO-20786947	VALVE, FUEL	1
		VO-995906	HEXAGON SCREW	4
		VO-25339078	HEX NUT M14 FINE (11MM)	4
		VO-3979639	GASKET	2
		MK-NARV56306	CABLE TIE 1=25PK	1
		VO-21488833	STEERING PUMP	1
		VO-85103703	O-RING	1
		VO-977030	O-RING	2
		VO-21349444	SOCKET	1
		VO-85122800	ATF DEX3 1LTR	2
		VO-20840154	HOSE CLAMP 60-80mm	1
		VO-22885952	CASTLE NUT P/S PUMP	1
		VO-982724	DOWDY WASHER O.D. 24mm	2
		LO-600	Rectify P/Steer leaks	2.5
		VO-20852765	DOWDY WASHER O.D. 24mm	4
		VO-22835610	SERVO PIPE	1
			Mileage:	
			Hrs:	
		VO-4317000	Gearbox, remove	0.54
		VO-4132000	Clutch cylinder, replace. Gearbox remove	0.18
		VO-4007000	Clutch, gearbox, pulling position, calib	0.12
		VO-4317200	Gearbox, install	0.9

PC	Type	Code	Description (Original)	#
		VO-85013166	CYLINDER	0.4
		VO-4132000	Clutch cylinder, replace. Gearbox remove	0.08
		VO-4007000	Clutch, gearbox, pulling position, calib	0.08
		VO-4317200	Gearbox, install	0.6
		VO-4313100	Sealing ring input shaft, replace. Gearb	0.4
		VO-4313200	Brake, intermediate shaft, overhaul. Rem	0.4
			Removed	
		VO-2162500	Flywheel, resurface. Flywheel, removed	1
		VO-1790600	Diagnostic with Tech Tool/GD. Connect-di	0.5
			Connect-disconnect of diagnostic tool included	
		LO-431	PWM valve, oil contaminated	1
	*	411	Clutch, replace 20% Parts	
		VO-85013766	CLUTCH KIT, EXCH	0.8
			Removed and replaced the steering pump.	
	*	97	ENVIRONMENTAL CHARGE	
	*	91	WORKSHOP CONSUMABLES	
2018-06-22 - Mileage: 718286 - Order nr: 8103464				
	*	M	PLEASE FILL IN	
			Contact:Workshop/Daryl -0754 662 832	
		LO-214	valve adjustment fault	3.5
			Mileage:	
			Hrs:	
			Next Service:	
		VO-1677396	NUT	12
		VO-21344803	HEX. SOCKET SCREW	12
		VO-20716774	TERMINAL	5
		VO-60110514	HOUSING	1
		VO-20716780	LOCKING DEVICE	1
		VO-946911	NUT	12
		LO-2000	Replace faulty OBD plug	2.52
			cant get computer to read active fault on dash	
	*	97	ENVIRONMENTAL CHARGE	
			Connected laptop and do all downloads. Access piston	
			cooling fault. Found bad connector at pin/plug. Repair and	
			reconnect. Clear fault codes.	
	*	91	WORKSHOP CONSUMABLES	
2017-12-12 - Mileage: 0 - Order nr: 8095649				
			Repair without detail info	

PC	Type	Code	Description (Original)	#
2017-11-03 - Mileage: 566265 - Order nr: 8093929				
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-3712000	Cable harness, engine control unit, repl	2.1
			replace	
2017-11-03 - Mileage: 564968 - Order nr: 8093930				
	*	20	ROAD SIDE ASSISTANCE VOLVO	
			ROAD SIDE ASSISTANCE VOLVO 700.00	
			AFTER HOURS CALLOUT	
			TRAVELLED TO WORKSHOP, PICKED UP PARTS AND TRAVELLED TO	
			VEHICLE AT SUTTON FORREST. DIAGNOSED BLOWN TURBOCHARGER AND	
			ORGANIZED TOW. RETURNED HOME	
2017-11-02 - Mileage: 566265 - Order nr: 4085253				
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-3712000	Cable harness, engine control unit, repl	2.1
			replace	
	*	91	WORKSHOP CONSUMABLES	
2017-11-02 - Mileage: 564968 - Order nr: 4085254				
	*	20	ROAD SIDE ASSISTANCE VOLVO	
			ROAD SIDE ASSISTANCE VOLVO 700.00	
			AFTER HOURS CALLOUT	
			TRAVELLED TO WORKSHOP, PICKED UP PARTS AND TRAVELLED TO	
			VEHICLE AT SUTTON FORREST. DIAGNOSED BLOWN TURBOCHARGER AND	
			ORGANIZED TOW. RETURNED HOME	
2017-10-31 - Mileage: 564968 - Order nr: 8093743				
	*	20	ROAD SIDE ASSISTANCE VOLVO	
			ROAD SIDE ASSISTANCE VOLVO 700.00	
			AFTER HOURS CALLOUT	
			TRAVELLED TO WORKSHOP, PICKED UP PARTS AND TRAVELLED TO	
			VEHICLE AT SUTTON FORREST. DIAGNOSED BLOWN TURBOCHARGER AND	
			ORGANIZED TOW. RETURNED HOME	
2017-10-20 - Mileage: 566265 - Order nr: 8093306				
	*	3712000	Cable harness, engine control unit, repl	
		VO-22343361	CABLE HARNESS - FM/FH(4)	1
		AU2-PERM84101	PX POXY 5 MIN GENP	1
		MK-9718-BBC4	Brake Cleaner 400G	1

PC	Type	Code	Description (Original)	#
		VO-983472	CABLE TIE, Injector Harness	8
			Rectify misfire in engine Ä4 injector fault on dash.	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-3712000	Cable harness, engine control unit, repl	2.1
			replace	
			Parts only	
		91	WORKSHOP CONSUMABLES	
2017-10-13 - Mileage: 564968 - Order nr: 3031647				
			DRIVER: JOHN - 0407 742 534	
			OFFICE - 0417 631 673	
		LO-1940000	ROAD SIDE ASSISTANCE VOLVO	5
		VO-2551800	Engine turbocharger, replace. Chassis mo	1.6
		20	SUBLET: TOW	
		VO-21383182	SILENCER	1
		VO-21312238	CHARGE AIR HOSE	1
		AU2-CAL85121773	ULTIMATE 15w40 Bulk VDS-4	2
		VO-85020372	TURBOCHARGER, EXCH	1
		VO-20784537	GASKET	1
		VO-1543499	FLANGE NUT	4
		VO-22206133	GASKET	1
		VO-420643	GASKET	1
		VO-21940615	SEALING RING	1
		VO-21345127	STUD	4
		OTH-S100	BRAKE CLEANER	2
		OTH-MX4-300	LANOX 300G AEROSOL	1
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
			mounted	
		VO-2586200	SCR catalytic muffler, replace	1.4
		VO-2652000	Charge air pipe, replace	0.3
		VO-2653100	Charge air cooler, leakage test	0.6
		LO-255	CLEAN OUT EXHAUST AND INTAKE PIPES	1
		VO-2100600	Cylinder Compression, test	0.2
			Elchaars invÄ38948 25.10.17 TR	
		92	TRAVEL 211 km Ö Å1:40 p/km	
			AFTER HOURS CALLOUT	
			TRAVELLED TO WORKSHOP, PICKED UP PARTS AND TRAVELLED TO	

PC	Type	Code	Description (Original)	#
	🔧		VEHICLE AT SUTTON FORREST. DIAGNOSED BLOWN TURBOCHARGER AND	
	🔧		ORGANIZED TOW. RETURNED HOME	
🔧	*	91	WORKSHOP MATERIALS	
🔍 2017-08-24 - Mileage: 531757 - Order nr: 7235255				
🔧	🔧	LO-210	ENGINE MISS AND FAULT ON DASH	2.2
🔧	🔧	VO-20538793	SEALING STRIP	0.4
🔧	🔧	VO-85013271	UNIT INJECTOR, EXC	0.4
🔧	🔧	VO-21532258	SEALING RING	1
🔧	🔧	VO-983472	CABLE TIE	6
🔧	🔧	VO-21344774	FLANGE SCREW	1
🔧	🔧	VO-20526428	SEALING RING	1
🔧	🔧	VO-1677370	SEALING RING	1
	🔧		Check for faults, found A4 injector misfiring.	
	🔧		Remove rocker cover, replace injector, adjust valves and	
	🔧		refit cover.	
	🔧		Wash and road test.	
	🔧		60% majour parts and labour covered under goodwill	
	🔧		assistance	
🔧	🔧	VO-2373400	Unit injector, replace (one)	2.4
🔧	🔧	VO-20538793	SEALING STRIP	0.6
🔧	🔧	VO-85013271	UNIT INJECTOR, EXC	0.6
🔧	*	91	WORKSHOP CONSUMABLES	
🔍 2017-08-14 - Mileage: 525687 - Order nr: 8417476				
🔧	🔧	LO-237	Engine miss	4.26
	🔧		Chris - 0408 540 140	
	🔧		Driver - 0407-742-534	
	🔧		Driver called and stated that truck was vibrating and missin	
	🔧		g and that there was a fault for "injector fault/error". We	
	🔧		advised that he come to our workshop for checks. He asked w	
	🔧		e go down there. We sourced parts injectors etc and travell	
	🔧		ed down to Chinderah truck stop. Hooked up pc and could find	
	🔧		no fault with truck or injector codes in history. Checked	
	🔧		fuel pressure and for aeration and all OK. Carried out PC t	
	🔧		ests no fault found. Removed rocker cover an checked over w	
	🔧		ith nothing to note. Removed rocker cover and checked over	
	🔧		all OK. Reassembled and travelled back to workshop followi	
	🔧		ng truck on its way to Nolans workshop.	
🔧	*	91	WORKSHOP CONSUMABLES	

PC	Type	Code	Description (Original)	#
 W 2017-05-15 - Mileage: 445851 - Order nr: 8086952				
	*	8360000	Roof hatch leaking water.	
	*	80	Remove and refit roof latch	
 W 2017-05-08 - Mileage: 460668 - Order nr: R01015480				
		VO-2170600	Oil sump, remove	0.2
		VO-2170800	Oil sump, install	0.6
		VO-2300300	Fuel system, bleeding	0.2
		VO-2510400	Gaskets, exhaust manifold, replace	1.8
		VO-2586200	SCR catalytic muffler, replace	1.4
		VO-21768034	GASKET KIT	1
		VO-21253770	CYLINDER LINER KIT	1
		VO-20580558	BEARING	1
		VO-85020372	TURBOCHARGER, EXCH	1
		VO-21447682	GASKET	1
		VO-85013271	UNIT INJECTOR, EXC	1
		VO-21801388	YOKE	1
		VO-21344774	FLANGE SCREW	1
		VO-20541940	SEALING STRIP	1
		VO-949656	O-RING	1
		VO-983472	CABLE TIE	10
		VO-85013933	CYLINDER HEAD, EXC	1
		VO-1677370	SEALING RING	2
		VO-20526428	SEALING RING	1
		VO-21940615	SEALING RING	1
		VO-20852765	GASKET	4
		VO-21532258	SEALING RING	1
		VO-21503575	SEALING RING	1
		VO-21383182	SILENCER	1
		VO-22321908	EXHAUST PIPE	1
		VO-1629499	CLAMP	2
		VO-994195	FLANGE SCREW	2
		VO-990951	FLANGE LOCK NUT	2
		VO-22718180	KIT	1
		VO-22827995	SENSOR	1
		VO-21834205	FILTER	1
		VO-21115501	FILTER	1
		VO-FK18B	FILTER KIT	1
		VO-3092340	SEALANT	1

PC	Type	Code	Description (Original)	#
		VO-1161277	SILICONE SEALANT	1
		VO-2118400	Cylinder head, install and remove from overhaul stand	0.8
		VO-2135700	Piston and liner, replace (one). Cylinder head and sump removed	1.9
		VO-2141700	Valve guide wear, check. all	0.4
		VO-2117700	Cylinder head, transfer parts	0.5
		VO-2112600	Cylinder head, replace	8.4
		VO-2100600	Cylinder Compression, test	0.2
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-994447	FLANGE SCREW	6
		VO-20966752	O-RING	1
		VO-980464	STRIP CLAMP	15
		VO-990861	FLANGE SCREW	24
		VO-994445	FLANGE SCREW	1
		VO-22275838	SEALING RING	2
		VO-21092243	SEALING RING	7
		VO-994441	FLANGE SCREW	3
		VO-22807993	OIL LEVEL SENSOR	1
		VO-20938963	SEAL	1
		VO-21433769	SEALING RING	2
		VO-21447682	GASKET	1
			C: COOLANT IN EXHAUST	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
			CARRY OUT CAMPAIGN	
		VO-2800800	EMS and ACM, sw , update. Only campaign	0.4
			COOLANT IN EXHASUT	
		1940000	TOW VEHICLE	0
2017-03-30 - Mileage: 0 - Order nr: 8085263				
		M	PLEASE FILL IN	
			Customer Order Number:	
			Name:	
			Phone:CALL JIM FOR O/N 07 5466 2818 0417 631 673	
			Mileage:	
			Hrs:	
		812	Roof hatch leaking water.	
			Alpha Glass booked for 11-12 pm to do this.	
		20	Sublet -	
			Remove and refit roof latch	
2017-03-17 - Mileage: 445851 - Order nr: 4084943				

PC	Type	Code	Description (Original)	#
		M	PLEASE FILL IN	
			Customer Order Number:	
			Name:	
			Phone:CALL JIM FOR O/N 07 5466 2818 0417 631 673	
			Mileage:	
			Hrs:	
		812	Roof hatch leaking water.	
			Alpha Glass booked for 11-12 pm to do this.	
		20	Sublet -	
			Remove and refit roof latch	
W 2017-01-20 - Mileage: 385983 - Order nr: 8082680				
		VO-3640400	Light switch, replace	1
		VO-3649500	Switch steering wheel buttons, replace	1.25
			C3628 Cab, interior lights, cable harness, install. FH (4)	
			S3652 ACM, SW update. FH/FM (4)	
		LO-3540800	Interior Lights, Cable Harness, Install	0.5
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-22154333	SWITCH PANEL	1
		VO-22935545	WIRES	8
		VO-21957049	SWITCH	1
		VO-21957053	SWITCH	1
		VO-2549400	ACM, SW, update. only campaign	0.2
			HEADLIGHT SWITCH ILLUMINATION N/W	
			STEERING BUTTON STICKING.	
			Removed and replaced steering wheel buttons. Tested for	
			operation and found to be Ok.	
		97	ENVIRONMENTAL CHARGE	
			Tested the switch panel. Headlight not switching hazard	
			lights. Tested the panel and found to be faulty. Removed and	
			replaced the panel and tested for operation. Ok.	
		91	WORKSHOP CONSUMABLES	
W 2016-11-25 - Mileage: 346637 - Order nr: 8080545				
		VO-1706500	18 Months ECU download and oil sample. O	0.9
		VO-2850800	Exhaust back pressure sensor, replace	0.2
		VO-8394887	OIL TEST KIT	4
		VO-85139619	PRESSURE SENSOR - EXHAUST	1
		VO-21582423	KIT	1
		MK-NARV56820BK	TAPE NITTO BLACK	1

PC	Type	Code	Description (Original)	#
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-3710200	Electric wires and connections, check	0.4
		VO-3711700	Connector, replace (1-8 cables)	0.3
2016-11-16 - Mileage: 341241 - Order nr: 8080198				
		VO-2510400	Gaskets, exhaust manifold, replace	1.8
		VO-20855371	GASKET EXH/MANIFOLD	6
		VO-20784537	GASKET TURBO BASE	1
		VO-420641	TURBO FEED GKT	1
		VO-420643	TURBO DRAIN GKT	1
		VO-21940615	SEALING RING	1
		MK-9718-BBC4	CLEANER 400G BRAKE	1
		VO-469601	TURBO O-RING	1
		20	Sublet repairs engine	
		VO-20938963	SEAL	1
		VO-22718180	KIT - HI -TEMP TURBO MTG	1
			MANIFOLD AND BASE GASKET LEAKING	
			sublet to engine engineering to face maniflod	
		VO-2510000	Inlet and exhaust manifolds. Secondary o	0.4
2016-07-26 - Mileage: 266387 - Order nr: 8075954				
		721	FRONT LEAF SPRING	
		VO-257939	FRONT SPRING - FM/FH(4)	1
2016-07-18 - Mileage: 266298 - Order nr: 8075547				
		VO-1706400	12 Months ECU download and oil sample. O	0.9
		VO-8100300	12 Months cab inspection	0.4
		LO-3000	FAULT CODES ON DASH	2.29
		VO-2540000	Catalytic converter and emission control	0.2
		LO-8600100	C3538 CAB TILT PUMP, FILLER PLUG REPLACE	0.5
			C3538 Cab tilt pump, filler plug, replace. FH (4)	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
			S3485 Instrument cluster, SW update. FH/FM (4)	
		VO-22861085	REPAIR KIT	1
		VO-8394887	OIL TEST KIT	4
		VO-21480006	FILLER NECK	1
		VO-3815800	IC, SW update. Campaign only	0.3
		VO-1820200	Localised wash for fault tracing	0.3
2016-04-18 - Mileage: 220126 - Order nr: 8072116				
		M	PLEASE FILL IN	

PC	Type	Code	Description (Original)	#
	📄		Mileage:	
	📄		Hrs:	
	📄		Name: DARYL	
	📄		Phone: 54662951	
🟢	*	92	VAN MILEAGE km's Ö Å1.48/km.	
	📄		TRAVEL TO GATTON	
🟢	🔧	LO-383P221	SET K-FACTOR TO 100 KM/PH	1.5
	📄		Connected the laptop and adjusted k factor to 100km and road	
	📄		tested and checked for operation.Ok.	
🟢	*	91	WORKSHOP CONSUMABLES	
🔍 2016-03-29 - Mileage: 188758 - Order nr: RBWJ30				
🟡	🔧	VO-2522800	Flexible exhaust pipe, replace	0.3
🟡	📄		EXHAUST LEAK UNDER VEHICLE	
🟡	🔧	VO-22321908	EXHAUST PIPE	1
🔍 2016-02-25 - Mileage: 142053 - Order nr: 8070178				
🟡	*	8430200	Windscreen, replace	
🟡	🔧	VO-22089731	WINDSCREEN - TINTED / LPOS	1
🟡	*	80	Sublet ALPHA GLASS	
🔍 2016-02-24 - Mileage: 142053 - Order nr: 4084145				
🟢	*	812	Replace windscreen.	
🟢	🔧	VO-22089731	WINDSCREEN - TINTED / LPOS	1
🟢	*	80	Sublet ALPHA GLASS	
🔍 2016-02-05 - Mileage: 154054 - Order nr: 8069205				
🟡	*	M	PLEASE FILL IN	
	📄		Mileage:154054	
🟡	🔧	VO-8430000	Glass and sealing moulding for windscre	0.5
	📄		Hrs:1992	
	📄		Name:Daryl.	
	📄		Phone:5466 2951	
	📄		Drove to wash bay. Hose cab found leak and top RHS of	
	📄		windscreen.	
🔍 2016-01-22 - Mileage: 142053 - Order nr: 8068935				
🟢	*	812	Replace windscreen.	
🟡	🔧	VO-2610000	Radiator and connections. Secondary oper	2.6
🟢	🔧	VO-22089731	WINDSCREEN - TINTED / LPOS	1
🟢	*	80	Sublet ALPHA GLASS	
🟡	🔧	VO-2610800	Radiator, replace	2.8
🟡	🔧	VO-2611100	Radiator hose, replace (lower). Coolant	0.1

PC	Type	Code	Description (Original)	#
			drained	
		VO-2616300	Water hose, replace (hose with two clamp	0.2
			clamps). Coolant drained	
		VO-2616500	Water hose, replace (hose with two clamp	0.3
			clamps and bracket). Coolant drained	
		VO-2612100	Breather hose between radiator and expan	0.3
			expansion tank, replace	
		VO-1820200	Localised wash for fault tracing	0.3
		VO-2631800	Fan ring, replace	0.2
		VO-2630000	Fan, fan shroud and clutch. Secondary op	0.2
2016-01-01 - Mileage: 6 - Order nr: 201850				
		96000		0
2015-12-27 - Mileage: 121100 - Order nr: S189932				
		VO-3300000	Starting system, general. Secondary operation number, TIGHTEN CABLE ON BACK OF STARTER MOTOR	0.3
			TRUCK NOT STARTING	
		VO-1940100	Action service fee. national	3
			TRUCK BROKEN DOWN NOT STARTING	
2015-12-22 - Mileage: 15299 - Order nr: T52410				
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
			BREAKDOWN , TRUCK LOSING POWER	
		VO-3710000	INSPECT WIRING , BATTERY BOX , CABLES , LOCATE FAULT WITH BROKEN EARTH CABLE TO CHASSIS RAIL , REPAIR , TEST	1.7
		1940000	travel from qtc toowoomba to unit on gore highway between captains mountain & goondiwindi - return	4.2
			BREAKDOWN ON GORE HIGHWAY BETWEEN MILLMERRAN & GOONDIWINDI , LOSING POWER - action service file # 2	
2015-12-01 - Mileage: 5 - Order nr: 201850				
		96000		0
2015-11-24 - Mileage: 81965 - Order nr: 8062088				
		VO-8510000	Upholstery for door, wall/side, rear she	0.1
		VO-82259497	STORAGE TRAY	1
			shelf, luggage rack	
			DOOR POCKET	
2015-11-06 - Mileage: 81965 - Order nr: 8066055				
		LO-719L43M	Calibrate weight scale guages.	0.5
		VO-3632400	Windscreen washer pump, replace	0.4
		352	Light malfunction on dash.	
		VO-82289560	LEVEL SENSOR	1





PC	Type	Code	Description (Original)	#
2015-11-01 - Mileage: 4 - Order nr: 201850				
		96000		0
2015-10-01 - Mileage: 3 - Order nr: 201850				
		96000		0
2015-09-18 - Mileage: 49983 - Order nr: 8064305				
		VO-5910000	Electro-magnetic brake. Secondary operat	0.7
		AU2-CAL85108913	VOLVO VCS COOLANT - 5LTR	1
		VO-2600600	Cooling system, pressure test	0.5
		LO-861	To gain access to the oil cooler	2.6
			Remove and install bullbar and mounting brackets	
		VO-3525200	Headlamp complete, replace (right hand s	1.1
		VO-8231200	Grille lower, replace	0.3
		VO-8231300	Footstep grille, replace	0.2
		VO-8271000	Footstep, mounted on cab, replace	1
		VO-1820200	Localised wash for fault tracing	0.3
2015-09-04 - Mileage: 38668 - Order nr: 8063985				
	*	M	PLEASE FILL IN	
			Mileage:44612	
		LO-891	MISCELLANEOUS-EXTERNAL EQUIPMNT	1.8
		VO-994861	WASHER	4
		VO-84055742	LAMP	1
			Inspect Leaking Roof	
		VO-3560400	Spot lamp, corner panel, replace	1
		VO-8911000	Sun visor complete, replace	0.3
		VO-21596685	SUN VISOR KIT	1
			Hrs:585	
			Name:JIM 0417631673	
			Phone:	
			Next Service Due:	
		VO-8716482	ADHESIVE SIKAFLEX	2
		VO-8550700	Headlining, remove	0.8
		VO-8550500	Headlining, install	0.9
			Water testing	
			Left Hand side	
		VO-84055744	LAMP SPOT - FH(4)	1
2015-09-04 - Mileage: 38668 - Order nr: 8063804				
		LO-3000	Inspect fault lights on dash	1.6
		VO-6455200	Power steering pipe, replace	1.2

PC	Type	Code	Description (Original)	#
	*	60	MAKE UP STEERING LINE	
			LEAK AT THE POWER STEERING BOX	
		VO-1820200	Localised wash for fault tracing	0.3
			Connected laptop, read out fault codes adn carried out a	
			vehicle information test, erased all fault codes, hard copy	
			of error codes attached to RO	
2015-09-01 - Mileage: 2 - Order nr: 201850				
		96000		0
2015-08-28 - Mileage: 33300 - Order nr: 8063533				
	*	M	PLEASE FILL IN	
			Mileage:33300	
		VO-3560400	Spot lamp, corner panel, replace	1
		VO-1702600	Program control unit	0.1
			Hrs:441	
			Name:JIM 0417631673	
			Phone:	
			Next Service Due:	
		VO-84055744	LAMP SPOT - FH(4)	1
			WATER LEAKING INTO CAB R/H/S ABOVE DRIVERS HEAD INTO LOCKER	
			BOX	
			ABS WARNING LIGHT ON FOR TRUCK AND TRAILER	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-5936100	Sensor yaw rate, calibration	0.2
		VO-8490000	Outside trim parts, glass, sealing mould	0.2
			mouldings, miscellaneous	
			checking for water ingress	
2015-08-01 - Mileage: 1 - Order nr: 201850				
		96000		0
2015-07-30 - Mileage: 11260 - Order nr: 8062469				
	*	M	PLEASE FILL IN	
			Mileage:	
			Hrs:	
			Name:FREEMAN	
			Phone:07 5466 2951	
		VO-1721000	Warranty service. After 4 weeks or maxim	2
		LO-835	CHECK D/S WINDOW - NOT STAYING UP?	1
		LO-719	CALIBRATED WEIGHT SCALE	1.7

PC	Type	Code	Description (Original)	#
	🔍		Inspected operation of window, could not fault either	
	🔍		left or right sides, lubricated channels	
🔍 2015-07-09 - Mileage: 4321 - Order nr: 8061714				
📌	🔍	LO-820	PAINT T/T BLACK	1
	🔍		- GENERAL	
📌	*	MTPAINT	PANELSHOP PAINT	
📌	*	91	PANELSHOP CONSUMABLES	
	🔍		REFER NEW TRUCK FIT UPS	
	🔍		ORDER NO;4013701	
🔍 2015-07-09 - Mileage: 100 - Order nr: 8061992				
📌	🔍	LO-170	REGISTRATION	3
🔍 🌐 2015-07-09 - Mileage: 100 - Order nr: 8061733				
📌	*	M	PLEASE FILL IN	
	🔍		Mileage:	
	🔍		Hrs:.....	
	🔍		Name:.....	
	🔍		Phone:.....	
🌐	🔍	LO-856	CAB BUNK	1
🌐	🔍	VO-82378986	HINGE FITTING	1
🌐	🔍	VO-82328298	HINGE FITTING	1
🔍 2015-06-24 - Mileage: 68 - Order nr: 8058621				
📌	🔍	LO-171	PRE DELIVERY WITH PLATES	6.5
📌	*	MTELEC186	RIVETS	
📌	*	10	VEHICLE DETAIL	
📌	*	10	TARE WEIGHT	
📌	🔍	LO-810	FIT AEROFOIL	3
📌	*	10	CUSTOM BADGE	
📌	🔍	LO-350	3 X LED LIGHTS TO EACH MIRROR	3.1
📌	🔍	LO-350	3 X LED LIGHTS TO EACH SIDE OF CAB	3.55
📌	🔍	LO-852	DRIVERS SHEEP SKIN SEAT COVER	0.55
	🔍		NOLANS LOGO	
📌	*	860	NOLANS PARTS KIT	
	🔍		BELTS, RADIATOR HOSES, FILTERS N O AIR	
📌	🔍	LO-843	LEFT & RIGHT WEATHERSHIELDS	1.6
📌	🔍	LO-360	CALIBRATE LOAD SCALES SOFTWARE	1
	🔍		IN TRUCK FROM FACTORY	
📌	🔍	LO-350	RELOCATE EXISTING REASR OF CAB WORK	2.4
	🔍		LIGHTS TO THE AERO KIT SIDE WINGS	

PC	Type	Code	Description (Original)	#
		LO-610	IMEX FULL STAINLESS STEEL DRESS RING	1.35
			TO STEER AXLE	
		LO-360	PROGRAM 4 MINUTE IDLE SHUT DOWN	1
		LO-360	ENSURE 12 & 24 VOLT PLUTS ARE LED OK	1
		LO-712	S&F JOST JSK37 CZ GREASE TOP 185 FEET	2
			DRILL Ö CENTRE + 50 + 100	
		LO-826	CHANGE REAR PLASTIC GUARDS TO SMOOTH	5
			STAINLESS STEEL WITH ALLOY MOUNT CLAMPS	
		LO-360	CHECK K FACTOR WITH LOADED TEST TRAILER	1
			100KMH	
		LO-250	REPLACE EXHAUST TAIL PIPE	1.5
			SAME AS 200397	
	*	10	WINDOW TINT	
	*	10	POLISH FUEL TANKS	
	*	610	VOLVO POLISHED DURABRITE	
			AND R150 STEER TYRE	
	*	60	R150 TYRE	
	*	20	EXHAUST	
		LO-712	FRONT ALLOY DECK PLATE	3.7
		OTH-NPNC/PCOVER	90-3 COVER KEYLOCK	2
		OTH-UES32752	ANTILUCE FASTENER 50MM THREAD	2
		VO-20393237	RUBBER MOULDING	2
		OTH-25060	WEAR PLATE ANTI-VIB CLIP S/S	2
		OTH-NPNC/PKEY	E3-5-15 KEY KEYLOCK	2
		OTH-NPNC/PLATCH	E3-15-25 LATCH KEYLO	2
		AU2-9703- JSK37CZ201TO	.JSK 37 CZ/185 C/W	1
		OTH-FAB1	TAPE MASKING 48MM	2
		MK-NARV54406BL	FUSE HOLDER 1=1	1
		OTH-26260CK	LUCIDITY MARKER WHITE STAINLES	6
		VO-990976	LOCK NUT	12
		MK-NARV56707	TUBING 7MM 1=10M	2
		MK-NARV56406	CABLE TIE 1=100PK	1
		VO-25171459	TORX SCREW M4 x 18mm	12
		VO-6781769	SPLICE RED	30
		OTH-26260AK	LUCIDITY MARKER AMBER STAINLES	6
		VO-990976	LOCK NUT	12
		MK-NARV56600	HEATSHRINK 1=1 150	1

PC	Type	Code	Description (Original)	#
		VO-25392050	RELAY RETAINER	1
		VO-979002	TERMINAL FEMALE	5
		VO-21244697	RELAY	1
		VO-949597	SLEEVE LOCKING	5
		MK-NARV56820BK	TAPE NITTO BLACK	1
		VO-25171459	TORX SCREW M4 x 18mm	12
		VO-82217702	ATTACHMENT KIT	1
		VO-6781769	SPLICE RED	10
		VO-8141219	Grommet, antenna coaxial cable	2
		OTH-AMB25B	STICKY PAD	10
		MK-NARV56306	CABLE TIE 1=25PK	1
		OTH-VSHEEPNOLANSRH	SHEEPSKIN NOLANS	1
		VO-84165756	WEATHERSHIELD (FH4)	1
		VO-22273743	HOSE	1
		VO-21133830	HOSE	1
		VO-20464675	V-RIBBED BELT	1
		VO-22275091	V-RIBBED BELT	1
		VO-FK18B	FILTER KIT	1
		VO-970771	CABLE SEAL	4
		VO-1500600	RUBBER BUSH	2
		VO-8141219	Grommet, antenna coaxial cable	2
		MK-9711-4017RSVVS6S	DRESS DISC H/CAP	1
		VO-8394442	CLIPS, HUBCAP FIT	12
		MK-9750-SS11SINCNG	S/STEEL GRD NO RIB	4
		MK-9750-MMABPOL	BRACKET	16
		AU2-20572280	WHEEL 22.5 X 8.25 DURA BRITE	1
		VO-993723	CABLE TERMINAL	3
		VO-20716730	HOUSING	1
		VO-20716731	HOUSING	1
		VO-995632	HOUSING	1
		VO-21708450	FMS PREPERATION KI	1
		LO-810	FMS GATEWAY	3.1
		70	PAINT TURN TABLE	
		MTELEC6	4000- Twin Core Cable	
		MTELEC6	4000- Twin Core Cable.	
		MK-980AX26	TERMINAL, FEMALE V	6
		MTELEC6	4000- Twin Core Cable..	

PC	Type	Code	Description (Original)	#
	*	MTELEC206	4000- 12.8mm conduit	
	*	70	TURN TABLE MOD PLATE	
	■	VO-85135865	CONVERSION KIT	1
	☒		MOUNT Ö 50MM FORWARD OF CENTRE	
	☒		FRONT ALLOY DECKPLATE	
	*	MTELEC187	WALK PLATE CHECKER PLATE	
	☒		CHROME NUT COVERS ALL AXLES	
	☒		HUBCAPS TO REAR AXLES	
	☒		ADD RUBER LOOP BETWEEN THE NEW GUARDS	
	☒		NO HAIR REQUIRED	