



Vehicle History Summary



Fleet #	19
Registration	KST44
Make	Kenworth
Model	K104
VIN / Chassis #	6F50000001A421321
Build Date	2001

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-5146	12/11/2022	826409	0	A - 30 Days		Colin Scott
S-5069	15/10/2022	824849	0	A - 30 Days		Kelvyn Fuller
S-5086	17/09/2022	823374		C - Annual		Kelvyn Fuller
I-64	17/09/2022	823374		HEAVY VEHICLE ANNUAL INSPECTION - TRUCKS		Kelvyn Fuller
S-5001	17/09/2022	823374	0	A - 30 Days		Colin Scott
S-4960	18/08/2022	821824	0	A - 30 Days		Colin Scott
T-1435	10/08/2022	0	0	NEW VALVE		Tyreright
S-4835	16/07/2022	820253	0	A - 30 Days		Colin Scott
S-4812	18/06/2022	819710	0	A - 30 Days		Colin Scott
T-1399	30/05/2022	0	0	Puncture	1 PUNCTURE	Tyreright
T-1395	21/05/2022	0	0	Puncture		Tyreright
S-4715	21/05/2022	818418	0	A - 30 Days		Colin Scott
S-4678	23/04/2022	817576	0	A - 30 Days		Colin Scott
S-4677	25/03/2022	816688	0	A - 30 Days		Colin Scott
S-4676	25/02/2022	815938	0	A - 30 Days		Colin Scott
T-1336	27/01/2022	0	0	STRIP & FIT	8 STRIP AND FIT	Tyreright
S-4451	27/01/2022	813974	0	A - 30 Days		Colin Scott
R-2028	19/01/2022	0	0	Misc	R & R ROD END ON GEAR LEAVER	SH&M Fuller Transport Repairs
T-1324	13/01/2022	0	0	STRIP & FIT	2 STRIP AND FIT 2 BALANCE	Tyreright
R-2027	12/01/2022	0	0	Brakes	R & R SUPPLIED POSITION 4 BRAKE SHOE KIT AND LEAKING SHOCK ABSORBER	SH&M Fuller Transport Repairs
S-4210	30/12/2021	809400	0	B - 30k		Colin Scott
S-4225	25/11/2021	801477	0	A - 30 Days		Colin Scott

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
T-1301	24/11/2021	0	0	FIT NEW		Tyreright
R-2002	17/11/2021	0	0	EXHAUST	FIT NEW EXHAUST Y SECTION , EXHAUST FLEX, L/H/F SHOCK ABSORBER POST AND BUSHES, FIT INTAKE PIPE CLAMPS, WELD PLATE ON BULLBAR FOR SPOT LIGHT. MOST PARTS SUPPLIED	SH&M Fuller
R-1999	12/11/2021	0	0	Windscreen	R & R L/H/S AND R/H/S WINDSCREENS	Windscreen For Trucks
R-2023	02/11/2021	0	0	Misc	CHECK HORTON FAN CIRCUIT AGAIN LOCATE FAULT AND FIX CONTACT REVERSE LEG TO BATTERY	ROTHALE PTY LTD
S-4224	21/10/2021	790432	0	A - 30 Days		Colin Scott
S-4178	25/09/2021	777553	0	A - 30 Days		Colin Scott
S-4177	25/09/2021	777553	0	C - Annual		Colin Scott
I-4	25/09/2021	777553	0	HEAVY VEHICLE ANNUAL INSPECTION - TRUCKS		Colin Scott
T-1284	22/09/2021	0	0	STIP AND FLIP		Tyreright
S-3114	21/08/2021	766561	0	A - 30 Days		Colin Scott
R-1515	06/08/2021	759646		MISC	R & R THROUGH SHIFT SEAL, SWAY BAR BUSHES, V STAY BUSHES	SH&M Fuller
S-4134	17/07/2021	752543	0	B - 30k		Colin Scott
S-4133	17/07/2021	752543	0	A - 30 Days		Colin Scott
R-1346	03/07/2021			AIR Conditioner	RECLAM SMALL AMOUNT REFRIGERATANT. FIT UP NEW COMPRESSOR TX VALVE. R/D AND FLUSH SYSTEM. REGAS	ROTHALE PTY LTD
S-4156	19/06/2021	742075	0	A - 30 Days		Kelvyn Fuller
T-1225	03/06/2021			Re - Treads		TYRE EVOLUTION
T-1226	03/06/2021			New		TYRE EVOLUTION
S-3591	09/05/2021	722746	0	A - 30 Days		Colin Scott
S-3590	09/05/2021	722746	0	B - 30k		Colin Scott
T-1159	13/04/2021			Pressure Test		TYRE EVOLUTION
T-1160	13/04/2021			STRIP		TYRE EVOLUTION
S-3115	02/04/2021	709908	0	A - 30 Days		Colin Scott
S-3116	12/03/2021	700719	0	A - 30 Days		Colin Scott
S-3117	19/02/2021	691002	0	A - 30 Days		Colin Scott

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-1261	17/02/2021			fuel leak	REMOVE AND REPLACE FUEL CROSSOVER BARS ON PIPING	SH&M Fuller
S-3685	22/01/2021	684374	0	A - 30 Days		Colin Scott
S-3686	22/01/2021	684374	0	B - 30k		Colin Scott
R-1217	19/12/2020			AIR Conditioner	GO TO VEHICLE FIND LEAK IN A/C. REPLACE ONE HOSE , EVACUTATE REGARE . L/H WINDOW UP FIT PLUG FIND TO COMBINATION LAMP	ROTHALE PTY LTD

Signed:

Name:

Date:
