

Work Order	Start Date	Description
331577	16-Feb-16	workorder to set truck up to mine specs
337373	1-Mar-16	WORK ORDER FOR MONTHLY ALLOCATIONS
334412	3-Mar-16	WEEKLY SERVICE FOR SANDVIK TH663
334413	3-Mar-16	DAILY SERVICE FOR SANDVIK TH663.
334959	9-Mar-16	WORK ORDER FOR MONTHLY HIRE OF TR18
335016	10-Mar-16	WEEKLY SERVICE FOR SANDVIK TH663
335017	10-Mar-16	DAILY SERVICE FOR SANDVIK TH663.
335331	11-Mar-16	Recalibrate retarder code 183.4215.1 coming up
335059	14-Mar-16	Carry out 50hr service.
335437	17-Mar-16	Change diff & final drive oils in both axles. Approx 125hrs
335721	17-Mar-16	WEEKLY SERVICE FOR SANDVIK TH663
335722	17-Mar-16	DAILY SERVICE FOR SANDVIK TH663.
336039	20-Mar-16	fire detected fault.
336095	21-Mar-16	check tranny fault and fire alarm codes coming on
336297	23-Mar-16	WEEKLY ORDER FOR AIR FILTER/PARTS USED ON SANDVIK
336248	24-Mar-16	WEEKLY SERVICE FOR SANDVIK TH663
336249	24-Mar-16	DAILY SERVICE FOR SANDVIK TH663.
336255	25-Mar-16	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
336930	31-Mar-16	WEEKLY SERVICE FOR SANDVIK TH663
336931	31-Mar-16	DAILY SERVICE FOR SANDVIK TH663.
337176	3-Apr-16	repair and refit hand rail.
337502	7-Apr-16	WEEKLY SERVICE FOR SANDVIK TH663
337503	7-Apr-16	DAILY SERVICE FOR SANDVIK TH663.
337511	7-Apr-16	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
338219	8-Apr-16	Seat base nuts come loose
338593	14-Apr-16	WEEKLY SERVICE FOR SANDVIK TH663
338594	14-Apr-16	DAILY SERVICE FOR SANDVIK TH663.
339132	19-Apr-16	replace main fuse
338640	20-Apr-16	Repair handrail and step
339245	21-Apr-16	WEEKLY SERVICE FOR SANDVIK TH663
339246	21-Apr-16	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
339247	21-Apr-16	DAILY SERVICE FOR SANDVIK TH663.
339649	24-Apr-16	Stopped in decline after 14T of over size dropped in tub.
339669	25-Apr-16	gear fault . stuck in reverse . P0730 ??
339894	28-Apr-16	WEEKLY SERVICE FOR SANDVIK TH663
339895	28-Apr-16	DAILY SERVICE FOR SANDVIK TH663.
339994	28-Apr-16	shut down . Reset circuit breakers
340645	30-Apr-16	reset circuit breaker fuel pump
340659	1-May-16	Replace door handle.(spare to back on shelf)
340660	1-May-16	Replace door handle (spare replacement)
340701	1-May-16	Sandvik Safety Bulletin #2016/07 Rev1. New design fuel tank
340774	3-May-16	replace accumulators bracket.
341015	4-May-16	broken clamp on radiator hose.
340021	5-May-16	Retorque of wheel bearings at first 1000hr service.
340710	5-May-16	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
340878	5-May-16	WEEKLY SERVICE FOR SANDVIK TH663
340879	5-May-16	DAILY SERVICE FOR SANDVIK TH663.

356652	5-May-16	CHECK / ADJUST WHEEL BEARING PRELOAD TENSION - see 340021.
356653	5-May-16	CHECK / ADJUST WHEEL BEARING PRELOAD TENSION - see 340021
341378	9-May-16	flat front tyre POS 2
341672	11-May-16	popped c/braker f2085 box position /steering sensor supply
340957	12-May-16	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
341553	12-May-16	WEEKLY SERVICE FOR SANDVIK TH663
341554	12-May-16	DAILY SERVICE FOR SANDVIK TH663.
341745	13-May-16	fit 2 x new tyres (pos1 & 2) mich XTXL
341816	14-May-16	CHECK FUEL TANK BREATHER
341822	14-May-16	fix door window winder and refit handrail
341834	14-May-16	calibrate weight scale sensor.
342202	18-May-16	fit actuator for operator seat
342203	18-May-16	brake oil tank - add additive to oil
342204	18-May-16	flush cooling system - refill with caltex coolant
342205	18-May-16	replace multi controller switch
342166	19-May-16	WEEKLY SERVICE FOR SANDVIK TH663
342167	19-May-16	DAILY SERVICE FOR SANDVIK TH663.
342172	20-May-16	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
342309	20-May-16	Set up live SOS sample ports on machine
342334	20-May-16	Low engine power, not pulling out of first gear with 62t
343131	26-May-16	WEEKLY SERVICE FOR SANDVIK TH663
343132	26-May-16	DAILY SERVICE FOR SANDVIK TH663.
343197	26-May-16	Pos 3 tyre alarm going off
343885	2-Jun-16	WEEKLY SERVICE FOR SANDVIK TH663
343886	2-Jun-16	DAILY SERVICE FOR SANDVIK TH663.
343186	3-Jun-16	replace aftercooler bolts
343892	3-Jun-16	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
344496	9-Jun-16	WEEKLY SERVICE FOR SANDVIK TH663
344497	9-Jun-16	DAILY SERVICE FOR SANDVIK TH663.
344734	12-Jun-16	Truck 18. Bad comms reception & transmission.
345156	16-Jun-16	WEEKLY SERVICE FOR SANDVIK TH663
345157	16-Jun-16	DAILY SERVICE FOR SANDVIK TH663.
345165	18-Jun-16	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
345371	18-Jun-16	down popped circet brakers
345596	21-Jun-16	reset circuit brakers again
345770	23-Jun-16	WEEKLY SERVICE FOR SANDVIK TH663
345771	23-Jun-16	DAILY SERVICE FOR SANDVIK TH663.
345853	23-Jun-16	reset circuit brakers at 10pm
345854	23-Jun-16	reset circuit brakers at 2am
346661	29-Jun-16	reset circuit breaker
346546	30-Jun-16	WEEKLY SERVICE FOR SANDVIK TH663
346547	30-Jun-16	DAILY SERVICE FOR SANDVIK TH663.
346712	30-Jun-16	reset circuit breaker
346561	2-Jul-16	2000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
346927	3-Jul-16	Fault light come on
346947	4-Jul-16	daily, window and jack leg creep
347181	7-Jul-16	DAILY SERVICE FOR SANDVIK TH663.
347220	7-Jul-16	change transmission oil, change upbox oil, sample & change

347306	7-Jul-16	replace inner door handle.
347150	9-Jul-16	WEEKLY SERVICE FOR SANDVIK TH663
347715	11-Jul-16	jumpstart on go bay and transmission filter clogged alarm
347955	14-Jul-16	WEEKLY SERVICE FOR SANDVIK TH663
347956	14-Jul-16	DAILY SERVICE FOR SANDVIK TH663.
347967	16-Jul-16	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
348566	18-Jul-16	Batterys flat Replace with new going flat in a short period
348584	18-Jul-16	Popped c/brakers
348639	20-Jul-16	circuit brakers tripped out
348766	21-Jul-16	WEEKLY SERVICE FOR SANDVIK TH663
348767	21-Jul-16	DAILY SERVICE FOR SANDVIK TH663.
349107	21-Jul-16	retarder fault . recalibrate retarder.
349138	21-Jul-16	sandvik training.
349151	21-Jul-16	fuel leak on fuel pump, plug loose. e-stop fault.
349158	21-Jul-16	tripped circuit breakers in centre hitch
349510	23-Jul-16	repair bent front step and replace lh rear view mirror.
349551	24-Jul-16	faults on display. isolate and test send back to work.
349757	26-Jul-16	tighten fuel receiver, loose.
349767	26-Jul-16	change out pos 1 tyre puncture - fit 2 new tyres to match up
349882	28-Jul-16	WEEKLY SERVICE FOR SANDVIK TH663
349883	28-Jul-16	DAILY SERVICE FOR SANDVIK TH663.
350192	1-Aug-16	Front fan motor leaking . Warranty ??
350196	1-Aug-16	repair and mod hand rails
350222	1-Aug-16	Top up tranny oil
349908	2-Aug-16	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
350250	2-Aug-16	REpair bracket to tranny oil oil filler
350252	2-Aug-16	Replace original Sandvik fuel fast fill on fuel tank with
350392	4-Aug-16	WEEKLY SERVICE FOR SANDVIK TH663
350393	4-Aug-16	DAILY SERVICE FOR SANDVIK TH663.
350571	5-Aug-16	remove and repair damaged hand rail.
350227	8-Aug-16	Re-position VHF Radio the same as TR19
350646	8-Aug-16	Replace damaged display screen
350178	9-Aug-16	oil leaking from front fan - DUPLICATE. SEE 350192
351013	11-Aug-16	WEEKLY SERVICE FOR SANDVIK TH663
351014	11-Aug-16	DAILY SERVICE FOR SANDVIK TH663.
351142	11-Aug-16	replace rear tyres with run outs. pos 4 bald. operator
351071	12-Aug-16	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
351245	12-Aug-16	replace po's 3 & 4 tyre with new
351296	13-Aug-16	Tub not lifting well - low on lift pressure
351300	14-Aug-16	Retarder not working/getting jammed on
351302	14-Aug-16	retarder not working properly. Recalibrate . OK
351096	15-Aug-16	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
351880	16-Aug-16	Tub was split from impact by oversize being dropped in.
351655	17-Aug-16	Low power . Engine oil level too high and derated.
351845	17-Aug-16	speed sensor fault
351798	18-Aug-16	WEEKLY SERVICE FOR SANDVIK TH663
351799	18-Aug-16	DAILY SERVICE FOR SANDVIK TH663.
352076	18-Aug-16	repair seat back adjuster handle.

352215	19-Aug-16	reset circuit breaker
352238	20-Aug-16	replace hoses front cooler fan motor.
352618	24-Aug-16	retension wheel nuts all wheels - found pos 3 nuts needing a
352512	25-Aug-16	WEEKLY SERVICE FOR SANDVIK TH663
352513	25-Aug-16	DAILY SERVICE FOR SANDVIK TH663.
353204	31-Aug-16	Reset circuit breakers
353212	31-Aug-16	reset fuse rear box
351187	1-Sep-16	clean up old allison transmissions for rebuild
353145	1-Sep-16	WEEKLY SERVICE FOR SANDVIK TH663
353146	1-Sep-16	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
353147	1-Sep-16	DAILY SERVICE FOR SANDVIK TH663.
353195	8-Sep-16	3000 ENGINE TUNE UP, WATER PUMP CHECK, VIBRATION DAMPER
353775	8-Sep-16	WEEKLY SERVICE FOR SANDVIK TH663
353776	8-Sep-16	DAILY SERVICE FOR SANDVIK TH663.
353989	10-Sep-16	replace feed rope - ACTUALLY JB06 SEE 354042
353990	10-Sep-16	air con not working
353994	10-Sep-16	Check damage from hitting wall
353999	10-Sep-16	air con fault
354506	13-Sep-16	fit new up box breather
352593	14-Sep-16	Allison Transmission Diagnostics Tooling
348160	15-Sep-16	fit wear plates to inside of tray where required
354642	15-Sep-16	WEEKLY SERVICE FOR SANDVIK TH663
354643	15-Sep-16	DAILY SERVICE FOR SANDVIK TH663.
354730	15-Sep-16	spare parts for servicing. return filter gasket.
354731	15-Sep-16	replace cabin mounting rubbers
354650	16-Sep-16	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
354770	16-Sep-16	emergency steer pump siezed.
354781	16-Sep-16	Exhaust clamps
354783	16-Sep-16	replace turbo cooler air hose.
354784	16-Sep-16	spare bearings for tub lift cylinder.
354789	16-Sep-16	blown hose centre hitch.
355127	20-Sep-16	centre hitch lower bearing retaining plate loose.
355363	21-Sep-16	replacement wheel chocks for sanvik trucks
355257	22-Sep-16	WEEKLY SERVICE FOR SANDVIK TH663
355258	22-Sep-16	DAILY SERVICE FOR SANDVIK TH663.
355730	23-Sep-16	PULL DROP BOX LUBE PUMP OFF AND LOCTITE GEAR ON - CHECK
355793	25-Sep-16	replace wiper blade and daily
355794	25-Sep-16	REpair damaged hand rail
355889	26-Sep-16	tranny fault stuck in second gear
356051	29-Sep-16	WEEKLY SERVICE FOR SANDVIK TH663
356052	29-Sep-16	DAILY SERVICE FOR SANDVIK TH663.
356368	1-Oct-16	replace all tyres.
356399	1-Oct-16	dash module not loading up. MCcon connection. reboot from
356076	3-Oct-16	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
356794	5-Oct-16	please install folder holder in cabin for operator to hold
356850	6-Oct-16	WEEKLY SERVICE FOR SANDVIK TH663
356851	6-Oct-16	DAILY SERVICE FOR SANDVIK TH663.
356960	6-Oct-16	Hydraulic hose leak rubbed throw on chasse

356980	7-Oct-16	reset circuit brakers
357028	8-Oct-16	Pull off wall po;s3 wheel off ground
357031	8-Oct-16	check retarder recalibrate
357058	9-Oct-16	Check scales
357113	10-Oct-16	weight cell fault - subject to warranty
357408	12-Oct-16	Short circuit box float solenoid XR1.2 fault.
357409	12-Oct-16	Suspension accumulators transferring oil - warranty
357575	12-Oct-16	Box up alarm on - clean sensor - isolate - restart ok
357615	12-Oct-16	Throwing numerous codes engine alerts,high engine speeds
357509	13-Oct-16	WEEKLY SERVICE FOR SANDVIK TH663
357510	13-Oct-16	DAILY SERVICE FOR SANDVIK TH663.
357659	13-Oct-16	recalibrate load scale cells. adrian and barry.
357728	15-Oct-16	low engine power. blocked dpf see history notes.
358095	17-Oct-16	tranny fault alarm, retarder set to high overheating.
358726	20-Oct-16	WEEKLY SERVICE FOR SANDVIK TH663
358727	20-Oct-16	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
358728	20-Oct-16	DAILY SERVICE FOR SANDVIK TH663.
353663	22-Oct-16	DPF CLEAN SANDVIK TH663
359339	24-Oct-16	Reset rear fuse replace bolts in rear light braket
359603	26-Oct-16	Reset brakers in rear of truck X 4 . Could not see which
359611	26-Oct-16	need to make transport container for DPF exhust unit
359393	27-Oct-16	WEEKLY SERVICE FOR SANDVIK TH663
359394	27-Oct-16	DAILY SERVICE FOR SANDVIK TH663.
359690	28-Oct-16	check a/c fault. replace filter working fine.
354785	29-Oct-16	replace steering cylinder dead end bearings.
356450	29-Oct-16	wiper/ horn switch need replacing
356930	29-Oct-16	replace front steering bushes on frame.
359730	29-Oct-16	replace door strut.
359902	1-Nov-16	air vent in back seat broken need replaceing
359905	1-Nov-16	replace mudguard on TR18 as per w/o 353994
359907	1-Nov-16	tyre pressure monitering system upgraded mounting kit
359916	1-Nov-16	check a/c blower fan
360097	2-Nov-16	replace tranny oil and filter to upgraded tranny filter
360046	3-Nov-16	WEEKLY SERVICE FOR SANDVIK TH663
360047	3-Nov-16	DAILY SERVICE FOR SANDVIK TH663.
360048	3-Nov-16	CHECK / ADJUST WHEEL BEARING PRELOAD TENSION
360049	3-Nov-16	CHECK / ADJUST WHEEL BEARING PRELOAD TENSION
360164	3-Nov-16	air con not cold clean out cab filter
360191	4-Nov-16	A/C not working . Evaporator iceing up
360259	5-Nov-16	electrical small air compressor sized
360066	6-Nov-16	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
360530	8-Nov-16	suspension linear sensor fault . recalibrate
360786	9-Nov-16	Code spn630 fmi
360694	10-Nov-16	WEEKLY SERVICE FOR SANDVIK TH663
360695	10-Nov-16	DAILY SERVICE FOR SANDVIK TH663.
360816	10-Nov-16	retarder not working . recalibrate and test . all good
360928	11-Nov-16	check all turbo lube lines
360755	12-Nov-16	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION

360948	12-Nov-16	tranny pressure fault. low pressure warning, check sensor
360507	14-Nov-16	Sandvik to supply stands for TH663 trucks
360561	15-Nov-16	replace damaged hand rail
361585	16-Nov-16	check radio operation
361481	17-Nov-16	WEEKLY SERVICE FOR SANDVIK TH663
361482	17-Nov-16	DAILY SERVICE FOR SANDVIK TH663.
360517	21-Nov-16	tooling for steering bushes
361500	21-Nov-16	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
361878	22-Nov-16	Tranny code p2637 torque management feed back signal
361991	24-Nov-16	WEEKLY SERVICE FOR SANDVIK TH663
361992	24-Nov-16	DAILY SERVICE FOR SANDVIK TH663.
362164	25-Nov-16	seat adjuster needs fixing
362174	26-Nov-16	replace seat back adjuster, and repair wiper washers.
362193	26-Nov-16	reset circuit breaker
362778	30-Nov-16	reset circuit breaker
362729	1-Dec-16	WEEKLY SERVICE FOR SANDVIK TH663
362730	1-Dec-16	DAILY SERVICE FOR SANDVIK TH663.
362824	1-Dec-16	cost for licencing to have Automine operational
362958	4-Dec-16	check suspension and cab mount bushes
362952	5-Dec-16	oil leak . hole in main suction line
362965	5-Dec-16	blown suction hose
362759	7-Dec-16	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
363718	7-Dec-16	Oil leak/blown hose at hyd cooler assy . Replace 2 hoses .
363825	8-Dec-16	DAILY SERVICE FOR SANDVIK TH663.
364098	8-Dec-16	replace lh rear hand rail hinge. and latch.
364149	9-Dec-16	tripped circuit breaker in rear box.
364206	11-Dec-16	rear box fuse tripped.
364208	11-Dec-16	a/c fault.
364209	11-Dec-16	blown hose on top of tranny rubbed through on filler
363824	13-Dec-16	WEEKLY SERVICE FOR SANDVIK TH663
364444	14-Dec-16	retension all planetary retaining bolts on all wheel ends.
364453	14-Dec-16	repair pos 4 rim side ring locking lug cracked.
364488	14-Dec-16	make up fitting to sample tranny oil.
364343	15-Dec-16	WEEKLY SERVICE FOR SANDVIK TH663
364344	15-Dec-16	DAILY SERVICE FOR SANDVIK TH663.
364906	20-Dec-16	re-calibrate tyre monitor
364923	20-Dec-16	Popped c/breaker f2085
365012	22-Dec-16	WEEKLY SERVICE FOR SANDVIK TH663
365013	22-Dec-16	DAILY SERVICE FOR SANDVIK TH663.
365025	23-Dec-16	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
364462	28-Dec-16	workorder to modify stock item 15180
365599	29-Dec-16	DAILY SERVICE FOR SANDVIK TH663.
364582	30-Dec-16	spares for thermostat failures
365598	30-Dec-16	WEEKLY SERVICE FOR SANDVIK TH663
365950	30-Dec-16	TURBO CHANGE OUT - SANDVIK TH663
365997	31-Dec-16	reset circuit brakers
366017	1-Jan-17	Flat tyre underground po's 1
366062	2-Jan-17	check and clear tranny code P0732 . 80-1842-5

366370	5-Jan-17	WEEKLY SERVICE FOR SANDVIK TH663
366371	5-Jan-17	DAILY SERVICE FOR SANDVIK TH663.
366464	5-Jan-17	replace cabin top bushes.
366645	6-Jan-17	door window dropping tighten bolts in handle
366702	8-Jan-17	cabin filter blocked, replace. reset c/b in rear cabinet.
366708	8-Jan-17	replace circuit breaker f2062 rear j-box, u/s.
366936	10-Jan-17	tranny fault, transmission high oil pressure.
366958	10-Jan-17	reset circuit breakers
366403	11-Jan-17	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
367072	12-Jan-17	WEEKLY SERVICE FOR SANDVIK TH663
367073	12-Jan-17	DAILY SERVICE FOR SANDVIK TH663.
360790	18-Jan-17	replace fan motor hose
366309	18-Jan-17	replace front exhaust manifold cover
367016	18-Jan-17	Fit document holder as per INX action
367940	19-Jan-17	WEEKLY SERVICE FOR SANDVIK TH663
367941	19-Jan-17	DAILY SERVICE FOR SANDVIK TH663.
368154	22-Jan-17	found metal in tranny oil - high pressure oil alarm on
368187	22-Jan-17	TRANSMISSION CHANGE OUT
368536	25-Jan-17	replace blown brake hose
368554	25-Jan-17	change out tranny oil filter and oil after tranny change out
368063	26-Jan-17	Rotate tyres as per Tyre Report.
368478	26-Jan-17	WEEKLY SERVICE FOR SANDVIK TH663
368479	26-Jan-17	DAILY SERVICE FOR SANDVIK TH663.
368604	27-Jan-17	Check lubrication to pump splines off PTO drive.
368691	28-Jan-17	check and adjust seat .
368731	29-Jan-17	park brake won't release . trace fault to no communication
368495	30-Jan-17	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
369027	31-Jan-17	repairs to seat
369087	1-Feb-17	Hydraulic filter light coming on . Change out filter. One
369089	1-Feb-17	window won't stat up. make needed repairs
369143	1-Feb-17	Repair mud flap
369211	2-Feb-17	WEEKLY SERVICE FOR SANDVIK TH663
369212	2-Feb-17	DAILY SERVICE FOR SANDVIK TH663.
369905	7-Feb-17	grease nipple broken off rh steer cylinder dead end.
370041	9-Feb-17	WEEKLY SERVICE FOR SANDVIK TH663
370042	9-Feb-17	DAILY SERVICE FOR SANDVIK TH663.
370167	9-Feb-17	hydraulic return filter light on . change filter.
370219	10-Feb-17	change out rear tyre with tr19's old ones
370316	12-Feb-17	replace rear diff pinion seal
370342	13-Feb-17	knocking sound coming from under truck , possible
370073	14-Feb-17	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
370416	14-Feb-17	Make up dummy plug for jack remote receptacle on
370568	16-Feb-17	WEEKLY SERVICE FOR SANDVIK TH663
370569	16-Feb-17	DAILY SERVICE FOR SANDVIK TH663.
370876	18-Feb-17	check a/c not cold - check radio static and remove door
370631	20-Feb-17	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
371265	23-Feb-17	WEEKLY SERVICE FOR SANDVIK TH663
371266	23-Feb-17	DAILY SERVICE FOR SANDVIK TH663.

371418	24-Feb-17	tr18 broken corner window
371484	25-Feb-17	replace all 4 tyres
371286	26-Feb-17	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
371683	27-Feb-17	Po's 3 tyre monitor leak detected
371876	28-Feb-17	Replace steel wheel chocks with plastic ones due to weight
362574	2-Mar-17	replace upbox output flange bolts as per
366409	2-Mar-17	UNI JOINT COMPONENT CHANGE OUT - SEE 372476
370317	2-Mar-17	dropbox front drive pinion seal leaking
370361	2-Mar-17	Fit Up-graded rear drive shaft support bearing as per
372046	2-Mar-17	WEEKLY SERVICE FOR SANDVIK TH663
372047	2-Mar-17	DAILY SERVICE FOR SANDVIK TH663.
372194	2-Mar-17	pos 2 air sensor u/s. replace.
372476	2-Mar-17	UNI JOINT COMPONENT CHANGE OUT
372298	4-Mar-17	check low power - check boost pressures
372446	5-Mar-17	low power not changing up gears.
372489	6-Mar-17	repair seat slides.
372738	7-Mar-17	Accelerator pedal worn
370655	8-Mar-17	workorder to book out rotatable transmission R19264
372996	9-Mar-17	WEEKLY SERVICE FOR SANDVIK TH663
372997	9-Mar-17	DAILY SERVICE FOR SANDVIK TH663.
373098	9-Mar-17	check weighing system errors
373186	11-Mar-17	blown hose in center hitch blocking central decline
373013	12-Mar-17	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
373211	12-Mar-17	Truck hot oily smell from out side , picked up by loader
373273	13-Mar-17	Po' 1 guard rubbing on guard check dog bone
373294	13-Mar-17	up grade soft ware
373024	14-Mar-17	DIESEL INJECTORS CHANGE OUT
370978	15-Mar-17	Upgrade retarder as per Sandvik 2016/24 rev2 this assists
373060	15-Mar-17	replace original starter motors with Delco MT39MT units
373660	15-Mar-17	CANCELLED - JOB DONE ON 373013 - 1000hr SERVICE
373578	16-Mar-17	WEEKLY SERVICE FOR SANDVIK TH663
373579	16-Mar-17	DAILY SERVICE FOR SANDVIK TH663.
373715	16-Mar-17	front led light low beam needs replacing
373743	17-Mar-17	truck leveling device fallen off inside cab
373756	17-Mar-17	window washer bottle needs replacing - part ordered
373760	17-Mar-17	retarder software upgrade
373816	19-Mar-17	low beam light u/s - fit hellra until original turns up
373421	21-Mar-17	Cummins & Sandvik to install an updated sump.
373448	21-Mar-17	Replace throttle pedal corner worn a way
374085	21-Mar-17	replace front step - bent/ damaged - ordered 21-3-17
373610	22-Mar-17	3000 HOUR ENGINE TUNE UP - VALVE & INJECTOR CLEARANCES,
374286	22-Mar-17	oil leak - brake hose
374081	23-Mar-17	after cooler cracked - cummins to fit new one
374213	23-Mar-17	WEEKLY SERVICE FOR SANDVIK TH663
374214	23-Mar-17	DAILY SERVICE FOR SANDVIK TH663.
374352	24-Mar-17	check P0973 gear fault . Low current H-J solenoid.
374394	25-Mar-17	Check TR18s radio for busy lockout fault, seemed fine and
374787	29-Mar-17	Noise when driving guard rubbing on tyre

374751	30-Mar-17	WEEKLY SERVICE FOR SANDVIK TH663
374752	30-Mar-17	DAILY SERVICE FOR SANDVIK TH663.
374762	31-Mar-17	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
375064	31-Mar-17	fit new batteries - one failed dropped to 3 volts
374788	1-Apr-17	Fit wear plates to front outside corners of tray where welds
375319	4-Apr-17	Oil leak at fan pump. o-ring
374694	5-Apr-17	Purifier /silencer/ muffler cracked has been repaired will
375396	5-Apr-17	Drivers window drops down
375526	5-Apr-17	Spare hose fittings. Cooler fan.
375560	5-Apr-17	Check fault codes
375451	6-Apr-17	DAILY SERVICE FOR SANDVIK TH663.
375606	6-Apr-17	starting , broken battery terminal .
375633	6-Apr-17	circuit breaker tripped out in rear box
375906	7-Apr-17	tranny fault
375450	9-Apr-17	WEEKLY SERVICE FOR SANDVIK TH663
375961	9-Apr-17	replace needed tranny hoses
375988	10-Apr-17	fit genuine sandvik head light in place of hella light
376257	13-Apr-17	WEEKLY SERVICE FOR SANDVIK TH663
376258	13-Apr-17	DAILY SERVICE FOR SANDVIK TH663.
376435	14-Apr-17	tranny fault, h/j solenoid fault. fit dummy coil.
376274	15-Apr-17	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
376490	16-Apr-17	rh hand rail damage.
377098	18-Apr-17	check tranny fault
377319	20-Apr-17	WEEKLY SERVICE FOR SANDVIK TH663
377320	20-Apr-17	DAILY SERVICE FOR SANDVIK TH663.
377853	22-Apr-17	bad smell coming from truck ?? Can not fault ,
377372	25-Apr-17	rotate tyres 1 to 4 & 2 to 3
378305	27-Apr-17	WEEKLY SERVICE FOR SANDVIK TH663
378306	27-Apr-17	DAILY SERVICE FOR SANDVIK TH663.
378316	28-Apr-17	DPF CLEAN SANDVIK TH663
378509	28-Apr-17	pos 4 inner side ring dog broken off. monitor.
378323	29-Apr-17	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
378549	29-Apr-17	retarder fault
378568	30-Apr-17	fit up-graded auto retarder switch.
378590	30-Apr-17	reset circuit breaker
378593	1-May-17	slop in suspension frame dog bone.
379047	4-May-17	WEEKLY SERVICE FOR SANDVIK TH663
379048	4-May-17	DAILY SERVICE FOR SANDVIK TH663.
379232	5-May-17	pos 1 low air pressure alarm coming on
379278	7-May-17	LH tyre sensor not working . REplace sensor
379331	8-May-17	Work order to capture Atlas Copco Transmission costs from
379527	11-May-17	WEEKLY SERVICE FOR SANDVIK TH663
379528	11-May-17	DAILY SERVICE FOR SANDVIK TH663.
379201	12-May-17	No emergency glass hammer
379663	12-May-17	replace front ladder damaged by operator
379664	12-May-17	replace tyre montiering reciever as faulty as per adrian
379546	14-May-17	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
379769	14-May-17	replace radio extension speaker

380140	18-May-17	DAILY SERVICE FOR SANDVIK TH663.
380559	19-May-17	replace isolator
380194	20-May-17	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
377945	21-May-17	Replace exhaust flex starting to leak
379572	21-May-17	rear pinion seal leaking
380139	21-May-17	WEEKLY SERVICE FOR SANDVIK TH663
380905	23-May-17	AFFF gone off. Truck stuck in decline
381003	25-May-17	WEEKLY SERVICE FOR SANDVIK TH663
381004	25-May-17	DAILY SERVICE FOR SANDVIK TH663.
381165	26-May-17	replace turbo lube supply hard line rubbing in engine.
381175	26-May-17	rear tyre pressure warning alarm coming on. tyre pressures
381021	28-May-17	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
381464	30-May-17	repair rear camera mount. cracked in half.
381578	30-May-17	truck jammed ph200.
381841	31-May-17	truck hit wall and got wedged - damaged window rubber
381721	1-Jun-17	DAILY SERVICE FOR SANDVIK TH663.
381720	3-Jun-17	WEEKLY SERVICE FOR SANDVIK TH663
381293	5-Jun-17	Fit Tray wear pack to inside of tray
382337	6-Jun-17	Cancelled during entry
382579	7-Jun-17	Very slow to take off/build up boost
382488	8-Jun-17	WEEKLY SERVICE FOR SANDVIK TH663
382489	8-Jun-17	DAILY SERVICE FOR SANDVIK TH663.
382668	9-Jun-17	change flat tyre pos 4 tread puncture
382736	10-Jun-17	radio aerial lead u/s, replace.
382034	11-Jun-17	Change LHS steering pins and bushes
382035	11-Jun-17	replace door strut and handle cover
382747	11-Jun-17	repair front hand rail
382774	11-Jun-17	roll over at saddle
382504	12-Jun-17	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
383205	15-Jun-17	WEEKLY SERVICE FOR SANDVIK TH663
383206	15-Jun-17	DAILY SERVICE FOR SANDVIK TH663.
383379	15-Jun-17	purchase & replace DPF after rollover
383540	15-Jun-17	DAILY SERVICE FOR SANDVIK TH663.
383443	17-Jun-17	Check steering and pins . OK
383444	17-Jun-17	Check center hitch . OK
383445	17-Jun-17	Check seat operation and seat belt . OK
383447	17-Jun-17	check axle mountings . OK
383448	17-Jun-17	check suspension operation and mountings
383449	17-Jun-17	Check cab and mountings
383450	17-Jun-17	Check tranny and engine mounts . OK
383475	17-Jun-17	Shut down estop pushed in by rock
383484	17-Jun-17	DAily and check over . All Good :)
383513	18-Jun-17	Engine over heating. Fan pump not making pressure.
382331	20-Jun-17	Change out electronic heater tap
382338	20-Jun-17	Sandvik to do DPF data download
383691	20-Jun-17	No air flow , change A/C filter
383792	20-Jun-17	Engine heat sheild damaging oil lines repair as per 46/2017
383965	20-Jun-17	Reset braker

384097	22-Jun-17	WEEKLY SERVICE FOR SANDVIK TH663
384098	22-Jun-17	DAILY SERVICE FOR SANDVIK TH663.
384337	25-Jun-17	pos 3 puncture.
384353	25-Jun-17	high speed shaft let go - blocking decline
384360	26-Jun-17	replace remote coil and spool for pilot to steering and dump
384677	27-Jun-17	replacement tub lift cylinder cover.
384877	28-Jun-17	Adjust Box and Steering Pump Pressure
384951	28-Jun-17	reset rear fuse / circuit breaker
384195	29-Jun-17	R/H taillight/brake light not working
384846	29-Jun-17	WEEKLY SERVICE FOR SANDVIK TH663
384847	29-Jun-17	DAILY SERVICE FOR SANDVIK TH663.
385004	29-Jun-17	check out noise in cab and suspension
385081	1-Jul-17	loose tub pins
384799	5-Jul-17	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
385838	5-Jul-17	batterys u/s replaced
385736	6-Jul-17	DAILY SERVICE FOR SANDVIK TH663.
385872	6-Jul-17	reset tyre pressures alarm going off
385032	7-Jul-17	resample up box and check mag plug
386116	7-Jul-17	check excessive exhaust smoke - no DPF exhaust fitted
386144	8-Jul-17	pos 1 tyre pressure sensor playing up reading high
386201	9-Jul-17	repair air cleaner door broken bolts - low power
386202	9-Jul-17	straighten handrail rhs rear
386203	9-Jul-17	turbo heat extraction pipe and clamps need replacing
386254	10-Jul-17	replace rhs handrail and check for othe damage
386348	13-Jul-17	DAILY SERVICE FOR SANDVIK TH663.
386704	13-Jul-17	reset fuse in rear box
387175	13-Jul-17	brake pressure filter coming on
387182	13-Jul-17	brake filter light on
386372	17-Jul-17	POS 3 FINAL DRIVE CHANGE OUT SANDVIK TH663
386373	17-Jul-17	POS 4 FINAL DRIVE CHANGE OUT SANDVIK TH662
387500	18-Jul-17	blown fuse and not starting
386535	19-Jul-17	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
387650	20-Jul-17	DAILY SERVICE FOR SANDVIK TH663.
387806	20-Jul-17	cab mounts need replacing (upper)parts on order
385041	21-Jul-17	workorder to purchase annual subscription for
387871	21-Jul-17	replace upper cab mount rubbers and bolts
388070	24-Jul-17	Adjust door latch
388084	24-Jul-17	Hose leaking out of ferall above brake oil tank.
388086	24-Jul-17	Check radio, hand piece.
388567	27-Jul-17	DAILY SERVICE FOR SANDVIK TH663.
388711	27-Jul-17	over heating . blown coolant hose to coolant filter.
388727	27-Jul-17	refill with cooland and check over for leaks
388628	28-Jul-17	install aletek DPF mufffler @ 8182 hrs
388878	29-Jul-17	oil leak on hyd filter
388996	31-Jul-17	air con belts u/s replaced
389358	3-Aug-17	DAILY SERVICE FOR SANDVIK TH663.
389519	3-Aug-17	brake filter restriction fault. checked nothing found.
389366	5-Aug-17	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.

388758	6-Aug-17	Brake pressure filter alarm coming on
389647	6-Aug-17	change out brake filter restriction switch, parts ordered on
388882	7-Aug-17	Door has no stopper
389741	8-Aug-17	repair front step
389806	8-Aug-17	blown hose
389920	10-Aug-17	DAILY SERVICE FOR SANDVIK TH663.
390052	10-Aug-17	fit a/c filter
390018	11-Aug-17	Latch on front step U/S
398474	11-Aug-17	WHEEL REPLACEMENT SANDVIK TH663
398475	11-Aug-17	WHEEL REPLACEMENT SANDVIK TH663
390180	13-Aug-17	retorque rear wheels
390207	13-Aug-17	air restriction on
390223	14-Aug-17	Speed shaft let go taking out multiple hard lines.
390037	15-Aug-17	replace all four tyres
390672	17-Aug-17	DAILY SERVICE FOR SANDVIK TH663.
391027	19-Aug-17	oil leak in centre hitch test fitting u/s.
390731	20-Aug-17	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
391074	20-Aug-17	replace engine breather with one off old engine.
391089	20-Aug-17	change air filters
391150	21-Aug-17	Order spare protection Rubbers for lift cylinders
391308	21-Aug-17	replace rear camera bracket
391365	22-Aug-17	check and replace cab mounts if required.
391387	22-Aug-17	check over speed shaft, tension etc.
391393	22-Aug-17	engine breather u/s replace with second hand off old engine.
391517	24-Aug-17	DAILY SERVICE FOR SANDVIK TH663.
391702	24-Aug-17	reset rear fuse
391750	25-Aug-17	replace side window from rock damage
391529	26-Aug-17	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
391532	27-Aug-17	CHECK / ADJUST WHEEL BEARING PRELOAD TENSION
391533	27-Aug-17	CHECK / ADJUST WHEEL BEARING PRELOAD TENSION
392139	28-Aug-17	retorque all wheel ends to 610 nm - 450 flb
391541	29-Aug-17	RENEW 12 MONTHLY CUMMINS INSIGHT LICENCE
392364	31-Aug-17	DAILY SERVICE FOR SANDVIK TH663.
392488	31-Aug-17	check/ repair /replace handrails on service day
392572	1-Sep-17	check jack leg creeping
392573	1-Sep-17	fix rear camera mount
392599	2-Sep-17	RHS camera needs replacing and camera cable
392600	2-Sep-17	cut plastic off inner guard rubbing on tyre pos 1
392660	3-Sep-17	reset circuit breaker
392687	4-Sep-17	lh inner guard rubbing on wheel.
392154	5-Sep-17	LH front window seal.
391868	6-Sep-17	Retaining bolts on pins still missing/broken.
393188	7-Sep-17	DAILY SERVICE FOR SANDVIK TH663.
393215	13-Sep-17	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
394376	13-Sep-17	oil leak at rear of transmission
394280	14-Sep-17	DAILY SERVICE FOR SANDVIK TH663.
394447	14-Sep-17	dpf blockage alarm. turn off as per adrian orourke.
393388	15-Sep-17	RHS arm rest end broken off

394508	15-Sep-17	fit radio external speaker.
394313	16-Sep-17	Repair articulation lock bar as per safety bulletin 2017-65
394831	18-Sep-17	sandvik up grade.
395023	21-Sep-17	DAILY SERVICE FOR SANDVIK TH663.
395175	21-Sep-17	dove tail cracking needs repair
395805	27-Sep-17	tighten tub pivot bolts
395846	28-Sep-17	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
395847	28-Sep-17	DAILY SERVICE FOR SANDVIK TH663.
396158	29-Sep-17	getting hot
396189	30-Sep-17	coolant filter has been by-passed re-plumbing required.
396190	30-Sep-17	lh front steering cylinder pin retainer bolts broken.
396251	1-Oct-17	a/c fault.
396254	1-Oct-17	brake oil pressure filter blocked.
396486	3-Oct-17	Workorder to purchase remote head radios for trucks
396739	4-Oct-17	grease line on rh tub pin snapped.
396748	4-Oct-17	brake filter alarm wiring needs repair.
396629	5-Oct-17	DAILY SERVICE FOR SANDVIK TH663.
396996	8-Oct-17	reset circuit breakers
395045	10-Oct-17	3000 HOUR ENGINE TUNE UP - VALVE & INJECTOR CLEARANCES,
396365	10-Oct-17	operators complained about tone of horns replace horn
396658	10-Oct-17	6000 HYDRAULIC OIL CHANGE FOR SANDVIK TH663 TRUCK.
397379	10-Oct-17	check turbo mounting bolts
396517	11-Oct-17	Sample Point Upgrade - Sandvik
397491	12-Oct-17	DAILY SERVICE FOR SANDVIK TH663.
397616	12-Oct-17	fuel pump fault. fuel pump pressure switch wiring, rubbed
397644	12-Oct-17	reset circuit breakers
397732	14-Oct-17	blown steer hose in centre hitch.
397785	15-Oct-17	a/c clutch faulty on compressor.
397024	16-Oct-17	Order spare TH663 wheels
397505	16-Oct-17	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
398116	17-Oct-17	front axle pinion seal leaking
398117	17-Oct-17	compensator valve leaking oil on main pump
398128	17-Oct-17	snapped bolts in tub hinge pins. tub clevis worn, will
398190	17-Oct-17	retorque pos 3 wheel nuts
398301	19-Oct-17	DAILY SERVICE FOR SANDVIK TH663.
398505	20-Oct-17	oil leak above front diff
400047	25-Oct-17	replace blown oring
399942	26-Oct-17	DAILY SERVICE FOR SANDVIK TH663.
399970	28-Oct-17	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
400213	28-Oct-17	blown hose pos 1 jack leg.
399943	29-Oct-17	CHECK / ADJUST WHEEL BEARING PRELOAD TENSION
399944	29-Oct-17	CHECK / ADJUST WHEEL BEARING PRELOAD TENSION
400459	31-Oct-17	reset rear circuit breakers
400646	1-Nov-17	Replace damage air filter housing
400657	1-Nov-17	RH steer cyl dead end u/s in cylinder bore - sloppy bush
400591	2-Nov-17	DAILY SERVICE FOR SANDVIK TH663.
400768	3-Nov-17	Missing wheel chock
400929	6-Nov-17	New wheels for Sandvik trucks.

401548	9-Nov-17	DAILY SERVICE FOR SANDVIK TH663.
401819	12-Nov-17	engine oil leak front timing area inspect and report.
401839	12-Nov-17	Reset rear circuit breaker
401561	13-Nov-17	TURBO CHANGE OUT - SANDVIK TH663
401576	13-Nov-17	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
401585	13-Nov-17	rotate tyres 1- 4 & 3 - 2
402177	15-Nov-17	rh steer cylinder sloppy in bearing dead end. bearing
402224	15-Nov-17	brake oil temps high during the last several days brake hyd
402088	16-Nov-17	DAILY SERVICE FOR SANDVIK TH663.
402308	16-Nov-17	repair missing bolts in radio
402413	17-Nov-17	replace two way radio to the new style
402414	17-Nov-17	fit new style horn
402451	18-Nov-17	brake hose come loose
402474	19-Nov-17	Checked with Carl the auto sparkie about the new radio
402570	20-Nov-17	replace bolts in rear tub pins
402158	22-Nov-17	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
402210	22-Nov-17	Fit bushes to rear frame for tub pivot as per Sandvik
402862	23-Nov-17	DAILY SERVICE FOR SANDVIK TH663.
403026	23-Nov-17	DPF CLEAN SANDVIK TH663
402460	30-Nov-17	front timing cover seal leaking again - @10111hrs
403634	30-Nov-17	DAILY SERVICE FOR SANDVIK TH663.
403745	30-Nov-17	replace rh side light
403747	30-Nov-17	Optimine Alert - DPF
403646	1-Dec-17	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
403910	3-Dec-17	suspension dropping check tap seem to be loose tighten up
404256	5-Dec-17	replace lh hand rail
404521	6-Dec-17	Engine wont rev up
403801	7-Dec-17	Change tranny filter at next service. See attached pics from
404426	7-Dec-17	DAILY SERVICE FOR SANDVIK TH663.
405142	8-Dec-17	Purchase of mag plug boxes. PJL quote 23545
405188	9-Dec-17	change out seat lumber support faulty.
405246	10-Dec-17	retarder fault
405284	11-Dec-17	Transmission filter blockage alarm coming on. change out
405285	11-Dec-17	retarder fault, actuator u/s change out.
405288	11-Dec-17	alternator not charging, alternator u/s.
405543	13-Dec-17	monitor engine oil consumption and record.
405602	14-Dec-17	DAILY SERVICE FOR SANDVIK TH663.
405776	14-Dec-17	terminal W fault on screen
405796	14-Dec-17	reset rear fuse
405915	16-Dec-17	tranny fault code came on / replace tranny filter and
396749	17-Dec-17	drop box dipstick tube to be replaced.
400267	17-Dec-17	Rear wiper not working (parts ordered 3/11/17)
403025	17-Dec-17	handrail behing cab need weld repair
405829	18-Dec-17	replace rear diff & final drive oils DONE @ 10360HRS
405632	20-Dec-17	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
406364	20-Dec-17	replace coolant line off turbo
406333	21-Dec-17	DAILY SERVICE FOR SANDVIK TH663.
406714	24-Dec-17	brake cooling fan motor leaking oil

406744	26-Dec-17	fault code tranny filter blocked - changed filter and oil
407023	27-Dec-17	recalibrate retarder = coming on to quick
406391	28-Dec-17	Install new tub protection plates to outside of new tub
406943	28-Dec-17	DAILY SERVICE FOR SANDVIK TH663.
405834	29-Dec-17	purchase allison licence for tough book 150PC02
407299	31-Dec-17	trans filter blockage light on change oil and filter and
407303	31-Dec-17	replace rhr tilt pin grease line
407533	2-Jan-18	a/c not cold replace air filter a/c was iced up
407545	2-Jan-18	Replace 1/4 window seal
407756	3-Jan-18	trans filter blocked light
407670	4-Jan-18	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
407671	4-Jan-18	DAILY SERVICE FOR SANDVIK TH663.
407210	5-Jan-18	Upgrade cooler hoses as per Sandvik Bulletin 2017-89
407931	6-Jan-18	change hyd return filter - fault light coming on
408326	8-Jan-18	hyd return filter blockage fault. sensor plug dirty.
408376	9-Jan-18	pos 3 puncture.
408646	10-Jan-18	hydraulic filter blockage alarm - check wiring
408519	11-Jan-18	DAILY SERVICE FOR SANDVIK TH663.
406395	15-Jan-18	Change out tub. Linebore rear frame pin holes. Lineborer
408540	15-Jan-18	UNI JOINT COMPONENT CHANGE OUT
408574	15-Jan-18	TRANSMISSION CHANGE OUT - WARRANTY. SEE HISTORY NOTES.
392502	16-Jan-18	replace speed shaft & damaged hard lines from shaft failure
404775	16-Jan-18	Aftercooler housing cracked
409414	18-Jan-18	DAILY SERVICE FOR SANDVIK TH663.
409609	19-Jan-18	fit 4X new tyres
409628	19-Jan-18	replace lift cyls x2 during tub changeout
409639	19-Jan-18	Work order to capture cost for fusion radio. and install
409761	19-Jan-18	check engine cooling fan speed 1850rpm, 247bar max pump
409762	19-Jan-18	check suspension accumulators pressure.
409771	19-Jan-18	check brake flushing pump pressure.
418016	19-Jan-18	WHEEL REPLACEMENT SANDVIK TH663
418017	19-Jan-18	WHEEL REPLACEMENT SANDVIK TH663
419730	19-Jan-18	WHEEL REPLACEMENT SANDVIK TH663 - INCORRECT HOURS ENTERED.
419731	19-Jan-18	WHEEL REPLACEMENT SANDVIK TH663
409760	20-Jan-18	check engine cooler stand by pressure at 45bar adjust to
409805	20-Jan-18	check engine cooler fan speed 1950rpm.
409871	22-Jan-18	Retorque all 4 wheels
409872	22-Jan-18	Repair oil leak at brake pump
409484	25-Jan-18	Replace hydraulic cooler old one leaking
410213	25-Jan-18	DAILY SERVICE FOR SANDVIK TH663.
409423	26-Jan-18	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
410391	26-Jan-18	replace leaking exhaust flex
410467	27-Jan-18	check tranny high pressure fault
410558	29-Jan-18	Brake manifolds parts for axle assemblies -
410794	30-Jan-18	Manufacture TH663 tub chariot
410951	1-Feb-18	DAILY SERVICE FOR SANDVIK TH663.
411096	1-Feb-18	Upgrade TH663 Optimine Software to Version 2.5
411264	3-Feb-18	oil leak near cab - loose fitting

411266	3-Feb-18	order new fuel reciever
411298	4-Feb-18	repair front step.
411305	4-Feb-18	low power issue replace air filters etc.
407624	5-Feb-18	CHECK / ADJUST WHEEL BEARING PRELOAD TENSION
407625	5-Feb-18	CHECK / ADJUST WHEEL BEARING PRELOAD TENSION
410999	5-Feb-18	Measure axle spline wear as per Sandvik service bulletin
411553	5-Feb-18	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
412184	7-Feb-18	reset circuit breakers
412227	7-Feb-18	remove large rock from tub
410984	8-Feb-18	Conduct NDT on TH663 High-Speed shaft
412065	8-Feb-18	DAILY SERVICE FOR SANDVIK TH663.
412099	8-Feb-18	Installation of the split screen radion into TR18
412077	9-Feb-18	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
412333	9-Feb-18	air con not cold enough
412334	9-Feb-18	oil leaks under truck wash and check leak repaired
412798	12-Feb-18	repair oil leak on rhs steer cyl
413194	15-Feb-18	DAILY SERVICE FOR SANDVIK TH663.
413353	15-Feb-18	replace hose for cooler fan motor.
413649	19-Feb-18	overload reset circuit breaker
413950	21-Feb-18	Reprogram TR 18 to rectifie Ch 6 issue.
413849	22-Feb-18	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
413850	22-Feb-18	DAILY SERVICE FOR SANDVIK TH663.
414089	24-Feb-18	front diff pinion seal leaking (Parts on order WM)
414816	28-Feb-18	replace both rhs windows rock came through windows
414746	1-Mar-18	DAILY SERVICE FOR SANDVIK TH663.
415244	6-Mar-18	fit fuel receiver.
415426	8-Mar-18	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
415427	8-Mar-18	DAILY SERVICE FOR SANDVIK TH663.
408018	9-Mar-18	replace hyd tank filter return switch
415241	9-Mar-18	check out low power issue. jumps between 1st and 2nd loaded.
416189	15-Mar-18	DAILY SERVICE FOR SANDVIK TH663.
416307	15-Mar-18	DPF CLEAN SANDVIK TH663
416633	16-Mar-18	tail lights out. repair ok.
416657	17-Mar-18	Replace cabin floor mat
417118	19-Mar-18	tripped circuit breaker rear box.
417219	22-Mar-18	DAILY SERVICE FOR SANDVIK TH663.
417330	22-Mar-18	check load scale operation - recalibrate
409463	24-Mar-18	Install new guards for TH663 High Speed Shaft
417231	24-Mar-18	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
417535	26-Mar-18	straighten up rhr top hand rail
417842	27-Mar-18	hyd alarm was on and over full
418014	29-Mar-18	DAILY SERVICE FOR SANDVIK TH663.
418159	29-Mar-18	Hydraulic return filter blocked
418161	29-Mar-18	Tub won't lift, check hydraulic filter wiring
418015	30-Mar-18	ENGINE CHANGE OUT SANDVIK TH663 - failed
418367	3-Apr-18	test
418370	3-Apr-18	Install Aletex DPF once rotatable items are back on site
418803	4-Apr-18	Reset circuit breakers

418371	5-Apr-18	Rotate tyres as per Tyre Report 29/03/2018
418668	5-Apr-18	DAILY SERVICE FOR SANDVIK TH663.
418828	5-Apr-18	lhs steer cyl leaking parts ordered 5/4/18
418833	5-Apr-18	replace rhs steer cyl
418885	6-Apr-18	Optimine Subscription until the end of 2018
418899	6-Apr-18	repair rhs camera
418669	7-Apr-18	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
418956	7-Apr-18	replace hyd return filter
419001	9-Apr-18	remote jacking plug u/s needs replacing
419002	9-Apr-18	replace clamp on suspension accumulator
419003	9-Apr-18	rear center drive shaft supprot bearing worn
419004	9-Apr-18	lh steer cylinder leaking
419028	9-Apr-18	Missing one wheel chock
419362	10-Apr-18	check air filter restriction (sensor playing up)
419624	11-Apr-18	replace engine air filter
419527	12-Apr-18	DAILY SERVICE FOR SANDVIK TH663.
419717	13-Apr-18	air filter restriction alarm on. sensor u/s.
419741	13-Apr-18	replace 1 x cab mounts rear
419837	15-Apr-18	clean out front window washer line
420010	16-Apr-18	sample hydraulic oil
420187	17-Apr-18	hose blown on fron axle.
420380	17-Apr-18	sample pos 3 & pos 4 final drives , inspect as per sos
420547	19-Apr-18	DAILY SERVICE FOR SANDVIK TH663.
421055	26-Apr-18	DAILY SERVICE FOR SANDVIK TH663.
421056	26-Apr-18	3000 HOUR ENGINE TUNE UP - VALVE & INJECTOR CLEARANCES,
421523	28-Apr-18	suspension dropped wont pump up tip load to get out -
421080	29-Apr-18	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
421566	1-May-18	Rear Diff U/S
421567	1-May-18	Check suspension
421599	2-May-18	REAR DIFF CHANGE OUT SANDVIK TH663
421646	2-May-18	suspension fault, suspension went down whilst loaded. bought
422058	2-May-18	all steer cylinder pins have movement.
421845	3-May-18	DAILY SERVICE FOR SANDVIK TH663.
421915	7-May-18	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
422889	10-May-18	DAILY SERVICE FOR SANDVIK TH663.
423090	10-May-18	replace pos 3 tyre sensor and inflate pos 2 tyre to correct
423112	10-May-18	fit air filters.
423726	15-May-18	oil leak - centrehitch hose
422960	17-May-18	DAILY SERVICE FOR SANDVIK TH663.
422961	18-May-18	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
424458	18-May-18	ajust a/c belts
424459	18-May-18	fit spacers to turbo mount bolts
424460	18-May-18	replace becon light
424462	18-May-18	lh steer cylinder leaking
424765	24-May-18	DAILY SERVICE FOR SANDVIK TH663.
425015	24-May-18	hyd filter restrictor fault. pin u/s on switch.
425170	27-May-18	repair hand rails.
424429	31-May-18	air filter housing needs replacing next service day

424461	31-May-18	brake release pump not working
425475	31-May-18	DAILY SERVICE FOR SANDVIK TH663.
425745	31-May-18	tranny pressure fault (no fault found)
425476	1-Jun-18	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
426050	4-Jun-18	check suspension / opperator had a score back
426339	7-Jun-18	DAILY SERVICE FOR SANDVIK TH663.
426820	8-Jun-18	low coolant alarm came on - low coolant top up @30 litres
426362	11-Jun-18	CHECK / ADJUST WHEEL BEARING PRELOAD TENSION
427271	14-Jun-18	DAILY SERVICE FOR SANDVIK TH663.
427272	15-Jun-18	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
432811	15-Jun-18	replace both starter motors
433040	18-Jun-18	a/c not working
447593	18-Jun-18	TURBO CHANGE OUT - SANDVIK TH663 - WITH NEW ENGINE ON 418015
433124	21-Jun-18	DAILY SERVICE FOR SANDVIK TH663.
426928	22-Jun-18	Fit runouts to POS 3 & POS 4, as per Tyre Report 7/06/2018
433525	22-Jun-18	Pos 2 tyre puncture
433577	24-Jun-18	any future slop in steering cylinders. frame will require
433621	24-Jun-18	refit rubber mat over batteries
433644	25-Jun-18	oil leak at steering/hoist pump compensator valve.
433760	25-Jun-18	tripped circuit breaker in centre hitch jbox.
433928	26-Jun-18	front wiper blade change out, repair wiper washers.
433933	26-Jun-18	blown hose off steering/hoist pump to pressure filter.
433963	26-Jun-18	oil leak
433823	28-Jun-18	Replace all 4 tyres
433873	28-Jun-18	DAILY SERVICE FOR SANDVIK TH663.
434112	28-Jun-18	replace blown hose in centre hitch
386370	30-Jun-18	POS 1 FINAL DRIVE CHANGE OUT SANDVIK TH663
434088	4-Jul-18	Repair trans. oil leak from control valve
434696	5-Jul-18	DAILY SERVICE FOR SANDVIK TH663.
434144	6-Jul-18	check hydraulic hoses from steering valve
435029	6-Jul-18	retarder coming on along the flat. check inclination sensor.
435095	8-Jul-18	replace reverse beeper
434717	9-Jul-18	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
435673	10-Jul-18	C/O engine oil
434718	11-Jul-18	CHECK / ADJUST WHEEL BEARING PRELOAD TENSION
434911	11-Jul-18	weld rhs handrail
435721	12-Jul-18	DAILY SERVICE FOR SANDVIK TH663.
436004	12-Jul-18	replace drivers seat belt
436045	13-Jul-18	replace rear hand rails on both sides
436073	13-Jul-18	check inclination fault - cleaned plugs
436202	16-Jul-18	replace boost hose
436569	19-Jul-18	DAILY SERVICE FOR SANDVIK TH663.
436864	20-Jul-18	oil leak on steer cly
436921	20-Jul-18	restet circuit breakers and check terminals on isolater
436993	22-Jul-18	blown main hyd hose to box hyd valve
437175	23-Jul-18	replace hose as per p/n ordered - SEE LINK
437184	23-Jul-18	repair wipers. (Waiting on parts. WM)
437197	23-Jul-18	Replace Trans filter and Transducer

437492	25-Jul-18	Repair oil leak on steer cylinder
437289	26-Jul-18	DAILY SERVICE FOR SANDVIK TH663.
437290	28-Jul-18	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
437685	29-Jul-18	replace rubbed turbo hoses
437571	2-Aug-18	SANDVIK TO CARRY OUT VCM SOFTWARE UPGRADE
438067	2-Aug-18	DAILY SERVICE FOR SANDVIK TH663.
438297	2-Aug-18	replace wiper blade on front
438349	3-Aug-18	replace rear wiper blade
438375	3-Aug-18	e/prom fault
437628	4-Aug-18	repair horn wiring
437629	4-Aug-18	repair jacking control wiring
438459	5-Aug-18	scratch out tub
438493	6-Aug-18	replace top cab mounts
437953	7-Aug-18	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
439133	9-Aug-18	DAILY SERVICE FOR SANDVIK TH663.
439134	10-Aug-18	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
439847	10-Aug-18	retarder fault
439871	10-Aug-18	tighten up rear drop box yoke
439872	10-Aug-18	retarder spool seal weeping
439873	10-Aug-18	engine oil cooler leaking coolant - WARRANTY
439876	10-Aug-18	retarder fault
440316	14-Aug-18	Stuck in 1st gear
440419	15-Aug-18	FIT X4 NEW TYRES (TYRES REMOVED FOR RUN OUT STOCK)
440261	16-Aug-18	DAILY SERVICE FOR SANDVIK TH663.
440677	20-Aug-18	test
440795	21-Aug-18	Broken rear camera mount
440974	22-Aug-18	rear tail light out. break in the wiring from front of rear
440869	23-Aug-18	DAILY SERVICE FOR SANDVIK TH663.
441125	24-Aug-18	replace rear light
441173	24-Aug-18	low level sensor on the brake tank u/s
441209	25-Aug-18	replace brake oil level sensor
441236	26-Aug-18	Repair lever on drivers seat
441266	26-Aug-18	inclometer fault
440889	27-Aug-18	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
441468	27-Aug-18	reset oil level on engine
441715	28-Aug-18	replace brake pressure filter
440890	29-Aug-18	RENEW 12 MONTHLY CUMMINS INSIGHT LICENCE
441075	30-Aug-18	send tyres out for repair
441655	30-Aug-18	DAILY SERVICE FOR SANDVIK TH663.
441929	31-Aug-18	replace rear camera mount
442021	2-Sep-18	change out a/c cab filter
442697	4-Sep-18	replace broken bolts in tub pin rhs
442791	5-Sep-18	test
442882	5-Sep-18	front step latch u/s, replace.
442664	6-Sep-18	DAILY SERVICE FOR SANDVIK TH663.
442925	6-Sep-18	start fault, battery were low on charge, jump start, alt
443045	8-Sep-18	a/c not working not blowing air
442685	10-Sep-18	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.

443281	10-Sep-18	replaced a/c cab with a longhole fan. Parts on order
443410	10-Sep-18	No 2 cylinder rocker shaft bolts broken
455694	10-Sep-18	1500hr Engine tune-up by Cummins
456232	10-Sep-18	3000 HOUR ENGINE TUNE UP - VALVE & INJECTOR CLEARANCES,
443695	12-Sep-18	Throttle pedal has a chip out of side - needs a new pedal
443491	13-Sep-18	DAILY SERVICE FOR SANDVIK TH663.
443782	13-Sep-18	blown hose on engine and oil cap onside of engine blew off
443827	14-Sep-18	blown hose from steering pressure filter to steer valve
443861	14-Sep-18	change brake pressure filter alarm coming on
443908	15-Sep-18	needs front wiper blade replaced
444181	17-Sep-18	replace front wiper blade ass
444427	19-Sep-18	check over steering etc after hitting wall.
444429	19-Sep-18	replace cabin mount, worn out.
444430	19-Sep-18	replace wiper washer motor. completed.
444440	19-Sep-18	replace cabin mount, worn out.
444353	20-Sep-18	DAILY SERVICE FOR SANDVIK TH663.
445124	26-Sep-18	engine pre lube pump not working
445191	26-Sep-18	inspect prelube pump for part numbers
444945	27-Sep-18	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
444946	27-Sep-18	DAILY SERVICE FOR SANDVIK TH663.
445229	27-Sep-18	check suspension sitting low
445258	28-Sep-18	fit new radio
445274	28-Sep-18	Adjust A/C belts
445313	30-Sep-18	Rear support bearing worn
445320	30-Sep-18	clean battery terminals - REPLACED BATTERIES
445677	1-Oct-18	check tranny fault
445688	1-Oct-18	check transmission fault
446301	4-Oct-18	DAILY SERVICE FOR SANDVIK TH663.
446630	7-Oct-18	repair front washers / not working
446692	8-Oct-18	COOLER MOTOR U/S
446701	8-Oct-18	fan motor u/s not working
446929	9-Oct-18	sample transmission oil
447076	11-Oct-18	DAILY SERVICE FOR SANDVIK TH663.
447336	11-Oct-18	C/O cab filter
447376	12-Oct-18	Retarder fault
447104	15-Oct-18	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
447801	15-Oct-18	repair tub tail wear plate, welds cracked.
448015	17-Oct-18	front wiper.
448107	17-Oct-18	fit fusion radio extension speaker.
447890	18-Oct-18	DAILY SERVICE FOR SANDVIK TH663.
448460	22-Oct-18	replace blown center hitch hose
453341	25-Oct-18	DAILY SERVICE FOR SANDVIK TH663.
453606	25-Oct-18	workorder to purchase annual subscription for
453788	26-Oct-18	scrath tub out and wash
453856	28-Oct-18	replace window washer water pump
453504	29-Oct-18	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
453390	30-Oct-18	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
454211	31-Oct-18	lh steering cylinder live end pin bolts snapped. repaired

454279	31-Oct-18	replace a/c cab filter not cold enough
454070	1-Nov-18	DAILY SERVICE FOR SANDVIK TH663.
454580	3-Nov-18	engine oil in engine bay
454588	3-Nov-18	reset rear fuse
454899	6-Nov-18	replace fast fill adaptor
455047	8-Nov-18	DAILY SERVICE FOR SANDVIK TH663.
386371	9-Nov-18	POS 2 FINAL DRIVE CHANGE OUT SANDVIK TH663
402820	9-Nov-18	DROPBOX CHANGE OUT SANDVIK TH663
402821	9-Nov-18	UPBOX CHANGE OUT FOR SANDVIK TH663
445312	9-Nov-18	Replace broken brake accumulator mounting brackets
447799	9-Nov-18	FRONT DIFF CHANGE OUT SANDVIK TH663
453602	9-Nov-18	Replace rubber mat in cabin
455365	9-Nov-18	Horn weak
455364	9-Nov-18	Headlights dull
455434	10-Nov-18	replace front wiper blade.
455915	15-Nov-18	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
455916	15-Nov-18	DAILY SERVICE FOR SANDVIK TH663.
456209	15-Nov-18	excessive movement sideways movement in dog bone
456210	15-Nov-18	replace hand rail locks on lhr hand rail
456211	15-Nov-18	replace fire extingsher
455948	19-Nov-18	6000 HYDRAULIC OIL CHANGE FOR SANDVIK TH663 TRUCK.
456407	19-Nov-18	tranny pressure high / replaced filter
456470	22-Nov-18	DAILY SERVICE FOR SANDVIK TH663.
456974	25-Nov-18	tranny pressure light on clean plug
448118	26-Nov-18	rh tub pin has broken bolts. (Parts on order)
457154	27-Nov-18	test
456818	29-Nov-18	repair e stop fault
457206	29-Nov-18	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
457207	29-Nov-18	DAILY SERVICE FOR SANDVIK TH663.
457970	1-Dec-18	fit for purpose, UIS, Checklist
458001	2-Dec-18	retorque pos 3&4
458056	3-Dec-18	test by tanya
458058	3-Dec-18	test
436039	5-Dec-18	Replace trans. filter ass. as per Sandvik Bulletin 2018-57
458558	5-Dec-18	check high engine temp
458323	6-Dec-18	DAILY SERVICE FOR SANDVIK TH663.
458578	6-Dec-18	purchase allison licence for tough book 150PC02
458599	6-Dec-18	engine over temp fault, cooling pump faulty.
458984	13-Dec-18	DAILY SERVICE FOR SANDVIK TH663.
457356	14-Dec-18	TR18 Fit 4 x new BKT tyres
459595	16-Dec-18	check transmission fault
459606	16-Dec-18	replace hand rail latches
459607	16-Dec-18	replace top cab mounts
459810	17-Dec-18	repair hand rails
460155	19-Dec-18	change out pos 4 flat tyre
459890	20-Dec-18	DAILY SERVICE FOR SANDVIK TH663.
460404	21-Dec-18	Check tyre pressure sensor
459916	23-Dec-18	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.

460885	24-Dec-18	a/c fault. frozen up evaporator. defrost and send back to
460967	26-Dec-18	a/c fault compressor u/s. compressor constantly powered up.
459917	27-Dec-18	UNI JOINT COMPONENT CHANGE OUT
460358	27-Dec-18	DAILY SERVICE FOR SANDVIK TH663.
461000	27-Dec-18	a/c clutch powered up constantly
461056	28-Dec-18	air con not working lost all gas
461193	31-Dec-18	trans fault / blocked filter
461508	1-Jan-19	check drive line centre baerings
461561	3-Jan-19	DAILY SERVICE FOR SANDVIK TH663.
461945	3-Jan-19	Measure rear drive shaft support bearing for wear
462575	9-Jan-19	Check ac. Filter blocked. Iced up
462379	10-Jan-19	DAILY SERVICE FOR SANDVIK TH663.
462535	10-Jan-19	Connect up the flow switches on the Phx 4110 heat exchangers
462380	11-Jan-19	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
462718	12-Jan-19	A/C not working
462804	14-Jan-19	Engine sump leaking
462970	14-Jan-19	check engine oil level / cracked sump
463034	17-Jan-19	DAILY SERVICE FOR SANDVIK TH663.
463780	19-Jan-19	engine overheating
463813	20-Jan-19	Air filter housing needs replacing
463820	20-Jan-19	Re-fit muffler mounting straps
464018	21-Jan-19	cracked engine sump.
464020	21-Jan-19	front wipers seized, free up.
464149	22-Jan-19	tranny fault.
464225	23-Jan-19	sample transmission oil
464091	24-Jan-19	DAILY SERVICE FOR SANDVIK TH663.
464350	24-Jan-19	Optimine Subscription
464369	24-Jan-19	check hydraulic pumps on pto are not leaking hydraulic oil
464400	24-Jan-19	hyd return filter fault- spring missing
464472	25-Jan-19	replace blown hose
464928	29-Jan-19	replace after cooler gasket
464953	29-Jan-19	replace tranny filter
464120	30-Jan-19	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
464746	31-Jan-19	DAILY SERVICE FOR SANDVIK TH663.
465318	2-Feb-19	fuel fill issue, quick fill turning off straight away when
465326	2-Feb-19	rear circuit breaker tripped.
465557	4-Feb-19	check new radios if speakers working ok and install new
465854	5-Feb-19	replace rh side wiper motor and am/fm radio.
465176	7-Feb-19	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
465631	7-Feb-19	DAILY SERVICE FOR SANDVIK TH663.
466239	10-Feb-19	replace trans filter
466727	11-Feb-19	replace quick fill nozzle
466728	11-Feb-19	replace isolator
466737	11-Feb-19	repair fuel leak
466902	12-Feb-19	air con not cold
465946	13-Feb-19	replace brake flush & brake charge pump
466825	13-Feb-19	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
467055	13-Feb-19	truck damage replace corner window and repair hand rails

466826	14-Feb-19	DAILY SERVICE FOR SANDVIK TH663.
467067	14-Feb-19	Cracks in articulation pump stops to be repaired
467120	15-Feb-19	check diesel leak, spillage from fueling ok.
467830	19-Feb-19	a/c fault, filter blocked.
467832	19-Feb-19	oil leak from tranny filler. remove, clean, and refit.
468099	20-Feb-19	no cooling fans - pump u/s
467890	21-Feb-19	DAILY SERVICE FOR SANDVIK TH663.
468149	21-Feb-19	replace pos 2 tyre with run out, by rob drane
468240	22-Feb-19	replace quick fill
468264	23-Feb-19	tyre sensor oring failed, replaced sensor calibrated, ok
468630	25-Feb-19	weld up hand rails
468688	28-Feb-19	DAILY SERVICE FOR SANDVIK TH663.
469043	28-Feb-19	Over-heating adjust cooling fan pump
469059	1-Mar-19	Install radio hand piece bracket (same as TR24)
469072	1-Mar-19	replace o-ring on hose above coolant header tank. tightened
469212	1-Mar-19	Over-heating, check cooling fan pump
468724	3-Mar-19	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
469401	5-Mar-19	tranny fault, oil cold. ok.
469498	5-Mar-19	tow off wall.
469760	6-Mar-19	replace rh hand rail.
408706	7-Mar-19	Coolant Hose Re-route as per Sandvik Bulletin 2017-52
464349	7-Mar-19	Mud guard on lift cylinder missing
469454	7-Mar-19	DAILY SERVICE FOR SANDVIK TH663.
469834	7-Mar-19	Welds on hand rail broken
469884	7-Mar-19	replace trans filter
469915	8-Mar-19	Order spare fan pump for TH663 trucks p.o. req app
469933	8-Mar-19	replace pos 4 tyre
469455	9-Mar-19	CHANGE SEAT BELT
468600	11-Mar-19	Inspect each TH663 for fan pump type
472686	14-Mar-19	DAILY SERVICE FOR SANDVIK TH663.
473141	16-Mar-19	TH663 TRANSMISSION CHANGE OUT - CUMMINS POWERED
473092	17-Mar-19	emergency steering pump not working.
473093	17-Mar-19	tripping c/b, front wiper motor u/s. replace.
473099	17-Mar-19	radio repairs aerial not earthing correctly.
473100	17-Mar-19	machine surging, lock up clutch fault. - TRANNY FAILURE SEE
468903	20-Mar-19	Order new hose for updated cooling fan pump
473571	20-Mar-19	door window smashed. hit wall.
473680	20-Mar-19	tranny filter check and change
473681	20-Mar-19	retorque pos 1 wheel nuts
472950	21-Mar-19	Rear drive shaft - pillow bearing worn
473396	21-Mar-19	DAILY SERVICE FOR SANDVIK TH663.
473786	21-Mar-19	tranny fault code p070d tranny level fault
473822	22-Mar-19	Replace perviously repaired join in antenna cable with
473920	23-Mar-19	replace retarder actuator
473427	24-Mar-19	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
474471	26-Mar-19	replace trans temp sensor
474521	26-Mar-19	transmission temp fault
474530	26-Mar-19	e stop fault

474717	27-Mar-19	transmission warning
474409	28-Mar-19	DAILY SERVICE FOR SANDVIK TH663.
474804	29-Mar-19	Work order for capturing costs for IP Changeover on
474865	29-Mar-19	wedged in stockpile let rear tyres down to get out
474883	30-Mar-19	front wiper fault, wiper stopping intermittently across
474928	30-Mar-19	tranny getting hot going down - change oil and filter and
475598	3-Apr-19	pos 1 tyre pressure sensor u/s.
475384	4-Apr-19	DAILY SERVICE FOR SANDVIK TH663.
469005	7-Apr-19	oil leak at steering/hoist pump compensator valve.
469329	7-Apr-19	replace engine oil filter remote lines, starting to weep.
473960	7-Apr-19	replace all hand rails / rusted and worn out
476424	7-Apr-19	check engine low power
476429	7-Apr-19	check engine overheating
476804	9-Apr-19	hyd oil getting hot
476737	11-Apr-19	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
476739	11-Apr-19	DAILY SERVICE FOR SANDVIK TH663.
477044	11-Apr-19	Truck was losing signal half way down U/G, replaced arial
477083	11-Apr-19	replace pos 3 tyre - BKT tyre and starting to split apart
477154	12-Apr-19	Engine overheating, change thermostats
477299	15-Apr-19	Replace rear driveline support bearing and bracket
477334	15-Apr-19	check out over heating issue, ran pump test, fan speeds,
477366	15-Apr-19	check excessive suspension dog bone wear.
477670	18-Apr-19	DAILY SERVICE FOR SANDVIK TH663.
477929	18-Apr-19	replace turbo hose clamp
478102	21-Apr-19	No upshift when loaded
478120	22-Apr-19	wont up shift loaded
478134	22-Apr-19	engine running hot
478698	24-Apr-19	Low power - check boost leaks
478502	25-Apr-19	DAILY SERVICE FOR SANDVIK TH663.
478719	25-Apr-19	replace the engine temp sensor.
478784	26-Apr-19	emergency steering pump not working.
478904	27-Apr-19	inspect rear drive shaft centre bearings for excessive
479319	30-Apr-19	grease injector parts and fittings - as per Ian Tonkin
479499	30-Apr-19	replace rear wiper motor. u/s.
479665	1-May-19	oil leak around pto. change o-ring on cooler hose fitting.
479380	2-May-19	DAILY SERVICE FOR SANDVIK TH663.
479734	2-May-19	replace pos 3 & 4 tyre sensors
479910	5-May-19	cracked door window
479911	5-May-19	check coolant leak
479472	7-May-19	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
480719	7-May-19	replace blocked a/c filter
480667	8-May-19	CHECK / ADJUST WHEEL BEARING PRELOAD TENSION - FRONT AXLE
480668	8-May-19	CHECK / ADJUST WHEEL BEARING PRELOAD TENSION - REAR AXLE
480669	9-May-19	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
480670	9-May-19	DAILY SERVICE FOR SANDVIK TH663.
480926	9-May-19	jump start
480969	9-May-19	repair broken a/c cover.
476738	9-May-19	3000 HOUR ENGINE TUNE UP - VALVE & INJECTOR CLEARANCES,

481141	10-May-19	repair oil leak on dump/steer pump. o-ring u/s on plug.
481197	11-May-19	engine overheating. intercooler radiator pack blocked up
481672	13-May-19	engine reported as overheating. checked intercooler
481770	16-May-19	DAILY SERVICE FOR SANDVIK TH663.
482028	16-May-19	repair a/c bracket
481002	17-May-19	Pos 4 tyre worn out
481720	21-May-19	Center engine breather leaking
482515	21-May-19	check software fault - nothing found
482584	22-May-19	check operator seat wont move sideways
482416	23-May-19	DAILY SERVICE FOR SANDVIK TH663.
480988	24-May-19	Coolant leak from head gasket NO. 1
483207	27-May-19	Retarder output temp high 145.c
483221	27-May-19	Low engine power reported
483626	29-May-19	no start fault.
483671	29-May-19	Trans oil leak from from control valve body
483290	30-May-19	DAILY SERVICE FOR SANDVIK TH663.
483855	30-May-19	quick fill oh fuel tank not working
483896	31-May-19	check a/c fault - replace a/c filter
484019	2-Jun-19	check transmission fault - nothing found
484042	2-Jun-19	truck over heating coming up decline
484046	2-Jun-19	check engine over heating har expo
484088	3-Jun-19	check software faults - cleared & nothing found
484341	4-Jun-19	a/c compressor seized
484342	4-Jun-19	replace air con filter
484254	5-Jun-19	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
484255	6-Jun-19	DAILY SERVICE FOR SANDVIK TH663.
484853	7-Jun-19	Replace transmission breather
484977	9-Jun-19	a/c fault, evaporator iced up. happened twice during the
484982	9-Jun-19	blown rear fuse.
484157	11-Jun-19	replace all cab mounts and mount bolts
484307	12-Jun-19	4 X TYRES
485832	12-Jun-19	REPLACE #1 HEADGASKET
485556	13-Jun-19	DAILY SERVICE FOR SANDVIK TH663.
486193	15-Jun-19	reset rear fuse
485835	19-Jun-19	TH663 TURBO CHANGE OUT - CUMMINS
486524	20-Jun-19	DAILY SERVICE FOR SANDVIK TH663.
486804	20-Jun-19	wont select gears. tranny temp reading negative.
486914	22-Jun-19	remote fault and ecm codes.
486918	22-Jun-19	not grabbing second gear. retarding on flat at high revs.
487161	24-Jun-19	a/c frozen.
487162	24-Jun-19	seat back adjustment u/s, change out seat.
487163	24-Jun-19	engine oil leak.
487354	25-Jun-19	straighten hand rail.
487509	25-Jun-19	A/C freezing up
487608	26-Jun-19	tranny filter blocked alarm. change filter.
487610	26-Jun-19	a/c fault. power to compressor clutch constantly from
487436	27-Jun-19	DAILY SERVICE FOR SANDVIK TH663.
487699	27-Jun-19	check retarder operation

487945	29-Jun-19	blown hose
487978	30-Jun-19	replace blown hose on hyd tank
488123	1-Jul-19	check lockup
488313	3-Jul-19	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
488535	3-Jul-19	replace damaged camera and light on rhs
488314	4-Jul-19	DAILY SERVICE FOR SANDVIK TH663.
488611	4-Jul-19	LH Steer cyl. live end broken cap bolts
488690	5-Jul-19	pos 1 mud flap rubbing on tyre.
488708	6-Jul-19	Pos 1 inner guard rubbing
489345	9-Jul-19	yellow alarm hyd oil filter blockage.
489422	10-Jul-19	Hazard card put in by Diamond drills that NO2 monitor goes
489269	11-Jul-19	DAILY SERVICE FOR SANDVIK TH663.
489619	12-Jul-19	replace horns
489625	12-Jul-19	lh load pin / retarder fault
489688	13-Jul-19	replace pump mounting orings
489726	13-Jul-19	replace hyd filter pressure switch
489772	14-Jul-19	tranny fault ??? - no start lost power
488832	15-Jul-19	INSPECT AND REPORT WHICH CUMMINS POWERED
490143	16-Jul-19	trans filter blocked replace filter
490146	16-Jul-19	replace damaged side window
490198	18-Jul-19	DAILY SERVICE FOR SANDVIK TH663.
490224	21-Jul-19	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
490917	23-Jul-19	VCM Screen return / button 1 not working
491031	25-Jul-19	DAILY SERVICE FOR SANDVIK TH663.
491395	27-Jul-19	trans filter blockage light on
491706	1-Aug-19	DAILY SERVICE FOR SANDVIK TH663.
492264	3-Aug-19	Load cell error alarm active
492829	6-Aug-19	Trans filter blocked, trans pressure high error
492864	6-Aug-19	pos 4 tyre pressure sensor high alarm.
491806	7-Aug-19	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
492788	7-Aug-19	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
492789	8-Aug-19	DAILY SERVICE FOR SANDVIK TH663.
493116	8-Aug-19	rear tub pins have 5/10 mm of movment
493117	8-Aug-19	rear window cracked
493119	8-Aug-19	front diff pinion seal leaking
493140	8-Aug-19	dropbox cooler leaking oil
492212	9-Aug-19	Weld lug under tub to support come-a-long & sling
493212	10-Aug-19	replace split dropbox cooler
494130	14-Aug-19	re-callibrate tyre sensors
493900	15-Aug-19	DAILY SERVICE FOR SANDVIK TH663.
494373	18-Aug-19	coolant leak from 1 and 2 head/rocker box water tube.
494399	18-Aug-19	rh tub pin bolts loose and snapped. replace bolts.
494545	19-Aug-19	remove broken bolt from rh tub hinge pin. fit new bolts.
494599	20-Aug-19	replace rear window. cracked.
494860	21-Aug-19	jump start, test batteries.
494678	22-Aug-19	DAILY SERVICE FOR SANDVIK TH663.
495106	24-Aug-19	replace a/c filter
495180	25-Aug-19	help tr18 tip its load at saddle / was over loaded 75 ton

495397	26-Aug-19	reset rear fuse
495887	29-Aug-19	DAILY SERVICE FOR SANDVIK TH663.
496280	29-Aug-19	workorder to purchase annual subscription for
496406	31-Aug-19	Trans filter restriction
495917	1-Sep-19	250 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK.
493316	2-Sep-19	Repair tub sides and install wear bar package
494743	3-Sep-19	Sandvik to inspect weighing system
496575	3-Sep-19	Batteries u/s
496577	3-Sep-19	Replace cab mounts
496781	3-Sep-19	Trans selection fault
496232	4-Sep-19	check seat belt
496884	4-Sep-19	Replace LH steer hose
496892	4-Sep-19	WASH FOR TRANSPORT TO ORANGE
496737	5-Sep-19	DAILY SERVICE FOR SANDVIK TH663.
497065	6-Sep-19	check seat operation
497184	8-Sep-19	Replace missing emergency glass hammer
497213	8-Sep-19	check drivers seat for sharp edges
498765	16-Sep-19	TH663 TRANSMISSION CHANGE OUT - CUMMINS POWERED
497059	20-Sep-19	weld up steering stop on lhs / cracked
500098	24-Sep-19	Send hand rails & fuel tank to Sandvik, Orange (see history)
501319	2-Oct-19	Safety Bulletin 2019-41 - Fuse Box Cover Opening
501754	7-Oct-19	WO to capture costs associated with B19UG05H
506325	7-Nov-19	DAILY SERVICE FOR SANDVIK TH663.
507000	7-Nov-19	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
514724	7-Nov-19	REAR DIFF CHANGE OUT SANDVIK TH663
506523	8-Nov-19	TURBO CHANGE OUT - SANDVIK TH663 VOLVO ENGINE
506524	8-Nov-19	UPBOX CHANGE OUT FOR SANDVIK TH663 - VOLVO POWERED
506525	8-Nov-19	ENGINE CHANGE OUT SANDVIK TH663 - VOLVO POWERED
506528	8-Nov-19	DPF CLEAN SANDVIK TH663 - VOLVO ENGINE
506529	8-Nov-19	UNI JOINT COMPONENT CHANGE OUT
506531	8-Nov-19	TH663 TRANSMISSION CHANGE OUT - VOLVO POWERED
506026	9-Nov-19	CARRY OUT FIT FOR PURPOSE / UIS
506618	10-Nov-19	replace retarder actuator.
506663	11-Nov-19	125 HR SERVICE - CHANGE OIL IN WHEEL ENDS AND DIFFS
506664	11-Nov-19	First 250hr Service - Replace upbox and dropbox oil
506665	11-Nov-19	PREFORM 50HR SERVICE FROM REBUILD
506668	11-Nov-19	DPF CLEAN SANDVIK TH663 - VOLVO ENGINE
506669	11-Nov-19	ADJUST VALVE CLEARANCE - ENGINE
506944	11-Nov-19	CHANGE QUICK FILL FITTINGS READY FOR CASTORL OILS UPGRADE
506946	11-Nov-19	a/c leak on condensor fittings loose. evacuate repair and
506969	11-Nov-19	Low drop box oil fault
506971	11-Nov-19	Check a/c
507117	12-Nov-19	Blocked brake filter
507049	14-Nov-19	DAILY SERVICE FOR SANDVIK TH663.
507340	14-Nov-19	brake filter light coming on - replaced pressure switch
507370	14-Nov-19	replace door strut
507371	14-Nov-19	retorque all wheels
507373	14-Nov-19	check a/c operation

507375	14-Nov-19	weld up steering stops both sides
507520	15-Nov-19	check oil leak ???
507639	17-Nov-19	dpf lights on ???
507660	17-Nov-19	dpf temp low out of range
506666	18-Nov-19	AFTER 500 HRS CLEAN DPF SYSTEM FILTER
507215	20-Nov-19	replace heater tap valve. u/s not adjusting correctly.
507995	20-Nov-19	a/c u/s - replace compressor
507835	21-Nov-19	DAILY SERVICE FOR SANDVIK TH663.
508140	21-Nov-19	check exhaust system fault
508578	25-Nov-19	replace a/c filter.
508583	25-Nov-19	low drop box oil pressure alarm. suction hose on pump loose.
508696	28-Nov-19	DAILY SERVICE FOR SANDVIK TH663.
509032	28-Nov-19	Blown R/H lift o'ring
508730	3-Dec-19	250 HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
509511	3-Dec-19	replace rear tail light
509571	5-Dec-19	DAILY SERVICE FOR SANDVIK TH663.
510164	5-Dec-19	check machine stability.
510203	6-Dec-19	replace rear window cracked.
510206	6-Dec-19	CHECK / ADJUST WHEEL BEARING PRELOAD TENSION - FRONT AXLE
510207	6-Dec-19	CHECK / ADJUST WHEEL BEARING PRELOAD TENSION - REAR AXLE
510208	6-Dec-19	3000 HOUR ENGINE TUNE UP - VALVE & INJECTOR CLEARANCES,
510255	7-Dec-19	boost hose blown off intercooler. replace clamp.
509666	8-Dec-19	Rotate tyres. P1 & P4 - P2 & P3
510316	8-Dec-19	clean out tub.
510359	9-Dec-19	TH663 TRANSMISSION CHANGE OUT - VOLVO POWERED
510484	9-Dec-19	dpf alarm, dpf damaged on vcm.
510486	9-Dec-19	tranny fault alarm, level alarm. tranny oil level overfull.
510524	9-Dec-19	Low oil level sensor fault
510867	11-Dec-19	Check retarder
510601	12-Dec-19	DAILY SERVICE FOR SANDVIK TH663.
511124	12-Dec-19	check suspension
511386	14-Dec-19	Check suspension
511413	14-Dec-19	Replace pos 1 tyre
511414	14-Dec-19	Replace cab filter
511535	16-Dec-19	Check scales
511540	16-Dec-19	check air intake system as per bad sos
510638	18-Dec-19	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
511938	18-Dec-19	sample engine oil change filters and oil
511668	19-Dec-19	DAILY SERVICE FOR SANDVIK TH663.
511988	19-Dec-19	stuck on wall
512000	19-Dec-19	crankcase pressure fault alarm.
512119	20-Dec-19	window seal refit top corner
512178	21-Dec-19	Check brake release pressure, check for burnt oil
511725	24-Dec-19	fit new horn
511726	24-Dec-19	replace brake oil - burnt
512442	26-Dec-19	DAILY SERVICE FOR SANDVIK TH663.
513083	27-Dec-19	re-set circuit breaker
513176	29-Dec-19	repaired aircleaner housing on daily

513607	31-Dec-19	retarder fault, calibrate inclinometer, new part on order
513787	1-Jan-20	Blocked brake return filter
513515	2-Jan-20	DAILY SERVICE FOR SANDVIK TH663.
513516	2-Jan-20	250 HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
514153	3-Jan-20	Replace side window
514463	7-Jan-20	Re-sample Hydraulics - FOLLOW CORRECT SAMPLE PROCEDURES
514606	7-Jan-20	replace front light
514700	8-Jan-20	Check tyre pressures
514729	8-Jan-20	Re-sample POS 2 - RED SAMPLE
514535	9-Jan-20	DAILY SERVICE FOR SANDVIK TH663.
514881	9-Jan-20	Check operation of tyre pressure transducers
514901	9-Jan-20	tyre sensors not working
515553	13-Jan-20	Bent handrails
515601	13-Jan-20	air con not cold
515695	16-Jan-20	DAILY SERVICE FOR SANDVIK TH663.
515696	17-Jan-20	3000 HOUR ENGINE TUNE UP - VALVE & INJECTOR CLEARANCES,
515697	17-Jan-20	CHECK / ADJUST WHEEL BEARING PRELOAD TENSION - FRONT AXLE
515698	17-Jan-20	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
515699	17-Jan-20	CHECK / ADJUST WHEEL BEARING PRELOAD TENSION - REAR AXLE
516125	18-Jan-20	no jack leg movements. ls valve jammed.
516559	23-Jan-20	DAILY SERVICE FOR SANDVIK TH663.
517241	30-Jan-20	Install and trial updated tyre pressure sensors.
517621	30-Jan-20	DAILY SERVICE FOR SANDVIK TH663.
518189	30-Jan-20	replace rh side window.
518379	1-Feb-20	seat wont adjust as broken cable mount - repaired
518452	2-Feb-20	emergency steer engaging
518454	2-Feb-20	over boost fault - check turbo acuator
515017	4-Feb-20	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
517674	4-Feb-20	250 HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
518984	5-Feb-20	puncture pos 4. drill steel through tyre.
518063	6-Feb-20	DAILY SERVICE FOR SANDVIK TH663.
519127	6-Feb-20	replace a/c cab filter
519263	8-Feb-20	scratch tub out & reset scales
519393	11-Feb-20	Sandvik to install trans control software
519976	13-Feb-20	DAILY SERVICE FOR SANDVIK TH663.
520556	14-Feb-20	scales not reading correctly. float coil u/s.
520557	14-Feb-20	retarder fault, actuator u/s. replace and calibrate.
519551	17-Feb-20	Fit 4 X tyres
520157	19-Feb-20	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
520495	20-Feb-20	Remove inter axle bearing block and pillow bearing from
521181	20-Feb-20	DAILY SERVICE FOR SANDVIK TH663.
521696	23-Feb-20	repair hand rails
522134	27-Feb-20	DAILY SERVICE FOR SANDVIK TH663.
522175	2-Mar-20	250 HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
522978	2-Mar-20	WO to capture potential engine failure - DO NOT CLOSE
523276	5-Mar-20	DAILY SERVICE FOR SANDVIK TH663.
523914	9-Mar-20	air con not cold
524393	12-Mar-20	DAILY SERVICE FOR SANDVIK TH663.

524832	13-Mar-20	blown centre hitch hose
524955	15-Mar-20	pos 4 tyre sensor.
525335	16-Mar-20	boost hose blown clamp.
524428	17-Mar-20	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
525426	19-Mar-20	DAILY SERVICE FOR SANDVIK TH663.
525852	21-Mar-20	scales not working
525881	21-Mar-20	tagged out for incident in workshop
525979	21-Mar-20	Warranty Claim Clino sensor
525904	22-Mar-20	check tub up alarm & warning system
525905	22-Mar-20	check tub and cylinders for damage
525145	23-Mar-20	Both air filter restriction lines disconnected
525146	23-Mar-20	Coolant filter missing???
526202	26-Mar-20	DAILY SERVICE FOR SANDVIK TH663.
526582	26-Mar-20	replace horn combination switch. horn not working
526876	28-Mar-20	check a/c not cold - change filter
527133	29-Mar-20	no start - reset fuse in front box
525144	30-Mar-20	S.O.S Sample ports not fitted
527157	30-Mar-20	blown hose on ore pad bay 1.
527202	30-Mar-20	retarder fault, change out actuator.
527551	1-Apr-20	250 HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
527552	2-Apr-20	DAILY SERVICE FOR SANDVIK TH663.
527615	2-Apr-20	Re-sample Transmission, Upbox, Pos 1, F. Diff and Pos 2
528625	7-Apr-20	check retarder - recalibrated
527854	9-Apr-20	engine oil filter for tr18
528581	9-Apr-20	DAILY SERVICE FOR SANDVIK TH663.
528915	10-Apr-20	operator seat compressor u/s
528977	11-Apr-20	blown boost hose clamp
529054	12-Apr-20	boost hose clamp blown.
529098	13-Apr-20	boost hose blown off.
529673	14-Apr-20	check horn operation
529274	16-Apr-20	DAILY SERVICE FOR SANDVIK TH663.
529896	16-Apr-20	pos 4 tyre
529309	20-Apr-20	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
530422	20-Apr-20	replace rh side cab window
530515	23-Apr-20	DAILY SERVICE FOR SANDVIK TH663.
531807	30-Apr-20	DAILY SERVICE FOR SANDVIK TH663.
531911	4-May-20	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
533155	6-May-20	250 HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
533156	7-May-20	DAILY SERVICE FOR SANDVIK TH663.
533629	9-May-20	a/c fault.
534155	13-May-20	check over suspension couldnt fault.
534277	14-May-20	DAILY SERVICE FOR SANDVIK TH663.
534491	14-May-20	replace hand rail
535099	19-May-20	turbo boost noise ?
535100	19-May-20	turbo boost noise ?
535035	21-May-20	DAILY SERVICE FOR SANDVIK TH663.
535400	21-May-20	check brake pedal
535432	22-May-20	operator reported brakes are spongy.

535438	22-May-20	replace brake treadle valve, worn out.
535074	25-May-20	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
535257	27-May-20	Rotate tyres P1-P4, P2-P3
535725	28-May-20	DAILY SERVICE FOR SANDVIK TH663.
537368	3-Jun-20	scrach out tub
537427	3-Jun-20	washers not working
535770	4-Jun-20	2000 HOUR ENGINE TUNE UP - VOLVO TAD1643VE ENGINE
537166	4-Jun-20	DAILY SERVICE FOR SANDVIK TH663.
538090	11-Jun-20	DAILY SERVICE FOR SANDVIK TH663.
538755	15-Jun-20	replace LHR hand rail
538909	15-Jun-20	repair cracks tub on both sides
539343	17-Jun-20	Safety Bulletin 2020-33, seat shock absorber check
539357	17-Jun-20	Check integrity of fuel hoses, refer to the attached
539051	18-Jun-20	DAILY SERVICE FOR SANDVIK TH663.
539594	19-Jun-20	front diff pinion seal leaking.
539615	19-Jun-20	Replace cab filter
539641	20-Jun-20	overheating drop box. clean out cooler, and drain oil to
539937	22-Jun-20	repaired o ring on lh steer cylinder
539331	24-Jun-20	RH Mud guard needs replacing
540394	24-Jun-20	Scales not reading correctly
540006	25-Jun-20	DAILY SERVICE FOR SANDVIK TH663.
539589	26-Jun-20	replace fuel hose from pump to head.
539593	26-Jun-20	change out 2 x rear hand rails service day.
540007	26-Jun-20	250 HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
540509	26-Jun-20	replace front diff breather
540534	26-Jun-20	dropbox temps high???
540731	29-Jun-20	Replace horns - Not loud enough
541114	30-Jun-20	Check brakes
541116	30-Jun-20	Electrical fault in ignition switch
541378	1-Jul-20	Scales intermittently working - T Tziotis
541388	1-Jul-20	door handle & grab handle rubber for all trucks
541059	2-Jul-20	DAILY SERVICE FOR SANDVIK TH663.
541666	4-Jul-20	flat tyre
541682	5-Jul-20	reverse camera display faulty. lines on lh side of screen.
541995	6-Jul-20	scales not reading correctly change out coil
542221	9-Jul-20	DAILY SERVICE FOR SANDVIK TH663.
542571	9-Jul-20	check brakes - all passed tests
542572	9-Jul-20	scratch out tub
542669	10-Jul-20	replace battery isolator
542701	10-Jul-20	replace tyre sensor
541652	11-Jul-20	Front left window seals
542222	11-Jul-20	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
543151	13-Jul-20	repair grease fault
543918	15-Jul-20	check grease fault
543574	16-Jul-20	DAILY SERVICE FOR SANDVIK TH663.
543987	16-Jul-20	check auto greaser working
544099	17-Jul-20	autogreaser fault - valve faulty need replacing
542775	19-Jul-20	Assess movement in LH lower suspension cyl pin

543607	19-Jul-20	DPF CLEAN SANDVIK TH663 - VOLVO ENGINE
544195	19-Jul-20	clean tub out
544196	19-Jul-20	replace radio aerial - got 1 from sparkies
544459	23-Jul-20	DAILY SERVICE FOR SANDVIK TH663.
544976	23-Jul-20	check grease system ???
544460	24-Jul-20	250 HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
545166	24-Jul-20	replace auto greaser
545237	25-Jul-20	amber grease pressure fault,air rated grease??
545281	26-Jul-20	refit 1/4 window
545283	26-Jul-20	replace estop
545480	27-Jul-20	Install Mobilaris hardware
545634	30-Jul-20	DAILY SERVICE FOR SANDVIK TH663.
545746	4-Aug-20	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
547497	4-Aug-20	pos 4 tyre. Old work order 529896 was closed.
547448	6-Aug-20	DAILY SERVICE FOR SANDVIK TH663.
547848	7-Aug-20	brake pressure differance
547851	7-Aug-20	replace drop box filler cap
547449	8-Aug-20	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
548021	9-Aug-20	REPLACE LEAKING HOIST PUMP COMPENSATOR HOSE
548022	9-Aug-20	REPLACE LOAD LIGHT
548023	9-Aug-20	MONITOR CENTRE BEARING REAR DRIVE SHAFT
548024	9-Aug-20	AJUSTED LH DOOR HYD TANK
547480	10-Aug-20	WHEEL REPLACEMENT SANDVIK TH663 POS 1
547481	10-Aug-20	WHEEL REPLACEMENT SANDVIK TH663 POS 2
547482	10-Aug-20	WHEEL REPLACEMENT SANDVIK TH663 POS 3
547483	10-Aug-20	WHEEL REPLACEMENT SANDVIK TH663 POS 4
548440	13-Aug-20	DAILY SERVICE FOR SANDVIK TH663.
548888	15-Aug-20	blown hose in centre hitch.
547966	16-Aug-20	replace pressure filter hosing
548980	16-Aug-20	oil leak at rhs suspension cylinder blown oring - wash truck
549140	17-Aug-20	retension all pos wheel nuts.
548514	18-Aug-20	check auto lube system
549286	20-Aug-20	DAILY SERVICE FOR SANDVIK TH663.
549287	21-Aug-20	TURBO AND STARTER MOTOR CHANGE OUT
548316	24-Aug-20	WO to capture cost to fabricate engine stand
550300	26-Aug-20	250 HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
550301	27-Aug-20	DAILY SERVICE FOR SANDVIK TH663.
550705	28-Aug-20	no start circuit breaker tripped.
550729	28-Aug-20	replace fuel / water separator - nil stock on service day
550789	29-Aug-20	replace LHS headlight
550794	29-Aug-20	replace front lhs headlight
550890	30-Aug-20	replace window washer pump
550941	31-Aug-20	replace a cooler hose - split
550960	31-Aug-20	low tranny alarm fault P070c
551431	1-Sep-20	pos 2 tyre puncture - H 4760
551651	2-Sep-20	pos 2 change out tyre matching.
551089	3-Sep-20	DAILY SERVICE FOR SANDVIK TH663.
552711	10-Sep-20	DAILY SERVICE FOR SANDVIK TH663.

552746	14-Sep-20	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
553472	14-Sep-20	refit RFID fuel id and scratch out tub
553486	15-Sep-20	lh brake accumulator low 40bar adjust to 90bar.
553741	15-Sep-20	door proximity sensor u/s.
553699	17-Sep-20	DAILY SERVICE FOR SANDVIK TH663.
554228	18-Sep-20	low grease pressure fault alarm
553193	19-Sep-20	Windscreen wiper not washing properly
554368	20-Sep-20	2way not working
554826	22-Sep-20	no start / faulty rct cap
554517	24-Sep-20	DAILY SERVICE FOR SANDVIK TH663.
555067	24-Sep-20	check scales working - recalibrate done on daily
555714	1-Oct-20	DAILY SERVICE FOR SANDVIK TH663.
555754	4-Oct-20	250 HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
555924	7-Oct-20	Service Bulletin 2020-36 IMPROVED REAR DRIVELINE
556887	8-Oct-20	DAILY SERVICE FOR SANDVIK TH663.
556538	12-Oct-20	Hyd oil leak from main imp pump, might be an "O"
556539	12-Oct-20	Engine oil leak, looks to be coming from
557988	15-Oct-20	DAILY SERVICE FOR SANDVIK TH663.
558442	15-Oct-20	repair damaged hand rail
559299	21-Oct-20	intake pressure high
559082	22-Oct-20	DAILY SERVICE FOR SANDVIK TH663.
559637	23-Oct-20	Check integrity of fuel hoses and hose burst sleeve,
559659	23-Oct-20	Broken UP BOX fill point
559672	23-Oct-20	blown fuse.
558556	24-Oct-20	Steering Knob busted
559118	25-Oct-20	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
559745	25-Oct-20	Replace rear guard lights
559747	25-Oct-20	Fit front remote diff breather
559748	25-Oct-20	Front L/H/S corner window cracked
559119	26-Oct-20	2000 HOUR ENGINE TUNE UP - VOLVO TAD1643VE ENGINE
559788	26-Oct-20	Replace radio speakers
560177	29-Oct-20	DAILY SERVICE FOR SANDVIK TH663.
559621	30-Oct-20	Steering knob broken
559622	30-Oct-20	Radio handpiece needs replacing black tape
560482	30-Oct-20	damaged top hand rail
560631	1-Nov-20	pos 4 tyre pressure high
560291	4-Nov-20	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
560924	5-Nov-20	DAILY SERVICE FOR SANDVIK TH663.
561356	5-Nov-20	Mobilaris Round 2 - BLE Adapter Kit Install
562061	6-Nov-20	boost pressure high fault.
560957	9-Nov-20	UNI JOINT COMPONENT CHANGE OUT
562462	9-Nov-20	WO to capture costs of wastegate actuators
560958	10-Nov-20	CHECK / ADJUST WHEEL BEARING PRELOAD TENSION - FRONT AXLE
560959	10-Nov-20	CHECK / ADJUST WHEEL BEARING PRELOAD TENSION - REAR AXLE
562693	11-Nov-20	check brake accumulator pressures, charge valve leaking.
561542	12-Nov-20	Handset cable damaged wires exposed.
562578	12-Nov-20	DAILY SERVICE FOR SANDVIK TH663.
563174	15-Nov-20	door handle snapped

563175	15-Nov-20	a/c u/s
562613	16-Nov-20	250 HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
563280	16-Nov-20	unblock a/c drain and replace filter
562623	17-Nov-20	Replace high speed shaft covers
563725	17-Nov-20	Replaced U/S lead for radio handpiece
563750	18-Nov-20	operator reported he Couldn't transmit out on radio, went
563660	19-Nov-20	DAILY SERVICE FOR SANDVIK TH663.
564671	24-Nov-20	drop box temp sensor u/s.
563833	25-Nov-20	Courtney to make sandvik truck trolley
564589	26-Nov-20	DAILY SERVICE FOR SANDVIK TH663.
565928	2-Dec-20	replace a/c filter
565658	3-Dec-20	DAILY SERVICE FOR SANDVIK TH663.
566012	3-Dec-20	retarder fault. rocks under actuator.
566029	3-Dec-20	Retarder fault
566811	8-Dec-20	retarder fault. relay u/s.
565696	9-Dec-20	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
567196	9-Dec-20	missing safety link pin.
566759	10-Dec-20	DAILY SERVICE FOR SANDVIK TH663.
567492	12-Dec-20	check lube fault ???
566696	15-Dec-20	tub repairs cracks rh side of tub. please plan in.
567206	16-Dec-20	Replace centre hitch link pin - unseize and lubricate
568053	17-Dec-20	DAILY SERVICE FOR SANDVIK TH663.
566880	23-Dec-20	Courtney to audit TH663's for Boily work required and damage
568313	23-Dec-20	Window washer bottle full of rocks - B West
569005	24-Dec-20	DAILY SERVICE FOR SANDVIK TH663.
569275	24-Dec-20	split exhaust manifold
569278	24-Dec-20	replace turbo boost hose
569303	24-Dec-20	slow leak pos 1 tyre ???
569347	26-Dec-20	re -fit jack donut pad
569413	28-Dec-20	replace upbox breather with one from rear container
569031	29-Dec-20	250 HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
569150	30-Dec-20	Rotate tyres P1-P4, P2-P3
569998	30-Dec-20	repair oil @ mian hoist pump
569999	30-Dec-20	repair turbo heat sheild
570003	30-Dec-20	boilys to fabricate steer lock pin
567271	31-Dec-20	Rear number needs repairing
567273	31-Dec-20	Rear of tub needs plating both sides
567274	31-Dec-20	Pos 2 mud flap plates need removing as per up date
567275	31-Dec-20	2 bonnets on top need straightening
569746	31-Dec-20	DAILY SERVICE FOR SANDVIK TH663.
570044	31-Dec-20	Check radio as it was reported as dropping out... couldnt
570133	1-Jan-21	Blown centre hitch hose
570167	2-Jan-21	replace front step. bent.
570181	2-Jan-21	Replace front wiper blade
570146	2-Jan-21	NEEDS WIPER BLADES
570195	3-Jan-21	check radio operation, ok.
571165	6-Jan-21	check scale operation, operator brought up fluctuating.
570999	7-Jan-21	DAILY SERVICE FOR SANDVIK TH663.

571546	11-Jan-21	blown rear fuse
571145	13-Jan-21	rh brake light not working.
572098	14-Jan-21	DAILY SERVICE FOR SANDVIK TH663.
572439	14-Jan-21	Replace damaged handrail
572659	17-Jan-21	radio hand piece u/s.
572704	18-Jan-21	Low power
573022	18-Jan-21	low power and overheating
572160	19-Jan-21	Action SOS results attached
573123	20-Jan-21	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
573124	21-Jan-21	DAILY SERVICE FOR SANDVIK TH663.
575079	26-Jan-21	not starting
574968	28-Jan-21	DAILY SERVICE FOR SANDVIK TH663.
574969	29-Jan-21	6000 HYDRAULIC OIL CHANGE FOR SANDVIK TH663 TRUCK.
575435	30-Jan-21	water pump u/s, threw belts off, pulley walking off shaft.
575675	1-Feb-21	auto greaser fault.
574823	2-Feb-21	replace rear center bearing
574916	2-Feb-21	check rear centre bearing
576241	3-Feb-21	door proximity fault, 24v power dropping out.
575631	4-Feb-21	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
575272	4-Feb-21	Windscreen washer nozzles blocked
575273	4-Feb-21	Reservoir has rocks in it
575991	4-Feb-21	DAILY SERVICE FOR SANDVIK TH663.
575992	6-Feb-21	250 HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
576535	6-Feb-21	pos 1 tyre sensor
576626	7-Feb-21	Replace front step
576709	7-Feb-21	REPLACE UPPER CAB MOUNTS
576659	8-Feb-21	tyre sensor fault ???
577534	10-Feb-21	retarder not working correctly
576802	11-Feb-21	DAILY SERVICE FOR SANDVIK TH663.
578087	16-Feb-21	E-stop fault center hitch
578034	18-Feb-21	DAILY SERVICE FOR SANDVIK TH663.
578070	24-Feb-21	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
578384	25-Feb-21	unblocked front washers
578797	25-Feb-21	DAILY SERVICE FOR SANDVIK TH663.
579643	26-Feb-21	blown hose top of hyd tank.
579740	27-Feb-21	Check A/C
579373	3-Mar-21	cab floor bubbled up needs new rubber floor
580072	4-Mar-21	DAILY SERVICE FOR SANDVIK TH663.
580918	7-Mar-21	repair jackleg fault
581044	9-Mar-21	replace 2 x front lights
580421	11-Mar-21	repair cracks in tub both sides near lift cylinders
581220	11-Mar-21	DAILY SERVICE FOR SANDVIK TH663.
581264	15-Mar-21	250 HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
582001	15-Mar-21	Replace engine dipstick
582261	18-Mar-21	DAILY SERVICE FOR SANDVIK TH663.
582302	21-Mar-21	DPF CLEAN SANDVIK TH663 - VOLVO ENGINE
583976	24-Mar-21	replace front wiper blade
582829	25-Mar-21	Broken right arm rest

583529	25-Mar-21	DAILY SERVICE FOR SANDVIK TH663.
584001	25-Mar-21	replace batteries, starting to get down.
582920	26-Mar-21	replace exahust y piece
584164	27-Mar-21	tranny fault. p2736, p2738, p2684.
584744	30-Mar-21	replace dipstick snapped.
584752	30-Mar-21	crankshaft shaft sensor fault. check sensor and plug.
583854	31-Mar-21	Mobilaris speed Upgrade
584946	31-Mar-21	Crank position sensor fault
584662	1-Apr-21	DAILY SERVICE FOR SANDVIK TH663.
585110	2-Apr-21	blown rear fuse
584178	3-Apr-21	rh arm rest broken.
585133	3-Apr-21	tranny fault ??? - NO LABOUR
584703	6-Apr-21	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
586183	6-Apr-21	check retarder fault
586116	8-Apr-21	DAILY SERVICE FOR SANDVIK TH663.
586462	8-Apr-21	check a/c opperation.
586639	11-Apr-21	front camera gone out
587181	12-Apr-21	Grease fault. Pot empty
586427	15-Apr-21	Change brake flushing filter and fuel filter when in stock
587251	15-Apr-21	DAILY SERVICE FOR SANDVIK TH663.
587810	17-Apr-21	Replace L/H quarter window seal
587291	21-Apr-21	250 HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
589195	21-Apr-21	A/C not getting cold
589245	21-Apr-21	Fuel pressure alarm comming up
589054	22-Apr-21	DAILY SERVICE FOR SANDVIK TH663.
589435	23-Apr-21	Broken handrails
589574	25-Apr-21	Alt charge fault
589128	27-Apr-21	replace hoses at up box
589129	27-Apr-21	scratch out tub and reset scales
589132	27-Apr-21	REAR TUB PINS REQUIRE SHIMS
589830	27-Apr-21	Side camera fault
587458	28-Apr-21	Change out 4 tyres
590182	28-Apr-21	Re-set rear fuse
589880	29-Apr-21	DAILY SERVICE FOR SANDVIK TH663.
590220	29-Apr-21	Check scales
590224	29-Apr-21	replace access door latch
589462	30-Apr-21	Check Upbox for possible poor SOS result
590483	30-Apr-21	replace fan cooler hose
590571	1-May-21	a/c compressier siezed
589366	4-May-21	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
591209	5-May-21	turbo boost fault
590216	6-May-21	No mobilaris screen - H Symes
590856	6-May-21	DAILY SERVICE FOR SANDVIK TH663.
591267	6-May-21	E-stop fault
590857	7-May-21	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
591458	9-May-21	Retarder oil leak
591470	9-May-21	Check A/C
590695	10-May-21	Check movement at speed shaft??

590892	12-May-21	POS 3 FINAL DRIVE CHANGE OUT SANDVIK TH663
590893	12-May-21	POS 4 FINAL DRIVE CHANGE OUT SANDVIK TH663
592879	12-May-21	POS 3 FINAL DRIVE CHANGE OUT SANDVIK TH663
592880	12-May-21	POS 4 FINAL DRIVE CHANGE OUT SANDVIK TH663
592022	13-May-21	DAILY SERVICE FOR SANDVIK TH663.
592672	15-May-21	repair horn wiring
591457	16-May-21	Oil leak at back of engine (monitor)
591459	16-May-21	Rear door/cover damaged
591460	16-May-21	POS 1 - wheel cover bent- leave or replace?
591461	16-May-21	UP BOX output shaft splines worn
592736	16-May-21	check engine alarm - cam & crack sensors
592998	18-May-21	not starting
593262	19-May-21	check scales
592924	20-May-21	DAILY SERVICE FOR SANDVIK TH663.
593354	21-May-21	up box out put flange loose on shaft.
592958	22-May-21	250 HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
592776	24-May-21	auto greaser over greasing
593917	25-May-21	p2684 fault code. replace tranny harness.
593944	26-May-21	No start. Crank angle sensor fault ??
593844	27-May-21	DAILY SERVICE FOR SANDVIK TH663.
594144	27-May-21	engine wiring harness needs replacing
593481	30-May-21	RHS side bottom suspension pin has movement in a-frame.
593483	30-May-21	oil leak around fuel pump.
593888	1-Jun-21	Carry out repairs as per Safety Bulletin B000066 2021-05-14
593901	1-Jun-21	Carry out repairs as per Safety Bulletin B000064 2021-05-12
592256	2-Jun-21	Mobilaris - re-mount tablet
595404	2-Jun-21	check scales
595115	3-Jun-21	DAILY SERVICE FOR SANDVIK TH663.
595614	4-Jun-21	tranny fault. gear shift selector missing.
595683	5-Jun-21	ignition fault.
593587	7-Jun-21	SOS - HIGH CONTAMINATION AND WEAR - UPBOX
596006	7-Jun-21	Replace tub coil
596177	7-Jun-21	drop box alarm.
596251	10-Jun-21	DAILY SERVICE FOR SANDVIK TH663.
596801	11-Jun-21	check for rocker cover oil leaks after fire incident
596285	14-Jun-21	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
597071	14-Jun-21	check throttle pedal
597873	15-Jun-21	replace dropbox temp sensor
598122	16-Jun-21	side camera u/s & unblock window washers
598123	16-Jun-21	check retarder fault
597365	17-Jun-21	DAILY SERVICE FOR SANDVIK TH663.
597006	21-Jun-21	tranny cooler hose orings @retarder weeping need replacement
597007	21-Jun-21	centre hitch starting to wear - Adjust
597008	21-Jun-21	tub support pins & bushers need doing
598832	22-Jun-21	Boost fault
598869	23-Jun-21	missing fuel cap
599133	23-Jun-21	No grease
598685	24-Jun-21	DAILY SERVICE FOR SANDVIK TH663.

599273	25-Jun-21	check engine oil leak
598723	27-Jun-21	TURBO AND STARTER MOTOR CHANGE OUT
599417	27-Jun-21	repair side camera & reset rear fuse
599418	27-Jun-21	replace oring on brake tank filter - damaged oring
599473	28-Jun-21	replace exhaust lagging with turbo change out
599645	28-Jun-21	hose from turbo cover to cooler needs replacing
598735	29-Jun-21	replace engine oil and filters
600030	29-Jun-21	replace blown coolant hose
600031	29-Jun-21	repair auto return fault & replace leaking valve
598004	30-Jun-21	Repair damage to front corner of tub
598724	30-Jun-21	250 HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
599174	1-Jul-21	SOS - HIGH CONTAMINATION - HYDRAULIC SYSTEM
599176	1-Jul-21	SOS - HIGH PQ & EXCESSIVE MAGNETIC DEBRI - TRANSMISSION
599943	1-Jul-21	DAILY SERVICE FOR SANDVIK TH663.
600368	2-Jul-21	Front side camera not working
601046	5-Jul-21	R/H arm rest faulty
601082	5-Jul-21	cab mounts tighten.
601153	8-Jul-21	DAILY SERVICE FOR SANDVIK TH663.
601767	8-Jul-21	Oil leak at brake tank
602623	14-Jul-21	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
602624	15-Jul-21	DAILY SERVICE FOR SANDVIK TH663.
603881	16-Jul-21	replace down coil on pos 3 jack leg.
603897	16-Jul-21	Engine fault P2684
601882	17-Jul-21	tub repairs on rear & rhs of tub
601893	17-Jul-21	Mobilaris screen small crack
601896	17-Jul-21	Comms speaker is U/S - M Elstan
604006	18-Jul-21	P2684 tranny fault
602022	19-Jul-21	replace cab mounts next service day
602469	19-Jul-21	rear fuse alarm on / repaired wiring to breaker
602571	20-Jul-21	replace grease injector in center hitch
604282	22-Jul-21	DAILY SERVICE FOR SANDVIK TH663.
605483	27-Jul-21	replace blown coolant hose
605219	29-Jul-21	DAILY SERVICE FOR SANDVIK TH663.
605341	1-Aug-21	250 HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
604968	2-Aug-21	Scales not weighing correctly
605486	3-Aug-21	Rotat tyres: P1 - P4 & P2 - P3
605342	4-Aug-21	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
605609	4-Aug-21	Check condition and serviceability of all wheel chocks and
607024	4-Aug-21	Rear fuse blown
607092	4-Aug-21	p0176 tranny fault turbine speed sensor.
606334	5-Aug-21	DAILY SERVICE FOR SANDVIK TH663.
607273	7-Aug-21	check scales, SCATCHED OUT TUB, RESET SCALES
607285	7-Aug-21	brake hose blown front dif
607324	7-Aug-21	check tranny sensor fault
607351	8-Aug-21	TRANNNY FAULT?
606198	9-Aug-21	Dog bone bushes U/S
608015	10-Aug-21	up box oil level fault, scale fault & washer motor not worki
608188	11-Aug-21	check truck after hitting comms box underground

608191	11-Aug-21	pos 2 tyre
607924	12-Aug-21	DAILY SERVICE FOR SANDVIK TH663.
607219	13-Aug-21	UPBOX SENSOR FAULT
608918	17-Aug-21	repair oil leak from harness grommet going into head.
608872	19-Aug-21	DAILY SERVICE FOR SANDVIK TH663.
608873	19-Aug-21	1000 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
608358	20-Aug-21	replace up box dipstick tube.
609344	20-Aug-21	replace pos 4 tyre
608589	21-Aug-21	grease block in centre hitch u/s, corroded.
608917	24-Aug-21	oil leak from injector wiring harness going into head.
608789	24-Aug-21	Window spray not working everytime
609730	26-Aug-21	DAILY SERVICE FOR SANDVIK TH663.
610086	27-Aug-21	Turbo cooler pipe
610781	30-Aug-21	washer bottle leaking.
610782	30-Aug-21	tranny fault.
610923	31-Aug-21	check seat
610869	2-Sep-21	DAILY SERVICE FOR SANDVIK TH663.
610870	4-Sep-21	CHECK / ADJUST WHEEL BEARING PRELOAD TENSION - FRONT AXLE
610871	4-Sep-21	CHECK / ADJUST WHEEL BEARING PRELOAD TENSION - REAR AXLE
611525	4-Sep-21	check engine oil pressure fault ???
611530	4-Sep-21	repair coolant leak on tranny cooler
610913	5-Sep-21	250 HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
611554	5-Sep-21	retarder actuator needs replacing waiting on parts today
612033	7-Sep-21	fit mobilaris charge cable
612057	7-Sep-21	ignition dropping out when driving ???
611164	8-Sep-21	Engine air intake - check system for leaks - high PQ, Iron
611956	9-Sep-21	DAILY SERVICE FOR SANDVIK TH663.
612444	11-Sep-21	Front wipers not working
611531	12-Sep-21	Tranny hose beside pumps to bottom of tranny weeping
612535	12-Sep-21	Coolant hose U/S
613121	15-Sep-21	Drop box temp fault
612307	16-Sep-21	top bracket broken on LHS and RHS suspension accumulator.
612833	16-Sep-21	DAILY SERVICE FOR SANDVIK TH663.
613162	16-Sep-21	replace tub pin bolts
614627	20-Sep-21	check retarder ???
614630	20-Sep-21	retorque pos 1 & 2
615091	22-Sep-21	repair rct fuel cap wiring
615117	22-Sep-21	check engine & tranny fault ???
613160	23-Sep-21	rhs cab window cracked
614889	23-Sep-21	DAILY SERVICE FOR SANDVIK TH663.
614267	24-Sep-21	scratch out tub
615944	28-Sep-21	500 ENGINE HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
616133	28-Sep-21	UHF radio not working
616375	29-Sep-21	clean out tub
616434	29-Sep-21	check cabin mounts.
615945	30-Sep-21	DAILY SERVICE FOR SANDVIK TH663.
616537	30-Sep-21	scratch out tubs
616578	1-Oct-21	Install M1 lock on manually operated fuel cap

616157	2-Oct-21	Fit 4 New Tyres
616647	2-Oct-21	engine not cranking
616747	3-Oct-21	not starting at fuel bay
617105	7-Oct-21	DAILY SERVICE FOR SANDVIK TH663.
616646	9-Oct-21	replace starter motor
617633	9-Oct-21	Rear fuse fault
617358	13-Oct-21	Inspect Upbox Seals, breather, sensors and casings
617479	14-Oct-21	tranny valve body leaking.
618238	14-Oct-21	DAILY SERVICE FOR SANDVIK TH663.
617605	16-Oct-21	rh front marker light out.
618274	18-Oct-21	250 HOUR SERVICE FOR SANDVIK TH663 TRUCK VOLVO ENG.
619207	18-Oct-21	no start at fuel bay
619991	19-Oct-21	replace coolant leak on engine
617463	21-Oct-21	Remove 5th gear
619910	21-Oct-21	DAILY SERVICE FOR SANDVIK TH663.
620359	22-Oct-21	Check seat
620417	23-Oct-21	Low coolant. Replace header tank cap.
620477	24-Oct-21	using coolant
620603	28-Oct-21	DAILY SERVICE FOR SANDVIK TH663.
620643	1-Nov-21	DPF CLEAN SANDVIK TH663 - VOLVO ENGINE
620296	4-Nov-21	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
623707	26-Nov-21	Replace Y piece of exhaust, used on TR19 w/o 623379
654462	7-Jun-22	Move TR18, JB09 and GR04 to the HV Laydown area