

SERVICE SCHEDULE

VOLVO FM7 TWIN STEER VAC TRUCK YEAR 2001 VIN:YV5J4DEG41D122168

DATE	SERVICE	A SERVICE	B SERVICE	C SERVICE	REPAIR	B SERVICE INTERVAL: 15000	C SERVICE INTERVAL:120000
	TYPE				COMMENTS:		
16/09/2020	R & C			322102	322102	Front Bumper, 4 x Offset Rims Steer, 4 x LED Comp Lamp, 2 x LED work	
						lamp ,Lower step bracket, Dash Panel, Grab Handle, Lower Grille section,	
						2 x step plate upper, Turbo & gaskets, Step Guard RHS, Step well RHS,	
						UHF, Speakers, Wipers, Metal Rail W/Insert, Headlight Surrounds,	
						Drink Holder, Door Panel L & R Rod & Clips, Heater Knob,	
						Front M/Guard RH, Ash Tray, Window Winder FH, Courtesy Lamp,	
						Adaptors, Lid, Control Knob FH, Pinion V-Seal F,Door Window Panels	
						L & RHS, Mudguard ,24v Radio. Removed & replaced. C Service	
6/01/2021	R				322102	4 x Plugs, 8 x Black Plugs,2 x Spot/Fog Covers, RH front step, 3 x Bushing,	
						1 x Buffer, 1 x C/Pin M8*30, 3 x Clevis Pins,4 x Lock Springs, 1 x Spring,	
						2 x Carriers, 2 x LED Headlight Globes H4 Twin Pack, Solenoid Valve	
						127mm Silent raincap, 4 x Desiccant Cartridge. Removed & replaced.	
10/02/2021	R				332102	Removed & Replaced Cab Tilt Pump	
30/04/2021	R				327247	Truck was stuck in high range & pump engine clutch not engaging as	
						well. On further investigation found clutch finger had been broken off.	
						Remove Gearbox drive of engine, remove High & Low Range splitter of	
						Gearbox. Dismantled clutch, Had to purchase new	
						clutch & kit for High/Low Range for gearbox. Fitted Pump Engine	
						clutch back to motor & Fitted High/Low cylinder back into Gearbox	
						Refitted Gearbox into truck. Tested ALL OK	
7/07/2021	B		346878			B Service completed	
17/03/2022	R		366090			Volvo completed work: 17/3/2022	
						replace broken front indicator lens and make all light operate	
						all lights operate. Replace broken light assembly and checked	
						operation of all lights. Found issues with brake light not working and	
						other lights flashing replaced fuse . 2nd axle Drag link tie rod at	
						pitman arm worn removed & replaced.	
18/03/2022	B		366135			B Service completed Repalced Coolant	
22/08/2022	B		380339			B service Completed by Volvo	