

Reg No	Description	Date	Odometer	Posting Class Code	Job Description	Supplier Name	Invoice No
1NY7YN	MERCEDES-BENZ 447 VITO 114BLUETEC MWB 7G	28/06/2022	155317	S	Carry out 150,000KM SERV - B Service	Mercedes-Benz Brighton	MBCS330280
		28/06/2022	155317	M	Carry out Labour	Mercedes-Benz Brighton	MBCS330280
		28/06/2022	155317	M	Carry out Service SMS	Mercedes-Benz Brighton	MBCS330280
		7/12/2021	126691	S	Carry out Service A capped	Mercedes-Benz Brighton	MBCS321711
		3/11/2021	0	M	Check and report on broken RH wing assembly casing damaged by wind storm	Innovation Group (Sureplan) Pty Ltd	2219867HO
		3/11/2021	0	M	driver to go to merc to get quote 1st then email off to client for approval	Innovation Group (Sureplan) Pty Ltd	2219867HO
		3/11/2021	0	M	change IG4 when Merc dealer calls us	Innovation Group (Sureplan) Pty Ltd	2219867HO
		5/10/2021	116862	T	Tyre Work Details - NSF	Tyrepower Profleet	127722
		5/10/2021	116862	T	FALKEN VAN01 - 205/65R16 107T (AU10331411)	Tyrepower Profleet	127722
		5/10/2021	116862	T	81181 - SUV 4WD / LIGHT COMM - Fitting Fee - Fitti	Tyrepower Profleet	127722
		5/10/2021	116862	T	81393 - SUV 4WD / LIGHT COMM - Balance - Steel Whe	Tyrepower Profleet	127722
		5/10/2021	116862	T	Tyre Work Details - OSF	Tyrepower Profleet	127722
		5/10/2021	116862	T	FALKEN VAN01 - 205/65R16 107T (AU10331411)	Tyrepower Profleet	127722
		5/10/2021	116862	T	81181 - SUV 4WD / LIGHT COMM - Fitting Fee - Fitti	Tyrepower Profleet	127722
		5/10/2021	116862	T	81393 - SUV 4WD / LIGHT COMM - Balance - Steel Whe	Tyrepower Profleet	127722
		5/10/2021	116862	T	Tyre Work Details - NSR	Tyrepower Profleet	127722
		5/10/2021	116862	T	FALKEN VAN01 - 205/65R16 107T (AU10331411)	Tyrepower Profleet	127722
		5/10/2021	116862	T	81181 - SUV 4WD / LIGHT COMM - Fitting Fee - Fitti	Tyrepower Profleet	127722
		5/10/2021	116862	T	81393 - SUV 4WD / LIGHT COMM - Balance - Steel Whe	Tyrepower Profleet	127722
		5/10/2021	116862	T	Tyre Work Details - OSR	Tyrepower Profleet	127722
		5/10/2021	116862	T	FALKEN VAN01 - 205/65R16 107T (AU10331411)	Tyrepower Profleet	127722
		5/10/2021	116862	T	81181 - SUV 4WD / LIGHT COMM - Fitting Fee - Fitti	Tyrepower Profleet	127722
		5/10/2021	116862	T	81393 - SUV 4WD / LIGHT COMM - Balance - Steel Whe	Tyrepower Profleet	127722
		5/10/2021	116862	T	Tyre Work Details	Tyrepower Profleet	127722
		5/10/2021	116862	T	81194 - SUV 4WD / LIGHT COMM - Alignment - Four Wh	Tyrepower Profleet	127722
		28/04/2021	99682	S	Carry out Service B	Mercedes-Benz Brighton	MBCS312461
		28/04/2021	99682	M	Carry out Service SMS	Mercedes-Benz Brighton	MBCS312461
		28/04/2021	99682	M	Check and report on BLIND SPOT INOP - Rebook	Mercedes-Benz Brighton	MBCS312461
		22/02/2021	91364	M	Check and report on Brake Warning Light On - TBA	Mercedes-Benz Brighton	MBCS309327
		22/02/2021	91364	M	Carry out Service SMS	Mercedes-Benz Brighton	MBCS309327
		22/02/2021	91364	M	Fit New Front Brake Pads	Mercedes-Benz Brighton	MBCS309327
		22/02/2021	91364	M	Fit New Front Discs	Mercedes-Benz Brighton	MBCS309327
		22/02/2021	91364	M	Carry out Labour	Mercedes-Benz Brighton	MBCS309327
		22/02/2021	91364	M	Replace rear brake pads.	Mercedes-Benz Brighton	MBCS309327
		22/02/2021	91364	M	Fit New Rear Discs	Mercedes-Benz Brighton	MBCS309327
		22/02/2021	91364	M	Carry out Labour	Mercedes-Benz Brighton	MBCS309327
		19/02/2021	0	M	Fit New Fit New roof racks	Sundry	57325
		19/02/2021	0	M	see attached invoice	Sundry	57325
		8/09/2020	74796	S	Carry out A Service	Mercedes-Benz Brighton	300881
		8/09/2020	74796	M	Carry out Labour	Mercedes-Benz Brighton	300881
		8/09/2020	74796	M	Replace LHR reflector - damaged	Mercedes-Benz Brighton	300881
		8/09/2020	74796	T	Fit New 2 TYRES 205/65/16 Continental	Mercedes-Benz Brighton	300881
		8/09/2020	74796	M	Adjust Wheel Alignment - free to be able to go tyres at close to BJ	Mercedes-Benz Brighton	300881
		30/12/2019	57364	M	Repair Clean and flush fuel tank - Filled up With Petrol in Diesel Tank	Mercedes-Benz Brighton	609502
		30/12/2019	57364	M	Carry out Labour 375.00	Mercedes-Benz Brighton	609502
		30/12/2019	57364	M	Diesel Fuel 27.44	Mercedes-Benz Brighton	609502
		30/12/2019	0	M	Roadside callout	NRMA BusinessWise	20191230
		4/10/2019	48302	M	Carry out Service SMS	Mercedes-Benz Brighton	285332
		4/10/2019	48302	S	Carry out 45,000KM SERV "B"Service	Mercedes-Benz Brighton	285332
		4/10/2019	48302	M	Carry out Labour	Mercedes-Benz Brighton	285332
		4/10/2019	48302	M	Fit New Replace Wiper Inserts x 2	Mercedes-Benz Brighton	285332
		4/10/2019	48302	M	Carry out Labour	Mercedes-Benz Brighton	285332
		3/04/2019	21122	S	Carry out 25,000KM SERV	Mercedes-Benz Brighton	275801
		3/04/2019	21122	M	Carry out Labour	Mercedes-Benz Brighton	275801
		3/04/2019	21122	M	Carry out Service SMS	Mercedes-Benz Brighton	275801
		3/04/2019	21122	M	Recall 99MBZ4 - Replace NSF Door Pins	Mercedes-Benz Brighton	275801