

Tool No.	Make	Model	Serial No.	Service Frequency	Service Type	Service Notes
3308	Komatsu	TC220LC-8		21/09/2021 (On Demand)	General Maintenance	inspect over heating issue - tom kerlin
3308	Komatsu	TC220LC-8		13/09/2021 (On Demand)	General Maintenance	inspect seat - tom kerlin
3308	Komatsu	TC220LC-8		13/09/2021 (On Demand)	General Maintenance	chase parts for float, take all shockeys off and brakes off, take seals off lowering rams, change brakes, shockeys, clean up - Jordon Christian
3308	Komatsu	TC220LC-8		06/09/2021 (On Demand)	General Maintenance	replace cutting edge on bucket - tom kerlin
3308	Komatsu	TC220LC-8		27/07/2021 (On Demand)	General Maintenance	install plumb hoses & quick hitch. - Tom Kerlin
3308	Komatsu	TC220LC-8		26/07/2021 (On Demand)	General Maintenance	service and repair oil leak - Tom Kerlin
3308	Komatsu	TC220LC-8		29/06/2021 (On Demand)	General Maintenance	chase up parts required for repairs and pay for them @ 11694hrs - zen goldsworthy
3308	Komatsu	TC220LC-8		28/06/2021 (On Demand)	General Maintenance	removed tilt hitch bought back to workshop and cleaned, started stripping down @ 11694hrs - zen goldsworthy
3308	Komatsu	TC220LC-8		23/06/2021 (On Demand)	General Maintenance	tilt hitch leaking from pivot seals, tested, went to everett st to check if any parts could be used from #377 @ 11694 - zen goldsworthy
3308	Komatsu	TC220LC-8		03/06/2021 (On Demand)	General Maintenance	cut mesh out of bucket/bucket # 448 - Brendan Floriduz
3308	Komatsu	TC220LC-8		01/06/2021 (On Demand)	General Maintenance	Re-Seal hyd control valve & replace leaking hyd hoses - Zen Goldsworthy
3308	Komatsu	TC220LC-8		01/06/2021 (On Demand)	General Maintenance	Clean Unit - Joel Baldwin
3308	Komatsu	TC220LC-8		31/05/2021 (On Demand)	General Maintenance	Clean excavator - Joel Baldwin

3308	Komatsu	TC220LC-8		25/05/2021 (On Demand)	General Maintenance	Hydraulic oil leak, tested & found main control valve leaking, re-fitted all panels, filled hyd oil & chased up parts req - Zen Goldsworthy
3308	Komatsu	TC220LC-8		25/05/2021 (On Demand)	General Maintenance	Repair Rock bucket - Brendan Floriduz
3308	Komatsu	TC220LC-8		21/04/2021 (On Demand)	General Maintenance	Plant Relocation and Condition Report 21 Apr 2021 / 3308 / Ken Wittmann
3308	Komatsu	TC220LC-8		16/04/2021 (On Demand)	General Maintenance	Plant Relocation and Condition Report 16 Apr 2021 / 3308 / MC390 Cosgrove Stage 206 / Ken Wittmann
3308	Komatsu	TC220LC-8		14/04/2021 (On Demand)	Preventive	plant relocation checklist - ken wittmann
3308	Komatsu	TC220LC-8		08/04/2021 (On Demand)	General Maintenance	Tested over heating fault - Zen G
3308	Komatsu	TC220LC-8		30/03/2021 (On Demand)	Preventive	plant relocation checklist - tyrone wright
3308	Komatsu	TC220LC-8		17/03/2021 (On Demand)	General Maintenance	Replace cutting edge on bucket - Tom Kerlin
3308	Komatsu	TC220LC-8		23/02/2021 (On Demand)	General Maintenance	Picked up c stopper for radiator, picked up hose and clamps from Pirtek - Zen Goldsworhty
3308	Komatsu	TC220LC-8		01/02/2021 (On Demand)	General Maintenance	Engine over heating, found no foam around radiator, fitted what, tested good. Checked engine loosing engine oil, found breather broken, spitting out oil. New one ordered - Zen Goldsworthy
3308	Komatsu	TC220LC-8		27/01/2021 (On Demand)	General Maintenance	Clean excavator - Joel Baldwin
3308	Komatsu	TC220LC-8		21/01/2021 (On Demand)	Preventive	500hr service @ 11253hrs, change out radiator & thermostat, exhaust manifold - Ross Wise

3308	Komatsu	TC220LC-8		19/01/2021 (On Demand)	General Maintenance	R&R komatsu Radiator - Bayswater Road Radiators - Inv No 447067
3308	Komatsu	TC220LC-8		19/01/2021 (On Demand)	General Maintenance	Bayswater Road Radiators - Pressure wash, remove top tank and report findings - 90% Blocked solid internally, new radiator recommended. - Manufacture new heavy duty radiator, pressure test and paint.
3308	Komatsu	TC220LC-8		06/01/2021 (On Demand)	General Maintenance	Remove radiator - order parts for thermo stat - Tom Kerlin
3308	Komatsu	TC220LC-8		06/01/2021 (On Demand)	General Maintenance	Remove radiator, order part for thermo stat - Tom Kerlin
3308	Komatsu	TC220LC-8		18/12/2020 (On Demand)	General Maintenance	Remove blown hose from excavator drive motor. Make up new hose & refit to machine, fill oil & test ok. - Pirtek Inv No EM700019339
3308	Komatsu	TC220LC-8		01/12/2020 (On Demand)	Corrective	Replace cutting edges on Komatsu Digger
3308	Komatsu	TC220LC-8		30/11/2020 (On Demand)	Corrective	Replaced GET bolts on mud bucket, blade bent and bolts snapped - Changed new GET - Zen Goldsworthy
3308	Komatsu	TC220LC-8		13/10/2020 (On Demand)	Corrective	Kenny's Auto Electrical Inspect and repair aircon
3308	Komatsu	TC220LC-8		30/09/2020 (On Demand)	Preventive	Kenny's Auto Electrical Test AC systems. Found to be low on gas and no blower fan
3308	Komatsu	TC220LC-8		16/09/2020 (On Demand)	Corrective	UKW 1 x recoil 2 x idler assy
3308	Komatsu	TC220LC-8		15/09/2020 (On Demand)	Corrective	Hastings Deering Remove and install track assembly
3308	Komatsu	TC220LC-8		11/09/2020 (On Demand)	Corrective	Leg not folding out, bent mount back - Zen Goldsworthy

3308	Komatsu	TC220LC-8		26/08/2020 (On Demand)	Corrective	24 Hour Hose Removed, manufactured and fit hose from valve bank to boom
3308	Komatsu	TC220LC-8		25/08/2020 (On Demand)	Corrective	Blown hydraulic hose - filled with hydraulic oil -Zen G
3308	Komatsu	TC220LC-8		24/08/2020 (On Demand)	Corrective	Refitted track that came off LHS - Zen G
3308	Komatsu	TC220LC-8		22/07/2020 (On Demand)	Corrective	refit belly plate - zen goldsworthy
3308	Komatsu	TC220LC-8		22/06/2020 (On Demand)	Corrective	500hr service, cleaned out battery tray, repaired front cab lights - zen goldsworthy
3308	Komatsu	TC220LC-8		18/06/2020 (On Demand)	Corrective	Mendi 500 Hour Service Sheet -Zen G
3308	Komatsu	TC220LC-8		18/06/2020 (On Demand)	Corrective	Mendi Mendi Constructions limited pre-workshop release safety & maintenance inspection policy - EXCAVATOR -inspected by Zen G
3308	Komatsu	TC220LC-8		18/06/2020 (On Demand)	Corrective	500hr service, flushed out radiator - zen goldsworthy
3308	Komatsu	TC220LC-8		21/11/2019 (On Demand)	Corrective	clean a/c, change out coolant, adjust belt - Ross Wise
3308	Komatsu	TC220LC-8		12/11/2019 (On Demand)	Corrective	fix oil leak, change a/c belt, pick up cutting edge bolts - tom kerlin
3308	Komatsu	TC220LC-8		12/11/2019 (On Demand)	Corrective	installed engine speed sensors - scott healing
3308	Komatsu	TC220LC-8		11/11/2019 (On Demand)	Corrective	tightened grousers, changed out speed sensors, repaired oil leaks on hydraulic pump - Scott Healing
3308	Komatsu	TC220LC-8		06/09/2019 (On Demand)	Corrective	changed out fuel sensor - scott healing
3308	Komatsu	TC220LC-8		03/09/2019 (On Demand)	Preventive	1000hr service and defects @ 9826hrs - Scott HEaling

3308	Komatsu	TC220LC-8		27/08/2019 (On Demand)	Corrective	remove old hoses, clean up parts, fit new hoses for LH wheel motor, degrease and hose off oil, test for leaks, fit guards - Calvin Jack
3308	Komatsu	TC220LC-8		24/08/2019 (On Demand)	Corrective	24hr Hose - hose replacement
3308	Komatsu	TC220LC-8		19/08/2019 (On Demand)	Corrective	change cutting edge - Calvin Jack
3308	Komatsu	TC220LC-8		12/06/2019 (On Demand)	Corrective	fit dipper cylinder hose - 24hr hose
3308	Komatsu	TC220LC-8		17/04/2019 (On Demand)	Corrective	250hr service inspection - 9390hrs - Tom Kernin
3308	Komatsu	TC220LC-8		17/04/2019 (On Demand)	Corrective	Repair 2way
3308	Komatsu	TC220LC-8		13/03/2019 (On Demand)	Corrective	Cut and fit front screen - 676mm LAMGLGR 2140 X 1220 - Instant Windscreens
3308	Komatsu	TC220LC-8		08/03/2019 (On Demand)	Corrective	Check aircon operation. - Ross Wise
3308	Komatsu	TC220LC-8		15/02/2019 (On Demand)	Corrective	Replaced LHS idler, inspect broken recoil - Scott Healing & Tom Kerlin
3308	Komatsu	TC220LC-8		23/01/2019 (On Demand)	Preventive	Checked idler, radiator, cleaned down tracks. Scott Healing
3308	Komatsu	TC220LC-8		26/11/2018 (On Demand)	Corrective	Changed out fan belt. Matt Doyle
3308	Komatsu	TC220LC-8		28/09/2018 (On Demand)	Corrective	Service digger. Tom Kerlin
3308	Komatsu	TC220LC-8		28/09/2018 (On Demand)	Preventive	500hr service @ 8747hrs - Matt Doyle
3308	Komatsu	TC220LC-8		11/09/2018 (On Demand)	Corrective	24hr Hose - hose from valve bank to boom
3308	Komatsu	TC220LC-8		23/07/2018 (On Demand)	General Maintenance	Predator Signs - replace all signage on excavator
3308	Komatsu	TC220LC-8		16/07/2018 (On Demand)	Corrective	Tint a Car - replace tinting in cab
3308	Komatsu	TC220LC-8		10/07/2018 (On Demand)	Corrective	Fixed door latch, welded up crank in power tilt, changed sensor, checked over machine. Scott Healing
3308	Komatsu	TC220LC-8		10/07/2018 (On Demand)	General Maintenance	Pre-workshop release @ 8460hrs - Scott Healing

3308	Komatsu	TC220LC-8		15/06/2018 (On Demand)	Corrective	@8386. Pick up batteries, drove to bushland beach, changed out batteries. Matt Doyle
3308	Komatsu	TC220LC-8		31/05/2018 (On Demand)	Corrective	Picked up airbox cover from ukw. took to bushland beach, inspected intake system for contaminant. put back together. Matt Doyle
3308	Komatsu	TC220LC-8		05/05/2018 (On Demand)	Corrective	@8239. Install new am/fm radio. Ross Wise
3308	Komatsu	TC220LC-8		04/05/2018 (On Demand)	Preventive	250hr service @ 8239hrs - Ross Wise
3308	Komatsu	TC220LC-8		01/05/2018 (On Demand)	Corrective	Inspected oil leak on quick hitch valve, replaced oring, oil still leaking through sensor. Ordered sensor. Scott Healing
3308	Komatsu	TC220LC-8		24/04/2018 (On Demand)	Corrective	Changed cutting edge of 411 bucket. Matt Doyle
3308	Komatsu	TC220LC-8		03/04/2018 (On Demand)	Corrective	@8125 Replace bottom track roller - Tom Kerlin. Matt Doyle
3308	Komatsu	TC220LC-8		10/02/2018 (On Demand)	Corrective	Replace intake pipe. Tom Kerlin
3308	Komatsu	TC220LC-8		09/02/2018 (On Demand)	Corrective	Changed air intake idler. Ross Wise
3308	Komatsu	TC220LC-8		30/01/2018 (On Demand)	Preventive	250Hr service @ 7994hrs - Matt Doyle. Tom Kerlin Changed engine oil and engine filters. Changed final drive oil. Changed cracked tilt bucket fitting. Ordered intake hose.
3308	Komatsu	TC220LC-8		29/01/2018 (On Demand)	Corrective	24Hr Hose - replace 2 hoses on end of the boom
3308	Komatsu	TC220LC-8		29/09/2017 (On Demand)	Corrective	Change tacks, turn cutting edge. @7634. Larry Pegoraro
3308	Komatsu	TC220LC-8		28/09/2017 (On Demand)	Corrective	Change tracks. Larry Pegoraro
3308	Komatsu	TC220LC-8		27/09/2017 (On Demand)	Corrective	Change tracks. Larry Pegoraro

3308	Komatsu	TC220LC-8		26/09/2017 (On Demand)	Corrective	Service & Finals, assis with track change, replace isolator and E-stop. Camden Redgrave Chnage tracks, remove track plates,drive sproket and chain. Fit new drive sprocket, weld cracks in LHS idler. Larry Pegoraro
3308	Komatsu	TC220LC-8		25/09/2017 (On Demand)	Corrective	Inspect and diagnose hydraulic pump not working. Remove hydraulic pump and hoses, disassemble pump, found multiple bits of debris in pump, clean out housing and remove scoring from housing, clean parts and rebuild pump with new seals and thrust plates. Refit and test. too much presswure for pump, refit relief block and adjust. retest ok. Camden Redgrave
3308	Komatsu	TC220LC-8		22/07/2017 (On Demand)	Corrective	Removed steel line for bucket hitch tilt. Braised up crack, fitted back to machine and tested - Matt Doyle @7379hrs
3308	Komatsu	TC220LC-8		24/06/2017 (On Demand)	Scheduled	250hr service carried @ 7314hrs (Camden Redgrave)
3308	Komatsu	TC220LC-8		24/06/2017 (On Demand)	Preventive	Service. @7314. Camden Redgrave
3308	Komatsu	TC220LC-8		06/06/2017 (On Demand)	Corrective	Pumped up tracks, sent back to work (Matt Doyle)
3308	Komatsu	TC220LC-8		13/05/2017 (On Demand)	Preventive	Service Excavator. @7116. Larry Pegoraro
3308	Komatsu	TC220LC-8		13/05/2017 (On Demand)	Preventive	250 hr service carried out; inspected hitch assembly - in good condition @ 7116 hrs (Larry Pegoraro)

3308	Komatsu	TC220LC-8		06/04/2017 (On Demand)	Preventive	Re-fit RHS track and adjust. Larr Pegoraro
3308	Komatsu	TC220LC-8		06/03/2017 (On Demand)	Preventive	250hr service carried out at @ 6787 hrs (Matt Doyle)
3308	Komatsu	TC220LC-8		06/03/2017 (On Demand)	Corrective	Diagnose air-conditioner not getting cold. @6789. Camden Redgrave
3308	Komatsu	TC220LC-8		10/02/2017 (On Demand)	Corrective	Changed out air cleaner @ 6706 hrs (Ross Wise)
3308	Komatsu	TC220LC-8		16/12/2016 (On Demand)	Preventive	250hr service carried out @ 6539hrs (Matt Doyle)
3308	Komatsu	TC220LC-8		15/12/2016 (On Demand)	Corrective	Filled oil drums, got ready for service (Matt Doyle)
3308	Komatsu	TC220LC-8		18/11/2016 (On Demand)	Corrective	Fitted new beacon (Matt Doyle)
3308	Komatsu	TC220LC-8		11/11/2016 (On Demand)	Corrective	Change track drive sprockets & fit new radio (Larry Pegoraro)
3308	Komatsu	TC220LC-8		07/11/2016 (On Demand)	Corrective	Service, changed overflow bottle, tightened AC belt (Matt Doyle)
3308	Komatsu	TC220LC-8		07/11/2016 (On Demand)	Preventive	500hr service carried out @ 6277 hrs (Matt Doyle)
3308	Komatsu	TC220LC-8		17/09/2016 (On Demand)	Corrective	Replaced bonnet struts @ 6067 hrs (Matt Doyle)
3308	Komatsu	TC220LC-8		02/09/2016 (On Demand)	Preventive	250 Hour Service @ 6027 hours (Larry Pegoraro & Matt Doyle)
3308	Komatsu	TC220LC-8		02/07/2016 (On Demand)	Corrective	Change hydraulic oil and filters @ 5699 hrs (Matt Doyle)
3308	Komatsu	TC220LC-8		24/06/2016 (On Demand)	Preventive	250hr service carried out; changed RHS rear track roller, checked two-way ok, changed out filters @ 5699 hrs
3308	Komatsu	TC220LC-8		16/06/2016 (On Demand)	Corrective	Replace oring right rear (Advantage Tyres)

3308	Komatsu	TC220LC-8		06/05/2016 (On Demand)	Corrective	Kenny's Auto Elec - Proceed to site to inspect A/C. Found system was low on gas. Top up and run system - working fine. Put in oil and dye and run. Couldnt find leak any where, suspect evaporator. Noticed blend door for fresh and recycle is broken. Evaporator possibly full of dust and blocked. Recommend evaporator change, TX Valve, drier and evaporator box will have to come out - Quote on repairs
3308	Komatsu	TC220LC-8		02/03/2016 (On Demand)	Preventive	250hr service carried out @ 5374 hrs (Will Nicholas)
3308	Komatsu	TC220LC-8		16/02/2016 (On Demand)	Preventive	Check a/c, found low on gas. Check for leaks. Gas 1kg @ 5145 hrs (Ross Wise)
3308	Komatsu	TC220LC-8		01/02/2016 (On Demand)	Corrective	Test digger for starting fault, repaired wiring to turbo timer @ 5626 hrs (Jamie Stock)
3308	Komatsu	TC220LC-8		01/12/2015 (On Demand)	Preventive	250hr service carried out @ 5078 hrs (Ross Wise/Will Nicholas)
3308	Komatsu	TC220LC-8		24/11/2015 (On Demand)	Corrective	Change out two batteries @ 4992 hrs (Will Nicholas)
3308	Komatsu	TC220LC-8		18/11/2015 (On Demand)	Corrective	C/O front RH idler @ 4992 hrs (Ross Wise)
3308	Komatsu	TC220LC-8		13/10/2015 (On Demand)	Preventive	250hr service carried out @ 4768 hrs (Ross Wise)
3308	Komatsu	TC220LC-8		28/08/2015 (On Demand)	Preventive	250hr service carried out; changed flashing light bulb, c/o cutting edge @ 4536 hrs (Ross Wise)
3308	Komatsu	TC220LC-8		14/07/2015 (Five Yearly)	Preventive	Noise Survey - No recommended control measures at time of survey.

3308	Komatsu	TC220LC-8		27/06/2015 (On Demand)	Preventive	Carry out 250hr service; tested A/C no fault found. @ 4274 hrs (Will/Ross)
3308	Komatsu	TC220LC-8		02/05/2015 (On Demand)	Preventive	Carry out 250hr service; pressure check a/c checked ok, gased 1kg, c/o final drive oil, check batter bucket - all ok @ 4013 hrs (Ross/Will)
3308	Komatsu	TC220LC-8		24/02/2015 (On Demand)	Preventive	250hr service carried out @ 3735 hrs (Ross)
3308	Komatsu	TC220LC-8		13/12/2014 (On Demand)	Preventive	250hr service carried out @ 3454 hrs (Ross)
3308	Komatsu	TC220LC-8		20/11/2014 (On Demand)	Corrective	Removed bucket and fitted quick hitch and plumbed up. Removed manifold from side of engine (engine oil) replaced all orings, refitted, tested all good @ 10338 hrs (Rob)
3308	Komatsu	TC220LC-8		13/09/2014 (On Demand)	Preventive	1000 hr service carried out - c/o fan belt, c/o swing, final drive, pump box (Ross & Matt)
3308	Komatsu	TC220LC-8		05/08/2014 (On Demand)	Corrective	Fit new bolts to cutting edge of mud buckt, check water leak coming from water pump, need new fan belt @ 2793 hrs (Ken)
3308	Komatsu	TC220LC-8		11/07/2014 (On Demand)	Preventive	250hr service @ 2770 hrs (Brendan)
3308	Komatsu	TC220LC-8		01/07/2014 (Five Yearly)	Preventive	Noise Survey
3308	Komatsu	TC220LC-8		11/06/2014 (On Demand)	Preventive	Travel to Libertyrise, top up batteries and jump start test charge @ 2556 hrs (Brendan)
3308	Komatsu	TC220LC-8		16/04/2014 (On Demand)	Preventive	
3308	Komatsu	TC220LC-8		15/04/2014 (On Demand)	Preventive	Carry out 250hr service @ 2281 hrs (Brendan & Ross)

3308	Komatsu	TC220LC-8		03/04/2014 (On Demand)	Preventive	Chase up 2000hr service kit @ 2214 hrs (Ross)
------	---------	-----------	--	-------------------------------	------------	--