

Job Code	Klms	Title	Invoice Value	Start Date	Date Completed	Invoice No.
62670	290,648 KLMS	LV52 - HEADLIGHT OUT	\$ 119.75	14/12/2020	14/12/2020	7136726
62345	290,642 KLMS	LV52 - RH BRAKE LIGHT NOT WORKING	\$ 38.00	1/12/2020	2/12/2020	7136417
59762	287,212 KLMS	LV52 - STEERING SHUTTER/ROOF RUST	\$ 1,076.34	3/08/2020	7/09/2020	7133965
59458	284,199 KLMS	LV52 - 285,000 KLM SERVICE	\$ 330.46	21/07/2020	21/07/2020	7132545
59386	284,199 KLMS	LV52 - REPAIR FRIDGE	\$ 92.50	15/07/2020	20/07/2020	7132334
57918	274,319 KLMS	LV52 - BONNET LATCH	\$ 25.00	6/05/2020	6/05/2020	7130778
56937	272,185 KLMS	LV52 - REPLACE TYRE	\$ 45.00	16/03/2020	17/03/2020	7129099
56183	269,742 KLMS	LV52 - SERVICE/TEST BATTERY	\$ 800.95	31/01/2020	19/02/2020	7128506
56084	265,950 KLMS	LV52 - VIBRATION IN VEHICLE	\$ 101.25	28/01/2020	28/01/2020	7127902
55600	264,872 KLMS	LV52 - HEADLIGHT NOT WORKING	\$ 52.60	17/12/2019	17/12/2019	7127108
54677	262,497 KLMS	LV52 - REPLACE WIPER BLADES	\$ 28.50	30/10/2019	30/10/2019	7126180
54530	261,617 KLMS	LV52 - REFIT FRIDGE	\$ 72.69	24/10/2019	28/10/2019	7125753
53134	256,924 KLMS	LV52 - SERVICE	\$ 799.56	14/08/2019	16/08/2019	7124174
52261	252,502 KLMS	LV52 - HEADLIGHT OUT	\$ 64.20	19/06/2019	19/06/2019	7122838
50963	244,194	LV52 - CHECK OVER BEFORE TRIP	\$ 198.00	5/04/2019	5/04/2019	7121375
49865	242,057 KLMS	LV52 - LIGHTS NOT WORKING	\$ 45.00	11/02/2019	11/02/2019	7119675
49248	239,898 KLMS	LV52 - 240,000 KLMS SERVICE	\$ 163.86	2/01/2019	2/01/2019	7118835
49068	239,533 KLMS	LV52 - OVERSIZE SIGNS & BEACONS NOT WORKING	\$ 50.00	12/12/2018	12/12/2018	7118424
48780	238,096 KLMS	LV52 - CHECK OVERHEAD SIGN & BRAKES	\$ 67.50	30/11/2018	30/11/2018	7117920
48534	232,177 KLMS	LV52 - FIT 2ND BATTERY FOR FRIDGE	\$ 227.10	19/11/2018	19/11/2018	7117758
48381	227,967 KLMS	LV52 - CHECK OVER/TYRE PRESSURES	\$ 67.50	9/11/2018	9/11/2018	7117516
48266	227,967 KLMS	LV52 - BATTERY	\$ 50.00	5/11/2018	6/11/2018	7117481
48153	227,405 KLMS	LV52 - 225,000 KLM SERVICE	\$ 250.51	29/10/2018	29/10/2018	7117115
47123	220,829 KLMS	LV52 - ROTATING BEACON	\$ 185.00	4/09/2018	6/09/2018	7115883
46028	215,159 KLMS	LV52 - CHECK OVER	\$ 38.75	9/07/2018	9/07/2018	7114324
45815	214,818 KLMS	LV52 - HEADLIGHT OUT	\$ 148.13	28/06/2018	28/06/2018	7113985
44274	212,285 KLMS	LV52 - BOTH UHF RADIOS NOT WORKING	\$ 45.02	22/03/2018	22/03/2018	7111786/7111900
44229	211,765 KLMS	LV52 - FIT PLUG FOR FRIDGE	\$ 225.41	21/03/2018	21/03/2018	7111785
43895	211,652	LV52 - SEAT BELT LATCH	\$ 32.45	28/02/2018	28/02/2018	7111256
43515	209,116	LV52 - SERVICE	\$ 858.95	7/02/2018	16/02/2018	71111032
43329	208,448	LV52 - FLASHING LIGHT NOT WORKING	\$ 96.75	25/01/2018	29/01/2018	7110607
39689	196,390	LV52 - BROKEN AERIALS, ROTATING LIGHT	\$ 407.40	27/06/2017	30/06/2017	7105967
39463	...	LV52 - BATTERY ISOLATOR	\$ 100.65	13/06/2017	30/06/2017	7105966
39206	195,039	LV52 - SERVICE	\$ 321.47	29/05/2017	1/06/2017	7105574
38684	189,407	LV52 - OIL LEAK - FIT SEAL	\$ 111.25	19/04/2017	18/05/2017	7105064
38453	186,575	LV52 - LIGHTS, BEACON	\$ 105.00	7/04/2017	26/04/2017	7104577
38177	182,884	LV52 - FIT SHU ROO	\$ 987.13	15/03/2017	31/03/2017	7104157
37544	179,993	LV52 - PREP FOR USAGE	\$ 1,295.33	1/02/2017	1/02/2017	7103450