

Work Order	Start Date	Description
424880	24-May-18	Fit For Purpose inspection
425049	25-May-18	Install fixed radio and a handheld + charging dock.
425666	30-May-18	switch reverse camera from mirror to normal image.
425667	30-May-18	daily service.
425759	31-May-18	damage to front wipers
425655	2-Jun-18	Install reducing piece for shotcrete spray nozzle
426370	5-Jun-18	WORK ORDER FOR MONTHLY COST ALLOCATIONS
426636	7-Jun-18	intermediate fault with remotes
426672	7-Jun-18	Check remote's operation
426286	8-Jun-18	Carry out 50hr service on SC08 as per attatched
426874	9-Jun-18	machine fault system voltage drop, caused by flashing light
427396	13-Jun-18	Check and adjust boom roll over speeds. Reported slow.
427418	13-Jun-18	Front windscreen popped out, re-fit
427264	14-Jun-18	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
427397	15-Jun-18	Move A/C drain lines in cab so they drain externally
432818	15-Jun-18	replace blocked dpf muffler
432935	17-Jun-18	exhaust break not working
433054	19-Jun-18	check air pressure release tap on boom
433160	21-Jun-18	Check water & air reel operation - stiff to operate
433159	22-Jun-18	Chem. sight glass - see if better view point possible
433401	22-Jun-18	repair air hose at nozzle.
433537	22-Jun-18	bleed up chem pump and tighten fitting
433539	23-Jun-18	check a/c fault - low gas
433545	23-Jun-18	park brake coming on intermittently. check jack leg
433546	23-Jun-18	retarder not working, actuator u/s on exhaust brake.
433138	24-Jun-18	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
433944	26-Jun-18	swing tube blocked. replace short delivery line near nozzle.
433958	26-Jun-18	replace wiper blades
433818	26-Jun-18	Windscreen cracked - no cracks found
433819	26-Jun-18	Windscreen cover needs attention
433869	28-Jun-18	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
434273	2-Jul-18	Remote bracket bent
434691	5-Jul-18	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
434989	5-Jul-18	replace 10m delivery line.
434994	5-Jul-18	replace air line to y-piece.
435775	10-Jul-18	hyd filter blockage alarm.
435848	11-Jul-18	WORK ORDER FOR MONTHLY COST ALLOCATIONS
435881	12-Jul-18	Check exhaust brake butterfly as per Normet Bulletin
435882	12-Jul-18	Check exhaust brake butterfly valve end float
436046	13-Jul-18	replace fuel cap / strainer
435717	14-Jul-18	500 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
436173	16-Jul-18	Bullhose rubbing on pressure washer
436342	17-Jul-18	Wiper blade and arm replaced
436340	17-Jul-18	Chem. sight line blocked
436774	18-Jul-18	replace -6 hose
436775	18-Jul-18	replace viribrator
436797	18-Jul-18	replace 3m bull hose

436564	19-Jul-18	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
436822	19-Jul-18	air filter light coming on
436905	20-Jul-18	replace wiper assembly
437011	22-Jul-18	flat tyre pos 1 - retorque wheel nuts start of next shift
437187	23-Jul-18	jack leg fault
437205	23-Jul-18	pos 2 flat tyer
437337	23-Jul-18	make up depth probes
437346	24-Jul-18	replace jack leg switch
437471	25-Jul-18	replace boom air line
437494	25-Jul-18	Air line blockage
437549	26-Jul-18	fit wiper blades
437554	26-Jul-18	replace fitting on boom
437310	30-Jul-18	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
437979	30-Jul-18	fan belt u/s
437983	30-Jul-18	oil leak at front of motor
438064	2-Aug-18	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
438391	3-Aug-18	clean cooler pack and hyd cooler
438400	4-Aug-18	replace hydrascaler fitting needs hose replaced
438448	5-Aug-18	remote cable replaced - no boom movements
438462	5-Aug-18	replace chem hose
438471	6-Aug-18	lhs jack leg switch broken
438492	6-Aug-18	repair remote lead broken wire in plug
438533	6-Aug-18	no revs on throttle pedal
437946	7-Aug-18	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
438556	7-Aug-18	chem line blocked
439209	8-Aug-18	replace chem hose in pump
439217	8-Aug-18	hydro scaler fault blocked water line
439224	8-Aug-18	fit new chem pump hose and unblock chem line
439131	9-Aug-18	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
439773	9-Aug-18	hydro scaler not working
439792	9-Aug-18	replace both wiper arms and blades
439840	10-Aug-18	No hand held radio
439841	10-Aug-18	Chem sight glass U/S
439905	11-Aug-18	repair exhaust brake
439956	12-Aug-18	replace vibrator
439997	13-Aug-18	replace mounting on hopper for vibrator
439998	13-Aug-18	fit new lock for afff bottle
440002	13-Aug-18	replace rubber buffer pads on boom
440014	13-Aug-18	rod fallen off exhaust brake
440296	14-Aug-18	chem fault
440311	14-Aug-18	Zoom slides jammed up
440388	15-Aug-18	Remote cradle bent
440387	15-Aug-18	R/H wiper missing
440259	15-Aug-18	1000 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
439197	16-Aug-18	replace bump stops boom.
440556	17-Aug-18	pos 1 puncture. replace wheel assy.
440592	17-Aug-18	Retension pos 1
440616	18-Aug-18	replace 3m delivery line.

440663	19-Aug-18	fix rubber flap holding flap open on hopper
440666	19-Aug-18	replace 10m concrete hose and fix water blockage
440756	20-Aug-18	clean out chem non return valve at nozzle.
440764	20-Aug-18	Cancelled during entry
441025	22-Aug-18	pos 4 puncture.
441033	22-Aug-18	replace 3m delivery line.
441064	22-Aug-18	hopper drain hatch won't close properly
440867	23-Aug-18	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
441088	23-Aug-18	replace chem fitting in tank
441446	27-Aug-18	check exhaust brake actuator needs replacing
441463	27-Aug-18	change pos 4 tyre
440981	28-Aug-18	Change out the coolant so it is the same as the rest of the
441707	28-Aug-18	align rear elbow on hopper
441758	28-Aug-18	Replace Hydralcal
441823	29-Aug-18	hyd cooler fan u/s
441841	29-Aug-18	engine overheating
441842	29-Aug-18	replace hydrosailer pump
441881	30-Aug-18	replace air hose
441882	30-Aug-18	hydralcal not working - low pressure
441653	31-Aug-18	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
442000	1-Sep-18	adjust pressures on hydrosailer unit
442038	2-Sep-18	replace 2.7m delivery line.
442047	2-Sep-18	bent hopper plate.
442101	3-Sep-18	replacement hopper bottom plate assembly - DONE ON 445684
442717	4-Sep-18	straighten up hopper plate.
442884	5-Sep-18	hopper plate seal needs replacing on next service day please
442885	5-Sep-18	boom zoom cyl guard damaged, straighten out and refit on
442891	5-Sep-18	daily.
442892	5-Sep-18	repair hopper plate.
442662	6-Sep-18	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
442801	6-Sep-18	Rebuild Jacon remotes sets.
442924	6-Sep-18	replace hyd cooler fan
442926	6-Sep-18	zoom cylinder cover rewire
442927	6-Sep-18	hydro scaler pressure issue
442913	6-Sep-18	Wipers need TLC
442983	7-Sep-18	replace hydrosailer and repair - New unit from Normet
442989	7-Sep-18	check exhaust brake
439983	7-Sep-18	Cracked mirror
443069	9-Sep-18	thermo fan popping fuse i, installed 30a resettable fuse
443105	9-Sep-18	replace remote lead
443141	10-Sep-18	Retractor stop on form oil reel U/S
443445	11-Sep-18	Install external mine radio speaker
443846	14-Sep-18	boom hose blown.
443857	14-Sep-18	alt belt squealing
443945	16-Sep-18	hydra scaler fault
443982	17-Sep-18	fit new air filters.
443516	18-Sep-18	500 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
444465	19-Sep-18	check a/c operation - blocked filter before evaporator

444469	19-Sep-18	boom knuckle pins and bushes need replacing
441769	20-Sep-18	fit s/s 90 deg fitting in chem tank next service day
442883	20-Sep-18	replace wiper blades.
441772	20-Sep-18	Brakes squealing
444351	20-Sep-18	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
444497	20-Sep-18	repair swing tube
444498	20-Sep-18	replace chem site glass hose
439984	20-Sep-18	Windscreen cracked
444569	21-Sep-18	exhaust brake sticking on
444594	22-Sep-18	refit exhaust brake linkage back on
444595	22-Sep-18	replace -6 hose
444610	23-Sep-18	repair blockage in air system
444612	23-Sep-18	replace hydroscler
444627	23-Sep-18	rock fall on boom front section damaged
445016	25-Sep-18	brake not holding
444885	25-Sep-18	Cab floor lifting.
444887	25-Sep-18	Poor comms in drives.
444888	25-Sep-18	Hopper door hard to engage. DONE ON 445684
445190	26-Sep-18	replace u/s vibrator
444943	27-Sep-18	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
445239	27-Sep-18	Check for high axle oil temp alarm
445240	27-Sep-18	Exhaust brake stuck on
445248	27-Sep-18	Front lights going out
445213	27-Sep-18	Jack leg sensor playing up.
445308	29-Sep-18	adjust jack leg proxy
445346	30-Sep-18	replace delivery lines
445348	30-Sep-18	pos 2 flat
445684	1-Oct-18	Chem fault, not turning off, VALVE TO CHANGE OUT
446485	3-Oct-18	Remote lead.u/s
446529	4-Oct-18	remotes not working
446531	4-Oct-18	replace rct module and fuel cap
446542	4-Oct-18	hydroscler u/s - check filters & pressures
446543	4-Oct-18	remote fault
446622	6-Oct-18	repair hyd oil leak
446658	7-Oct-18	throttle not working
446326	8-Oct-18	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
447041	9-Oct-18	over heating washed out cooler pack
446733	9-Oct-18	NO Hand held radio
447138	9-Oct-18	repair remote cable
447264	10-Oct-18	remotes not working switch in cab not turned on
447201	11-Oct-18	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
447291	11-Oct-18	RH Bump stop split
447380	12-Oct-18	Repair leaking chem fitting.
447402	12-Oct-18	C/O blown chem hose
447464	14-Oct-18	Replace fan belt
448032	16-Oct-18	replace hose on transmission sight glass.
447887	18-Oct-18	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
447888	18-Oct-18	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES

448179	18-Oct-18	repair chem fault
448146	18-Oct-18	Radio aerial needs fixing
448207	19-Oct-18	Rotation head loose
448275	20-Oct-18	short hard line on hydro scaler u/s (Parts on order)
448596	23-Oct-18	replaced cracked mirror
453555	24-Oct-18	replace hopper cutting ring & seal
453576	24-Oct-18	replace hose on y piece
453338	25-Oct-18	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
453638	25-Oct-18	fault code 1041, work hyd filters clogged.
453640	26-Oct-18	replace front work light, u/s.
453829	27-Oct-18	a/c not getting cold enough.
447286	28-Oct-18	need to wire up hyd cooler fan to engine run not constantly
453833	28-Oct-18	straighten shotcrete control box.
453834	28-Oct-18	repair hyd oil leak at rear valve.
453498	29-Oct-18	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
453978	29-Oct-18	replace wiper arm and wiper blades
453388	30-Oct-18	1000 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
454015	30-Oct-18	chem fault blocked flow tube.
454016	30-Oct-18	repalce rear view mirror.
454023	30-Oct-18	exhaust brake linkage fallen apart. cable tie together.
454028	30-Oct-18	replace engine belt
454107	30-Oct-18	replace exhaust brake arm
454110	30-Oct-18	replace wheel end mag plugs& diff mag plugs (Parts on order)
454194	30-Oct-18	Blocked chem hose
447285	1-Nov-18	pressure washer reel leaking - nathan chasing up
454067	1-Nov-18	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
454068	1-Nov-18	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
454320	1-Nov-18	replace cab mirror
454341	1-Nov-18	exhaust brake end popped off
454350	1-Nov-18	Zoom sticky, change out slides
454361	1-Nov-18	exhaust brake u/s
454524	2-Nov-18	chem pump not working
454536	2-Nov-18	replace lh feed rope
454541	2-Nov-18	exhaust brake stuck on
454612	3-Nov-18	blocked air filter & fire suppression gone off
454637	4-Nov-18	refit new fire supp caps
454805	5-Nov-18	block in air line
454827	5-Nov-18	replace pos 2 tyre
455117	6-Nov-18	replace pos 3 tyre
455256	7-Nov-18	replace blown hose
444481	8-Nov-18	Replace A/C condensor
455044	8-Nov-18	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
455045	8-Nov-18	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
455343	8-Nov-18	replace fan belt
455344	8-Nov-18	wrap hose loom on boom and replace concrete hose
455270	8-Nov-18	Hopper head board opening up
455271	8-Nov-18	Holes in hopper rubber
455375	9-Nov-18	Replace the drivers side window.

455377	9-Nov-18	replace swing tube wear plate and ring.
455378	9-Nov-18	hopper grate jammed. clean all concrete off ok.
455384	9-Nov-18	replace rotation joystick on spare remote set.
455448	10-Nov-18	need inner door handle / lock assembly replaced
455663	12-Nov-18	engine shutdown. plug out of remote box.
455638	12-Nov-18	LH Bump stop U/S
456106	14-Nov-18	tranny temp sensor u/s.
455911	15-Nov-18	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
440984	16-Nov-18	INSTALL REMOTE GREASE LINES TO THE SUSPENSION CYLINDERS.
456255	16-Nov-18	replace wiper blades
456264	16-Nov-18	chem meter not working
455912	17-Nov-18	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
456296	17-Nov-18	replace hydroscaler nozzle
456599	20-Nov-18	replace bull hose
456618	20-Nov-18	repair wiring on remote plug
456772	21-Nov-18	Replace remote cable
456233	22-Nov-18	Chem control unit spool replacement - SUBJECT TO WARRANTY
456467	22-Nov-18	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
456468	22-Nov-18	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
456845	23-Nov-18	electrical fault on dash, #422, blown fuse.
456877	23-Nov-18	High diff temp light come on
456925	24-Nov-18	Boom stuck dry slides
456968	25-Nov-18	1st stage of boom stuck - pull aprt clean out
457124	26-Nov-18	1 st stage boom not extending out all the way
457017	26-Nov-18	Hydroscaler weak as
457018	26-Nov-18	Exhaust brake u/s (trammimg)
457019	26-Nov-18	Chem flow high
457378	28-Nov-18	replace air filters and wipers. tighten air fitting.
457204	29-Nov-18	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
457569	29-Nov-18	A/C not great
457925	30-Nov-18	replace remotes
457980	1-Dec-18	chem pump not working
457996	2-Dec-18	rock fall boom bent tilt cylinder / replaced
458032	2-Dec-18	check hydroscaler operation
458187	3-Dec-18	un block blockage in air line
444886	4-Dec-18	Poor door seal.- SEE HISTORY
454366	4-Dec-18	repair bent covers over electrical box lhs rear frame
455274	4-Dec-18	Door still U/S
456310	4-Dec-18	Lots of play in tilt cylinder pin
456311	4-Dec-18	Washer reservoir leaking
456422	4-Dec-18	Belt slips on start up
456423	4-Dec-18	Using 35lts too much chem per cut
456424	4-Dec-18	Form reel stopper u/s
457233	4-Dec-18	500 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
458420	4-Dec-18	replace blown carrier hose
458421	4-Dec-18	hydroscaler leak
458422	4-Dec-18	fan belt & idler pulley u/s
458496	5-Dec-18	repace hydro hose on boom

458497	5-Dec-18	replace pressure washer hose
458542	5-Dec-18	replace fitting of water filter housing
458543	5-Dec-18	repair nozzle head
458320	6-Dec-18	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
458321	6-Dec-18	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
458607	6-Dec-18	tighten chem fitting.
458778	7-Dec-18	replace shotcrete discharge hose at the end of the boom.
458791	7-Dec-18	blown air hose in boom loom
458812	8-Dec-18	hydra scaler and pressure washer low pressure. fitting u/s
458813	8-Dec-18	rehang air hose.
458816	8-Dec-18	replace hydra scaler fitting.
458920	10-Dec-18	vibrator not working. ok.
458930	10-Dec-18	repair wiring to vibrater
459050	11-Dec-18	remotes need looking at boom movements have delay in up/down
459317	12-Dec-18	replace zoom slide pieces
459320	12-Dec-18	replace fitting on chem sight tube.
459321	12-Dec-18	chem reading incorrectly. reported by m.luckett. tested as
459322	12-Dec-18	reverse camera tripping out when reversing, going dark.
459343	12-Dec-18	Cancelled during entry
458981	13-Dec-18	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
458982	13-Dec-18	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
459483	13-Dec-18	remove blockage in air line
459493	14-Dec-18	Park brake comes on over bumps
459495	14-Dec-18	Holes in hopper & rubber flaps U/S
459528	14-Dec-18	joy stick on remotes sticking replace with reco set
459530	15-Dec-18	replace light
459566	15-Dec-18	replace zoom cylinder
459608	16-Dec-18	repair remote set
459814	17-Dec-18	replace swing tube cutting ring
460144	19-Dec-18	repair chem fault
460160	19-Dec-18	replace joy stick
459888	20-Dec-18	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
460401	21-Dec-18	Jump start
460427	21-Dec-18	swing tube timing, clean up shot crete. swing tube covering
460314	21-Dec-18	Cabin leaks water when washing (seals & windows).
460453	22-Dec-18	Weld crack in drivers door
459914	23-Dec-18	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
460473	23-Dec-18	concrete pump swing fault. recharge accumulator.
460500	23-Dec-18	check front brakes for wear change out axle if required.
460873	24-Dec-18	Check concrete pump timing, cylinder by-passing
460881	24-Dec-18	concrete pump timing, accumulator low on charge. recharge to
460882	24-Dec-18	a/c fault, condensor u/s. may have a slow leak.
460355	27-Dec-18	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
460977	27-Dec-18	reverse camera not working.
461061	28-Dec-18	replace broken fittings on boom
461091	28-Dec-18	remotes stopped working - joystick?
454136	29-Dec-18	fit chem strainer inline to reduce blockages
460356	29-Dec-18	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER

461115	29-Dec-18	replace fittings on boom
461134	30-Dec-18	Retarder not pulling up very well
461165	30-Dec-18	hydroscler hose
461170	30-Dec-18	broken hydraulic fitting, top up oil
461475	31-Dec-18	chem meter fault using to much chem
461515	1-Jan-19	Pressure washer wand leaking
461516	1-Jan-19	L/H swing cylinder still leaking - SEE 462635
461619	2-Jan-19	replace pressure washer trigger
461620	2-Jan-19	Chem pump not working electrical- running on manual for now
461558	3-Jan-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
461984	3-Jan-19	Replace rear camera
461985	3-Jan-19	Replace Pos 1 tyre
461992	3-Jan-19	Chem fault, pump not turning
462122	4-Jan-19	Air con u/s
461998	4-Jan-19	Hand held radio charger not charging
461559	5-Jan-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
462158	5-Jan-19	No throttle
462162	5-Jan-19	pos 4 flat
462163	5-Jan-19	Lost throttle
462208	6-Jan-19	hopper need sealing at hinge joint.(leaking around front
462233	6-Jan-19	Re-torque pos 1 and 4 tyres
462234	6-Jan-19	Blown carrier hose
462289	7-Jan-19	Replace work lights
462299	7-Jan-19	Jack leg fault
462308	7-Jan-19	Check A/C stopped working
462309	7-Jan-19	Repair and replace vibrator
462310	7-Jan-19	Air seat not working
462256	7-Jan-19	Exhaust brake not working properly---Refer WO 461134---
462431	8-Jan-19	Chem fault
462447	8-Jan-19	Concrete pump fault
461720	9-Jan-19	replace fitting on LH swing tube cylinder
462530	9-Jan-19	Jack leg fault. Load sense coil.
462376	10-Jan-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
462628	10-Jan-19	repair rotation head oil leak
462635	10-Jan-19	replace rhs piston pump cup & LH swing cyl
462009	11-Jan-19	replace wash down pump for Mick
462676	11-Jan-19	Remotes not connecting
462683	11-Jan-19	Chem fault - ongoing, valve didn't fix it.
462703	11-Jan-19	zoom stuck on first stage
462705	11-Jan-19	check chem fault
462377	12-Jan-19	1000 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
462766	13-Jan-19	Electrical fault, no hydroscler,conc,vibe,pressure washer
462768	13-Jan-19	A/C u/s
462785	13-Jan-19	park brake not releasing
462802	14-Jan-19	Replace fan hub
462942	14-Jan-19	adjust jack leg proxy
461621	16-Jan-19	Repair wiring to portable 2way charger
461719	16-Jan-19	replace joy stick in spare remotes

463415	16-Jan-19	a/c u/s
463030	17-Jan-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
463031	17-Jan-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
463565	17-Jan-19	Check hopper proxy switch wiring
463576	17-Jan-19	a/c fault.
463731	18-Jan-19	air blockage, adjust chem, clean strainer
463740	19-Jan-19	a/c u/s. low on gas.
463847	20-Jan-19	fit up remote condensor a/c
464008	21-Jan-19	Broken fitting on swing cylinder
464158	22-Jan-19	vibrator stopped, started working again.
461723	23-Jan-19	repair spare remote set
461514	24-Jan-19	Form oil reel stopper U/S
464087	24-Jan-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
464088	24-Jan-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
464375	24-Jan-19	change tee peice on boom
464379	24-Jan-19	replace pivot pin and bushes
464489	26-Jan-19	repair wiring at the diagnostic plug
464491	26-Jan-19	wiring fault at diagnostic plug
464563	27-Jan-19	check brake accumulator light coming on - nothing found
464576	28-Jan-19	replace front zoom cylinder
464603	28-Jan-19	check hyd's surging
464604	28-Jan-19	replace hydroscale hard pipe
464613	28-Jan-19	chem blocked - flushed out
464615	28-Jan-19	change 10m bull hose
464788	29-Jan-19	chem pump fault not metering correctly
464923	29-Jan-19	wash out chem tank
464703	30-Jan-19	REPLACE HYDRAULIC OIL & FILTERS.
465092	30-Jan-19	replace rh swing cylinder
464743	31-Jan-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
465220	31-Jan-19	recharge swing tube accumulator
465262	1-Feb-19	brake charge fault. brake charge not charging correctly.
465263	1-Feb-19	reverse camera u/s.
465275	1-Feb-19	pos 2 puncture.
465380	3-Feb-19	bracket on rh side of cabin repair.
465381	3-Feb-19	clean machine.
465538	4-Feb-19	repair concrete leaking from swing tube crank seal.
465566	4-Feb-19	no start - cracked fuel filter housing
465846	5-Feb-19	replace the fan belt tensioner. pulley is worn.
465880	5-Feb-19	replace blown concrete pump hose
464775	6-Feb-19	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
465992	6-Feb-19	replace wiper arm and blade. replace amber led flashing
465170	7-Feb-19	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
465627	7-Feb-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
465628	7-Feb-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
466068	7-Feb-19	replace 3m bull hose
466071	7-Feb-19	check hyd's surging
466075	7-Feb-19	replace joy stick
466078	7-Feb-19	replace 10 mtr bull hose

465240	8-Feb-19	Rebuild Swing tube and agitator
466103	8-Feb-19	replace blown hose
466158	9-Feb-19	chem pump u/s
466178	9-Feb-19	replace hyd hose off pump
466224	10-Feb-19	replace blown cab hose
464371	11-Feb-19	Check & replace concrete pump hydraulic return filter
466744	11-Feb-19	replace retainer plate on boom
466753	11-Feb-19	replace extension rear hopper
466754	11-Feb-19	replace hose under cab
466255	11-Feb-19	No chem flow warning still present
466823	14-Feb-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
467081	14-Feb-19	Hyd. pump surging again
467113	15-Feb-19	general repairs and check over. (greased, checked boom,
467173	16-Feb-19	remote fault swap out remotes.
467197	16-Feb-19	change flat tyre pos 1
467216	16-Feb-19	retension pos 1 wheel.
467217	16-Feb-19	blown hyd hose behind cabin.
465677	18-Feb-19	LHS steering pin and bush
465940	18-Feb-19	Rebuild spraying nozzle
466853	18-Feb-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
467941	19-Feb-19	fix oil leak under cab
466854	20-Feb-19	CHANGE CHEMICAL (ACCELERATOR) PUMP HOSE.
468071	20-Feb-19	replace wear plate and cutting ring
468074	20-Feb-19	acid clean radiator and condensor unit before service
468076	20-Feb-19	replace all boom slides
468106	20-Feb-19	replace fan belt
467887	21-Feb-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
468126	21-Feb-19	brake charge fault, brake pressure bleeding off constantly.
468161	21-Feb-19	rubber caught in airline
468222	22-Feb-19	disasemled brake charge valve block , cleaned bits of
468201	22-Feb-19	WINDSCREEN LEAKS
468202	22-Feb-19	CHEM FLOW FAULT STILL PRESENT
468263	23-Feb-19	broken banana levers on boom , no parts
468286	23-Feb-19	check low power - cleaned out brake valve again
468291	23-Feb-19	replace remotes
464413	24-Feb-19	test boom functions slow and no power
464414	24-Feb-19	swing tube fault ?? Calibrate ???
465541	25-Feb-19	repair cover over hydraulic cooler so it is easy
468365	25-Feb-19	Hydroscaller U/S
468614	25-Feb-19	clean hyd system and brake valve , ajust pressures
468615	25-Feb-19	hydroscalier not working
468616	25-Feb-19	replace the banana arms
467913	26-Feb-19	500 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
468885	26-Feb-19	replace nozzle bull hose tube
468939	27-Feb-19	chem tank damaged over pressureize damaged top
468684	28-Feb-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
468994	28-Feb-19	Chem strainer bent and often clogs
469066	1-Mar-19	air gauge behind cabin u/s. change out.

469208	1-Mar-19	Low battery voltage, not starting
469280	3-Mar-19	blown carrier hose.
468721	4-Mar-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
469358	4-Mar-19	hyd return filter leaking oil. to be changed out when parts
469370	4-Mar-19	check oil leak on return filter.
469377	4-Mar-19	operator cabin door strut needs replacing
468854	5-Mar-19	REPLACE DAMAGED WHEELS
469490	5-Mar-19	replace hydro scaler hose.
469752	6-Mar-19	no start. rct fuel cap module u/s.
469803	6-Mar-19	repair remotes, replace joystick.
469827	6-Mar-19	clean chem pump strainer
469450	7-Mar-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
469910	8-Mar-19	handheld cradle not bolted down
472138	9-Mar-19	tow off wall
472144	9-Mar-19	repair chem flow
472148	9-Mar-19	zoom tube stuck - tram to surface
472222	10-Mar-19	replace drivers mirror
472224	10-Mar-19	replace drivers mirror
469480	11-Mar-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
472259	11-Mar-19	replace bushes in boom in pivot end
472261	11-Mar-19	replace boom pin and bushes
472739	11-Mar-19	replaced main dcv feed hose
472292	12-Mar-19	cracked mirror and bent mirror arm
472294	12-Mar-19	H/held charger loose
469487	13-Mar-19	Replace front axle - oil is getting diluted.
472814	13-Mar-19	Boom creeps when washing out
472887	13-Mar-19	replace broken mirror
472899	13-Mar-19	replace head light
472902	13-Mar-19	chem pump not working
472682	14-Mar-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
472936	14-Mar-19	chem pump not working and replace vibrator
472921	14-Mar-19	Windscreen still leaking
472923	14-Mar-19	Hoper work light loose
472982	15-Mar-19	replace a/c filters.
473019	15-Mar-19	flush chem lines and check over chem pump
473050	16-Mar-19	flow test chem pump. ok.
473094	17-Mar-19	engine overheating wash coolers.
473095	17-Mar-19	pressure washer working intermittently.
473096	17-Mar-19	change out remotes, plug on underside damaged.
472740	18-Mar-19	turn rotation motor 180deg next service day. oil level holes
473230	18-Mar-19	Nozzle tube bent
473308	18-Mar-19	delivery line going over the cab is u/s. change out.
473310	18-Mar-19	remotes u/s lh joystick faulty. change out joystick.
473344	19-Mar-19	exhaust brake u/s
472713	20-Mar-19	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
473392	21-Mar-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
473879	22-Mar-19	hit wall check damage to machine
473906	23-Mar-19	replace blown hose

473949	24-Mar-19	replace wiper blade
473962	24-Mar-19	chem flow issue / blockage
473978	24-Mar-19	repair nozzle damage
473425	25-Mar-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
473991	25-Mar-19	hydraulic cooler shroud u/s
473992	25-Mar-19	chem pressure guage
474493	26-Mar-19	start fault / no power
474539	26-Mar-19	broken fitting y piece
474193	26-Mar-19	HOpper leaks R/H side
474716	27-Mar-19	chem hose
474601	27-Mar-19	Reverse camera cuttin in and out
474602	27-Mar-19	Hyd pump starting to surge again
474404	28-Mar-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
474758	28-Mar-19	replace fan belt idler pulley.
474771	28-Mar-19	jump start, batteries u/s?
474829	29-Mar-19	repair and straighten nozzle. service day.
474834	29-Mar-19	hydroscler leak and head damage.
474862	29-Mar-19	clean and flush chem lines as blocked
474405	30-Mar-19	1500HR SWING TUBE SEALS CHANGE OUT
474896	30-Mar-19	make up chem strainer.
474978	31-Mar-19	boom zoom jamming up.
474982	31-Mar-19	leaking chem fitting.
474436	1-Apr-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
475144	1-Apr-19	Hose hanger bent
475439	2-Apr-19	front windscreen badly pitted plan in for replacement.
475440	2-Apr-19	change out front and rear axle oils badly burnt.
475455	2-Apr-19	replace shotcreter remotes
475456	2-Apr-19	check out oil leak under cab, replace pressure reducing
475539	3-Apr-19	replace nozzle rotation joy stick.
475553	3-Apr-19	hydrascaler u/s cracked body.
475533	3-Apr-19	alternator belt slipping
475534	3-Apr-19	remote knob missing
475380	4-Apr-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
475672	4-Apr-19	hose rack ben
473855	5-Apr-19	Fit new camera to offside of machine
475381	5-Apr-19	1000 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
476362	5-Apr-19	check charge fault
468203	8-Apr-19	lhs front parker light cracked - part ordered
476785	9-Apr-19	replace smashed windscreen
476813	9-Apr-19	replace boom hose
476866	10-Apr-19	check alt/ fan belt slipping
477016	10-Apr-19	replace blown hose on boom
476733	11-Apr-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
477088	11-Apr-19	replace 10m bull hose
477157	12-Apr-19	Chem running out of nozzle, check one way check valve
477165	12-Apr-19	Repair door lock
477189	13-Apr-19	replace 2.7m delivery line.
477255	14-Apr-19	Chem fault

476769	15-Apr-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
477340	15-Apr-19	Replace pressure washer
477347	15-Apr-19	Replace hopper plate seal
475333	16-Apr-19	Repair wiper linkages
477401	16-Apr-19	Fuel key not working on surface tank
477715	16-Apr-19	Trouble starting
475476	17-Apr-19	Replace swing tube crank support bearing
477848	17-Apr-19	a/c not getting cold . Condensor blocked , clean out
477853	17-Apr-19	replace lh joystick.
477665	18-Apr-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
477935	18-Apr-19	replace Y67 valve spool and coil
477937	18-Apr-19	replace pressure washer lance
478053	20-Apr-19	Repair leaking pressure washer
478077	21-Apr-19	electrical fault with the hopper
477696	22-Apr-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
477919	22-Apr-19	sample engine oil
478149	22-Apr-19	replace starter motor
478150	22-Apr-19	wash out a/c condenser
478151	22-Apr-19	replace horn
478183	23-Apr-19	rear centre support bearing for driveline has movement
478568	23-Apr-19	Vibrator not working
478571	23-Apr-19	concrete pump piston seals u/s
478496	25-Apr-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
478497	26-Apr-19	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
478870	26-Apr-19	Replace pressure washer lance
479272	29-Apr-19	replace boom zoom slides.
478529	29-Apr-19	CHANGE CHEMICAL (ACCELERATOR) PUMP HOSE.
479255	29-Apr-19	check over chem operation. calibrate chem.
479314	30-Apr-19	replace nozzle tilt adapter lever.
479315	30-Apr-19	replace rear grease injector block for the swing tube etc.
479501	30-Apr-19	chem issue. check over system with normet.
479376	2-May-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
479791	2-May-19	top hyd. oil, check leaks
479884	4-May-19	top hyd oil
479885	4-May-19	changed remotes
479907	5-May-19	concrete pump issue ???
479464	6-May-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
479951	6-May-19	making some spare remote leads
479465	7-May-19	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
480553	7-May-19	front window needs replacing
480555	7-May-19	main boom pivot pins & bushes need replacing
480724	7-May-19	replace pos2 tyre
480662	9-May-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
480873	9-May-19	rubber seal in airline, cleared out all good
480920	9-May-19	Hopper leaking on LHS
480965	9-May-19	hyd oil getting hot, repair wiring to cooler fan.
480966	9-May-19	vibrator not working efficiently, rubber mounts worn out.
480968	9-May-19	hopper grate mounting/hinge rubbers u/s.

481122	11-May-19	Install chem strainer on SC08 (same as SC09 arrangement)
481165	11-May-19	Engine belt squealing
481260	12-May-19	pressure washer and hydroscaler fault cutting in and out.
480404	13-May-19	Replace RHS live end steer cyl. pin & bush
480697	13-May-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
480558	14-May-19	door hinges need replacing
480586	14-May-19	form oil gun needs replacing. pressure washer handle
481766	16-May-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
482053	16-May-19	pressure washer on/off button broken
482076	17-May-19	replace hyd. oil cooler fan
482196	19-May-19	blown tyre
481801	20-May-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
482279	20-May-19	replace vibrator
482282	20-May-19	REPLACE COMPLETE BOOM ASSEMBLY
482283	20-May-19	replace pressure washer switch box
481704	21-May-19	Replace wiper assembly
481802	21-May-19	500 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
482678	22-May-19	check fan belt ??? - nothing found
482411	23-May-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
482702	23-May-19	wet box tap u/s
482703	23-May-19	swing tube oil leak
482859	24-May-19	Top up engine & hyd. oils
482927	26-May-19	swing tube wear ring missing. replace.
482932	26-May-19	chem fault. chem only working on full manual. fit strainer.
482455	27-May-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
483180	27-May-19	chem issue reported by operator. couldnt fault.
483181	27-May-19	zoom cylinder leaking from wiper seal. change out cylinder.
483187	27-May-19	brake charge pressure bleeding off with engine
483227	28-May-19	change out wipers.
483244	28-May-19	replace boom support rubber pads.
483631	29-May-19	swing tube cylinder hose u/s.
483675	29-May-19	Alternator u/s
483285	30-May-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
483840	30-May-19	replace pos 3 tyre
483863	30-May-19	chem issue / clean out chem filter
483890	31-May-19	replace boom slides
483973	1-Jun-19	cleaned out chem strainer
484016	2-Jun-19	check chem fault
484031	2-Jun-19	replace wiper blades
484134	3-Jun-19	replace joy stick
484154	3-Jun-19	fit bigger chem strainer
483336	3-Jun-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
484297	4-Jun-19	repair exhaust brake
484319	4-Jun-19	repair start fault & repair reverse camera
484411	5-Jun-19	replace floor mat
484412	5-Jun-19	door rubber seal needs replacing
484414	5-Jun-19	Hopper guard cracked and leaking
484250	6-Jun-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES

484860	7-Jun-19	Concrete pump tripping out, air pressure low
483939	8-Jun-19	chem pump control valve block needs replacing
484283	10-Jun-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
484146	11-Jun-19	boom rotation motor sight glass needs replacing
485635	11-Jun-19	front axle trunion worn. plan in when front axle change out
485644	11-Jun-19	chem cutting out on auto whilst spraying.
484403	12-Jun-19	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
485552	13-Jun-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
485969	13-Jun-19	replace hydro scailer hose
486205	15-Jun-19	second stage jamed on boom
486238	16-Jun-19	replace chem flow meter
486249	16-Jun-19	chem fault / fit new valve assembly and test
486268	16-Jun-19	repair no chem
485590	17-Jun-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
486424	17-Jun-19	replace pos 2 tyre
485633	18-Jun-19	swing tube has play in the swing clevis to input shaft.
485634	18-Jun-19	repair damage to lh side of machine around rear control box
485636	18-Jun-19	front axle pins and bushes worn on struts.
486474	18-Jun-19	chem issue not pumping correctly
486572	18-Jun-19	replace swing cylinder on hls
485846	19-Jun-19	Chem pump faulty - pump ordered
486714	19-Jun-19	replace chem hose
486729	19-Jun-19	repair chem leak
486519	20-Jun-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
486774	20-Jun-19	start fault change out remote set.
486779	20-Jun-19	pos 1 puncture.
486748	20-Jun-19	Check a/c - not real cold
486749	20-Jun-19	check retarder operation - exhaust brake
486852	21-Jun-19	Delivery lines blocked
486977	23-Jun-19	a/c fault clean out condensor.
486995	23-Jun-19	Vibrator not working
486554	24-Jun-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
487319	24-Jun-19	Wiper motor u/s
487643	26-Jun-19	repair chem leak, loose fitting.
487431	27-Jun-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
487713	27-Jun-19	replace remote on/off switch
487734	27-Jun-19	check rear camera and clean out lense and seal up
487920	29-Jun-19	refit window
487921	29-Jun-19	repair chem tank
487975	30-Jun-19	a/c compressor u/s
488356	2-Jul-19	not working on auto & leaking chem fitting in tank
488371	2-Jul-19	replace replace hydra scailer nozzle & hose
487467	3-Jul-19	1000 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
488509	3-Jul-19	replace hydra scailer hose - HOSE C4405 WORK BENCH
488513	3-Jul-19	replace pos 4 tyre
488541	3-Jul-19	repair discharge nozzle
488542	3-Jul-19	retorque pos 4 wheel
488306	4-Jul-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES

488583	4-Jul-19	Inside door latch not holding
488598	4-Jul-19	Front hard line damaged
488638	4-Jul-19	pos 4 flat tyre.
488672	5-Jul-19	Chem tank breather blocked
488689	5-Jul-19	replace remote set remotes not working.
488341	8-Jul-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
488882	8-Jul-19	chem fault, blocked.
489338	9-Jul-19	chem blockage.
489340	9-Jul-19	jump start.
489521	10-Jul-19	replace pressure washer activation button.
489263	11-Jul-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
489601	11-Jul-19	needs x2 front wiper blades
488642	12-Jul-19	front windscreen cracked.
489614	12-Jul-19	replace front windscreen
489674	12-Jul-19	chem pump not turning off
489699	13-Jul-19	chem pump not working on auto
489742	14-Jul-19	replace belt tensioner and belt
489296	15-Jul-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
489915	15-Jul-19	replace hopper cutting ring
489917	15-Jul-19	replace all wheels
489918	15-Jul-19	replace broken fitting on rear diff
490244	16-Jul-19	No hyd's & brake fault
489424	17-Jul-19	Cabin fills with water
490388	17-Jul-19	weld up hopper dump plate
490194	18-Jul-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
490522	19-Jul-19	chem pump fault on auto. spool jammed.
490529	19-Jul-19	replace 10m delivery line.
490545	19-Jul-19	Rear camera bracket broken
490546	19-Jul-19	Operator reported oil leak @ swing cylinder
490638	21-Jul-19	no chem on auto, replace chem proportional spool.
490220	22-Jul-19	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
490838	23-Jul-19	Program chem dosage same as SC09
490922	23-Jul-19	Chem not working on auto
490929	23-Jul-19	Loosing boom movements intermittently
491026	25-Jul-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
491272	25-Jul-19	chem fault on auto - ongoing had to go back to work
491290	25-Jul-19	lost all boom functions
491376	27-Jul-19	change hyd oil & filters
491061	29-Jul-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
491604	29-Jul-19	replace rhs swing cyl
491830	30-Jul-19	Chem pump fault
491062	31-Jul-19	CHANGE CHEMICAL (ACCELERATOR) PUMP HOSE.
491984	31-Jul-19	1500HR SWING TUBE SEALS CHANGE OUT
492082	31-Jul-19	drawing air into concrete pump
491702	1-Aug-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
492252	2-Aug-19	brake accumulator pressure low.
492304	3-Aug-19	brake accumulator light coming on, no boom power,
492377	4-Aug-19	exhaust brake u/s. wiring u/s repair.

492383	4-Aug-19	replace chem strainer. corroded.
491795	5-Aug-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
492420	5-Aug-19	Brake accumulator light coming on
492850	6-Aug-19	Air blockage at mixer due to air hose seal going through
492863	6-Aug-19	hydra scaler hose at nozzle u/s.
491796	7-Aug-19	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
492977	7-Aug-19	Replace boom slides
493055	7-Aug-19	repair hopper light flickering.
492784	8-Aug-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
493084	8-Aug-19	replace chem hose
493174	9-Aug-19	check chem flow on auto / manual
493195	9-Aug-19	seat not pumping up - repaired wiring
493196	9-Aug-19	replace seat belt
493197	9-Aug-19	adjust jackleg sensors
493227	10-Aug-19	ajust manual flow switch
493257	11-Aug-19	replace reverse camera
493265	11-Aug-19	a/c loosing gas in the evap
492816	12-Aug-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
493953	13-Aug-19	replace chem pump / by normet
493955	13-Aug-19	repair rear hopper
493971	13-Aug-19	brake charge fault
493972	13-Aug-19	aircon fault
493973	13-Aug-19	replace fan belt
493974	13-Aug-19	replace hungry board
493975	13-Aug-19	check excessive movement in seat base
493079	15-Aug-19	replace chem pump assembly
493891	15-Aug-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
494165	15-Aug-19	A/C U/S
493157	16-Aug-19	Normet to come to site and repair chem fault
494288	16-Aug-19	pos 1 puncture.
493892	17-Aug-19	500 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
494403	18-Aug-19	blown hose.
494557	19-Aug-19	hydra scaler u/s, leaking from segments.
494594	20-Aug-19	replace fitting on chem strainer. pump side.
494601	20-Aug-19	chem not working on auto,manual tap cant be adjusted.
494755	20-Aug-19	chem manual valve not shutting off when in off position.
494762	20-Aug-19	replace the manual chem shut off tap.
494923	21-Aug-19	swing tube fault, adjust accumulator pressure to 60bar.
494930	21-Aug-19	Swing tube & concrete pump slow @ 1500 RPM
494931	21-Aug-19	Boom zoom jamming up, Vibrator no working
494672	22-Aug-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
494992	22-Aug-19	replace 10m Delivery hose
494993	22-Aug-19	Windscreen wiper missing
495023	22-Aug-19	hopper plate bent
495024	22-Aug-19	hydro scaler not working
495025	22-Aug-19	no chem on auto
494240	23-Aug-19	replace the air conditioning condensor.
495086	23-Aug-19	check boom speeds

494709	26-Aug-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
495184	26-Aug-19	replace joy stick in remotes
495216	26-Aug-19	repair form oil electrical fault
495944	27-Aug-19	repair bad earth on hopper switch
496108	27-Aug-19	replace blown hose under chem tank
496174	28-Aug-19	Please check hand held charger working
496175	28-Aug-19	Check all window wipers are working/ check wiper blades
496176	28-Aug-19	Check A/C vent mount is cracked
496265	28-Aug-19	replace blown hose under chem tank
496266	28-Aug-19	replace blown hose
495883	29-Aug-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
496348	30-Aug-19	Hydra scaler not working
496349	30-Aug-19	Hopper limit switch not working
496416	31-Aug-19	Pos 2 flat tyre
496425	31-Aug-19	Hydra scaler and vibrator fault
496453	1-Sep-19	form oil pump not working.
496454	1-Sep-19	Repair corroded cable ends at wax pump
496481	1-Sep-19	concrete pump not pumping. resling hoses.
495217	2-Sep-19	replace damaged hose on boom
495913	2-Sep-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
496509	2-Sep-19	Console oil leak
496541	2-Sep-19	Brake charge fault
496797	3-Sep-19	Pressure washer lance u/s
496733	5-Sep-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
497173	7-Sep-19	repair oil leak on chem pump & repair chem leak
496767	9-Sep-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
497258	10-Sep-19	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
497850	10-Sep-19	Replace pressure washer hose
498494	11-Sep-19	replace blown hose
498254	12-Sep-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
498510	12-Sep-19	Replace hydra scaler hose.
498613	13-Sep-19	POS 1 flat
498646	14-Sep-19	tighten hyd suction pipe.
498679	14-Sep-19	Zoom stuck.
498690	15-Sep-19	Nozzle pins and bushes worn - floppy
498736	15-Sep-19	Engine over heating.
498288	16-Sep-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
499195	17-Sep-19	engine warning alarm spn609 fmi12 cnt2, nothing found.
499200	17-Sep-19	10m delivery line u/s
499358	18-Sep-19	Blown hose.
499137	19-Sep-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
499537	21-Sep-19	replace pos 2 tyre
499554	21-Sep-19	replace broken banana bars
499168	23-Sep-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
500019	24-Sep-19	repair chem fault
500105	24-Sep-19	chem not working on auto
500119	24-Sep-19	amber engine fault light on
499871	26-Sep-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES

500397	27-Sep-19	Air con . done blocked filter
500499	28-Sep-19	replace pressure washer lance and nozzle.
500526	29-Sep-19	Slow pumping rate.
500531	29-Sep-19	Replace wiper blades
499908	2-Oct-19	1000 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
501431	2-Oct-19	replace 10m delivery line, blocking up.
500828	3-Oct-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
501469	3-Oct-19	concrete pump pumping slow
501562	4-Oct-19	no pressure to swing tube ram
501606	4-Oct-19	replace a/c blower fan
501611	4-Oct-19	engine overheating - washed coolers
500864	7-Oct-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
501774	7-Oct-19	make a bracket for side tool box
501910	8-Oct-19	repair banana bars and replace bush bearings
501912	8-Oct-19	replace rear hyd cooler fan
501972	10-Oct-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
502489	12-Oct-19	Jump start
502002	14-Oct-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
502539	14-Oct-19	change out batteries going flat.
502541	14-Oct-19	check trans fault on display.
502542	14-Oct-19	windscreen wipers and arms replace.
502583	14-Oct-19	A/c not working
502659	17-Oct-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
503257	18-Oct-19	new belt & tensioner
503258	18-Oct-19	air seat air valve u/s req replacement
503312	18-Oct-19	replace pressue washer nozzle
503421	20-Oct-19	replace fan belt
502689	21-Oct-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
503568	21-Oct-19	repair front work lights
502699	22-Oct-19	re-sample and change oil in Pos 2 wheelend
503733	22-Oct-19	chem fault not pumping
503734	22-Oct-19	replace viribrator
504033	22-Oct-19	pressure washer not working
503835	23-Oct-19	replace chem hose -16 x 5m hose
504042	23-Oct-19	replace vibrator
503660	24-Oct-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
504100	24-Oct-19	Repair e stop fault
504121	24-Oct-19	chem fitting on boom leaking.
504127	24-Oct-19	repair wipers.
503264	25-Oct-19	INSTALL STEREO AND SPEAKERS IN SC08
503267	25-Oct-19	Check operation of a/c blower fan
504169	25-Oct-19	Jump start
504248	27-Oct-19	Hydra scaler leaking water near pos 3 wheel
504249	27-Oct-19	curtain needs repair on front winscreen
504898	28-Oct-19	Top up hyd
503595	29-Oct-19	Check fan belt squealing
503596	29-Oct-19	Check operation of concrete vibrator
503725	29-Oct-19	replace hopper flat

505123	29-Oct-19	boom light u/s.
505139	29-Oct-19	engine overheating
503689	30-Oct-19	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
503806	30-Oct-19	Fit external horn speaker for two way
503823	30-Oct-19	Replace edge rubber on concrete hopper
503824	30-Oct-19	Assess and repair oil leak at centre hitch
505201	30-Oct-19	Replace hydrascaler hose
505202	30-Oct-19	wash radiator
504993	31-Oct-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
505688	1-Nov-19	unblock air delivery valve
505740	2-Nov-19	repair bent hopper door and replace
505040	3-Nov-19	CHANGE CHEMICAL (ACCELERATOR) PUMP HOSE.
505842	3-Nov-19	check chem meter operation
505041	4-Nov-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
506205	5-Nov-19	replace wiper blades
506206	5-Nov-19	replace bull hose
506376	6-Nov-19	check low air pressure
505562	7-Nov-19	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
505587	7-Nov-19	Replace hopper grate vibration dampers
506143	7-Nov-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
506513	8-Nov-19	leaking hose on boom, 1.5m dash 12.
506176	11-Nov-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
506957	11-Nov-19	overheating. clean out radiator.
506191	12-Nov-19	Chemical tank lid, breather to be replaced
506990	12-Nov-19	fitted 2 x washer nozzles.
506991	12-Nov-19	replaced drivers side wiper.
506992	12-Nov-19	fit two bolts in swivel lever bearing end cap.
507044	14-Nov-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
507367	14-Nov-19	jump start
507548	15-Nov-19	over heating / fan hub u/s
507045	16-Nov-19	500 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
507573	16-Nov-19	stuck in drain - tow out
507593	16-Nov-19	replace outer air filter
507601	16-Nov-19	jump start no fuel going to fuel solonid
507609	16-Nov-19	Both in cab isolators (battery & start) require replacement
507637	17-Nov-19	replace both isolators & lugs
507659	17-Nov-19	repair y block nozzle bracket
507717	18-Nov-19	replace wiper blades
507884	19-Nov-19	jump start
508034	20-Nov-19	replace blown hose
507831	21-Nov-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
508102	21-Nov-19	Blown air line to nozzle
507522	22-Nov-19	Fabricate electrical box to test remotes
508234	23-Nov-19	Hydra scaler pump
507715	25-Nov-19	replace front window & seal
507716	25-Nov-19	make front window curtain
507863	25-Nov-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
508348	25-Nov-19	Replace wiper arms

507758	26-Nov-19	replace front light
507759	26-Nov-19	repaired hopper gate valve
508897	27-Nov-19	oil leak at pos 1 wheel. hyd oil.
508693	28-Nov-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
508911	28-Nov-19	hydra scale fault
508993	28-Nov-19	10m delivery line take down and fit
508994	28-Nov-19	Check pressure washer
509008	28-Nov-19	TPS U/S - swapped for one off second pedal
509010	28-Nov-19	Cutter ring and seal worn
509028	28-Nov-19	Replace side pedal tps
509198	1-Dec-19	inspect oil leak ar rear of machine
509205	1-Dec-19	chem issue / auto not working
509223	1-Dec-19	hyd oil leak at rear of machine
508727	2-Dec-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
509349	2-Dec-19	check operators seat
509388	2-Dec-19	chem fault
509565	5-Dec-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
510229	6-Dec-19	fault, additive pump pulse missing.
510230	6-Dec-19	fan belt squealing constantly.
509594	9-Dec-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
510477	9-Dec-19	zoom slides u/s.
510478	9-Dec-19	h-frame bushes worn on boom.
510488	9-Dec-19	remote lead u/s.
510843	11-Dec-19	pos 1 puncture.
510594	12-Dec-19	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
510595	12-Dec-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
511136	12-Dec-19	check front windscreen / rock fall
510218	13-Dec-19	replace pressure washer gauge
511333	13-Dec-19	Remote fault
511360	13-Dec-19	replace hopper door
511415	14-Dec-19	Replaced brocken hyd fitting
511418	14-Dec-19	replace y piece
511429	14-Dec-19	replace pos 1 tyre
511446	15-Dec-19	Retorque pos 1
511475	15-Dec-19	Pulse sensor for chem pump playing up
511491	15-Dec-19	replace turbo head on pressure washer
511493	15-Dec-19	replace blown hose in center hitch
511452	15-Dec-19	Fan belt Noisy
510547	17-Dec-19	LHS steer cylinder pin and bearing live end to be replaced
511659	19-Dec-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
511660	22-Dec-19	1500HR SWING TUBE SEALS CHANGE OUT
512252	22-Dec-19	hyd oil leak swing cylinder. pump cover.
512267	22-Dec-19	shot crete pumping piston u/s, delaminated lh side.
511697	23-Dec-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
512669	24-Dec-19	blown hose on boom.
511903	25-Dec-19	Brake charge fault
511971	26-Dec-19	Replace form oil hose reel assembly--PART HERE 7/1/20--
512438	26-Dec-19	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES

513085	27-Dec-19	red alarm 1035- coolant temp
512468	30-Dec-19	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
513401	30-Dec-19	replace external speaker two way
513403	30-Dec-19	replace lh window wiper boss a wiper blades
513563	31-Dec-19	RH Wiper arm missing
513564	31-Dec-19	No hand held radio
513788	1-Jan-20	Exhaust brake not working
513511	2-Jan-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
514075	2-Jan-20	Vibrator not working
513133	4-Jan-20	Replace wiper blades
513134	4-Jan-20	Check chem pump operation on auto
513135	4-Jan-20	Check nozzle head assembly - loose / worn pins
514257	5-Jan-20	Replace 3m delivery line
514428	6-Jan-20	Hopper hungry board
513547	8-Jan-20	1000 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
514699	8-Jan-20	Replace reverse camera
514529	9-Jan-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
514857	9-Jan-20	Rock fall on boom
514905	9-Jan-20	rear pinion seal leaking
515094	11-Jan-20	Low air pressure
514405	13-Jan-20	Rear diff to be changed. (Brake pack at wear limit)
514561	13-Jan-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
515581	13-Jan-20	Swing tube not working
515593	13-Jan-20	ajust and check exhaust brake
515599	13-Jan-20	pumping in reverse
514959	14-Jan-20	Re-sample engine oil.
515764	14-Jan-20	Replace boom lever and Banana bar pins & bushes
515788	14-Jan-20	Check rear diff level
515691	16-Jan-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
516030	17-Jan-20	Replace door lock
516045	17-Jan-20	workorder to capture missing parts from store not booked out
516123	18-Jan-20	check alternator charge. critical low voltage.
516158	19-Jan-20	Charge fault
515727	20-Jan-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
516303	20-Jan-20	Replace Delivery Line U/S
516438	20-Jan-20	Replace belt tensioner
516467	20-Jan-20	change out concrete 2 inch hose.
516469	20-Jan-20	replace lights at front and rear of machine.
516470	20-Jan-20	replaced broken bolt at swing tube front bush mount.
516623	21-Jan-20	retension pos 3 and 4 wheels.
515080	22-Jan-20	No windscreen wipers
516712	22-Jan-20	replace chem hose and hyd hose
516787	22-Jan-20	replace hopper vibrator u/s stopped working.
516791	22-Jan-20	exhaust brake not working.
516554	23-Jan-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
517248	23-Jan-20	replace pressure washer nozzle
517287	23-Jan-20	hydroscaier leaking or hose
517348	24-Jan-20	eletrical fault at afff box

517403	25-Jan-20	blown hoses above diff
516582	27-Jan-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
517516	27-Jan-20	Lhs concrete pump cylinder scored
517614	27-Jan-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
516468	28-Jan-20	Replace front diff--PARTS HERE-- Making oil
516583	28-Jan-20	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
517725	28-Jan-20	engine water pump failed
518112	29-Jan-20	jump start
517615	30-Jan-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
518218	30-Jan-20	change out remotes, joysticks not engaging intermittently.
518300	31-Jan-20	changed nozzle cylinder hose.
518356	1-Feb-20	tighten up hoses.
518370	1-Feb-20	lost boom movements - fault on control panel
518375	1-Feb-20	check pressure relief valve on chem tank
518419	2-Feb-20	replace exhaust brake actuator, u/s.
518460	2-Feb-20	check concrete pump - bit sluggish
518461	2-Feb-20	check chem check valve - replace y piece
518399	2-Feb-20	hydroscler is weak
517515	3-Feb-20	replace alternator pulley
517669	3-Feb-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
517670	3-Feb-20	CHANGE CHEMICAL (ACCELERATOR) PUMP HOSE.
518694	3-Feb-20	check nozzle movements hitting fittings, going to far.
515009	4-Feb-20	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
516921	5-Feb-20	Chem level glass U/S
518967	5-Feb-20	replace boom lift cylinder pin and bush.
518058	6-Feb-20	REPLACE HYDRAULIC OIL. CHECK SOS HISTORY BEFORE STARTING AS
518059	6-Feb-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
519200	7-Feb-20	repair no chem flow
518770	10-Feb-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
519030	12-Feb-20	form oil hose reel to be replaced.-REFER WO 511971--
519969	13-Feb-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
520515	13-Feb-20	replace vibrator - u/s
520519	13-Feb-20	remote lead changeout
520520	13-Feb-20	hydrascaler hose leaking
520628	14-Feb-20	air fault - while trying to spray
520763	16-Feb-20	replace blown hyd hose on concrete pump.
520764	16-Feb-20	replace blown hyd hose at cooler.
519428	17-Feb-20	drivers window / damage
520010	17-Feb-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
520011	17-Feb-20	500 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
521052	17-Feb-20	operator reported not enough chem whilst spraying.
521053	17-Feb-20	pressure washer reel mount cracked, repair.
521054	17-Feb-20	tidy up boom hoses replace hydra scaler hose.
521173	17-Feb-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
521263	18-Feb-20	engine overheating, clean out radiator.
521439	19-Feb-20	engine overheating radiator blocked.
521440	19-Feb-20	form oil not working.
521174	20-Feb-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES

521470	20-Feb-20	Wear ring and cutting ring stock level
521713	23-Feb-20	replace bolt in water filter
521736	23-Feb-20	check concrete pump speeds ???
521741	23-Feb-20	engine belt come off
521215	24-Feb-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
521798	24-Feb-20	Replace engine oil pressure switch
522129	27-Feb-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
522609	27-Feb-20	replace chem hose and fitting
522610	27-Feb-20	overheating - wash out radiator
522576	27-Feb-20	Won't stay at stable pump speed below 16m3/hr
522681	28-Feb-20	zoom getting stuck clect/ clean slides
522682	28-Feb-20	air seat not working - repaired wiring
522701	29-Feb-20	windscreen wiper not working.
522725	29-Feb-20	chem leak and dash 8 hose.
522726	29-Feb-20	blown dash 8 hose.
522731	29-Feb-20	replace leaking zoom hose
522800	1-Mar-20	hyd oil leak off zoom fitting.
522170	2-Mar-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
522961	2-Mar-20	top up hyd oil.
522975	2-Mar-20	assess slop in centre hitch pins top and bottom.
522977	2-Mar-20	install air on/off switch into spare remotes.
523183	3-Mar-20	air hose on boom u/s.
523215	3-Mar-20	change hydraulic oil and filter - refer attached SOS #0105
523332	3-Mar-20	wet box wont fill up.
523271	5-Mar-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
523647	5-Mar-20	repair hydroscaier
523672	5-Mar-20	repair water leaks on hydro scailer
523725	6-Mar-20	replace pressure washer gauge
523730	6-Mar-20	replae chem hose
523272	7-Mar-20	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
523302	9-Mar-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
523913	9-Mar-20	wash down concreete pump area
524388	9-Mar-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
524456	10-Mar-20	1500HR SWING TUBE SEALS CHANGE OUT
524389	12-Mar-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
524897	14-Mar-20	replace nozzle rotation motor.
524968	14-Mar-20	repair hopper grate switch.
524969	14-Mar-20	change out chem hose to nozzle.
524970	14-Mar-20	replace 2 x 3m concrete hoses.
524971	14-Mar-20	replace rotation head bolts.
524964	15-Mar-20	replace window wiper.
524991	15-Mar-20	Repair light over hopper
524419	16-Mar-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
525329	16-Mar-20	supply hose to pressure washer reel faulty.
525523	17-Mar-20	engine overheating check radiator.
525666	18-Mar-20	no remotes jack leg sensor adjust pos 1.
525422	19-Mar-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
525728	19-Mar-20	replace remotes / joy sticks not working

525800	20-Mar-20	no remotes
525838	21-Mar-20	Wipers U/S
525839	21-Mar-20	Form oil gun U/S
525840	21-Mar-20	Jack leg sensor playing up
525922	22-Mar-20	joy stick not working lhs
525460	23-Mar-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
525995	23-Mar-20	chem punp hose
525996	23-Mar-20	replace fan belt
526012	23-Mar-20	replace burnt rear diff oil
526019	23-Mar-20	Chem fault, blocked strainer
521809	24-Mar-20	replace boom rubber buffers
521810	24-Mar-20	replace engine oil pressure sensor - used s/h senosr off old
526383	24-Mar-20	Rear camera not working
526480	25-Mar-20	replace main air hose on boom
526197	26-Mar-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
526811	27-Mar-20	remote fault - lead u/s
526835	28-Mar-20	top front lights cutting in and out.
526836	28-Mar-20	reverse camera cutting in and out.
526837	28-Mar-20	chem line on y-piece loose.
526838	28-Mar-20	front wipers not working.
526230	30-Mar-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
527193	30-Mar-20	Replace operators seat
526145	31-Mar-20	Replace steer cylinder live end pins and bushes
526244	31-Mar-20	Tyres worn
527445	31-Mar-20	replace faulty light bar with 2 x work lights.
527446	31-Mar-20	replace boom head tilt mount.
527447	31-Mar-20	repair wiper and washer.
527604	31-Mar-20	check exhaust brake operation.
527608	31-Mar-20	chem leak at y-piece and rear chem hose.
527616	31-Mar-20	replace 2.7m delivery line.
527619	31-Mar-20	rear camera u/s
527758	1-Apr-20	checm fitting repair.
526594	2-Apr-20	Excessive play in nozzle plate
527547	2-Apr-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
527982	4-Apr-20	replace door handle
527983	4-Apr-20	replace nozzle tilt cyl
527992	4-Apr-20	repair hopper door
528045	5-Apr-20	remotes switches not working
528325	6-Apr-20	replace hydroscale hose 1.6m
527580	8-Apr-20	1000 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
528577	9-Apr-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
528882	9-Apr-20	chem pump fault
528975	11-Apr-20	flush chem l;ines and reset chem taps
528993	11-Apr-20	fitting on chem tank leaking.
528994	11-Apr-20	pressure washer not working at all.
528612	13-Apr-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
529078	13-Apr-20	replace fuel cap and fix wiring
529321	14-Apr-20	Exhaust brake not working

529646	14-Apr-20	alternator shaft broke - replace alt and belt and tensioner
528864	16-Apr-20	Replace LH concrete pumping cylinder
529270	16-Apr-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
529929	16-Apr-20	replaced 10 meter soft line
530016	17-Apr-20	CHECK OPERATION OF EXHAUST BRAKE
530071	18-Apr-20	front diff over full
530095	18-Apr-20	remotes & cable ???
529076	20-Apr-20	change out complete boom as all bushes and segments worn
529305	20-Apr-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
530299	20-Apr-20	front diff change over / over full
530300	20-Apr-20	reseal hopper
529322	21-Apr-20	Pressure washer low pressure
529658	21-Apr-20	Diagnose water in hydraulics (should have been fixed)
529659	21-Apr-20	Fit rubber flap over concrete pump area
529661	21-Apr-20	Re-hose first section of boom hoses
529662	21-Apr-20	Auto-sparky service
530585	21-Apr-20	replace pressure washer
529840	22-Apr-20	Replace engine belt pulley
530510	23-Apr-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
530009	24-Apr-20	HAND HELD CHARGER U/S
530015	24-Apr-20	CHECK OPERATION OF PRESSURE WASHER
531394	24-Apr-20	hydra scaler head bent.
531396	24-Apr-20	retorque pos 1 and 2 wheels.
531437	25-Apr-20	swing tube not swinging right across to opposite side.
531457	25-Apr-20	oil leak under cab and check boom lights staying on
531487	26-Apr-20	Oil leaking from brake charge area near lh jack leg.
530547	27-Apr-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
531710	27-Apr-20	concrete pump flow down - change out pump
529657	28-Apr-20	Re-work chem tank overflow
531963	28-Apr-20	replace lh boom light.
532126	29-Apr-20	e-stop fault remote lead u/s.
531802	30-Apr-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
532219	30-Apr-20	check hydro scaler - low pressure
531418	2-May-20	Chem sight glass U/S
532385	2-May-20	elec box getting hot
532403	3-May-20	hyd cooler fan not working
532433	3-May-20	replace hydro scaler hose
531898	4-May-20	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
531899	4-May-20	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
532837	4-May-20	replace main hydroscler hose
532865	4-May-20	hydro scaler hose u/s
532872	4-May-20	check chem pump operation
532873	4-May-20	replace - 12 hose pump supply hose
532874	4-May-20	cleaned out air gauge
532875	4-May-20	replaced -8 hose in center hitch
532877	4-May-20	repair switch in remotes
533378	6-May-20	Chem pump not working
533149	7-May-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES

533551	8-May-20	check chem pump operation
533150	9-May-20	CHANGE CHEMICAL (ACCELERATOR) PUMP HOSE.
533617	9-May-20	clean radiator out and check exhaust brake working
533185	11-May-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
534078	12-May-20	a/c fault low on gas charge.
533186	13-May-20	REPLACE HYDRAULIC OIL. CHECK SOS HISTORY BEFORE STARTING AS
533317	13-May-20	2 Middle hood lights U/S
533318	13-May-20	A/C Noisy
533319	13-May-20	Horseshoe doesn't line up
534412	13-May-20	chem fittings replaced in pump to boom
534271	14-May-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
534706	17-May-20	replace batteries
534311	18-May-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
535084	19-May-20	replace vibrator
535150	19-May-20	replace blown carrier hose
535277	20-May-20	concrete pump fault ??? Shuttering ???
535336	20-May-20	concrete pump fault ???
535031	21-May-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
535481	22-May-20	replace fitting on park brake hose to front axle
535495	23-May-20	form oil not working broken wire to coil.
535496	23-May-20	replace remote lead, cuts in lead.
535497	23-May-20	engine overheating, wash out radiator.
535546	24-May-20	remotes u/s.
535568	24-May-20	remote lead fault - swap out
535070	25-May-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
535917	26-May-20	Replaced Wiper Blade
536129	27-May-20	replace wiper pivots worn out.
536156	27-May-20	replace reverse camera full of water.
536187	27-May-20	chem issue on auto clean out chem lines.
535720	28-May-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
536298	28-May-20	refit boom guard
535756	1-Jun-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
537203	2-Jun-20	replace swing tube cylinder
537370	3-Jun-20	replace u/s chem fitting
537435	3-Jun-20	wiper motor u/s
537162	4-Jun-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
537494	4-Jun-20	Horn stuck on
537507	4-Jun-20	hydra scaler hose loose on nozzle.
537631	6-Jun-20	chem leak loose hose.
537189	8-Jun-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
537717	8-Jun-20	Replace 10m delivery line
537726	8-Jun-20	Throttle fault
537202	9-Jun-20	replace nozzle rotation motor
538303	9-Jun-20	rear bump stop lh side to be replaced, u/s.
537533	10-Jun-20	500 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
537460	11-Jun-20	Hand held charger won't charge
538086	11-Jun-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
538598	12-Jun-20	check wipers for operation

538627	13-Jun-20	repair wiper arms
538628	13-Jun-20	check chem hoses for stainless steel fittings
537644	14-Jun-20	Shotcrete pump turning off when priming up
538119	15-Jun-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
538902	15-Jun-20	replace cutting ring and seal
539251	16-Jun-20	weld up nozzle pipe
539252	16-Jun-20	replace broken chem fitting
539046	18-Jun-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
539492	18-Jun-20	no boom movements.
539526	18-Jun-20	chem hose fitting u/s.
539528	18-Jun-20	hopper gate bent up.
539545	18-Jun-20	Replace cab light
539592	19-Jun-20	hopper grate bent up repair service day.
539610	19-Jun-20	adjust camera.
539655	20-Jun-20	retarder not working.
539712	21-Jun-20	chem fitting u/s.
539076	22-Jun-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
539886	22-Jun-20	Resample Front diff - bad sample
539887	22-Jun-20	Resample POS 1 - bad sample
539888	22-Jun-20	Resample POS 2 - bad sample
539902	22-Jun-20	exhaust brake not working.
540168	23-Jun-20	Door handle u/s
540169	23-Jun-20	remote fault
540207	23-Jun-20	Fan belt U/S
539338	24-Jun-20	Door window seized
539339	24-Jun-20	1 X Flood light U/S
540300	24-Jun-20	rear mudguards bent.
540000	25-Jun-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
540038	29-Jun-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
540763	29-Jun-20	check for air restriction ???
540798	29-Jun-20	remotes not working
540805	30-Jun-20	exhaust brake
541115	30-Jun-20	Hydraulic fault, hydroscale staying on
540284	1-Jul-20	Crack in bracket holding elbow requires welding
541243	1-Jul-20	Replace worn boom slides
541244	1-Jul-20	Replace swing tube pivot bearing
541500	1-Jul-20	hopper plate snapped off
541053	2-Jul-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
541568	2-Jul-20	replace remotes.
541709	5-Jul-20	door stuck shut
540732	6-Jul-20	Very weak boom movements - J Cook
540733	6-Jul-20	Horse shoe bracket needs re-aligning - J Cook
541764	6-Jul-20	replace fitting and hose on chem y piece
541973	6-Jul-20	front axle changeout - oil burnt and brake disc worn
541990	6-Jul-20	replaced blown fuse for lights and fixed wiring
542385	6-Jul-20	replaced missing bolts in swing tube bush housing
541092	7-Jul-20	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
542019	7-Jul-20	Replace hopper seals

542039	7-Jul-20	Exhaust brake actuator U/S
542284	7-Jul-20	Replace drive shaft centre bearing grease nipples with
542216	9-Jul-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
542583	9-Jul-20	exhaust brake not working
542584	9-Jul-20	top up hyd oil
542643	10-Jul-20	Wax gun shorts out rig when turned on - Jim Villella
542675	10-Jul-20	jump start
542749	11-Jul-20	secured hoses and re wrap
542753	11-Jul-20	repair broken spray head
542788	12-Jul-20	chem pump not working
542249	13-Jul-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
543138	13-Jul-20	Check operation of retarder - Retarder U/S - Jin Villella
542021	14-Jul-20	instal inline air strainer
542032	14-Jul-20	Fit camera screen for off side camera
543570	16-Jul-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
542644	17-Jul-20	Air con fan not much puff - Jim Villella
542645	17-Jul-20	Crack in nozzle tube - Jim Villella
544111	17-Jul-20	check exhaust brake working
543603	20-Jul-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
544319	20-Jul-20	unblock all auto greaser lines on swing tube and hopper
544320	20-Jul-20	reposition tranny sight glass breather
544321	20-Jul-20	checked calibration oil transmission oil on dipstick
543527	21-Jul-20	Overheating badly uphill - Jim Villella
543799	22-Jul-20	replace cutting ring & wear plate
543925	22-Jul-20	hopper grate pins & bushs need replacing
544785	22-Jul-20	Check starter motor operation
544454	23-Jul-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
544935	23-Jul-20	chem leak at nozzle
544982	23-Jul-20	jump start
545171	24-Jul-20	jump start
545173	24-Jul-20	replace batteries, found 4pole isolater u/s
544491	27-Jul-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
545472	27-Jul-20	Install Mobilaris hardware
545576	28-Jul-20	centre hitch has free play check service day
546060	29-Jul-20	replace swing cylinder
546073	29-Jul-20	check chem pump operation
546079	29-Jul-20	blown o'ring on concrete pump
545628	30-Jul-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
546107	30-Jul-20	check jack leg fault no load sense.
546108	30-Jul-20	hyd oil leak off swing tube accumulator.
546523	30-Jul-20	non return check leaking on chem line at y-piece.
546600	31-Jul-20	swing tube spigot bearing loose bolts 1 x stripped 16mm
546601	31-Jul-20	pos 2 puncture
545629	1-Aug-20	1000 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
546618	1-Aug-20	Resample POS 2 as per attached sos report
546754	2-Aug-20	no pumping fwd on shotcrete pump.
545447	3-Aug-20	Replace rear hopper seal on changeover shaft
545450	3-Aug-20	Replace leaking swing tube cylinder

545512	3-Aug-20	replace wiper blade
545574	4-Aug-20	remove cooler pack and wash out coolers
545734	4-Aug-20	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
547374	4-Aug-20	banana bar pins and bushes worn.
546037	5-Aug-20	Replace air con condensor
547443	6-Aug-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
547890	7-Aug-20	hydroscailer u/s - unblock nozzle
547916	8-Aug-20	hydroscailer u/s leaking from unit
547917	8-Aug-20	chem fault / flow valve u/s
548027	9-Aug-20	chem stuck on
546714	9-Aug-20	Engine brake u/s
546715	9-Aug-20	Wipers u/s
546716	9-Aug-20	Top lights u/s
547334	10-Aug-20	Replace rear axle - overfilling with oil
547475	10-Aug-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
548346	10-Aug-20	replace wiper blades
548357	10-Aug-20	replace hydroscaier hose
548519	11-Aug-20	replace u/s brake steer pump
548526	11-Aug-20	oil leak in center hitch
548527	11-Aug-20	check over heating
548528	11-Aug-20	retorque pos 3&4
547776	13-Aug-20	repair damaged wiring to boom lights
547777	13-Aug-20	Check jack leg operation.
547794	13-Aug-20	a/c not working
548435	13-Aug-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
548768	13-Aug-20	throttle fault. clean plug and check wiring.
548784	13-Aug-20	replace 2.7m shotcrete hose
548822	14-Aug-20	replace boom folding bump stops.
548845	14-Aug-20	chem non return valve blocked.
548852	14-Aug-20	no chem flow.
548865	14-Aug-20	check pump struggling to pump fwd
548868	14-Aug-20	chem fault line blocked at non return valve
548882	15-Aug-20	chem pump not shutting off. chem fault on auto.
548906	15-Aug-20	remote fault lead u/s.
548950	15-Aug-20	Jack legs not going fully down
548971	16-Aug-20	pumping issue. concrete under swing tube cylinders.
548471	17-Aug-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
549148	17-Aug-20	replace swing tube spigot. worn out.
549159	17-Aug-20	replace hydra scaler, leaking out segment.
549190	17-Aug-20	wet drive near nipper store slid into drain - tow out
548503	18-Aug-20	CHEM FAULT NOT WORKING ON AUTO
549204	18-Aug-20	altenator charging cable covered in green death.
549205	18-Aug-20	lh hopper bent.
549206	18-Aug-20	cleaned chem sight glass replaced fittings.
549211	18-Aug-20	fabricated new remote and lead mount.
548592	19-Aug-20	set brake/steer pump pressures
549510	19-Aug-20	hopper gate switch faulty
549534	19-Aug-20	engine overheating wash out radiator

549535	19-Aug-20	vibrator not working
549536	19-Aug-20	hyd oil leak at swing tube cyl/ accumulator
549282	20-Aug-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
549588	20-Aug-20	replace coolant level sensor
549589	20-Aug-20	need 2.7 m shotcrete hose
548802	21-Aug-20	Chem not turning off at desired
548803	21-Aug-20	Pump not working @ 170 RPM
549312	24-Aug-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
549313	24-Aug-20	CHANGE CHEMICAL (ACCELERATOR) PUMP HOSE.
550098	24-Aug-20	replace operators door hinges
550099	24-Aug-20	replace door seal
550100	24-Aug-20	pressure washer reel needs replacing
549203	25-Aug-20	driveshaft centre bearing worn requires replacement.
549207	25-Aug-20	front windscreen pitted.
549209	25-Aug-20	rh steering cylinder pins and bushes worn.
549314	25-Aug-20	1500HR SWING TUBE SEALS CHANGE OUT
549315	26-Aug-20	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
549450	26-Aug-20	replace hydra scaler mounts.
550610	26-Aug-20	alarm going off in cab ???
550294	27-Aug-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
550712	27-Aug-20	swing tube not swinging across properly.
549549	27-Aug-20	Hopper light stuck on
550812	29-Aug-20	replace nozzle chem Y piece - and check valve u/s
550084	31-Aug-20	replace lights on cab
550329	31-Aug-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
550970	31-Aug-20	blown hose in cabinet on side boom control
550991	31-Aug-20	broken water tap on rear of machine.
551432	1-Sep-20	top up hyd oil
551665	2-Sep-20	operator reported wax not working.
551666	2-Sep-20	repair air fitting on rear of machine.
551085	3-Sep-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
551817	4-Sep-20	replace damaged remote lead
551832	4-Sep-20	REPLACE RH COTTON REEL PLATE & NYLONS
551125	7-Sep-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
552707	10-Sep-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
553059	10-Sep-20	concrete pump pumping issue. pipe blockage.
553062	10-Sep-20	remove bars on hopper grate, shotcrete not passing through.
553093	11-Sep-20	Exhaust brake not working
553094	11-Sep-20	Rear axle overfull
553095	11-Sep-20	Lights on cabin roof dropping out
551834	12-Sep-20	Remote switches for chem and pump are backwards
553225	12-Sep-20	replace chem y block and check valve as snapped off
553461	14-Sep-20	park brake valve faulty, leakage through valve causing
553485	15-Sep-20	reposition oil fitting away from air intake pipe.
553788	15-Sep-20	pos 1 tyre flat
552740	16-Sep-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
552976	16-Sep-20	Workorder to capture costs of Rotable Hopper to suit
552986	16-Sep-20	replace boom slide pieces next service

552990	16-Sep-20	retorque center hitch
553946	16-Sep-20	no throttle, toomuch rubbish behind seat interfering with
553948	16-Sep-20	retorque pos 1 wheel nuts.
553950	16-Sep-20	zoom stuck out, free up.
553870	16-Sep-20	Engine brake u/s
553694	17-Sep-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
553695	18-Sep-20	500 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
554281	19-Sep-20	front throttle not working
554443	21-Sep-20	replace hopper rubber
553755	22-Sep-20	Install grease lines to hopper mounts - replace worn pivots
553757	22-Sep-20	Work order to capture costs of hopper parts used
555001	23-Sep-20	repair pressure washer
554510	24-Sep-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
555161	24-Sep-20	Replaced mine radio antenna was old type (hazard card)
555278	28-Sep-20	chem check valve on y-piece leaking, replace.
555295	28-Sep-20	Door latch u/s unable to open door from outside
555478	28-Sep-20	repair sticky toggle switch on remotes.
555828	29-Sep-20	bend hopper hatch back into shape.
555829	29-Sep-20	remote cable cut repair.
554546	30-Sep-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
556010	30-Sep-20	Jack leg fault
555852	30-Sep-20	Engine brake u/s
555055	1-Oct-20	Poor outgoing comms
555710	1-Oct-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
556114	1-Oct-20	replace blown hose
556446	3-Oct-20	hyd pump noisy ???
556511	4-Oct-20	Oil leak at centre hitch
555750	7-Oct-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
555910	7-Oct-20	One way chem valve at nozzle u/s
556883	8-Oct-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
556330	9-Oct-20	fill up hyd tank
557431	9-Oct-20	blown hose.
556405	10-Oct-20	check exhaust brake
556479	11-Oct-20	replace wiper baldes
557535	11-Oct-20	replace hoses on boom.
557536	11-Oct-20	hopper door bent.
556788	12-Oct-20	CHECK HYD PUMP
556917	12-Oct-20	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
557079	13-Oct-20	hyd pump noisy lost pressure
557080	13-Oct-20	flat tyre pos 2 tyre
557924	13-Oct-20	repaired damaged boom hoses.
557925	13-Oct-20	replaced cab work light.
557926	13-Oct-20	repaired a/c fan switch.
557927	13-Oct-20	concrete pump hyd fault. found small piece of debris in
558190	13-Oct-20	Swing tube slow
557215	14-Oct-20	hyd pump fault ???
558370	14-Oct-20	Replace hose on nozzle
557984	15-Oct-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES

558422	15-Oct-20	Hopper door
557420	16-Oct-20	replace hyd tank breather.
558553	17-Oct-20	steel pipe cracked
558570	17-Oct-20	vibrator u/s. fixed damaged end cap.
557923	20-Oct-20	rear boom pins and bushes worn. will need replacement.
559155	20-Oct-20	replace pressure washer nozzle
559188	20-Oct-20	pos 2 flat tyre
558017	21-Oct-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
559077	22-Oct-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
558644	25-Oct-20	replace damaged fitting on boom
559794	26-Oct-20	Replace wiper blades
559795	26-Oct-20	Top radiator hose U/S
559796	26-Oct-20	Replace pressure washer reel
559154	27-Oct-20	hopper cutting edge needs replacing next service
559156	27-Oct-20	folding boom fault/ pressure sensor - see byron pad
559157	27-Oct-20	nozzle concrete steel pipe needs replacing next service day
559114	28-Oct-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
560172	29-Oct-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
560532	30-Oct-20	lh jack leg sensor broken inside cab
560547	31-Oct-20	blown 1 1/2 air hose to nozzle
560633	1-Nov-20	nozzle tilt cylinder u/s bent
560678	2-Nov-20	replaced front wiper arms and blades
561050	3-Nov-20	unable to slow concrete pump speed??
560276	4-Nov-20	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
560277	4-Nov-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
560920	5-Nov-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
561350	5-Nov-20	Mobilaris Round 2 - BLE Adapter Kit Install
561351	5-Nov-20	Mobilaris Round 2 - BLE Adapter Kit Install
561530	5-Nov-20	exhaust brake not working.
562098	6-Nov-20	Jack leg fault
562139	7-Nov-20	air blockage, line had minsup seals in line.
560953	8-Nov-20	1000 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
562199	8-Nov-20	cabin lights not working.
562230	8-Nov-20	Blown boom hose
562486	9-Nov-20	Brake pressure bleeding off when pedal applied
562487	9-Nov-20	Adjust front brake pressure
562488	9-Nov-20	Alternator pully U/S
562489	9-Nov-20	Drivers sliding window jammed
562501	10-Nov-20	replace pressure washer turbo head.
562502	10-Nov-20	topped up brake accumulator. both at 35bar adjust to 40bar.
562573	12-Nov-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
562869	12-Nov-20	Operator unable to transmit comms. Replaced radio hand piece
562967	12-Nov-20	vibrator stopped working
562033	13-Nov-20	Cabinet door rhs missing
562034	13-Nov-20	Rear camera blurry spot
563089	14-Nov-20	check low engine power - exhaust brake come off
562608	16-Nov-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
563277	16-Nov-20	check jackleg sensor issue ???

563278	16-Nov-20	lhs swing tube cyl needs replacing next service day
563294	16-Nov-20	replace lh swing cylinder
563296	16-Nov-20	chem not shutting off
563656	19-Nov-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
563993	19-Nov-20	chem check valve leaking on y-piece.
564003	19-Nov-20	low engine power, ball joint came off waste gate actuator.
564005	19-Nov-20	chem issue blocked.
564007	19-Nov-20	Repair front lights
562991	20-Nov-20	Form Oil gun U/S
564049	20-Nov-20	Swing cylinder bush worn
563054	21-Nov-20	Nozzle plate bent
564157	22-Nov-20	Exhaust brake not working
564179	22-Nov-20	no engine power actuator came off exhaust brake
564180	22-Nov-20	chem issue blockage.
563257	23-Nov-20	Replace hopper gasket
563689	23-Nov-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
564465	23-Nov-20	Replace pressure washer
564672	24-Nov-20	boom zoom jamming up.
564678	24-Nov-20	oil leak on rotation head.
563966	26-Nov-20	REPLACE K14 & K15 RELAYS AND BASES
564583	26-Nov-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
564930	26-Nov-20	boom not working slow & loading up hyd pump
564959	26-Nov-20	exhaust brake arm come off
565036	27-Nov-20	replace lh jack leg sensor
565065	27-Nov-20	refit exhaust brake lever
564212	30-Nov-20	Boom turning lug and bushes worn
564617	30-Nov-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
564752	2-Dec-20	Replace hopper assembly
564763	2-Dec-20	WO for alternator wrong supply
565967	2-Dec-20	not pumping ???
565647	3-Dec-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
566021	3-Dec-20	blown hose.
566023	3-Dec-20	replace fitting on tilt cylinder turn 180 degrees.
565648	4-Dec-20	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
566068	4-Dec-20	boom sticking.
565649	5-Dec-20	CHANGE CHEMICAL (ACCELERATOR) PUMP HOSE.
566130	5-Dec-20	replace exhaust brake ball joint.
565379	7-Dec-20	boom zoom sticking
566697	8-Dec-20	repair oil leak at nozzle.
566698	8-Dec-20	repair air line at boom.
566699	8-Dec-20	adjust exhaust brake.
566700	8-Dec-20	changed out crushed delivery hose.
566701	8-Dec-20	adjust swing tube cylinders.
566837	8-Dec-20	pos 1 puncture.
566838	8-Dec-20	horn sounding continuously.
566850	8-Dec-20	No horn
567127	9-Dec-20	retension pos 1 wheel.
567191	9-Dec-20	replace dash 6 hose.

567237	9-Dec-20	Chem fault
566752	10-Dec-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
567402	11-Dec-20	repair chem leak
566125	12-Dec-20	Replace leaking steer cylinders
566785	14-Dec-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
568100	15-Dec-20	replace vibrator
568146	15-Dec-20	not pumping chem
568306	16-Dec-20	remote fault ??
568047	17-Dec-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
568407	18-Dec-20	nozzle tilt hose and fitting repair.
568444	18-Dec-20	Hyd oil leak
568622	18-Dec-20	Concrete pump pivot shaft u/s
567743	21-Dec-20	replace rotaion motor as per Byron pad
567967	21-Dec-20	replace steer cyl RHS
567968	21-Dec-20	replace front window
568081	21-Dec-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
568997	24-Dec-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
569295	24-Dec-20	replace tube on hopper
569335	26-Dec-20	replaced windscreen washer nozzle
569336	26-Dec-20	repaired front light wiring
569027	28-Dec-20	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
570038	30-Dec-20	check estop fault
569738	31-Dec-20	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
570072	31-Dec-20	hopper drain rubber u/s.
570148	2-Jan-21	check wiper operation.
569795	4-Jan-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
570988	4-Jan-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
570635	5-Jan-21	shorten hose at boom.
570637	5-Jan-21	replace nozzle head mount plate bracket.
571061	5-Jan-21	L/H joystick U/S
569796	6-Jan-21	500 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
571206	6-Jan-21	replace chem fitting.
570989	7-Jan-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
571339	8-Jan-21	Remotes not working
571030	11-Jan-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
571512	11-Jan-21	Repair remote leads and remotes
571526	11-Jan-21	Replace wiper arm and blade
571545	11-Jan-21	repair y piece bracket
572092	14-Jan-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
572638	17-Jan-21	Blown nozzle head hoses
572131	18-Jan-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
572703	18-Jan-21	Check exhaust brake operation
573041	18-Jan-21	hyd fault. hyd pressure wouldnt go over 150bar.
573043	18-Jan-21	horn intermittent fault repaired.
572448	20-Jan-21	Replace shoulder harnesses on remotes
573117	21-Jan-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
574227	23-Jan-21	Replace tilt cylinder fitting
573156	25-Jan-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER

574763	25-Jan-21	air con not working
575253	27-Jan-21	Stuck in drain
574961	28-Jan-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
575268	28-Jan-21	chem fault stopped working whilst spraying.
575269	28-Jan-21	a/c not working.
575369	29-Jan-21	chem fitting leaking on strainer.
575003	1-Feb-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
573061	2-Feb-21	Air con not working. Rod G.
575618	4-Feb-21	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
575984	4-Feb-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
576483	5-Feb-21	replace vibrator
576509	6-Feb-21	replae blown hose
576028	8-Feb-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
576265	10-Feb-21	quick nozzle wash valve u/s.
577436	10-Feb-21	replace nozzle tilt cyl & rubber buffer
577461	10-Feb-21	Replacement air shut of switches for machine and remotes
576796	11-Feb-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
576418	12-Feb-21	front axle oscillation lock cylinders- pins/bushes worn
576420	12-Feb-21	A/C CONDENSOR BLOCKED
576421	12-Feb-21	FRONT AXLE OSCILLATION SUPPORT BEARINGS WORN
577680	12-Feb-21	E-stop fault on remotes
577795	14-Feb-21	Chem fault
602576	14-Feb-21	2000HR NORMET SHOTCRETER BANANA ARM REPLACEMENT
576653	15-Feb-21	Engine retarder U/S - S Christian
576838	15-Feb-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
578149	15-Feb-21	Repair cab lights
578150	15-Feb-21	Lift cylinder pin and bush worn at head end
578151	15-Feb-21	Replace 10m delivery line
578152	15-Feb-21	Replaced damaged hydroscaler hose at nozzle
578026	18-Feb-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
578027	20-Feb-21	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
578530	20-Feb-21	vibrator not working
578618	21-Feb-21	throttle not working at times
578654	21-Feb-21	Exhaust brake linkage broken
577938	22-Feb-21	Work order to capture costs to manufacture PVC seat covers
578673	22-Feb-21	replace exhaust brake
579304	24-Feb-21	Remotes not working
578403	25-Feb-21	replace door window
578791	25-Feb-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
579604	25-Feb-21	Repair damage to side of machine
579615	25-Feb-21	Remote fault
578500	26-Feb-21	replace lh wiper blade
579711	27-Feb-21	AFFF DAMAGED
579791	28-Feb-21	no start fuse blown in dash.
578831	1-Mar-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
580324	3-Mar-21	loss of throttle, metal bar on seat proxi switch.
580326	3-Mar-21	pos 1 puncture.
580356	3-Mar-21	Re-tension pos 1

580065	4-Mar-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
580425	4-Mar-21	replace remotes
580769	5-Mar-21	inflate pos 1 tyre
579710	6-Mar-21	I PAD CRACKED
579709	6-Mar-21	SIDE RH TOOL BOX DAMAGED
579706	6-Mar-21	SLIDES ON BOOM EXTENSION WORN
580806	6-Mar-21	flat battery
580851	6-Mar-21	check concrete pump fault
580852	6-Mar-21	zoom jamming up
580872	6-Mar-21	rollover came loose on boom
580103	8-Mar-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
580971	8-Mar-21	replace boost hose
580991	8-Mar-21	replace pressure washer hose
581216	11-Mar-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
581854	12-Mar-21	Water leak from hydroscaler
581859	12-Mar-21	FIT NEW PVC SEAT COVER
581827	12-Mar-21	AUTO CHEM CUTS OUT INTERMITTENTLY
581897	12-Mar-21	hyd filter blockage indicator leaking.
581950	14-Mar-21	Brake fault
581951	14-Mar-21	Jack legs slow
581952	14-Mar-21	Vibrator not working
581953	14-Mar-21	Hard line on rotation head bent
581954	14-Mar-21	Crack in hopper
581955	14-Mar-21	Exhaust brake u/s
581956	14-Mar-21	Air leak on y piece
580989	15-Mar-21	manifold gasket starting to leak
580990	15-Mar-21	piston seals starting to leak
581256	15-Mar-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
582010	15-Mar-21	Replace fan belt
582147	15-Mar-21	Park brake fault
582335	16-Mar-21	Air blockage
582797	17-Mar-21	nozzle rotation head motor u/s.
582257	18-Mar-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
581826	19-Mar-21	ROTATION HEAD BRACKET BENT
583019	20-Mar-21	blown console hose
583020	20-Mar-21	blown hose at rotation head
582296	22-Mar-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
583314	22-Mar-21	repair chem fault
582204	23-Mar-21	Banana arm needs bushes replaced
583720	23-Mar-21	wash out radiator
583983	24-Mar-21	jump start
583525	25-Mar-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
584034	25-Mar-21	clean out chem check valve, leaking.
584038	25-Mar-21	chem issues clean out lines.
584039	25-Mar-21	remote fault swap out remotes with sc10.
584049	25-Mar-21	Tighen rear camera
584100	26-Mar-21	vibrator fault, vibrator not vibrating hard enough.
584101	26-Mar-21	chem fault check coil and spool.

582993	27-Mar-21	repair next service day spray head pivot
584244	28-Mar-21	repair remotes and lead.
583265	29-Mar-21	Change out rotation head limiter flange
583566	29-Mar-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
584430	29-Mar-21	replace cutting ring
584431	29-Mar-21	replace hydra scaler.
584724	30-Mar-21	repaired bent tool box mount
584725	30-Mar-21	repaired load sensing valve fault for jack legs.
584728	30-Mar-21	replaced park brake 25bar pressure reducing valve.
584781	30-Mar-21	Pos 1 and 2 re-torque
584927	31-Mar-21	retension pos 1 and 2 wheels.
584658	1-Apr-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
585043	1-Apr-21	replace nozzle tube
584153	3-Apr-21	2 x 3m soft lines u/s
584698	4-Apr-21	1500HR SWING TUBE SEALS CHANGE OUT
585205	4-Apr-21	spin hopper wear plate
585722	4-Apr-21	replace hopper plate
584417	5-Apr-21	Replace hopper hold down clamps
584699	6-Apr-21	1000 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
584727	6-Apr-21	replace pressure washer turbo head.
586301	7-Apr-21	front axle oscillation lock cylinders- pins/bushes worn
586112	8-Apr-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
586446	8-Apr-21	Chem fault
586536	9-Apr-21	Blown hose under chem tank
586553	9-Apr-21	Chem fault - tripping out concrete pump
586596	10-Apr-21	Blown hose
586607	11-Apr-21	zoom sticking and check low pressure
586146	12-Apr-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
586678	12-Apr-21	Accumulator leaking
586679	12-Apr-21	Retarder U/S
587528	14-Apr-21	Repair Y-piece
587529	14-Apr-21	Repair oil leak
587531	14-Apr-21	Repair chem leak
587246	15-Apr-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
587610	15-Apr-21	lost engine start, possible issue with k140 relay
587616	15-Apr-21	hyd cooler fan u/s
587621	15-Apr-21	concrete pump fault. found transducer on valve block damaged
587775	17-Apr-21	concrete pump cut out?
586677	19-Apr-21	Boom movements very slow
587286	19-Apr-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
587589	22-Apr-21	Tramming slow - L Lockett
587590	22-Apr-21	All chem hoses/fittings to be replaced due to
589049	22-Apr-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
587678	23-Apr-21	REPLACE INLINE AIR STRAINER
589437	23-Apr-21	Exhaust brake, Hydra scaler leak at nozzle, hyd overheating.
587942	26-Apr-21	adjust nitrogen in fire supp.
587943	26-Apr-21	hyd. Cooler fan switch c/o
587949	26-Apr-21	Ipad and hand held radio U/S - J Villella

589085	26-Apr-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
589789	26-Apr-21	Exhaust brake fault
589133	27-Apr-21	FOLDING BOOM SENSOR FAULT
589135	27-Apr-21	POS 1 HYD LOCK CYLINDER LEAKING
589136	27-Apr-21	LH STEER CYLINDER LEAKING OUT ROD END
589815	27-Apr-21	Broken boom cylinder sensor cable. Cable end to be replaced
589876	29-Apr-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
590239	29-Apr-21	replace 2 x blown hoses
590269	29-Apr-21	no chem. Unblocked hose
590510	30-Apr-21	chem fault ???
590511	30-Apr-21	concrete pump shutting off???
589499	1-May-21	Wax gun U/S - B. Poulter
590588	1-May-21	check concrete pump stopping
589923	3-May-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
590746	3-May-21	replace pressure washer hose
589356	4-May-21	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
590079	5-May-21	Chem sight glass blocked
590974	5-May-21	replace shotcrete 3mtr lines
590221	6-May-21	NO HEAT SHIELD FROM TURBO TO
590852	6-May-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
591273	6-May-21	Hydroscaler fault
591293	6-May-21	fire suppression activated hose rubbed through.
591315	7-May-21	Zoom cylinder leaking
591361	7-May-21	check out zoom slides jamming up
591362	7-May-21	zoom sticking
591378	7-May-21	concrete pump output fault code 1139.
590758	10-May-21	needs new hyd level sensor
590886	10-May-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
591967	11-May-21	Replace pressure washer coil and dim plug
591968	11-May-21	Boom slides need replacing worn
592281	12-May-21	Check boom zoom
592018	13-May-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
592401	13-May-21	zoom spool sticking
592402	13-May-21	check tps throttle
592674	15-May-21	replace remotes
592680	15-May-21	zoom stuck
592743	16-May-21	check boom lift speed - adjust
592056	17-May-21	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
591969	18-May-21	LHS front axle bump stop worn
591955	18-May-21	Wipers, only one
593237	19-May-21	concrete pump slow
593266	19-May-21	POS 1 RETORQUE
592920	20-May-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
593317	20-May-21	chem fault. adjust relief on pump.
593338	20-May-21	Hydroscaler fault
592805	24-May-21	repair hopper door
592955	24-May-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
593608	24-May-21	Install covers to remote joysticks

593156	26-May-21	Taxi up shotcrete hoses from Alfagomma
593840	27-May-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
594280	27-May-21	hyd fault loading up pump
593352	28-May-21	Chem sight glass u/s
593393	28-May-21	Replace machine I.D. decals
594351	28-May-21	hyd's loaded up causing slow boom movments
593431	29-May-21	replace y198 complete valve assembly. worn spool.
594456	29-May-21	remotes playing up at times
593875	31-May-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
594932	1-Jun-21	chem tank sight glass needs replacing - tank needs to be
593965	2-Jun-21	replace front windscreen. next service.
595112	3-Jun-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
595610	4-Jun-21	repair wiring to rear camera.
595687	5-Jun-21	Defects - tagged out by mining
595712	6-Jun-21	Exhaust brake U/S
595713	6-Jun-21	Park brake sensor fault
595714	6-Jun-21	Concrete pump tripping out at high speed
595715	6-Jun-21	Swing tube and cylinders not synchronising
595716	6-Jun-21	Brake accumulator not accumulating at any RPM
595717	6-Jun-21	Auto chem not delivering consistant flow rate
595757	6-Jun-21	check exhaust brake operation.
595156	7-Jun-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
596167	7-Jun-21	Check banana arm for cracks
595157	9-Jun-21	CHANGE CHEMICAL (ACCELERATOR) PUMP HOSE.
596246	10-Jun-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
596750	11-Jun-21	replace hydroscailer hose
596866	12-Jun-21	replace batteries & isolator
596894	12-Jun-21	check crack on boom ????
596278	14-Jun-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
597308	15-Jun-21	replace concrete nozzle pipe
597541	15-Jun-21	fitted new nozzle tilt bracket
598068	16-Jun-21	No hand held radio - J Villella
598069	16-Jun-21	No eyewash - J Villella
597362	17-Jun-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
596757	18-Jun-21	No guard on remotes J Villella
598296	18-Jun-21	Blown hydroscaier hose
598348	19-Jun-21	Repair hopper plate
598349	19-Jun-21	Check vibrator
597399	21-Jun-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
598434	21-Jun-21	repair front window wipers.
597542	22-Jun-21	fitted new hopper handle
597543	22-Jun-21	unblock chem sight glass
598613	22-Jun-21	remove swing tube to clean out set shotcrete.
598006	23-Jun-21	replace exhaust brake butterfly section
598680	24-Jun-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
598240	25-Jun-21	Crack/dent in rotation head housing
598681	25-Jun-21	500 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
599307	25-Jun-21	replace drivers door lock

599634	28-Jun-21	replace boom light
599635	28-Jun-21	replace boom slides
599641	28-Jun-21	repair folding boom pressure sensor
600019	28-Jun-21	replace hydrascaler fittings
600018	29-Jun-21	engine boost hose needs changing next service day
599939	1-Jul-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
600315	1-Jul-21	Replace hydroscaler fitting
600347	1-Jul-21	repair hydra scaler nozzle.
600351	1-Jul-21	hydra scaler fault. replace water filters.
600352	1-Jul-21	air issue.
600363	2-Jul-21	Check hydroscaler
600374	2-Jul-21	No chem valve on boom leaking lots of chem
600466	3-Jul-21	Repair lights. wiring damaged rubbed through.
599403	4-Jul-21	Missing pressure washer nozzle - L Luckett
599986	5-Jul-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
600169	7-Jul-21	Wax gun U/S - J Villella
600170	7-Jul-21	Wires exposed on 10 m softline - J Villella
601147	8-Jul-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
601741	8-Jul-21	make up remote lead
601840	9-Jul-21	excessive engine oil temp / amber light on
601186	12-Jul-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
602981	13-Jul-21	check no start
603098	14-Jul-21	replace leaking pressure reducing valve under cab
601706	15-Jul-21	Boom oscillation pin RHS worn - Rear Boom pins/bushes
601707	15-Jul-21	boom banana link rear upper pins/bushes worn
601708	15-Jul-21	Nozzle head pin and bush worn
601688	15-Jul-21	Form oil U/S - H Symes
602617	15-Jul-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
603572	15-Jul-21	Blown hose
601808	16-Jul-21	Replace First Aid & Eye Wash Decals on machine
601815	16-Jul-21	SOS - IRON UP AND VISCOSITY DOWN - REAR DIFF
603869	16-Jul-21	horn not working intermittently.
601894	17-Jul-21	Have to run at full RPM to pump - J Villella
601895	17-Jul-21	No wrap on nozzle hoses - J Villella
602513	19-Jul-21	replace wiper blades
602514	19-Jul-21	replace seat belt
602515	19-Jul-21	repaired lhs work light wiring
602516	19-Jul-21	form oil reel not locking
602517	19-Jul-21	boom folding pressure sensor alarm error on start up
602662	19-Jul-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
602690	20-Jul-21	vibrator u/s
604337	20-Jul-21	fit new cutting ring.
603059	21-Jul-21	Rotation head sticking - L Luckett
604278	22-Jul-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
604688	22-Jul-21	replace blown hose
604695	22-Jul-21	tighten remote bolts
603842	23-Jul-21	Hopper rubber not sealed on sides. Fibre crete
604886	25-Jul-21	repair remotes

604912	25-Jul-21	turn hopper plate
604022	26-Jul-21	Remote strap u/s
604313	26-Jul-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
605388	26-Jul-21	replace broken chem fitting
605416	26-Jul-21	retorque pos 3& 4
604336	27-Jul-21	alternator bearing noisy.
604355	27-Jul-21	C/O Rear Axle
604683	29-Jul-21	Chem transfer hose squashed - M Walker
605214	29-Jul-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
605797	29-Jul-21	Blown hydroscler hose
604724	30-Jul-21	Hydroscler hose too long - L Luckett
604725	30-Jul-21	Remotes bit bent - B Davy
605852	30-Jul-21	Check remotes
604937	2-Aug-21	replace hydrascailer hose
605326	2-Aug-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
605451	3-Aug-21	Rotation head has a big dent in it - C Manley
606277	3-Aug-21	Replace wipers
606278	3-Aug-21	Replace radiator cap
606279	3-Aug-21	Unblock form oil nozzle
606280	3-Aug-21	Repair hoses and re-wrap boom
605327	4-Aug-21	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
606329	5-Aug-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
607178	5-Aug-21	replace blown carrier hose
607184	5-Aug-21	blown carrier hose
605832	6-Aug-21	Check power to Wi-Fi tag.
606330	6-Aug-21	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
607341	8-Aug-21	check a/c operation??condenser was blocked with chem
607364	8-Aug-21	engine airbox needs to be replaced heavy paint inside it
607818	9-Aug-21	damaged fitting on boom
606276	10-Aug-21	Diesel engine harness main plug damaged
608256	11-Aug-21	lost gears, revs & exhaust break not working ???
607139	12-Aug-21	brake charge cycling evey 3-4 sec
607919	12-Aug-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
607223	13-Aug-21	Knuckle retract very slow - B Davy
608548	13-Aug-21	replace horn.
607955	16-Aug-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
607970	17-Aug-21	Needs shelter plate for zoom - B Padgeham
608787	17-Aug-21	replaced 2 x hoses on boom.
608868	19-Aug-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
609319	20-Aug-21	replace engine fan hub
609351	20-Aug-21	Eng alarm coming up, loosing revs, e-stop fault
609364	20-Aug-21	plan in to remove and replace engine coolers and
609440	21-Aug-21	blown from carrier to bulkhead
609465	22-Aug-21	replace boom slides
609490	22-Aug-21	complete recharge a/c system, condensor,dryer etc
608908	23-Aug-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
609670	23-Aug-21	replace blown pressure washer hose
609671	23-Aug-21	replace 2 x spraying lights

609672	23-Aug-21	replace a/c condensor
609725	26-Aug-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
610367	28-Aug-21	Water leak hydra scaler
610402	28-Aug-21	jump start.
609766	30-Aug-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
610755	30-Aug-21	Door strut
610757	30-Aug-21	Pump cutting ring
610764	30-Aug-21	Top radiator hose (Temp repair) New hose to be fitted when
610948	31-Aug-21	Exhaust manifold gasket leaking.
611302	1-Sep-21	engine shutdown
610856	2-Sep-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
611418	2-Sep-21	shutting down lights coming on fire suppression box ??
611510	4-Sep-21	p4 blown tyre
611553	5-Sep-21	p4 re torque
610909	6-Sep-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
612188	8-Sep-21	replace mobilaris charge cable and base
612189	8-Sep-21	radiator side tank leak, replaced hose
611948	9-Sep-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
612478	11-Sep-21	E-stop fault
611987	13-Sep-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
612782	14-Sep-21	repaired wiper and washers.
612825	16-Sep-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
612491	19-Sep-21	Right window wiper u/s
612866	20-Sep-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
614623	20-Sep-21	replace hopper wear plate & cutting ring
614640	20-Sep-21	replace rhs low head light
614881	21-Sep-21	1000 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
614882	23-Sep-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
615259	24-Sep-21	Blown hose on boom
615294	25-Sep-21	Boom hoses plumbed up wrong way
614923	27-Sep-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
615587	27-Sep-21	Replace hydroscaler hose
615592	27-Sep-21	Replace coolant level sensor
615939	30-Sep-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
616601	1-Oct-21	blown carrier hose
616616	1-Oct-21	check boom lights ???
615981	4-Oct-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
617033	4-Oct-21	pressure washer nozzle blocked
617036	4-Oct-21	remotes smashed / ranover need parts for repair
617056	5-Oct-21	coolant level sensor u/s
617099	7-Oct-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
617672	10-Oct-21	y-piece fitting snapped.
617146	11-Oct-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
618159	12-Oct-21	Not starting , faulty park brake switch contact
618180	12-Oct-21	front diff over full by 20lts.
618611	12-Oct-21	pos 1 puncture.
618639	13-Oct-21	Pos 1 tyre , broke down in the link
617454	14-Oct-21	Wax gun u/s

617455	14-Oct-21	Door handle stiff
617456	14-Oct-21	Driving lights flickering
618232	14-Oct-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
618958	15-Oct-21	Swing tube fault
619038	16-Oct-21	Repair oil leak on boom
618268	18-Oct-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
619183	18-Oct-21	swing tube jammed ??
619184	18-Oct-21	top part of door bent hard to shut
619490	18-Oct-21	replace u/s carrier hoses
619491	18-Oct-21	replace nozzle tilt pin & lever
619493	18-Oct-21	clean up battery terminals
620009	20-Oct-21	main swing tube hose
620119	20-Oct-21	swing tube jammed @ chem bay
619904	21-Oct-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
620461	24-Oct-21	Remote box. Change out.
619946	25-Oct-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
619179	25-Oct-21	Windscreen seal U/S - L Lockett
619180	25-Oct-21	Nozzle loose AF - L Lockett
619969	26-Oct-21	replace front work light harness
619993	26-Oct-21	hopper switch cam needs replacing
620098	27-Oct-21	Driving lights flickering - J Villella
620599	28-Oct-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
620364	29-Oct-21	Install upgraded hydraulic return filter assembly
621024	29-Oct-21	replace tilt cylinder hose
621084	30-Oct-21	blown hose on boom
620637	1-Nov-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
621280	1-Nov-21	engine tensioner pulley needs replacing
621281	1-Nov-21	repaired hyd cooler fan wiring
621282	1-Nov-21	replace blown carrier hose
620282	4-Nov-21	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
621354	4-Nov-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
621823	4-Nov-21	remote fault change out remotes.
621824	4-Nov-21	shotcrete blockage.
621893	5-Nov-21	replace delivery lines.
621220	8-Nov-21	boom slides
621221	8-Nov-21	lift cylinder pins and bearings
621203	8-Nov-21	Door still a bit bent (hard to open) - J Villella
621390	8-Nov-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
622330	8-Nov-21	lower head lights not working.
622331	8-Nov-21	repair chem sight glass.
621537	9-Nov-21	check lhs head lights flickering
622491	9-Nov-21	retension pos 1 and 2
622497	9-Nov-21	Repair lights
622670	10-Nov-21	e-stop fault, check over all e-stop switches.
622402	11-Nov-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
622403	12-Nov-21	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
622833	12-Nov-21	replace remotes & lead
622914	13-Nov-21	shutting down?

622918	13-Nov-21	chem line leaking fitting
621974	14-Nov-21	Low beam lights u/s
622439	14-Nov-21	CHANGE CHEMICAL (ACCELERATOR) PUMP HOSE.
623063	15-Nov-21	banana bar bushes in H frame to be planned in
623064	15-Nov-21	source and make store stock stainless M8x25 cap screw
623339	16-Nov-21	REPLACE HYDRAULIC OIL.
623340	18-Nov-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
622881	20-Nov-21	Chem sight glass blocked - J Villella
622882	20-Nov-21	E Stop fault - B Davy
623757	20-Nov-21	Chem pump not working
622943	21-Nov-21	Tilt cylinder leaking - L Luckett
623375	22-Nov-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
623924	22-Nov-21	changed 1 x led light.
623640	25-Nov-21	Replace K49 E-Stop Relay
624110	25-Nov-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
624569	25-Nov-21	shutting down - repair e stop fault
624622	26-Nov-21	engine shutting down & concrete pump ???
623926	29-Nov-21	needs new rear bump stops x 2. IN CAT CONTAINER
624157	29-Nov-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
624904	29-Nov-21	replace hopper grill plate rubber
624274	30-Nov-21	Remove rear wheels and clean concrete from rim & axle
625007	2-Dec-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
625534	2-Dec-21	High beams no working
623925	6-Dec-21	no lagging on exhaust (turbo to exhaust pipe).
625067	6-Dec-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
626041	6-Dec-21	Pos 2 puncture
626196	7-Dec-21	pos 2 retorque.
626452	8-Dec-21	replace blown cab light.
626113	9-Dec-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
626652	10-Dec-21	vibrator u/s
626708	11-Dec-21	jump start
626728	11-Dec-21	hole in coolant hose
626147	13-Dec-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
626990	13-Dec-21	replace zoom slides
627151	13-Dec-21	repaired form oil gun
627153	13-Dec-21	repaired hopper grate mounts
627154	13-Dec-21	repaired mobilaris charger
626165	14-Dec-21	Needs a light facing back along mirror line
627249	16-Dec-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
628132	16-Dec-21	remotes stopped working , swapped out remote set off SC11
626607	17-Dec-21	oil cooler fan noisy - L Luckett
626608	17-Dec-21	LH Driving light U/S - L Luckett
628438	18-Dec-21	replace 3m hydra scaler hose.
627156	20-Dec-21	lh swing tube cyl weeping
627286	20-Dec-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
628820	21-Dec-21	blown -6 hose. replace pressure washer lance.
628619	23-Dec-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
628651	27-Dec-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER

628562	28-Dec-21	Mobilaris tablet not charging
629889	29-Dec-21	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
629556	30-Dec-21	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
629928	30-Dec-21	replace wiper arms and blades.
629244	2-Jan-22	replace rear hyd cooler fan next service day
629310	3-Jan-22	replace chem hose
629312	3-Jan-22	replace bushes on rotation motor
630329	3-Jan-22	brake charge fault, fluctuating. change out pressure
630331	3-Jan-22	fit stainless steel fittings and new hose to chem
629627	5-Jan-22	REMOVE COOLER PACK AND WASH OUT
630404	6-Jan-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
630405	7-Jan-22	500 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
631392	10-Jan-22	Replace ball valve for chem shutoff valve
631194	11-Jan-22	check pump not working ???
631488	13-Jan-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
632733	14-Jan-22	Air blockage
632756	14-Jan-22	Jump start
632879	16-Jan-22	Remote fault
631532	17-Jan-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
633222	18-Jan-22	pressure washer and hydra scaler not working.
633122	20-Jan-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
634315	22-Jan-22	replace fitting on y block
634337	22-Jan-22	replace blown air hose
633157	24-Jan-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
633168	25-Jan-22	Shotcrete pump wear plate needs replacing
633169	25-Jan-22	Replace TPS wiring harness - damaged has been repaired
633170	25-Jan-22	Replace air filter restriction sender - plug damaged
634770	25-Jan-22	fittings for sc08 to stock up
634793	25-Jan-22	replaced zoom slides
634794	25-Jan-22	replace reverse camera cable
634641	27-Jan-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
635042	27-Jan-22	replace wax nozzle and pressure washer nozzle
634231	28-Jan-22	HYDRO SCALER IS PULSING
634310	29-Jan-22	exhaust brake u/s
634311	29-Jan-22	air con u/s condensor blocked
635230	29-Jan-22	repair rear wiring to lights.
635231	29-Jan-22	exhaust brake fault.
634541	31-Jan-22	POS 1 and POS 2 Inspection - dirt in oils
634682	31-Jan-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
635351	31-Jan-22	change out batteries.
635512	31-Jan-22	1500HR SWING TUBE SEALS CHANGE OUT
635383	1-Feb-22	exhaust brake not working replace fuse.
635384	1-Feb-22	replaced form oil filter.
635385	1-Feb-22	replace faulty y200 coil.
635513	3-Feb-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
635135	4-Feb-22	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
636053	4-Feb-22	replace 9kg fire ext
636054	4-Feb-22	replace battery

635557	8-Feb-22	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
636365	10-Feb-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
636851	10-Feb-22	Fan hub loose
636953	11-Feb-22	Engine fault - shutting down
636999	12-Feb-22	Engine fault - shutting down
636245	14-Feb-22	air discharge valve on boom air line needs replacing
636262	14-Feb-22	front window needs replacing
636400	14-Feb-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
637098	14-Feb-22	replace park brake relay
637103	14-Feb-22	3/8 hose of header tank needs replacing
637096	14-Feb-22	Horn U/S - repaired wiring to horn
637785	16-Feb-22	keeps blowing fuses - swap out remotes and lead
637536	17-Feb-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
637948	18-Feb-22	Needs hydroscaler hose
638103	20-Feb-22	crack in fuel line, got one from bone yard engine
637097	21-Feb-22	2 Left spotlight u/s
637573	21-Feb-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
638691	23-Feb-22	No swing tube when under load
638373	24-Feb-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
638744	24-Feb-22	Window washer u/s
638745	24-Feb-22	iPad U/S
638796	24-Feb-22	Check pump pressure
638797	24-Feb-22	Windscreen wipers not working
638798	24-Feb-22	Check horn operation
638838	25-Feb-22	Horn sounds randomly - alarm??
638839	25-Feb-22	Rear camera very scratched
638274	28-Feb-22	replace horn
638405	28-Feb-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
639175	28-Feb-22	replace zoom wear pieces.
639426	1-Mar-22	replaced wiper washer motor.
639427	1-Mar-22	repair front bump stop.
639485	1-Mar-22	check hyd pressure dropping and retension POS 2 wheel nuts
639586	2-Mar-22	damage to hoop over hopper, damaged by agitator.
639589	2-Mar-22	replace pos 1 jack leg proxi sensor.
639644	2-Mar-22	check alt may have failed
639296	3-Mar-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
639675	3-Mar-22	hopper bottom plate come off - door in cab
639882	5-Mar-22	hydroscaler not working?seals leaking
639340	7-Mar-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
640733	7-Mar-22	replace banana arm
640774	8-Mar-22	2000HR NORMET SHOTCRETER BANANA ARM REPLACEMENT
640817	10-Mar-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
641224	11-Mar-22	check hydroscaler and pumping fault
639929	13-Mar-22	Conc pump wont start up directly after use
641391	13-Mar-22	Jump start
640855	14-Mar-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
641412	14-Mar-22	replace mobilaris charger
641456	14-Mar-22	replace engine belt

641457	14-Mar-22	REPLACE ENGINE BELT
641596	17-Mar-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
642352	18-Mar-22	swing tube stopped
641280	19-Mar-22	Hopper bottom plate u/s
642411	19-Mar-22	change pressure reducing valve for swing tube
642415	19-Mar-22	change pressure reducing valve for swing tube
642426	19-Mar-22	engine stopping ??? Hyd loading up
641631	21-Mar-22	1000 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
643499	22-Mar-22	blown trans hose
643335	24-Mar-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
643812	24-Mar-22	replace joysticks on remotes.
643813	24-Mar-22	replace pins and bushes on rotation tilt.
643814	24-Mar-22	replace hopper grate hinge bushes.
643815	24-Mar-22	replace boom pins and bushes.
643968	27-Mar-22	blown -20 air hose
643370	28-Mar-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
644676	28-Mar-22	Oil leak on rotation head
644924	29-Mar-22	Replace remote lead
643695	31-Mar-22	Replace remote set deteriorated, water ingress
644743	31-Mar-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
645367	1-Apr-22	replace remote lead
645409	2-Apr-22	replace 3m concrete hose
644782	4-Apr-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
645563	4-Apr-22	replace boom slides
645564	4-Apr-22	fit boom hose bracket & replace hoses
645594	4-Apr-22	replace zoom cylinder
645653	7-Apr-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
645522	11-Apr-22	1 driving light u/s
645687	11-Apr-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
646593	11-Apr-22	Replace hydroscaler hose
646594	11-Apr-22	Replace nozzle tilt cylinder
645605	12-Apr-22	hopper wear plate & cutting ring need replacing
646740	12-Apr-22	replace wiper blades - parts booked on weekly
646929	13-Apr-22	Back camera u/s
647019	13-Apr-22	blown hose nozzle tilt.
646683	14-Apr-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
647157	15-Apr-22	check seat swivel ???
646721	18-Apr-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
647303	18-Apr-22	hydroscaler not working
647304	18-Apr-22	x4 front lights and rear work light not working
647306	18-Apr-22	repaired nozzle air hose
647308	18-Apr-22	windscreen wipers and washers
647318	18-Apr-22	repaired rear axle high temp sensor
645801	19-Apr-22	Inspect hopper grate chain and hook for servicability.
647637	19-Apr-22	repair remotes,joysticks etc
647594	21-Apr-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
647949	21-Apr-22	4 pole isolator u/s. replace.
647964	21-Apr-22	delivery line blocked, unblock rock stuck in line.

647128	22-Apr-22	cleaned out air filter
647190	23-Apr-22	Axel temp sensor U/S - J Villella
647191	23-Apr-22	Electrical gremlins on start up - J Villella
647307	25-Apr-22	Air filter clogging - B Anderson
647309	25-Apr-22	Broken wiper arm - B Anderson
647627	25-Apr-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
648197	25-Apr-22	replace hopper limit switch.
648206	25-Apr-22	replaced diff breather.
648284	27-Apr-22	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
648285	28-Apr-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
648717	28-Apr-22	SOS engine oil in Daily - last result had coolant contam.
648084	30-Apr-22	Hydroscler very weak pulsing
648085	30-Apr-22	Chem 1 way valve u/s chem keeps coming out when
649056	1-May-22	check swing tube operation , could not fault ?
649172	2-May-22	replace swing tube cutting ring seal
649216	2-May-22	chem fault, repair flow control valve
648391	4-May-22	6 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
649369	5-May-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
649077	8-May-22	A/C doughty - J Villella
649078	8-May-22	Hopper leaks - J Villella
649413	8-May-22	CHANGE CHEMICAL (ACCELERATOR) PUMP HOSE.
649414	9-May-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
650183	9-May-22	Chem hose leaking on boom
650189	9-May-22	Replace boom slides
650520	11-May-22	oil leak on boom - loos fitting
649641	12-May-22	Hyd oil temp (pressure) guage u/s
650347	12-May-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
650928	15-May-22	top up hyd oil
650383	16-May-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
651468	16-May-22	replace boost hose
651719	17-May-22	replace u/s vibrator
651947	18-May-22	repair oil leak at swing tube valve block
651948	18-May-22	chem not working on auto
652003	18-May-22	repair chem fault
651612	19-May-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
652120	19-May-22	oil leak on swing tube accumulator fitting. replace o-ring.
652136	19-May-22	side camera not working
652219	20-May-22	Oil leak at rear. swing tube accumulator block pitted
652220	20-May-22	Window smashed
652221	20-May-22	Hydrascaler losing pressure
652289	22-May-22	replaced cracked engine intake elbow.
651002	23-May-22	zoom jamed up / strip boom and replace slides
651644	23-May-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
651659	24-May-22	folding boom pressure sensor / repaired wirnig
651664	24-May-22	rear H sectionpins & bushes need replaceing
651665	24-May-22	rear hopper gate pivots bushes L&R need replaceing
652021	26-May-22	Trial zoom cylinder cover bolts
652515	26-May-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES

653167	28-May-22	oil leak @ concrete pump accumulator
652553	30-May-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
653323	30-May-22	Hydroscaler not pumping
653383	30-May-22	Replace boom slides
653400	30-May-22	make up remote leads
653557	2-Jun-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
654135	4-Jun-22	replace hydrascaler hose
654411	6-Jun-22	remote fault no nozzle rotation - fit joystick
653603	7-Jun-22	500 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
654540	7-Jun-22	replace cutting ring and seal
654732	8-Jun-22	replace lever to Rotable boom - s/n 22090
654747	8-Jun-22	replace hydrascaler
654497	9-Jun-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
655179	10-Jun-22	lhs joystick u/s - remotes coming up
654527	13-Jun-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
655758	13-Jun-22	new wiper blades required / nil stock
655759	13-Jun-22	front parkers out parts required
653650	14-Jun-22	Replace worn zoom
655735	14-Jun-22	REPLACE POS 1 TYRE
655778	14-Jun-22	RETORQUE POS 1
655679	16-Jun-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
656445	18-Jun-22	turbo making squealing noise. waste gate seized shut.
655328	20-Jun-22	C/O Turbo and exhaust brake
655716	20-Jun-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
657014	21-Jun-22	repair engine intake mount.
657015	21-Jun-22	repaired and tidied up boom hoses.
657267	23-Jun-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
657301	27-Jun-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
657830	27-Jun-22	repair remote straps - replace bolts
658292	29-Jun-22	replace nozzle bolts
657388	30-Jun-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
657430	4-Jul-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
658771	4-Jul-22	replace suspension cylinder bearings and fix grease lines
659035	4-Jul-22	repaired grease line to rear hopper outlet
658935	7-Jul-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
659589	7-Jul-22	Vibrator not working
659652	8-Jul-22	repair vibrator wiring
659702	9-Jul-22	hydrascailer pressure switch fault
659723	9-Jul-22	vibrator u/s take bolts
658976	11-Jul-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
659590	14-Jul-22	Pos 1 retorque wheel nuts
660717	14-Jul-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
661699	17-Jul-22	Engine brake u/s
659822	18-Jul-22	replace vibrator
659839	18-Jul-22	replace rear tail light assembly
659840	18-Jul-22	replace cab light
659841	18-Jul-22	repair wiring on high beam lights
659842	18-Jul-22	both front jack legs need replacing

660760	18-Jul-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
659965	19-Jul-22	Workorder to capture cost to replace remote leads
661911	19-Jul-22	replaced rh joystick on remotes.
661913	19-Jul-22	repaired chem fittings on boom.
661966	21-Jul-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
662267	21-Jul-22	JACK LEG PROXY U/S
661700	24-Jul-22	A/C making weird noises
662001	25-Jul-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
662797	28-Jul-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
663296	30-Jul-22	Remote fault
663320	30-Jul-22	check vibrator.
662839	1-Aug-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
663485	1-Aug-22	Mobilaris not working
663486	1-Aug-22	Jack leg fault
663487	1-Aug-22	Boom movements slow
663488	1-Aug-22	Replace folding boom cylinder
663747	2-Aug-22	Shutting down, overheating
663146	4-Aug-22	3 MONTHLY FIRE SUPPRESSION TEST & INSPECTION
663652	4-Aug-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
663884	4-Aug-22	replaced U/S hand held charger
664430	5-Aug-22	blown hose on boom from cab to boom
664488	6-Aug-22	engine over heating
664513	6-Aug-22	vibrator u/s
664515	6-Aug-22	check start fault ??
664516	6-Aug-22	repair oil leak
663684	8-Aug-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
664835	9-Aug-22	engine shut down
664783	11-Aug-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
665099	11-Aug-22	remote fault - change out and repair old set
665112	11-Aug-22	Check a/c cutting out - possible low gas or leak
665055	12-Aug-22	Noisey belt - B Anderson
665056	12-Aug-22	replace nozzle hardline mount - 15359 - B Anderson
665130	12-Aug-22	A/C U/S - Poulter
665545	13-Aug-22	nozzle rotation head - check position
664816	15-Aug-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
664826	16-Aug-22	replace coolant level sensor
664827	16-Aug-22	ajusted jack leg switches
665763	18-Aug-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
666046	18-Aug-22	check estop fault
665129	19-Aug-22	Exhaust smokey - B Poulter
666147	20-Aug-22	carrier hose - 10
666193	20-Aug-22	repair front lights
666211	20-Aug-22	blown hose on boom
665807	23-Aug-22	250 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
666664	23-Aug-22	replace nozzle rotation motor
666690	23-Aug-22	replace cutting ring seal
666691	23-Aug-22	replace lhs jackleg earth strap
666514	25-Aug-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES

667200	25-Aug-22	Engine shutting down
666243	28-Aug-22	Wiper RHS U/S- Missing - L Kelly
666550	29-Aug-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
668097	29-Aug-22	Replace engine mount
668098	29-Aug-22	Replace isolators
668099	29-Aug-22	Tidy up hoses on boom
668121	29-Aug-22	park brake coming on when going over bumps.
668266	30-Aug-22	Repair pressure washer switch
668267	30-Aug-22	Repair blocked nozzle
668463	31-Aug-22	Check alternator. u/s replace.
668182	1-Sep-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
668235	5-Sep-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
668876	5-Sep-22	Change out boom slides
668895	5-Sep-22	Repair remotes
669167	8-Sep-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
671119	8-Sep-22	Blown hose
671357	11-Sep-22	Chem pump not working
669208	12-Sep-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
671663	12-Sep-22	tranny temp being high.
671811	15-Sep-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
672310	18-Sep-22	oil leak at rhs swing tube cylinder
671850	19-Sep-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
672368	19-Sep-22	replace hyd hoses on boom
672369	19-Sep-22	replace rhs swing tube cylinder
673086	21-Sep-22	no throttle. seat proxy u/s
672605	22-Sep-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
673197	23-Sep-22	jump start and check remotes operation.
673263	24-Sep-22	vibrator not working. no power to vibrator.
672370	26-Sep-22	steer cylinder crossover hose rusty needs replacing
672645	26-Sep-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
673460	26-Sep-22	Replace damaged fuel line
673483	26-Sep-22	repair rear lights and wiring
673887	28-Sep-22	pos 3 puncture.
673639	29-Sep-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
673678	3-Oct-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
674416	3-Oct-22	NORMET SHOTCRETER BOOM SLIDE CHANGE OUT
674836	5-Oct-22	replace outer door handle & gas strut
674846	5-Oct-22	check concrete pump not working
674592	6-Oct-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
674901	6-Oct-22	chem line fitting & rehang hoses on boom
674204	7-Oct-22	REPLACE ZOOM SLIDES
674325	9-Oct-22	checked a/c operation
674437	10-Oct-22	replace zoom slides
674438	10-Oct-22	replaced joy stick
674439	10-Oct-22	mobilaris faults at times / speed sensor
674440	10-Oct-22	front & rear diff over full check next service day
674628	10-Oct-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
675102	10-Oct-22	A/C not working.

675103	10-Oct-22	check cabin door not shutting.
675130	10-Oct-22	replace side view mirror.
675667	11-Oct-22	tapped m6 threads in a/c filter box.
675668	11-Oct-22	repaired hyd filter housing bracket.
676003	12-Oct-22	check a/c no cold enough - washed condensor coming up
675720	13-Oct-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
675754	17-Oct-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
675669	18-Oct-22	hopper cutting ring and wear plate need replacing.
677164	19-Oct-22	Repair chem fault
676713	20-Oct-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
677301	23-Oct-22	cabin door handle u/s
677370	23-Oct-22	dash 12 carrier hose u/s.
676747	24-Oct-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
677664	25-Oct-22	replace rear bump stop rubbers
677665	25-Oct-22	repaired lower hopper door
677501	27-Oct-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
677943	27-Oct-22	Wont start. Fuel Cap issue
677254	29-Oct-22	Mobilaris bracket broken
677536	31-Oct-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
678295	31-Oct-22	Change out front and rear diff oil
678461	3-Nov-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
678865	3-Nov-22	door latch jammed shut.
678869	3-Nov-22	replace water filters
678462	4-Nov-22	5 YEARLY FIRE SUPPRESSION TEST & INSPECTION
678540	7-Nov-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
679331	7-Nov-22	change out hydra scaler. leaking.
679375	8-Nov-22	replaced side mirror.
679376	8-Nov-22	replaced both wiper arms/blades.
679377	8-Nov-22	cleaned out a/c drain and filter mount area.
679426	10-Nov-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
679814	10-Nov-22	door not opening - adjust
679825	10-Nov-22	vibrator stopped - blown circuit breaker
679874	11-Nov-22	Door strut missing.- J.Villella
679928	11-Nov-22	vibrator u/s
679461	14-Nov-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
680116	14-Nov-22	replace nozle tilt cyl hoses
680117	14-Nov-22	unblock a/c drains
680119	14-Nov-22	adjust door sensor because parkbrake coming on
680120	14-Nov-22	repair hyd temp sensor wiring
680122	14-Nov-22	replace rear diff oil - overfull
679378	15-Nov-22	engine rocker cover gasket leaking oil. please order seals.
680428	17-Nov-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
679875	18-Nov-22	Stereo U/S-C.McLeod
680811	18-Nov-22	tighten front spot lights.
680097	21-Nov-22	cab door inges need replacing
680121	21-Nov-22	speedo not working - need auto sparky
680126	21-Nov-22	hopper grease fittings need replacing
680467	22-Nov-22	1000 HOUR SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER

681123	24-Nov-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
680848	26-Nov-22	Traffic awareness not available - mobilaris
682283	27-Nov-22	Check out engine loading while operating
681156	28-Nov-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
682389	28-Nov-22	Replace front cab work light
682820	28-Nov-22	hole in exhaust before muffler
682821	28-Nov-22	Change out light
682822	28-Nov-22	pressure washer hose reel U/S
682823	28-Nov-22	Needs a new exhaust brake butterfly
682824	28-Nov-22	Replace exhaust brake actuator
682713	1-Dec-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
682342	5-Dec-22	check excessive engine black smoke
682776	5-Dec-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
683794	6-Dec-22	Safety Bulletin 8_2022 - Gear lock out causing Park Brake
683735	8-Dec-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
684264	10-Dec-22	vibrator u/s
684270	10-Dec-22	pressure washer reel has fallen off ???
683766	12-Dec-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
684707	13-Dec-22	no power, trams up hill at 2km/h / check exhaust brake ??
684618	15-Dec-22	DAILY SERVICE & INSPECTION - SHOTCRETE MACHINES
684991	15-Dec-22	Door locked shut
684657	19-Dec-22	WEEKLY SERVICE & INSPECTION OF SF050D SPRAYMEC SHOTCRETER
685125	25-Dec-22	Fan belt squeals a lot when cold