



**WA Heavy Vehicle
Accreditation**

ACCREDITATION ROADWORTHINESS CHECKLIST

This form is not for licensing purposes, but is only to be used for Western Australian Heavy Vehicle Accreditation. This form summarises what is required to assess the roadworthiness of vehicles.

Owner Details (to be completed by Applicant)

Name in Full: Family Name/Company Name

Given Names:

--	--

ABN:

1	7	3	3	9	3	8	5	3	2	9	
---	---	---	---	---	---	---	---	---	---	---	--

Business Address: (must be completed)

Suburb:

Postcode:

SOUTH AVENUE

Postal Address: (if different from above)

Suburb:

Postcode:

Postal Address: (if different from above)					
---	--	--	--	--	--

Vehicle Details

Year: 2003 Make: KENWORTH Vehicle Type: 6 Wheeler Model: 404

Engine No:

1	4	0	4	2	8	8	3								
---	---	---	---	---	---	---	---	--	--	--	--	--	--	--	--

VIN/Chassis No:

6	F	5	0	0	0	0	0	3	A	4	2	4	1	3	0		
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	--	--

Compliance Plate:

Fitted Y / N

Month / Year

Registration Plate Number:

--

--	--	--	--

6	7	7	3	1			
---	---	---	---	---	--	--	--

I certify that I have inspected this vehicle and, to the best of my knowledge and abilities, declare that it is in a roadworthy condition at the time of inspection.

Inspected By:

Name: _____

AARON PUESSELL

Qualifications/Experience:

15 YEARS ~~TRUCK~~ INDUSTRY - 30 Years AG

Signature: _____

[Handwritten signature]

Date: _____

1	9	1	1	0	1	2	0	2	1
---	---	---	---	---	---	---	---	---	---

Odometer Reading:

--	--	--	--	--	--

Note: This form needs to be signed by a person who is deemed competent under the WA Heavy Vehicle Accreditation System.

1. Approved Inspection Station: or
2. Qualified Mechanic: or
3. Person who has had at least five years experience in the maintenance of heavy vehicles.

Group	Pass	Fail	Item	Comments
Drive Line	☒	☐	Engine	SOFT ENGINE MOUNTS. NEEDS REPLACING (Monitoring)
			Exhaust	
			Transmission & Differential	
			Speedometer & Speed Limiter	
			Vehicle Performance	
Electrical	☒	☐	Fuel & Oil Leaks	
			Wiring, Battery, Connectors, etc.	
			Head, Driving & Parking	
			Indicators	
			Stop, Tail & Number Plate	NEW ONES FITTED.
			Reflectors & Reverse	
			Horn, Dash Lights, Heater/Demister	
Body Work	☒	☐	Screen Wiper/Washer	
			Number Plates & Registration Label	
			Panels, Mudflaps, Tare, Aggregate & Combination	
			White Stripe, Rear Markers	
			Corrosion/Rust	
			Seats and Seat Belts if required	
			Pedal Pads, Dangerous Items	
Chassis & Suspension	☒	☐	Glass, Mirrors	
			Doors/Windows & Controls	
			Damage	
			Corrosion/Rust	
			Suspension & Shock Absorbers	Monitor U bolts.
Steering	☐	☐	Coupling, Turn Table, King Pin	
			Box, Linkage	
			Ball Joints & King Pins, Wheel Bearings	small amount of play
Brakes	☒	☐	Performance	
			Lines & Hoses, Reservoir	
			Service/Foot Brake	
			Hand/Parking Brake	
			Warning Lights	NEW IND'S FITTED.
Wheels & Rims	☒	☐	Performance	
			Fluid/Air Leaks	
			Serviceability, Compatibility, Acceptability	



K404

PAID

Webbie's Mechanical62 Dowd Street
WELSHPOOL WA 6106
Australia

Phone: 0894936021

webbiesmechanical@gmail.com

www.webbiesmechanical.com

ABN: 15 367 474 402

Invoice: IV00000000979

Tax Invoice

Invoice date: 15/09/2021

Bill to:

Due:

22/09/2021

Purchase Order:

A67731 6747hrs

ITEM	DESCRIPTION		UNITS	UNIT PRICE (inc GST)	TAX TYPE	AMOUNT (inc GST)
LAB	Labour heavy vehicle per hour tradesman - B service	Hrs	3	120.00	GST	360.00
END	Penrite DHD Convoy 15W/40	Qty	45	10.505	GST	472.725
LF14000NN	Fleetguard Oil Filter LF14000N Cummins	Qty	1	82.50	GST	82.50
FS1007	Fleetguard Fuel/Water FS1007 Cummins	Qty	1	126.50	GST	126.50
OW	Oil Wastage	Qty	45	0.396	GST	17.82
FW	Filter wastage	Qty	2	2.00	GST	4.00
CONT	Consumables Truck Service	Qty	1	20.00	GST	20.00
3334801CA	Dynadrive 80W/90 per litre - front diff	Qty	18	15.40	GST	277.20
3334801CA	Dynadrive 80W/90 per litre - rear diff	Qty	16	15.40	GST	246.40
OW	Oil Wastage	Qty	30	0.396	GST	11.88
LAB	Labour heavy vehicle per hour tradesman - change diff oils	Hrs	1	120.00	GST	120.00
LAB	Labour heavy vehicle per hour tradesman - replace bonnet hinge mounts	Hrs	1.5	120.00	GST	180.00
11844	Hinge Hood Upper KW	Qty	2	170.775	GST	341.55
11843	Hood Hinge Upper KW	Qty	2	110.00	GST	220.00
AB	Labour heavy vehicle per hour tradesman - replace cab air bags	Hrs	1.5	120.00	GST	180.00
	Cab air bag 1102-A082	Qty	2	210.00	GST	420.00
LAB	Labour heavy vehicle per hour tradesman - replace airbags x 4	Hrs	3	120.00	GST	360.00
	K303-28 Air bag rear	Qty	4	248.00	GST	992.00
	Lamp assembly Turn Signal	Qty	1	123.59	GST	123.59
LAB	Labour heavy vehicle per hour tradesman - replace LHS rear brake shoes	Hrs	1.5	120.00	GST	180.00
KSMA312470 7QP	Brake shoe Drive Meritor KW	Qty	1	165.00	GST	165.00
CONT	Consumables Truck Service	Qty	1	20.00	GST	20.00
COOLGREEN	Penrite Coolant Green per L	Qty	2.5	5.984	GST	14.96

GST: \$448.74
Total (inc GST): \$4,936.13
Amount Paid: \$0.00
AMOUNT DUE: \$4,936.13

Notes

Issues noted during service
Bottom radiator mounts have movement – monitor
Play in steering arm – monitor
Front and rear diff oil very dirty – changed
Cab airbags split and leaking – replaced
4 rear air bags cracked and leaking air – replaced
Front engine mounts squished – monitor
Engine miss – worse after 1500rpm – needs further investigation - truck has a limiter in place to stop it over revving and that is the noise present
Front spring u bolts broken
LHS rear brake shoes low – replaced
Slack adjusters are seized – freed up
Coolant topped up 5L

How to Pay Due 22/09/2021

Bank Deposit via EFT

Bank: NAB

Name: Webbies Mechanical

BSB: 086006

AC#: 415552632

Ref#: IV00000000979



Merredin Auto Electrics
& Air Conditioning

TAX INVOICE

V-100

Invoice Date
22 Jul 2021

Invoice Number
INV-1401

Reference
1GUY 179

ABN
98 649 345 977

Merredin Auto Electrics &
Air Conditioning

ABN 98 649 345 977 -
AU08159

4 Fifth Street
PO Box 641

MERREDIN WA 6415

Phone (08) 9041 3013

Mobile 0418 990 120

Email

mdnautoelec@bigpond.co
m

Description	Quantity	Unit Price	GST	Amount AUD
KENWORTH TRUCK				
TEST STARTING FAULT. DIAGNOSE BREAK IN MAIN ENGINE WIRING HARNESS DOWN LEFT SIDE OF ENGINE FOR START CIRCUIT. STRIP BACK HARNESS AND REWIRE START CIRCUIT AS REQUIRED. REPAIR DAMAGED WIRING IN HARNESS. DIAGNOSE AND REPLACE FAULTY BATTERIES. CLEAN UP ALL BATTERY CABLE CONNECTION AND REPAIR CORRODED TERMINALS TO MAIN POWER CIRCUIT BREAKER. RETEST START AND CHARGE SYSTEMS. MAKE UP AND REPLACE CAB TO CHASSIS EARTH.				
BOSCH 105D31R BATTERIES	4.00	220.00	10%	880.00
EARTH CABLE	1.00	35.00	10%	35.00
WIRING, TUBING, LUGS, SUNDRIES	1.00	50.00	10%	50.00
LABOUR	10.00	125.00	10%	1,250.00
			Subtotal	2,215.00
			TOTAL GST 10%	221.50
			TOTAL AUD	2,436.50

Due Date: 29 Jul 2021
BANKWEST MERREDIN
BSB: 306 022
ACCOUNT NO: 0233255