

# Takata VIN Lookup

This VIN Lookup database is only applicable to Holden, Opel & Saab vehicles sold in **Australia**, which are impacted by the Consumer Goods (Motor Vehicles with Affected Takata Airbag Inflators and Specified Spare Parts) Recall Notice 2018.

**Your vehicle identification number (VIN)**

## Enter your 17 Digit VIN

The VIN can be found: (1) on the bottom corner of windscreen on passenger side, (2) inside the driver's door, or (3) near the firewall in the engine.

Go >

VIN: 6H8WHY19F1L760043

LAST UPDATED: 1 June 2023



## No Recalls Found

**There are no outstanding recalls associated with your vehicle.**

This could mean that your vehicle was never affected by the Takata Recall, or is complete.

No further action is required for your vehicle in relation to the Takata Recall.

GM Holden never fitted like-for-like Affected Takata Airbag Inflators to any Holden, Opel or Saab vehicle as part of the Takata Recall. If you would like further information please contact Holden Customer Care on 1800 632 826.

To make sure you are contactable for any future recalls, make sure your contact details are up to date by clicking the link below.