

Coates Hire Pre Divestment Inspection Checklist

Pumps

Description _ Vacuume Excavator 1145126

This checklist is a record of a visual inspection which identifies defects reasonably known to Coates at the time. It should only be used as a guide. The buyer should rely on their own inspection and assessment of the equipment. The equipment is used and sold as is. Coates does not warrant that the equipment is new, fit for purpose, of merchantable quality, free from defects in materials and workmanship, or complies with all relevant laws, Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on Coates which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. The Coates Hire Used Equipment Terms and Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or at www.coateshire.com.au.

General Information: *** Copy Data Plate information in this section ***

Make/ Model	<u>Vermeer VX250 30</u>	Engine/Motor - Make/Model	<u>Yanmar 3GNDA</u>
Year	<u>13.01.2015</u>	Engine Serial Number	<u>3TNV82A</u>
Serial Number	<u>VX25S110414849</u>	Meter Reading	<u>1384</u>

Comments: _____

Features:

List features or options for the machine:	Self Priming <input type="checkbox"/>	Comments:
Inlet Diameter: <u>75mm</u>	Frame Mount <input type="checkbox"/>	<u>Suction tool, reduction tool, wash wand included</u>
Outlet Diameter: <u>100mm</u>	Trailer Mount <input type="checkbox"/>	_____
Output Volume: _____		

Overall Appearance:

	Good	Fair	Poor	Comments:
Control Station\Operator Station	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Sheet metal\Fiberglass Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>Average condition</u>
Paint	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Lights	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Control Station

	Operates			Comments:
	Yes	No	N/A	
Operator Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<u>All works ok</u>
Gauges Operational?	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

Engine or Electric Motor:

Power:	Diesel <input checked="" type="checkbox"/>	Gas <input type="checkbox"/>	Electric <input type="checkbox"/>	
Does it start?	<input checked="" type="checkbox"/>	<input type="checkbox"/>		Comments:
Did it need to be jumped?	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Acceptable Power	<input checked="" type="checkbox"/>	<input type="checkbox"/>		<u>Engine good</u>
Unusual Noises	<input type="checkbox"/>	<input checked="" type="checkbox"/>		

Chassis

	Good	Fair	Poor	Inoper	Missing	N/A	Comments:
Frame Condition	<input checked="" type="checkbox"/>	<input type="checkbox"/>					
Trailer Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>ok condition</u>				
Trailer Electrical Connections	<input checked="" type="checkbox"/>	<input type="checkbox"/>					
Trailer Brakes	<input checked="" type="checkbox"/>	<input type="checkbox"/>					
Switches	<input checked="" type="checkbox"/>	<input type="checkbox"/>					

Tyre Condition:

Left - Front		Left - Rear		Comments:
Brand- <u>Bridgestone</u>		Brand- <u>Bridgestone</u>		<u>Tyres average</u>
Size- <u>225.75.15</u>		Size- <u>225.75.16</u>		
Condition <u>Good</u>		Condition <u>Good</u>		

Any other known issues, faults: Old unit all working