Coates Inspection Checklist	
Scissor Lift (Electric or Internal Combustion)	Photos
See Scissor Lift Photo Log for required pictures Asset # 1150845	
General Information: *** Copy Data Plate information in this section *** Make/ Model JLG 1930ES Engine / Motor - Make / Model N/A Year 2014 Engine Serial Number N/A Serial Number B200019003 Meter Reading 318 Comments: Disposla due to Ten year inspection due	Data Plate
Features: Max Lift Height 5.7mt 760mm x 1870mm - 900mm extension Platform Extension Battery Charger Generator Generator	4-Corner Photos Left-Front Corner Left-Rear Corner Right-Front Corner Right-Fraer Corner Damage Damage Damage Damage
Overall Appearance:	
Good Fair Poor Control Station\Operator Station Sheet metal\Fiberglass Condition Paint Good Fair Poor Control Station\Operator Station Fair Poor Control Station\Operator Station Fair Poor Control Station\Operator Station Fair Poor Control Station\Operator Station Fair Poor Control Station\Operator Station	
Control Station	Hour Meter
Operates Yes No N/A Operator Controls: Platform	Ground Controls Platform Controls Guages Damage Damage
Engine or Electric Motor:	
Power: Diesel Gas Dual Fuel Electric Yes No Does it start? Comments: Did it need to be jumped? Acceptable Power Unusual Noises	Right Side hood open Left Side hood open
Hydraulics Operates Leaks	
Yes No N/A Yes No N/A Comments: Pump Hoses Cylinders Drive Motors Brakes Parking Brakes Ves No N/A Yes No N/A Comments: minor leaks starting on both wheel seals minor leaks starting on both wheel seals	Pump Cylinders Drive Motor Damage Damage Damage
Chassis: Good Fair Poor Inoper Missing N/A Comments:	
Frame Condition	Scissor Linkage (Extend) Steering Linkage Work Platform
Tire Condition:	Tire pictures at a 45 degree angle
Left - Front Left - Rear Right - Front Right - Rear Brand- Soildeal Brand- Soildeal Brand- Soildeal Brand- Soildeal Size- 323x100 Size- 323x100 Size- 323x100 Condition- fair Condition- fair Condition- fair	showing the tread and side walls Left-Front Left-Rear Right-Front Right-Rear