Coates Inspection Checklist

Trucks

Photos

See Truck Photo Log for required pictures **Asset #** _____ 1184079

General Information: *** Copy Data Plate information in this section ***

Make/ Model	Fuso Canter 515	Engine / Motor - Make / Model	
Year	2017	Engine Serial Number	
Serial Number	JLFFEA61B0KJ30362	Meter Reading	81372

Comments:

☐ Data Plate

Features:

Pickup ☐ Flat Bed ☐ Dump ☐ Boom ☐ Other ☒

				Yes	No
Drive Syatem	2WD ☒	4WD ☐	Power Take Off	☐	☐

Axle Weights Rating: Front _____

Axle Weights Rating: Rear _____

Registration Information Number _____ Year _____ Month _____

4-Corner Photos

☐ Left-Front Corner
☐ Left-Rear Corner
☐ Right-Front Corner
☐ Right-Rear Corner
☐ *Damage*
☐ *Damage*

Overall Appearance:

	Good	Fair	Poor	
Control Station\Operator Station	☐	☒	☐	
Sheet metal\Fiberglass Condition	☐	☒	☐	
Paint	☐	☒	☐	
Lights	☐	☒	☐	

Operator Station

	Good	Fair	Poor	N/A	
Seat Condition	☐	☒	☐	☐	
Steering Controls	☐	☒	☐	☐	
Powertrain Controls	☐	☒	☐	☐	
Hydraulic Controls	☐	☒	☐	☐	

☐ Hour Meter
☐ Guages
☐ *Damage*
☐ *Damage*

Operational	Operates Yes	Operates No	Operates N/A		Operates Yes	Operates No	Operates N/A
Safety Belt	☒	☐	☐	Horn	☒	☐	☐
Gauges	☒	☐	☐	Warning Alarms	☒	☐	☐
Air Conditioner	☒	☐	☐	Odometer	☒	☐	☐
Heater	☒	☐	☐	Wipers	☒	☐	☐

Engine or Electric Motor:

Power: Diesel ☒ Gas ☐

	Yes	No	
Does it start?	☒	☐	Comments: Has starting issue needs assisstance with Aerostart (Pump)
Did it need to be jumped?	☐	☒	
Acceptable Power	☒	☐	
Unusual Noises	☐	☒	

☐ Right Side hood open
☐ Left Side hood open

Transmission

Transmission Type Auto ☐ Manual ☐ Number of Speeds _____

	Operates Yes	Operates No	Operates N/A		Operates Yes	Operates No	Operates N/A
Forward	☒	☐		Clutch	☐	☐	☐
Reverse	☒	☐		Parking Brake	☒	☐	
Shifting	☐	☐		Brakes	☒	☐	

Chassis

	Good	Fair	Poor	Inoper	Missing	N/A	Comments:
Bumpers	☐	☒	☐	☐	☐	☐	
Windshield Condition	☐	☒	☐	☐	☐	☐	
Trailer Electrical Connections	☐	☒	☐	☐	☐	☐	
Work Body Function	☐	☒	☐	☐	☐	☐	

☐ Work Body
☐ Work Body
☐ Work Body
☐ *Damage*
☐ *Damage*
☐ *Damage*

Tire Condition:

Tire pictures at a 45 degree angle showing the tread and side walls

Left - Front	Left - Rear	Right- Front	Right - Rear
Brand-	Brand-	Brand-	Brand-
Size-	Size-	Size-	Size-
Condition-	Condition-	Condition-	Condition-
Fair	Fair	Fair	Fair

☐ Left
☐ Right