from defects in materials and workmanship, or complies with all relevant laws, Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on Coates which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. The Coates Hire Used Equipment Terms and Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or at www.coateshire.com.au.

General Information: *** Copy Data Plate information in this section ***

Make/ Model: AUSWIDE
Year: 2018
Serial Number: 6PT26V86H0HRZ369
Engine/Motor - Make/Model:
Engine Serial Number:
Meter Reading:
Comments:

Features: List features or options for the machine:

	Yes	No
Battery Pack (Electric)	☐	☐
Solar Panel	☐	☐

Number of Batteries:
Battery Size:
Fuel Tank Capacity:

Overall Appearance:

	Good	Fair	Poor
Control Station\Operator Station	☐	☐	☐
Sheet metal\Fiberglass Condition	☐	☐	☑
Paint	☐	☐	☐
Lights	☐	☐	☐

Comments:

Control Station

	Operates Yes	Operates No	N/A
Operator Controls	☐	☐	
Gauges Operational?	☐	☐	☐
Controller	☐	☐	☐

Comments:

Engine or Electric Motor:

Power: Diesel ☐ Gas ☐ Electric ☐ Solar ☐

	Yes	No
Does it start?	☐	☐
Did it need to be jumped?	☐	☐
Acceptable Power	☐	☐
Unusual Noises	☐	☐

Comments:

Chassis:

	Good	Fair	Poor	Inoper	Missing	N/A
Landing Gear / Outriggers	☐	☐	☐	☐	☐	☑
Frame Condition	☐	☐	☑	☐	☐	☐
Trailer Lights	☐	☑	☐	☐	☐	☐
Trailer Electrical Connections	☐	☑	☐	☐	☐	☐
Trailer Brakes	☐	☑	☐	☐	☐	☐
Switches	☐	☐	☐	☐	☐	☑
Arrow Board	☐	☐	☐	☐	☐	☑
Message Center	☐	☐	☐	☐	☐	☑
Solar Panel	☐	☐	☐	☐	☐	☑
Battery and Connections	☐	☐	☐	☐	☐	☑

Comments:

Tyre Condition:

Left - Front	Left - Rear
Brand-	Brand-
Size-	Size-
Condition- POOR	Condition- POOR.

Comments:

Any other known issues, faults:

TRAILER has multiple cracks throughout.