

QTY/ UNITS	ITEM NO.	DESCRIPTION	UNIT	EX AMOUNT	CODE
	1	Work completed 20/12/24 Service Kobalco excavator XE113 989 hrs			
1	Parts	Service filter kit		\$305.00	GST
20	EngOil	Litres Engine Oil	1	\$150.00	GST
12	Fin Dr Oil	Litre Final Drive Oil		\$96.00	GST
4	LabC	Labour Hours		\$400.00	GST

Sub Total \$951.00

GST \$95.10

TOTAL AMOUNT PAYABLE \$1,046.10

Terms: 7 days net

Rego #	N5851	Serial #	YY09052449	Hours	528	QTY.	UNIT	AMOUNT.
--------	-------	----------	------------	-------	-----	------	------	---------

***Carry out Kobelco 500 Hour Service as per manufacturer's recommendations as listed below**

KOBELCO SK135SR-7 EXCAVATOR

- Change Engine oil and oil filter (15W40)
- Change Outer air cleaner
- Change Inner air cleaner
- Change Reduction motor oil (80W90)
- Check Air intake hoses
- Check For exhaust leaks
- Change Fuel filters
- Check Fuel line condition
- Top up Engine Coolant, check all clamps (Kobelco)
- Clean Radiator and oil cooler free from excessive debris build-up
- Clean Fuel cap and strainer
- Check Engine mounts
- Adjust Fan belt condition and tension
- Adjust A/C belt condition and tension
- Replace Cab filters
- Top up Washer bottle
- Check Hydraulic oil return filter
- Top up Hydraulic oil level and condition (ISO46)
- Check Hydraulic hoses, lines and fittings
- Adjust Track tension
- Check Sprockets and track Rollers
- Check Machine for leaks
- Check Battery electrolyte and connections
- Check All lights and horn

EFT Banking Details	
----------------------------	--

Rego #	N5851	Serial #	YY09052449	Hours	528	QTY.	UNIT	AMOUNT.
--------	-------	----------	------------	-------	-----	------	------	---------

Check Safety lock lever operation
 Check Seatbelt
 Grease All Pins
 Check Slew motor oil (Change at initial 500 hour)
 Grease Slew Bearing and pinion
 Check Bucket teeth and side cutters (if fitted)
 Check Quick Hitch Operation (Check safety pin is fitted if fitted)
 Test operation
 Fit service sticker
 Check over all work carried out (i.e Filters, Fluid levels, Filler caps, Belts, Belly plates, Panels, Reset service indicator etc)

Travelled to site. Carried out 500-hour service as per above checklist. Replaced engine oil.
 Replaced all filters as per list. Checked oils/fluids & topped to correct levels as required.
 Checked over machine & tested operation for faults, none evident.
 Carried out rest of service & greased machine.

VI898:OIL FILTER	1.00	44.21	44.21
4645015W40 DH-2 ENGINE OIL 1L	18.00	10.07	181.31
4018080W90 GEAR OIL 1L	5.00	7.90	39.50
40190ISO 46 HYDRAULIC OIL 1L	14.00	7.96	111.49
GREAMULTI-PURPOSE EP GREASE	2.00	14.00	28.00
VI898:FUEL FILTER SK135SR-7 / 140SRLC-7 / 140LC-11	1.00	93.31	93.31
YN211FUEL FILTER	1.00	58.73	58.73
VI898:FUEL FILTER	1.00	44.21	44.21
LP11FAIR FILTER INNER SK135SR-7 / 140SRLC-7 / 140LC-11	1.00	67.31	67.31

EFT Banking Details	
----------------------------	--

Rego #	N5851	Serial #	YY09052449	Hours	528	QTY.	UNIT	AMOUNT.
LP11FAIR FILTER OUTER SK135SR-7 / 140SRLC-7 / 140LC-11						1.00	96.43	96.43
LQ50\CAB FILTER						1.00	131.60	131.60
YT50\CAB FILTER						1.00	88.10	88.10
ADCSCLEAR SCREEN 30ML						1.00	3.00	3.00
Travel Charges						2.40	130.00	312.00
Total Labour								430.30

Subtotal	1,729.50
Add GST	172.94
Total	1,902.45

