

Coates Hire Pre Divestment Inspection Checklist Boom Lift (Electric or Internal Combustion)

Name _____ Branch _____
Description TRAILER MOUNTED BOOM Asset # 1171625 Service Job # _____

This checklist is a record of a visual inspection which identifies defects reasonably known to Coates at the time. It should only be used as a guide. The buyer should rely on their own inspection and assessment of the equipment. The equipment is used and sold as is. Coates does not warrant that the equipment is new, fit for purpose, of merchantable quality, free from defects in materials and workmanship, or complies with all relevant laws, Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on Coates which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. The Coates Hire Used Equipment Terms and Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or at www.coateshire.com.au.

General Information: *** Copy Data Plate Information in this section ***

Make/ Model NIFTY 120TPE Engine/Motor - Make/Model HONDA
Year 2016 Engine Serial Number _____
Serial Number 0432960 Meter Reading 427

Comments: _____

Features: TRAILER MOUNTED Max Lift Height 10M Comments: _____
Drive System 2WD ☒ 4WD ☒ Platform size _____
AC Chord to Basket Yes ☒ No ☒ Battery Charger Yes ☒ No ☒
Air to Basket ☒ Generator ☒
Does Basket Rotate ☒ Outriggers ☒
Knuckle Boom ☒ Extendable axles ☒
Straight Boom ☒ Articulating Jib ☒

Overall Appearance: Good Fair Poor Comments: _____
Control Station/Operator Station ☒ ☒ ☒
Sheet metal/Fiberglass Condition ☒ ☒ ☒
Paint ☒ ☒ ☒
Lights ☒ ☒ ☒

Control Station Operates Yes No N/A Comments: _____
Operator Controls: Platform ☒ ☒ ☒
Operator Controls: Ground ☒ ☒ ☒
Gauges Operational? ☒ ☒ ☒

Engine or Electric Motor: Power: Diesel ☒ Gas ☒ Dual ☒ Electric ☒ AIRCEL / ELECTRIC
Does it start? ☒ ☒ ☒
Did it need to be jumped? ☒ ☒ ☒
Acceptable Power ☒ ☒ ☒
Unusual Noises ☒ ☒ ☒
Comments: REQUIRES BATTERIES REPLACED
NEEDS FUEL RECOIL O/S

Hydraulics Operates Yes No Leaks Yes No Comments: _____
Pump ☒ ☒ ☒ ☒
Hoses ☒ ☒ ☒ ☒
Cylinders ☒ ☒ ☒ ☒
Drive Motors ☒ ☒ ☒ ☒
Brakes ☒ ☒ ☒ ☒
Parking Brakes ☒ ☒ ☒ ☒
HYDRAULIC LEAK AT ROTATOR - POSSIBLE ORING

Chassis: Good Fair Poor Inoper Missing N/A Comments: _____
Frame Condition ☒ ☒ ☒ ☒ ☒ ☒
Mast/ Boom Sections ☒ ☒ ☒ ☒ ☒ ☒
Boom Extension Wear Guides ☒ ☒ ☒ ☒ ☒ ☒
Basket Condition ☒ ☒ ☒ ☒ ☒ ☒
Outriggers and Pads Condition ☒ ☒ ☒ ☒ ☒ ☒
Rotational Gear Condition ☒ ☒ ☒ ☒ ☒ ☒
Extendable Axle ☒ ☒ ☒ ☒ ☒ ☒
TurnTable Bearing Play ☒ ☒ ☒ ☒ ☒ ☒
- TRAVEL LOCK CRACKED

Tyre Condition: Left - Front Left - Rear Right - Front Right - Rear
Brand- MAXXIS Brand- Brand- MAXXIS Brand-
Size- 175 R 14C Size- Size- 175 R 14 RC Size-
Condition- FAIR Condition- Condition- FAIR Condition-

Definium Device fitted? Yes No Definium device returned to BU ASM

BASKET Alarm O/S