



DISCLAIMER: Second-Hand Plant Condition and Safety

This document is Jungheinrich Australia Pty Ltd's (**Jungheinrich**) official notice that the second-hand plant offered for sale through this transaction (direct sale or auction) may contain faults or deficiencies that could pose risks to health and safety.

Important Information

Safety & Compliance of the Plant

Given the plant is second-hand, please be aware it may include wear and tear, or be missing safety features that were not present or required at the time of original manufacture.

Jungheinrich has taken all reasonably practicable steps to identify any faults in the plant. The **enclosed** Condition Report sets out the current condition of this plant, including any identified faults.

While all efforts have been made to identify faults, there may be other faults present that did not show up at time of inspection

Operational Safety Notice

The plant should not be used until all identified faults have been rectified and the equipment is deemed safe for operation.

It is the responsibility of the purchaser to ensure that the plant is inspected, serviced, and, if necessary, modified to meet current safety standards before use.

By participating in this sale and purchasing the second-hand plant, the purchaser acknowledges receipt of this notice and accepts full responsibility for ensuring the plant is safe for use.

Operating condition of the plant

Note: this condition report is a safety report only and does not represent overall appearance or operating condition of the plant

For any questions please contact Jungheinrich



Used Sale Safety & Compliance Check

MHE-000032 / 90578610 / Melbourne Service / 02/09/2025 /
Jungheinrich / EMD118

Complete

Flagged items	0
Report ID	MHE-000032
Technician Name	Melbourne Service
Conducted on	02/09/2025 11:41 AM AEST
Branch	Melbourne
Unit Details	
Equipment No.	90578610
Brand	Jungheinrich
Model	EMD118

Include Images of the Front, Rear & Sides of the Unit




Photo 1



Photo 2



Photo 3



Photo 4



Photo 5

Observations Summary

Truck Category

Category 1 - Pedestrian Type Trucks

Emergency Stop accessible and operational

Yes

Tiller arm switch allows drive function only in prescribed range

Yes

Tiller head crush prevention operational

Yes

Horn/Warning device operational

Yes

Confirm safety systems not bypassed or malfunctioning?

Yes

Additional Observations & Actions

Technician Sign off



isaac puli
02/09/2025 11:44 AM AEST

Media summary




Photo 1



Photo 2



Photo 3



Photo 4



Photo 5