

Coates Hire Pre Divestment Inspection Checklist

Generators (Diesel or Petrol)

Name _____ Branch _____
 Description 80KV Asset # 11877946 Service Job # _____

This checklist is a record of a visual inspection which identifies defects reasonably known to Coates at the time. It should only be used as a guide. The buyer should rely on their own inspection and assessment of the equipment. The equipment is used and sold as is. Coates does not warrant that the equipment is new, fit for purpose, of merchantable quality, free from defects in materials and workmanship, or complies with all relevant laws, Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on Coates which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. The Coates Hire Used Equipment Terms and Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or at www.coateshire.com.au.

General Information: *** Copy Data Plate information in this section ***

Make/ Model PERKINS Engine / Motor - Make / Model _____
 Year 2017 Engine Serial Number _____
 Serial Number R5515192029939C Meter Reading 24099

Comments: _____

Features: List features or options for the machine:

Generator Type Single Phase ☐ 3 Phase ☒ Comments: _____
 Frame mount ☐ Trailer mount ☒
 Generator KVA Rating 80KVA
 Power Outlets Qty Single Phase 3 Amps per outlet 20A, 32A, 50A
 Qty 3 Phase 3 Amps per outlet 10A, 15, 15

Overall Appearance:

	Good	Fair	Poor	Comments:
Control Station/Operator Station	☒	☐	☐	_____
Sheet metal/Fiberglass Condition	☒	☐	☐	
Paint	☒	☐	☐	
Lights	☒	☐	☐	

Control Station

Comments: _____
 Operates
 Yes No N/A
 Operator Controls ☒ ☐ ☐
 Gauges Operational? ☒ ☐ ☐

Engine:

Comments: _____
 Power: Diesel ☒ Petrol ☐
 Does it start? Yes ☐ No ☒
 Did it need to be jumped? ☐ ☒
 Acceptable Power ☒ ☐
 Unusual Noises ☒ ☐
ENGINE SIEZED
No GO

Chassis

	Good	Fair	Poor	Inoper	Missing	N/A	Comments:
Landing Gear / Outriggers	☒	☐	☐	☐	☐	☐	<u>ELECTRIC BRAKES</u>
Frame Condition	☒	☐	☐	☐	☐	☐	
Trailer Lights	☒	☐	☐	☐	☐	☐	
Trailer Electrical Connections	☒	☐	☐	☐	☐	☐	
Trailer Brakes	☒	☐	☐	☐	☐	☐	
Switches	☒	☐	☐	☐	☐	☐	
Power Cables	☒	☐	☐	☐	☐	☐	

Tyre Condition:

Left - Front	Left - Rear	Right - Front	Right - Rear
Brand- <u>TRABANO</u>	Brand- <u>TRAN</u>	Brand- <u>TRABANO</u>	Brand- _____
Size- <u>185R 14C</u>	Size- <u>←</u>	Size- <u>185R 14C →</u>	Size- _____
Condition- <u>GOOD</u>	Condition- _____	Condition- <u>GOOD</u>	Condition- _____

Definium Device fitted? Yes No Definium device returned to BU ASM