



Bank Account Details for Direct Payments:
 Acct Name: TRAF TRACTOR
 BSB: 633000 Acct No: 118215821

CNH Industrial Genuine Parts
 Refrigerant Trading Authorisation AU19498
 VACC Accredited Farm Machinery Dealer

ABN: 28 102 809 503
 PO Box 159 Trafalgar VIC 3824
 accounts@ttmi.com.au
 (03) 5633 1588
 www.ttmi.com.au

TRAFALGAR (VIC) - 8-14 Saleyards Road, Trafalgar, 3824 - 03 5633 1588
 MAFFRA (VIC) - 2 Empire Place, Maffra, 3860 - 03 5141 1700
 LEONGATHA (VIC) - 15-19 Hughes Street, Leongatha, 3953 - 03 5637 3300
 LONGFORD (TAS) - 6-8 Wellington Street, Longford, 7301 - 03 6391 2411
 LATROBE (TAS) - 49 Percival Street, Latrobe, 7307 - 03 6426 4200
 WARRNAMBOOL (VIC) - 40 Caramut Road, Warrnambool, 3280 - 03 5559 3300
 COLAC (VIC) - 357 Princes Highway, Colac West, 3250 - 03 5234 3500

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Invoice To:

MORWELL VIC 3840

Deliver To:

MORWELL VIC 3840

Document No.:	545670
Invoice To:	1964
Document Date:	19/03/2021
Repair Order No.:	308838
Rego No.:	ZSEH630
Make/Model:	MCCORMICK CX100
Serial No.:	C10AS4JJE2001546
Hours:	
P/Order No.:	

Genrep01

CLUTCH AND TRANSMISSION REPAIR

Labour Total \$7,739.97

 13/10/2020
 TEST DRIVE TRACTOR
 MAIN CLUTCH UNSERVICEABLE
 THIRD GEAR JUMPING OUT
 FWD/REV LEVER IN UNUSUAL POSITION
 HANDBRAKE CABLE SEIZED
 LHR AXLE SEAL UNSERVICEABLE

 BRING TRACTOR INTO WORKSHOP
 REMOVED LOADER, LOADER FRAMES, SIDE STEPS, FUEL TANK, BATTERY BOX, ETC
 SUSPENDED CAB
 REMOVED REAR TYRES
 DISCONNECTED PIPING, WIRING, ETC, 4X4 SHAFT
 REMOVED LINKAGE ARMS, STARTER MOTOR
 REMOVED EXHAUST PIPE
 SPLIT TRACTOR AT BELL HOUSING
 REMOVED BACK END, GEAR BOX AS COMPLETE UNIT
 REMOVED CLUTCH, FLYWHEEL ASSEMBLY
 PRESSURE WASHED TRANS ASSEMBLY READY FOR REPAIRS

 START TO STRIP DOWN GEARBOX ASSEMBLY TO GET INTO THIRD GEAR SYNCHRO
 REMOVED ALL COVERS
 REMOVED THROW OUT BEARINGS, CROSS SHAFT, TA CLUTCH, ETC

 SPENT TIME CUTTING OUT SEIZED GEARS USING PULLEYS ETC TO REMOVE MAIN SHAFT
 GEAR BOX FULLY DISASSEMBLED



TTMI



Bank Account Details for Direct Payments:
Acct Name: TRAF TRACTOR
BSB: 633000 Acct No: 118215821

CNH Industrial Genuine Parts
Refrigerant Trading Authorisation AU19498
VACC Accredited Farm Machinery Dealer

ABN: 28 102 809 503
PO Box 159 Trafalgar VIC 3824
accounts@ttmi.com.au
(03) 5633 1588
www.ttmi.com.au

TRAFALGAR (VIC) - 8-14 Saleyards Road, Trafalgar, 3824 - 03 5633 1588
MAFFRA (VIC) - 2 Empire Place, Maffra, 3860 - 03 5141 1700
LEONGATHA (VIC) - 15-19 Hughes Street, Leongatha, 3953 - 03 5637 3300
LONGFORD (TAS) - 6-8 Wellington Street, Longford, 7301 - 03 6391 2411
LATROBE (TAS) - 49 Percival Street, Latrobe, 7307 - 03 6426 4200
WARRNAMBOOL (VIC) - 40 Caramut Road, Warrnambool, 3280 - 03 5559 3300
COLAC (VIC) - 357 Princes Highway, Colac West, 3250 - 03 5234 3500

*** DOCUMENT COPY ***

Invoice To:

MORWELL VIC 3840

Deliver To:

MORWELL VIC 3840

SERVICE TAX INVOICE

Document No.:	545670
Invoice To:	1964
Document Date:	19/03/2021
Repair Order No.:	308838
Rego No.:	ZSEH630
Make/Model:	MCCORMICK CX100
Serial No.:	C10AS4JJE2001546
Hours:	
P/Order No.:	

Genrep01

REAR MAIN SEAL U/S
RING GEAR U/S
MAIN CLUTCH U/S
1ST/2ND SYNCHRO U/S
3RD/4TH SYNCHRO U/S
FWD/REV SYNCHRO U/S
MAIN SHAFT REQUIRES MACHINE WORK
MAIN SHAFT CARRIER PLATE DAMAGED NIL STOCK AUS, NIL STOCK AT WRECKERS
3 MONTHS WAIT FROM OVERSEAS
3RD GEAR U/S (DAMAGED BY SYNCHRO AND DAMAGING MAIN SHAFT)

SENT PARTS OUT TO BE MACHINED

REMOVED BROKEN LOADER BOLTS FROM TRANS HOUSING
PRESSURE WASH AND CLEAN UP ALL SURFACES READY FOR REBUILD

CLEANED UP ALL SHAFTS, GEARS, ETC
UNPACKED ALL NEW PARTS
CLEAN OUT BELL HOUSING
REPLACED RING GEAR ON FLYWHEEL
SORT PARTS READY TO START ASSEMBLY

FIT SLIP RINGS ONTO MAIN SHAFT
ASSEMBLE MAIN GEARBOX WITH NEW 1ST/2ND SYNCHRO, 3RD/4TH SYNCRHO, GEAR AND CARRIER PLATE
REASSEMBLE FRONT T/A SECTION OF GEAR BOX

FIT 4X4 DROP BOX TO TRANS ASSEMBLY



TTMI



Bank Account Details for Direct Payments:
Acct Name: TRAF TRACTOR
BSB: 633000 Acct No: 118215821

CNH Industrial Genuine Parts
Refrigerant Trading Authorisation AU19498
VACC Accredited Farm Machinery Dealer

ABN: 28 102 809 503
PO Box 159 Trafalgar VIC 3824
accounts@ttmi.com.au
(03) 5633 1588
www.ttmi.com.au

TRAFALGAR (VIC) - 8-14 Saleyards Road, Trafalgar, 3824 - 03 5633 1588
MAFFRA (VIC) - 2 Empire Place, Maffra, 3860 - 03 5141 1700
LEONGATHA (VIC) - 15-19 Hughes Street, Leongatha, 3953 - 03 5637 3300
LONGFORD (TAS) - 6-8 Wellington Street, Longford, 7301 - 03 6391 2411
LATROBE (TAS) - 49 Percival Street, Latrobe, 7307 - 03 6426 4200
WARRNAMBOOL (VIC) - 40 Caramut Road, Warrnambool, 3280 - 03 5559 3300
COLAC (VIC) - 357 Princes Highway, Colac West, 3250 - 03 5234 3500

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Invoice To:
MORWELL VIC 3840
Deliver To:
MORWELL VIC 3840

Document No.:	545670
Invoice To:	1964
Document Date:	19/03/2021
Repair Order No.:	308838
Rego No.:	ZSEH630
Make/Model:	MCCORMICK CX100
Serial No.:	C10AS4JJE2001546
Hours:	
P/Order No.:	

Genrep01

FIT NEW REAR MAIN, FLYWHEEL(MACHINED) AND CLUTCH ASSEMBLY

REMOVE REAR RHS AXLE ASSEMBLY
REMOVE AND REPLACE AXLE SEAL
REFIT REAR RHS AXLE ASSEMBLY

REFIT TRANS UNDER CAB
BOLTED TO ENGINE
STARTED CONNECTING PIPES WIRING ECT

SERVICE TRANS AND ENGINE
FIT LINKAGE ARMS
FIT NEW BRAKE OVERFLOW HOSE, ETC

FIX CAB BACK ONTO AXLES
FILL WITH OILS

COMPLETE ASSEMBLY OF TRACTOR

START
CHECK ALL OPERATIONS
ALL OK
SMALL LEAKS ON LOADER

FIXED ISSUE WITH BUCKET LOCK ON FEL
FIXED OIL LEAK AT FRONT THIRD FUNCTION BLOCK
PRESSURE WASHED AND TEST DRIVE, ALL OK





Bank Account Details for Direct Payments:
 Acct Name: TRAF TRACTOR
 BSB: 633000 Acct No: 118215821

CNH Industrial Genuine Parts
 Refrigerant Trading Authorisation AU19498
 VACC Accredited Farm Machinery Dealer

ABN: 28 102 809 503
 PO Box 159 Trafalgar VIC 3824
 accounts@ttmi.com.au
 (03) 5633 1588
 www.ttmi.com.au

TRAFALGAR (VIC) - 8-14 Saleyards Road, Trafalgar, 3824 - 03 5633 1588
 MAFFRA (VIC) - 2 Empire Place, Maffra, 3860 - 03 5141 1700
 LEONGATHA (VIC) - 15-19 Hughes Street, Leongatha, 3953 - 03 5637 3300
 LONGFORD (TAS) - 6-8 Wellington Street, Longford, 7301 - 03 6391 2411
 LATROBE (TAS) - 49 Percival Street, Latrobe, 7307 - 03 6426 4200
 WARRNAMBOOL (VIC) - 40 Caramut Road, Warrnambool, 3280 - 03 5559 3300
 COLAC (VIC) - 357 Princes Highway, Colac West, 3250 - 03 5234 3500

*** DOCUMENT COPY ***

SERVICE TAX INVOICE

Invoice To:

MORWELL VIC 3840

Deliver To:

MORWELL VIC 3840

Document No.:	545670
Invoice To:	1964
Document Date:	19/03/2021
Repair Order No.:	308838
Rego No.:	ZSEH630
Make/Model:	MCCORMICK CX100
Serial No.:	C10AS4JJE2001546
Hours:	
P/Order No.:	

Genrep01

FIT ROTARY HOE AND UNSEIZE TOP LINK
 CHECK OVER AND RUN UP

 ALL OK

 TIME TAKEN 118HRS
 TIME CHARGED 60HRS

Part Number	Part Description	Quantity	Nett Value	Total Cost
3145060R91	SEAL - SHAFT SEAL	1.00	28.25	28.25
638-54115	Misc	1.00	2.87	2.87
399798R91	Misc	2.00	13.44	26.88
3214797R1	FILTER - ENGINE OIL	1.00	15.64	15.64
S.127066	Clutch Kit with Bearings	1.00	1,020.57	1,020.57
87682999	FILTER - AIR (INNER) S/S 76094	1.00	23.05	23.05
84217229	FILTER - AIR (OUTER)	1.00	42.28	42.28
84214564	FILTER - FUEL (LONG)	1.00	26.60	26.60
398329R1	Misc	1.00	16.86	16.86
304844A1	Misc	2.00	1,402.06	2,804.12
293583A1	Misc	1.00	52.45	52.45
258444A1	Misc	8.00	6.88	55.04
256519A1	Misc	1.00	4.32	4.32
254510A1	Misc	1.00	2.53	2.53
254509A1	Misc	1.00	2.52	2.52
253944A3	Misc	1.00	989.96	989.96
245832A1	Misc	2.00	36.17	72.34
431145A1	FILTER - HYDRAULIC OIL - 'O' R	1.00	175.98	175.98





Bank Account Details for Direct Payments:
 Acct Name: TRAF TRACTOR
 BSB: 633000 Acct No: 118215821

CNH Industrial Genuine Parts
 Refrigerant Trading Authorisation AU19498
 VACC Accredited Farm Machinery Dealer

ABN: 28 102 809 503
 PO Box 159 Trafalgar VIC 3824
 accounts@ttmi.com.au
 (03) 5633 1588
 www.ttmi.com.au

TRAFALGAR (VIC) - 8-14 Saleyards Road, Trafalgar, 3824 - 03 5633 1588
 MAFFRA (VIC) - 2 Empire Place, Maffra, 3860 - 03 5141 1700
 LEONGATHA (VIC) - 15-19 Hughes Street, Leongatha, 3953 - 03 5637 3300
 LONGFORD (TAS) - 6-8 Wellington Street, Longford, 7301 - 03 6391 2411
 LATROBE (TAS) - 49 Percival Street, Latrobe, 7307 - 03 6426 4200
 WARRNAMBOOL (VIC) - 40 Caramut Road, Warrnambool, 3280 - 03 5559 3300
 COLAC (VIC) - 357 Princes Highway, Colac West, 3250 - 03 5234 3500

*** DOCUMENT COPY ***

Invoice To:

MORWELL VIC 3840

Deliver To:

MORWELL VIC 3840

SERVICE TAX INVOICE

Document No.:	545670
Invoice To:	1964
Document Date:	19/03/2021
Repair Order No.:	308838
Rego No.:	ZSEH630
Make/Model:	MCCORMICK CX100
Serial No.:	C10AS4JJE2001546
Hours:	
P/Order No.:	

Genrep01

242186A2	Misc	1.00	565.29	565.29
218271A1	GASKET	1.00	82.62	82.62
116597A1	Misc	2.00	13.48	26.96
105471C1	SEAL	1.00	24.89	24.89
S.40364	RING GEAR	1.00	191.15	191.15
FREIGHT	FREIGHT	1.00	175.00	175.00
A54022	BEARING	3.00	22.80	68.40
638-54125	O RING	1.00	2.91	2.91
88868	Misc	1.00	0.48	0.48
CONS	WORKSHOP CONSUMABLES	1.00	27.00	27.00
Parts Totals:		41.00		\$6,526.96

Sublet01

PARTS AND LABOUR TO: REPAIR RAM AS REQUESTED DISASSEMBLE RAM WASH ALL PARTS AND BEAD BLAST HEAD POLISH CHROME SHAFT REPLACE ALL SEALS ASSEMBLE ---	Labour Total	\$368.38
---	---------------------	-----------------

Sublet03

PARTS AND LABOUR TO REPAIR WORN SPLINE SECTION ON GEARBOX SHAFT ---	Labour Total	\$1,181.26
--	---------------------	-------------------



TTMI



Bank Account Details for Direct Payments:
Acct Name: TRAF TRACTOR
BSB: 633000 Acct No: 118215821

CNH Industrial Genuine Parts
Refrigerant Trading Authorisation AU19498
VACC Accredited Farm Machinery Dealer

ABN: 28 102 809 503
PO Box 159 Trafalgar VIC 3824
accounts@ttmi.com.au
(03) 5633 1588
www.ttmi.com.au

TRAFALGAR (VIC) - 8-14 Saleyards Road, Trafalgar, 3824 - 03 5633 1588
MAFFRA (VIC) - 2 Empire Place, Maffra, 3860 - 03 5141 1700
LEONGATHA (VIC) - 15-19 Hughes Street, Leongatha, 3953 - 03 5637 3300
LONGFORD (TAS) - 6-8 Wellington Street, Longford, 7301 - 03 6391 2411
LATROBE (TAS) - 49 Percival Street, Latrobe, 7307 - 03 6426 4200
WARRNAMBOOL (VIC) - 40 Caramut Road, Warrnambool, 3280 - 03 5559 3300
COLAC (VIC) - 357 Princes Highway, Colac West, 3250 - 03 5234 3500

*** DOCUMENT COPY ***

<p>Invoice To:</p> <p>MORWELL VIC 3840</p> <p>Deliver To:</p> <p>MORWELL VIC 3840</p>

Document No.:	545670
Invoice To:	1964
Document Date:	19/03/2021
Repair Order No.:	308838
Rego No.:	ZSEH630
Make/Model:	MCCORMICK CX100
Serial No.:	C10AS4JJE2001546
Hours:	
P/Order No.:	

SERVICE TAX INVOICE

Sublet03

308838

Advisor: NICKY MORRIS

Sub Total for All:	\$15,816.57
Rounding:	\$0.00
GST:	\$1,581.66
Total:	\$17,398.23

Our goods come with guarantees that cannot be excluded under the Australian Consumer Law. You are entitled to a replacement or refund for a major failure and for compensation for any other reasonably foreseeable loss or damage. You are also entitled to have the goods repaired or replaced if the goods fail to be of acceptable quality and the failure does not amount to a major failure.

Bank Account Details for Direct Payments:

Bank: BBL Branch: TRAFALGAR
BSB: 633000 Account No.: 118215821 Account Name: TRAF TRACTOR

