

SERVICE TAX INVOICE

Ian Weigh Toyota
 Ian Weigh Toyota Rockhampton T 07 4924 5200
 127 Denison Street,
 Rockhampton, QLD 4700 email@ianweightoyota.com.au
 PO Box 1187 Rockhampton QLD 4700 ianweightoyota.com.au

BSB: 064-710 ACC: 10043785
 ABN: 90 148 491 233
 DL: 3621466 ARC: AU32360

REPAIR ORDER No: JCT0106752	PAGE: 1
C1 Customer (Cash)	

Customer: TARABAH GRAZING PTY LTD 'Tarabah Station' TAMBO QLD 4478		DATE: 21/12/2023	TIME IN: 9:00 AM	TIME OUT: 4:15 PM	KILOMETERS: 101406	ADVISER: LT1	
VEHICLE: Hilux 4x4 SR 2.8L T Diesel Automatic Doubl					MONTH/YEAR 11/2016	AIR:	
REG. No: 050FV5	STOCK No:	SELLING DEALER:					
CUSTOMER No: 29851	VIN: MR0KA3CD801303030	ENGINE No: 1GD4216573					
CONTACT NAME: Mr Barry Mayne			COLOUR/TRIM Glacier White/Black Fabric		ORDER No:		
CONTACT NUMBERS: H:0746549389 M:0427549389			WAR. EXP:	WAR. KM:	EXT.WAR.EXP:	EXT.WAR.KM:	
						RDR Date: 21/12/2016	

	PRICE	QTY/HRS	AMOUNT
JOB DETAILS			
JOB 1 DISCREPANCY WITH ODOMETER READING AT TIME OF SERVICE			
Last submission of recall work to Toyota Australia was; 17 June 2021, from Central Highlands Toyota. Odometer reading at time of this submission was 162,807kms. 6 December 2019, from Central Highlands Toyota. Odometer reading at time of this submission was 108,440kms. Odometer reading at time of service with Ian Weigh Toyota on 25 October 2023 101,406kms			
MIS	Miscellaneous/Environmental		100.00
JOB 1 SUBTOTAL			100.00
JOB DETAILS			
JOB 2	Carried out 60 months/100,000km service as per handbook		288.00
Carried out 60 months/100,000km service as per handbook. Includes:- Replaced engine oil & oil filter. Inspected drive belt. Inspected cooling system, hoses & connections. Inspected radiator & condenser for debris & signs of damage. Inspected battery electrolyte, cleanliness & security. Inspected brake fluid. Inspected water sediment accumulator. Inspected air cleaner element. Cleaned air flow meter. Checked power steering fluid. Inspected fuel cap, fuel lines & connections. Inspected brake pads & discs. Checked brake pipes & hoses. Checked exhaust system for security & leaks. Inspected steering wheel, gear & linkages. Tightened propeller shaft bolts. Lubricated propeller shaft. Inspected rear differential oil. Inspected towbar & bullbar/nudge bar mounts (if fitted). Tightened chassis & body bolts & nuts. Inspected front differential oil. Inspected ball joints & dust covers.			

***** CONTINUED *****

VEHICLE RELEASE		PREFERRED CONTACT METHOD		<input type="checkbox"/> LETTER	<input type="checkbox"/> PHONE	<input type="checkbox"/> DO NOT CONTACT
<input type="checkbox"/> WORK EXPLAINED	<input type="checkbox"/> VEHICLE WASHED	<input type="checkbox"/> FLOOR MAT SECURITY EXPLAINED	<input type="checkbox"/> EMAIL	<input type="checkbox"/> MOBILE/SMS		
<input type="checkbox"/> COST EXPLAINED	<input type="checkbox"/> ALL COURTESY ITEMS REMOVED					
DELIVERED BY:	DATE:					
RECEIVED BY:	TIME:	<input type="checkbox"/> CASH	<input type="checkbox"/> ACCOUNT	<input type="checkbox"/> EFTPOS/CREDIT CARD		
AMOUNT RECEIVED WITH THANKS			RECEIVED BY			