

## BK Civil - Work Order Summary

**Asset:**  
BK158 - CLAAS Axion 950 Tractor

**Location:**

**Current Tracker Hours:**

**Current Tracker Kms:**

Work Order	Description	Created	Created Hours	Created Km	Completed	Priority	Item Status	Assigned To/Completed By
30867	no reverse	20/05/2023	6050	1148	19/05/2023	Do Not Operate		Murray Sampson
30108	Suspended Axle fault	16/03/2023	6050	1148	21/03/2023	Do Not Operate		Murray Sampson
30109	fit 3 point linkage	16/03/2023	6050	1148	15/03/2023	Ask Supervisor		David Wood
27361	Transmission fault	01/07/2022	6046	1122	21/06/2022	Repair Next Service		
26927	Nb reverse	20/05/2022	6037	1076	20/05/2022	Repair Next Service		
26268	6000 hours service	09/03/2022	5953	864	24/02/2022	Routine Service		Saul Whiley
26170	Not starting	25/02/2022	5947	849	15/02/2022	Repair Next Service		
26159	A/C	24/02/2022	5945	847	16/02/2022	Repair Next Service		
26160	250hr service	24/02/2022	5945	847	17/02/2022	Repair Next Service		Saul Whiley
26115	pick up plate from tow n and draw up rear hitch	19/02/2022	5941	833	16/02/2022	Ask Supervisor		Jordan Humberdross
26116	cut and weld up hitch	19/02/2022	5941	833	17/02/2022	Ask Supervisor		Jordan Humberdross
21729	A/C fault	28/02/2021	5887	629	28/02/2021	Repair Next Service		Jemalong Branch
21536	Tyres, A/C	25/02/2021	5868	559	24/02/2021	Repair Next Service		Jemalong Branch
18216	Transmission fault and derate	13/12/2020	5785	168	18/02/2021	Repair Next Service		Jemalong Branch
15654	5750 hours service	05/11/2020	5724	0	01/05/2021	Routine Service		Jemalong Branch
14931	Fit TFO Tracker Unit 11595	23/10/2020	0	0	04/11/2020	Ask Supervisor		Toowoomba Branch WSHOP - W