



# Vehicle History Summary



Fleet #	130
Registration	KST94
Make	Kenworth
Model	T610
VIN / Chassis #	6F5000000MA469327
Build Date	2021

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-5155	05/11/2022	374067	0	A - 30 Days		Colin Scott
T-1476	02/11/2022	372009	0	NWR	2x NEW GITI65R237 295/80 1 X NWR	Tyreright
R-2147	28/10/2022	0	0	ELECTRICIAL	Connected up computer and checked codes - active code for loss of prime. Followed fault finding tree. Step 2 of fault finding tree refers to service bulletin regarding crystal build up in aftertreatment system. Removed and cleaned out all adblue lines, Inline filter and injector. Found blockage in inline filter. Refit all parts. Checked filters - all ok. Completed adblue flush. Checked codes - code is now inactive and aftertreatment system working as it should. Cleared codes. \$240.00 BLOCKED FILTER NOT COVERED BY WARRANTY. Warranty Repairs/Service At No Charge Removed kick panel. Removed trailer air pressure switch and found full of water. Blew out manifold and replaced switch. Put kick panel back on. Code now inactive. CLAIM 442502	Brown & Hurley
T-1474	24/10/2022	366305	0	STRIP & FIT	1X STRIP 1X FITTING STK RUNOUT TO POS 8 1X DISPOSAL	Tyreright
S-5081	07/10/2022	358023		A - 30 Days		Kelvyn Fuller
S-5043	07/10/2022	358023	0	A - 30 Days		Colin Scott
S-5007	17/09/2022	345206	0	A - 30 Days		Colin Scott
T-1458	14/09/2022	0	0	STRIP & FIT		Tyreright
S-4902	16/08/2022	308202	0	B - 60k	ENGINE OIL AND FILTERS SUPPLIED	SH&M Fuller Transport Repairs
T-1419	18/07/2022	0	0	NEW & BALANCE		Tyreright

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-4850	16/07/2022	308139	0	A - 30 Days		Colin Scott
R-2087	29/06/2022	0	0	Misc	REMOVE AND REPLACE SUPPLIED POS 1 & 2 SLACK ADJUSTERS, REPLACE LEAKING DIFF OIL FILER, TENSION LOOSE OIL FILTER HOUSING L, CHECK DIFF OIL LEAK	SH&M Fuller Transport Repairs
S-4820	18/06/2022	292575	0	A - 30 Days		Colin Scott
T-1407	03/06/2022	0	0	STRIP & FIT		Tyreright
T-1407	03/06/2022	0	0	NEW & BALANCE		Tyreright
S-4819	14/05/2022	273404	0	A - 30 Days		Colin Scott
I-43	09/04/2022	537245	0	HEAVY VEHICLE ANNUAL INSPECTION - TRUCKS		
S-4667	09/04/2022	258977	0	C - Annual		Colin Scott
S-4670	09/04/2022	258977	0	B - 60k		Colin Scott
T-1364	22/02/2022	0	0	Balance, STRIP & FIT	2 STRIP & FIT , 2 BALANCE	Tyreright
S-4534	10/02/2022	232033	0	A - 30 Days		Colin Scott
S-4443	27/01/2022	219000	0	B - 60k		Colin Scott
T-1326	16/01/2022	0	0	STRIP & FIT	2 STRIP AND FIT 2 BALANCE	Tyreright
S-4241	19/12/2021	199957	0	A - 30 Days		Colin Scott
S-4201	18/11/2021	176708	0	A - 30 Days		Colin Scott
S-4186	14/10/2021	152839	0	A - 30 Days		
S-4185	14/10/2021	152839	0	B - 60k		
S-4171	18/09/2021	134029	0	A - 30 Days		Colin Scott
S-3213	28/08/2021	119915	0	A - 30 Days		Colin Scott
S-3226	31/07/2021	100720	0	A - 30 Days		Kelvyn Fuller
S-4131	17/07/2021	91084	0	A - 30 Days		Colin Scott
S-4132	17/07/2021	91084	0	B - 60k		Colin Scott
T-1251	14/07/2021			New		Tyreright
T-1232	23/06/2021			Rotate		Tyreright
S-4149	19/06/2021	67952	0	A - 30 Days		Kelvyn Fuller
S-3578	16/05/2021	48732	0	A - 30 Days		Colin Scott
S-3599	24/04/2021	34785	0	A - 30 Days		Brown & Hurley
S-3600	24/04/2021	34785	0	B - 60k		Brown & Hurley
T-1136	16/03/2021			Pressure Test		TYRE EVOLUTION

Signed:

\_\_\_\_\_

Name:

\_\_\_\_\_

Date:

\_\_\_\_\_