



Your recall status

Please be sure to read the entire page and follow our advice carefully. To book a Toyota service, please [click here](#).

Applicable Warranty Extensions

If your vehicle exhibits the following conditions, please contact your preferred Toyota dealer.

Campaign Code

[VHG06]

Condition Description

Diesel Particulate Filter defect can cause white smoke during regeneration, trigger the Indicator Lamp and reduce engine power

Vehicle Details

| | |
|------------------------------|-------------------------------|
| VIN | MR0EB3DD600550237 |
| Model | Hilux 4x2 |
| Colour | Glacier White |
| Trim | Black Fabric |
| Series | DC 4X2 W/mate T/D 6A Hi-Rider |
| Production year/month | 2019-03 |
| Time/Date | 11:50:10 18/11/2024 |

This search is provided for information purposes to assist Toyota guests and should not be solely relied upon. The Toyota VIN search tool is available for Toyota vehicles only that are supplied through authorised networks (i.e. it does not include 'grey imports'). The search results contain the best information currently available to Toyota.

*Recall Number (REC) is a unique identifier assigned to vehicle recalls by the Department of Infrastructure, Transport, Regional Development and Communications. Previously, Product Recall Australia (PRA) numbers were assigned by the Australian Competition and Consumer Commission (ACCC), therefore the Toyota Safety Recall Website may display REC number or PRA number formats.

For more detail about REC numbers and/or PRA numbers, please visit

<https://www.vehicle recalls.gov.au/> or <https://www.productsafety.gov.au/>

Note: Takata airbag mandatory safety recalls are controlled/monitored by the ACCC and will display the PRA Number only.