



# Vehicle History Summary



Fleet #	100
Registration	KST28
Make	DAF
Model	XF105
VIN / Chassis #	XLRTT47MSEG040164
Build Date	2015

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-5160	19/11/2022	1262346		A - 30 Days		Kelvyn Fuller
S-5145	12/11/2022	1258986	0	A - 30 Days		Colin Scott
R-2149	08/11/2022	1249777	0	Engine	Bring in, check for codes, found 20 inactive codes, clear codes and road test, fault for short to supply came active, unplug exhaust brake solenoid, code went inactive, found wiring for the plug damaged, code went inactive due to disturbing the wiring, replace plug as required, plug in, code came active for open circuit, test wiring, found fault to be exhaust brake solenoid, conclude fault in wiring to have caused the solenoid to malfunction, remove and replace solenoid as required, carry out roadtest. Bring in, check for codes, found code returned for oil pressure sensor low voltage, check wiring, found to test out ok, change out oil pressure sensor, also had exhaust warning for after catalyst temperature out of range compared to ambient, test wiring from EAS module to temp sensor, found to be ok, noticed a previous repair, cut open and found some loose connections, change out joiners and retest, all ok, resecure wiring, road test, no codes have returned	Brown & Hurley
S-5073	14/10/2022	1249851		A - 30 Days		Kelvyn Fuller
S-5033	24/09/2022	1247747	0	A - 30 Days		Colin Scott
T-1454	09/09/2022	0	0	Puncture	1 PUNCTURE	Tyreright
S-4963	29/08/2022	1242659	0	A - 30 Days		Colin Scott

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-4866	12/08/2022	1239335	0	B - 50k	R & R WIPER BLADES, INDICATOR BULBS, TAIL LIGHT BULBS, REAR SHOCKY RUBBERS, AIR COUPLINGS, MUDGUARD SNAILS, LIGHT BULBS AND COVER. REPAIR LIGHTS AND WIRING	SH&M Fuller Transport Repairs
S-4838	30/07/2022	1239335	0	A - 30 Days		Colin Scott
T-1429	27/07/2022	0	0	Puncture		Tyreright
S-4815	02/07/2022	1224553	0	A - 30 Days		Colin Scott
S-4735	04/06/2022	1208848	0	A - 30 Days		Colin Scott
S-4733	28/05/2022	1204345	0	A - 30 Days		Colin Scott
S-4719	21/05/2022	1200259	0	A - 30 Days		Colin Scott
R-2078	03/05/2022	0	0	Misc	REMOVE SEIZED COMPRESSOR AND REPLACE WITH NEW ONE,, SUPPLY SOLOR CONNECTING TERMENIAL	ROTHDALE
T-1387	19/04/2022	0	0		3 x New tires	Tyreright
S-4665	09/04/2022	1187676	0	C - Annual		Colin Scott
I-42	09/04/2022	1187676	0	HEAVY VEHICLE ANNUAL INSPECTION - TRUCKS		Colin Scott
S-4669	09/04/2022	1187676	0	B - 50k		Colin Scott
T-1379	05/04/2022	0	0	STRIP & FIT		Tyreright
S-4656	01/04/2022	1099433	0	A - 30 Days		Colin Scott
S-4643	25/03/2022	1183210	0	A - 30 Days	wheel seal FLH drive	Colin Scott
S-4638	18/03/2022	1180006	0	A - 30 Days		Colin Scott
R-2059	06/03/2022	0	0	ELECTRICIAL	CHECK A/C ADD SMALL AMOUNT RB4A	ROTHALE PTY LTD
R-2048	04/02/2022	0	0	Air Conditioner	GO TO WHERE VEHICLE IS - PICK UP A/C HOSE AND RETURN TO DEPOT : MACHINE BRASS WELD ON FITTINGS TO SUIT DAF STEEL PIPES. RETURN AND FIT A/C HOSE. EVACUATE AND REGAS WITH K & S GAS.	ROTHALE PTY LTD
R-2030	27/01/2022	0	0	Power Steering	R & R POWER STEER HOSE. TOP UP FLUID AND TEST OPERATION	SH&M Fuller Transport Repairs
S-4447	20/01/2022	1159868	0	A - 30 Days		Colin Scott
R-2025	30/12/2021	0	0	Air Conditioner	GO TO TRUCK - SUPPLY MANUAL REST CIRCUIT BREAKER	ROTHALE PTY LTD
S-4242	20/12/2021	1151285	0	A - 30 Days		Colin Scott
R-2012	16/12/2021	0	0	Alarm	CHECK OUT AND FIND PROBLEM. PLACE TERMINAL ADHESIVE LINED ( 2) - JOINER PUSH - TIE CABLE	Brown & Hurley

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-4204	25/11/2021	1146691	0	B - 50k		Colin Scott
S-4194	04/11/2021	1136597	0	A - 30 Days		Colin Scott
S-4189	28/10/2021	1133717	0	A - 30 Days		Colin Scott
R-1975	27/10/2021	0	0	Misc	CHECK OUT - FOUND RHF STEER SHOCK ABSORBER LOOSE. REAR CAB SHOCK ABSORBER BOTTOM BUSH WORN BUT NOT LOOSE. R & R STOP WHEEL SUSPEN SABSORBER, PIVOT BEARING, SPRING SUSPENSION CAB COIL REA, SPRING SUPS CAB MECH FRONT, SEAL RING MOUNTINGS, BEARING PIN, VIBRATION DAMPER.	Brown & Hurley
S-4181	02/10/2021	1124866	0	A - 30 Days		Colin Scott
S-4169	11/09/2021	1115812	0	A - 30 Days		Colin Scott
R-1529	31/08/2021		1120107	MISC	R & R POSITION 4 HUB SEAL	SH&M Fuller
S-3144	28/08/2021	1108716	0	A - 30 Days		Colin Scott
R-1513	31/07/2021	1103099		MISC	R & R SUPPLIED PINION SEAL AND SLACK ADJUSTER	SH&M Fuller
S-3145	31/07/2021	1103104	0	A - 30 Days		Colin Scott
R-1509	27/07/2021	1098780		MISC	CHECK TRANSMISSION STICKING IN GEAR, HARSH ON SELECTION , GEARBOX HAS BEEN REPLACED . OUTPUT OF TRANSMISSION LEAKING	Brown & Hurley
T-1247	07/07/2021			STIP & FIT		Tyreright
S-4145	03/07/2021	1092541	0	B - 50k		Colin Scott
S-4144	03/07/2021	1092541	0	A - 30 Days		Colin Scott
R-1335	16/06/2021	1080426		MISC	WARNING ON DASH CLEAR, HAD BEEN CLEARED BEFORE BUT BACK ON BEFORE GETTING TO WORKSHOP. R & R GAS SENSOR NOX AFTER CATALYST , GAS SENSOR NOX FOR CATALYST, CONNECTOR ELEC REPAIR. L/H/S/R FRONT SPRING TOP BUSH NEEDS REPLACEING. R & R SPRING SHACKLE	Brown & Hurley
S-3937	05/06/2021	1080295	0	C - Annual		Colin Scott
T-1228	05/06/2021			HANKOOK		Tyreright
I-8	05/06/2021	1080295	0	HEAVY VEHICLE ANNUAL INSPECTION - TRUCKS		Colin Scott
S-3936	05/06/2021	1080295	0	A - 30 Days		Colin Scott
R-1327	01/06/2021			Air Conditioner	FLUSH SYSTEM . FIT UP NEW R/D EVAPORATOR. REGAS	ROTHALE PTY LTD

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-3939	30/05/2021	1080154	0	A - 30 Days		Kelvyn Fuller
S-3147	30/04/2021	1072880	0	A - 30 Days		Colin Scott
R-1307	23/04/2021	1071208		AIR BAGS	R & R POSITION 3 & 4 AIRBAGS SUPPLIED	SH&M Fuller
S-3148	26/03/2021	1053998	0	A - 30 Days		Colin Scott
R-1280	11/03/2021	1045050		Lights	REMOVE INTERIOR PANELS TO GAIN ACCESS TO LIGHT. REMOVE DAMAGED LIGHT. CLEAN SURFACE AND INSTALL LIGHT WITH SEALANT TO SUIT. REMOVE BROKEN GLASS FROM TRUCK . REFIT INTERIOR PANEL	Brown & Hurley
S-3654	26/02/2021	1039657	0	A - 30 Days		Colin Scott
S-3675	29/01/2021	1025137	0	A - 30 Days		Colin Scott
T-1073	29/01/2021			Puncture		TYRE EVOLUTION
R-1240	20/01/2021	1020199		Sensor Fault	R & R POSITION 1 & 2 BRAKE PADS, SENSORS FOR PAD WEAR REKIT POSITION 1 CALIPER ( PARTS SUPPLIED )	SH&M Fuller
S-3178	08/01/2021	1017723	0	A - 30 Days		Kelvyn Fuller
T-1022	24/11/2020			New		TYRE EVOLUTION
T-1021	24/11/2020			Pressure Test		TYRE EVOLUTION

Signed: \_\_\_\_\_

Name: \_\_\_\_\_

Date: \_\_\_\_\_